

Available from

GPO Sales Program
Division of Technical Information and Document Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Printed copy price: ~~\$8.50~~_____

and

National Technical Information Service
Springfield, Virginia 22161

Title List of Documents Made Publicly Available

June 1-30, 1980

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	3
Domestic Licensing of Production and Utilization Facilities - Docket 50	9
Domestic Licensing of Special Nuclear Material - Docket 70	266
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71	279
Nondocketed Items	289
10CFR - Commission Meeting Records	289
ACRS - Advisory Committee on Reactor Safeguards	291
COMMISSION - NRC Commissioners	294
CONTRACT - NRC Contracts and Modifications	296
FOIA - Freedom of Information Act Requests and Releases	300
GEN TECH IS - Generic Technical Issues	305
I&E - Inspection and Enforcement	305
MISC - Public Document Room Miscellaneous	306
NUREG - NUREG Reports and Related Correspondence	306
ORG - Correspondence with Other Organizations	311
PR - Proposed Rule	311
PRM - Petition for Rulemaking	316
PROJ - Projects - Predocket Licensing	317
PT21 - Noncompliance Reports and Related Correspondence	317
QA999 - Quality Assurance Inspections	318
REGGD - Regulatory Guides	321
RES - Research and Technical Assistance Reports	321
REVIEW GRP - NRC Research Review Groups	324
SECY - Position Papers Before the Commission	324
STATE PROG - State Programs	325
TOPREP - Vendor Reports and Related Correspondence	328
WASTE MGT - Nuclear Waste Management	329
XPORTLIC - Export and Import Licenses	330
Personal Author Index	339
Corporate Source Index	369
Report Number Index	399
Cross Reference of Enclosures to Principal Documents	401
Appendix A - Definitions of Docket 50 Categories	417
Appendix B - Definitions of Nondocketed Categories	425

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS


The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A)
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale, "Available at NTIS"; or "Available at GPO "

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

- IOCFR – Commission Meeting Records
- ACRS – Advisory Committee on Reactor Safeguards
- COMMISSION – NRC Commissioners
- CONTRACT – NRC Contracts and Modifications
- FOIA – Freedom of Information Act Requests and Releases
- GEN TECH IS – Generic Technical Issues
- I&E – Inspection and Enforcement
- MISC – Public Document Room Miscellaneous
- NUREG – NUREG Reports and Related Correspondence
- ORG – Correspondence with other organizations

PR - Proposed Rule
 PRM - Petition for Rulemaking
 PROJ - Projects-Predocket Licensing
 PT21 - Noncompliance Reports and Related Correspondence
 QA999 - Quality Assurance Inspections
 REGGD - Regulatory Guides
 RLS - Research and Technical Assistance Reports
 REVIEW GRP - NRC Research Review Groups
 RM - Rulemakings
 SECY - Position Papers Before the Commission
 STATE PROG - State Programs
 TOPREP - Vendor Reports and Related Correspondence
 WASTE MGT - Nuclear Waste Management
 XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on the next page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x 48mm duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8348	In Situ Uranium Leaching Project	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8355	AMAX Environmental Services, Inc.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8380	Rocky Mountain Energy Co.	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8434	Home State Mining Co., LA	6
40-0299	Union Carbide Corp.	3	40-8452	Bear Creek Uranium Co.	6
40-0665	Anaconda Co. South Texas Uranium Projects	3	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
40-0672	Nuclear Metals, Inc.	3	40-8576	Edlow International Co.	7
40-1162	Western Nuclear, Inc.	3	40-8584	Union 76 Minerals Exploration Co.	7
40-1341	Edgemont Uranium Mine, TVA, and Mines Development, Inc.	4	40-8681	Energy Fuels Nuclear, Inc.	7
40-2061	West Chicago Facility, Kerr-McCoe Corp.	4	40-8684	J & P Corp.	7
40-2259	Pathfinder Mines Corp.	4	40-8693	Ogle Petroleum, Inc.	8
40-3392	Allied Chemical Corp.	4	40-8697	Rocky Mountain Energy Co.	8
40-3453	Atlas Minerals	4	40-8698	Platona Resources, Ltd.	8
40-4337	Marquette Univ.	5	40-8714	Cleveland Cliffs Iron Co.	8
40-4492	Federal American Partners (Mining)	5	40-8720	Standard Oil Co. of Indiana	8
40-5001	AMAX Environmental Services, Inc.	5	40-8721	Rocky Mountain Energy Co.	8
40-6622	Pathfinder Mines Corp.	5	40-8722	Brush-Wellman, Inc.	8
40-6659	Petrotomics Co., Getty Oil	5	40-8727	Kerr-McCoe Nuclear Corp.	8
40-7869	Platona Resources, Ltd.	5	40-8728	Teton Exploration Drilling Co., Inc.	8
40-8027	Kerr-McCoe Corp.	5	40-8745	Ogle Petroleum, Inc.	8
40-8052	Mitsui & Co. (USA), Inc.	5	40-8752	Pinal Minerals & Mining, Ltd.	8
40-8064	Exxon Minerals Co. USA, Exxon Corp.	5	40-8768	Kerr-McCoe Nuclear Corp.	8
40-8084	Lisbon Mine, Rio Algom Corp.	5	50-2	Univ. of Michigan Research Reactor	9
40-8102	Exxon Minerals Co. USA, Exxon Corp.	5	50-3	Indian Point Station, Unit 1	9
40-8304	Wyoming Mining Corp.	6	50-5	Pennsylvania State Univ. Research Reactor	9
			50-10	Dresden Nuclear Power Station, Unit 1	9
			50-18	Vallecitos Boiling Water Reactor	11

Docket	Name	Page	Docket	Name	Page
50-20	Massachusetts Institute of Technology Research Reactor	11	50-213	Haddam Neck Plant	21
50-27	Washington State Univ. Research Reactor	12	50-219	Oyster Creek Nuclear Power Plant	22
50-29	Yankee-Rowe Nuclear Power Station	13	50-220	Nine Mile Point Nuclear Station, Unit 1	24
50-30	Plum Brook Research Reactor Facility	13	50-223	Univ. of Lowell Research Reactor	25
50-54	Union Carbide Research Reactor	13	50-224	Univ. of California Research Reactor	25
50-70	General Electric Test Reactor	13	50-225	RP1 Critical Experiment	26
50-73	General Electric Nuclear Test Reactor	13	50-228	Aerotest Radiography & Research Reactor	26
50-83	Univ. of Florida Training Reactor	14	50-237	Dresden Nuclear Power Station, Unit 2	26
50-111	North Carolina State Univ. Research Reactor	14	50-243	Oregon State Univ. Research Reactor	27
50-116	Iowa State Univ. Research Reactor	14	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28
50-128	Texas A&M Univ. Research Reactor	14	50-245	Millstone Nuclear Power Station, Unit 1	29
50-129	West Virginia Univ. Research Reactor	14	50-247	Indian Point Station, Unit 2	31
50-133	Humboldt Bay Power Plant, Unit 3	14	50-249	Dresden Nuclear Power Station, Unit 3	33
50-141	Stanford Univ. Research Reactor	15	50-250	Turkey Point Plant, Unit 3	35
50-142	UCLA Training Reactor	15	50-251	Turkey Point Plant, Unit 4	37
50-147	Rockwell International Corp. Critical Facility	15	50-254	Quad-Cities Station, Unit 1	39
50-150	Ohio State Univ. Research Reactor	15	50-255	Palisades Nuclear Plant	41
50-155	Big Rock Point Nuclear Plant	15	50-259	Browns Ferry Nuclear Power Station, Unit 1	43
50-157	Cornell Univ. Research Reactor	17	50-260	Browns Ferry Nuclear Power Station, Unit 2	45
50-160	Georgia Institute of Technology Research Reactor	17	50-261	H. B. Robinson Plant, Unit 2	47
50-166	Univ. of Maryland Research Reactor	17	50-263	Monticello Nuclear Generating Plant	48
50-170	National Naval Medical Center	17	50-264	Dow Chemical Co.	49
50-171	Peach Bottom Atomic Power Station, Unit 1	17	50-265	Quad-Cities Station, Unit 2	49
50-184	National Bureau of Standards Reactor	18	50-266	Point Beach Nuclear Plant, Unit 1	51
50-185	Plum Brook Reactor — Mock-up	18	50-267	Fort St. Vrain Nuclear Generating Station	52
50-186	Univ. of Missouri Research Reactor	18	50-269	Oconee Nuclear Station, Unit 1	54
50-192	Univ. of Texas Research Reactor	18	50-270	Oconee Nuclear Station, Unit 2	56
50-201	West Valley Reprocessing Plant	18	50-271	Vermont Yankee Nuclear Power Station	58
50-206	San Onofre Nuclear Station, Unit 1	19	50-272	Salem Nuclear Generating Station, Unit 1	59
50-208	Columbia Univ. Research Reactor	21	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	62

Docket	Name	Page	Docket	Name	Page
50-277	Peach Bottom Atomic Power Station, Unit 2	64	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	113
50-278	Peach Bottom Atomic Power Station, Unit 3	66	50-320	Three Mile Island Nuclear Station, Unit 2	115
50-280	Surry Power Station, Unit 1	68	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	122
50-281	Surry Power Station, Unit 2	71	50-322	Shoreham Nuclear Power Station	125
50-282	Prairie Island Nuclear Station, Unit 1	73	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	126
50-285	Fort Calhoun Station, Unit 1	75	50-324	Brunswick Steam Electric Plant, Unit 2	129
50-286	Indian Point Station, Unit 3	76	50-325	Brunswick Steam Electric Plant, Unit 1	131
50-287	Oconee Nuclear Station, Unit 3	78	50-327	Sequoyah Nuclear Plant, Unit 1	133
50-288	Reed College Research Reactor	80	50-328	Sequoyah Nuclear Plant, Unit 2	137
50-289	Three Mile Island Nuclear Station, Unit 1	80	50-329	Midland Plant, Unit 1	140
50-293	Pilgrim Nuclear Power Station, Unit 1	86	50-330	Midland Plant, Unit 2	141
50-294	Michigan State Univ. Research Reactor	88	50-331	Duane Arnold Energy Center	143
50-295	Zion Nuclear Power Station, Unit 1	88	50-333	James A. Fitzpatrick Nuclear Power Plant	145
50-296	Browns Ferry Nuclear Power Station, Unit 3	90	50-334	Beaver Valley Power Station, Unit 1	147
50-297	North Carolina State Univ. PULSTAR Reactor	92	50-335	St. Lucie Plant, Unit 1	149
50-298	Cooper Nuclear Station	92	50-336	Millstone Nuclear Power Station, Unit 2	151
50-301	Point Beach Nuclear Plant, Unit 2	93	50-338	North Anna Power Station, Unit 1	153
50-302	Crystal River Nuclear Plant, Unit 3	94	50-339	North Anna Power Station, Unit 2	155
50-304	Zion Nuclear Power Station, Unit 2	97	50-341	Enrico Fermi Atomic Power Plant, Unit 2	158
50-305	Kewaunee Nuclear Power Plant	99	50-344	Trojan Nuclear Plant	159
50-306	Prairie Island Nuclear Station, Unit 2	100	50-346	Davis-Besse Nuclear Power Station, Unit 1	164
50-309	Maine Yankee Atomic Power Plant	101	50-348	Joseph M. Farley Nuclear Plant, Unit 1	165
50-311	Salem Nuclear Generating Station, Unit 2	103	50-352	Limerick Generating Station, Unit 1	166
50-312	Rancho Seco Nuclear Generating Station	105	50-353	Limerick Generating Station, Unit 2	167
50-313	Arkansas Nuclear One, Unit 1	107	50-354	Hope Creek Nuclear Station, Unit 1	168
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	109	50-355	Hope Creek Nuclear Station, Unit 2	168
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	110	50-357	Univ. of California	169
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	112	50-358	William H. Zimmer Nuclear Station, Unit 1	169
			50-361	San Onofre Nuclear Station, Unit 2	171
			50-362	San Onofre Nuclear Station, Unit 3	173

Docket	Name	Page	Docket	Name	Page
50-363	Forked River Nuclear Station, Unit 1	174	50-414	Catawba Nuclear Station, Unit 2	205
50-364	Joseph M. Farley Nuclear Plant, Unit 2	175	50-416	Grand Gulf Nuclear Station, Unit 1	206
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	176	50-417	Grand Gulf Nuclear Station, Unit 2	208
50-367	Bailey Generating Station	179	50-423	Millstone Nuclear Power Station, Unit 3	210
50-368	Arkansas Nuclear One, Unit 2	180	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	211
50-369	William B. McGuire Nuclear Station, Unit 1	181	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	211
50-370	William B. McGuire Nuclear Station, Unit 2	183	50-433	Univ. of California at Santa Barbara Research Reactor	212
50-373	LaSalle County Station, Unit 1	184	STN-50-437	Floating Nuclear Plant	212
50-374	LaSalle County Station, Unit 2	186	50-438	Belleville Nuclear Plant, Unit 1	213
50-376	North Coast Nuclear Plant, Puerto Rico	187	50-439	Belleville Nuclear Plant, Unit 2	214
50-382	Waterford Generating Station, Unit 3	187	50-440	Perry Nuclear Power Plant, Unit 1	215
50-387	Susquehanna Steam Electric Station, Unit 1	188	50-441	Perry Nuclear Power Plant, Unit 2	216
50-388	Susquehanna Steam Electric Station, Unit 2	190	50-443	Seabrook Nuclear Station, Unit 1	216
50-389	St. Lucie Plant, Unit 2	192	50-444	Seabrook Nuclear Station, Unit 2	217
50-390	Watts Bar Nuclear Plant, Unit 1	193	50-445	Comanche Peak Steam Electric Station, Unit 1	218
50-391	Watts Bar Nuclear Plant, Unit 2	195	50-446	Comanche Peak Steam Electric Station, Unit 2	221
50-392	Chin-Shan Power Reactor, Unit 1, Taiwan	196	50-448	Douglas Point Nuclear Station, Unit 1	224
50-395	Vigil C. Summer Nuclear Station, Unit 1	196	50-449	Douglas Point Nuclear Station, Unit 2	224
50-397	WPPSS Nuclear Project, Unit 2	197	50-452	Greenwood Energy Center, Unit 2	224
50-400	Shearon Harris Nuclear Power Plant, Unit 1	199	50-453	Greenwood Energy Center, Unit 3	224
50-401	Shearon Harris Nuclear Power Plant, Unit 2	199	50-454	Byron Station, Unit 1	224
50-402	Shearon Harris Nuclear Power Plant, Unit 3	200	50-455	Byron Station, Unit 2	225
50-403	Shearon Harris Nuclear Power Plant, Unit 4	200	50-456	Bridwood Station, Unit 1	226
50-404	North Anna Power Station, Unit 3	201	50-457	Bridwood Station, Unit 2	227
50-405	North Anna Power Station, Unit 4	201	50-458	River Bend Station, Unit 1	228
50-409	La Crosse Boiling Water Reactor	202	50-459	River Bend Station, Unit 2	228
50-410	Nine Mile Point Nuclear Station, Unit 2	203	50-460	WPPSS Nuclear Project, Unit 1	229
50-412	Beaver Valley Power Station, Unit 2	204	50-461	Clinton Power Station, Unit 1	229
50-413	Catawba Nuclear Station, Unit 1	204	50-462	Clinton Power Station, Unit 2	230
			50-466	Allens Creek Nuclear Station, Unit 1	230

Docket	Name	Page	Docket	Name	Page
50-467	Allens Creek Nuclear Station, Unit 2	232	STN-50-528	Palo Verde Nuclear Station, Unit 1	253
50-471	Pilgrim Nuclear Power Station, Unit 2	232	STN-50-529	Palo Verde Nuclear Station, Unit 2	254
STN-50-482	Wolf Creek Generating Station	233	STN-50-530	Palo Verde Nuclear Station, Unit 3	255
STN-50-483	Calloway Plant, Unit 1	234	50-537	Clinch River Breeder Reactor	257
STN-50-485	Sterling Power Project Nuclear, Unit 1	235	50-538	Memphis State Univ. Research Reactor	257
STN-50-486	Calloway Plant, Unit 2	235	STN-50-546	Marble Hill Nuclear Station, Unit 1	257
STN-50-488	Perkins Nuclear Station, Unit 1	236	STN-50-547	Marble Hill Nuclear Station, Unit 2	259
STN-50-489	Perkins Nuclear Station, Unit 2	237	50-548	Fort Calhoun Station, Unit 2	261
STN-50-490	Perkins Nuclear Station, Unit 3	238	50-549	Greene County Nuclear Power Plant	261
STN-50-491	Cherokee Nuclear Station, Unit 1	239	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	261
STN-50-492	Cherokee Nuclear Station, Unit 2	239	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	262
STN-50-493	Cherokee Nuclear Station, Unit 3	240	STN-50-556	Black Fox Station, Unit 1	263
50-496	Montague Nuclear Power Station, Unit 1	240	STN-50-557	Black Fox Station, Unit 2	263
50-497	Montague Nuclear Power Station, Unit 2	240	STN-50-561	B-SAR-205	263
STN-50-498	South Texas Project, Unit 1	240	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	263
STN-50-499	South Texas Project, Unit 2	243	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	264
50-500	Davis-Besse Nuclear Power Station, Unit 2	246	STN-50-573	Ko-Ri, Unit 2, Korea	265
50-501	Davis-Besse Nuclear Power Station, Unit 3	246	STN-50-574	Bagnoc Nuclear Power Project, Philippines	265
STN-50-502	Haven Nuclear Plant, Unit 1	246	STN-50-591	ESSAR	265
STN-50-508	WPPSS Nuclear Project, Unit 3	247	STN-50-592	Palo Verde Nuclear Station, Unit 4	265
STN-50-509	WPPSS Nuclear Project, Unit 5	247	STN-50-593	Palo Verde Nuclear Station, Unit 5	265
50-513	WPPSS Nuclear Project, Unit 4	247	STN-50-596	New Haven, Unit 1	266
50-514	Pebble Springs Nuclear Plant, Unit 1	248	STN-50-597	New Haven, Unit 2	266
50-515	Pebble Springs Nuclear Plant, Unit 2	248	50-599	Carroll Facility I	266
STN-50-516	Jamesport Nuclear Station, Unit 1	248	50-600	Carroll Facility II	266
STN-50-517	Jamesport Nuclear Station, Unit 2	248	70-0008	Battelle Columbus Laboratories	266
STN-50-518	Hartsville Nuclear Plant, Unit 1	249	70-0025	Rockwell International Corp.	266
STN-50-519	Hartsville Nuclear Plant, Unit 2	250	70-0027	Babcock & Wilcox Co.	267
STN-50-520	Hartsville Nuclear Plant, Unit 3	251	70-0033	Texas Instruments, Inc.	267
STN-50-521	Hartsville Nuclear Plant, Unit 4	252	70-0036	Combustion Engineering, Inc.	268
STN-50-522	Skagit Nuclear Power Project, Unit 1	252	70-0089	Massachusetts Institute of Technology	268
STN-50-523	Skagit Nuclear Power Project, Unit 2	253	70-0095	Massachusetts Institute of Technology	268

Docket	Name	Page	Docket	Name	Page
70-0124	Teledyne Isotopes	265	70-1252	Edlow International Co.	275
70-0135	Babcock & Wilcox Co.	266	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	275
70-0143	Nuclear Fuel Services, Inc.	269	70-1308	Morris Operations, General Electric Co.	276
70-0194	Massachusetts Institute of Technology	270	70-1314	National Aeronautics & Space Administration, Langley Research Center	277
70-0267	Nuclear Science & Technology Facility at State Univ. of New York	270	70-1319	U.S. Nuclear, Inc.	277
70-0364	Parks Township Site, Babcock & Wilcox Co.	270	70-1359	IRT Corp.	277
70-0371	United Nuclear Corp.	270	70-1510	Nuclear Assurance Corp.	277
70-0398	Dept. of Commerce	270	70-1621	Conover & Associates, Inc.	277
70-0442	Dept. of HEW, Food and Drug Administration	271	70-1729	Food Recovery & Storage Station, Allied General Nuclear Services	277
70-0572	Monsanto Research Corp.	271	70-1812	General Atomic Co.	277
70-0623	Kenyon College	271	70-1966	Tennessee Valley Authority	277
70-0657	Union Carbide Corp.	271	70-1992	Mt. Auburn Hospital, Cambridge, MA	277
70-0698	Waltz Mill Site, Westinghouse Electric Corp.	271	70-2131	Edlow International Co.	277
70-0734	General Atomic Co.	271	70-2260	St. Joseph Hospital, Stamford, CT	277
70-0754	Vulcanics Nuclear Center, General Electric Co.	271	70-2474	Holy Name Hospital, Teaneck, NJ	277
70-0778	General Electric Co., Nuclear Energy Products Division	272	70-2485	Edlow International Co.	277
70-0785	State Univ. of New York at Buffalo	272	70-2486	St. Elisabeth Hospital, Medical Center, Lafayette, IN	277
70-0820	United Nuclear Corp.	272	70-2523	General Atomic Co.	277
70-0824	Babcock & Wilcox Co.	272	70-2542	Westinghouse Electric Co.	278
70-0925	Climaxon Facility, Kerr-McGee Corp.	273	70-2609	Commonwealth Edison Co.	278
70-0938	Massachusetts Institute of Technology	273	70-2619	Bloomington Hospital, Bloomington, IN	278
70-0984	Pacific Northwest Laboratory	273	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	278
70-1007	General Electric Co.	273	70-2805	Nissho-Iwai American Corp.	278
70-1100	Combustion Engineering, Inc.	273	70-2838	Cincinnati Gas & Electric Co.	278
70-1113	General Electric Co.	274	70-2885	Commonwealth Edison	278
70-1113	Westinghouse Electric Corp.	274	70-2909	Westinghouse Electric Corp. Power Systems	278
70-1113	Westinghouse Electric Corp.	274	70-2910	Tennessee Valley Authority	279
70-1113	Westinghouse Electric Corp.	274	70-2920	Alabama Power Co.	279
70-1113	Kerr-McGee Corp.	275	70-2928	Tennessee Valley Authority	279
70-1113	Westinghouse Electric Corp.	275	71-0015	Chicago Bridge & Iron Co.	279

Docket	Name	Page	Docket	Name	Page
71-0102	Source Products & Equipment Co., Inc.	219	71-5975	Model: 5975, Schlumberger Well Services	282
71-0108	Univ. of Missouri	219	71-5980	Model: GE-600, General Electric Co.	282
71-0135	Babcock & Wilcox Co.	219	71-6058	Model: B3-1, Nuclear Engineering Co.	282
71-0164	Massachusetts Institute of Technology	219	71-6144	Model: 6144, Nuclear Engineering Co.	282
71-0165	Dept. of the Navy	280	71-6206	Model: B, Babcock & Wilcox Co.	282
71-0173	Battelle-Pacific Northwest Laboratory	280	71-6272	Model: Poly Panther, Teledyne Energy Systems	282
71-0185	BBF, Inc.	280	71-6275	Model: LL-28-4, Chem-Nuclear Systems, Inc.	282
71-0230	Babcock & Wilcox Co.	280	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	282
71-0384	New England Nuclear Corp.	280	71-6387	Model: 60, Battelle Memorial Institute	283
71-0387	Massachusetts Materials Research, Inc.	280	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	283
71-0388	Dept. of the Navy, USS Canopus	280	71-6553	Model: Paducah Tiger, Dept. of Energy	283
71-0389	Univ. of Georgia	280	71-6581	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	283
71-0390	Dept. of Commerce, National Bureau of Standards	280	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	283
71-0391	Dept. of the Navy	280	71-6639	Model: M5-1A, Dept. of the Army	283
71-4888	Model: Sentinel-25A, B, C, C3, D, E, F, Teledyne Energy Systems	280	71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	283
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	280	71-6697	Model: 8500 PKG, General Electric Co.	283
71-5026	Model: BC-48-220, Atcor, Inc.	281	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	283
71-5071	Model: URIPS-P-1, Dept. of the Navy	281	71-6717	Model: 6717 B	284
71-5364	Model: NP1-67-0442, Neutron Products, Inc.	281	71-6744	Model: Poly Tiger, Nuclear Engineering Co.	284
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	281	71-6771	Model: SN-1, Nuclear Engineering Co.	284
71-5607	Model: GE T-2, General Electric Co.	281	71-6786	Model: URIPS-8B, Dept. of the Navy	284
71-5796	Model: 181361, Picker Corp.	281	71-9001	Model: IF-300, General Electric Co.	284
71-5830	Model: SNAP 21, Dept. of the Navy	281	71-9007	Model: 520, Argonne National Laboratory	284
71-5862	Model: Sentinel-100F, Teledyne Energy Systems	281	71-9009	Model: FL 10-1, General Electric Co.	284
71-5926	Model: 100, General Electric Co.	281	71-9010	Model: NL1-1/2, NL Industries, Inc.	284
71-5939	Model: GE-1500, General Electric Co.	281	71-9011	Model: E-MEH-09-00004, Dept. of Transportation	285
71-5940	Model: EX-16-10, Battelle Columbus Laboratories	282	71-9015	Model: TN-8, Transnuclear, Inc.	285
71-5942	Model: GE-700, General Electric Co.	282	71-9016	Model: TN-9, Transnuclear, Inc.	285
71-5957	Model: BMI-1, Dept. of Energy	282			

Docket	Name	Page	Docket	Name	Page
71-9018	Model: BU-6, General Electric Co.	285	71-9089	Model: HN-100 S, Hitman Nuclear & Development Corp.	287
71-9019	Model: BU-7, General Electric Co.	285	71-9091	Model: 30 A; General Electric Co.	287
71-9023	Model: NLI-10/24, NI Industries, Inc.	285	71-9093	Model: HN-400, Hitman Nuclear & Development Corp.	287
71-9032	Model: 650, Technical Operations, Inc.	285	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc.	287
71-9039	Model: 715, Technical Operations, Inc.	285	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	287
71-9044	Model: GE-1600, General Electric Co.	285	71-9103	Model: NLI-6502	288
71-9045	Model: GE-1000, General Electric Co.	286	71-9111	Model: CN6-80A, Chem-Nuclear Systems, Inc.	288
71-9046	Model: GE-1100, General Electric Co.	286	71-9113	Model: T-100, Chem-Nuclear Systems, Inc.	288
71-9050	Model: GE-900, General Electric Co.	286	71-9132	Model: T-3, Nuclear Packaging, Inc.	288
71-9051	Model: GE-1400, General Electric Co.	286	71-9135	Model: Centary, Gamma Industries	288
71-9070	Model: N-55, Dept. of Energy	286	71-9138	Model: 78-D-1458, Dept. of the Navy	288
71-9071	Model: AP-101, Chem-Nuclear Systems, Inc.	286	71-9141	Model: 900 Type B, Technical Operations, Inc.	288
71-9073	Model: OH-142, Nuclear Packaging, Inc.	286	71-9853	Model: ORNL -- BNL -- NBS Unirradiated Fuel Container, Dept. of Energy	288
71-9079	Model: HN-100 Series 2, Hitman Nuclear & Development Corp.	286			
71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	287			
71-9086	Model: HN-100 Series 1, Hitman Nuclear & Development Corp.	287			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerostat Radiography & Research Reactor	50-228	26	Calloway Plant, Unit 2	STN-50-486	235
Allens Creek Nuclear Station, Unit 1	50-466	230	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	112
Allens Creek Nuclear Station, Unit 2	50-467	232	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	113
Arkansas Nuclear One, Unit 1	50-313	107	Carroll Facility I	50-599	266
Arkansas Nuclear One, Unit 2	50-368	180	Carroll Facility II	50-600	266
Duane Arnold Energy Center	50-331	143	Catawba Nuclear Station, Unit 1	50-413	204
B-SAR-205	STN-50-561	263	Catawba Nuclear Station, Unit 2	50-414	205
Bagneux Nuclear Power Project, Philippines	STN-50-574	265	Cherokee Nuclear Station, Unit 1	STN-50-491	239
Bally Generating Station	50-367	179	Cherokee Nuclear Station, Unit 2	STN-50-492	239
Beaver Valley Power Station, Unit 1	50-334	147	Cherokee Nuclear Station, Unit 3	STN-50-493	240
Beaver Valley Power Station, Unit 2	50-412	204	Chia-Shan Power Reactor, Unit 1, Taiwan	50-392	196
Bellefonte Nuclear Plant, Unit 1	50-438	213	Clinch River Breeder Reactor	50-537	257
Bellefonte Nuclear Plant, Unit 2	50-439	214	Clinton Power Station, Unit 1	50-461	229
Big Rock Point Nuclear Power Plant	50-153	15	Clinton Power Station, Unit 2	50-462	230
Black Fox Station, Unit 1	STN-50-556	263	Columbia Univ. Research Reactor	50-308	21
Black Fox Station, Unit 2	STN-50-557	263	Comanche Peak Steam Electric Station, Unit 1	50-445	218
Braidwood Station, Unit 1	50-456	226	Comanche Peak Steam Electric Station, Unit 2	50-446	221
Braidwood Station, Unit 2	50-457	227	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	109
Browns Ferry Nuclear Power Station, Unit 1	50-259	43	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	110
Browns Ferry Nuclear Power Station, Unit 2	50-260	45	Cooper Nuclear Station	50-298	92
Browns Ferry Nuclear Power Station, Unit 3	50-296	90	Cornell Univ. Research Reactor	50-157	17
Brunswick Steam Electric Plant, Unit 1	50-325	131	Crystal River Nuclear Plant, Unit 3	50-302	94
Brunswick Steam Electric Plant, Unit 2	50-324	129	Davis-Besse Nuclear Power Station, Unit 1	50-346	164
Byron Station, Unit 1	50-454	224	Davis-Besse Nuclear Power Station, Unit 2	50-500	246
Byron Station, Unit 2	50-455	225	Davis-Besse Nuclear Power Station, Unit 3	50-501	246
Calloway Plant, Unit 1	STN-50-483	234			

Name	Docket	Page	Name	Docket	Page
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	62	Shearon Harris Nuclear Power Plant, Unit 3	50-402	200
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	126	Shearon Harris Nuclear Power Plant, Unit 4	50-403	200
Douglas Point Nuclear Station, Unit 1	50-448	224	Hartsville Nuclear Plant, Unit 1	STN-50-518	249
Douglas Point Nuclear Station, Unit 2	50-449	224	Hartsville Nuclear Plant, Unit 2	STN-50-519	250
Dow Chemical Co.	50-264	49	Hartsville Nuclear Plant, Unit 3	STN-50-520	251
Dresden Nuclear Power Station, Unit 1	50-10	9	Hartsville Nuclear Plant, Unit 4	STN-50-521	252
Dresden Nuclear Power Station, Unit 2	50-237	26	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	122
Dresden Nuclear Power Station, Unit 3	50-249	33	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
ESSAR	STN-50-591	265	Haven Nuclear Plant, Unit 1	STN-50-502	246
Joseph M. Farley Nuclear Plant, Unit 1	50-348	165	Hope Creek Nuclear Station, Unit 1	50-354	168
Joseph M. Farley Nuclear Plant, Unit 2	50-364	175	Hope Creek Nuclear Station, Unit 2	50-355	168
Enrico Fermi Atomic Power Plant, Unit 2	50-341	158	Humboldt Bay Power Plant, Unit 3	50-133	14
James A. Fitzpatrick Nuclear Power Plant	50-333	145	Indian Point Station, Unit 1	50-3	9
Floating Nuclear Plant	STN-50-437	212	Indian Point Station, Unit 2	50-247	31
Forked River Nuclear Station, Unit 1	50-363	174	Indian Point Station, Unit 3	50-286	76
Fort Calhoun Station, Unit 1	50-285	75	Iowa State Univ. Research Reactor	50-116	14
Fort Calhoun Station, Unit 2	50-548	261	Jamesport Nuclear Station, Unit 1	STN-50-516	248
Fort St. Vrain Nuclear Generating Station	50-267	52	Jamesport Nuclear Station, Unit 2	STN-50-517	248
General Electric Test Reactor	50-70	13	Kewaunee Nuclear Power Plant	50-305	99
General Electric Nuclear Test Reactor	50-73	13	Ko-RI, Unit 2, Korea	50-573	265
Georgia Institute of Technology Research	50-160	17	La Crosse Boiling Water Reactor	50-409	202
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	28	LaSalle County Station, Unit 1	50-373	184
Grand Gulf Nuclear Station, Unit 1	50-416	206	LaSalle County Station, Unit 2	50-374	186
Grand Gulf Nuclear Station, Unit 2	50-417	208	Limerick Generating Station, Unit 1	50-352	166
Greene County Nuclear Power Plant	50-549	261	Limerick Generating Station, Unit 2	50-353	167
Greenwood Energy Center, Unit 2	50-452	224	Maine Yankee Atomic Power Plant	50-309	101
Greenwood Energy Center, Unit 3	50-453	224	Marble Hill Nuclear Station, Unit 1	STN-50-546	257
Idaho Plant	50-213	21	Marble Hill Nuclear Station, Unit 2	STN-50-547	259
Indian Point Nuclear Power Plant,	50-400	199	Massachusetts Institute of Technology Research Reactor	50-20	11
Indian Point Nuclear Power Plant,	50-401	199	William B. McGuire Nuclear Station, Unit 1	50-369	181

Name	Docket	Page	Name	Docket	Page
William B. McGuire Nuclear Station, Unit 2	50-370	183	Palo Verde Nuclear Station, Unit 1	STN-50-528	253
Memphis State Univ. Research Reactor	50-538	257	Palo Verde Nuclear Station, Unit 2	STN-50-529	254
Michigan State Univ. Research Reactor	50-294	88	Palo Verde Nuclear Station, Unit 3	STN-50-530	255
Midland Plant, Unit 1	50-329	140	Palo Verde Nuclear Station, Unit 4	STN-50-592	265
Midland Plant, Unit 2	50-330	141	Palo Verde Nuclear Station, Unit 5	STN-50-593	265
Millstone Nuclear Power Station, Unit 1	50-245	29	Peach Bottom Atomic Power Station, Unit 1	50-171	17
Millstone Nuclear Power Station, Unit 2	50-336	151	Peach Bottom Atomic Power Station, Unit 2	50-277	64
Millstone Nuclear Power Station, Unit 3	50-423	210	Peach Bottom Atomic Power Station, Unit 3	50-278	66
Montague Nuclear Power Station, Unit 1	50-496	240	Pebble Springs Nuclear Plant, Unit 1	50-514	248
Montague Nuclear Power Station, Unit 2	50-497	240	Pebble Springs Nuclear Plant, Unit 2	50-515	248
Monticello Nuclear Generating Plant	50-263	48	Pennsylvania State Univ. Research Reactor	50-5	9
National Bureau of Standards Reactor	50-184	18	Perkins Nuclear Station, Unit 1	STN-50-488	236
National Naval Medical Center	50-170	17	Perkins Nuclear Station, Unit 2	STN-50-489	237
New Haven, Unit 1	STN-50-596	266	Perkins Nuclear Station, Unit 3	STN-50-490	238
New Haven, Unit 2	STN-50-597	266	Perry Nuclear Power Plant, Unit 1	50-440	215
Nine Mile Point Nuclear Station, Unit 1	50-220	24	Perry Nuclear Power Plant, Unit 2	50-441	216
Nine Mile Point Nuclear Station, Unit 2	50-410	203	Phipps Bend Nuclear Plant, Unit 1	STN-50-553	261
North Anna Power Station, Unit 1	50-338	153	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	262
North Anna Power Station, Unit 2	50-339	155	Pilgrim Nuclear Power Station, Unit 1	50-293	86
North Anna Power Station, Unit 3	50-404	201	Pilgrim Nuclear Power Station, Unit 2	50-471	232
North Anna Power Station, Unit 4	50-405	201	Plum Brook Reactor — Mock-up	50-185	18
North Carolina State Univ. PULSTAR Reactor	50-297	92	Plum Brook Research Reactor Facility	50-307	13
North Carolina State Univ. Research Reactor	50-111	14	Point Beach Nuclear Plant, Unit 1	50-266	51
North Coast Nuclear Plant, Puerto Rico	50-376	187	Point Beach Nuclear Plant, Unit 2	50-301	93
Oconee Nuclear Station, Unit 1	50-269	54	Prairie Island Nuclear Station, Unit 1	50-282	73
Oconee Nuclear Station, Unit 2	50-270	56	Prairie Island Nuclear Station, Unit 2	50-306	100
Oconee Nuclear Station, Unit 3	50-287	78	Quad-Cities Station, Unit 1	50-254	39
Ohio State Univ. Research Reactor	50-150	15	Quad-Cities Station, Unit 2	50-265	49
Oregon State Univ. Research Reactor	50-343	27	Rancho Seco Nuclear Generating Station	50-312	105
Oyster Creek Nuclear Power Plant	50-219	22	Reed College Research Reactor	50-288	80
Paiades Nuclear Plant	50-255	41			

Name	Docket	Page	Name	Docket	Page
River Bend Station, Unit 1	50-458	228	Three Mile Island Nuclear Station, Unit 1	50-289	80
River Bend Station, Unit 2	50-459	228	Trojan Nuclear Plant	50-344	159
H. B. Robinson Plant, Unit 2	50-261	47	Turkey Point Plant, Unit 3	50-250	35
Rockwell International Corp. Critical Facility	50-147	15	Turkey Point Plant, Unit 4	50-251	37
RPI Critical Experiment	50-223	26	UCLA Training Reactor	50-142	15
Salem Nuclear Generating Station, Unit 1	50-272	59	Union Carbide Research Reactor	50-54	13
Salem Nuclear Generating Station, Unit 2	50-311	103	Univ. of California	50-357	169
San Onofre Nuclear Station, Unit 1	50-206	19	Univ. of California at Santa Barbara Research Reactor	50-433	212
San Onofre Nuclear Station, Unit 2	50-361	171	Univ. of California Research Reactor	50-224	25
San Onofre Nuclear Station, Unit 3	50-362	173	Univ. of Florida Training Reactor	50-83	14
Seabrook Nuclear Station, Unit 1	50-443	216	Univ. of Lowell Research Reactor	50-223	25
Seabrook Nuclear Station, Unit 2	50-444	217	Univ. of Maryland Research Reactor	50-166	17
Scoquaham Nuclear Plant, Unit 1	50-327	133	Univ. of Michigan Research Reactor	50-2	9
Scoquaham Nuclear Plant, Unit 2	50-328	137	Univ. of Missouri Research Reactor	50-186	18
Shoreham Nuclear Power Station	50-323	125	University of Texas Research Reactor	50-192	18
Skagit Nuclear Power Project, Unit 1	STN-50-522	252	Vallecitos Boiling Water Reactor	50-18	11
Skagit Nuclear Power Project, Unit 2	STN-50-523	253	Vermont Yankee Nuclear Power Station	50-271	58
South Texas Project, Unit 1	STN-50-498	240	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	211
South Texas Project, Unit 2	STN-50-499	243	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	211
Stanford Univ. Research Reactor	50-141	15	Washington State Univ. Research Reactor	50-27	12
Sterling Power Project, Nuclear, Unit 1	STN-50-485	233	Waterford Generating Station, Unit 3	50-382	187
St. Lucie Plant, Unit 1	50-335	149	Watts Bar Nuclear Plant, Unit 1	50-390	193
St. Lucie Plant, Unit 2	50-389	192	Watts Bar Nuclear Plant, Unit 2	50-391	195
Virgil C. Summer Nuclear Station, Unit 1	50-395	196	West Valley Reprocessing Plant	50-201	18
Surry Power Station, Unit 1	50-280	68	West Virginia Univ. Research Reactor	50-129	14
Surry Power Station, Unit 2	50-281	71	Wolf Creek Generating Station	STN-50-482	233
Susquehanna Steam Electric Station, Unit 1	50-387	188	WPPSS Nuclear Project, Unit 1	50-460	229
Susquehanna Steam Electric Station, Unit 2	50-388	190	WPPSS Nuclear Project, Unit 2	50-397	197
Texas A&M Univ. Research Reactor	50-128	14	WPPSS Nuclear Project, Unit 3	STN-50-508	247
			WPPSS Nuclear Project, Unit 4	50-513	247
			WPPSS Nuclear Project, Unit 5	STN-50-509	247

Name	Docket	Page	Name	Docket	Page
Yankee-Rowe Nuclear Power Station	50-29	13	William H. Zimmer Nuclear Station, Unit 1	50-358	169
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	263	Zion Nuclear Power Station, Unit 1	50-295	88
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	264	Zion Nuclear Power Station, Unit 2	50-304	97

DOCKETED ITEMS

LOW LEVEL RADIOACTIVE DISPOSAL SITES

DOCKET 27-016 DEATY/NV

0004170099 Forwards Waste Packaging Insp Rept 80-00 on 000400-0201 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/26 2pp

0004170098 Waste Packaging Insp Rept 80-00 on 000128-0201 No noncompliance noted Major areas inspected waste shipments & packaging/vehicle placarding/packaging conditions & labels
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/26 2pp
0004170098 Waste Packaging Insp Rept 80-00 on 000128-0201 No noncompliance noted Major areas inspected waste shipments & packaging/vehicle placarding/packaging conditions & labels
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/26 2pp

0004170093 Forwards Waste Packaging Insp Rept 80-00 on 000121-0201 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170049 Waste Packaging Insp Rept 80-00 on 000121-0201 No noncompliance noted Major areas inspected waste shipments & packaging/vehicle placarding/packaging conditions & labels
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp
0004170049 Waste Packaging Insp Rept 80-00 on 000121-0201 No noncompliance noted Major areas inspected waste shipments & packaging/vehicle placarding/packaging conditions & labels
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

DOCKET 27-009 SHEPHERD, J. L. NUCLEAR ENGINEERING CO

0004170096 Forwards combined IE Investigation Repts 80-004/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01
NRC has prepared civil penalties to Union Carbide, Union Carbide & French Labs respective states & DOT notified
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/18 2pp

0004170095 IE Combined Investigation Repts 80-004/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01 27-0040/80-01
NRC has prepared civil penalties to Union Carbide, Union Carbide & French Labs respective states & DOT notified
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/18 2pp

0004170092 Exception to ARLS 790903 decision declared final per ARLS 790903 under Section 16 Atomic Energy Act & NEPA decision has completed transportation of waste to other states w/o consideration of consequences Certificate of No Harm
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/24 2pp

0004170025 Motion to strike ANL-Chicago Section 000121 exception to ARLS 790903 decision Right to exceptions waived due to failure to file timely petition No discernible injury established Certificate of No Harm
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/24 2pp

0004170144 Order instructing American Nuclear Encl. Chicago section to include in brief intended to be filed in support of exception to ARLS 790903 order response to State of IL
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/24 2pp

0004170044 Advice NRC that Board Chairman, VP de Polio, is temporarily assuming positions of president & chief executive officer effective immediately
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/24 2pp

0004170044 Advice NRC that Board Chairman, VP de Polio, is temporarily assuming positions of president & chief executive officer effective immediately
SMITH, D. H. Region 1, Philadelphia, Office of the Director 00/04/24 2pp

DOCKET 27-047 BARNHILL, SC. CHEM-NUCLEAR SYSTEMS

0004170030 Forwards waste packaging Insp Rept on 000313-14 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170031 Waste packaging Insp Rept on 000313-14 No noncompliance noted Major areas inspected license-shipping vehicles including for compliance w/ DOT & IBC regulations including shipping paper & DOT placarding requirements
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170032 Forwards Waste Packaging Insp Rept 80-00 on 000313 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170033 Waste Packaging Insp Rept 80-00 on 000313 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & prohibited articles or contents
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170034 Forwards Waste Packaging Insp Rept 80-00 on 000313-14 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170035 Waste Packaging Insp Rept 80-00 on 000313-14 No noncompliance noted Major areas inspected compliance w/ DOT & IBC regulations re shipping paper & placarding requirements
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170036 Forwards Waste Packaging Insp Rept 80-00 on 000313-14 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170037 Waste Packaging Insp Rept 80-00 on 000313-14 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & prohibited articles or contents
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170038 Forwards waste packaging Insp Rept on 000313-14 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170039 Waste packaging Insp Rept on 000313-14 No noncompliance noted Major areas inspected license-shipping vehicles including shipping paper requirements, DOT placarding requirements, radiation levels & labeling
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

0004170040 Forwards Waste Packaging Insp Rept 80-00 on 000313-14 No noncompliance noted
SMITH, D. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp

DOCKETED ITEMS

- 000400000 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected licensee-shipper vehicles including shipping paper requirements, DOT placarding requirements, radiation levels & marking & labeling
POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 0004180407 Forwards waste packaging insp rept on 800312-14 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004180408 Waste Packaging Insp Rept on 800312-14 No noncompliance noted Major areas inspected licensee-shipper vehicles for compliance with DOT regulations including shipping paper, placarding & radiation levels
POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 App
- 0004180417 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004180404 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected compliance of licensee-shipper vehicles with DOT regulations including shipping paper & placarding requirements & radiation levels
POTTER, J.P., PERMY, M.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 0004190329 Forwards Waste Packaging Insp Rept 80-03 on 800312-14 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004190330 Waste Packaging Insp Rept 80-03 on 800312-14 No noncompliance noted Major areas inspected compliance with DOT regulations including shipping paper, placarding & radiation levels
POTTER, J.P., POTTER, R.A. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 App
- 0004190341 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004190371 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & DOT marking & labeling
POTTER, J.P., PERMY, M.W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 0004200357 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 1p
- 0004200340 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
PERMY, M.W., POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 0004190359 Forwards Waste Packaging Insp Rept 80-03 on 800414-15 No noncompliance noted
OTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 2pp
- 0004190352 Waste Packaging Insp Rept 80-03 on 800414-15 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
OTTER, J.P., PERMY, M.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 2pp
- 0004190370 Responds to 800419 request for technical assistance Technical assistance that NRC expects to provide involves preparation of independent site-specific environ assessment document
SMITH, G.H. Low Level Waste Licensing Branch 80/05/18 1p
- 0004190370 Requests 15 addl copies of site stabilization & closure plan & 10 copies of environ assessment to complete review distribution
BRADY, K.E. & Low Level Waste Licensing Branch 80/05/29 1p
- 0004200342 Forwards "Preliminary Site Stabilization & Closure Plan for Borewell Low Level Waste Disposal Facility," in response to NRC 800329 1p
MILLWARD, A. Chesebrough Systems, Inc 80/04/26 1p
- 0004200470 "Preliminary Site Stabilization & Closure Plan for Borewell Low Level Waste Disposal Facility"
Chesebrough Systems, Inc 80/05/31 4pp
- DOCKET 27-048 RICHMOND, VA. NUCLEAR 8004000100 10
- 0004200490 Forwards combined IE Investigation Repts 80-034/80-01 27-0348/80-01, 27-0349/80-01, 27-0350/80-01, 27-0351/80-01 & 27-0352/80-01 NRC has proposed civil penalties to Union Carbide, South Kline & French Labs respective states & DOT notified
OLICK, R.W. Region 1, Philadelphia, Office of the Director 80/05/18 2pp
- 0004200495 IE Combined Investigation Repts 80-034/80-01, 27-0348/80-01, 27-0349/80-01, 27-0350/80-01 & 27-0351/80-01 Union Carbide failed to meet bill of lading, South Kline & French Labs failed to use proper packaging
OLICK, R.W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/18 4pp
- 0004180037 Forwards Waste Packaging Insp Rept 80-04 on 800304-15 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004180039 Waste Packaging Insp Rept 80-04 on 800304-15 No noncompliance noted Major areas inspected compliance of waste shipments with DOT regulations including vehicle placarding & package marking & labeling
OLICK, R.W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/22 10pp
- 0004190559 Forwards Waste Packaging Insp Rept 80-04 on 800307-18 No noncompliance noted
SMITH, G.H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004190548 Waste Packaging Insp Rept 80-04 on 800307-18 No noncompliance noted Major areas inspected compliance of waste shipments with DOT regulations including vehicle placarding, package conditions & marking & labeling
OLICK, R.W. Region 2, Chicago, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- 0004190545 Forwards Waste Packaging Insp Rept 80-04 on 800303-15 No noncompliance noted
DAVIS, B.E. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/05/08 2pp
- 0004190548 Waste Packaging Insp Rept 80-04 on 800303-15 No noncompliance noted
DAVIS, B.E. Region 3, Chicago, Office of the Director 00/05/08 1p
- 0004190577 Waste Packaging Insp Rept 80-04 on 800303 Noncompliance noted failure to mark tank used to transport radwaste
FISHBEIN, L. Region 2, Chicago, Fuel Facility & Materials Safety Branch 80/05/08 2pp
- 0004200422 PWD-U-80-034 on 800516 NRC was notified that shipment of 74 55-gallon drums of low specific activity material was received onsite 020815 w/o one drum in damaged condition
OLICK, R.W. Region 3, San Francisco, Office of the Director 80/05/16 1p
- 0004200422 PWD-U-80-043 on 800403 DL Ray plans to tear low level radwaste drums at site on part of deq-ing briefing & site tour to include high level waste disposal research projects on Hanford reservation & PFFP
OLICK, R.W. Region 3, San Francisco, Office of the Director 80/05/03 1p
- 0004200444 Advises NRC that board chairman, VP de Pol, is temporarily assuming positions of president & chief executive officer, effective immediately
SABERS, P. Nuclear Engineering Co., Inc. - Subs of Teledyne, Inc 80/04/03 1p

DOCKETED ITEMS

3

0004170150 PWD-V-00-048 on 000403, shipment of ten drums of low level radioactive received from decontaminated shipment not in compliance with regulations because of improper labels, seals, manifests on trailer & improper shipping documents
THOMAS, R D Region 3, San Francisco, Office of the Director 00/06/04 1p

0004240204 PWD-V-00-044 on 000402, shipment of 132 drums of radioactive received, one w/leaking drum leak caused contamination levels of 2,000 dpm on trailer and 1,000-1,300 on several of employees. Contamination cleaned up & trailer released
THOMAS, R D Region 3, San Francisco, Office of the Director 00/06/04 1p

0004240200 PWD-V-00-047 on 000403, shipment of 012 drums of low level radioactive received. One drum had 3-inch gash in side & closure bolt in clamp ring had fallen out. Second drum seeping liquid from bottom. Bural permit cancelled
THOMAS, R D Region 3, San Francisco, Office of the Director 00/06/03 1p

0004490200 PWD-V-00-044 on 000403, upon opening back door on trailer, 55-gallon drum of low level radioactive fell, almost striking employee. Cause by improper bracing of shipment. Leaking drum put into overpack & placed in disposal trench
THOMAS, R D Region 3, San Francisco, Office of the Director 00/06/03 1p

0004500100 PWD-V-00-030 on 000401, of 188 drums of low level radioactive received, one had broken locking ring & four had loose locking rings. No significant radioactive contamination. All cancelled burial permits & trailers left from use of site
THOMAS, R D Region 3, San Francisco, Office of the Director 00/04/04 1p

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0219 UNION CARBIDE CORP

0004030037 Discusses Union Carbide Corp plans of four releases of tailings at project & remedial actions. Recommendations that corrective actions be incorporated into license. Surface & core samples should be analyzed at them in small table 1
WELLS, R T Uranium Recovery Licensing Branch 00/05/08 2p

0004090058 Advises that License 0004-048 is amended to incorporate corrective actions noted in 770302 & 000106 re: release of tailings slurry & liquid into unrestricted areas
SCARANO, R A Uranium Recovery Licensing Branch 00/05/08 2p

0004190037 Submits contract costs incurred & manhours used in reviewing Amend 12 for License 0004-048 submitted on 000329
KOTRICK, J Uranium Recovery Licensing Branch 00/05/10 2p

0004040086 Advises of intent due re fee for manpower expenditures required for review of application for Amend 12 to License 0004-048
ROLLINS, D License Fee Management Branch 00/05/09 1p

0004200036 Informs that Amend 12 for License 0004-048 is included 000408. AEC initiated amend requiring corrective actions to include release of tailings slurry & liquid into unrestricted areas. No fee required
WELLS, R T Uranium Recovery Licensing Branch 00/05/04 1p

DOCKET 40-0445 ANACONDA CO. SOUTH TEXAS URANIUM PROPERTIES

0004000032 "App to Radon & Radium-Daughter Concentrations in Air in Vicinity of Anacosta W Mill"
ROBERTS, J S - LINDSTROM, J D - DUNGEY, C S Argonne National Laboratory FIN A-2209 HURE07C-1133 APP 7/9/13/30 Map Available at HTS.

DOCKET 40-0472 MACLENN METALS, INC

0004200037 Forwards Waste Packaging Ship Rep 00-03 on 000227-24. No noncompliance noted.
ROBERTS, J S Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/04 1p

---0004200034 Waste Packaging Ship Rep 00-03 on 000227-24 No noncompliance noted. Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
ROBERTS, J S Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/03/17 7p

DOCKET 40-1142 WESTERN NUCLEAR, INC

0004040037 Forwards report of 7/9/10 observations re control of 11/6 at site Photos for Patterson area also sent
FRANCIS, E Wagoning, State of 00/03/01 1pp

0004107092 Submits evaluation of vendor permit request following 000400 meeting independent analyst reported that dam could fail w/ enough under worst case conditions. Plan for monitoring, debris sweeps & dewatering will be required
AGUIRRE, M C Wagoning, State of 00/03/07 4p

0004030204 Forwards "Chronology of Events & Stability Assessments re Dump Area Spill West Mill Tailings Retention Embankment"
Bent details investigation & stability analysis of existing embankment based on conditions at Section A-A
DOUGLAS, D Western Nuclear, Inc (subs of Phelps Dodge Corp.) 00/05/08 1p

---0004000343 "Chronology of Events & Stability Assessments re Dump Area Spill West Mill Tailings Retention Embankment" Two versions
LINDSEY, M C
O'Connell Consulting Engineers, Inc 00/05/00 10p

0004040096 Advises that application for permit is incomplete. Specific items in application file must be reviewed by statute
Tail mapping, methods & referencing deficiencies represent urgent need for vendor to provide reclamation plan
FRANCIS, E Wagoning, State of 00/05/00 10p

0004120002 Responds to 000404 & 14 letter Authorization to charge production cost fees for public documents. advise state copies have been sent. All judicial review of final NRC actions vested in US Courts of Appeal. Comments solicited
SCARANO, R A Uranium Recovery Licensing Branch 00/05/05 10p

0004030001 Submits trip report re 000406 visit w/ NRC Dept of Western Nevada, D'Appalena Consulting Engineers, Inc & owner to inspect excavation of test pits & visually estimate amount of debris in larger beneath tailings embankment
WELLS, R T Uranium Recovery Licensing Branch 00/05/12 2p

0004090076 Responds to 000318 ltr re impact of contaminants from tailings pond seepage has resulted in some degradation of oxide & adjacent offsite groundwater showing chemical concentrations that exceed drinking water standards
LINDSEY, J J Uranium Recovery Licensing Branch 00/05/10 1p

0004090012 Responds to 000304 ltr re impact of contaminants from tailings pond evaluation indicates seepage has resulted in degradation of oxide & offsite groundwater showing chemical concentrations that exceed drinking water standards
LINDSEY, J J Uranium Recovery Licensing Branch 00/05/12 1p

0004090019 Responds to 000304 ltr re contaminants from existing tailings pond moving underground to groundwater. River bottom monitoring program will be conducted which includes analysis of groundwater wells
LINDSEY, J J Uranium Recovery Licensing Branch 00/05/12 2p

0004090056 Responds to 000401 ltr re mill site. Forward FEE in ref to concerns re surface & groundwater contamination. How stable & offsite wells determined unsafe for drinking. License will be required to submit binding plan w/o and
LINDSEY, J J Uranium Recovery Licensing Branch 00/05/12 2p

0004240005 Forwards 2 Hls 000558 ltr assuring that bonanza areas had been properly cleaned
DOUGLAS, D Western Nuclear, Inc (subs of Phelps Dodge Corp.) 00/05/10 1p

---0004240006 Advises that all equipment bonanza area properly cleaned subsequent to 770402 tailing pond overtopping. Nothing is ever left that could be buried in dirt or could affect site structure
WELLS, R T Western Nuclear, Inc (subs of Phelps Dodge Corp.) 00/05/08 2p

0004240451 Forwards petition to intervene in licensing proceeding REDEAR, J E. Wagoning Outdoor Council 00/03/01 1p

---0004240459 Petition to intervene in licensing proceeding alleging that groundwater adjacent to mill tailings is contaminated in excess of permitted limits. Proposed Hearing
ROBERTS, J S Wagoning Outdoor Council 00/03/01 1p

DOCKETED ITEMS

5

--0006100274 IC Insp Rept 40-0493/D5-01 on 000403 Noncompliance noted Major areas suspected cont activities re raising Nodul Mill tailings dam
GALLIN E Region 4, Dallas, Research Construction & Engineering Support Branch BR04N D B , TAPPA J L Region 4, Dallas, Office of the Director 00/04/25 3pp

0004050509 Requests to 000106 request for administrative amend authorizing 100-FT raise to tailings retention sgs Request cannot be considered as administrative amend due to steps of review Required applicable HMC regulation encl
SCAMMELIN A Uranium Recovery Licensing Branch 00/05/07 1pp

0004050574 Classification conversation w/ Dual re str to Atlas Minerals concerning new raise on tailings structure No plans exist for transporting tailing pile to same site yet to be selected
HEARBY G T Atlas Minerals 00/05/08 1p

DOCKET 40-0237 HANQUETTE UNIV

0004050600 Discussion IC Insp of Licensee 000-201-40-02031-04 & 40-02031-10 on 000423 & 0508 & forwards notice of violation
KEPPLER E D Region 3, Chicago, Office of the Director 00/05/21 3pp

--0004060099 Notice of violation From insp on 000423 & 0508 Noncompliance noted HCL quantities of C-14 & I-131 used w/ performance of licensing & radioactive melt over did not have proper training
* Region 3, Chicago, Office of the Director 00/05/21 3pp

DOCKET 40-0496 FEDERAL AMERICAN PARTNERS (MINING)

0004040320 Submits add comments re OES for proposed facility Draft about assess cumulative effect from all sources at existing mill sites in addition to effect of proposed mill
DANIELSON L J GUYERON H J National Wildlife Federation 00/04/16 3pp

0004050187 Advises that E Kemp will replace T Spies as regulatory agency contact & coordinator
WRIGHT R H Affiliation Unknown 00/05/14 1p

0004060212 Summary of 000414 meeting w/Federal American Partners in Silver Spring, MD re environ reat appl on surface tailings disposal alternatives
GILLON D H Uranium Fuel Licensing Branch 00/05/22 3pp

0004060339 Forwards request for add info to be included in engineering design reat on tailings reat alternatives for 1985 reat
"Rept to Environ Rept - Subsurface Tailings Disposal." is inadequate Partnership reat must be submitted by 000516
LINSINGER J J Uranium Recovery Licensing Branch 00/05/22 3pp

DOCKET 40-5001 AMAX ENVIRONMENTAL SERVICES, INC

0004070411 Forwards summary of 000526 meeting re results of radiological surveys & hydrogeologic data conducted under license 078-140 & 084-1219
O'REILLY J P Region 2, Atlanta, Office of the Director 00/05/29 3pp

DOCKET 40-6622 PATHFINDER MINES CORP

0004070147 Recommendations approval of licensee 701120 request to amend License 000-440 eliminating Condition 28 re drain cover mill amend will not significantly affect environ or dam safety Graduation curves encl
PERSON L S Uranium Recovery Licensing Branch 00/05/28 3pp

DOCKET 40-6659 PETROBRAS CO. BETTY OIL

0004050334 Summary of 000401 meeting w/licensee in Silver Spring, MD re license renewal application Radiological effluent & environ monitoring program encl
NOTTCHER J L Uranium Recovery Licensing Branch 00/05/05 3pp

DOCKET 40-7049 PLATEAU RESEARCH, LTD

0004050302 Requests approval to proceed w/coversing residents from Hydro-wat leaching facility w/ mine waste
HEARBY G J Plateau Research, Ltd 00/05/27 3pp

DOCKET 40-8027 KERR-MCCOY CORP

0004050557 Forwards "Raffinate Program, 1978 Completion Rept." per License 000-1010-0004 & Rept provides results & analysis of growing masses & fund charact of tailing of treated raffinate produced during 1978
BRELLEY W J Kerr-McCoy Nuclear Corp 00/04/13 1p

--0005000665 "Raffinate Fertilizer Program 1979 Completion Rept."
* Kerr-McCoy Nuclear Corp 7/27/71 1p

0004050523 Application for amend of License 000-1010 authorizing unlimited use of treated raffinate produced at Sequoyah facility as fertilizer Justification for proposed amend encl
BRELLEY W J Kerr-McCoy Nuclear Corp 00/05/16 3pp

0004050592 Requests payment of add fee re 000516 application for amend to License 000-1010 Request classified as major safety & environ amend
WELLS J J License Fee Management Branch 00/05/27 1p

0004050534 Advises that major safety & environ amend fee is required for review of 000532 request to permit disposal of raffinate sludge in below grade pit
WELLS J J Licensing Management Branch 00/06/02 1p

0004050626 Forwards OK State Univ 000329 str explaining use of word "preliminary" in hydrogeologic reat generated for vendor raffinate study Client/ass app C of 1979 raffinate fertilizer completion reat submitted to HMC on 000415
BRELLEY W J Kerr-McCoy Nuclear Corp 00/04/02 3pp

0004060445 Forwards "Geologic Macroenvironmental Phase of EL River Below Tashliar Reservoir Adjacent to Effluent Outfall at Sequoyah Facility" Kerr-McCoy Nuclear Corp-Done-Gl-01 1978-Dec 1979
BRELLEY W J Kerr-McCoy Nuclear Corp 00/05/06 1p

--0006000447 "Geologic Macroenvironmental Phase of EL River Below Tashliar Reservoir Adjacent to Effluent Outfall at Sequoyah Facility" Kerr-McCoy Nuclear Corp-Done-Gl-01 1978-Dec 1979
* Kerr-McCoy Nuclear Corp 00/06/03 7pp

DOCKET 40-0032 HETSLU & CO. (UVA)-INC

0004120139 Forwards plan to implement safeguard requirements for 0004 of moderate & low strategic significance
SAMBIT T NISUL & Co. Ltd 00/05/13 3pp

DOCKET 40-0044 EXCON MINERALS CO. USA, EXCON CORP

0004030224 Forwards summary of first quarter 1980 solution mine pilot operations Restoration operations provide primary source of fluids from solution mining activity in tailings pond
TRIMBLE W H Excon Minerals Co. USA 00/04/24 1pp

DOCKET 40-0084 LISSEN HILL, RSC ALCON CORP

0004040187 Application to amend License 00A-119 increasing capacity of tailings dam by raising height of settling lower pond Owen & Moore Fertilizing reat not ext
LANTON R P Rio Algon, Ltd 00/03/20 3pp

DOCKET 40-0102 EXCON MINERALS CO. USA, EXCON CORP

0004030429 Notifies of exposure of individual during w ending 000408, aluminum concentrations of soluble material U in excess of 100PPM 100 1000 HLL drag area washed down w/acidification of subsurface reduction in U concentration
SHANKER J E Excon Minerals Co. USA 00/03/27 3pp

DOCKETED ITEMS

DOCKET 40-0004 WYOMING MINERAL CORP.

0004000403 Summary of 000310-13 meeting w/licenses in Silver Spring, MD re status of ongoing livestock easement into shallow zone. Includes in-leach flow & removal of R&D license. Licensee made commitments for additional actions to amend LINESHW, J. J. Uranium Recovery Licensing Branch 00/04/13 7pp

DOCKET 40-0008 IN SITU URANIUM LEACHING PROJECT

0004000800 Advances that 710004 request permission to commence surface reclamation at test site is being processed as amended to license 000-1220 Requests payment of Category 20 amount for full license amendment classification and L10000 License Fee Management Branch 00/01/01 8pp

--0004000901 Forwards addendum to HC Bost 710024 re: "Synopsis of Research Institute U Leaching Test Activities," providing add'l data re groundwater monitoring. Requests permission to commence surface reclamation CARLOS, P. C. Union Minerals 79/10/06 1p

--0004000902 Addendum to "Synopsis of Research Institute U Leaching Project" entitled "Results of Aquifer Stabilization Observation & Other Surveys" * * * * * Public Exploration Co. Subs of Union Oil Co. of California 79/10/06 3pp

0004100051 Requests info re compliance w/when Chapter 34 regulations re in situ mining by 000300 & advances that add reclamation work as aquifer may be required if water sample analyses are not favorable. EISENHAUER, K. Wyoming State of 00/04/22 1p

DOCKET 40-0025 APAX ENVIRONMENTAL SERVICES, INC.

0004200411 Forwards summary of 000520 meeting re results of radiological surveys & hydrogeological data conducted under License 010-140 & 000-1210 * * * * * O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/29 10pp

DOCKET 40-0030 ROCKY MOUNTAIN ENERGY CO.

0004100244 Requests correction of 000035 amend request Line 4. Paragraph 1, Page 12 of request should read "sampling will be weekly," instead of "daily." Daily sampling of excursion well not necessary. NEUMAN, H. B. Rocky Mountain Energy Co 00/05/06 2pp

0004100430 Forwards add'l sample results from 000403-14 sampling of Potters III monitor wells S-11 H-10 back within baseline range for parameters except U less than 1.2 mg/l H-10 still shows U & vanadium levels above baseline. NEUMAN, H. B. Rocky Mountain Energy Co 00/05/14 6pp

0004200271 Forwards encl to in situ R&D license, per Chapter 33W mining requirements. NEUMAN, H. B. Rocky Mountain Energy Co 00/05/07 3pp

0004100407 Forwards amended application for in situ research testing. License Form should be considered part of original license application submitted in accordance w/State of WY Dept of Energy Public Regulation. HANCKEL, R. C. Rocky Mountain Energy Co 00/04/04 1P

DOCKET 40-0434 HOME STATE MINING CO. LA

0004200504 Forwards overlaid drawings for license renewal application for Beulah Metals License 000-1009, per 000517 notice. SANDOZ, J. W. Homestake Mining Co 00/01/17 3pp

--0004200296 "Flow Diagram Ion Exchange Circuit" * HANLEY, E. Homestake Mining Co 79/12/31 1p

--0004200304 "Proposed Project Site" * HANLEY, E. A. Homestake Mining Co 00/01/31 1p

--0004200310 Exhibits proposed program describing experimental ion exchange plant. Plant will be located at Beulah mine site area previously disturbed by mining activities & within permitted area of ACT/937/009. SANDOZ, J. W. Homestake Mining Co 00/01/16 4pp

DOCKET 40-0492 BEAR CREEK URANIUM CO.

0004200104 Responds to NRC 000500 comments re tailings dam & tailings basin incremental areas requiring compaction work will be sealed & stripped of topsoil. Sufficient clay matrix will be added to compact areas as required permeability. HEDLOCK, R. L. Bear Creek Uranium Co 00/05/19 3pp

0004200708 Requests technical assistance to review proposed dam raise & reclamation plan, per 790314 memo Safety evaluation concerning hydrologic aspects of review should be completed by 000429. BEARMAN, R. A. Uranium Recovery Licensing Branch 00/05/23 1p

DOCKET 40-0493 INDIANAY HILL, WYOMING MINING CORP.

0004000403 Summary of 000310-13 meeting w/licenses in Silver Spring, MD re status of ongoing livestock easement into shallow zone. Includes in-leach flow & removal of R&D license. Licensee made commitments for add'l study & additional to amend L100000 J. J. Uranium Recovery Licensing Branch 00/04/13 7pp

0004000404 Forwards weekly water quality analysis results for shallow monitor & shallow research wells for 000320, 0402 & 08. Piezometric contour map, arsenic & selenium assay results & maps of new shallow research well locations. MICHELS, D. L. Wyoming Mineral Corp. 00/04/16 8pp

--0004000510 "Production Units 1,2,3,4,5 & Research Well Locations, Piezometric Contours" Sheet 1 of 1 * Wyoming Mineral Corp. 00/04/16 1p

--0004000512 "Production Units 1,2,3,4,5 & Research Well Locations" Sheet 1 of 1 * Wyoming Mineral Corp. 00/04/16 1p

0004000509 Forwards alternate livestock restoration progress report for Wolf Field E Field A restoration plan not yet approved by NRC. MICHELS, D. L. Wyoming Mineral Corp. 00/04/24 15pp

0004000515 Expresses concern re recent NRC action concerning U mining site. Licensing of City of Buffalo, WY will suffer severe & immediate setbacks if work at mine is curtailed or terminated. HECHT, E. G., HANCKEL, J. A., HANLEY, G. F. Buffalo, NY 00/04/25 1p

0004000503 Urges NRC to combat regulatory measures which resulted in closing of mining. Many persons besides licensee employees will lose their job/careers. Broadened economic deterioration in surrounding area. OHLAND, R. A. Amstar Excavators 00/04/25 1p

0004000510 Urges NRC to approve regulatory measures that led to closing of mining site. Curtailment of operations will have tremendous adverse impact on local economy. Many persons besides those on rare payroll will lose jobs. ROSS, G. L. Ross Construction Co 00/04/25 1p

0004000510 Opposes closing of mining operations. Closing would be severe loss to Johnson County, WY. COOK, J. H. Affiliation Unknown 00/04/26 1p

0004000507 Forwards info re composition of livestock at site in response to request re 000401 show cause order. Office of the Executive Director for Operations 00/04/28 2pp

0004200570 Notifies State of WY Dept of Environ Quality that closure of In Situ U mine will affect business operations resulting in layoffs. Emphasizes that in-situ operation minimizes effects of mining on environment. LARSEN, D. H., LARSEN, J. C. Affiliation Unknown 00/04/28 1p

0004200504 Responds to request to revise Permit 476 changing livestock to median. Bioreactors. Adverses that proposed change in livestock is conditionally approved. HANCKEL, R. C. Wyoming State of 00/05/04 3pp

0004000403 Forwards biweekly status report of shallow monitor zone. Info includes water quality analysis results, arsenic piezometric & selenium assay results & monitoring data for wells 000-1 & 000-17. MICHELS, D. L. Wyoming Mineral Corp. 00/05/12 10pp

DOCKETED ITEMS

7

0004120143 Forwarded "Renewal of NY Mining Corp to Order to Show Cause"
Requests NRC take prompt action to lift show cause order
TIERRE, R W Wyoming Mineral Corp 00/05/12 1p

--0004120173 Answer to order to show cause Assets that order was
unwarranted No public health safety or other interest
is jeopardized by continued operation Requests NRC take
prompt action to lift order
TIERRE, R W Wyoming Mineral Corp 00/05/12 50pp

0004050244 Forwarded "Irregular Shallow Zone Evaluation Rept - Presents
data to fulfill requirements for lifting immediate
effectiveness of 000401 show cause order
TIERRE, R W Wyoming Mineral Corp 00/05/14 2pp

--0004050440 "Irregular Shallow Zone Evaluation Rept - Overview drawings
only
+ Wyoming Mineral Corp 00/05/14 54pp

0004040947 Forwarded NRC 000401 order to show cause directing shutdown
of facility in response to 000309 ltr No similar action
contemplated for Rocky Mountain Energy Co or Nine Lake
facility
GONNARD, R A Uranium Recovery Licensing Branch 00/05/20 1p

0004100362 Ack receipt of 000509 ltr which approves use of sodium
bicarbonate-based lixiviant at site Use of ammonia-based
lixiviant in all production units will be discontinued &
Permit 478 revised to incorporate change in lixiviant
HICHERM, D W Wyoming Mineral Corp 00/05/22 1p

0004170127 Advances approval of NY Minerals Corp application for
Amend 2 to License BW-1301 authorizing use of sodium
bicarbonate in place of ammonium-bearing lixiviant
KUMPMAN, R A Uranium Recovery Licensing Branch 00/05/23 2pp

0004020564 Confirm 000503 telcon advising that order has been issued
allowing commencement of injection of sodium bicarbonate/
bicarbonate lixiviant into well field at Irregular Shallow
Mining Project Amend 2 to Source Energy License BW-1301 and
GONNARD, R A Uranium Recovery Licensing Branch 00/05/23 1p

--0004020563 Order modifying license & terminating 000421 show cause
order
HARTSH, J B Division of Waste Management 00/05/23 2pp

--0004020570 Amends Source Well License BW-1341 by revising Conditions
10 & 33 Amends authorizes U recovery from max of 80 acres of
well field by in situ solution extraction from U ore bodies
GONNARD, R A Uranium Recovery Licensing Branch 00/05/23 1p

0004020640 Advances of 000523 discussion w/State of NY prior to
issuance of 000523 order to license resumption of operation
is limited to Units 1-3 at present time Unit 4 will be
considered
LINDGREN, J A Uranium Recovery Licensing Branch 00/05/27 1p

0004020611 Concurs w/need of order to allow NY Minerals to resume
operations Use of sodium bicarbonate rather than ammonium
bicarbonate in units authorized Staff has not had chance to
review water quality analysis
ACOSTA, M C Uranium Recovery Licensing Branch 00/05/28 1p

0004020526 Summary of 000507 meeting w/NY Mining Corp in Reilly-HS re
NRC evaluation of vendor analysis of available geologic &
hydrogeologic data
KUMPMAN, R A Uranium Recovery Licensing Branch 00/05/06 2pp

0004020310 Requests water quality analysis on newly drilled shallow
monitor wells & shallow waste monitor wells
HICHERM, D W Wyoming State of 00/06/12 1p

DOCKET 40-0376 EOLSH INTERNATIONAL CO

0004090207 Ack receipt of 000403 ltr informing NRC of steps taken to
correct violations noted in NRC 791204 ltr
GONNARD, R W Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 00/05/20 1p

--0004050408 Responds to NRC 791204 ltr re violations noted during IE
Insp Corrective actions will provide evidence for
Instructions on basis of radiation/mutation protection &
& emergency response Well storage area relocated
HARTSH, J B Eflow International Co 00/04/30 11pp

DOCKET 40-0388 UNION 76 MINERALS EXPLORATION CO

0004040183 Forwarded revised seismic monitoring procedures & fee for
administrative amend to License BW-1330-per 000507
telcon
ACOSTA, A P Union Minerals 00/04/11 3pp

0004020833 Advances NRC that full placement has resumed on Cell C of
subsurface tailings impoundment at U project Revised
tentative data for commencement of tailings cell liner
installation to 000506
ACOSTA, A P Union Minerals 00/04/08 1p

0004180208 Advances that mill start-up date has been scheduled for 000515
per 790208 cover ltr per License BW-1350
ACOSTA, A P Union Minerals 00/03/14 1p

0004070403 Forwarded annual revision or reclamation bond including
mill decommissioning, mill site & tailings dam reclamation
Summary breakdown of costs associated w/reclaiming mill &
tailings area only
ACOSTA, A P Union 76 Minerals Exploration Co 00/04/19 7pp

DOCKET 40-0401 ENERGY FUELS NUCLEAR, INC

0004020505 OFS re operation of White Mesa U Project
w/ Office of Nuclear Material Safety & Safeguards 7/10/03-04/04
7/10/12/01 200pp

0004030608 Advances of 000404 training session in rebus & radon progeny
labeling
KATSE, D O Uranium Recovery Licensing Branch 00/04/01 1p

000410415W Forwarded administrative fee for amend to License BW-1338
CLARKSEN, D C Energy Fuels Nuclear, Inc 00/05/08 2pp

0004180156 Responds to 000509 request to provide written info re
proposal to expand White Mesa U mill Proposal will involve
expanding mill to 3,011-3,511 TPD capacity, w/associated
enlargement of tailings disposal facility
BARKER, C E Energy Fuels Nuclear, Inc 00/05/22 2pp

0004180231 Confirms 000522 telcon stating intent to revise position re
archaeological data recovery program changes at White Mesa U
project Revises letter to form of license amend re testing of
underdrain sites & 1982 completion date
DANER, C E Energy Fuels Nuclear, Inc 00/05/23 2pp

0004020589 Discusses problems re memorandum of agreement concerning
U mill site Problems relate to Energy Fuels Nuclear
interpretation of memorandum & insuring that artifacts are
not transported out of state Related mail sent
DITTMER, T Utah State of 00/05/23 2pp

0004020281 Forwarded IE Insp Rept 40-0381/00-02 re 000303 No
noncompliance noted
GONNARD, R A Region 4, Dallas, Fuel Facility & Materials Safety
Branch 00/05/28 2pp

--0004020285 IE Insp Rept 40-0401/00-02 re 000505 No noncompliance noted
Major areas inspected will be preparation including
organization & administration
HILSH, R L Region 4, Dallas, Office of the Director 000404/0
Region 4, Dallas, Fuel Facility & Materials Safety Branch
00/05/27 2pp

0004020234 Forwarded State of UT 000521 ltr to Energy Fuels Nuclear, Inc
000514 & 07 ltrs re White Mesa archaeological data recovery
Expresses concern re removal of U debris from project
BARKER, C E Energy Fuels Nuclear, Inc 00/05/29 2pp

0004020441 Requests payment of fee associated w/000323 request for
relier from License Conditions 41 & 47 of License BW-1338
Request requires major safety & security fee
HILSH, J D License Fee Management Branch 00/04/06 1p

DOCKET 40-0404 J & P CORP

0004090210 Notifies NRC that no activities have been started under
License BW-1337 Licensee is acquiring baseline data &
studying another potential RAD site NRC will be notified
when test plan & schedule become definitive
BRLINS, D C J & P Corp 00/05/08 1p

DOCKETED ITEMS

DOCKET 40-8693 GULF PETROLEUM, INC.

8004060204 Forwards quarterly report for License GUM-1373 Rept. indicates no leak activities exceeding 6 radiation levels within safe ranges & below working levels
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 1p

--8004060207 "Operational Summary" quarterly report
x Teton Exploration Drilling Co., Inc. 05/04/09 15pp

8004060604 Forwards "Upper Control Limits per Excursion Indicators" -
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 2pp

8004060602 Forwards addl copies of final restoration report for eight phase of project GUM repl.
CATCHELLE, G. G. Gile Petroleum, Inc. 05/05/09 1p

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO.

8004060099 Forwards application to amend License GUM-1328 to allow use of carbonate rather than acid treatment & change procedures associated with use of carbonate treatment
NELSON D. Rocky Mountain Energy Co. 05/04/09 2pp

--8004060093 Application for amend of License GUM-1328 authorizing use of carbonate rather than acid treatment & changing procedures associated with use of carbonate treatment
x Rocky Mountain Energy Co. 05/04/09 42pp

8004060508 Forwards addendum to 760718 application for mining, processing
info required in Chapter 230 WFO and
SMITH, L. E. Rocky Mountain Energy Co. 05/05/09 3p

DOCKET 40-8698 PLACIDUS RESOURCES, LTD.

8004060520 Notifies that Amend 2 to License GUM-1371 was submitted by HRC & is therefore for comment. Amend requires advance notification of certain count milestones for trap purposes
PERKINS, J. LINCOLN, J. Uranium Recovery Licensing Branch 05/05/09 1p

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO.

8004060518 Forwards addl data & amplification of requested changes to License GUM-1332 in response to HRC request. Changes detailed in 800221 submitted do not require license amend & do not increase radiological hazards
LEUBENACK, T. F. Cleveland-Cliffs Iron Co. 05/05/09 12pp

8004060503 Requests amend to Surface Habit License GUM-1332 Amend would change Conditions 10 & 11 Condition 10 to include how addl info transmitted & Condition 11 to permit project site areas of 4/2 acres (and less) for each
LEUBENACK, T. F. Cleveland-Cliffs Iron Co. 05/05/09 3pp

DOCKET 40-8720 STANWOOD COIL CO. OF INDIANA

8004060505 Notifies HRC that groundwater restoration may begin within 30-60 days in Aquifer H at site. Leach solution injection & mining activities will continue in Aquifer D while restoration takes place in Aquifer H
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 1p

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO.

8004060507 Summary of 800425 meeting w/attend in Silver Spring, MD re means of verifying whether hydraulic connection exists between Trap 260000 & Parkman Reservoir at site
SMITH, L. E. Uranium Recovery Licensing Branch 05/05/09 4pp

DOCKET 40-8722 BRUSH-BELMONT, INC.

8004060508 Informs that due to late delivery of components, startup of recovery plant will be delayed from 05/05/09 to 05/05/09
Supplements 800321 to re License GUM-1354 activities
PERKINS, J. Brush-Belmont, Inc. 05/05/09 1p

DOCKET 40-8727 HERR-HORNE NUCLEAR CORP.

8004060544 Forwards License GUM-1378 authorizing vendor to purchase & transfer source & byproduct/mill tail results from minewater U extraction (EIA & safety analysis also sent)
DORRANS, R. A. Uranium Recovery Licensing Branch 05/04/09 1p

--8004060544 License GUM-1378 authorizing vendor to purchase & transfer source & byproduct/mill tail results from minewater U extraction
DORRANS, R. A. Uranium Recovery Licensing Branch 05/04/09 3pp

--8004060549 Guidelines for decontamination of facility & equipment prior to release for unrestricted use or termination of license
for byproduct/mill tail of U
x Uranium Recovery Licensing Branch 05/11/09 5pp

--8004060501 EIA supporting issuance of License GUM-1378 authorizing the exchange plant for U recovery from minewater
MILLER, H. J. Uranium Recovery Licensing Branch 05/04/09 20pp

DOCKET 40-8730 TETON EXPLORATION DRILLING CO., INC.

8004060503 Forwards data in response to R Science 800408 request re North & South Leucatherge reservoir. Items include: current status design specs Review of soil data needed to proceed w/ groundwater restoration
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 19pp

8004060504 Forwards results of consolidated test requested by HRC. Overall concentration at 2.050 w/ under saturated conditions is 55 to 47 compared w/ 35 under ambient moisture conditions
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 4pp

8004060509 Requests use of freeboard analysis for North & South Leucatherge evaporation ponds per 800221 re: "Enhancement info for North & South Leucatherge Reservoirs" - Accumulated re-200 concentration data discussed
NELSON D. Teton Exploration Drilling Co., Inc. 05/04/09 2pp

DOCKET 40-8745 GULF PETROLEUM

8004060518 Clarifies agreement on groundwater issues made w/State of WY Dept of Environ. Quality during 800218 meeting. Criteria apply to casing unit 1 Criteria for other units will be based on Unit 1 results & addl baseline data
PERKINS, J. LINCOLN, J. Uranium Recovery Licensing Branch 05/05/09 4pp

8004060544 Forwards "Brush Basin Project Radiological Safety Program," in support of HRC source mill license application
CATCHELLE, G. G. Gile Petroleum, Inc. 05/05/09 1p

--8004060503 "Brush Basin Project Radiological Safety Program" -
x Gile Petroleum, Inc. 05/05/09 22pp

DOCKET 40-8752 BIRDA FEDERAL & MINING, LTD.

8004060509 Requests opportunity to meet w/HRC re facility license renewal following review of documents sent by A2 HRC HRC would advise of future plans for regulating U activities & legislation that would affect plant
MORLUND, J. M. Radiation & Environmental Monitoring, Inc. 05/05/09 5pp

DOCKET 40-8754 HERR-HORNE NUCLEAR CORP.

8004060505 Notifies of completion of preliminary review of application for source mill license application acceptable for further processing. Assigns docket number & requests addl copies of application
DORRANS, R. A. Uranium Recovery Licensing Branch 05/04/09 1p

DOCKETED ITEMS

9

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 30-3 UNIV. OF MICHIGAN RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

0004002556 Forwards emergency plan for facility
RESN.W Michigan Univ. of 00/04/12 1p

--0004002044 Emergency plan for facility
Michigan Univ. of 7/5/97/30 79pp

DOCKET 30-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

0004002062 Forwards revised Pages 1-14 & new Page 14a for proposed
plan 100750 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790101," transmitted by NRC 000519
11r Page 14a not sent
EISENHUT.D.G. Division of Licensing 00/05/38 79pp

G Adjudicatory correspondence

0004000847 Over granting extension until 000707 for Commission to
select whether to revise ALM-133 & portions of ALM-261
GILL.D.G. Office of the Secretary of the Commission 00/06/16
1p

0004000184 Forwards US 000432 notice to disqualify Commissioner
HEISS.E.S. JORDAN.H.S. Shields, Harman & Meixner 00/04/23 1p

--0004000192 Responds to 790719 11r re utility siting criteria Indian Point
sites meet NRC regulations & criteria Considerable energy
has been expended to secure public health & safety
MEMORIE.J.M. Atomic Energy Commission, Directorate of Licensing
7/3/09/10 0pp

H General correspondence

0004000044 Requests public debate re evacuating large populations near
power plants Opposes plants located in densely populated
areas
HARR.M. Affiliation Unknown 00/02/19 1p

0004000027 Responds to 000319 11r re location of nuclear power plants
in areas of high populations density Every effort is being
made to protect public health & safety at all nuclear power
plants
GENTON.H.H. Office of Nuclear Reactor Regulation, Director
04/04/23 2pp

F Operating license stage documents & correspondence

7911000033 Confirms requirements re condensation oscillation loads
for Mark I containment, long-term program developed at 790015
meeting with 1 owners group Confidentiality declassification test
& plan schedule due by 791001
EISENHUT.D.G. Division of Operating Reactors 79/10/02 49pp

791100140 Forwards "Discussion of TMI Lessons Learned Short-Term
Requirements" Revisions to initial implementation schedule for
NUREG-0070 requirements should be submitted w/ certification
within 30 days if schedule requirements cannot be met
GENTON.H.H. Office of Nuclear Reactor Regulation, Director
79/10/30 0pp

--791100047 "Discussion of TMI Lessons Learned Short-Term Requirements"
Office of Nuclear Reactor Regulation, Director 79/10/30
79pp

0004000103 Forwards add TMI-3 related requirements to operating
reactors Licensee requirements for TMI Action Plan include
staff training, licensing exams & licensee dissemination
of operating experience Response requested within 30 days.
EISENHUT.D.G. Division of Licensing 00/06/07 152pp

0004000132 Requests comments on NUREG-0077, "Handbook for Low Pressure
Toughness & Laminar Flowing on PWR Steam Generator &
Heat Exchanger Pump Support" Proposed review procedure &
implementation schedule sent
EISENHUT.D.G. Division of Licensing 00/08/19 79pp.

0004000404 Forwards slides used by slide during 000432 meeting re
technology exchange in area of mitigation features for
severe accidents at facilities
00088.D. Westinghouse Electric Corp 00/04/03 1p

G Inspection reports, IC Bulletins & correspondence

0004000044 Forwards IC Circular 00-13, "Grid Strip Scraps in
Westinghouse Fuel Assemblies" No written recommendations required
GRIER.H.H. Region 1, Philadelphia, Office of the Director
00/06/20 1p

H Periodic operating reports & related correspondence

0004007040 Forwards data specified in Section 401 Certification for
May 1980 to NY State Dept. of Environ Conservation
HARTI.M.A. Consolidated Edison Co. of New York 00/04/10 1p

--0004000038 Circulating water temp-press electrical output & power water
discharge info for May 1980
Consolidated Edison Co. of New York 00/06/10 10pp

0004000029 Forwards "Quarterly Rep on Seismic Monitoring Network
in Vicinity of Indian Point-NY Consolidated Edison Project-
Dec 1979-Pas 1980"
CARROLL.W. Consolidated Edison Co. of New York 00/06/13 1p

--0004000038 "Quarterly Rep on Seismic Monitoring Network in Vicinity
of Indian Point-NY Consolidated Edison Project-Dec 1979-Pas
1980"
Meadow-Clyde Consultants, Inc 00/05/12 46pp

0004000426 Forwards daily fish counts from intake screens for May 1980
CARROLL.W. Consolidated Edison Co. of New York 00/06/13 1p

--0004000427 Daily fish counts from intake screens for May 1980
Consolidated Edison Co. of New York 00/06/13 1p

DOCKET 20-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

0004000376 Informs NRC that new physical security plan for physical
protection of RRR of low strategic significance will be
submitted by 000001
LEVINE.S.H. Pennsylvania State Univ 00/06/06 1p

DOCKET 50-10 DUKESBORO NUCLEAR POWER STATION, UNIT 1

G NRC Draft/Final Environmental Statements, replies & correspondence

0004000000 Forwards Facility DER re environ considerations under NEPA
re primary cooling sys chemical decontamination NUREG-0068-6
notice of issuance & availability EIS should be prepared
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/05/30 1p

--0004000194 Notice of issuance & availability of Facility DER re
primary cooling sys chemical decontamination NUREG-0068-6
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/05/30 2pp

--0004000198 DER re primary cooling sys chemical decontamination
Office of Nuclear Reactor Regulation, Director NUREG-0068-6
00/05/31 43pp

0004000005 Advice of issuance of DER re primary cooling sys chemical
decontamination
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/05/30 2pp

0004000080 Forwards DER re primary cooling sys chemical
decontamination DER has been sent to EPA & DOE of FR for
publication Requests comments within 45 days of FR
publication
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/05/30 4pp

0004000014 Forwards DER NUREG-0068-6 for proposed primary cooling sys
chemical decontamination FR notice of availability sent LTR
sent to addressees re attached LTR
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/05/30 0pp

0004000070 Forwards notice of availability which is being forwarded to
DOE of FR for publication of DER
CRUTCHFIELD.S.H. Operating Reactors Branch 5 00/06/30 3pp

DOCKETED ITEMS

0006176453 Acl receipt of draft EIR re primary cooling sys chemical decontamination No comment at this time
CUTCHER, H. L. Agricultural Dept of 00/06/10 5p

0006046032 Informer NRC Chas 1020 Region 5 info has reviewed draft EIR re primary cooling sys chemical decontamination & has no comments
CHITCHEL, D. C. Housing & Urban Development, Dept of 00/06/10 1p

0006030410 Advices that review of DCS re primary cooling sys chemical decontamination failed to resolve concerns on prime handout
FITZGERALD, J. Illinois, State of 00/06/10 1p

F Security: medical, emergency & fire protection plans

791040551 Notification of 791030-1100 meeting w/utal in Elen, IL to review emergency plans
SEWAN, R. F. Operating Reactors Branch 3 (Pre 791030) 79/10/20 2pp

0006020205 Refers: Meet new telephone sys called Health Physics Network (HPN) has been installed at site. Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys. Airlines will also be used.
MURPHY, J. D. Region 3, Chicago, Office of the Director 00/06/10 2pp

0006040331 Forwards comment re 790510 substantial of training & qualification plan Response requested within 30 days
Comments withheld (ref 10CFR2 7901)
CRUTCHFIELD, D. Operating Reactors Branch 5 00/03/09 2pp

0006040487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50.46 & App B to 10CFR50.5 is expected to be published in FR by end of May
CRUTCHFIELD, D. G. Division of Licensing 00/05/19 46pp

0006130063 Forwards Insurer Pages 1-14 & new Page 14a for proposed rule 10CFR50.5 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 000510
for Page 14a not encl
CRUTCHFIELD, D. G. Division of Licensing 00/05/20 73pp

0006020427 Requests revision of 000204 subsequent contingency plan in accordance with description described in add to 10CFR50.5
Response requested within 30 days. Encl 10CFR50.5
CRUTCHFIELD, D. G. Operating Reactors Branch 5 00/05/27 2pp

0006100293 Forwards Revision 3 to draft emergency plan Emergency plan Station approval also encl
CRUTCHFIELD, D. G. Commonwealth Edison Co 00/06/04 2pp

—0006100319 Draft emergency plan annex
a Commonwealth Edison Co 00/07/31 41pp

—0006100324 Draft emergency plan annex
a Commonwealth Edison Co 00/07/31 50pp

—0006100333 Draft emergency plan annex
a Commonwealth Edison Co 00/07/31 52pp

—0006100340 Draft emergency plan annex
a Commonwealth Edison Co 00/07/31 37pp

—0006100347 Revision 1 to draft emergency plan
a Commonwealth Edison Co 00/07/31 139pp

0006100551 Provides info re action of NRC & NRC contractor personnel to facilities in connection with partial of station physical
for 10CFR50.5 is scheduled for approx 3 use
beginning 000619 list of authorized NRC personnel encl
MURPHY, J. D. Region 3, Chicago, Office of the Director 00/06/09 4pp

0006040316 Forwards, "Exposed Nuclear Power Station 000619 Emergency Response Plan Exercise" to Illinois Gov. for emergency plan
CRUTCHFIELD, D. G. Commonwealth Edison Co 00/06/10 2pp

—0006042318 "Exposed Nuclear Power Station 000619 Emergency Response Plan Exercise"
a Commonwealth Edison Co 00/06/19 43pp

0006040419 Responds to NRC 000429, 000508, 09 & 20 ltr requesting addl info re guard training & qualification plans Requests that response substantial data be extended to 000524
CRUTCHFIELD, D. G. Commonwealth Edison Co 00/06/10 3p

H General correspondence

0006170481 Forwards copies of advertisements based on info from public. Tenth House that advertisements will gain public support & have some impact on IL Commerce Commission in future rate cases
LEGISLATIVE COUNCIL 00/06/10 5pp

0006030483 Responds to 000409 request that EIR for chemical decontamination be prepared EIR will be prepared
CRUTCHFIELD, D. G. Office of Nuclear Reactor Regulation, Director 00/06/20 1p

—0006030687 Responds to 000328 ltr re facility chemical decontamination Questions re EIR permits will be R 00/06/09 2pp

F Operating license stage documents & correspondence

0006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site. Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys. Airlines will also be used.
MURPHY, J. D. Region 3, Chicago, Office of the Director 00/06/10 2pp

0006030645 Forwards addl TH1-2 related requirements to operating reactors. Licensee requirements for TH1 Action Plan include: (1) ensuring compliance with 10CFR50.5 (2) ensuring dissemination of operating experience Response requested within 30 days
CRUTCHFIELD, D. G. Division of Licensing 00/05/07 150pp

0006020177 Forwards NUREG-0645, Vol 1 & 11 & NUREG-0628 M/A encl
CRUTCHFIELD, D. G. Operating Reactors Branch 5 00/05/16 2pp

0006130122 Requests comments on NUREG-0577, "Potential for Low Pressure Turbines & Corrosion Testing on PWR Steam Generator & Reactor Coolant Pump Systems." Proposed review procedures & implementation schedule encl
CRUTCHFIELD, D. G. Division of Licensing 00/05/19 70pp

0006100495 Forwards response to 000227 memo re facility decontamination "For Comment" issue of DCS will be ready by end of May
CRUTCHFIELD, D. G. Office of Nuclear Reactor Regulation, Director 00/05/29 4pp

—0006120481 Requests short paper on what is being done at facility, what type of approval NRC gave & what negative declaration or written assessment should be performed
MURPHY, J. D. Commission 00/02/27 1p

0006030042 Application to amend License EPR-02, EPR-03, EPR-05, EPR-09 & EPR-20. Clarifying term "separable," submitted as Tech Spec change request in response to NRC 000410 ltr
CRUTCHFIELD, D. G. Commonwealth Edison Co 00/05/30 2pp

—0006030078 Tech Spec change request for Tech Spec Sections 1-0-1, 2-0-1, 3-0-1, 4-0-1 & 5-0-1 re definitions, administrative controls, safety limits, testing safety sys setting & limiting conditions for operation
a Commonwealth Edison Co 00/05/30 40pp

0006100355 Responds to H Fletcher questions re BEB, Topic 18-1, spent fuel storage. Spent fuel storage photo designed to withstand anticipated earthquake loadings on Class 1 structure
CRUTCHFIELD, D. G. Commonwealth Edison Co 00/06/02 2pp

0006100591 Advices that reorganization of Ofc of Nuclear Reactor Regulation became effective on 000604. Project Manager P/O'Connor will coordinate licensing activities for facilities in connection with partial of station physical
for 10CFR50.5 is scheduled for approx 3 use
beginning 000619 list of authorized NRC personnel encl
MURPHY, J. D. Region 3, Chicago, Office of the Director 00/06/09 4pp

0006030404 Ltr to all DRI licensees forwarding "For Comment" edition of NUREG-0645, "Fuel Feedwater, Nozzle & Control Rod Drive Motors Load Nozzle Checking." Comments will be evaluated by NRC prior to final implementation M/A encl
CRUTCHFIELD, D. G. Division of Licensing 00/06/05 22pp

0006100436 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 790800 request
MURPHY, J. D. Commonwealth Edison Co 00/06/11 2pp

DOCKETED ITEMS

11

- 0004200008 Comments re NRC evaluation of WEP Topic XV-20, "Radiological Consequences of Fuel Damage Accidents." Table 20-2 contained typographical error yrs included in peaking factor data should be removed Date is unclear
JAMESON, R F Commonwealth Edison Co 00/06/11 1p
- 0004190037 Forwards commitments to comply w/requirements & schedules in NRC 000307 1tr re add TRU-2 related requirements Dresden Unit 1 is currently undergoing extensive refueling & decontamination therefore no response is provided
MELTZER, D L Commonwealth Edison Co 00/06/12 10pp
- 0004200326 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of GC-100, "Core Seal Program for Nuclear Generating Stations." Revised Revision 11 includes basis on which equivalent education requirements will be established
MELTZER, D L Commonwealth Edison Co 00/06/02 1p
- B Inspection reports, IE Bulletins & correspondence**
- 0004200330 Forwards waste packaging insp rept on 000303-14
No noncompliance noted
STOHL, J P Region 3, Chicago, Office of the Director 00/04/07 2pp
- 0004200341 Waste packaging insp rept on 000303-14 No noncompliance noted Major areas inspected intermodal-shipping vehicles inspected for compliance w/DOE & NRC regulations including shipping papers & DOT placarding requirements
POTTER, J P, SRD&M, R A Region 3, Chicago, Office of the Director & Materials Safety Branch 00/03/20 4pp
- 0004200510 Forwards IE Circular 00-00, "NRC Tech Spec Incompleteness - Reactor Protection Sys Response Time." No written response required
STOHL, J P Region 3, Chicago, Office of the Director 00/04/10 1p
- 0004190500 Forwards IE Insp Repts 90-016/90-07, 90-207/90-07 & 90-249/90-10 on 000303-0404 & notice of violation
MELTZER, D L Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/24 2pp
- 0004190512 Notice of violation from insp on 000303-0404, "Reactor Protection Sys Response Time."
Region 3, Chicago, Office of the Director 00/04/22 1p
- 0004190520 IE Insp Repts 90-016/90-07, 90-207/90-07 & 90-249/90-10 on 000303-0404 Noncompliance noted Failure to follow radiation protection procedures
SABERS, J L, TONGUE, V H, SRD&M, R A Region 3, Chicago, Office of the Director 00/04/22 8pp
- 0004200119 Advises that IE Circular 00-00, "NRC Tech Spec Incompleteness - Reactor Protection Sys Response Time," was sent to listed units on 000410
CARROLL, G E Region 3, Chicago, Office of the Director 00/04/02 8pp
- 0004200018 Forwards IE Insp Rept 90-016/90-08 on 000303-05, 03-13-14, 0405 & 09 & notice of violation
DAVILA, B Region 3, Chicago, Fuel Facility & Materials Safety Branch 00/05/14 2pp
- 0004200320 Notice of violation from insp on 000303-05, 07-13-14, 0405 & 09
Region 3, Chicago, Office of the Director 00/05/04 1p
- 0004200324 IE Insp Rept 90-016/90-08 on 000303-05, 07-13-14, 0405 & 09. Noncompliance noted Failure to make adequate provision to determine compliance w/100CR20 150 & concentrations in excess of Tech Spec limits in discharge canal
TONGUE, V H, Region 3, Chicago, Fuel Facility & Materials Safety Branch PAUL, R A Region 3, Chicago, Office of the Director 00/05/06 7pp
- 0004190336 Addl response to RISA request for all categories of documents re CPC Forwards documents listed in app
FELTZER, D M Division of Rules and Records 00/05/23 3pp
- 0004190099 Forwards response to updated memo received on 000313 re still in interrogatories re proposed imposition of civil penalties
Cover sheet of IE Insp rept addl
MELTZER, D L Region 3, Chicago, Office of the Director 00/03/21 2pp
- 0004190328 RD on 740128 during primary containment leak rate test, excessive leakage was detected passing through 2-inch line in radwaste piping caused by removal of two air operated valves Two-inch line was repaired
MORDELL, M P Commonwealth Edison Co 74/02/28, 2pp
- 0004190141 Except of IE Insp Rept 90-016/90-01 conducted on 740128 & 30 noncompliance noted open 2-inch line violated containment integrity for two dual cycles & no RPT was submitted re containment testable penetration
HAGLER, F, DANCE, H C Atomic Energy Commission 74/02/20 4pp
- 0004190142 Respond to AEC 740228 1tr re leakage in 2-inch line penetrating primary containment Emergency procedures have been revised to require closing motor-operated isolation valves after freshwater injection is terminated
LEE, B Commonwealth Edison Co 74/02/20 3pp
- 0004200037 Review that IE Circular 00-13, "Grid Stray Damage in Steamgenerator Fuel Assemblies," was sent to listed units on 000328
PAPPAS, R Region 3, Chicago, Office of the Director 00/05/30 2pp
- 0004190558 Forwards response to IE Bulletin 00-04, "Engineered Safety Features (ESF) Reactor Controls." Proposed notes identified only if present sys design may comprise protective action of equipment
MELTZER, D L Commonwealth Edison Co 00/04/10 9pp
- B Periodic operating reports & related correspondence**
- 0004190120 Forwards monthly operating rept for Apr 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/03/12 1p
- 0004190122 Monthly operating rept for Apr 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/03/08 20pp
- 0004190448 Forwards monthly operating rept for May 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/04/09 1p
- 0004190452 Monthly operating rept for May 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/04/02 4pp
- 0004190457 Monthly operating rept for May 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/04/02 4pp
- 0004190461 Monthly operating rept for May 1990
STOHL, J P Region 3, Chicago, Office of the Director 00/04/02 4pp
- DOCKET 90-18 VALUATION DOILING WATER REACTOR**
- J Insurance & Indemnity Information
- 0004190199 Forwards Enforcement 113 to AEC Policy 90-1, "CORRECTION: A Reactor & Fuel Element Inc. & NRC Nuclear Consultants, Inc. 1tr 00/04/10 2pp
- DOCKET 90-30 HANSHAWSETT INVT OF RECH REB REACTOR
- F Security, medical, emergency & fire protection plans**
- 0004200290 Forwards table listing all licenses authorizing 99% form, location, type of mtg, authorized amounts & 000031 inventory
Table withheld (ref 100FR 290)
CLARK, L Massachusetts Institute of Technology 00/06/23 1p
- F Operating license stage documents & correspondence**
- 0004200292 Forwards table listing all licenses authorizing 99% form, location, type of mtg, authorized amounts & 000031 inventory
Table withheld (ref 100FR 290)
CLARK, L Massachusetts Institute of Technology 00/06/23 1p
- G Repairable occurrences, LERs & related correspondence**
- 0004200408 RD 90-30/90-02 on 000319, intermittent tripping of shim blade number 1 not in accordance w/Tech Specs Covered by Foreign mtg. Inspecting action Electromagnet containing foreign metal repaired & other blades checked
GILMAN, J, CLARK, L Massachusetts Institute of Technology 00/05/22 4pp
- 0004200004 Forwards revised Page 2 of RD 90-30/90-02 and 000323, Reviser corrects second paragraph of Section 7 re frequency of blade thickness measurements & clarifies description of electromagnetic coupling of blade
MORDELL, J, CLARK, L Massachusetts Institute of Technology 00/05/27 2pp

DOCKETED ITEMS

0006226051 Forwards revised Page 2 to RD 50-20/80-2
BERNARD, J. CLARK, L. Massachusetts Institute of T
80/05/27 to

--008A203062 Revised Page 2 to NO 50-28/60-2 correcting second paragraph of Section 7 to read "routinely measured every 4 months" =
* Massachusetts Institute of Technology NO/08/27 is

SECRET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

Operating license stage documents & correspondence

SECRET SO-29 YANKEE-1000 NUCLEAR POWER STATION

[illegible]

93560924M7 Forwarded proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 196105 - Rule adds new Section 30.40 & App B to 19CFR55 & is expected to be published in FR by end of May
EIM360UJ.D @ Division of Licenses 80/05/19 46pp

0956130603 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 750101." Transmitted by NRC 000319 14c Page 14a not encl
EISN6047, b 0 Division of Licensing 00/03/22 73pg

20040303028 Webbs revised commitments & schedule for mod of suppression sys Add engineering requirements & potential long delivery time for add components necessitate change in site construction fire detectors to be implemented 03/10/04
R0000, D E Yankee Atomic Electric Co 03/03/07 4/p

8002930536 Forwards revised responsibility matrix for a security plan brief withheld (ref ID: A67770)
HOOBY, D E. Yankee Atomic Electric Co. 80/04/16 3pg

* Operating license stage documents & correspondence

8036698265 Forwards add TH1-2 related requirements to operating reactor Licensees requirements for TH1 Action Plan include shift training, licensing exams & license dissemination of operating experience Response requested within 30 days
EIS@NRC.D.O. Division of Licensing 80/08/07 150pp

6036250157 Fenwick, RUSCO-0604, Vol 1 5, 11 & RUSCO-0618 M/o emc
CAUTECFIELD, D. Operating Reactors Branch 5 26/05/16 Zps

0046130122 Request comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports - Proposed review procedure & implementation schedule etc"

0004000167 Provides current status of program to evaluate
Terminating efforts relative to installation of LOCA
restraints due to issuance of Westinghouse owners pro-
"Asymetric LOCA Loads Evaluation Rept"
MAY, J A Yankee Atomic Electric Co 80/05/28 2pg

0036190090 Advises that reorganization of Div of Nuclear Reactor Regulation became effective on 003440 Project manager A Berger will coordinate licensing activities for Facility Reorganization described in encl

GRUOTFIELD D Operating Reactors Branch 5 06/04/02 0501

B096070280 Submits evaluation of instrumentation for detection of inadequate core tooling, in accordance w/TE Category "A" Item 2 & 3 Installation of further instrumentation not planned

RH/TH/L L Yenkee Abniet Electric Co B0/06/04 400

enter equipment list & "Yukon River Containment
Team Live Sulfur Inside Containment" re
on of electrical equipment Analysis #
06 will be completed by Sept & Oct 1990
See Atomic Electric Co 03/05/03 Zips

Reese Containment Analysis for Main Steam Line
 shutdown =
 Electric Co 80/86/90 4248.

000470006 Forwards Implementation schedule & summary status
commitments in response to HQ 000307 ltr re addl
requirements from The Action Plan
HSE/D E Nether Atomic Electric Co 06/06/19 app

© 2005 Blackwell Publishing Ltd, *JE Guidelines* 4, correspondence

800618C054 February 18 Insp Rept SO-029/80-03 re 830215-29 No
noncompliance noted
800608E J Region 3: Philadelphia, Reaction Operations Section
Support Branch 00/04/29 Zpp

--0006180057 IF 1444 Regt 50-029/MO-03 on 002215-1F No noncompliance noted Major areas inspected circumstances surrounding failure of low pressure turbine
MARTIN T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch /OLEY T Region 1, Philadelphia, Office of the Director 00/04/25 Gpp

BO56030103 Forwarded RE Hgt Meeting Rept 50-049/50-04 on 000227
 004960R-E J Region I, Philadelphia, Reactor Operations Notice
 Support Branch 05/05/01 1a

--8006030110 IE Mtg Meeting Rept 90-029/80-04, Areas discussed details
re establishment of onsite SFC for purpose of placing full-
time NRC Inspector at Facility
FOLEY, T, HEDGECOCK, J J Region 1, Philadelphia, Office of the
Director MARTIN, T T Region 1, Philadelphia, Reactor Operations
Northern District Branch, 80004/029 See

6006250164 Forwards 1E loop Rept 50-029/50-07 on 000317-24 Re
noncompliance noted
STUNNED, E J Region I, Philadelphia, Reactor Operations Nuclear
Support Branch 80/05/06 Doc

--B002950148 JK Insp Regt 50-029/80-07 re 000217-24 Re noncompliance
retd Major areas inspected emergency procedures for small
break LOCATIONS & monthly operating regts
NHTB: T Region 1, Philadelphia, Weather Operations Nuclear
Support Branch FOLBY, T, RAYMOND, H J Region 1, Philadelphia
Office of the Director 80/05/05 HJC

0006060503 Forward "Main Steam Line Rupture Analyses For Yankee Reactor"
in response to IE Bulletin 88-04 Overall conservatism of
design to main steam line ruptures has not been tested
Second level review underway
0006060503 D E Yankee Atomic Electric Co. 88/05/03 2pg

```
--S00a06050a "Main Steam Line Rupture Analysis for Yankee Bows"
  * Yankee Atomic Electric Co. NRC 80/03vD1 2/79
```

8D04245940 Submits addl info re IE Bulletin 79-39. "Packaging Low Level Radwaste For Transport & Disposal." Training program being revised to insure that training committed to in atal 790925 ltr to NRC will be provided.
H000Y.D E Varney Atomic Electric Co. 80/03/27 Sps

0006200033 Forwarded IE Circular 80-13, "Cold Start Damage in
Westinghouse Fuel Assemblies - No written response required
OTHER: R N Region I, Philadelphia. Office of the Director
80/05/28 tp

00060502883 informs that util is in process of addressing IE Bulletin 77-03A Response has requested diversion of engineering resources from identified safety issues
HELDER, L H Yankee Atomic Electric Co 00/06/93 Rco

605680467 Discussion of Bulletin 79-034, "Longitudinal Weld Defects in ASME SA-502 Type D04 Stainless Steel Pipe" Bulletin describes minor design deficiencies, rather than generic problems.
HESSER, L. W. Nanke Atomic Electric Co. 80/05/29 200

R. Petraitis covering reports & related correspondence

8006170636 Forwards monthly operating rept for May 1980
H000V-D E Yankee Atomic Electric Co 80/06/12 1a

--0006170630 Monthly operating repl for May 1960
DEERS, F C Yankee Atomic Electric Co 00/06/62 See

B. Reportable occurrences, LERs & related correspondence

8906160006 Advise that LOR 80-29/89-05 was not used for 1990
PCSKING, M A Region I, Philadelphia, Office of the Director
80/04/10 is

DOCKETED ITEMS

13

DOCKET NO-30 FLINT BROOK RESEARCH REACTOR FACILITY

DOCKETED000303 Notification of 800417 meeting of NRC/MSA Lewis Research Ctr in Bethesda, MD to discuss NRC/MSA application for authorization to dismantle Flint Brook test reactor & reactor reactor
NRC/MSA/MSA - Operating Reactors Branch 4 80/04/12 App

DOCKET NO-54 UNION CARBIDE RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

DOCKETED00095 Forwards combined IE Investigation Reports 80-094/80-01 80-044/80-01 80-003/80-01 80-007/80-01 80-007/80-01
NRC has prepared civil penalties to Union Carbide, Smith
Kline & French Labs Respective states & 350 notified
80/04/18 App

DOCKETED00095 IE Combined Investigation Reports 80-094/80-01 80-044/80-01 80-003/80-01 80-007/80-01 80-007/80-01
NRC has prepared civil penalties to Union Carbide, Smith
Kline & French Labs Respective states & 350 notified
80/04/18 App

DOCKETED00095 Forwards IE Insp Rept 80-054/80-02 on 800414-17 No
noncompliance noted
HARTIN, W D Region 1, Philadelphia, Safeguards Branch 80/05/14 App

DOCKETED000468 IE Insp Rept 80-054/80-02 on 800414-17 No noncompliance
noted Major areas inspected security plan/protection of
DRM existing organization address control, alarm sys, keys &
locks details withheld (ref 800412 798)
DEVIL, J H Region 1, Philadelphia, Safeguards Branch
80/05/13 App

B Reportable occurrences, IRRs & related correspondence

DOCKETED000282 RD on 800503, rad was discovered separated from rad drive &
remained fully in core Reactor was immediately shut down
Routine Insp of present rod until continue of normal
attention to similar type of rod failures
HARTIN, W D Union Carbide Corp 80/05/15 App

DOCKET NO-70 GENERAL ELECTRIC TEST REACTOR

Q Adequacy correspondence

DOCKETED000450 Forwards notice of appearance & Certificate of Dnt vs show
cause order per GSTR
HARTIN, W D House of Rep 80/04/12 App

DOCKETED000450 Notice of appearance vs show cause order per GSTR
Certificate of Dnt vs
HARTIN, W D House of Rep 80/04/12 App

J Insurance & indemnity information

DOCKETED000450 Forwards Endorsement 24 to HARTIN, W D
GORE, H A Bank & Lehman, Inc. R & H Nuclear Consultants, Inc
80/04/20 App

D Advisory Committee on Reactor Safeguards reports & correspondence

DOCKETED00011 Summary of ACRS Subcommittee on GSTR 79114 meeting in
Burlington, CA vs geologic & seismologic aspects of GSTR
NRC - ACRS - Advisory Committee on Reactor Safeguards 80/04/15 App

DOCKETED00002 Discusses recommendation for add subcommittee investigations
at & beneath GSTR Payson can to establish feasibility of
isolating GSTR from foundation disturbance in event of
earthquake
PHILLIPS, D G Phillips, D G 80/05/02 App

DOCKETED00011 Notice of ACRS Subcommittee on GSTR 800414-17 meeting in
Dnt, CA to review geologic, seismologic & structural
engineering aspects of plant site
HARTIN, W D Office of the Secretary of the Commission 80/05/22 App

P Operating license stage documents & correspondence

DOCKETED000450 Forwards NRC safety evaluation vs proper geologic & seismic
design bases per GSTR
HARTIN, W D Division of Licensing 80/05/22 App

DOCKETED000450 Safety evaluation vs geologic & seismic design bases for
facility including NRC 79087 report stating that surface
effect of 2 to 3 meters could occur beneath GSTR Surface effect
of one meter beneath facility in appropriate design basis
NRC - Office of Nuclear Reactor Regulation, Director 80/05/22 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

DOCKETED000457 Forwards USGS 000450 11r to NRC & USGS repts, "Faults of
GSTR Test Reactor Site, Vallecitos Nuclear Ctr, Pleasanton,
CA", "Seismicity of Livermore Valley, CA Region, 1969-79" &
"Surface Faulting Near Livermore, CA"
HARTIN, W D Interior, Dept. of, Geological Survey 80/04/20 App

T Hearing transcripts on non-antitrust matters

DOCKETED00011 Transcript of ACRS Nuclear Safety Subcommittee 800414
meeting in Dnt, CA in matter of GSTR show cause order
Per 1-254
NRC - Advisory Committee on Reactor Safeguards 80/04/14 App

DOCKETED00011 Transcript of ACRS Subcommittee on GSTR 800417 meeting in
Dnt, CA Per 227-507 Hearing 800417
NRC - Advisory Committee on Reactor Safeguards 80/04/17 App

DOCKET NO-79 GENERAL ELECTRIC NUCLEAR TEST REACTOR

Q Inspection reports, IE Bulletins & correspondence

DOCKETED000450 Forwards IE Insp Rept 80-073/80-01 on 800025, 80-08 & 0303 RD
noncompliance noted
HARTIN, W D San Francisco, Fuel Facility & Materials Safety
Branch 80/05/08 App

DOCKETED ITEMS

--8004090912 IE Insp Rept 50-073/80-01 on 800285.26.28 & 0700 No noncompliance noted Region 2 areas inspected emergency planning, radiation safety, procedures, personnel exposure, instruments & test of facilities
BEGGS, R. E., NRC/ASDR, P. A., P.280, R. 5, San Francisco, Office of the Director 80/07/02 3pp

SECRET 50-083 SMIV OF FLORIDA TRAINING REACTOR

Q Inspection reports, IE Evaluation & correspondence

8004090919 A-1 receipt of 800507 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-083/80-01
LENN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/21 1p

--8004090940 Responds to NRC 800807 ltr re violations noted in IE Insp Rept 50-083/80-01 Corrective actions Tech Space changed, daily check changed to incorporate restricted testing of off-normal interlock
DIAZ, H. J. Florida, Univ. of Tennessee 80/05/07 2pp

--8004091491 forwards IE Insp Rept 50-083/80-01 on 800317-02 & notice of violation
LENN, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/09 2pp

--8004091494 Notice of violation from Insp on 800317-02
Region 2, Atlanta, Office of the Director 80/04/09 1p

--8004091505 IE Insp Rept 50-083/80-01 on 800317-20 Noncompliance noted failure to perform required safety walk checks prior to startup
MELLOS, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/09 4pp

B Reportable occurrences, LERs & related correspondence

8004090945 IO during wk of 800501-06 surface contamination monitoring was performed Operator in charge was assigned to work at another facility No procedures exist for assigning responsibility Procedures have been revised
BEGGS, R. E., Florida, Univ. of Tennessee 80/05/22 1p

8004090946 Forwards Univ. of FL re: failed temp control thermocouple on Varian electron capture unit failure led to contamination of lab & exposure of personnel to tritium
BEGGS, R. E. Assigned Director for State Agreements Program 80/05/03 3pp

SECRET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

8004100470 Forwards dismantling plan re R-3 IO SN reactor, in response to NRC request
BEGGS, R. E., THORNTON, J. L. North Carolina State Univ 80/04/05 2pp

--8004100480 Dismantling plan re facility
North Carolina State Univ 80/03/15 2pp

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Evaluation & correspondence

8004100291 Forwards IE Insp Rept 50-116/80-01 on 800518-14 No noncompliance noted
DAVIS, B. A. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/04 2pp

--8004100298 IE Insp Rept 50-116/80-01 on 800313-14 No noncompliance noted Major areas inspected emergency planning implementation procedures, coordination w/support agencies & monitoring equipment
BEGGS, R. E., CHICAGO, P. J. Region 3, Chicago, Office of the Director 80/06/04 3pp

DOCKET 50-130 TEXAS A&M UNIV RESEARCH REACTOR

Q Inspection reports, IE Evaluation & correspondence

8004090927 Ack receipt of 800414 ltr in response to NRC 800405 ltr & action of violation Requests add ltr to properly evaluate adequacy of corrective action, including corrective steps taken, results & steps taken to avoid further violations
MORRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/05/15 2pp

--8004090934 Responds to item of noncompliance noted in IE Insp Rept 50-128/80-01 Corrective actions SOP Book Surveillance Record has been placed in front of Ops 1 of each set of SOPs for documentation of SOP book surveillance items 50 and 2800, R. E. Texas A & M Univ 80/04/14 4pp

8004090943 Ack receipt of 800414 & 8002 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-128/80-01
MORRIS, D. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/05/03 1p

--8004090952 Responds to NRC 800918 ltr re violations noted in IE Insp Rept 50-128/80-01 Corrective actions redundant SOP book will not be returned to control room
MORRIS, D. L. Texas A & M Univ 80/05/23 2pp

B Reportable occurrences, LERs & related correspondence

8004090948 IO on 800501, secondary cooling tower fan discovered to have disintegrated causing damage to cooling tower & resulting in loss of secondary cooling capacity Caused by failure of Fan Transmission Mounting Temporary fan assembly installed
MELT, D. R. Texas A & M Univ 80/05/03 3pp

DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

8004090941 Application to amend License R-88 Amend allow for A-month extension of license to permit transfer of fuel & components of reactor
BLANK, S. T., KERR, J. W. West Virginia Univ 80/05/24 1p

DOCKET 50-133 HUMBOLDT BAY PLANT UNIT 2

F Security, medical, emergency & fire protection plans

8004090975 Notifies that FEMA/NRC Steering Committee has reconsidered appropriate size of emergency planning zones for small water cooled power reactors Steering Committee has accepted and position on planning basis for reactors
TREVINO, T. A. Operating Reactors Branch 2 80/05/14 2pp

8004090987 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule order was Section 50.48 & 50.49 to 10CFR50 & is expected to be published in FR by end of May
EISENHUT, D. Division of Licensing 80/05/19 4pp

8004100505 Forwards Revised Pages 1-14 & New Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not sent
EISENHUT, D. Division of Licensing 80/05/22 7pp

8004100517 Requests participation in study of problem-related problems in nuclear representation NRC representatives will visit facility & interview security dept personnel
TREVINO, T. A. Operating Reactors Branch 2 80/05/03 2pp

B Adjudicatory correspondence

8004100547 Forwards Intervenor proposed time schedule for further proceedings & historical summary leading to present status of plant
EISENHUT, D. Jones, Brown & Clifford 80/04/06 2pp

--8004100549 Proposed time schedule for further proceedings 800401-0930 for consultant data re seismic & geologic studies, 800501 for NRC & intervenor statements & 800501 for F&E conclusions w/certificate of Rev & historical summary
EISENHUT, D. Jones, Brown & Clifford 80/04/06 2pp

DOCKETED ITEMS

15

00046200372 Order re AOS 800403 prehearing conference in Eureka, CA. Licensee motion to hold DL amend proceeding in abeyance until 800501 granted unless intervenors are directed by file conventions 48 days after receipt of consultant report. LADN R. H. Atomic Safety and Licensing Board Panel 80/04/17 App

P. Operating license stage documents & correspondence

00046200148 Forwards addl TMS-2 related requirements to operating reactor licensees requirements for the Action Plan including safety monitoring, licensing status & licensee identification of operating experience responses requested within 30 days. EDO04UT, D. O. Division of Licensing 80/05/07 13pp

80046200192 Requests comments on 800403-0077, "Potential for Low Pressure Turbine & Ladder Towering" from Steam Generator & Reactor Coolant Pump Support. Proposed review procedure & implementation schedule encl. EDO04UT, D. O. Division of Licensing 80/05/19 7pp

80046200044 Ltr to all NWR licensees forwarding "For Comment" edition of 800403-0017, "SWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking". Comments will be evaluated by NRC prior to final implementation N/A encl. EDO04UT, D. O. Division of Licensing 80/05/03 2pp

D. Inspection reports, IE Bulletin & correspondence

80046200146 Forwards IE Circular 80-09, "SWR Tech Spec Incompleteness - Reactor Protection Sys Response Time". No written response required. EDO04UT, D. O. Division of Licensing 80/05/19 1p

80046200082 Forwards IE Circular 80-15, "Grid Strap Damage in Wilmington Fuel Assemblies". No written response required. EDO04UT, D. O. Division of Licensing 80/05/28 1p

R. Periodic operating reports & related correspondence

80046200022 Forwards monthly operating report for May 1980. WE04R, R. H. Pacific Gas & Electric Co. 80/05/04 1p

--00046200022 Monthly operating report for May 1980. WE04R, R. H. Pacific Gas & Electric Co. 80/05/03 App

Y. Hearing transcripts on non-amendment matters

80046200251 Transcript of 800403 prehearing conference in Eureka, CA. Pg 1-189. Committee 80/05/03 190pp

DOCKET 80-141 STANFORD UNIV. RESEARCH REACTOR

80046200102 Submits info re Univ application to terminate reactor facility license RMO & release site for unrestricted use. HED04R, R. H. Stanford Univ. 80/05/03 App

DOCKET 80-142 UCLA TRAINING REACTOR

0. Adjudicatory correspondence

80046200028 Notice of establishment of AOS 80 to provide in proceeding on petitions to intervene NWR requests for hearing & to provide over proceeding in event that hearing is ordered. LADN R. H. Atomic Safety and Licensing Board Panel 80/05/10 2pp

80046200282 Response to Campus Committee to Bridge the Gap 800402 petition to intervene. Petitioner seeks to amend & amend requirements & should be added as per 80/05/03 intervention requirement is satisfied. M/Certificate of Rev. GRAY, J. H. Hearing Branch 1 80/05/01 14pp

80046200117 Application for extension until 800707 for Regents of Univ. of CA to respond to Committee to Bridge the Gap 800402 petition to intervene. Petition was not received until 800601 declaration of mail was encl. HEL04R, R. H. Stanford Univ. of Berkeley 80/05/12 1pp

80046200271 Forwards Regents of Univ. of CA 800402 application for extension of time to answer petition to intervene. States no objection to requested extension N/A encl. GRAY, J. H. Hearing Branch 1, 80/05/04 1p

80046200430 Order granting extension until 800708 for licensee to respond to Campus Committee to Bridge the Gap petition to intervene re proposed renewal of license. DOW04R, R. H. Atomic Safety and Licensing Board Panel 80/05/18 1p

80046200204 Forwards NRC 800403 response to Committee to Bridge the Gap petition to intervene in proposed renewal of license. NRC 800403 has been updated to include all AOS 800403 N/A encl. GRAY, J. H. Hearing Branch 1 80/05/24 1p

S. Inspection reports, IE Bulletin & correspondence

80046200309 Forwards IE Insp Rpt 80-142/80-02 on 800404 & 8004-14 of notice of violation. CROW, J. L. Region 3, San Francisco. Reactor Operations Nuclear Support Branch 80/05/07 2pp

--00046200371 Notice of violation from Insp on 800404 & 8004-14. Region 3, San Francisco. Office of the Director 80/05/06 1p

--00046200378 IE Insp Rpt 80-142/80-02 on 800404 & 8004-14 Noncompliance noted regarding by operators & review by supervisors. Personnel needs improvement & neutron thermal detector exceeded Tech Spec requirement. STE04R, R. H. Region 3, San Francisco. Office of the Director 80/05/06 1pp

DOCKET 80-147 ROCKWELL INTL. CORP. CRITICAL FACILITY

D. Inspection reports, IE Bulletin & correspondence

80046200018 Requests closure Insp for license 800403 request to terminate license CO-17 Insp necessary to confirm radiation survey results. DOW, T. H. Assistant Director for Operating Reactors 80/05/13 1pp

DOCKET 80-150 SHED STATE UNIV. RESEARCH REACTOR

D. Inspection reports, IE Bulletin & correspondence

80046200102 Forwards IE Insp Rpt 80-150/80-02 on 800404-17 No noncompliance noted. HE04R, R. H. Region 3, Chicago. Reactor Operations Nuclear Support Branch 80/05/08 2pp

--00046200113 IE Insp Rpt 80-150/80-02 on 800404-17 No noncompliance noted. Major areas inspected: logs & records, reactor surveillance, qualification training & reviews & audits. DOW, T. H. Region 3, Chicago. Office of the Director 80/05/07 2pp

DOCKET 80-155 SHED STATE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

80046200134 Forwards comments & discussion re 790502 submittal of guard training plan. Request requested within 30 days. Comments & discussion withheld (ref 100402 7901). SHED, R. H. Operating Reactors Branch 80/05/15 2pp

80046200087 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule sets new Section 50.4B & App B to 10CFR50 & is expected to be published in FR by end of May. EDO04UT, D. O. Division of Licensing 80/05/19 4pp

80046200014 Requests that revised pages for safeguards contingency plan. Revision 1, bearing appropriate revision number & date per encl comments be submitted within 30 days of receipt of ltr. Encl withheld (ref 100402 7901). SHED, R. H. Operating Reactors Branch 80/05/20 2pp

80046200062 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Transmitted by NRC 800403 ltr Page 14a not encl. EDO04UT, D. O. Division of Licensing 80/05/22 7pp

S. Adjudicatory correspondence

80046200208 Responses to licensee first set of interrogatories. Identifies documents planned to be used in support of case. Forwarding ltr encl. STE04R, R. H. Affiliation Unknown 80/05/28 4pp

0006170706 Informs NRC of current plans re design deficiency concerning partial closure of ventilation isolation valves. Plans differ from those submitted as LDR 79-04 & 80-23 on 7/1/80 & 8/10/82 respectively
HQP/PAW, D P Consumers Power Co 00/06/13 3pp

0006170707 Informs NRC of mod re using check valve operations to assure operability. Precautions & procedures will be implemented to reduce possibility of vacuum within containment. Public health & safety will not be jeopardized
HQP/PAW, D P Consumers Power Co 00/06/13 2pp

DOCKET 90-107 CORNELL UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

0006160406 Application to renew License R-60 For 20 yrs. Current license expires 000629. License will forward complete application demonstrating that facility responds & ops can be safely operated over renewal period
CORNELL, D Cornell Univ 00/06/27 1p

DOCKET 90-160 GEORGIA INST OF TECH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

0006160421 Requests extension until 000629 to complete necessary changes for submittal of amended security plan. Implementation of plan would be accomplished within 30 days following NRC approval
RUSSELL, J L Georgia Institute of Technology 00/06/27 1p

0006160424 Forwards proposed technical entering plan. Plan submitted (ref 000612 700)
KIRSLAND, R B Georgia Institute of Technology 00/06/23 1p

B Reportable occurrences, LDRs & related correspondence

0006161018 Re an 000610 heavy-metal trap recorder TPA-85 was not recalled after replacement of worn sliding contacts to prevent select switch. Cause has related importance of recall emphasized to personnel
KIRSLAND, R B Georgia Institute of Technology 00/06/23 3pp

DOCKET 90-166 UNIV OF MARYLAND RESEARCH REACTOR

C Utility Environmental Report (EDR), amendments & correspondence

0006161020 CIA supporting renewal of CL
Maryland, Univ of 00/06/30 14pp

F Security, medical, emergency & fire protection plans

0006161032 Emergency plan
Maryland, Univ of 00/06/30 60pp

K Utility Final Safety Analysis Report (FSAR) & amendments

0006161014 FEAR for MD Univ Training Reactor
Maryland, Univ of 00/05/11 800pp

0006161014 Chapter 1 of MD Univ Training Reactor FEAR: "Introduction & General Description of Facility"
Maryland, Univ of 00/06/11 12pp

0006161080 Chapter 2 of MD Univ Training Reactor FEAR: "Site Characterization"
Maryland, Univ of 00/06/11 14pp

0006161016 Chapter 3 of MD Univ Training Reactor FEAR: "Reactor Facility"
Maryland, Univ of 00/06/11 15pp

0006161016 Chapter 4 of MD Univ Training Reactor FEAR: "Reactor"
Maryland, Univ of 00/06/11 46pp

0006161017 Chapter 5 of MD Univ Training Reactor FEAR: "Reactor Coolant & Purification Sys"
Maryland, Univ of 00/06/11 10pp

0006161020 Chapter 6 of MD Univ Training Reactor FEAR: "Experimental Facilities"
Maryland, Univ of 00/06/11 12pp

0006161027 Chapter 7 of MD Univ Training Reactor FEAR: "Instrumentation & Control"
Maryland, Univ of 00/06/11 5pp

0006161012 Chapter 8 of MD Univ Training Reactor FEAR: "Auxiliary Equipment"
Maryland, Univ of 00/06/11 11pp

0006161013 Chapter 9 of MD Univ Training Reactor FEAR: "Waste Rpt"
Maryland, Univ of 00/06/11 4pp

0006161014 Chapter 10 of MD Univ Training Reactor FEAR: "Conduct of Operation"
Maryland, Univ of 00/06/11 19pp

0006161018 Chapter 11 of MD Univ Training Reactor FEAR: "Safety Analysis"
Maryland, Univ of 00/06/11 14pp

P Operating license stage documents & correspondence

0006161019 Tech Specs for facility
Maryland, Univ of 00/06/20 5pp

V Operator Examinations

0006161019 MD Univ Training Reactor Refueling Program
Maryland, Univ of 00/06/20 12pp

DOCKET 90-175 NATIONAL NUCLEAR MEDICAL CENTER

P Operating license stage documents & correspondence

0006160923 Forwards comments & suggested changes to Tech Specs. MILLER, J R Standardization & Special Projects Branch 00/05/12 2pp

DOCKET 90-176 PEACH BOTTOM ATOMIC POWER PLANT, UNIT 1

II General correspondence

0006170909 Discusses 000430 ltr to NRC expressing concern re arrangements for recent meeting at plant. Meetings between NRC & licensee are open to public in most cases. Public announcement was issued on 000501 well before meeting date. DENTON, H R Office of Nuclear Reactor Regulation, Director 00/05/30 14pp

--0006170909 Provides statement for use of NRC review teams during public meetings while making site visits to assess emergency preparedness measures. On 7/1/87, President directed FEMA to keep lead in office emergency planning & plan assessment. CAMP, P A Federal Emergency Management Agency 00/05/07 1p

0006170134 Responds to 000505 & 58 ltr re R. Schlaf & H. Walters concerns about arrangements made for recent meeting at facility. Public announcement was issued well in advance of meeting. Public announcement & mailing list sent. DICKROD, H J Office of the Executive Director for Operations 00/06/02 19pp

0006170135 Responds to 000506 ltr re arrangements made for recent meeting at facility. Public announcement was issued well in advance of meeting. Public announcement & mailing list sent. DICKROD, H J Office of the Executive Director for Operations 00/06/03 14pp

--0006170135 Requests info re constituent inquiry about NRC notification of 000428 public meeting.
WYTHIANS, C Reacts 00/06/07 1p

E Financial Information

0006160921 Forwards 0001 "1999 Annual Financial Rpt" & 1980 internal cash flow statements as evidence of guarantee of payment of deferred premiums.
BRADLEY, W J Philadelphia Electric Co. 00/05/15 7pp

- 8004200257 Submits comments to aid in evaluation of environ impact of immobilizing high level wastes at facility. Selection of final waste form prior to selection of repository site may not be consistent w/ "safe approach" noted in 100 Regt. HSLRD, J.C. High Level Waste Licensing Management Branch 05/04/25 2pp
- 8004200097 Ack receipt of Mar 1985 Regt re insp & evaluation of APB high level waste storage sys. Expresses concern re manpower availability for milestone re completion of in-vent & wasteform space photographs. 05/03/13 2pp
- 8004200110 Summary of 800416 meeting w/vendor in Silver Spring, MD re results of NRC analyses of effect of tornado generated missiles at West Valley site. HANDBRY, C.J. Advanced Fuel & Spent Fuel Licensing Branch 05/05/19 4pp
- 8004200144 Summary of 800416 meeting w/NRC & NY State Energy RD Authority in Silver Spring, MD re results of NRC analyses of effect of missiles at West Valley site. HANDBRY, C.J. Advanced Fuel & Spent Fuel Licensing Branch 05/05/26 6pp
- 8004200597 Confirms 800406 telcon re BAR for proposed mod to plant BAR being forwarded under separate cover. Requests return upon completion of research project. HANDBRY, C.J. Advanced Fuel & Spent Fuel Licensing Branch 05/06/06 1p
- 0 Inspection reports, IE Docketing & correspondence
- 8004200078 Ack receipt of 800410 ltr informing NRC of steps taken to correct violation noted in IE Insp Regt 20-201/00-02. MARTIN, H.J. Region I, Philadelphia, Safeguards Branch 05/05/01 1p
- 8004200001 Forwards IE Insp Regt 20-201/00-02 on 800420-01 & notice of violation. Notice of violation withheld (ref 100R2 7903). MARTIN, H.J. Region I, Philadelphia, Safeguards Branch 05/05/19 2pp
- 8004200006 IE Insp Regt 20-201/00-02 on 800420-01 Noncompliance noted. Failure to maintain physical barrier to vital area in effective condition. Details withheld (ref 100R2 7903). DEVLIN, J.W. Region I, Philadelphia, Safeguards Branch. LAOUN, R.H. Region I, Philadelphia, Office of the Director 05/03/12 1p
- 8004200192 Ack receipt of 800315 ltr informing NRC of steps taken to correct violation noted in IE Insp Regt 20-201/00-02. BRITTON, S.H. Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/05/21 1p
- 8004200597 Responds to NRC 800420 ltr re violation noted in IE Insp Regt 20-201/00-03. Corrective actions employee cited have been scheduled for whole body counting. BUCHHEIT, J.P. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 05/05/13 2pp
- 8004200201 Forwards IE Insp Regt 20-201/00-03 on 800420-2B & notice of violation. BRITTON, S.H. Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/04/23 2pp
- 8004200205 Notice of violation from Insp on 800420-2B. Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/05/18 1p
- 8004200208 IE Insp Regt 20-201/00-03 on 800420-2B Noncompliance noted. Failure to perform whole body count for all radiation workers on annual basis. CLEMONS, P. Region I, Philadelphia, Office of the Director. KANUP, P. Region I, Philadelphia, Fuel Facility & Materials Safety Branch. 05/04/18 7pp
- 0 Periodic operating reports & related correspondence
- 8004200573 Forwards results & flow measurements for Mar 1985 in accordance w/provisions of NRCED Permit WY00054773. SUCAMONTH, J.P. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 05/04/22 4pp
- 8004200141 Forwards corrected Table 5-B, "Bear Sample Data," of Environ Regt 27. Contains results of reanalysis of bear harvested Mar 1975 & analytical results of second bear harvested Mar 1975. SUCAMONTH, J.P. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 05/04/21 1p
- 8004200144 Corrected Table 5-B, "Bear Sample Data," of Environ Regt 27. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 05/04/21 1p
- 8004200244 Forwards quarterly report for Jan-Mar 1985. SUCAMONTH, J.P. Nuclear Fuel Services, Inc. West Valley Reprocessing Plant 05/04/20 1p
- 8004200247 Quarterly report for Jan-Mar 1985. Nuclear Fuel Services, Inc. West Valley Reprocessing Plant 05/04/28 12pp
- SECRET 80-206 SAN ONOFRE NUCLEAR STATION, UNIT 1
F Security, medical, emergency & fire protection plans
- 8004200487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 1961." Rule adds new Section 50.48 & App E to 10CFR55 & is expected to be published in FR by end of May. EINHORN, D.O. Division of Licensing 05/05/19 4pp
- 8004200363 Forwards revised Pages 1-14 & new Page 14a for proposed rule 100R250, "Fire Protection Program for Nuclear Power Plants Operating Prior to 1961." Transmitted by NRC 800519 (14 Page 14a not sent). EINHORN, D.O. Division of Licensing 05/05/22 73pp
- 8004200290 Advises that addl 90 days is required to respond to comments in NRC 800425 ltr re until 7/5/85 guard training & qualification plan addl time required to establish physical exercise program. Response will be submitted by NRC0501. BARNER, P. Southern California Edison Co. 05/05/23 1p
- 8004200213 Ack receipt of 791022 change in security plan change does not decrease plant effectiveness. CRUTSFIELD, D.H. Operating Reactors Branch 5 05/05/20 2pp
- 0 Adjudicatory correspondence
- 8004200461 Forwards mod of 800404 confirmatory order granting 800519 request for extension to complete requirements of order. STELLER, V. Office of Inspection & Enforcement, Office of the Director 05/05/23 2pp
- 8004200468 Mod of 800404 confirmatory order granting extension until one wk prior to return to site for completion of class re IE Bulletin 79-27 in 800468 order. STELLER, V. Office of Inspection & Enforcement, Office of the Director 05/05/23 2pp
- 8004200462 Responds to 800519 request for extension of deadline date for completion of class in 800404 order. Mod to order granting request sent. STELLER, V. Office of Inspection & Enforcement, Office of the Director 05/05/23 2pp
- 8004200464 Order extending shutdown to 800522 to permit insp of outstanding workpiece procedure items prior to return to site. STELLER, V. Office of Inspection & Enforcement, Office of the Director 05/05/22 2pp
- 0 General correspondence
- 8004200127 Comments on decreased income from investment in unit due to NRC attention to protectors rather than facts. Mo lives have been lost resulting from nuclear power plant failures. LEE, ETT, C.P. Affiliation Unknown 05/05/27 1p
- 0 Operating license stage documents & correspondence
- 8004200509 Forwards "Responses to NRC Requirements Established to Date Following The Accident," in response to NRC 790912 request. Includes commitments to actions set forth in NRC80-0376. DRAME, J.H. Southern California Edison Co. 79/10/17 3pp
- 8004200103 "Responses to NRC Requirements Established to Date Following The Accident." Southern California Edison Co. 79/10/31 44pp
- 8004200141 Forwards addl TRI-2 related requirements to operating reactors. Licenses requirements for TRI Action Plan include: staff training, licensing exams & license dissemination of operating experience. Response requested within 30 days. EINHORN, D.O. Division of Licensing 05/05/27 120pp

DOCKETED ITEMS

21

- 000403917 LER 00-021/017-0 on 000315 while conducting visual evaluation of feedwater sys per IC Bulletin 79-12. Three deficient supports were identified. Cause by broken rod hanger clamp & deformed guide supports will be repaired. CURRAN, J H Southern California Edison Co 00/05/29 1p
- 000403979 Comments on AD rep'd to Congress Per Final quarter CWO Supports change of working re. water heater cooling sys pump. HCHALL, B C Director's Office 00/06/04 1p
- 000403984 Forwards LER 00-028/099-0
OTTD004, H L Southern California Edison Co 00/04/06 2pp
- 000403989 LER 00-028/099-0 on 000505 during dry penstock leak of reactor coolant pump flange below in refueling outage. Linear indication found inside dome unmeted weld in base of flange installed to prevent radioactive action. CURRAN, J H Southern California Edison Co 00/04/06 1p
- 000403994 Final Part 21 rep'd re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch lines were cut to AD244P requirement. Investigations conducted & fixed at 42 listed facilities. HERR, J L Chemours Corp - Tube Turns Div 00/04/06 3pp
- 000403999 Forwards LER 00-024/097-0 & rep'd re automatic initiation of auxiliary feedwater sys per 000510 meeting w/NRC. DARRIN, K P Southern California Edison Co 00/06/10 7pp
- 000403999 LER 00-026/097-0 on 000409 preliminary results of main steam line break accident scenarios to determine containment response required corrective actions to reduce calculated peak containment pressure. Rep'd re 000510 meeting and CURRAN, J H Southern California Edison Co 00/06/09 4pp
- 000403999 Forwards LER 00-020/021-0
OTTD004, H L Southern California Edison Co 00/06/10 2pp
- 000403999 LER 00-020/021-0 on 000502 during refueling outage. Flow detected extending below into unit. Unit in heat exchanger E-202. Cause by improper clearance of previously repaired flow flow repaired. CURRAN, J H Southern California Edison Co 00/05/10 1p
- DOCKET 30-200 COLUMBIA UNIV RESEARCH REACTOR
F Refueling, medical, emergency & fire protection plans
000403999 Forwards info re five add. TMS-2 related requirements to operating reactors per 000507 request integrated assessment of collective impact of all requirements should be conducted. CURRAN, J H Southern California Edison Co 00/05/06 2pp
- DOCKET 30-210 MAGNAN NUCLEAR PLANT
F Refueling, medical, emergency & fire protection plans
000403999 Forwards request for add info re facilities' emergency plans. Plans should be evaluated against NUREG-0054 & encl comments by 000430. CRUTCHFIELD, S N Operating Reactors Branch 00/05/12 3pp
- 000403999 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790301." Rule added new Section 30.58 & App B in 10CFR50 & is expected to be published in FR by end of May. EISENHART, S O Division of Licensing 00/05/14 4pp
- 000403999 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790301." transmitted by NRC 000517 1br Page 14a not encl. EISENHART, S O Division of Licensing 00/05/22 73pp
- 000404007 Submits info to reaffirm adequacy of current fire protection plans to fulfill NRC commitments. One revision drawing encl. CURRAN, J H Southern California Edison Co 00/05/29 4pp
- P Operating license stage documents & correspondence
000403999 Requests add emergency change to route approved by NRC 000522 1br Change necessary due to portion of route being closed for main line withhold (ref 10CFR 7902). CURRAN, J H Southern California Edison Co 00/04/21, 1p
- 000404044 Advises that 000420 request for change in spent fuel route has been received & approved. Pages describing detail route for "Spent Fuel Route Survey" inserted withhold (ref 10CFR 7902). HCHALL, B C Physical Security Licensing Branch 00/04/22 1p
- 000404045 Forwards add TMS-2 related requirements to operating reactors. License requirements for TMS-2 include shifts meaning, licensing exams & licensee dissemination of operating experience. Response requested within 30 days. EISENHART, S O Division of Licensing 00/05/07 1pp
- 000404045 Forwards NUREG-0486, Vol 1 & 11 & NUREG-0515 W/ encl. CRUTCHFIELD, S N Operating Reactors Branch 00/05/16 2pp
- 000404045 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Low Fracture Toughness on PWR Steam Generator & Reactor Coolant Pump Supports." Prepared review procedure & implementation schedule encl. EISENHART, S O Division of Licensing 00/05/19 72pp
- 000404045 Application to amend License DFE-05 by incorporating revisions to Tech Specs for Millstone 2 in response to NRC 000410 request. Proposed changes are necessary for safe operation of Millstone 2. In only unit w/ Tech Specs. CURRAN, J H Connecticut Yankee Atomic Power Co. COUNCIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities) 00/05/22 2pp
- 000404045 Proposed revisions to Tech Specs for Millstone 2. Incorporating requirements of NRC 000410 1br to all power reactor licenses. = Northeast Nuclear Energy Co. (subs of Northeast Utilities) 00/05/21 7pp
- 000404045 Forwards "Environ Qualification of Electrical Equipment" in response to NRC requests Response to five items identified in NRC 000326 1br containing enviro qualification program schedule components worksheets encl. CURRAN, J H Connecticut Yankee Atomic Power Co. 00/06/02 20pp
- 000404045 Notifies that licensing activities are being coordinated by F. Carver, due to reorganization of Div. of Nuclear Reactor Regulation. Forwards description of reorganization. CRUTCHFIELD, S N Operating Reactors Branch 00/06/02 3pp
- 000404045 Reconfirms that all possible boron dilution paths evaluated in response to NRC 000420 1br. Marked since release 20 minutes to magnitude & terminate dilution flow. CURRAN, J H Connecticut Yankee Atomic Power Co. 00/06/04 2pp
- 000404045 Notifies that info re transient & accident analysis is provided by WCAP-0091 in response to NRC 790509 1br. NRC 000517 requests conflict w/ verbal agreement re scope of NUREG-0378 Requirement 2.1. Vol 1. No further action planned. CURRAN, J H Connecticut Yankee Atomic Power Co. 00/06/06 2pp
- 000404047 Forwards info re five add. TMS-2 related requirements. Applying to operating reactors per 000507 request integrated assessment of collective impact of all requirements should be conducted. CURRAN, J H Southern California Edison Co 00/05/06 2pp
- 000404048 Forwards request for add info re facilities' emergency plans. Plans should be evaluated against NUREG-0054 & encl comments by 000430. CRUTCHFIELD, S N Operating Reactors Branch 00/05/12 3pp
- 000404047 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790301." Rule added new Section 30.58 & App B in 10CFR50 & is expected to be published in FR by end of May. EISENHART, S O Division of Licensing 00/05/14 4pp
- 000404047 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790301." transmitted by NRC 000517 1br Page 14a not encl. EISENHART, S O Division of Licensing 00/05/22 73pp
- 000404047 Submits info to reaffirm adequacy of current fire protection plans to fulfill NRC commitments. One revision drawing encl. CURRAN, J H Southern California Edison Co 00/05/29 4pp
- P Operating license stage documents & correspondence
000403999 Requests add emergency change to route approved by NRC 000522 1br Change necessary due to portion of route being closed for main line withhold (ref 10CFR 7902). CURRAN, J H Southern California Edison Co 00/04/21, 1p

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

0004000191 Forwards IE Investigation Rpt 30-293/00-12 on 000305-07 & 19-05 in response to allegations re alleged shipment of spent fuel
MATHIS, M D Region 1, Philadelphia, Safeguards Branch 10/04/10 1p

0004000996 IE Investigation Rpt 30-293/00-12 on 000305-07 & 19-05 HRC conclusions noted Major areas inspected examination of pertinent documents & records & physical inventory of all fuel assemblies
HRCB, R. ROBERTS, R Region 1, Philadelphia, Office of the Director
JONES, J H Region 1, Philadelphia, Safeguards Branch 05/04/16 12pp

0004000017 Response to IE Bulletin 30-05 re vacuum condition resulting in damage to chemical vent header was today tanks Review determined adequate vacuum protection exists on those systems for which tank damage could occur
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/05/23 4pp

0004000461 Act receipt of 000500 1st inferring NRC of incorrect statements made in IE Insp Rpt 30-293/00-12 Corrected pages sent 10/01/10
MATHIS, M D Region 1, Philadelphia, Safeguards Branch 00/05/22 1p

0004000567 Response to NRC 000410 1st NorthRock Nuclear Energy Co previously identified as unit licensed to operate Hedden Neck Plant
GRIFFITH, D C NorthRock Nuclear Energy Co, 1404 S of NorthRock Utilities 00/05/08 2pp

0004000640 Forwards IE Circular 00-13, "Oil Spill Damage in Heat-Exchanger Fuel Assemblies" - No written response required in Page 104 not sent
GIBBS, R. W Region 1, Philadelphia, Office of the Director 00/05/20 1p

H Periodic operating reports & related correspondence

0004100826 Forwards monthly operating rpt for May 1980
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/06/12 1p

0004100028 Monthly operating rpt for May 1980
Connecticut Yankee Atomic Power Co 00/06/06 12pp

I Repeatable occurrences, LERs & related correspondence

0004200270 RD while performing leak rate testing: LER acceptance criteria exceeded Cause not stated Followup report will be provided within 10 days
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/03/17 1p

0004200427 Forwards ETS/WR/30-213/00-04
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/03/20 1p

0004200301 ETS/WR/30-213/00-04 during first startup 1980: LER activity level in water moderator RSD limit caused by high release of radioactive liquid discharge prior to refueling station Refueling requirements revised
Connecticut Yankee Atomic Power Co 00/03/28 2pp

0004200018 Forwards LER 30-00V/017-0
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/05/20, 1p

0004200301 LER 30-00V/017-0 on 000516 while performing local leak rate testing: leakage rate exceeded Tank Spec limits Caused by failure of component cooling water check valve due to warped seating surface Buoyancy prevented
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/05/03, 1p

0004200270 RS during odd current testing of steam generators 1 & 2, two tubes in steam generator 2 showed significant leak of SO₂ and degradation Add: leak identified & no further defects discovered
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/06/03 1p

0004200275 RS 30-213/00-06 on 000326 while venting vol integral tank to waste gas unexplained release of Xe-133 occurred Caused by inadequate capacity in waste gas Com to handle vol control tank vent Study of vol control vent design initiated
GIBBS, R. W Connecticut Yankee Atomic Power Co 00/06/36 2pp

0004200420 RD 30-00/19 on 000421 while performing review of Category I, Five active tube supports found missing From two separate high pressure safety Injection lines Three add supports found jeopardizing gas separability Supports to be replaced
STAVES, R. H Connecticut Yankee Atomic Power Co 00/06/20 1p

DOCKET 30-219 OVERSEAS NUCLEAR POWER PLANT

0004200441 Forwards Endorsements 04 & 05 to NRC Policy 00-06
GIBBS, R. W General Public Utilities - GPU Service Corp 00/06/23 2p

F Security, medical, emergency & fire protection plans

0004200128 Forwards comments re 000317 submittal of guard training & qualification plan Response requested within 30 days
Comments withheld (ref 100950 700)
GIBBS, R. W Operating Reactors Branch 3 00/06/07 2pp

0004100073 Response to 000516 telcon re NRC concerns for emergency readiness at Facility Leak action to be undertaken & completed by end of current outage
GIBBS, R. W Region 1, Philadelphia, Office of the Director 00/05/16 2pp

0004200487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50.40 & App E to 10CFR50 & is expected to be published in FR by end of May
GIBBS, R. W Division of Licensing 00/05/19 4pp

0004100560 Forwards revised Pages 1-4 & new Page 15a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 000519
GIBBS, R. W Division of Licensing 00/06/22 72pp

0004000349 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 100950 700)
FIBBICK, I R Jersey Central Power & Light Co 00/06/03 1p

0004200326 Notices that revised security officer training & qualification plan will be submitted by 09/03/80 in response to NRC request received on 000919
FIBBICK, I R Jersey Central Power & Light Co 00/06/23 1p

H General correspondence

0004200306 Forwards Glenn County, NJ Franchise, RA Sesser, 000500 maligned operating concerns re adequacy of repairs being made at Facility NRC should directly contact county officials w/ response
GIBBS, R. W House of Rep 00/03/14 2pp

0004200401 Response to 000508 maligned to Congressman Hughes re adequacy of spray sparger repairs: Request provided, in add safety evaluation is Annex 47 to License SPR-16 W/ add
GIBBS, R. W Office of Nuclear Reactor Regulation, Director 00/06/23 1pp

0004200403 Forwards RA Sesser, 000500 maligned re adequacy of spray sparger repairs: Per response
GIBBS, R. W House of Rep 00/06/14 2pp

J Insurance & indemnity information

0004200408 Forwards Endorsements 60, 67 & 70 to NRC Policy 00-164
GIBBS, R. W General Public Utilities - GPU Service Corp 00/06/19 1pp

P Operating license change documents & correspondence

0004200206 Advises that 791004 proposal for spent reactor fuel shipment rule meets requirements of 10CFR72.107 exemption of areas covered by enclosed replacement Rule withheld
(ref 100972 700)
GIBBS, R. W Physical Security Licensing Branch 00/04/16 2pp

0004000163 Forwards add TH-2 related requirements to operating reactors: Licensees requirements for TH Action Plan include shift monitoring, licensing exam & licensee designation of operating experience Response requested within 30 days
GIBBS, R. W Division of Licensing 00/05/07 10pp

DOCKETED ITEMS

23

- 0004020014 Summary of 000402-02 meeting w/Hark 1 source group in Ben Jones' re confirmatory analysis & testing programs concerning Mark 1 containment long-term program
SRINER, C J Assistant Director for Plant Systems 00/05/09 2pp
- 0004020007 Forwards NUREG-0481, Vol 1 & II & NUREG-0426 For info w/ sec
CRUTCHFIELD, D Operating Reactors Branch 5 00/05/16 2pp
- 0004020029 Requests comments on NUREG-0377, "Potential For Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule w/ sec
EISENHART, D Division of Licensing 00/05/19 7pp
- 0004020009 Forwards Tech Spec Change Request 04 for License DPH-16 Class II For sec
FINNROCK, J Jersey Central Power & Light Co 00/05/22 1p
- 0004020012 Application for Tech Spec Change Request 04 for License DPH-16 Certificate of DvC & until 000502 for to Lacy Township and
FINNROCK, J Jersey Central Power & Light Co 00/05/22 3pp
- 0004020014 Tech Spec Change Request 04 regarding Section 1 definition of "operable" & adding Section 3 re general limiting conditions for operation
w Jersey Central Power & Light Co 00/05/22 4pp
- 0004020026 Response to NRC 000214 for requesting docketed info re certain BOP topics
RODMAN, J Jersey Central Power & Light Co 00/06/02 2pp
- 0004020002 Notice/Plan Check facility licensing activities are being performed by M Paulsen, due to reorganization of Ofc of Nuclear Reactor Regulation Forwards Description of reorganization
CRUTCHFIELD, D Operating Reactors Branch 5 00/06/02 35pp
- 0004020004 Forwards act info re BOP Topic 01-B, "Belmont Design Consideration" in response to NRC request for Belmont Associates, "Belmont Reanalysis of Revised Emergency BOP Water Lines" and
RODMAN, J Jersey Central Power & Light Co 00/06/03 7pp
- 0004020012 "Belmont Reanalysis of Revised Emergency BOP Water Lines" *
John A. Belmont & Associates, Engineers (a/b/c UNR Corp) 7/9/12/19 14pp
- 0004020004 Ltr to all NRC licensees forwarding "For Comment" edition of NUREG-0419, "NRC Feedwater Nozzle & Control Rod Drive Water Line Failure Cracking" Comments will be evaluated by NRC prior to final implementation W/ sec
EISENHART, D Division of Licensing 00/06/05 22pp
- 0004020046 Submit further info re implementation of NUREG-0570 Description of upgrade of containment vent & nitrogen purge systems of release pathways design review & info re plant shielding review w/ sec
FINNROCK, J Jersey Central Power & Light Co 00/06/10 12pp
- 0004020023 Requests permission to complete model during 1901 full outage beginning no later than 001123 End list of model completed Plant/shield test on safety relief valve discharge device & vacuum breakers performed Four-month extension justified.
EISENHART, D Jersey Central Power & Light Co 00/06/11 2pp
- 0 Inspection reports, IE Bulletin & correspondence
- 0004020016 Forwards IE Insp Rept 00-219/00-09 on 000311-14 No noncompliance noted
SMITH, D H Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/06/04 2pp
- 0004020010 IE Insp Rept 00-219/00-09 on 000311-14 No noncompliance noted Major areas impacted inactive Insp Data Review meeting Plant Staff & Personnel on regional request
KEINIG, R L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, BR1000, L, WATSON, D Region 1, Philadelphia, Office of the Director 00/06/04 4pp
- 0004020009 Forwards IE Circular 00-06 "NRC Tech Spec Inconsistency - Reactor Protection Sys Response Time" No written response received
KEINIG, R L Region 1, Philadelphia, Office of the Director 00/06/10 1p
- 0004020007 Response to IE Bulletin 00-09, "Hydrant Actuator Deficiencies" Review of values that indicate that no AM-90 or AM-90 series hydra-actuator valve actuators are used in any safety/critical-related systems at facility
RODMAN, J Jersey Central Power & Light Co 00/06/09 1p
- 0004020003 Forwards IE Insp Rept 00-219/00-14 on 000406 No noncompliance noted
SMITH, D H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/06/12 2pp
- 0004020006 IE Insp Rept 00-219/00-14 on 000406 No noncompliance noted Region areas impacted status of radiation protection equipment
KIMMEL, P J, KEINIG, R L Region 1, Philadelphia, Office of the Director 00/06/09 3pp
- 0004020010 Forwards IE Insp Meeting Rept 00-219/00-10 on 000409
ONDER, D H Region 1, Philadelphia, Office of the Director 00/06/12 2pp
- 0004020003 IE Insp Meeting Rept 00-219/00-08 Areas discussed licensee corrective actions arising from Insp findings, radiation protection criteria resulting from recent Insp & actions to improve overall mgmt controls
SMITH, D H, KIMMEL, P J Region 1, Philadelphia, Office of the Director, KEINIG, R L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/06/12 3pp
- 0004020007 Ask receipt of 000303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 00-219/00-12 Ltr withheld (ref 100702 700)
HARTMAN, D Region 1, Philadelphia, Safeguards Branch 00/06/27 1p
- 0004020013 Forwards IE Insp Rept 00-219/00-12 on 000303-28 & notice of violation Notice of violation withheld (ref 100702 700)
HARTMAN, D Region 1, Philadelphia, Safeguards Branch 00/06/16 2pp
- 0004020017 IE Insp Rept 00-219/00-12 on 000303-28 Noncompliance noted: Corrective actions arising from Insp findings, radiation protection criteria resulting from recent Insp & actions to improve overall mgmt controls
SMITH, D H, KIMMEL, P J Region 1, Philadelphia, Office of the Director, KEINIG, R L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/06/16 1p
- 0004020004 Forwards IE Insp Rept 00-219/77-23
SMITH, D H Region 1, Philadelphia, Office of the Director 00/06/28 1p
- 0004020006 IE Insp Rept 00-219/77-23 on 000405 Insp meeting to discuss NRC concerns resulting from Radiation Protection Insp 00-219/77-23 Discussed licensee immediate corrective actions & long-term plans
KEINIG, R L Region 1, Philadelphia, Office of the Director, SMITH, D H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/06/27 22pp
- 0 Periodic operating reports & related correspondence
- 0004020005 Forwards monthly operating report for May 1993
RODMAN, J Jersey Central Power & Light Co 00/06/13 1p
- 0004020008 Monthly operating report for May 1993
RODMAN, J Jersey Central Power & Light Co 00/06/04 10pp
- 0 Reportable occurrences, LTRs & related correspondence
- 0004020018 Forwards RD 00-17-1P re possibility of removal of core then use control rod w/air-cooled fuel
CARROLL, J T Jersey Central Power & Light Co 00/06/16 1p
- 0004020003 RD 00-17-1P on 000516, during refueling shutdown, control rod interference checks revealed that rod block bypass jammer was not removed during control blade replacement, resulting in possible removal of control rods unapproved
FINNROCK, J Jersey Central Power & Light Co 00/06/16 2pp
- 0004020003 PNO-1-00-092 on 000512, one worker received 2-inch cracked medically stable of N2 saturation No gross release planned
SMITH, D H, KIMMEL, P J, KEINIG, R L Region 1, Philadelphia, Office of the Director 00/06/22 1p
- 0004020004 Forwards LER 00-01A/01-07
RODMAN, J Jersey Central Power & Light Co 00/06/23 1p

DOCKETED ITEMS

- 8004030450 LER 80-016/017-0 on 800352, while recognizing that 800420 discovery of defective pressure switch. PSC. Discontinued immediate test caused by locked fail-safe automatic switch. removed & will be replaced
R055: D A Jersey Central Power & Light Co 80/05/30 App
- 8004030419 Forwarded LER 80-017/017-0
R055: D A Jersey Central Power & Light Co 80/05/30 App
- 8004030424 LER 80-017/017-0 on 800316, while performing control rod interference tests, pressure transducer had position indication remained illuminated while operation ended. OSCD failed by operator & procedure in repairs & equipment failure
R055: D A Jersey Central Power & Light Co 80/05/30 App
- 8004160018 Forwarded LER 80-018/001-0
F018R001: D A Jersey Central Power & Light Co 80/05/09 App
- 8004160021 LER 80-018/001-0 on 800507, during monthly surveillance testing of reactor high pressure safety sensors, R055 found to be less conservative than specified. Caused by sensor repeatability sensor reset
R055: D A Jersey Central Power & Light Co 80/06/05 App
- 8004160030 Forwarded revised LER 80-001/017-1
F018R001: D A Jersey Central Power & Light Co 80/06/05 App
- 8004160035 Revised LER 80-001/017-1 on 800308, while performing electronic relief valve operability test, valve failed to open. Caused by improper staging of 3/8" air valve during assembly & testing. Valve operability test procedure revised
R055: D A Jersey Central Power & Light Co 80/06/05 App
- 8004160080 Forwarded revised LER 80-008/001-1
F018R001: D A Jersey Central Power & Light Co 80/06/05 App
- 8004160084 Revised LER 80-002/001-1 on 800216, during fuel bundle trip test prior to fuel "tagging", fuel bundle 303 was not authorized & not properly secured in core cell caused by personnel error & inadequate procedure. Procedure revised
R055: D A Jersey Central Power & Light Co 80/06/05 App
- 8004160094 Forwarded NO 80-019/002-0-IP
C018R001: D A Jersey Central Power & Light Co 80/06/06 App
- 8004160097 NO 80-019/002-0-IP on 800405, following issue of fire barrier, several penetrations found in degraded condition. Caused by delay in performing further fire watches attributed to personnel error. Fire watch being conducted
C018R001: D A Jersey Central Power & Light Co 80/06/06 App
- 8004160098 NO on 800502, during routine surveillance testing of isolation condenser unitization pressure switches, false high pressure signal caused reactor scram. Caused by opening of gauge valve had performed on instrument line
F018R001: D A Jersey Central Power & Light Co 80/06/16 App
- 8004200477 Forwarded updated LER 80-013/017-1
R055: D A Carolina Power & Light Co 80/06/16 App
- 8004200500 Updated LER 80-013/017-1 on 800309, fire suppression water gas removed from air to replace diesel pump & discharge valve V-7-A due to track in valve body caused by excessive stress between flange & valve due to increased vibration
R055: D A Carolina Power & Light Co 80/06/16 App
- 8004260103 Forwarded LER 80-019/001-0
R055: D A Jersey Central Power & Light Co 80/06/17 App
- 8004260107 LER 80-019/001-0 on 800517, during leak rate reduction program test procedures for low core spray, air heater valves were found to be inoperative caused by component failure. Subsequent for relief valves reset
R055: D A Jersey Central Power & Light Co 80/06/17 App
- 8004260174 Forwarded LER 80-020/017-0
R055: D A Jersey Central Power & Light Co 80/06/18 App
- 8004260212 LER 80-020/017-0 on 800403, following issue of fire barriers protecting safety-related areas, several penetrations found in degraded condition. Caused by deficiencies in installation, tests & personnel error in delay in establishing watches
R055: D A Jersey Central Power & Light Co 80/06/18 App
- 8004260244 Forwarded revised LER 79-024/001-1
R055: D A Jersey Central Power & Light Co 80/06/20 App
- 8004260203 Revised LER 79-024/001-1 on 790007, while excavating to make repairs on equipment drain tank line, leak discovered in secondary tank discharge pipe apparently caused by component failure. Line repaired
R055: D A Jersey Central Power & Light Co 80/06/20 App
- 8004260247 Forwarded LER 80-010/001-0
R055: D A Jersey Central Power & Light Co 80/06/20 App
- 8004260477 LER 80-010/001-0 on 790417, excavation was started to repair tank near inside penetration within pipe tunnel. Activity was detected by soil near SEDT. Pipe SEDT line resulted in R00016. Line will be repaired
R055: D A Jersey Central Power & Light Co 80/06/20 App
- 8004260478 Forwarded LER 80-022/001-0
F018R001: D A Jersey Central Power & Light Co 80/06/20 App
- 8004260482 LER 80-022/001-0 on 800503, prior to inservice loop reactor vessel hydro testing, revealed that electronically relief valve high pressure sensor IAWSD exceeded Test Spec setpoint
R055: D A Jersey Central Power & Light Co 80/06/20 App
- DOCKET 80-280 NINE HOUR POINT NUCLEAR STATION, UNIT 1
F Security, medical, emergency & fire protection plans
- 8004300087 Forwarded proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790011". Rule adds new Section 50.45 and 50.46 to 10CFR50.45 is expected to be published in FR by end of May
E018R001: D A Division of Licensing 80/05/19 App
- 8004130083 Forwarded revised Pages 1-1 & 1-2 New Page 124 for proposed rule 10CFR50.45 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790011". Transmitted by NRC 800519
E018R001: D A Division of Licensing 80/05/20 App
- 8004160038 Request participation in NRC study of people-related problem in nuclear subgroups. Initiative collection of data on licensee security review & practices, including visit to facility to interview, reviewing with personnel
E018R001: D A Division of Licensing 80/06/03 App
- 8004160475 Forwarded air description & drawings for proposed sprinkler protection of waste tanks in response to NRC 790726. Itr Containment receiving by 800715. Drawings available in Central Files only
E018R001: D A Niagara Mohawk Power Corp 80/06/10 App
- J Insurance & indemnity information
- 8004160081 Forwarded Amendment 7D to NELA Policy NF-144
M018R001: D A Niagara Mohawk Power Corp 80/06/04 App
- 8004160082 Forwarded Amendment 39 to NELA Policy NF-144
M018R001: D A Niagara Mohawk Power Corp 80/06/04 App
- P Operating license stage documents & correspondence
- 8004260200 Responds to ARE request for info re plans to shut down design testing & examinations of highly exposed control blades. Shutdown test performed in spring 1979. Scrammer test to be performed during failure tests
E018R001: D A Niagara Mohawk Power Corp 80/05/02 App
- 8004070103 Forwarded add TMI-2 related requirements to operating reactors. Licensee requirements for TMI-2 Action Plan include staff training, licensing exam & licensee dissemination of operating experience. Request requires within 30 days
E018R001: D A Division of Licensing 80/07/07 150pp
- 8004260314 Summary of 800422-23 meeting w/Mark J. Turner group in San Jose. CA re coordination analysis & testing program concerning Mark J. Turner's long-term program
E018R001: D A Assistant Director for Plant Systems 80/07/09 App
- 8004260322 Request comments on NUREG-0577, "Palatka for Low Pressure Equipment & Low Pressure Testing of PWR Steam Generator & Reactor Coolant Pump Supports". Prepared review procedure & implementation schedule etc.
E018R001: D A Division of Licensing 80/05/19 72pp

DOCKETED ITEMS

8004190214 Advises that decision of Dir of Nuclear Reactor Regulation director to request to suspend activities-revoke Q-removes radioactive waste & hold public hearings is final NRC action
CHILM, M. J. Office of the Secretary of the Commission 80/05/10 1p

8 Reportable occurrences, LEAs & related correspondence

8004000480 7905-0-90-030 Licensee provided U sample in reaction as part of class experiment Sample was returned via pneumatic sample transfer via to receiving station within ventilation hood Sample holder had cracked No exposures involved
VILAS, D. P. Region 3, San Francisco, Office of the Director 80/05/10 2pp

DOCKET 80-025 NRC CRITICAL EXPERIMENT

8 Security, medical, emergency & fire protection plans

8003000686 Forwarded DE Insp Rep't 50-025/80-03 on 800424-0501 No noncompliance noted
HARTEN, M. G. Region 1, Philadelphia, Safeguards Branch 80/05/16 2pp

8004000410 DE Insp Rep't 50-025/80-03 on 800424-0501 No noncompliance noted Major areas inspected: control plan, protection of BWR, security organization, access control, alarm, fire, etc. Safety & hardware details withheld (ref 10CFR2 7901)
BENJON, J. W. Region 1, Philadelphia, Safeguards Branch
HARTEN, M. G. Region 1, Philadelphia, Office of the Director 80/05/13 1p

DOCKET 80-020 AIRBORNE RADIOGRAPHY & RESEARCH REACTOR

8 Security, medical, emergency & fire protection plans

8004100298 Forwarded description of improvements on facility security re safeguards alarm sys changes withheld (ref 10CFR2 7901)
REINACHER, M. L. Aircraft Operations 80/05/13 1p

DOCKET 80-020 DRESDEN NUCLEAR POWER STATION, UNIT 2

8 Security, medical, emergency & fire protection plans

8004000240 Notification that new telephone was called Health Physics Network (HPN) has been installed at site Sys enhanced for use during emergencies to link all power plants & NRC
Emergency Notification Sys hotline will also be used
RUFFLER, J. D. Region 3, Chicago, Office of the Director 80/05/18 2pp

8004040123 Forwarded comments re 790818 submitted of training & qualification plan Response requested within 30 days
Comments withheld (ref 10CFR2 7901)
CRUTCHFIELD, B. Operating Reactors Branch 50/05/09 5pp

8004100298 Requests that FEMA review of state & local emergency plan be provided consistent w/act schedule to avoid potential delays in licensing decisions
AMERIN, J. P. Commission 80/05/13 2pp

8004000487 Forwarded proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790501" Rule added new Section 50.48 & 50.49 to 10CFR50 & is expected to be published in FR by end of May
EISENHART, D. G. Division of Licensing 80/05/19 4pp

8004100432 Forwarded revised Pages 1-54 & new Page 156 for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790501" Unsubmitted by NRC 800519 1st Page 156 not met
EISENHART, D. G. Division of Licensing 80/05/22 2pp

8004000487 Requests revision of 800324 re safeguards training plan in accordance w/comments described in ref to 1st Response requested within 30 days Encl withheld (ref 10CFR2 7901)
CRUTCHFIELD, B. Operating Reactors Branch 50/05/27 2pp

8004050276 Informs that licensee submitted add'l info on 800406 re fire protection review Evaluation sent re Item 3 & water suppression
HALL, R. E. Brookhaven National Laboratory 80/05/02 2pp

8004100393 Forwarded Revision 1 to draft emergency plan Emergency plan is then annexed
PEOPLE, D. L. Commonwealth Edison Co 80/05/06 2pp

8004100331 Draft emergency plan annex
Commonwealth Edison Co 80/07/31 52pp

8004100347 Revision 1 to draft emergency plan
Commonwealth Edison Co 80/07/31 137pp

8004100331 Provides info re access of NRC & NRC contractor personnel to facilities to conduct appraisal of health physics program Site plans is scheduled for approx 2 wks
including 800419 List of authorized NRC personnel encl
KAPPLER, J. Q. Region 3, Chicago, Office of the Director 80/06/05 4pp

8004000414 Forwarded, "Dresden Nuclear Power Station 800419 Emergency Response Plan Exercise," to verify comm idl emergency plan
PEOPLE, D. L. Commonwealth Edison Co 80/06/18 2pp

8004000439 "Dresden Nuclear Power Station 800419 Emergency Response Plan Exercise"
Commonwealth Edison Co 80/06/19 63pp

8004000490 Responds to NRC 800425-20, 800419, & 20 items requesting add'l info re guard training & qualification plans Requests that response submittal date be extended to 800504
PEOPLE, D. L. Commonwealth Edison Co 80/06/18 1p

8 Operating license stage documents & correspondence

7903401470 Forwarded O&P report NRC-2389-P, "Analogical Model for Computing Major Risk in Safety Relief Valve Discharge Line Following Valve Closure" Report provided as Task 7 & 2 of Task 3 program Rept withheld (ref 10CFR2 7901)
JAMES, R. P. Commonwealth Edison Co 79/03/12 1p

8004000565 Forwarded add'l TH-2 related requirements to operating license license requirements for TH-2 Action Plan include shift opening, licensing exams & licensee demonstration of operating experience Response requested within 30 days
EISENHART, D. G. Division of Licensing 80/05/27 100pp

8004000514 Summary of 800425-20 meeting w/Work 1 owners group in Wash DC re confirmatory analysis & testing programs concerning Work 1 containment long-term program
STREIB, C. J. Assistant Director for Plant Systems 80/05/09 8pp

8004000517 Forwarded NRC-0454, Vol 1 & 11 & NRC-0454, Vol encl
CRUTCHFIELD, B. Operating Reactors Branch 50/05/16 2pp

8004100192 Requests comments on NRC-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports" Prepared review procedure & implementation checklist encl
EISENHART, D. G. Division of Licensing 80/05/19 72pp

8004000476 Notifies of delay in evaluation of reactor-turbine blog design parameters due to difficulties in obtaining info on installed equipment weights & reviewing final as-built drawings Info will be forwarded by 800515
JAMES, R. P. Commonwealth Edison Co 80/05/21 1p

8004000562 Application to amend Licenses DPR-02, DPR-19, DPR-23, DPR-24 & DPR-30, clarifying term "available," submitted as Task Spec change request in response to NRC 800410 1st
MANUCCI, G. P. Commonwealth Edison Co 80/05/30 2pp

8004000502 Task Spec change request for Task Spec Sections 1, 0-5, 2, 2, & 2, 2, 0, 0, 0 & 0, 0 & 0, 0 & 0 re definitions, administrative controls, safety limits, limiting safety, etc. w/limiting conditions for operation
Commonwealth Edison Co 80/05/30 42pp

8004100335 Responds to re 1st letter questions re NRP Topic 12-2, report fuel storage spent fuel storage pool designed by withstand anticipated earthquake loadings as Class 1 structure
JAMES, R. P. Commonwealth Edison Co 80/05/06 2pp

8004000501 Advises that reorganization of Dir of Nuclear Reactor Regulation became effective on 800428 Project Manager P-5/Gowen will coordinate licensing activities for facility reorganization described in encl
CRUTCHFIELD, B. Operating Reactors Branch 50/06/02 33pp

8004000504 Ref to all NRC licensees forwarding "Plan Comment" edition of NRC-0454, "NRC Reactor Nucleic & Control Rod Drive Mechanism Re-evaluation" Comments will be evaluated by NRC prior to final Supplemental Information
EISENHART, D. G. Division of Licensing 80/06/08 22pp

DOCKETED ITEMS

27

0004130600 Forwards "Environ Qualification of Electrical Equipment- Dresden Nuclear Power Station, Unit 2." Vol 1-2
PEOPLE'S D L Commonwealth Edison Co 8/04/02 2pp

--0004130601 "Environ Qualification of Electrical Equipment-Dresden Nuclear Power Station, Unit 2." Vol 1 of 2
* Bechtel Power Corp 1000s of Bechtel Corp 1 8/04/02 4pp

--0004130602 "Environ Qualification of Electrical Equipment-Dresden Nuclear Power Station, Unit 2." Vol 2 of 2
* Bechtel Power Corp 1000s of Bechtel Corp 1 8/04/02 17pp

--0004130603 "Environ Qualification of Electrical Equipment-Dresden Nuclear Power Station, Unit 2." Vol 3 of 3
* Bechtel Power Corp 1000s of Bechtel Corp 1 8/04/02 20pp

0004130604 Forwards verification of analysis program used for determining voltages for facility electric distribution systems per 700000 request
UNNEEDEN R F Commonwealth Edison Co 8/04/01 3pp

0004130607 Forwards commitments to comply w/requirements & schedules in NRC 800507 (1) re 800170-2 related requirements Dresden Unit 1, is currently undergoing substantive work & documentation, therefore no response is provided
PEOPLE'S D L Commonwealth Edison Co 8/04/02 10pp

0004130609 Confirms availability of ECR equipment following a power supply failure, per 800425 request. Mode to ensure availability of IMPC following a power failure completed
Units 1, is currently undergoing substantive work & documentation, therefore no response is provided
UNNEEDEN R F Commonwealth Edison Co 8/04/02 2pp

0004130607 Forwards response to NRC 800516 re requesting info re turbine disc cracking stress corrosion cracks not observed to date
UNNEEDEN R F Commonwealth Edison Co 8/04/02 10pp

0004130608 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CEI-1A, "Core EA Program for Nuclear Generating Stations" Revised Revision 11 includes tests on which equivalent education requirements will be established
PEOPLE'S D L Commonwealth Edison Co 8/04/02 3p

g Inspection reports, IF Bulletin & correspondence

0004130610 Forwards IE Circular 80-0B, "EHR Tech Spec Inconsistencies - Reactor Protection Sys Response Time" No written response required
PEOPLE'S D L Region D, Chicago, Office of the Director 8/04/02 1p

0004130608 Forwards IE Insp Repts 50-010/80-07, 50-237/80-07 & 50-249/80-10 re 800300-0484 & notice of violation
PEOPLE'S D L Region D, Chicago, Reactor Operations Nuclear Support Branch 8/04/02 2pp

--0004130612 Notice of violation from Insp on 800300-0484
* Region D, Chicago, Office of the Director 8/04/02 1p

--0004130613 IE Insp Repts 50-010/80-07, 50-237/80-07 & 50-249/80-10 on 800300-0484. Noncompliance noted failure to follow radiation protection procedures
PEOPLE'S D L Region D, Chicago, Office of the Director 8/04/02 2pp

0004130608 Forwards to IE Bulletin 70-26 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated BAC breaking Central blade exposures will be monitored during cycles to verify projected anti-cyclical response
PEOPLE'S D L Commonwealth Edison Co 8/05/02 2pp

0004130608 Forwards response to IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls" Proposed made identified only if present sys design may compromise protective action of equipment
PEOPLE'S D L Commonwealth Edison Co 8/04/02 9pp

h Periodic operating reports & related correspondence

0004130600 Forwards monthly operating reports for Apr 1980
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130601 Monthly operating reports for Apr 1980
STEPHENSON S B Commonwealth Edison Co 8/05/02 2pp

0004130600 Forwards monthly operating reports for May 1980
STEPHENSON S B Commonwealth Edison Co 8/04/02 1p

--0004130601 Monthly operating reports for May 1980
STEPHENSON S B Commonwealth Edison Co 8/04/02 1pp

h Periodic operating reports, LERS & related correspondence

0004130604 Forwards LER 80-014/03L-0
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130605 LER 80-014/03L-0 on 800515, while shut down & conducting 200 psi primary gas hydrostatic leak inspection discovered dripping from LER1 check valve closed ambient
STEPHENSON S B Commonwealth Edison Co 8/05/02 2pp

0004130604 Forwards LER 80-014/03L-0
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130605 LER 80-014/03L-0 on 800515, during routine availability surveillance, torque to disqual vacuum breaker was found inadequate. Caused by swelling of torlon shaft bushings. Bushings were machined to achieve required clearance
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

0004130604 Forwards LER 80-014/03L-0
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130605 LER 80-014/03L-0 on 800425, during normal operation, main steam line had monitor 2C caused reactor protection sys channel A half-scan Count by had relay defective component replaced
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

0004130607 Forwards LER 80-014/03L-0
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130608 LER 80-014/03L-0 on 800515, during reactor startup, IMPC island steam isolation valve failed to Close. Caused by reactor breakdown steam caused valve packing to swell. Packing adjusted & valve cycled satisfactorily
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

0004130610 Forwards LER 80-017/03L-0
STEPHENSON S B Commonwealth Edison Co 8/06/02 3p

--0004130611 LER 80-017/03L-0 on 800515, following unit screwdown valve indication observed on IMPC island isolation valve due to failed valve caused by packing leak which allowed water to enter motor operator. Motor dried out & valve replaced
STEPHENSON S B Commonwealth Edison Co 8/06/02 3p

h Periodic operating reports, LERS & related correspondence

0004130600 Forwards monthly operating reports for Apr 1980
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

--0004130601 Monthly operating reports for Apr 1980
STEPHENSON S B Commonwealth Edison Co 8/05/02 2pp

h Periodic operating reports, LERS & related correspondence

0004130604 Forwards LER 80-014/03L-0 on 800515, while performing routine surveillance, torque to disqual vacuum breaker was found inadequate. Caused by swelling of torlon shaft bushings. Bushings were machined to achieve required clearance
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

h Periodic operating reports, LERS & related correspondence

0004130604 Forwards LER 80-014/03L-0 on 800515, while performing routine surveillance, torque to disqual vacuum breaker was found inadequate. Caused by swelling of torlon shaft bushings. Bushings were machined to achieve required clearance
STEPHENSON S B Commonwealth Edison Co 8/05/02 3p

SECRET NO-244 ROBERT EPHET CIVIL NUCLEAR PLANE, UNIT 1

F Security, medical, emergency & fire protection plans

0060092407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section NO 4B & 4C & to 10CFR50 & is expected to be published in FR by end of May
EISENHUT, D Division of Licensing 00/09/79 44pp

0060030363 Forwards revised Pages 1-34 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 000519
Page 14a not incl
EISENHUT, D Division of Licensing 00/05/82 72pp

0060030395 Rebuttal response to Items 3 & 4, 5, 11, 12 & 14 & 15 of note to fire protection plan requested by NRC 790214 safety evaluation. Completion schedule of work will be delayed beyond June 1980 due to complexity of designs
WHITE, L D Rochester Gas & Electric Corp 00/05/83 2pp

0060030308 Rebuttal response to NRC 790214 fire protection safety evaluation re status of Items 3, 134 (proposed strategies), 5 & 12 (fire control), 1, 24 (gassing & duct penetration), & 3 & 12 (gassing & duct penetration)
WHITE, L D Rochester Gas & Electric Corp 00/05/83 2pp

0060030355 Response to NRC 800425 for transmitting fire protection safety evaluation. Suppl Info re design, identification of previous submittals & verification of completed design and Dept 1 drawings available in Control Files
WHITE, L D Rochester Gas & Electric Corp 00/06/84 27pp

0060040912 Advises that NRC review of 000326 safeguards contingency plan revision is ongoing. Response within 30 days to comments contained in and that withheld (ref 790214)
CRUTCHFIELD, S Operating Reactors Branch 5 00/06/84 2pp

0 Adjudicatory correspondence

0060030176 Response to ASLB 800429 order requesting status reports. Recommends refusal of adjudicatory proceedings, schedule consideration until 1981, to prepare for hearing after issuance of SEP Supporting Documentation and
HEATH, E O Hearing Branch 4 00/04/80 2app

0060100205 Status report by NY State Energy Dec in response to ASLB 800429 order. Recommends that parties be permitted to identify additional contentions to that prehearing conference be held to discuss issues. Minutes of agreement & Certificate of Dec incl
ALLEN, E G New York State 00/05/80 4pp

0060100506 Status report in response to ASLB 800429 order. Recommends schedule for findings, safety evaluation, supply, discovery & further prehearing conference. Recommends dissemination of SEP progress in one yr
VIGST, H H Rochester Gas & Electric Corp VIGST, H H Lehigh, Lehigh Valley & Neff 00/06/82 0pp

---0060100010 Order denying applicant motion to exempt NY State intervention. Amits NY State contentions against C-G & H Certificate of Dec incl
LUTON, E Atomic Safety and Licensing Board Panel 77/03/85 7pp

0060100404 Order dismissing intervenor Rochester Committee for Scientific Info per 740312 & 791030 stipulations. Reopening proceedings after applicant compliance w/requirements. Requests for reconsideration may be filed within 60 days
CROSBYMAN, H Atomic Safety and Licensing Board Panel 00/06/82 3pp

F Operating license stage documents & correspondence

0060090183 Forwards add THP-2 related requirements to operating reactor. Licenses requirements for THP Action Plan include shifts training, licensing exam & license dissemination of operating experience. Response requested within 30 days
EISENHUT, D Division of Licensing 00/05/87 156pp

0060030094 Confirms 000519 sgt hearing in Dobari, NY arranged per 003429 (re: agenda incl)
OBER, B H Region 1, Philadelphia. Office of the Director 00/06/80 2pp

0060130122 Requester comments on NUREG-0577, "Potential for Low Fracture Equipment & Loading Testing on PWR Steam Generator & Reactor Containment Pump Supports." Proposed review procedure & implementation schedule incl
EISENHUT, D Division of Licensing 00/05/79 72pp

0060230154 Forwards NUREG-0564, vol 1 & 11 & NUREG-0611 w/ encl
CRUTCHFIELD, S Operating Reactors Branch 5 00/05/83 2pp

0060030318 Forwards data & results of 48-h Standby Auxiliary Feedwater Tests C & D w/ enclosure incl
WHITE, L D Rochester Gas & Electric Corp 00/05/86 37pp

0060030324 Forwards Procedure M-11, 5B, Revision 9, "Major Mechanical Insulation of Auxiliary Feed Pumps." & Procedure P-11, Revision 25, "Auxiliary Feedwater Sys." in response to NRC 800418 request
WHITE, L D Rochester Gas & Electric Corp 00/06/80 1p

---0060030208 Procedure M-11, 5B, Revision 9, "Major Mechanical Insulation of Auxiliary Feed Pumps."
WHITE, L D Rochester Gas & Electric Corp 00/06/80 3pp

---0060030347 Procedure P-11, Revision 25, "Auxiliary Feedwater Sys."
WHITE, L D Rochester Gas & Electric Corp 00/06/80 3pp

0060030394 Response to NRC 790214 request. Forwards revised unit 790214 comments re containment piping
WHITE, L D Rochester Gas & Electric Corp 00/05/80 2pp

0060040837 Ack receipt of 000429 for re piping stress analysis. Design criteria will be submitted by 000719 & stress analysis report for A-RWT & B main when final analysis containment will be submitted by 000919. Mod schedule will be based on analysis
WHITE, L D Rochester Gas & Electric Corp 00/05/80 1p

0060040920 Forwards nonproprietary version of RELAP4-EH blowdown input for facilities preparatory info and analysis reflects BRC proprietary analytical models & techniques for BRC feed data. Stroud has modification to an OWHF-77-58
WHITE, L D Rochester Gas & Electric Corp 00/05/80 23pp

0060040926 Submits verification of compliance w/short-term Lessons Learned Test Force requirements re ROD venting. Provisions made for venting reactor vessel head & pressurizer & for sweeping noncondensable gases from steam generator U tubes
WHITE, L D Rochester Gas & Electric Corp 00/06/82 4pp

0060100004 Motion that licensing application for plant not being coordinated by M. Neuchow due to reorganization of DEC of Nuclear Reactor Regulation. Forwards description of reorganization
CRUTCHFIELD, S Operating Reactors Branch 5 00/06/82 35pp

0060070021 Forwards response to NRC 002226 for requesting addl info re SEP design basis events. Topics cover steady state & unsteady errors, single failure analysis, steam line break analysis & primary pump rotor failure
WHITE, L D Rochester Gas & Electric Corp 00/06/83 10pp

0060080005 Forwards response to NRC 000206 request for info re "SEP Qualification Program Submittal Content"
MUSMAN, A Rochester Gas & Electric Corp 00/06/80 1p

0060100027 Comments on 000926 presentation to NRC Commissioners re status of SEP & review of effecting an back up
aggression by licensee. NRC has not provided guidelines. Issues whether prioritization have arisen
WHITE, L D Rochester Gas & Electric Corp 00/06/83 3pp

0060100514 Forwards addl response to 000407 for containing action items resulting from THP Action Plan, including feedback procedures of operating experience to plant staff & worker radiation protection improvements
WHITE, L D Rochester Gas & Electric Corp 00/06/83 21pp

0060090362 Forwards addl info re SEP Topic 10-16, "Radiological Consequences of Small Line Carrying Primary Cooling Outside Containment," per NRC 000311 request. Drawings referenced in Table 1 submitted w/790912 for overexposed drawing incl
WHITE, L D Rochester Gas & Electric Corp 00/06/84 7pp

---0060030345 "Piping Flow Diagram Heating, Ventilating & Air Conditioning"
Rochester Gas & Electric Corp 75/09/80 1p

0004030420 Responds to 000425 ltr requesting review assessment & add info on REP Topic 111-12 Unit unable to respond within time frame requested Response emailed 000601
 WHITE, L. D. Rochester Gas & Electric Corp 00/06/24 1p

Q Inspection reports, IE Bulletins & correspondence

0004030420 Ack receipt of 000601 ltr informing NRC of steps taken to correct deviation noted in IE Insp Reg 50-244/00-04
 000600, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/05/14 1p

--0004050429 Responds to NRC 000401 ltr re deviation noted in IE Insp Reg 50-244/00-04 Corrective actions now training effort to cover emergency procedure was undertaken
 WHITE, L. D. Rochester Gas & Electric Corp 00/05/01 2pp

--0004050426 Forwards IE Insp Reg 50-244/00-04 on 000303-07 & notice of deviation
 000600, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/05/13 2pp

--0004060426 Notice of deviation from Insp on 000303-07 & Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/10 1p

--0004060446 IE Insp Reg 50-244/00-04 on 000303-07 Noncompliance noted Failure to meet containment re training of personnel on new procedure
 KIRCHER, R. D., JOHNSON, D. F., BARNHART, W. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/10 9pp

0004060403 Forwards evaluation of still responses to IE Bulletin 79-06A & 79-06A/Revision 1 Appropriate actions taken to meet bulletin requirements
 CRUTCHFIELD, D. Operating Reactors Branch 5 00/05/20 20pp

0004060403 Forwards IE Circular 00-12L "Dry Ship Damage in Westinghouse Fuel Assembly" - No written response required
 CRIBB, R. H. Region 1, Philadelphia, Office of the Director 00/05/28 1p

0004060409 Responds to IE Bulletin 00-09, "Exam of Containment Liner Penetration Welds - Containment penetrations described in bulletin do not resemble design employed at facility
 WHITE, L. D. Rochester Gas & Electric Corp 00/05/29 1p

0004060404 Responds to IE Bulletin 00-05 re vacuum condition resulting in damage to chemical vent holding tanks Licensee is evaluating addition of vacuum protection for holding tanks which would satisfy criteria discussed in bulletin
 WHITE, L. D. Rochester Gas & Electric Corp 00/06/03 2pp

0004060406 Responds to IE Bulletin 00-10, "Decay Heat Removal Sys Operability - Circumstances & sequence of events of Steam-Break 000419 event were reviewed Review included adjustment to operational assessment group for on-shift discussions
 WHITE, L. D. Rochester Gas & Electric Corp 00/06/03 7pp

B Periodic operating reports & related correspondence

0004060407 Forwards monthly operating rep for May 1980
 00060, E. J. Rochester Gas & Electric Corp 00/06/09 1p

--0004060408 Monthly operating rep for May 1980
 ROHMANN, A. E. Rochester Gas & Electric Corp 00/06/09 2pp

C Repeatable occurrences, LEIs & related correspondence

00040603587 RD 00-04 during performance of post-test installation testing high power operated relief valve determined inoperable & REC were established caused by two switches which supply dc power in off position
 00060, E. J. Rochester Gas & Electric Corp 00/05/07 1p

0004060360 Forwards NRC-7603, "Metalurgical Investigation of Cracks in Pressurizer Nozzle-to-Safe-End Weld of Robert Emmet Girtor Nuclear Power Generating Station" - Reg is followup to LER 76-062
 WHITE, L. D. Rochester Gas & Electric Corp 00/05/28 1p

--0004060362 "Metalurgical Investigation of Cracks in Pressurizer Nozzle-to-Safe-End Weld of Robert Emmet Girtor Nuclear Power Generating Station" - RAG & V - CAPLAW, J. B. Westinghouse Electric Corp - Nuclear Energy Systems NRC-7603 00/03/29 27pp

0004060371 RD 00-05 on 000603 during performance of procedure 0-20 L breaker For A-loop accumulator discharge valve-MSV-045 discovered in closed position Cause not stated Breaker immediately placed in proper position
 00060, E. J. Rochester Gas & Electric Corp 00/06/03 1p

0004060401 RD 00-06 on 000603 during performance of safety injection valve position verification procedure discovered breaker For A-loop accumulator discharge valve-MSV-045 in closed position Breaker placed in proper position
 00060, E. J. Rochester Gas & Electric Corp 00/06/03 1p

0004060473 Forwards LER 00-00R/017-0
 WHITE, L. D. Rochester Gas & Electric Corp 00/06/16 1p

--0004060478 LER 00-00R/017-0 on 000603 during performance of monthly verification procedure Loop A accumulator injection circuit breaker found in an position Cause not stated Breaker returned to off position
 PETER, C. H. Rochester Gas & Electric Corp 00/06/16 2pp

V Operator Examinations

0004060408 Forwards info re specific training of shift technical operators & licensed operators in response to NRC 000500 Request Review of Licensed operators enrolled in training and
 WHITE, L. D. Rochester Gas & Electric Corp 00/05/12 5pp

DOCKET 00-249 HILLSTONE NUCLEAR POWER STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans

0004060426 Forwards request for add info re facilities' emergency plans Plans should be evaluated against NRC-0604 & sent elements by 000600
 CRUTCHFIELD, D. Operating Reactors Branch 5 00/05/12 31pp

0004060407 Forwards proposed rule entitled, "Fire Protection Program for Westinghouse Plant Operations Prior to 1980" & Rule adds new Section 50-40 & App B to 10CFR50 & is expected to be published in FR by end of May
 EISENHART, D. Division of Licensing 00/05/19 4pp

0004060403 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program For Nuclear Power Plant Operation Prior to 1980" as transmitted by NRC 000519
 Page 14a not sent
 EISENHART, D. Division of Licensing 00/05/22 70pp

0004060407 BUREAU adds to reaffirm adequacy of current fire protection plans to fulfill IEEE commitments One specific drawing not
 00060, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 00060, E. J. Northeast Utilities Admin Power Co 00/05/27 8pp

H General correspondence

0004060406 Advice of personnel change CJ Resnik relieved of duties as station superintendent on 000601
 00060, E. J. Northeast Utilities 00/06/02 1p

P Operating license issue documents & correspondence

0004060403 Forwards add 700-2 related requirements to operating license requirements for THX Action Plan include shifts training, licensing exams & licensee documentation of operating experience Response requested within 30 days
 EISENHART, D. Division of Licensing 00/05/07 130pp

0004060404 Summary of 000422-03 meeting w/Mark I owners group in San Jose, CA re confirmatory analysis & testing programs concerning Mark I containment long-term program
 GRIFFIN, C. I. Assistant Director for Plant Systems 00/05/09 9pp

0004060403 Discusses review of unit 000124 submitted advising that blast wall between boiler room & diesel generator room, as required by Amendment 25 to License 000-25, is in satisfactory installation of blast wall still required
 CRUTCHFIELD, D. Operating Reactors Branch 5 00/05/29 2pp

0004060408 Requests comments on NRC-0077, "Potential for Low Pressure Boiling & Saturated Steaming in RBMK Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule not
 EISENHART, D. Division of Licensing 00/05/29 7pp

- 8004250029 Forwards NUREG-0454, Vol. 1 & 11 & NUREG-0454 for info
NRC encl
CRUHQFIELD, C Operating Reactors Branch 5 8/20/87 2pp
- 8004250020 Application to amend License DPM-48 by incorporating
revisions to Tech Specs for Millstone 2 in response to NRC
8004250018 request. Proposed changes are necessary for safe
operation of facility. Millstone 2 is only unit of Unit Spec
CONNECIL, W Connecticut Yankee Atomic Power Co CONNECIL, W
Northeast Nuclear Energy Co (subs of Northeast Utilities)
8/20/87 2pp
- 8004250005 Requests participation of utility in interim reliability
evaluation program. Studies help identify accident sequences
& vulnerabilities in procedures & basic design. Utility should
appoint engineer to participate in initial 8004250004 meeting
EISENHART, D Division of Licensing 8/20/87 2pp
- 8004250036 Advises that dc power supply has been reviewed to verify
that impact of failure on RSCC performance is no more
limiting than previously analyzed active failures
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004250026 Responds to NRC 800507 request for info re undervoltage
protection. First Level 2 undervoltage scheme automatically
connected to 24KV bus of preferred offsite supply. Relays
physically located in control room
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004101042 Forwards add info on SEP topic 11-B, "Systemic Review,"
consisting of engineering data re findings of feedback
loop (drive mechanism, diesel oil air limit, isolation
condenser condensation line & shutdown cooling line
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 14pp
- 8004101005 Forwards aspartate cards of piping & instrumentation
diagrams for steam-up & sampling via NRC mail
CONNECIL, W P. Northeast Nuclear Energy Co (subs of
Northeast Utilities) 8/20/87 1p
- 8004101026 Forwards add info re revision qualification of electrical
equipment. Info does not fully respond to NRC request.
Analytical efforts are in progress at OE to substantiate
accuracy of P&ID and condition profiles in drawell
CONNECIL, W Northeast Utilities 8/20/87 30pp
- 8004100245 Provides descriptive info & design assessment of proposed
low level radioactive storage facility. NRC review
required. Facility will be operational late 1988
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004060057 Advises that reorganization of Div of Nuclear Reactor
Regulation became effective on 8/20/87. Project manager
will coordinate licensing activities for facility.
Reorganization described in encl
CRUHQFIELD, C Operating Reactors Branch 5 8/20/87 30pp
- 8004250038 Forwards Amends 48 & 59 to Licenses DPM-21 & DPM-45,
respectively & notice of issuance & availability
CLARK, R Operating Reactors Branch 3 8/20/87 4pp
- 8004250049 Amends 48 & 59 to Licenses DPM-21 & DPM-45, respectively,
deleting Sections 4 & 4.2 from ETO
CLARK, R Operating Reactors Branch 3 CRUHQFIELD, C
Operating Reactors Branch 5 8/20/87 2pp
- 8004250067 Notice of issuance & availability of Amends 48 & 59 to
Licenses DPM-21 & DPM-45, respectively
CLARK, R Operating Reactors Branch 3 8/20/87 4pp
- 8004250044 Ltr to all NRC Licensees regarding "For Comment" edition
of NUREG-0549, "NRC Feedwater Nozzle Control Rod Drive
Reaction Line Nozzle Cracking." Comments will be evaluated by
NRC prior to final implementation. encl
EISENHART, D Division of Licensing 8/20/87 2pp
- 8004250048 Notification of 800412 meeting results in Bethesda, MD to
diverse interim reliability evaluation program
SEDMAN, L Operating Reactors Branch 1 8/20/87 2pp
- 8004190437 Forwards info re five add 382-2 related requirements
applying to operating reactors per 800507 request. Integrated
assessment of collective impact of all requirements should
be conducted
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) CONNECIL, W Connecticut Yankee Atomic Power Co
8/20/87 10 30pp
- 8004250039 Discusses effect of dc power supply failure on RSCC
performance. Reactor info indicates unique transfer switch
controlling power supply to isolation condenser. Value 10-3
mode to transfer switch scheduled for Sept 1988 outage
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004250038 Submits responses to NRC questions re containment
atmospheric control. Six purge valves. Sufficient engineering
evaluations exist to justify continued purge & venting
operations as needed
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004250040 Updates schedule, previously submitted 7/20/87, for
implementing Mark I containment long-term program mode
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004250030 Responds to NRC 800214 ltr re request for SEP information to
deleted info addresses topic number, title & listing of
references identified by data link does not reflect
exhaustive review of docketed correspondence
CONNECIL, W Connecticut Yankee Atomic Power Co CONNECIL, W
Northeast Nuclear Energy Co (subs of Northeast Utilities)
8/20/87 14pp
- 8 Inspection reports, IE Bulletin 4 correspondence
--8004250039 Forwards IE Insp Repts 90-245/79-21 & 90-234/79-22 on
7/20/87. No noncompliance noted
BETHUNE, E Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 7/21/87 2pp
- 8004250024 IE Insp Repts 90-245/79-21 & 90-234/79-22 on 7/20/87. No
noncompliance noted. Major areas inspected plant items:
physical security, inspection of feedwater piping per IE Bulletin
79-12, fire protection & surveillance testing
HICKMAN, C Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch EISENHART, J T Region 1, Philadelphia, Office of
the Director 7/21/87 2pp
- 8004250038 Forwards IE Insp Repts 90-245/80-02 & 90-234/80-02 on
8/20/87. No noncompliance noted
BETHUNE, E Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 8/20/87 2pp
- 8004250057 IE Insp Repts 90-245/80-03 & 90-234/80-02 on 8/20/87. No
noncompliance noted. Major areas inspected control room &
accessible portions of Unit 1 reactor building, radiations, gas
burning generator & intake blids
EISENHART, J T, EISENHART, R P Region 1, Philadelphia, Office of
the Director EISENHART, R P Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 8/20/87 10pp
- 8004250057 Forwards IE investigation Rept 90-245/80-12 on 8/20/87-07 &
1/20/82 re response to allegations re illegal shipments of
spent fuel
HARTMAN, G Region 1, Philadelphia, Safeguards Branch 10/24/87
1p
- 8004250088 Forwards IE Circular 80-05, "NRC Tech Spec Inadequacy -
Reactor Protection Sys Response Time." No utility response
received
EISENHART, R Region 1, Philadelphia, Office of the Director
8/20/87 1p
- 8004250064 Responds to IE Bulletin 80-07 concerning 384-j pump
assembly. Visual inspection of 384-j pump performed & no
deficiencies or discrepancies discovered. Individual jet
pump differential pressure readings reviewed
CONNECIL, W Northeast Nuclear Energy Co (subs of Northeast
Utilities) 8/20/87 2pp
- 8004250132 Forwards IE Insp Repts 90-245/80-04 & 90-234/80-03 on
8/20/87. No noncompliance noted
BETHUNE, E Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 8/20/87 2pp
- 8004250087 IE Insp Repts 90-245/80-04 & 90-234/80-03 on 8/20/87. No
noncompliance noted. Major areas inspected plant operations,
logs & records, procedures, limit functions, radioactive mail
shipments, and IE Bulletin 4 circulars
EISENHART, R P Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch EISENHART, J T, EISENHART, R P Region 1,
Philadelphia, Office of the Director 8/20/87 10pp
- 8004250011 Rept receipt of 800505 ltr informing NRC of status of
feedwater storage supplied to Millstone 1 noted in SA
Program Insp Rept 7/20/87-03-79-23
EISENHART, W Region 4, Dallas, Office of the Director 8/20/87 1p

DOCKETED ITEMS

31

--B006409508 Follow-up B001280 ltr. advising that until owners have requested vendor to upgrade pressure sparger fabricated by Barlow Engineering Inc. Philadelphia New sparger cannot be fabricated in limited time before Fall 1980 Commitment BARLOW, J. General Electric Co. 05/05/80 2pp

B006240615 Ack receipt of B005000 ltr informing NRC of incorrect statements made in RE ltr Sept 5-29/80-10-10 Corrected pages sent via mail MARTIN, V. B. Region I, Philadelphia, Safeguards Branch 05/05/80 1p

--B006434867 Responds to NRC B00418 ltr Northwest Nuclear Energy Co incorrectly identified as USI licensed to operate Hudson Neck Plant COULTER, W. C. SMITH, D. C. Northwest Nuclear Energy Co (subs of Northwest Utilities) 05/05/80 2pp

B006309226 Forwards Mgt Meeting Rept 50-245/80-05 on B00313 CARLSON, R. T. Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/80 1p

--B0064300234 Mgt Meeting Rept 50-245/80-05 on B00313 Major areas discussed findings of investigation of allegations re 791219 waterhammer event & licensee activities in sgs node B report CARLSON, R. T., TRIFPL, E. Region I, Philadelphia, Reactor Construction & Engineering Support Branch B006309226, R. T. Region I, Philadelphia, Office of the Director 05/05/80 3pp

B006200491 Updated rept re recirculation pump interlock smp Requests replacement of requirements of tests 14B-2503 because of equipment required for obtaining parts, tools & planning for retesting outage COUMBS, M. G. COUMBS, H. B. Northwest Utilities 05/06/80 2pp

R. Periodic operating reports & related correspondence

B006110438 Forwards monthly operating rept for May 1980 B00229A, E. J. Northwest Utilities 05/06/80 1p

--B006170440 Monthly operating rept for May 1980 BARBER, G. Northwest Utilities 05/06/80 3pp

S. Reportable occurrences, LERs & related correspondence

B0061180609 PMS-1-80-087 on B005930, Inc. Failed flexible couplings on turbine drain extraction steam line caused unscheduled extended outage. Damage from bellows damaged at least three other tubes & some internal baffles in condenser GELMID, R. B. B006001, E. J. Region I, Philadelphia, Office of the Director 05/06/80 1p

B006240007 Forwards LER B0-007/001, G. B00229A, E. J. Northwest Nuclear Energy Co (subs of Northwest Utilities) 05/06/80 1p

--B006400093 LER B0-007/001, G. as B005930, discovered that semiannual functional test of cable weld smoke detection app had been overruled. Canceled by test app being failed on unit surveillance schedule. Verification of schedule performed. B. Northwest Nuclear Energy Co (subs of Northwest Utilities) 05/06/80 3pp.

SECRET 50-247 INDIAN POINT STATION, UNIT 2

P. Security, medical, emergency & fire protection plans

B006305487 Forwards proposed rule entitled, "Fire Protection Program For Nuclear Power Plants Operating Prior to 790301." Rule under new Section 50.4B & App R to 10CFR50 & is expected to be published in 25 or 30 days end of May B006305487, D. Division of Licensing 05/05/80 48pp

B006120063 Forwards revised Pages 1-14 & new Page 16a for proposed rule 10CFR50 "Fire Protection Program For Nuclear Power Plants Operating Prior to 790301." Transmitted by NRC B00519 ltr. Page 16a not sent B006305487, D. Division of Licensing 05/05/80 73pp

B006306280 Advises NRC of recent developments re emergency preparedness at facilities. Unit is reviewing emergency plans in accordance with NRC-024, retaining K&N Nuclear, Inc. to assist with NRC & Westchester Science in reviewing plans CARLSON, R. T. Consolidated Edison Co. of New York, E. J. Power Authority of the State of New York 05/06/80 5pp

B006180526 Forwards design details for oil collection sgs to be installed on reactor coolant pump-as fire protection safety evaluation requirements CARLSON, R. T. Consolidated Edison Co. of New York 05/06/80 4pp

O. Adjudicatory correspondence

B006400523 Order stating four-pronged approach to resolve USCE petition for Unit 1 decommissioning & Unit 2-3 shutdown adjudication before ASLJ, informal proceeding to determine issues, generic consideration & establishment of independent fact body CHILLIS, J. Office of the Secretary of the Commission 05/05/80 1pp

B006190318 Responds to B005923 petition re scheduling meetings outside Washington, DC area. Meetings are occasionally held outside of Washington, DC vicinity to allow persons living near plants opportunity to attend B006001, E. J. Division of Licensing 05/06/80 2pp

B006400217 Notice of withdrawal from proceeding effective B00602 Certificate of Div. mail LENTIS, B. H. Hearing Branch 2 05/06/80 4pp

B006190947 Order granting extension until B00707 for Commission to select whether to review ALAB-438 & petition of ALAB-061 CHILLIS, J. Office of the Secretary of the Commission 05/06/80 1p

B006400483 Comments on Commission B005930 order re safe operation & criteria of operation CP & GL established criteria should apply & burden of proof must remain as licensee. Specific design changes must be feasible WEISS, E. R. JORDAN, M. S. Union of Concerned Scientists, WEISS, E. R. Sheldon, Herman & Weiss 05/06/80 7pp

B006400212 Memorandum in response to Commission B005930 order initiating informal proceeding Urges development of industrywide policy guidance & state prior to consideration of units separately in adjudicatory hearings B006001, E. J. Consolidated Edison Co. of New York, E. J. Power Authority of the State of New York 05/06/80 23pp

B006400186 Forwards USCE B00583 notice to disqualify Commissioner Wendle WEISS, E. R. JORDAN, M. S. Sheldon, Herman & Weiss 05/06/80 1p

--B006400186 Notice to disqualify Commissioner Wendle from further participation in NRC deliberations re USCE petition for suspension of operations. Request is based on Wendle involvement with public as member of ASCE WEISS, E. R. JORDAN, M. S. Union of Concerned Scientists, WEISS, E. R. Sheldon, Herman & Weiss 05/06/80 10pp

--B006400186 Notifies that during ASCE 125th meeting on 7/6/77-19, review of USCE application was completed upon satisfactory completion of contract facility can operate with under 75th as public USCE member. Prof. qualifications sent WEISS, E. R. ASCE - Advisory Committee on Reactor Safeguards 7/07/77 10pp

--B006400186 Responds to 730717 ltr re still sitting criteria Indian Point after sent NRC regulations & criteria. Considerable energy has been expended to secure public health & safety WERNER, J. H. Atomic Energy Commission, Directorate of Licensing 73/07/10 3pp

II. General correspondence

B006300014 Requests public debate re monitoring large populations near power plants. Opposes plants located in densely populated areas HAN, R. Affiliation Unknown 05/03/80 1p

B006300027 Responds to B00519 ltr re location of nuclear power plants in areas of high population density. Every effort is being made to protect public health & safety of all nuclear power plants B006001, E. J. Office of Nuclear Reactor Regulation, Directorate 05/04/80 2pp

B006190434 Comments on B005930 order re shutdown of plants pending adequate emergency plans. No plant can operate with acceptable emergency plans with energy & economic factors would have minimal influence on decision to shut down. HAN, R. Affiliation Unknown 05/06/80 1pp

F. Operating license stage documents & correspondence

- 8004070165 Forwards addl TRN-2 related requirements to operating Reactor Licenses requirements for TRN Action Plan include shift working, licensing exams & licensee dissemination of operating experience Response requested within 30 days
EISENHUT, D O Division of Licensing 80/05/27 18pp
- 8006040502 Notification of 800520 meeting w/ utility contractors & consultants in Bethesda, MD to exchange technology re accident sequence & related phenomena per A. Schweser
800410 Itr to L Peoples
LONG, J H Reactor Systems Branch 80/05/15 3pp
- 8004130128 Requests Comments on NRC80-5077, "Potential for Low Pressure Feedwater & Low Pressure Turbine Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule incl
EISENHUT, D O Division of Licensing 80/05/19 7pp
- 8006170826 Forwards request for addl info required to complete review of non-class I seismic equipment resulting in finding of safety-related equipment Requests response within 45 days
WAGNA, S A Operating Reactors Branch 80/05/20 8pp
- 8004200172 Notification of 800530 meeting w/ utility in Bethesda, MD re severe accident mitigation features for facilities
EISENHUT, D O Operating Reactors Branch 80/05/23 1p
- 8004130208 Forwards Amend A1 to License DPM-26 safety evaluation & notice of issuance & availability
WAGNA, S A Operating Reactors Branch 80/05/23 2pp
- 80060410284 Amend A1 to License DPM-26 increasing staffing of station nuclear safety committee & incorporating NRC provisions allowing crew competition below min requirements for 2-4 period
WAGNA, S A Operating Reactors Branch 80/05/23 2pp
- 8006130220 Safety evaluation supporting Amend A1 to License DPM-26
Office of Nuclear Reactor Regulation, Director 80/05/23 2pp
- 8004130223 Notice of issuance & availability of Amend A1 to License DPM-26
WAGNA, S A Operating Reactors Branch 80/05/23 2pp
- 8006030174 Forwards request for addl info concerning SA program which supplements 800428 Itr Response should be provided within 30 days of Itr
WAGNA, S A Operating Reactors Branch 80/05/23 3pp
- 8006030259 Requests 800404 meeting w/ utility personnel to discuss Interim Reliability Evaluation Program (IREP) & potential impact on facility
EISENHUT, D O Division of Licensing 80/05/23 3pp
- 8006070470 Notification of 800403 meeting w/ utility in Bethesda, MD to discuss filtered vented containment sys & core retention devices
HESTER, J F Reactor Systems Branch 80/05/27 3pp
- 8004130251 Forwards drawings & addl info re electrical override/ bypass aspects of containment purge sys. in response to NRC 800423 Itr Remainder of response will be provided by 800718
Drawings available in Central File only
CARROLL, M J Consolidated Edison Co. of New York 80/05/28 18pp
- 8006042044 Forwards slides used by utility during 800403 meeting re technology changes in area of mitigation features for severe accidents at facility
EISENHUT, D O Hentingshouse Electric Corp 80/05/05 1p
- 8006170835 Forwards "Mitigation of Severe Accident Study Rept." Rept includes presentations made to NRC & ACRS on 800225 & 800305, respectively & consists of sketch-of-the-art analyses conducted within 60-day period
CARROLL, M J Consolidated Edison Co. of New York EARLY, P J Power Authority of the State of New York 80/04/15 3pp
- 8006170404 Informes that Section & of rept submitted on 800605 was inadvertently stamped proprietary Class 2 Rept is non-proprietary
CARROLL, M J Consolidated Edison Co. of New York EARLY, P J Power Authority of the State of New York 80/05/06 1p
- 8006170407 Responds to 800528 Itr transmitting rept covering work performed by various consultants Entree Hentingshouse rept non-proprietary
PEEPLES, S L Commonwealth Edison Co 80/06/09 3pp
- 8006170464 "Mitigation of Severe Accident Study Rept." consisting of work re evaluation of residual risk/steam applications, containment response for Class 2 accidents & post-accident containment vent sys conceptual designs
Hentingshouse Electric Corp 80/05/21 403pp
- 8006040404 Notification of 800612 meeting w/ utility in Bethesda, MD to discuss interim reliability evaluation program
EISENHUT, D O Operating Reactors Branch 80/06/09 3pp
- 8004130274 Forwards summary of actions taken to comply w/ NRC 800211 Confirmation Order re verification of pump recirculation & review of administrative checks & verification procedures for single failure point valves
EISENHUT, D O Consolidated Edison Co. of New York 80/06/10 8pp
- 8004130208 Forwards Com Ed 800505 & Power Authority of State of NY 800507 Itrs to DOE re economic effects of extended shutdown for consideration by NRC Task Force
CARROLL, M J Consolidated Edison Co. of New York EARLY, P J Power Authority of the State of New York 80/06/10 15pp
- 8006130424 Forwards response to five addl TRN-2-related requirements per 800587 request Response re implementation of item 1, shift working, will be sent as expeditiously as possible after receipt of NRC guidance
CARROLL, M J Consolidated Edison Co. of New York 80/06/12 8pp
- 8004270417 Summary of 800505 Technology Exchange Meeting 3 w/ utility in Bethesda, MD re accident mitigation features for facilities
LONG, J H Reactor Systems Branch 80/06/10 27pp
- 8006070203 Notification of 800618 meeting w/ utility contractors & consultants in Bethesda, MD for presentation in area of accident mitigation response for facilities Amend and
HESTER, J F Reactor Systems Branch 80/06/18 2pp
- 8006050553 Notification of 800617 meeting w/ utility & consultants in Bethesda, MD to discuss technology exchange re containment structural response failure procedures & failure modes
HESTER, J F Reactor Systems Branch 80/06/17 2pp
- 8006040304 Forwards request for Amend 2 to application for amend to DL No addl fee required
CARROLL, M J Consolidated Edison Co. of New York 80/06/23 2pp
- 8006040305 Request for Amend 2 to application for amend to DL modifying previous applications to reflect addl support for redesign
CARROLL, M J Consolidated Edison Co. of New York 80/06/19 3pp
- 8006040302 Proposed revised Tech Spec pages for Table 3.13 re safety-related short suppressors
Consolidated Edison Co. of New York 80/06/23 4pp
- 8006040254 Safety evaluation supporting Amend 2 to application for amend to DL
Consolidated Edison Co. of New York 80/06/30 3pp
- 8004130406 Forwards application for amend to License DPM-26 deleting certain fire protection safety evaluation requirements & modifying Tech Spec re limiting conditions for operation & surveillance
CARROLL, M J Consolidated Edison Co. of New York 80/06/23 2pp
- 8006040304 Application to amend License DPM-26 deleting certain fire protection safety evaluation requirements & modifying Tech Spec re incorporating limiting conditions for operation & surveillance requirements for addl fire detectors
CARROLL, M J Consolidated Edison Co. of New York 80/06/19 4pp
- 8006040267 Revised Tech Spec re incorporating limiting conditions for operation & surveillance requirements for addl fire detectors, hose stations & water supply capability safety evaluation incl
Consolidated Edison Co. of New York 80/06/30 18pp
- 8004200297 Affidavit certifying use of application for amend to DL & Amend 2 to application for amend to DL on 800619
LIBERATION, L F Consolidated Edison Co. of New York 80/06/23 1p
- 8 Inspection reports, EE Bulletins & correspondence
- 8006170770 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No non-compliance noted
BETTEL, D H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp

DOCKETED ITEMS

33

--800417078 Waste Packaging Insp Regt 80-05 on 800327-29 No noncompliance noted Region atoms embayed shipping paper requirements, DOT placarding requirements, definition levels, noncompliance with prohibited articles on containers PERCY, W. W. , POTTER, J. P. Region 2, Atlanta, Fuel Packaging & Materials Safety Branch 80/03/17 7pp

800417087 Forwards IE Insp Regt 80-247/74-25 on 791204-800302 No noncompliance noted BRADNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/20 2pp

--800417091 IE Insp Regt 80-247/74-25 on 791209-800302 Noncompliance w/ DOT regulations noted defective shipping container gasket resulted in leakage & contamination of exterior of shipping tank BARNICK, W. , BRADNER, E. J. Region 1, Philadelphia, Office of the Director 800417091 Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/24 10pp

800418021 Forwards response to IE Bulletin 80-04 Blemaine break case w/failure of auxiliary feedwater recirculation protection app would not result in containment overpressurization CHAMILL, M. J. Consolidated Edition Co. of New York 80/05/08 7pp

800418046 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies." No written response received CHAMILL, M. J. Region 1, Philadelphia, Office of the Director 80/05/08 1p

Periodic operating reports & related correspondence

800417043 Forwards data specified in Decline 401 Certification for May 1980 to NY State Dept of Environ Conservation HORTON, M. A. Consolidated Edition Co. of New York 80/06/10 1p

--800417048 Circulating under temp-gross electrical output & river water discharge info for May 1980 Consolidated Edition Co. of New York 80/06/10 16pp

800418052 Forwards "Quarterly Report on Seismic Monitoring Network in Vicinity of Indian Point," Consolidated Edition Co. of New York 80/06/13 1p

--800418053 "Quarterly Report on Seismic Monitoring Network in Vicinity of Indian Point," Consolidated Edition Co. of New York 80/06/13 1p

800418046 Forwards daily fish counts from intake screens for May 1980 CHAMILL, M. J. Consolidated Edition Co. of New York 80/06/13 1p

--800418047 Daily fish counts from intake screens for May 1980 Consolidated Edition Co. of New York 80/06/13 4pp

800417046 Forwards monthly operating report for May 1980 CHAMILL, M. J. Consolidated Edition Co. of New York 80/06/13 1p

--800417043 Monthly operating report for May 1980 EICH, E. Consolidated Edition Co. of New York 80/06/06 2pp

Reportable occurrences, LERs & related correspondence

800418047 PWR-1-80-011 on 800359: Four separate intake bomb threats were received. Two calls received by Peachkill II. Evening Star & by Supervisor's 24-hour Post of Peachkill II. Bomb search procedures initiated at both plants PERCY, W. W. , HORTON, M. A. Region 1, Philadelphia, Office of the Director 80/06/20 1p

800418017 PWR-1-80-014 on 800403: Evening Star of Dutchess, NY received phone call from unidentified male, stating that Block of Liberty Island & facilities used by West Branch of facilities reported no evidence of bomb JONES, E. H. , HORTON, M. A. Region 1, Philadelphia, Office of the Director 80/06/04 1p

800418022 PWR-1-80-015 on 800404: Daily News, NY City newspaper, received phone call from unidentified male admitting membership in Liberty Island & facilities used by West Branch of facilities reported no evidence of bomb JONES, E. H. , HORTON, M. A. Region 1, Philadelphia, Office of the Director 80/06/04 1p

800418040 Forwards LER 80-004/05L-0 ZARWAL, P. Consolidated Edition Co. of New York 80/06/11 1p

--800418048 LER 80-004/05L-0 on 800418: During normal operation, leak discovered at socket weld connection on seal injection header. Live +0.02 downstream of filters caused by leak in socket weld associated with live +0.02 degree alarm HANDEK, J. H. Consolidated Edition Co. of New York 80/06/11 1p

800417035 Forwards LER 80-004/05L-0 CHAMILL, M. J. Consolidated Edition Co. of New York 80/06/17 1p

--800417041 LER 80-004/05L-0 on 800403: During normal plant operation, all off-site electrical power was lost caused by lightning strike. Pumps cleaned of faulted condition HANDEK, J. H. Consolidated Edition Co. of New York 80/06/17 4pp

T Hearing transcripts on non-antitrust matters

800418012 Transcript of 800330 Affirmation Session 80-04 in Region 02 Pg 1-2 Commission 80/05/20 3pp

--800418032 Recommendations approval of next revised draft order Encl PA Briefed separate statement to be appended to order CHAMILL, M. J. Office of the General Counsel 80/05/29 16pp

--800418038 Response to 800324 ltr to J. Ahearne re problems of evacuating large populations in short period of time Program of evacuating emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant DENTON, H. E. Office of Nuclear Reactor Regulation, Director 80/04/26 2pp

--800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

800418044 Elaborates on concerns expressed in 800302 ltr re need for practical evacuation plans around nuclear power sites Problem of evacuating large populations in short time have been underestimated. Requests open hearings on issues NRC's Affiliation Unknown 80/05/24 2pp

DOCKETED ITEMS

--8006180031 Draft emergency plan annex
* Commonwealth Edison Co. 80/07/31 30pp

--8006180347 Revision 1 to draft emergency plan
* Commonwealth Edison Co. 80/07/31 139pp

8006180001 Provides info re access of NRC & NRC contractor personnel to facilities to conduct approval of basic physics program onsite phase is scheduled for approx 2 wk beginning 800619 List of authorized NRC personnel sent to PEOPLE'S L. Region 3, Chicago, Office of the Director 80/06/05 4pp

8006180014 Forwards: "Division Nuclear Power Station 800619 Emergency Response Plan Exercise," in verify Comm Ed emergency plan
PEOPLE'S L. Commonwealth Edison Co. 80/06/19 2pp

--8006180018 "Division Nuclear Power Station 800619 Emergency Response Plan Exercise"
* Commonwealth Edison Co. 80/06/19 43pp

8006180090 Response to NRC 800425-26, 0501-09 & 20 ltr requesting addl info re guard training & qualification plans Requests that response submit data be extended to 800604
PEOPLE'S L. Commonwealth Edison Co. 80/06/19 1p

F. Operating license stage documents & correspondence

8006180018 Forwards addl TRS-2 related requirements to operating reactor license requirements for TRS Action Plan include shifts scheduling, licensing exams & license dissemination of operating experience Response requested within 30 days
EISENHART, D. D. Division of Licensing 80/06/07 180pp

8006180014 Summary of 800425-26 meeting w/Mark I owners group in San Jose, CA re confirmatory analysis & testing program concerning Mark I containment long-term program
EISENHART, D. Assistant Director for Plant Systems 80/05/09 8pp

8006180122 Requests comments on NUREC-0077, "Potential For Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Contain. Pumping." Proposed review procedure & implementation schedule sent
EISENHART, D. D. Division of Licensing 80/05/19 72pp

8006180042 Application to amend License 800-2, 800-11, 800-25, 800-29 & 800-30 identifying tech. updates, submitted as Tech Spec change request in response to NRC 800510 ltr
NAUGHTON, M. F. Commonwealth Edison Co. 80/05/20 2pp

--8006180072 Tech Spec change request for Tech Specs Sections 3.0-1.2.2.1 & 3.0-1.2.2.2 & 3.0-1.2.2.3 re redefinition administrative controls, safety limits, limiting safety gap setting & limiting conditions for operation
* Commonwealth Edison Co. 80/05/20 42pp

8006180049 Ltr to all NRC licensees forwarding "Per Comment" edition of NUREC-0459, "RWR Feedwater Valve Control Red Drive Structure Line Noise Cracking." Comments will be evaluated by NRC prior to final implementation ltr sent
EISENHART, D. D. Division of Licensing 80/06/05 20pp

8006180054 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 770006 request
JANICKA, R. F. Commonwealth Edison Co. 80/06/11 3pp

8006180037 Forwards comments to reply w/requirements & schedules in NRC 800507 ltr re addl TRS-2 related requirements Division Unit 2 is currently undergoing extensive mod & decontamination, therefore no response is provided
PEOPLE'S L. Commonwealth Edison Co. 80/06/12 1pp

8006180019 Confirms availability of EOC equipment following 2 power supply failures per 800602 request. Hook to assure availability of NRC following 2 power failures completed at Dresden & in progress at Quad Cities
JANICKA, R. F. Commonwealth Edison Co. 80/06/12 2pp

8006180015 Forwards draft NRC-20225, "Evaluation of Jet Pump Seal-Down Seal Failure at Dresden Unit 3." Rept withheld (ref 10092 780)
JANICKA, R. F. Commonwealth Edison Co. 80/06/19 1p

8006180037 Forwards response to NRC 800514 ltr requesting info re turbine drive cracking stress corrosion cracks not observed to date.
JANICKA, R. F. Commonwealth Edison Co. 80/06/23 14pp

8006180036 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CC-10, "Form 55 for Program for Nuclear Generating Station." Revised Revision 12 includes items on which equivalent education requirements will be established
PEOPLE'S L. Commonwealth Edison Co. 80/06/23 1p

G. Inspection reports; IE Bulletins & correspondence

8006180010 Forwards IE Circular 80-06, "Heat Tech Spec Inconsistency - Reactor Protection Sys Response Time." No written response required
HOFLEDER, G. Region 3, Chicago, Office of the Director 80/06/18 1p

8006170008 Forwards IE Insp Repts 80-018/80-07, 80-237/80-07 & 80-245/80-10 re 800303-0404 & nature of violation
HOFLEDER, G. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/24 2pp

--8006170012 Notice of violation from Insp on 800303-0404
* Region 3, Chicago, Office of the Director 80/04/22 1p

--8006170020 IE Insp Repts 80-018/80-07, 80-237/80-07 & 80-245/80-10 on 800303-0404 Noncompliance noted failure to follow radiation protection procedures
HOFLEDER, G. F. Region 3, Chicago, Office of the Director 80/04/22 5pp

8006180076 Forwards IE Insp Rept 80-249/80-09 on 800410-11 Noncompliance noted
EISENHART, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/24 2pp

8006180077 IE Insp Rept 80-249/80-08 on 800401-11 Noncompliance noted. Major areas inspected: reactor water cleanup equipment damage from water hammer & control rod drive sys seismic restraint
EISENHART, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch, VLM: T. Region 3, Chicago, Office of the Director 80/04/23 4pp

8006180008 Response to IE Bulletin 79-3A Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated SMC limiting. Critical state exposures will be monitored during cycle to verify projected end-of-cycle exposure
PEOPLE'S L. Commonwealth Edison Co. 80/05/19 2pp

8006180020 Forwards response to IE Bulletin 80-06, "Engineered Safety Features (ESF) Break Controls." Proposed mods identified only if present sys design may compromise protective action of equipment
PEOPLE'S L. Commonwealth Edison Co. 80/05/10 9pp

H. Periodic operating reports & related correspondence

8006180100 Forwards monthly operating repts for Apr 1980
STEPHENSON, B. D. Commonwealth Edison Co. 80/05/12 1p

--8006180102 Monthly operating repts for Apr 1980
EISENHART, D. D. Commonwealth Edison Co. 80/05/09 26pp

8006170048 Forwards monthly operating repts for Mar 1980
STEPHENSON, B. D. Commonwealth Edison Co. 80/05/09 1p

--8006170046 Monthly operating repts for Mar 1980
EISENHART, D. D. Commonwealth Edison Co. 80/05/08 1pp

I. Repairable occurrences, LERs & related correspondence

8006180020 Forwards LER 80-002/03-0
STEPHENSON, B. D. Commonwealth Edison Co. 80/05/27 1p

--8006180008 LER 80-002/03-0 on 800426 during normal shutdown repair. Intermediate range monitor IE diagnostic and block valve found to trip below Tech Specs. Caused by electrical drift trip point immediately readjusted
HOFLEDER, G. F. Commonwealth Edison Co. 80/05/25 1p

8006180011 Forwards updated LER 80-002/03-1
STEPHENSON, B. D. Commonwealth Edison Co. 80/06/03 1p

--8006180012 Updated LER 80-002/03-1 on 800128 during normal operation while performing LPCI monthly surveillance. 80-3-190-113 valve would not close. Caused by stripped screw on end of main line terminal. Screw replaced & broken overhauled
STEPHENSON, B. D. Commonwealth Edison Co. 80/06/03 1p

DOCKETED ITEMS

35

0004239819 Forwards LER 00-029/031-0
STDPHENDON, S Commonwealth Edison Co 00/06/10 1p

--0004239819 LER 00-029/031-0 -- 000521, during main steam line high flow
isolation surveillance, flow switch EPIS 2-001-2A was out of
Tech Spec limits. No apparent cause. Switch successfully
returned. Tests will continue on monthly basis.
SPBIOFF, R Commonwealth Edison Co 00/06/11 1p

0004239819 Forwards LER 00-029/031-0
STDPHENDON, S Commonwealth Edison Co 00/06/12 1p

--0004239819 LER 00-029/031-0 -- 000519, during normal operation w/reactor
level instrument surveillance in progress, level switch
LIS 2-002-38A tripped below Tech Spec limit. Cause was
instrument immediately replaced w/manufacture's repair.
HOLLAND, P Commonwealth Edison Co 00/06/10 1p

0004239819 Forwards LER 00-029/031-0
STDPHENDON, S Commonwealth Edison Co 00/06/12 1p

--0004239819 LER 00-029/031-0 -- 000519, during normal operation w/reactor
level instrument surveillance in progress, level switch
LIS 2-002-38A tripped below Tech Spec limit. Cause was
misaligned valves, switch assembly Model 4810C, Series 48100
HOLLAND, P Commonwealth Edison Co 00/06/12 1p

0004240000 TUCNEY POINT PLANT, UNIT 3

P Security; medical; emergency & fire protection plans

0004090187 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790101." Rule
adds new Section 50.40 & App R to 100FR50 and is expected
to be published in FR by end of May.
EISENHART, G Division of Licensing 00/05/19 4pp

0004130043 Forwards revised Pages 1-18 to new Page 14. Per proposed
rule 100FR50 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790101." Issued by NRC 00/05/19
1p Page 14a NRC 00/05/19
EISENHART, G Division of Licensing 00/05/22 7pp

0004110217 Notification that revised emergency plan will be submitted by
00/05/19 in response to NRC 00/05/19 ltr
WRIGHT, R Florida Power & Light Co 00/06/06 1p

0004130214 Forwards safe shutdown evaluations for auxiliary high
pressure & cable spreading mode in response to NRC 790129
request for fire protection (see Regulatory control) via
assess safe subcritical core conditions after reactor trip
WRIGHT, R Florida Power & Light Co 00/06/09 21pp

0004090036 Notification of 0004019 meeting w/ULI in Bethesda, MD to
discuss fire protection program & implementation of App R
GROTHWILLER, M Operating Reactors Branch 1 00/06/09 2pp

0004240192 Forwards proposed revision to emergency plan App A to be
submitted under separate cover Implementation to begin by
01/01/01, depending on resource availability & final resolution
of open issues. Plan withheld (see Policy Act)
WRIGHT, R Florida Power & Light Co 00/06/19 1p

0004240191 Advice that will be re-evaluated Section 3.1.2 of NRC
790129. Fire protection SAR, Supplemental based on outside wall
of final generator bldg after better means to reduce
potential final generator bldg damage
WRIGHT, R Florida Power & Light Co 00/06/20 1p

G Adjudicatory correspondence

0004240030 Requests that NRC advise Board members of projected dates
for issuance of draft & final Tech Spec to allow them to
discuss scheduling of proceedings re issuance of OL amendments
Certificate of Svc ent
REID, H P Licensure, Hearings, Review & Trial 00/06/23 4pp

H General correspondence

0004300476 Responds to 000510 ltr re Facility EIR EIR prepared for all
CP & OL applications EIR preparation process discussed
GOLDEN, R C Hearing Branch 2 00/05/06 2pp

0004090188 Ack receipt of 000408 & 0007 ltr. Discusses criteria used
in granting or denying amendment requests 00/05/08
"Evaluation of Reactor Generator Tube Rupture Events," and
S&S ent
WRIGHT, R A Operating Reactors Branch 1 00/05/20 2pp

I Antitrust correspondence

0004040137 Notice by Orlando Utility Commission to withdraw intervention
& request to institute proceedings re Commission 790127
order City of Orlando petitioner & 00/06/06 settlement
resolved issues w/Florida & Certificate of Svc
WRIGHT, R C Orlando, FL 00/06/10 1p

P Operating license stage documents & correspondence

0004090188 Forwards add TRS-2 related requirements to operating
reactor license requirements for NRC Action Plan. Includes
short naming, licensing exams & licensee dissemination
of operating experience. Response requested within 30 days
EISENHART, G Division of Licensing 00/05/07 13pp

0004130132 Requests comments on 00/05/07, "Potential for Low Fracture
Toughness & Localized Buckling on PWR Steam Generator &
order Control Pump Nozzle." - Proposed review procedure &
implementation schedule ent
EISENHART, G Division of Licensing 00/05/19 7pp

0004090188 Corrects & supplements 000510 ltr re steam generator repair
Announcing reply will be submitted annually by 00/05/20
improvements designed to enhance secondary water chemistry
control being implemented
WRIGHT, R Florida Power & Light Co 00/05/27 2pp

0004090076 Forwards evaluation of 791220 response to NRC 790101
requirements for auxiliary feedwater. See Requests response
to comments on 00-4 & 00-2 re confirmation of compliance w/
revision to Recommendation 2 within 45 days
WRIGHT, R A Operating Reactors Branch 1 00/05/20 3pp

0004090097 "Proposed amend to Facility, OL, 00/05/21 & 00/05/21, Units 1
re Reactor Power Shift, Check-Turning Point Units 3 & 4."
Informal reply
WRIGHT, R C 00/05/21 PWR A-0035 00/06/09 7pp

0004090201 Forwards info supplementing response to NRC 790129 ltr re
replacement purge valves. Provisions are adequate to practice
failure of valves to close due to entrained debris in fluid
stream
WRIGHT, R Florida Power & Light Co 00/06/03 4pp

0004090042 Advises of intention to begin repair of Unit 4 steam
generator in Oct 1991 & Unit 3 in Oct 1992. Requests that
NRC begin preparation of EIR on Unit 3.3.3 proceeding re
amend to OL can be completed
WRIGHT, R Florida Power & Light Co 00/06/03 1p

0004090170 Application to amend App A of Licenses 00/05/31 & 00/05/41,
changing Tech Spec, Pages 3.2-2 & 3.2-4, to reflect results
of revised ECCS analysis of power distribution limits for
25% steam generator tube plugging. Reactors Tech Spec 00/05/31,
WRIGHT, R C Florida Power & Light Co 00/06/06 2pp

--0004090170 Revised Tech Spec, Pages 3.2-3 & 3.2-4 for Amend to App A of
Licenses 00/05/31 & 00/05/41. Reflects results of revised ECCS
analysis of power distribution limits for 25% steam
generator tube plugging
Florida Power & Light Co 00/06/05 2pp

--0004090177 "ECCS Analysis, 25% Steam Generator Tube Plugging"
00/05/27, A C Florida Power & Light Co 00/06/08 31pp

0004100073 Forwards info 00/05/27 ltr re proposed Amend to OL
pertaining steam generator repairs. Corrects & supplements
00/05/19 ltr re NRC
WRIGHT, R A 00/06/06 4pp

--0004100073 Corrects & supplements 00/05/19 ltr re proposed Amend to
OL, permitting steam generator repairs. Includes approved
various plant improvements, including installation of
condensate polishing demineralizers
WRIGHT, R C Florida Power & Light Co 00/05/27 2pp

0004090097 Forwards info re add TRS-related requirements per
00/05/07 ltr. Includes staff meeting, revising scope & criteria
of licensing exam, procedures for feedback of operating
experience to plant staff & PWR vendor rep.
WRIGHT, R C Florida Power & Light Co 00/06/12 3pp

DOCKETED ITEMS

0006240263 Request extension until 000001 to incorporate MEC proposed changes into Tech Specs as discussed in L-103-107 like effect of shared gas will need to be investigated & specs will need to be reviewed to determine applicability of 075 3 0 0 5 5 04105 R E Florida Power & Light Co 00/06/16 jp

8006280327 Requests that any info re plants or animals in site vicinity listed or proposed to be listed as endangered species be provided for preparation of EIS per annual review WARE, S A Operating Reactors Branch 1 08/06/79 Zgg

D Inspection reports, IE Bulletins & correspondence

80660903470 Forwarded RE: Insp Repts. 88-250/80-14 & 88-251/80-12 on
800850 & 15 No nonCompliance noted
HURFAY-C E Region 2, Atlanta, Weather Construction & Engineer
Support Branch 80/05/01 Top

--0004509473 2E Insp Repts 90-250/80-14 & 50-251/80-12 on 809410 & 11 Noncompliance noted Major areas inspected const status & action on previous Insp findings
REASON: J.R. Region 2: Atlanta, Reactor Construction & Engineering Support Branch WELCOX, J.D., HCPARTLAND, C.R. Region 2: Atlanta
Office of the Director 86/04/00 3pp

0606060509 Forwarded IE Bulletin 80-11, "Masonry Wall Design " Request
action & written response IE info Notice 79-20.
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
D'NEILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/08
Rep

0000000000 Forwarded in Bulletin 80-12, "Decay Heat Removal Sys
Operability," Requires action & response within 30 days
RE Info Notice 80-20, "Loss of Decay Heat Removal Capability
at Davis-Besse Unit 1 While in Refueling Mode" and
D'WELLY, J P Region 2 Atlanta, Office of the Director 80/05/08
Doc

0006209107 Fernando IE Circular 00-11. "Emergency Diesel Generator Lube Oil Cooler Failed." No written response required
D'MELLIV, J. P. Region 2, Atlanta, Office of the Director 00/05/13
One

9004600013 Act receipts of 900318-0321 & 0301 (hrs informing NRC of steps taken to correct violations noted in DE Insp Repts 90-250/79-26, 90-251/79-26, 90-252/79-23 & 90-269/79-22)
HUNTPW-C E Region 2, Atlanta, Reactor Construction & Engineering
Dussart Branch 00/05/19 1a

--8006400021 Responds to NRC 791219 ltr re violations noted in IE Insp
Repts 50-250/79-25, 50-251/79-25, 50-335/79-25 & 50-389/79-22
Corrective actions CA procedures will be revised w/out
compliance achieved by 800731
UNR30.R E Florida Power & Light Co 80/05/01 kp

--0004040005 Response to NRC 790210 & 800220 ltr re violations noted in
 IE Insp Rpts 80-208/79-05-50-250/79-35-50-335/79-03
 & 80-099/79-02 Corrective actions QA procedures will be
 revised re implementation of 10CFR21
 04020.R R Florida Power & Light Co 80/03/20 Dps

0006170155 Ack receipt of 060509 ivr informing HRC of steps taken to correct violations noted in DE Insp Repts 00-203/03-08 & 00-201/00-08
STPH, J. P. Jones, 2 - Atlanta, Fuel Facility & Materials Safety Branch, 06/05/09 ip

--00017617] Response to NRE 000424 for re violations noted in IE Insp
Repts SO-280/09-08 & SO-291/09-00 Corrective actions
personal counseled in correct procedural compliance
Notation made on callist tickler card
GRI14.8 E Florida Power & Light Co SO/05/17 Sop

--000417017z Forward 1K insp Repts SO-030/80-08 & SO-231/80-08 on
800323-08 & notice of violation
800408 J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 80/04/24 2pp

* Region 2: Atlanta, Office of the Director 80/04/23 1p

--00457018Z DE INTP Reps: 80-250380-00 & 80-251188-00 on 800325-20
Noncompliance noted failure to have & follow written
procedures for radioactivity counting equipment
IDENTIFICATION: 2 R Region 2, Atlanta, Office of the Director
GROUP: 0 Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 08/04/20 9pp

0004100037 AKA receipt of 000937 ltr informing ARE of steps taken to correct violations noted in DE Insp Rpts 88-250/08-10 & 90-251/00-10
LEADS, R C Region 6, Atlanta, Reactor Construction & Engineering Support Branch, 00/05/00, 1p

--B06198221 Extends to HRC B00454 ltr re violations noted in IE Se
Repts 90-050/00-10 & 90-051/00-10 corrective actions
preventative maint to be performed on critical portions of
plant communications sys
WFOIC, R E Florida Power & Light Co. 00/05/97 4pg

--0036105624 Confidential conversation w/ Vogt-Laurel, 4448 Response to
RE Resp Reply 00-290/00-10 & 00-291/00-10 will be submitted
by 000509
00010-F C Florida Power & Light Co 00/05/07 1a

--8006189528 Forwards IE Insp Repts 50-250/00-10 & 50-251/00-10 as
060201-29 & notices of violation & deviation
LEHIS/R C Region 2, Atlanta, Reacher Construction & Engineering
Buckner Branch, Doraville, Ga.

--006680002 Notice of violation from insp on 800801-29
* Region II, Atlanta, Office of the Director 80/04/02 1p

-000100013 Notice of deviation from comp in 000200-29
* Region 2, Atlanta, Office of the Director 80/04/02 1p

--B00410003A RE 1st Regt 89-230/03-10 & 89-231/00-10 as 000201-29
Intercompliance noted failure to generate final approved joint
procedures for auxiliary feedwater
VOSTILK, R Region 2, Atlanta, Office of the Director
MORTILK R Region 2, Atlanta, Research Operations Nuclear Support

0000000000 Submit supplemental response to IE Bulletin 79-25.
Failures of Washington SPD Rulings on Safety-Related Ops -
Rulings are tested monthly by licensed operations personnel
Ruling failures/maint & testing are documented
using a 5 x 8 inch card. See also: 0000000000

0006190846 Forwards response to IE Bulletin 79-013. "Environ
Qualification of Class IE Equipment" W/0 encl
001010.R & Florida Power & Light Co. 00/06/02 1p

0004200212 Acs receipt of 000521 ltr informing NRC of steps taken to correct deviation noted in BE Insp Repts 92-280/00-13 &
92-281/00-13
LEADS: C Region 2: Atlanta, Reactor Operations Nuclear Support
Branch 00/06/04 1p

--00462700016 Request to NRC 003425 for re deviation noted in EE Insp
Repts 50-250/80-15 & 50-251/80-13 Corrective actions had
initiated to install audible & visual alarm for loss of
voltage to fire pump
WFM:RME Florida Power & Light Co 03/05/21 App

--0000202219 Permaris LE jump Repts 90-250/90-13 & 90-251/90-13 as
000021-31 & notice of derivation
LENG-R E Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 08/04/95 App

--8606200222 Notice of deviation from Insp an 800301-21
* Region 2, Atlanta, Office of the Director 06/04/23 lp

0004200327 IE Inp Regis 50-250/50-15 6 50-281/80-13 en 000301-21
Noncompliance noted fire pumps inoperable for 17 days due
to bracket left open following maint
MARTIN W D Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch VOOE-LOWELL R J Region 2, Atlanta, Office of
Director 08/04/82 App

0000000000 Forward response to IE Bulletin 74-27. "Loss of Non-Class
IE instrumentation & Central Power Syst Was During
Operation". Power restoration to vital ac or dc buses is
accomplished per established plant operating procedures
MARIA-R E Florida Power & Light Co 00/06/88 3pp

0002230104 Forward supplemental response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation". Each alarm associated with loss of power to bus is addressed in appropriate amendment list.

00010-0 0 Florida Power & Light Co 00/06/06 2pp

006290304 Response to IE Bulletin 80-18 Sufficient hardware,
reference, diversity, reliability & control exist to handle
loss of decay heat removal occurrence
UNREQ. E E Florida Power & Light Co 80/06/88 Zpp

0004300079 Response to 14 Bulletin 00-05 Adequate measures to protect refueling water storage tank against vacuum conditions have been taken no more required
UNR15.R E Florida Power & Light Co 00/06/10 2pp

R Periodic operating reports & related correspondence

0004300474 Forwards monthly operating report for May 1990
00R10T.A D Florida Power & Light Co 00/06/07 1p

0004300471 Monthly operating report for May 1990
00R10T.V T Florida Power & Light Co 00/06/07 3pp

0004300474 Monthly operating report for May 1990
00R10T.V T Florida Power & Light Co 00/06/07 4pp

0004300474 Monthly operating report for May 1990
00R10T.V T Florida Power & Light Co 00/06/07 4pp

S Reportable occurrences, LERs & related correspondence

0004300499 PMS-11-00-013 on 000516 bomb threat was received by Central Dispatch, Metropolitan Dade County Public Safety Dept. Licenses conducted search; no bomb was found
H0043.J C 0100P01.E Region 2, Atlanta, Office of the Director NRC 00/05/19 3p

0004300505 Forwards LER 00-007/02L-0
00R10T.A D Florida Power & Light Co 00/05/26 1p

0004300503 LER 00-007/02L-0 on 000494 during planning & implementation of surveillance per Tech Spec 4.13 & 4.14 unit electrical penetration fire barriers found nonfunctional. Covered by incomplete installation barriers repaired
00R0P00A.H A Florida Power & Light Co 00/05/26 2pp

0004300508 PMS-11-00-006 on 000527, licensee was informed by Westinghouse that nonconformative error was found in computer inputs used Feb. 1979 to calculate peak flux box channel factor for fuel assemblies
00R10.J C 0100P01.E Region 2, Atlanta, Office of the Director 00/05/28 1p

0004300505 Forwards LER 00-011/01T-0
00R10T.A D Florida Power & Light Co 00/06/10 1p

0004300504 LER 00-011/01T-0 on 000507, unit was notified by NRC vendor that nonconformative error had been discovered in computer inputs used in Feb. 1979 10CFR50.40 App H LSCA analysis caused by personnel error
00R0P00A.H A Florida Power & Light Co 00/06/10 2pp

0004300501 Forwards LER 00-009/03L-0
00R10T.A D Florida Power & Light Co 00/06/10 1p

0004300505 LER 00-009/03L-0 on 000511 while performing OP 14024 3, when generator protection channels periodic testing caused trips of 31404 00-075 & 00054 found nonconformative. Covered by instrument drift diagnostics reset
00R0P00A.H A Florida Power & Light Co 00/06/10 1p

0004300507 Forwards LER 00-010/03L-0
00R10T.A D Florida Power & Light Co 00/06/12 1p

0004300506 LER 00-010/03L-0 on 000514 during normal operation process radiation monitors R-11 & R-12 were out of spec for approx 3 hrs. Caused by failure of air sampling blower due to normal wear. Blower repaired & monitor returned to spec
00R0P00A.H A Florida Power & Light Co 00/06/10 1p

DOCKET 00-031 TURNER POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

0004300487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50.48 & App B to 10CFR50 & is expected to be published in FR by end of May
00R0000T.D S Division of Licensing 00/05/19 4pp

0004300503 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 000519 1tr Page 14a not encl
00R0000T.D S Division of Licensing 00/05/22 2pp

0004300517 Notice that revised emergency plan will be submitted by 000519 in response to NRC 000510 1tr
UNR10.R E Florida Power & Light Co 00/06/06 1p

0004300504 Forwards safe shutdown evaluations for auxiliary bldg hallway & cable spreading rack in response to NRC 790207 request for fire protection info. Reactivity control app ensures safe subcritical core conditions after reactor trip
UNR10.R E Florida Power & Light Co 00/06/09 21pp

0004300506 Notification of 000419 meeting w/WHI in Dekalb, MD to discuss fire protection program & implementation of App B
00R0P00A.H Operating Reactors Branch 1 00/06/09 2pp

0004300502 Forwards proposed revision to emergency plan app to be submitted under separate cover. Implementation to begin w/ 010101 depending on resource availability & final resolution of open issues. Plan updated. Trial Plans Act
UNR10.R E Florida Power & Light Co 00/06/10 3p

0004300506 Advice that unit has re-evaluated Section 3.12 of NRC 790201 fire protection. BDR sprinkler heads on outside wall of diesel generator bldg offer better means to reduce potential diesel generator vapor damage
UNR10.R E Florida Power & Light Co 00/06/10 1p

G Adjudicatory correspondence

0004300506 Requests that NRC advise Board members of projected dates for issuance of draft & final EIS to enable parties to discuss scheduling of proceedings re issuance of EIS awards. Certificate of Dec encl
00R10.H F Louisiana-Nuclear-Reg-Agency & Tall 00/06/20 4pp

H General correspondence

0004300505 Response to 000410 its re facility EIS EIS prepared for all CP & CL applications. EIS preparation process discussed
00R0000T.D S Hearing Division 2 00/05/06 2pp

0004300508 Ack receipt of 000402 & 00029 1tr. Dismisses criteria used in granting or denying award requests. NRC00-0401.
"Evaluation of Steam Generator Tube Rupture Events" encl
UNR10.R A Operating Reactors Branch 1 00/05/20 2pp

I Antitrust correspondence

0004300507 Notice by Orlando Utility Commission to withdraw intervention & request to institute proceeding re Commission 790797 order City of Orlando, petitioner & unit 000405 petitioner resolved issues. Affidavits & Certificates of Dec
00R10.H C Orlando, FL NRC00.H C Univ. & C 00/06/30 4pp

P Operating license stage documents & correspondence

0004300505 Forwards add TH1-2 related requirements to operating reactor license requirements for TH Action Plan include shifts, training, licensing exams & licensee dissemination of operating experience. Response requested within 30 days
00R0000T.D S Division of Licensing 00/05/07 15pp

0004300502 Request comments on NRC00-0377, "Potential for Low Pressure Turbine & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Mappings." Proposed review procedure & implementation schedule encl
00R0000T.D S Division of Licensing 00/05/19 72pp

0004300503 Corrects & supplements 000318 1tr re steam generator repair. Monitoring reports will be submitted annually by 000321. Implementation designed to enhance secondary water chemistry control being implemented
UNR10.R E Florida Power & Light Co 00/05/27 2pp

0004300505 Forwards evaluation of 791205 response to NRC 790104 requirements for auxiliary feedwater. Has Requests responses to comments on 00-4 & 0L-3 & confirmation of conference w/ revision to Recommendation 2 within 45 days
UNR10.R A Operating Reactors Branch 1 00/06/30 3pp

0004300507 "Proposed Amend to Facility CLA 00R-01 & 00R-01, Delta 5 w/ Reactor Power Shifts Check/Trapping Point Units 3 & 4." Internal Page
00R10.H C EDCO, Inc. PWR A-020 0004000047 00/05/01 7pp

DOCKETED ITEMS

- 000170897 "Schematic Control Diagram Engine Control & Generator Excitation Standby Diesel Generator 2"
* Sargent & Lundy, Inc. 7/6/07/07 1p
- 000170902 "Schematic Diagram Reactor Core Isolation Cooling-Part 4"
* Sargent & Lundy, Inc. 02/02/07 1p
- 000170907 "Relaying & Metering Diagram Residual Auxiliary Transformer 12 & 4140 Volt Buschings 12 & 14"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000170919 "Relaying & Metering Diagram 4140 Volt Buschings Buses 13-1 & 14-1"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000170916 "Schematic Control Diagram 4140 Volt Buses 13-1 & 14-1 Main Feed Breakers"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000170922 "Schematic Control Diagram 4140 Volt Bus 13-1 Standby Breaker 1/2 Feed Breakers"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000170926 "Schematic Control Diagram 4500 Volt Bus 14-1 Standby Diesel 1 Feed 5 Bus Breaker"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000170932 "Schematic Control Diagram 480 Volt Transformer 10 & 19 & 10 & 19 Bus Breakers"
* Sargent & Lundy, Inc. 7/6/03/09 1p
- 000324090 Response to NRC 000425, 30,0501, 09 & 20 ltr requesting add info re guard training & qualification plans Requests that response be submitted. Date to be extended to 03/05/08
NRC/REG-0.0 Division of Licensing 03/05/08 1p
- H General correspondence
- 000120092 Response to 000480 ltr requesting response to J Smith concerns re radwaste dumping at facility Radwaste produced as result of plant operation shipped offsite for burial at licensed burial site
DISEMB, W J Office of the Executive Director for Operations 03/05/08 1p
- 000120094 Requests Response to J Smith ltr re radwaste dumping at facility
SAILOR, C T House of Rep 03/04/15 2pp
- F Operating license stage documents & correspondence
- 000309013 Forwards add TRS-2 related requirements to operating reactors licensees requirements for TRS Action Plan include staff training, licensing plans & licensee dissemination of operating experience Requests requested within 30 days
EISENHART, D O Division of Licensing 03/05/07 13pp
- 000403014 Summary of 000402-03 meeting with 3 owners group in San Jose, CA re certification analysis & testing programs concerning West 1 replacement long-term program
GRIFFIN, J Assistant Director for Plant Systems 03/05/07 0pp
- 000160122 Requests comments on NRC02-0077, "Potential for Low Pressure Turbine & Low Pressure Turbine on PWR Steam Generator & Reactor Coolant Pump Supports - Proposed review procedure & implementation schedule and"
EISENHART, D O Division of Licensing 03/05/19 72pp
- 000303042 Application to amend licensees 09P-2, 09P-19, 09P-23, 09P-24 & 09P-25, clarifying term "operable," submitted as Tech Op: change request in response to NRC 000419 ltr
HUGHSTON, W F Commonwealth Edison Co 03/05/03 3pp
- 000300072 Tech Spec change request for Tech Spec Section 1 G-1 2.2.1 & 2.2.2 2.2.3 & 2.2.4 & 2.2.5 re partial-load administrative controls, safety limits, limiting safety gas setting & limiting conditions for operation
* Commonwealth Edison Co 03/05/03 48pp
- 000303098 Ltr to all 30 licensees forwarding "For Comment" edition of NRC02-0019, "30 Reactor Neutronic & Control Rod Drive Return Line Failure Checking - Comments will be evaluated by NRC prior to final implementation ltr and"
EISENHART, D O Division of Licensing 03/04/05 22pp
- 000409036 Forwards proposed amend to 01, to extend end-of-cycle shutdown operation Class 11 ltr and
JAMES, R F Commonwealth Edison Co 03/06/06 4pp
- 000500032 Proposed amend to Classifying licensed shutdown limit from 207 to 400 reactor power forwards supporting documentation
* Commonwealth Edison Co 03/06/06 18pp
- 000190406 Forwards verification of analysis program used for determining voltages for partially electric distribution net per 710005 request
JAMES, R F Commonwealth Edison Co 03/06/11 3pp
- 000190307 Forwards commitments to comply w/requirements & schedule in NRC 000507 ltr re add TRS-2 related requirements Sweden SW-1 is currently undergoing extensive test & demonstration therefore no response is provided
PEDERSEN, L L Commonwealth Edison Co 03/06/12 10pp
- 000190419 Confirms availability of 0005 equipment following dc power supply failure per 000429 request Made to ensure availability of NRC facility of power failure completed at Sweden 5 in progress at Quad Cities
JAMES, R F Commonwealth Edison Co 03/06/12 2pp
- 000500077 Forwards response to NRC 000516 ltr requesting info re turbine start starting stress corrosion cracks not observed to date
JAMES, R F Commonwealth Edison Co 03/06/23 16pp
- 000507036 Forwards revised Revision 11 & 12 consisting of Page 1-7 of 03-19, "Code No 06 Program for Nuclear Generating Stations - Revised Revision 11 and 12" which have an which equivalent education requirements will be established
PEDERSEN, L L Commonwealth Edison Co 03/06/23 1p
- 0 Inspection reports, IIR Bulletins & correspondence
- 000323030 Forwards waste packaging ltr re 000323-14 No noncompliance noted
STON, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 03/04/07 2pp
- 000323041 Waste packaging ltr re 000323-14 No noncompliance noted Major areas inspected licensee-shipped vehicles inspected for compliance w/DOT & NRC regulations including shipping paper & DOT placarding requirements
FOTTER, J P Region 4, Atlanta, Fuel Facility & Materials Safety Branch 03/05/08 4pp
- 000400010 Forwards IF Circular 00-00, "04M Tech Reg Inconsistency - Reactor Protection Sys Response Time" No written response required
MORLEY, J G Region 3, Chicago, Office of the Director 03/04/10 1p
- 000300015 Forwards IE ltr Repts 30-254/00-07 & 30-265/00-10 re 000329-27 No noncompliance noted
DAVIS, A H Region 3, Chicago, Fuel Facility & Materials Safety Branch 03/04/22 2pp
- 000400010 IE ltr Repts 30-254/00-07 & 30-265/00-10 re 000329-27 No noncompliance noted Major areas inspected initial training & retraining of licensed & unlicensed personnel & licensed operator requalification training
SMITH, R E Region 3, Chicago, Office of the Director 03/04/17 4pp
- 000400020 Forwards IE ltr Repts 30-254/00-07 & 30-265/00-10 re 000401-02 No noncompliance noted
HEISBROCK, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 03/05/07 3pp
- 000400020 IE ltr Repts 30-254/00-07 & 30-265/00-10 re 000401-02 No noncompliance noted Major areas inspected initial training & retraining of licensed & unlicensed personnel & licensed operator requalification training
SMITH, R E Region 3, Chicago, Office of the Director 03/04/17 4pp
- 000400035 Forwards IE ltr Repts 30-254/00-10 & 30-265/00-10 re 000401-02 No noncompliance noted
HEISBROCK, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 03/05/16 2pp

- 0004020078 IE Insp Repts 90-04/04-10 & 90-26/04-10 on 000327-0507 His noncompliance noted Major areas inspected operational safety, emergency shutdown, maintenance & surveillance. SFDGMB, R.L., CHS00007895.H Region 3, Chicago, Office of the Director 00/05/15 3pp
- 0004030000 Responds to IE Bulletin 79-03-03 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated BRC loading. Control blade exposures will be monitored during cycles to verify predicted end-of-cycle exposure. REPLED, D.L. Commonwealth Edison Co 00/05/19 2pp
- 00040300530 Forwards response to IE Bulletin 80-04-06 "Engineered Safety Features (ESF) Reset Controls." Proposed model identified only if present key design may impede protective action of equipment. REPLED, D.L. Commonwealth Edison Co 00/05/10 3pp
- R Periodic operating reports & related correspondence
- 0004100070 Forwards monthly operating repts for May 1980. KULVIAMAKIS, H. Commonwealth Edison Co 00/05/30 1p
- 0004100084 Monthly operating repts for May 1980. Commonwealth Edison Co 00/05/30 20pp
- 0004100034 Forwards list of tests, tests & experiments completed during May 1980 & summary of safety evaluation. KULVIAMAKIS, H. Commonwealth Edison Co 00/06/02 2pp
- R Reportable occurrences, LERs & related correspondence
- 0004040190 PND-111-00-098 on 000519, approx 13 CI noble gases were released from offgas chemical absorber vss directly to main chimney when operator accidentally opened bypass valve. Motion being followed by resident inspector. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/20 1p
- 0004101041 Forwards LER 80-01/03L-3. KULVIAMAKIS, H. Commonwealth Edison Co 00/05/23 1p
- 0004101031 RER 80-01/03L-0 on 000429, reactor recirculation meter generator set 1A tripped due to low oil pressure from tube oil pump 1A1 trip. Possible caused by contractor personnel dropping mail on generator set control cabinet. SHULTZ, J. Commonwealth Edison Co 00/05/23 3pp
- 0004101004 Forwards LER 80-01/03L-3. KULVIAMAKIS, H. Commonwealth Edison Co 00/05/27 1p
- 0004101012 LER 80-01/03L-0 on 000429, main feed breaker to MCC 19-1 tripped. Caused by excessive current trip time which allowed phase-to-phase short, incorrect to be carried back to MCC 19-1 Motor & circuit breaker replaced. HOSIER, J. Commonwealth Edison Co 00/05/27 2pp
- 0004020091 Forwards LER 80-01/03L-0. KULVIAMAKIS, H. Commonwealth Edison Co 00/05/09 1p
- 0004200092 LER 80-01/03L-0 on 000331, during manual operation of relief valve, valve 1-60-38 failed to open. HPCS & other valves operable. Caused by dirty contact on valve operator hold-in coil switch. Switch replaced & valve returned to svc. 000502. CABLE, J. Commonwealth Edison Co 00/06/09 2pp
- 0004030030 EN-80-05 notice of violation & notice of proposed imposition of civil penalty will be issued on week 000400 Action based on noncompliance re external radiation levels on vehicle exceeding limits. Will issue press release. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/18 1p
- ROCKET 80-293 PALISADES NUCLEAR PLANT
Security, medical, emergency & fire protection plans
- 0004020054 Notification that new telephone sys called Health Physics Network (HPN) has been installed at site. Sys intended for use during emergencies to link all power plants & NRC. Emergency Notification Sys hotline will also be used. HOSIER, J. Region 3, Chicago, Office of the Director 00/04/18 2pp
- 0004020048 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule added new Section 50.40 & App 8 to 10CFR50 & is expected to be published in FR by end of May. EIDENHEIT, S.G. Division of Licensing 00/05/19 4pp
- 0004030080 Anticipate that review of safeguards contingency plan & Revision 1 dated 790601 & 800219 transmitted, complete. Requests revised plan within 30 days w/ appropriate revision marker. A date list withheld (ref 10CFR2.740). CRUTCHFIELD, D. Operating Reactors Branch 5 00/05/20 2pp
- 0004100043 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 000519. 1st Page 14a not encl. EIDENHEIT, S.G. Division of Licensing 00/05/22 73pp
- 0004040570 Requests response to mail comments for NRC review of 790323 General Training & Specification plan 8001 withheld (ref 10CFR2.740). Operating Reactors Branch 5 00/06/06 2pp
- G Addressing correspondence
- 0004050448 Discovery repts per ASD 000224 under General Interrogatories & request to produce documents on HSC initiated 000319. Poss request will file motion to compel NRC response to certain Interrogatories & documents. Related correspondence. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/04/25 2pp
- 0004100043 Motion to compel NRC to produce documents requested in HSC Interrogatories 2, 4, 5, 12, 13, 14, 15 & 17. Will will review NRC objections re other matter. Certificate of Rev encl. Related correspondence. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/14 2pp
- 0004060579 Memorandum & order granting extension until 000613 for parties to file joint or individual statements re agreement & rulings after Review repts due 000501 not required. Certificate of Rev encl. SMITH, H. Atomic Safety and Licensing Board Panel 00/06/02 2pp
- 0004100232 Memorandum & order granting CPC & NRC 000505 motion request to suspend discovery pending possible settlement of limitation of Issues Parties must file joint statement re areas of agreement & areas needing rulings by 000613. SMITH, H. Atomic Safety and Licensing Board Panel 00/06/02 1p
- 0004100123 Forwards draft agreed order on discovery re licensee physical tests. Requests that ASD enter order approving schedule. Related correspondence. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/09 4pp
- 0004100348 Order amending discovery schedule. Licenses granted until 000613 to file reply to 000514 motion to compel licensee shall respond to discovery initiated by NRC on 000525. SMITH, H. Atomic Safety and Licensing Board Panel 00/06/09 2pp
- 0004100224 Supplemental motion to compel NRC response to 000525 Interrogatories 2 through 5, 13 through 15 & 17. Will will provide relevant or necessary to determine Certificate of Rev encl. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/10 10pp
- 0004030013 Response to NRC 000418 Interrogatories re civil penalty proceedings including info re Sept 1979 discovery of tube vibration, re 10CFR2.740 isolation valves & associated relevant release. Certificate of Rev & documents encl. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/22 35pp
- 0004030017 "Replace Heaps & Chemical Filter Testing," health physics procedure. HOSIER, J., FISHBURN, T., DAVIS, A. Region 3, Chicago, Office of the Director 00/05/22 3pp
- 0004030030 "In Place Testing of Heaps Filters & Isotone Adsorbers," effective 790501. Consumers Power Co 79/03/11 12pp

DOCKETED ITEMS

45

---0004240273 Is Insg Regis 50-259/00-12-50-260/00-11 A 50-260/00-12 wa
000000-3707 Headquarter's recent failure to demonstrate HPCI
control while when HPCI was immediately run manually
WALKER, C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch, 300 N. W. 10th St., Atlanta, GA 30303, Office of
the Director 00/04/02 App

0004250129 Asa receipt of 000525 LTR concerning HRC of steps taken to
correct violations noted in IE Insg Regis 50-259/00-12-50-260/00-11
00-260/00-12 A 50-260/00-11
WALKER, C Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/04/02 Is

---0004250144 Response to HRC 000425 LTR re violations noted in IE Insg
Regis 50-259/00-12-50-260/00-11 A 50-260/00-11
Corrective actions personnel trained on SCORIS for emergency
director duties & training records corrected
WALKER, C Tennessee Valley Authority 00/04/02 App

---0004250153 Forwarded IE Insg Regis 50-259/00-12-50-260/00-12 &
50-260/00-12 to 000345-20 & 0031 2404 A notice of
violation
WALKER, C Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/04/02 App

---0004250155 Notice of violation from insg on 000204-20 & 0029-0404
* Region 2, Atlanta, Office of the Director 00/04/02 Is

---0004250165 Is Insg Regis 50-259/00-12-50-260/00-12 & 50-260/00-12
000345-20 & 0031 2404 A notice of violation to be
designated supervisor, to emergency director, to keep
training records in order, to prepare training procedures
WALKER, C Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/04/02 App
WALKER, C Region 2, Atlanta, Office of the Director 00/04/02 App

0004260220 Forwarded investigation results in response to IE Bulletin
00-260/00-12 A 50-260/00-12
As provided in meeting with HRC beginning 000716
Review will be completed by 000101
WALKER, C Tennessee Valley Authority 00/04/02 App

8 Periodic operating reports & related correspondence

0004270001 Forwarded monthly operating reports for May 1980
ALLEN, J. L. Tennessee Valley Authority 00/04/02 Is

---0004270007 Monthly operating reports for May 1980
* Tennessee Valley Authority 00/04/02 App

9 Reportable occurrences, (RFO) & related correspondence

0004280442 Forwarded LER 00-045/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004280482 LER 00-038/03-0 on 000428, during normal operation, open for
helium channel on 00-030/03-0 found abnormal. Caused by
helium collected in helium detector Helium detector
detector noted out of sequence control planned
* Tennessee Valley Authority 00/04/02 App

0004280487 Forwarded LER 00-045/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004280497 LER 00-040/03-0 on 000428, during routine startup, valve
1-F00-227-A would not fully open after closing. Caused by
short circuit due to failure of micro switch in valve
actuator. Switches failed due to contamination in actuator
* Tennessee Valley Authority 00/04/02 App

0004280497 Forwarded LER 00-041/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004280500 LER 00-041/03-0 on 000428, during normal operation, smoke
detector in reactor bldg alarmed & would not clear. Caused by
increased detector sensitivity. Detector replaced & fire
watch established until repairs made
* Tennessee Valley Authority 00/04/02 App

0004280504 Final Part 21 report on mixed heat of steel supplied by US
Steel from which 4-inch elbows & 2-inch tees were used for
ACSCHEM requirement. Investigation conducted & closed at
45 listed facilities
WALKER, J. L. Chemtron Corp., Tube Turns Div 00/04/02 App

0004270006 Forwarded LER 00-041/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004270007 Request to LER 00-041/03-0 on 000201, analysis of containment
purge & vent test indicated potential loss of secondary
containment caused by failure of vented plant design to
consider SCOC during normal containment purge
* Tennessee Valley Authority 00/04/02 App

0004270035 Forwarded LER 00-041/03-0, supplementing 000419 LER
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004270039 LER 00-041/03-0 on 000206, during refueling found two spare
unneeded 1-inch lines on penetration 1-4V weekly are manual
isolation valve per 1 inch interval to containment. Caused by
mislabeling of 1-4V line label & similar lines noted
* Tennessee Valley Authority 00/04/02 App

0004270047 Forwarded LER 00-042/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004270050 LER 00-042/03-0 on 000206, unit at 94% power, core spray
gun 3 room cooler failed. Caused by apparent malfunction of
check valves in Reactor Control valve removed, inspected &
reinstalled
* Tennessee Valley Authority 00/04/02 App

0004270050 Forwarded LER 00-042/03-0
CALHOUN, J. R. Tennessee Valley Authority 00/04/02 Is

---0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

0004270050 LER 00-044/03-0 on 000206, while reviewing instrument buses
per IE Bulletin 2V-2, failure of 200 volt dc battery board
determined to cause feeder. Also to increase to full flow
A stable lead pump. Issue closed by power reconnection
* Tennessee Valley Authority 00/04/02 App

DOCKETED ITEMS

P Operating license stage documents & correspondence

0004679168 Forwards addl TMI-2 related requirements to operating license. Licensee requirements for TMI Station Plan include shift scheduling, licensing status & license discontinuation of operating alternatives. Response requested within 30 days. ETSB/REG-2, G Division of Licensing 00/03/07 106ps

0004690014 Summary of 000423-23 meeting w/Mark 1 safety group in San Jose, CA re confirmation analysis & testing programs concerning Mark 1 containment long-term program. ORETEL/2, J Assistant Director, Off Plant System 00/05/09 6ps

0004630122 Requests comments on 000603-0577, "Potential for Low Pressure Turbine & Lamellar Tearing at PWR Steam Generator & Reactor Coolant Pump Supports" - Proposed review procedure & implementation schedule incl. ETSB/REG-2, G Division of Licensing 00/05/09 72ps

0004679017 Notification of 000529 meeting w/Mark 1 Bethesda, MD for will presentation of proposed schedule for implementation of major work requested by NRC. CLAW-E, J Operating Reactors Branch 2 00/05/07 1p

0004600094 Notification of 000529 meeting w/Mark 1 Bethesda, MD to discuss will proposed design of post-accident sampling facilities. CLAW-E, J Operating Reactors Branch 2 00/05/07 1p

0004610086 Act receipt of 000426 ltr to HQ Harris re effect of power supply failure. RC28 performance response will be provided before 000725 as given verbally to RI Client on 000530. HILLS, L M Tennessee Valley Authority 00/06/03 1p

0004630004 Ltr to all PWR Licensees forwarding "For Comment" edition of NUREG-3609, "SUR Fawcett Reactor & Central Road Drive Return Line Hertz Cracking." Comments will be evaluated by NRC prior to final implementation. Jm incl. ETSB/REG-2, G Division of Licensing 00/06/05 22ps

0004620804 Forwards proposed changes to Facility Tech Specs per DG Element 000410 ltr & 000703 3P provisions. HILLS, L M Tennessee Valley Authority 00/06/13 2ps

0004620023 Proposed Tech Spec revisions for safety-related sys Change justifications incl. Tennessee Valley Authority 00/06/12 22ps

0004620433 Forwards info concerning turbine since per 000516 request. Continued operation of facility is justified & OLC should not be modified, suspended or reloaded based on response. DURELL, J P Tennessee Valley Authority 00/06/15 16ps

0004679049 Forwards response to NRC 000507 ltr re implementation of five addl TMI-2 Licensee learned requirements concerning shift scheduling, licensing status, license discontinuation & small break LOCA general review actions. HILLS, L M Tennessee Valley Authority 00/06/20 9ps

Q Inspection reports, IE Bulletins & correspondence

0004690016 Forwards IE Circular 00-16, "SR Tech Spec Inconsistency - Reactor Protection Sys Response Time." No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 00/09/10 2ps

0004680008 Forwards IE Bulletin 00-11, "Reactor Wall Design." Requires action & written response. IE Info Notice 79-25, "Overloading of Structural Elements Due to Pipe Support" incl. O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/08 2ps

0004680067 Forwards IE Bulletin 00-10, "Using Heat Removal Sys Availability." No written response required. IE Info Notice 80-25, "Loss of Second Heat Removal Capability at Steam Generator Unit 3 While in Refueling Mode" incl. O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/09 2ps

0004612004 Forwards IE Circular 00-19, "Emergency Diesel Generator Load D1 Cooler Failure." No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/13 2ps

0004680102 Act receipt of 000520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004680464 Response to NRC 000404 ltr re violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. Corrective actions personnel provided that procedures must be followed when testing an aux critical piping leg or equipment. HILLS, L M Tennessee Valley Authority 00/05/20 3ps

0004640167 Forwards IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 in 000507-0004 ltr re violations. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 2ps

0004640168 Notice of violation from insp on 000507-0004. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004640174 IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 on 000507-0004 Nonconformance noted failure to follow procedure in last treatment of Unit 1 MPC steam piping. DANIEL, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004640201 Act receipt of 000520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004640202 Response to NRC 000423 ltr re violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. Corrective actions personnel instructed to keep shift engineer informed of work status & key status. HILLS, L M Tennessee Valley Authority 00/05/20 2ps

0004640204 Forwards IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 on 000507-0004 Notice of violation. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 2ps

0004640207 Notice of violation from insp on 000504-0007. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004640212 IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 on 000504-0007 Nonconformance noted failure to demonstrate MPC operation when RC28 sys inoperable for test. DANIEL, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 1p

0004650123 Act receipt of 000521 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. STORR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/06/04 1p

0004650144 Response to NRC 000423 ltr re violations noted in IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13. Corrective actions personnel trained on 000416 Per emergency director duties & training records corrected. HILLS, L M Tennessee Valley Authority 00/05/20 3ps

0004650150 Forwards IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 on 000504-0007 Notice of violation. STORR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/06/02 2ps

0004650153 Notice of violation from insp on 000524-0004 & 0005-0004. Region 2, Atlanta, Office of the Director 00/06/02 1p

0004650165 IE Insp Repts 00-259/00-15, 00-260/00-14 & 00-260/00-13 on 000524-0004 Nonconformance noted failure to train designated successors in emergency director & to keep training records in order. STORR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/06/02 1p

0004650228 Forwards investigation results in response to IE Bulletin 00-05 sys main action changes. Other possible actions will be provided in monthly progress report beginning 000710. Review will be completed by 001101. HILLS, L M Tennessee Valley Authority 00/06/12 2ps

DOCKETED ITEMS

47

- B Periodic operating reports & related correspondence

- 0004170501 Forwards monthly operating report for May 1980
MEMPHIS, TN Tennessee Valley Authority 00/06/10 1p
- 0004170507 Monthly operating report for May 1980
* Tennessee Valley Authority 00/06/10 32pp
- S Reportable occurrences, LERs & related correspondence

- 0004110149 Forwards LER 00-021/024-0
COLUMBUS, TN Tennessee Valley Authority 00/06/04 1p
- 0004101016 LER 00-021/024-0 on M0506 during routine shutdown,
particulate channel 2-M0506-204 was erroneously declared
inoperable caused by failure of remote amplifier amplifier
reported failure attributed to normal aging
* Tennessee Valley Authority 00/06/04 2pp
- 0004200204 Final Part 21 report re mixed heat exchanger supplied by US
Steel from which 3-inch plates & 3-inch tubes were used to
42344PB (segment) investigations conducted & closed at
44 listed facilities
SEAW, J.L. Champion Corp., Tube Tubes Div 00/06/05 3pp
- DOCKET 00-241 II B ROBINSON PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans

- 0004090087 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 700150" - Rule
added Section 50.48 - App B to 10CFR50 is expected
to be published in FR by end of May
EISENHUT, D.G. Division of Licensing 00/05/19 4pp
- 0004130643 Forwards revised Pages 1-14 & new Page 14a for proposed
rule 10CFR50 - "Fire Protection Program for Nuclear Power
Plants Operating Prior to 700150" - Transmitted by NRC 000519
for Page 14a not sent
EISENHUT, D.G. Division of Licensing 00/05/22 73pp
- 0004090087 Forwards request for add info re fire protection program
Licensee has yet to meet all administrative control
requirements outlined in NRC 000221 The fire brigade drills
will be performed in plant to produce teamwork
W0004-S-A Operating Reactors Branch 1 00/06/05 3pp
- 0004100993 Forwards add info to utility 000218 re re facility fire
protection Add info includes inspection of pipe,
containment general area, reaction coolant pump bay area,
electrical cable penetrations & fire water pipe rupture
UTLEY, E.C. Carolina Power & Light Co 00/06/12 27pp
- 0004240212 Forwards descriptions of plant emergency area to meet end-
of-year requirements & commitments Util not planning to
construct new facilities Existing structures will serve
functions
UTLEY, E.C. Carolina Power & Light Co 00/06/10 7pp
- D Adjudicatory correspondence

- 0004110209 Notice of withdrawal from proceeding effective 000402
Certificate of withdrawal
LEWIS, R.H. Hearing Branch 2 00/05/10 2pp
- I Financial information

- 0004120011 Responds to 000500 request for comment on utility B-7
registration statement Review identified no inaccurate
statements re NRC regulatory requirements or financial info
filed with NRC
CHRISTENSEN, E.C. Hearing Division 00/06/20 1p
- P Operating license status documents & correspondence

- 0004090087 Forwards add TH-2 related requirements to operating
reactors Licensee requirements for TH-2 Action Plan include
NPPS training, licensing exam & licensee demonstration
of operating experience Response requested within 90 days
EISENHUT, D.G. Division of Licensing 00/05/07 100pp
- 0004130222 Requests comment on NUREG-0577, "Potential for Low Fracture
Toughness & Low Alloy Steels in PWR Steam Generator &
Reactor Coolant Pump Systems" - Proposed review procedure &
implementation schedule sent
EISENHUT, D.G. Division of Licensing 00/05/19 72pp
- 0004100124 Responds to 000308 re re NRC position on utility approach of
applying ASIP program for improvement of off-site ASIP
Items NRC does not concur with utility approach Program of
spare or replacement parts not to be on controls
W0004-S-A Quality Assurance Branch 00/05/22 3pp
- 0004090087 Recommendations that utility establish common baseline for future
surveillance tests Util 770029 re re 770084 report providing
test results showed lack of consistency among individual
tests Reactor re structural integrity satisfied
W0004-S-A Operating Reactors Branch 1 00/05/20 2pp
- 0004090010 Forwards utility responses to NRC 000087 questions re dedicated
shutdown test graphs & fire protection drawings sent
UTLEY, E.C. Carolina Power & Light Co 00/06/02 34pp
- 0004080520 Forwards comments re proposed amend to Tech Specs re
radiological effluent & fire protection drawings sent
to be incorporated into proposed Tech Specs Requests process
control program for solidification of radioactive wastes
W0004-S-A Operating Reactors Branch 1 00/06/02 2pp
- 0004230008 Discusses NRC generic review of secondary gas plant flow
instabilities at nuclear plants & associated with 770029,
770016 & 770019 items Forwards safety evaluation re steam
generator water hammer
W0004-S-A Operating Reactors Branch 1 00/06/02 2pp
- 0004230010 Safety evaluation re steam generator water hammer Potential
for steam generator water hammer is sufficiently low to
permit continued operation Auxiliary feedwater flow should
be limited to 400 gpm
* Office of Nuclear Reactor Regulation, Director 00/02/21 4pp
- 0004230017 Forwards request for add info re adequacy of station
electric distribution system, based on NRC review of
util 770029 & 770019 items Requests response within 30 days
W0004-S-A Operating Reactors Branch 1 00/06/02 2pp
- 0004160050 Responds to NRC 000506 re re loss of offsite power survey
TH-2 extension requested re revised electrical files
associated with transmission gas Total response to survey
should be completed by 000508
UTLEY, E.C. Carolina Power & Light Co 00/06/09 2pp
- 0004100491 Responds to NRC 000507 generic re re second set of TH-2
related requirements for operating reactors Licensee can
meet all requirements except Item A 1.3 shift training for
which 30-day extension is requested
UTLEY, E.C. Carolina Power & Light Co 00/06/11 3pp
- 0004180204 Forwards evaluation of postulated scenario plus single
active failure re capacity of auxiliary feedwater system
Overhaul drawings available in Control Files only
UTLEY, E.C. Carolina Power & Light Co 00/06/12 4pp
- 0004230004 Application for amend to License 000-22, revising containment
purge & vent valve closing time Class III Fee paid
UTLEY, E.C. Carolina Power & Light Co 00/06/20 2pp
- 0004230009 Revised Tech Specs re containment purge & vent valve
isolation time
* Carolina Power & Light Co 00/06/30 3pp
- D Inspection reports, IE Bulletins & correspondence

- 0004200602 Forwards license response re deviation noted in IE Insp
Rep 00-241/79-29 Arrangement of control & ventilation control
valves does not meet applicable provisions of NPPA Sub E
Code
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/03/11 1p
- 0004130009 Forwards IE Insp Rep 00-241/80-07 on 000201-0402 No
noncompliance noted
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/04/29 2pp
- 0004130009 IE Insp Rep 00-241/80-07 on 000201-0402 No noncompliance
noted Major areas inspected operations, LERs & IE Bulletin
0001000
MURPHY, C.E. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/04/29 2pp

DOCKETED ITEMS

000405093 Forwards IE Bulletin 00-10, "Masonry Wall Design - Requires action & written response IE info letter 78-20.
Overloading of Structural Elements Due to Pipe Support Loads" and
O'REILLY, J.P. Region 2: Atlantic Office of the Director 00/05/08
Zpp

000405098 Forwards IE Bulletin 00-10, "Decay Heat Removal Sys Operability - Requires action & response within 30 days.
IE info letter 00-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 2 Available in Refueling Mode" and
O'REILLY, J.P. Region 2: Atlantic Office of the Director 00/05/09
Zpp

0004050108 Forwards IE Circular 00-10, "Emergency Diesel Generator Lube Oil Cooler Failures - No written response required"
O'REILLY, J.P. Region 2: Atlantic Office of the Director 00/05/10
Zpp

0004050472 Responds to IE Bulletin 00-12, "Decay Heat Removal Sys Operability - Operator training will include review of loss of decay heat removal incident hardware, administrative controls & adequate training
FURBER, J. Carolina Power & Light Co 00/06/03 Zpp

0004050301 Responds to IE Bulletin 00-09 re various condition resulting in damage to chemical vol control sys nuclear tanks Review & actions taken satisfy concerns of solicitor
FURBER, J. Carolina Power & Light Co 00/06/10 Zpp

0004050408 Notifies of new target dates for completion of Open Item 78-10-05 of IE Insg Regt 00-04/79 in Revision to work order program will be completed by 00/07/30 Revisions to implementing procedures will be completed by 00/02/30
STARKEY, R B. Carolina Power & Light Co 00/06/04 Zp

R Periodic operating reports & related correspondence

0004050025 Forwards monthly operating report for May 1980
STARKEY, R B. Carolina Power & Light Co 00/06/10 Zp

--0004050004 Monthly operating report for May 1980
STARKEY, R B. Carolina Power & Light Co 00/06/03 Zpp

S Reportable occurrences, LERs & related correspondence

00040500374 On 00/05/17 while operating at 40% reactor power level, power range high flux setpoint was not properly reset during quadrant power limit greater than 02. Cause under investigation. Setpoint reset & limit returned to operation
STARKEY, R B. Carolina Power & Light Co 00/05/19 Zp

0004050028 Forwards LER 00-013/001-0
STARKEY, R B. Carolina Power & Light Co 00/06/30 Zp

--0004050038 LER 00-013/001-0 on 00/05/17 while operating at 40% reactor power, radial tilt greater than Tech Spec limit was calculated via resulting power range high flux setpoint. Caused by misinterpretation of Tech Spec. Repeats reset
STARKEY, R B. Carolina Power & Light Co 00/05/20 Zpp

0004050052 Forwards replacement of Attachment 3 on steam generator insg & nuclear instrumentation number occurred. Caused by dead line dead to 1500 & three errors corrected
WILCOX, E E. Carolina Power & Light Co 00/06/08 13pp

0004050047 Forwards LER 00-013/001-0
STARKEY, R B. Carolina Power & Light Co 00/06/10 Zp

--0004050058 LER 00-013/001-0 on 00/05/06 while operating at 95% power, nuclear instrumentation number occurred. Caused by Control Rupts blow on HSE power range detector. Caused by double BSC circuit from detector N-42. Partial detector replaced
STARKEY, R B. Carolina Power & Light Co 00/06/05 Zpp

0004050072 Forwards updated LER 00-013/017-1
STARKEY, R B. Carolina Power & Light Co 00/06/10 Zp

--0004050094 Updated LER 00-013/017-1 on 00/05/17 while operating at 40% power, radial tilt calculated greater than Tech Spec limit. Caused by personnel incorrectly interpreting requirements. Personnel will be made aware of correct interpretation
STARKEY, R B. Carolina Power & Light Co 00/06/10 Zpp

DOCKET 00-062 HENTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

0004050031 Notifies that new telephone sys called Health Physics Support (HPS) has been installed at site. Sys intended for use during emergency to link all power plants & NRC. Emergency Health Physics Sys bellings will also be used
REYNOLDS, D. Region 2: Chicago Office of the Director 00/06/10
Zpp

0004050487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 70/01/01 - Rule over new Section 50.6 App F to 10CFR50 & is expected to be published in FR by end of May
KIRKENDALL, D. Division of Licensing 00/05/10 46pp

0004050515 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 70/01/01" transmitted by 00/05/09 for Page 14a not sent
KIRKENDALL, D. Division of Licensing 00/06/20 73pp

0004050034 Requests add time for completion of fire protection mod completion date of 00/09/10 has been established for fire detection-related installation - testing
HAYES, L D. Northern States Power Co 00/05/23 Zp

0004050174 Provides info re access of NRC & NRC contractor personnel to facility for operational of Health Physics program Personnel lost email
STARKEY, R B. Region 2: Chicago Office of the Director 00/05/27 Zpp

0004050430 Forwards status summary of open issues from 70/02/29 fire protection safety evaluation subject to implementation of end requirements until proposed resolutions are acceptable. Supplement to safety evaluation will be issued
1PPL10.T A. Operating Reactors Branch 2 00/05/26 Zpp

0004050108 Forwards BIE evaluations of submittals re open issues associated with fire protection 02R
1PPL10.T A. Operating Reactors Branch 2 00/06/04 Zpp

0004050091 Forwards comments on safeguards contingency plan indicating need for revisions & add. info Response must be provided within 60 days. Comments withheld (ref 10CFR27.705)
1PPL10.T A. Operating Reactors Branch 2 00/06/01 Zpp

0004050374 Forwards draft input to facility fire protection safety evaluation on items 2 & 1003, control of tank levels & 3 & 12, automatic water suppression sys Recommendations accepting key controls if control volume suppressed
HALL, R E. Brookhaven National Laboratory 00/06/13 Zpp

0004050037 Discusses submittal of final upgraded emergency plans. Extension may be necessary, depending on content of pending NRC rules on emergency plans. Schedule for emergency plan revisions targeted to meet 00/00/01 submittal date
HAYES, L D. Northern States Power Co 00/06/17 Zp

0004050206 Refuses of rejection to leave hoses connected to hydrants in hose house collection 000001. Proposed change will reduce line required to set up station in preparation for fire fighting
HAYES, L D. Northern States Power Co 00/06/10 Zp

G Administrative correspondence

0004050023 Notice of withdrawal from processing effective 00/06/02 Certificate of the end
LEWIS, S H. Hearing Branch 2 00/06/03 Zpp

F Operating license stage documents & correspondence

0004050101 Decommissioning study of Prairie Island Nuclear Generating Plant, Revision 1
JANSEN, R J. Nuclear Energy Service, Inc 00/06/23 R1 70/06/28 57pp

--0004050100 Decommissioning study of Henticello Nuclear Generating Plant, Revision 1
Nuclear Energy Service, Inc 00/06/23 R1 70/06/28 48pp

8006070160 Forward to add TH1-2 related requirements to operating reactor Licensees requirements for TH1 Action Plan include shift training, licensing exam & licensee dissemination or operating experience database requested within 30 days EES/ST-D G In review of licensing 80/08/07 100pp

--R03A0904n3 IE Insp Rept SO-262/80-07 re R03319-01 & 0487-1 Re noncompliance noted Major areas inspected plant operations small trash LDCA procedures fire protection IE Bulletin SO-23 79-286 78-10 IE Circular 79-37 IMPROVED R F, ENGLISH C. CHOLESE, W Region 3 Chicago Office the Reporter 09/09/02 2pp

8006163245 Ferrous Waste Packaging Insp Rept 00-00 on 000000 & nature of violation
DWHIS.A 8 Region 3, Chicago, Fuel Facility & Materials Safety
Branch 00/03/00 See

--2006100248 Nature of violation on 800303
+ Region 3, Chicago, Office of the Director 80005400 8a

--800610207 Waste Packaging Insp Regt 80-08 on 800303 Noncompliance
noted failure to mark tank used to transport redoxants
FLOWER, W L Region 3, Chicago, Fuel Facility & Materials Safety
Branch PSC&C Region 3, Chicago, Office of the Director
80/05/08 Zpp

8. Periodic variation versus 8 related correspondences

0006060396 Forwards Revision 1 to monthly operating rept for Apr 1980
MWER,L C Northern States Power Co 03/26/82 12

-2006040298 Monthly operating rept for Apr 1983, Revision 1
NTVAGS, A L. New York State Power Co 80/08/27 1p

006130225 Forwards monthly operating rept for May 1980
HAYEN,L G Northern States Power Co 03/06/09 1p

NYREG-2-A L Northern States Power Co 03/06/03 4a

5. *Receptible assignments*: LEMs 5 related assignments

8066000375 Forwards updated LER 79-010/00L-1
MAYER, L. © Northern States Power Co. 80/06/02 1a

--SDOW30328 Updated 79-015/03L-1 on 790712: During routine insp, steam leak from ISA Intermediate pressure feedwater heater was detected. Insulation removal revealed throughwall flaw in heater shell caused by erosion-corrosion.

8006200366 Forwards LXR 00-001/00L-0
KAYELL, D Northern Shales Power Co 03/06/12 1p

--8064200472 LBN 30-028/001-0 on 10/01/15 during normal sta
cone isolation cooling control power fuse opened Caus

SECRET 50-264 BOX CHEMICAL CD

0006190522 Response to NRC 000507 ltr re Dow Chemical Co TRIGA reactor facility computer reactor physical protection requirements
Response not received re Dow TRIGA TR1009 security plan
Security plan assets 790324 & 000325 FR rules & regulations
LMSBDR,H H Dow Chemical Co - Dow Chemical U S A Dow 03/26/99
in

© Reproduction license above documents is reserved.

9036200529 Advises that BWS-68D-001-P, "Topical Rept. Dev Sys for Solidification of Low Level Radwaste from Nuclear Power Plants," & Amend 1 to rept have been determined proprietary & will be withheld from public disclosure
MILLER, L R Standardization & Special Projects Branch 03/05/93
3pg

ROBERT TWO-STAR, MAJOR-CITY'S STATION, UNIT 2

[關於我們](#)
[服務項目](#)
[服務區域](#)
[服務時間](#)
[服務電話](#)
[服務地址](#)
[服務評價](#)
[服務建議](#)

0006200040 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used
NRPPLER, J G Region 3, Chicago, Office of the Director 80/04/36
Dex

- 0004070087 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 750101 - Rule add new Section 50.46 & App B to 10CFR50 & is expected to be published in FR by end of May
KIDENHUT, S G Division of Licensing 00/05/19 40pp
- 0004130043 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 750101." transmitted by NRC 000519
1st Page 14a not encl
KIDENHUT, S G Division of Licensing 00/05/02 73pp
- 0004070018 Forwards request for addl info needed for review of safety contingencies plan Requests addl info be submitted within 30 days of receipt of JTR Encl titled (ref)
10CFR50.7201
INDEL110.T A Operating Reactors Branch 2 00/05/27 3pp
- 0004100019 Forwards Revision 1 to draft emergency plan Emergency plan station annex also encl
PEOPLE'S D L Commonwealth Edison Co 00/04/06 3pp
- 0004100019 Draft emergency plan annex
Commonwealth Edison Co 00/03/31 40pp
- 0004100047 Revision 1 to draft emergency plan
Commonwealth Edison Co 00/03/31 13pp
- 0004170097 Forwards drawings & responses to questions re fire protection safe shutdown analysis requested in NRC 750103
1st
JANECEN, R F Commonwealth Edison Co 00/05/06 3pp
- 0004170064 "Single Line Diagram Emergency Power Sys"
Margent & Landy, Inc 70/07/00 1p
- 0004170091 "Schematic Control Diagram Engine Control & Generator
Excitation, Standby Diesel Generator 1 & 2"
Margent & Landy, Inc 70/07/00 1p
- 0004170097 "Schematic Control Diagram Engine Control & Generator
Excitation, Standby Diesel Generator 2"
Margent & Landy, Inc 70/07/00 1p
- 0004200090 Responds to NRC 000425-20, 00041-09 & 30 ltr requesting addl info re guard training & qualification plans Requests that response be submitted date be extended to 000604
PEOPLE'S D L Commonwealth Edison Co 00/04/10 1p
- H General correspondence
- 0004120082 Responds to 000415 ltr requesting response to J Smith concerns re radiactive dumping at Facility Radiactive product as result of plant operator shipped offsite for burial at licensed burial site
DIREKTS, J J Office of the Executive Director for Operations 00/05/00 1p
- 0004120084 Requests response to encl J Smith ltr re radiactive dumping at Facility
KATLBNCH, T House of Rep 00/04/15 2pp
- P Operating license stage documents & correspondence
- 0004090016 Forwards addl 10CFR related requirements re operating reactors Licenses requirements for this Action Plan include shift training, licensing exam & license cancellation of operating experience Response requested within 30 days
KIDENHUT, S G Division of Licensing 00/05/07 150pp
- 0004030054 Summary of 000422-23 meeting w/Herb J owners group in San Jose. Co re conditioners analysis & testing programs concerning Herb J containment long-term program
DIREKTS, J J Assistant Director for Plant Systems 00/05/09 8pp
- 0004100012 Requests comments on NUREG-0577, "Potential for Low Pressure Boilback & Low Pressure Boiling in PWR Steam Generator Reactor Containment Pump Bypass" Proposed review procedure & implementation schedule encl
KIDENHUT, S G Division of Licensing 00/05/19 72pp
- 0004130002 Clarification to amend Licenses 00041-09, 00041-10, 00041-20 & 00041-21 by "repeal," submitted as Tech Spec
Request re response to NRC 000410 ltr
MAURITHE, N F Commonwealth Edison Co 00/05/00 2pp
- 0004020072 Tech Spec change request for Tech Spec Sections 1-0-1 2-0-1 2-0-2 2-0-3 2-0-4 2-0-5 2-0-6 2-0-7 2-0-8 2-0-9 2-0-10 2-0-11 2-0-12 2-0-13 2-0-14 2-0-15 2-0-16 2-0-17 2-0-18 2-0-19 2-0-20 2-0-21 2-0-22 2-0-23 2-0-24 2-0-25 2-0-26 2-0-27 2-0-28 2-0-29 2-0-30 2-0-31 2-0-32 2-0-33 2-0-34 2-0-35 2-0-36 2-0-37 2-0-38 2-0-39 2-0-40 2-0-41 2-0-42 2-0-43 2-0-44 2-0-45 2-0-46 2-0-47 2-0-48 2-0-49 2-0-50 2-0-51 2-0-52 2-0-53 2-0-54 2-0-55 2-0-56 2-0-57 2-0-58 2-0-59 2-0-60 2-0-61 2-0-62 2-0-63 2-0-64 2-0-65 2-0-66 2-0-67 2-0-68 2-0-69 2-0-70 2-0-71 2-0-72 2-0-73 2-0-74 2-0-75 2-0-76 2-0-77 2-0-78 2-0-79 2-0-80 2-0-81 2-0-82 2-0-83 2-0-84 2-0-85 2-0-86 2-0-87 2-0-88 2-0-89 2-0-90 2-0-91 2-0-92 2-0-93 2-0-94 2-0-95 2-0-96 2-0-97 2-0-98 2-0-99 2-0-100 2-0-101 2-0-102 2-0-103 2-0-104 2-0-105 2-0-106 2-0-107 2-0-108 2-0-109 2-0-110 2-0-111 2-0-112 2-0-113 2-0-114 2-0-115 2-0-116 2-0-117 2-0-118 2-0-119 2-0-120 2-0-121 2-0-122 2-0-123 2-0-124 2-0-125 2-0-126 2-0-127 2-0-128 2-0-129 2-0-130 2-0-131 2-0-132 2-0-133 2-0-134 2-0-135 2-0-136 2-0-137 2-0-138 2-0-139 2-0-140 2-0-141 2-0-142 2-0-143 2-0-144 2-0-145 2-0-146 2-0-147 2-0-148 2-0-149 2-0-150 2-0-151 2-0-152 2-0-153 2-0-154 2-0-155 2-0-156 2-0-157 2-0-158 2-0-159 2-0-160 2-0-161 2-0-162 2-0-163 2-0-164 2-0-165 2-0-166 2-0-167 2-0-168 2-0-169 2-0-170 2-0-171 2-0-172 2-0-173 2-0-174 2-0-175 2-0-176 2-0-177 2-0-178 2-0-179 2-0-180 2-0-181 2-0-182 2-0-183 2-0-184 2-0-185 2-0-186 2-0-187 2-0-188 2-0-189 2-0-190 2-0-191 2-0-192 2-0-193 2-0-194 2-0-195 2-0-196 2-0-197 2-0-198 2-0-199 2-0-200 2-0-201 2-0-202 2-0-203 2-0-204 2-0-205 2-0-206 2-0-207 2-0-208 2-0-209 2-0-210 2-0-211 2-0-212 2-0-213 2-0-214 2-0-215 2-0-216 2-0-217 2-0-218 2-0-219 2-0-220 2-0-221 2-0-222 2-0-223 2-0-224 2-0-225 2-0-226 2-0-227 2-0-228 2-0-229 2-0-230 2-0-231 2-0-232 2-0-233 2-0-234 2-0-235 2-0-236 2-0-237 2-0-238 2-0-239 2-0-240 2-0-241 2-0-242 2-0-243 2-0-244 2-0-245 2-0-246 2-0-247 2-0-248 2-0-249 2-0-250 2-0-251 2-0-252 2-0-253 2-0-254 2-0-255 2-0-256 2-0-257 2-0-258 2-0-259 2-0-260 2-0-261 2-0-262 2-0-263 2-0-264 2-0-265 2-0-266 2-0-267 2-0-268 2-0-269 2-0-270 2-0-271 2-0-272 2-0-273 2-0-274 2-0-275 2-0-276 2-0-277 2-0-278 2-0-279 2-0-280 2-0-281 2-0-282 2-0-283 2-0-284 2-0-285 2-0-286 2-0-287 2-0-288 2-0-289 2-0-290 2-0-291 2-0-292 2-0-293 2-0-294 2-0-295 2-0-296 2-0-297 2-0-298 2-0-299 2-0-300 2-0-301 2-0-302 2-0-303 2-0-304 2-0-305 2-0-306 2-0-307 2-0-308 2-0-309 2-0-310 2-0-311 2-0-312 2-0-313 2-0-314 2-0-315 2-0-316 2-0-317 2-0-318 2-0-319 2-0-320 2-0-321 2-0-322 2-0-323 2-0-324 2-0-325 2-0-326 2-0-327 2-0-328 2-0-329 2-0-330 2-0-331 2-0-332 2-0-333 2-0-334 2-0-335 2-0-336 2-0-337 2-0-338 2-0-339 2-0-340 2-0-341 2-0-342 2-0-343 2-0-344 2-0-345 2-0-346 2-0-347 2-0-348 2-0-349 2-0-350 2-0-351 2-0-352 2-0-353 2-0-354 2-0-355 2-0-356 2-0-357 2-0-358 2-0-359 2-0-360 2-0-361 2-0-362 2-0-363 2-0-364 2-0-365 2-0-366 2-0-367 2-0-368 2-0-369 2-0-370 2-0-371 2-0-372 2-0-373 2-0-374 2-0-375 2-0-376 2-0-377 2-0-378 2-0-379 2-0-380 2-0-381 2-0-382 2-0-383 2-0-384 2-0-385 2-0-386 2-0-387 2-0-388 2-0-389 2-0-390 2-0-391 2-0-392 2-0-393 2-0-394 2-0-395 2-0-396 2-0-397 2-0-398 2-0-399 2-0-400 2-0-401 2-0-402 2-0-403 2-0-404 2-0-405 2-0-406 2-0-407 2-0-408 2-0-409 2-0-410 2-0-411 2-0-412 2-0-413 2-0-414 2-0-415 2-0-416 2-0-417 2-0-418 2-0-419 2-0-420 2-0-421 2-0-422 2-0-423 2-0-424 2-0-425 2-0-426 2-0-427 2-0-428 2-0-429 2-0-430 2-0-431 2-0-432 2-0-433 2-0-434 2-0-435 2-0-436 2-0-437 2-0-438 2-0-439 2-0-440 2-0-441 2-0-442 2-0-443 2-0-444 2-0-445 2-0-446 2-0-447 2-0-448 2-0-449 2-0-450 2-0-451 2-0-452 2-0-453 2-0-454 2-0-455 2-0-456 2-0-457 2-0-458 2-0-459 2-0-460 2-0-461 2-0-462 2-0-463 2-0-464 2-0-465 2-0-466 2-0-467 2-0-468 2-0-469 2-0-470 2-0-471 2-0-472 2-0-473 2-0-474 2-0-475 2-0-476 2-0-477 2-0-478 2-0-479 2-0-480 2-0-481 2-0-482 2-0-483 2-0-484 2-0-485 2-0-486 2-0-487 2-0-488 2-0-489 2-0-490 2-0-491 2-0-492 2-0-493 2-0-494 2-0-495 2-0-496 2-0-497 2-0-498 2-0-499 2-0-500 2-0-501 2-0-502 2-0-503 2-0-504 2-0-505 2-0-506 2-0-507 2-0-508 2-0-509 2-0-510 2-0-511 2-0-512 2-0-513 2-0-514 2-0-515 2-0-516 2-0-517 2-0-518 2-0-519 2-0-520 2-0-521 2-0-522 2-0-523 2-0-524 2-0-525 2-0-526 2-0-527 2-0-528 2-0-529 2-0-530 2-0-531 2-0-532 2-0-533 2-0-534 2-0-535 2-0-536 2-0-537 2-0-538 2-0-539 2-0-540 2-0-541 2-0-542 2-0-543 2-0-544 2-0-545 2-0-546 2-0-547 2-0-548 2-0-549 2-0-550 2-0-551 2-0-552 2-0-553 2-0-554 2-0-555 2-0-556 2-0-557 2-0-558 2-0-559 2-0-560 2-0-561 2-0-562 2-0-563 2-0-564 2-0-565 2-0-566 2-0-567 2-0-568 2-0-569 2-0-570 2-0-571 2-0-572 2-0-573 2-0-574 2-0-575 2-0-576 2-0-577 2-0-578 2-0-579 2-0-580 2-0-581 2-0-582 2-0-583 2-0-584 2-0-585 2-0-586 2-0-587 2-0-588 2-0-589 2-0-590 2-0-591 2-0-592 2-0-593 2-0-594 2-0-595 2-0-596 2-0-597 2-0-598 2-0-599 2-0-600 2-0-601 2-0-602 2-0-603 2-0-604 2-0-605 2-0-606 2-0-607 2-0-608 2-0-609 2-0-610 2-0-611 2-0-612 2-0-613 2-0-614 2-0-615 2-0-616 2-0-617 2-0-618 2-0-619 2-0-620 2-0-621 2-0-622 2-0-623 2-0-624 2-0-625 2-0-626 2-0-627 2-0-628 2-0-629 2-0-630 2-0-631 2-0-632 2-0-633 2-0-634 2-0-635 2-0-636 2-0-637 2-0-638 2-0-639 2-0-640 2-0-641 2-0-642 2-0-643 2-0-644 2-0-645 2-0-646 2-0-647 2-0-648 2-0-649 2-0-650 2-0-651 2-0-652 2-0-653 2-0-654 2-0-655 2-0-656 2-0-657 2-0-658 2-0-659 2-0-660 2-0-661 2-0-662 2-0-663 2-0-664 2-0-665 2-0-666 2-0-667 2-0-668 2-0-669 2-0-670 2-0-671 2-0-672 2-0-673 2-0-674 2-0-675 2-0-676 2-0-677 2-0-678 2-0-679 2-0-680 2-0-681 2-0-682 2-0-683 2-0-684 2-0-685 2-0-686 2-0-687 2-0-688 2-0-689 2-0-690 2-0-691 2-0-692 2-0-693 2-0-694 2-0-695 2-0-696 2-0-697 2-0-698 2-0-699 2-0-700 2-0-701 2-0-702 2-0-703 2-0-704 2-0-705 2-0-706 2-0-707 2-0-708 2-0-709 2-0-710 2-0-711 2-0-712 2-0-713 2-0-714 2-0-715 2-0-716 2-0-717 2-0-718 2-0-719 2-0-720 2-0-721 2-0-722 2-0-723 2-0-724 2-0-725 2-0-726 2-0-727 2-0-728 2-0-729 2-0-730 2-0-731 2-0-732 2-0-733 2-0-734 2-0-735 2-0-736 2-0-737 2-0-738 2-0-739 2-0-740 2-0-741 2-0-742 2-0-743 2-0-744 2-0-745 2-0-746 2-0-747 2-0-748 2-0-749 2-0-750 2-0-751 2-0-752 2-0-753 2-0-754 2-0-755 2-0-756 2-0-757 2-0-758 2-0-759 2-0-760 2-0-761 2-0-762 2-0-763 2-0-764 2-0-765 2-0-766 2-0-767 2-0-768 2-0-769 2-0-770 2-0-771 2-0-772 2-0-773 2-0-774 2-0-775 2-0-776 2-0-777 2-0-778 2-0-779 2-0-780 2-0-781 2-0-782 2-0-783 2-0-784 2-0-785 2-0-786 2-0-787 2-0-788 2-0-789 2-0-790 2-0-791 2-0-792 2-0-793 2-0-794 2-0-795 2-0-796 2-0-797 2-0-798 2-0-799 2-0-800 2-0-801 2-0-802 2-0-803 2-0-804 2-0-805 2-0-806 2-0-807 2-0-808 2-0-809 2-0-810 2-0-811 2-0-812 2-0-813 2-0-814 2-0-815 2-0-816 2-0-817 2-0-818 2-0-819 2-0-820 2-0-821 2-0-822 2-0-823 2-0-824 2-0-825 2-0-826 2-0-827 2-0-828 2-0-829 2-0-830 2-0-831 2-0-832 2-0-833 2-0-834 2-0-835 2-0-836 2-0-837 2-0-838 2-0-839 2-0-840 2-0-841 2-0-842 2-0-843 2-0-844 2-0-845 2-0-846 2-0-847 2-0-848 2-0-849 2-0-850 2-0-851 2-0-852 2-0-853 2-0-854 2-0-855 2-0-856 2-0-857 2-0-858 2-0-859 2-0-860 2-0-861 2-0-862 2-0-863 2-0-864 2-0-865 2-0-866 2-0-867 2-0-868 2-0-869 2-0-870 2-0-871 2-0-872 2-0-873 2-0-874 2-0-875 2-0-876 2-0-877 2-0-878 2-0-879 2-0-880 2-0-881 2-0-882 2-0-883 2-0-884 2-0-885 2-0-886 2-0-887 2-0-888 2-0-889 2-0-890 2-0-891 2-0-892 2-0-893 2-0-894 2-0-895 2-0-896 2-0-897 2-0-898 2-0-899 2-0-900 2-0-901 2-0-902 2-0-903 2-0-904 2-0-905 2-0-906 2-0-907 2-0-908 2-0-909 2-0-910 2-0-911 2-0-912 2-0-913 2-0-914 2-0-915 2-0-916 2-0-917 2-0-918 2-0-919 2-0-920 2-0-921 2-0-922 2-0-923 2-0-924 2-0-925 2-0-926 2-0-927 2-0-928 2-0-929 2-0-930 2-0-931 2-0-932 2-0-933 2-0-934 2-0-935 2-0-936 2-0-937 2-0-938 2-0-939 2-0-940 2-0-941 2-0-942 2-0-943 2-0-944 2-0-945 2-0-946 2-0-947 2-0-948 2-0-949 2-0-950 2-0-951 2-0-952 2-0-953 2-0-954 2-0-955 2-0-956 2-0-957 2-0-958 2-0-959 2-0-960 2-0-961 2-0-962 2-0-963 2-0-964 2-0-965 2-0-966 2-0-967 2-0-968 2-0-969 2-0-970 2-0-971 2-0-972 2-0-973 2-0-974 2-0-975 2-0-976 2-0-977 2-0-978 2-0-979 2-0-980 2-0-981 2-0-982 2-0-983 2-0-984 2-0-985 2-0-986 2-0-987 2-0-988 2-0-989 2-0-990 2-0-991 2-0-992 2-0-993 2-0-994 2-0-995 2-0-996 2-0-997 2-0-998 2-0-999 2-1000 2-1001 2-1002 2-1003 2-1004 2-1005 2-1006 2-1007 2-1008 2-1009 2-1010 2-1011 2-1012 2-1013 2-1014 2-1015 2-1016 2-1017 2-1018 2-1019 2-1020 2-1021 2-1022 2-1023 2-1024 2-1025 2-1026 2-1027 2-1028 2-1029 2-1030 2-1031 2-1032 2-1033 2-1034 2-1035 2-1036 2-1037 2-1038 2-1039 2-1040 2-1041 2-1042 2-1043 2-1044 2-1045 2-1046 2-1047 2-1048 2-1049 2-1050 2-1051 2-1052 2-1053 2-1054 2-1055 2-1056 2-1057 2-1058 2-1059 2-1060 2-1061 2-1062 2-1063 2-1064 2-1065 2-1066 2-1067 2-1068 2-1069 2-1070 2-1071 2-1072 2-1073 2-1074 2-1075 2-1076 2-1077 2-1078 2-1079 2-1080 2-1081 2-1082 2-1083 2-1084 2-1085 2-1086 2-1087 2-1088 2-1089 2-1090 2-1091 2-1092 2-1093 2-1094 2-1095 2-1096 2-1097 2-1098 2-1099 2-1100 2-1101 2-1102 2-1103 2-1104 2-1105 2-1106 2-1107 2-1108 2-1109 2-1110 2-1111 2-1112 2-1113 2-1114 2-1115 2-1116 2-1117 2-1118 2-1119 2-1120 2-1121 2-1122 2-1123 2-1124 2-1125 2-1126 2-1127 2-1128 2-1129 2-1130 2-1131 2-1132 2-1133 2-1134 2-1135 2-1136 2-1137 2-1138 2-1139 2-1140 2-1141 2-1142 2-1143 2-1144 2-1145 2-1146 2-1147 2-1148 2-1149 2-1150 2-1151 2-1152 2-1153 2-1154 2-1155 2-1156 2-1157 2-1158 2-1159 2-1160 2-1161 2-1162 2-1163 2-1164 2-1165 2-1166 2-1167 2-1168 2-1169 2-1170 2-1171 2-1172 2-1173 2-1174 2-1175 2-1176 2-1177 2-1178 2-1179 2-1180 2-1181 2-1182 2-1183 2-1184 2-1185 2-1186 2-1187 2-1188 2-1189 2-1190 2-1191 2-1192 2-1193 2-1194 2-1195 2-1196 2-1197 2-1198 2-1199 2-1200 2-1201 2-1202 2-1203 2-1204 2-1205 2-1206 2-1207 2-1208 2-1209 2-1210 2-1211 2-1212 2-1213 2-1214 2-1215 2-1216 2-1217 2-1218 2-1219 2-1220 2-1221 2-1222 2-1223 2-1224 2-1225 2-1226 2-1227 2-1228 2-1229 2-1230 2-1231 2-1232 2-1233 2-1234 2-1235 2-1236 2-1237 2-1238 2-1239 2-1240 2-1241 2-1242 2-1243 2-1244 2-1245 2-1246 2-1247 2-1248 2-1249 2-1250 2-1251 2-1252 2-1253 2-1254 2-1255 2-1256 2-1257 2-1258 2-1259 2-1260 2-1261 2-1262 2-1263 2-1264 2-1265 2-1266 2-1267 2-1268 2-1269 2-1270 2-1271 2-1272 2-1273 2-1274 2-1275 2-1276 2-1277 2-1278 2-1279 2-1280 2-1281 2-1282 2-1283 2-1284 2-1285 2-1286 2-1287 2-1288 2-1289 2-1290 2-1291 2-1292 2-1293 2-1294 2-1295 2-1296 2-1297 2-1298 2-1299 2-1300 2-1301 2-1302 2-1303 2-1304 2-1305 2-1306 2-1307 2-1308 2-1309 2-1310 2-1311 2-1312 2-1313 2-1314 2-1315 2-1316 2-1317 2-1318 2-1319 2-1320 2-1321 2-1322 2-1323 2-1324 2-1325 2-1326 2-1327 2-1328 2-1329 2-1330 2-1331 2-1332 2-1333 2-1334 2-1335 2-1336 2-1337 2-1338 2-1339 2-1340 2-1341 2-1342 2-1343 2-1344 2-1345 2-1346 2-1347 2-1348 2-1349 2-1350 2-1351 2-1352 2-1353 2-1354 2-1355 2-1356 2-1357 2-1358 2-1359 2-1360 2-1361 2-1362 2-1363 2-1364 2-1365 2-1366 2-1367 2-1368 2-1369 2-1370 2-1371 2-1372 2-1373 2-1374 2-1375 2-1376 2-1377 2-1378 2-1379 2-1380 2-1381 2-1382 2-1383 2-1384 2-1385 2-1386 2-1387 2-1388 2-1389 2-1390 2-1391 2-1392 2-1393 2-1394 2-1395 2-1396 2-1397 2-1398 2-1399 2-1400 2-1401 2-1402 2-1403 2-1404 2-1405 2-1406 2-1407 2-1408 2-1409 2-1410 2-1411 2-1412 2-1413 2-1414 2-1415 2-1416 2-1417 2-1418 2-1419 2-1420 2-1421 2-1422 2-1423 2-1424 2-1425 2-1426 2-1427 2-1428 2-1429 2-1430 2-1431 2-1432 2-1433 2-1434 2-1435 2-14

0004170048 Forwards IE Insp Repts 30-254/80-09 & 30-263/80-12 on noncompliance noted
HESLOMAN, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/05/81 2pp

--0004170276 IE Insp Repts 30-254/80-09 & 30-263/80-12 on 000401-02 on noncompliance noted Major areas inspected: initial training & retaining of licensed & unlicensed personnel & licensed operator requalification training
HESLOMAN, R. Region 3, Chicago, Office of the Director
JACKLIN, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/04/81 2pp

0004232079 Forwards IF Insp Repts 30-254/80-10 & 30-263/80-13 on 000320-0527 on noncompliance noted
HESLOMAN, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/05/81 2pp

--0004232079 IE Insp Repts 30-254/80-10 & 30-263/80-13 on 000327-0507 on noncompliance noted Major areas inspected: operational safety, long-term shutdown, and surveillance
SPENCER, R. L. CHSIS0071HDS, H Region 3, Chicago, Office of the Director 05/05/81 8pp

0004260500 Responds to IE Bulletin 79-24 Sweden Unit 2 is only facility requiring shutdown margin penalty for postulated BAC teaching Control blade exposures will be monitored during cycles to verify projected end-of-cycle exposures
PEEPLES, D. L. Commonwealth Edison Co 05/05/81 2pp

0004260550 Forwards response to IE Bulletin 00-56, "Engineered Safety Feature (ESF) Reset Controls." Proposed mode identified only if present and design may compromise protective action of equipment
PEEPLES, D. L. Commonwealth Edison Co 05/06/81 2pp

R General operating reports & related correspondence

0004310070 Forwards monthly operating repts for May 1980
KALIVAMARIS, M. Commonwealth Edison Co 05/05/80 1p

--0004310084 Monthly operating repts for May 1980
Commonwealth Edison Co 05/05/80 15pp

0004310034 Forwards list of mode tests & experiments completed during May 1980 & summary of safety evaluations
KALIVAMARIS, M. Commonwealth Edison Co 05/06/80 2pp

R Reportable occurrences, LEOs & related correspondence

0004310050 Forwards LER 80-012/02L-0
KALIVAMARIS, M. Commonwealth Edison Co 05/03/81 1pp

--0004310030 LER 80-012/02L-0 on 000426 reactor water conductivity exceeded 10 umhos/cm Tech Spec limit caused by depleted demineralizers Unit shutdown initiated Demineralizers regenerated & low conductivity coolant added to reactor
VANDERMAALD, J. Commonwealth Edison Co 05/05/81 2pp

0004310063 Forwards LER 80-013/02L-0
KALIVAMARIS, M. Commonwealth Edison Co 05/05/81 1p

--0004310036 LER 80-013/02L-0 on 000426, while performing LPCI meter operated valve accessibility test & DRW to suppress chamber test, cooling valve MS 2-1001-34 failed to close caused by binding of plunger arm on auxiliary interlock contacts
HESLOMAN, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/05/81 2pp

0004270286 Forwards LER 80-010/02L-0
KALIVAMARIS, M. Commonwealth Edison Co 05/06/80 1p

--0004270272 LER 80-010/02L-0 on 000371, while performing quarterly RBIV closure timing surveillance procedure 200 200-4 RBIV AD 2-200-10 closed in 2 2-4 & RBIV AD 2-200-22 closed in 1 1-4 caused by equipment failure Speed control valves adjusted
BETTERLICH, C. Commonwealth Edison Co 05/06/80 2pp

0004260320 DR-80-29 notice of violation & notice of proposed imposition of civil penalty will be issued on or about 000426 Action based on noncompliance re external radiation levels on vehicle exceeding limits Unit issue press release
BROCKWELL, T. M. & THORP, B. D. Office of Inspection & Enforcement, Office of the Director 05/06/81 1p

0004260320 POINT BEACH NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

0004260377 Notices that new telephone sys called Health Physics Network (HPN) has been installed at site One intended for use during emergencies to link all power plants & HPC Emergency Notification Sys helpline will also be used
HESLOMAN, R. Region 3, Chicago, Office of the Director 05/04/81 2pp

0004260407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 30-48 & App R to 102P550 & is expected to be published in FR by end of May
EISENHUT, S. Division of Licensing 05/05/81 46pp

0004310043 Forwards revised Pages 1-14 & new Page 14a for proposed rule 102P550 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 05/05/81 (1r Page 14a not sent)
EISENHUT, S. Division of Licensing 05/05/81 73pp

0004300432 Forwards add info re design of fixed water suppression sys. Fire Suppression Lines & Control Room Light Fixtures for fire protection safety evaluation identification requested by 000370, if design needs are required
FAY, C. M. Wisconsin Electric Power Co 05/06/81 18pp

0 Adjustments correspondence

0004310089 Request for hearing on 000404 mod of 791102 under re-examination of operation despite continued existence of steam generator corrosion processes Assn American Physical Society position re serious safety problem
FALMER, H. Wisconsin's Environmental Decade 05/03/81 2pp

0004170279 Response in objection to HI Environ Decade, Inc 000529 request for hearing re steam generator tube degradation. Interview revealed cracks before AND & failed to establish intent re mod to conformatory order identification of the CHSIS0071-0 & CHSIS0071-1 Wisconsin Electric Power Co CHSIS0071-0 Shaw, Pittman, Patton & Freshkops 05/04/81 2pp

F Operating license stage documents & correspondence

0004270165 Forwards add 791-2 related requirements to operating reactors Licensee requirements for 791 Action Plan include shift meaning licensing exam & license dissemination of operating experience Responses requested within 30 days
EISENHUT, S. Division of Licensing 05/03/81 150pp

0004260560 Notice that facility will use Chem Nuclear, Inc Model CMB 4-00-2 radioactive shipping cask for delivery of salts to campus
FAY, C. M. Wisconsin Electric Power Co 05/03/81 1p

0004310032 Requests comments on HESLO-0577, "Potential for Low Pressure Toughness & Laminar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule sent
EISENHUT, S. Division of Licensing 05/03/81 72pp

0004170284 Forwards Amends 45 & 50 to Licenses 39R-24 & 39R-27, respectively, safety evaluation & notice of license & availability
CLARK, R. A. Operating Reactors Branch 3 05/03/80 3pp

--0004170349 Amends 45 & 50 to Licenses 39R-24 & 39R-27, respectively, incorporating Tech Spec contained in App A & B in license Amends add limiting conditions for operation & surveillance requirements for low temp mitigating sys
CLARK, R. A. Operating Reactors Branch 3 05/03/80 36pp

0004170282 Safety evaluation supporting Amends 45 & 50 to Licenses 39R-24 & 39R-27, respectively
Office of Nuclear Reactor Regulation, Director 05/03/80, 15pp

--0004170283 Notice of license & availability of Amends 45 & 50 to Licenses 39R-24 & 39R-27, respectively
CLARK, R. A. Operating Reactors Branch 3 05/03/80, 3pp

0004130037 Forwards safety evaluation supporting design aspects of containment surge valve isolation override L&ER engineered safety feature arborization signal except radiation monitors which initiate containment surge isolation
CLARK, R. A. Operating Reactors Branch 3 05/03/80 2pp

- B004126039 Safety evaluation supporting design aspects of containment purge valve isolation system and other engineered safety features activation signals except radiation monitors which inhibit containment purge initiation
* Operating Reactors Branch 3 05/05/02 1p
- B004130060 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Converter Containment Purge Valve Isolation & Other Engineered Safety Feature Signals For Point Beach Nuclear Power Station Units 3 & 4"
HACKETT, D B 05/05, Inc FWH A-0021 050103-4139 7/9/03 1pp
- B004003344 Forwards description of proposed mode to instrument bus power supplies, in response to NRC 030424 Ltr Made will be completed by NIOS001 Diagram of proposed supply will be white & yellow instrument buses only
FAY, C M Wisconsin Electric Power Co 05/05/02 4pp
- B004101039 Ack receipt of B00014 ltr requesting that samples of steam generator tubes be provided to J. Mark at BNL Directed principle consultant/contractors to provide samples & deal w/td needs directly
FAY, C M Wisconsin Electric Power Co 05/05/02 1p
- B004101039 Advises that still is forwarding, under separate cover, set of piping & instrumentation diagrams for plant listing of diagram also. Forwarded w/package
FAY, C M Wisconsin Electric Power Co 05/06/04 1p
- B004102037 Discusses NW05/05-1280 re power plant staffing Util has neither solicited funding nor unlimited supply of people to implement as which may have developed Ltr TH-related aspects which have been covered
SOUTHERN T A Affiliation Unknown 05/05/05 4pp
- B004102033 Withdrew B00254 request for NRC contractor to visit facility to perform interviews & other activities associated w/NRC contract until B00027 ltr requested postponement on resumption of visit due to high level of plant activities
HEDBERG, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/06/05 1p
- B004106036 Responds to B00014 request that NRC contractor be allowed to visit facility to meet operating staff & meet emergency procedures Requests postponement or cancellation of visit due to high level of activities at plant
BURSTEIN, B Wisconsin Electric Power Co 05/05/07 3pp
- B004106040 Forwards response to NRC B00007 ltr re five add TH-2 related requirements for operating reactors Assume that implementation of add. requirements will not result to impose completion of previous comments
FAY, C M Wisconsin Electric Power Co 05/06/11 0pp
- 9 Inspection reports: IE Bulletin & correspondence
- B004106074 Forwards IE Insp Repts 36-26a/80-07 & 30-301/80-06 on B0040010 36-26a/80-06 No noncompliance noted
WATKINS, B Region 3, Chicago, Fuel Facility & Materials Safety Branch 05/06/02 3pp
- B004106081 IE Insp Repts 30-26a/80-07 & 30-301/80-06 on B0040010 No noncompliance noted Major areas inspected radiation protection program associated w/operating schedule including radiation protection procedures & training exposure control
HEDBERG, R F LUDWIG, R C Region 3, Chicago, Office of the Director FTH000, M L Region 3, Chicago, Fuel Facility & Materials Safety Branch 05/04/08 3pp
- B004106082 Forwards IE Insp Repts 30-26a/80-09 & 30-301/80-06 on B0040010 36-26a/80-09 & 30-301/80-06 No noncompliance noted
HEDBERG, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 05/05/16 3pp
- B004106089 IE Insp Repts 30-26a/80-09 & 30-301/80-06 on B0040010 36-26a/80-09 & 30-301/80-06 No noncompliance noted Major areas inspected plant procedures & operator training On B0040010 meeting was held to review plant performance
WATKINS, B F, SMITH, D L, HEDBERG, R F Region 3, Chicago, Office of the Director 05/05/16 1pp
- B004106083 Forwards proprietary response to IE Insp Repts 30-26a/80-06 & 30-301/80-05 Revision to modified amended security plan withdrawn (ref 102992 790)
BURSTEIN, B Wisconsin Electric Power Co 05/05/29 3pp
- B004106085 Responds to IE Bulletin 05/05 "Highlander Activator Deficiencies" No safety-related ops or component issue AIN-93 re 10-93 reactor highlander activator
FAY, C M Wisconsin Electric Power Co 05/05/29 1p
- B004000628 Responds to IE Bulletin 80-12, "Emergency Reactor Shutdown Availability" Plant decision does not call for automatic activation of ECCS recirculation or automatic positioning of containment recirculation pump valves
FAY, C M Wisconsin Electric Power Co 05/06/05 2pp
- B004000641 Ack receipt of B00029 ltr re operating NRC of steps taken to correct violations noted in IE Insp Repts 30-26a/80-06 & 30-301/80-05
HEDBERG, R F Region 3, Chicago, Safeguards Branch 05/06/10 1p
- B004000647 Responds to NRC B00002 ltr re violations noted in IE Insp Repts 30-26a/80-06 & 30-301/80-05 Corrective actions
BURSTEIN, B Wisconsin Electric Power Co 05/06/29 1p
- B004000648 Forwards IE Insp Repts 30-26a/80-06 & 30-301/80-07 on B00019-23 No noncompliance noted Major areas inspected mail control & accountability/operation measurement & control, storage inventory Repts details withheld (ref 102942 790)
HEDBERG, R F Region 3, Chicago, Safeguards Branch FTH000, A O, FTH000, J P Region 3, Chicago, Office of the Director 05/06/10 1p
- A Periodic operating reports & related correspondence
- B004106073 Forwards monthly operating reports for May 1980
FAY, C M Wisconsin Electric Power Co 05/06/10 1p
- B004106077 Monthly operating reports for May 1980
FAY, C M Wisconsin Electric Power Co 05/06/05 0pp
- B Reportable occurrences, LERs & related correspondence
- B004106049 Forwards LER 80-025/02L-3
FAY, C M Wisconsin Electric Power Co 05/06/02 1p
- B004106051 LER 80-025/02L-3 on B004106051 normal operation review & security logs revealed that designated fire brigade was below min supervision requirements at three occasions caused by operations personnel disqualification error
FAY, C M Wisconsin Electric Power Co 05/06/02 3pp
- V Operator Examinations
- B004106071 Requests concurrence that operating training program is equivalent to entire main content or background studies to justify arbitrary requirement Repts requested by B00001
FAY, C M Wisconsin Electric Power Co 05/06/04 3pp
- DOCKET 30-26A PART 81 VISUAL INSPECTION GENERATING STATION
- B004106052 IE Insp Repts 30-26a/80-07 & 30-301/80-06 on B0040010 36-26a/80-07 & 30-301/80-06 No noncompliance noted
HEDBERG, R F Region 3, Chicago, Fuel Facility & Materials Safety Branch 05/06/02 3pp
- B004106053 Forwards safety evaluation of facility accident remedial actions in support of full power operation Remedial actions results are available to justify full power operation provided that added conditions are met
HEDBERG, R F Assistant Director for Core & Containment Systems 05/04/90 1p
- B004106059 Safety evaluation of facility accident remedial actions in support of full power operation Remedial actions results are available to justify full power operation provided that added conditions are met
HEDBERG, R F Assistant Director for Core & Containment Systems 05/04/90 1pp
- F Security, medical, emergency & fire protection plans
- B004000641 Provides info re NRC contract personnel who are likely to visit facility w/NRC personnel to approve health physics program. Date phone is scheduled for approx 2 wks
BURSTEIN, B Region 4, Dallas, Office of the Director 05/09/19 1p
- B004000645 Forwards security plan mods re tables of changes & contents Plan withdrawn (ref 102972 790)
WATKINS, D M Public Service Co of Colorado 05/09/19 3pp

DOCKETED ITEMS

63

8004030545 Forwards revised Pages 1-34 of New Page 14a for proposed rule 100P50 "New Protection Program for Nuclear Power Plants Operating Prior to 7/30/01." Transmitted by NRC 03/03/19
150 Page 14a not corr.
EJH/MSUT.B & Division of Licensing 03/03/22 72pp

Operating license change documents & correspondence

8004030160 Forwards addl TH1-2 related requirements to operating license licenses requirements for TH1 Action Plan include shift retraining, licensing exam? & license dissemination of spending experience Response requested within 30 days
EJH/MSUT.B & Division of Licensing 03/03/27 130pp

8004030102 Requests comments on NUREG-0877, "Potential for Low Pressure Turbines & Immediate Testing on PWR Steam Generator & Reactor Coolant Pump Support." Proposed review procedure & implementation schedule email
EJH/MSUT.B & Division of Licensing 03/03/19 72pp

8004030201 Discusses status of Fluctuation testing for size-to-power program before date for completion of tests below 200 power cannot be established at present Region constraint devices do not represent adverse conditions as to 200 power
WMS/MSUT.B & Public Service Co of Colorado 03/03/27 2pp

8004030204 Forwards addl info requested by NRC supporting change to Tech Spec SF & L to fissile fuel thorium/U ratio. Demonstrates effects of target burnup on THSD discharge fuel performance under simulated core break conditions
GMAH/F & Public Service Co of Colorado 03/03/28 5pp

8004030273 Advises that licensee never received NRC 030307 ltr to all operating reactor licenses. Licensees advised copy from consultant but will have no immediate action until ltr is formally transmitted from NRC
GMAH/F & Public Service Co of Colorado 03/03/30 1p

8004030294 Forwards Startup Rept 15, "Initial Approach to Power Tests (R-Series)," for 030223-0322
WMS/MSUT.B & Public Service Co of Colorado 03/04/05 1p

8004030323 Startup Rept 15, "Initial Approach to Power Tests (R-Series)," for 030223-0322
Public Service Co of Colorado 03/03/22 2pp

8004030402 Requests letter from Tech Spec LCD 4 2 9 requirements until mid 1991 due to excessive purified helium leakage in Loop 2 steam generator penetration up Leakage paths represent penetration closure leakage different from LCD 4 2 9
WMS/MSUT.B & Public Service Co of Colorado 03/04/05 5pp

8004030474 Discusses licensee's PROBE request for route approval to cover shipments of spent fuel from facility chemical processing plant. Review of route approval request is sub to NRC fee schedule. Requests payment of review fee
RILLER/M & License Fee Management Branch 03/04/06 1p

8004030503 Advises that Dir. of Controller has been notified to issue license re 7/30/02 request for route approval to cover shipments of spent fuel from facility to 13 Chemical Processing Plant in Area 12
RILLER/M & License Fee Management Branch 03/04/06 1p

8004030419 Discusses previous commitment to conduct SR 5 3 3, secondary rodent activities at 72-hr intervals. Progress being made as at 72-hr intervals & SR 5 3 3 at 1-hr intervals due to 48-h duration of SR 5 3 3
WMS/MSUT.B & Public Service Co of Colorado 03/04/10 1p

8004030400 Advises that licensee cannot respond to NRC 030507 ltr re addl 1701-2 requirements re referenced NRC ltr on shift retraining & licensing examination. Licensee will respond upon receipt of appropriate correspondence
WMS/MSUT.B & Public Service Co of Colorado 03/03/19 1p

8004030199 Responds to question re effect of fissile fuel thorium/U ratio restriction. Total core ratio remains unchanged
GMAH/F & Public Service Co of Colorado 03/04/20 1p

Inspection reports, IE Bulletins & correspondence

8004030323 Comments on IE Info Bulletin 03-04 NRC should provide more specific & specific examples for retraining approach. Requests that NRC include speaker photos that will permit communication between site & NRC operations etc
WMS/MSUT.B & Public Service Co of Colorado 03/03/19 2pp

8004040541 Responds to IE Bulletin 03-03, "Loss of Charcoal from Old T-12 Fuel-Tank-Tray Assembly Cells." Lists filter cells used in reactor plant exhaust systems of inactive & stored cells found none or defects noted
LEE/M & Public Service Co of Colorado 03/03/22 1p

8004040343 Responds to IE Bulletin 03-04, "Engineered Safety Feature (ESF) Reactor Shutdown - Full Integrates Bulletin on applying only to PWRs & BWRs & not to HTGRs. Ltr constitutes closing re 70-day reporting requirement
WMS/MSUT.B & Public Service Co of Colorado 03/03/27 1p

8004040343 Submits supplemental reply to IE Bulletin 79-14, "Reinforcing Analysis for As-Built Safety-Related Piping Sys." To date, 25% of 188 seismic Class 1 seismic packages have been audited & 470 Field audit crew actions completed
GMAH/F & Public Service Co of Colorado 03/04/23 4pp

8004040178 Responds to IE Insp Rept 30-267/03-01 re 030419-10 ltr noncompliance noted Major areas inspected procedures, verifications of plant support & test/retest equipment program & plant tour
WMS/MSUT.B & Region 4, Dallas, Reactor Operations Nuclear Support Branch 03/03/30 2pp

8004040189 IE Insp Rept 30-267/03-01 re 030419-10 ltr noncompliance noted Major areas inspected procedures, verifications of plant support & test/retest equipment program & plant tour
WMS/MSUT.B & Region 4, Dallas, Reactor Operations Nuclear Support Branch 03/03/30 2pp

8004040505 Forwards IE Insp Rept 30-267/03-02 re 030419-10 ltr notice of violation
WMS/MSUT.B & Region 4, Dallas, Reactor Operations Nuclear Support Branch 03/03/30 2pp

8004040601 Notice of violation from Insp re 030419-10 ltr
WMS/MSUT.B & Region 4, Dallas, Reactor Operations Nuclear Support Branch 03/03/30 1p

8004040555 IE Insp Rept 30-267/03-03 re 030419-10 ltr noncompliance noted Failure to meet Tech Spec for design generator gas tank levels
WMS/MSUT.B & Region 4, Dallas, Office of the Director, Nuclear Support Branch 03/03/30 4pp

8004040504 Forwards IE Bulletin 03-11, "Reactor Wall Design." Requires action & written response IE Info Bulletin 79-08, "Overarching of Structural Elements Due to Pipe Support Loads."
WMS/MSUT.B & Region 4, Dallas, Office of the Director 03/03/30 1p

8004040288 Forwards IE Bulletin 03-12, "Decay Heat Removal Sys. Capability." No written response required IE Info Bulletin 03-03, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 while in Refueling Mode" email
WMS/MSUT.B & Region 4, Dallas, Office of the Director 03/03/29 1p

8004040503 Ack receipt of 030506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-267/03-04
WMS/MSUT.B & Region 4, Dallas, Reactor Operations Nuclear Support Branch 03/03/22 1p

8004040537 Responds to NRC 030480 ltr re violations noted in IE Insp Rept 30-267/03-04 corrective actions within 100 days of date of ltr & will be performed if request for change in Tech Spec wording will be submitted
LEE/M & Public Service Co of Colorado 03/03/04 2pp

8004040505 Notifies that IE Insp Rept 30-267/79-03 forwarded by 030519 ltr should be changed to 30-267/79-01
WMS/MSUT.B & Region 4, Dallas, Fuel Facility & Materials Safety Branch 03/03/22 1p

8004040507 Forwards IE Insp Rept 30-267/79-01 re 791204 ltr noncompliance noted
WMS/MSUT.B & Region 4, Dallas, Fuel Facility & Materials Safety Branch 03/03/19 2pp

8004040505 IE Insp Rept 30-267/79-01 re 791204 ltr noncompliance noted Major areas inspected requirements of waste handling, fire, audit program, regulations, instructions & operating procedures
WMS/MSUT.B & Region 4, Dallas, Fuel Facility & Materials Safety Branch 03/03/19 2pp

B Periodic operating reports & related correspondence

0004010375 Forwards monthly operating report for Apr 1980
WARRERJ.D. Public Service Co. of Colorado 00/03/29 1p

0004010391 Monthly operating report for Apr 1980
Public Service Co. of Colorado 00/03/29 7pp

0004010417 Forwards monthly operating report for May 1980
WARRERJ.D. Public Service Co. of Colorado 00/03/26 1p

0004010432 Monthly operating report for May 1980
WARRERJ.D. Public Service Co. of Colorado 00/03/02 5pp

B Reportable occurrences, LRIs & related correspondence

0004010430 Forwards LCR 00-004/03L-0
WARRERJ.D. Public Service Co. of Colorado 00/03/05 8pp

0004010431 LCR 00-004/03L-0 on 000552L at 4% thermal power. IC
circulator seal differential pressure decreased
significantly due to unknown reason. Spilling valve closed
& IC circulator buffer helium pressure returned to normal
Public Service Co. of Colorado 00/04/06 1p

0004010418 Forwards LCR 00-003/03L-0
WARRERJ.D. Public Service Co. of Colorado 00/03/04 6pp

0004010418 LCR 00-003/03L-0 From 000507-17, plant was operated
at emergency feedwater heater supply to helium circulator
under turbine driven oil line loop isolated on four separate
occasions caused by valve leakage & line leakage
WARRERJ.D. Public Service Co. of Colorado 00/03/06 1p

0004010435 RD on 000501 & 000502, release of radioactivity
occurred in reactor area caused by malfunction in helium
circulator gas in radiation was released into atmosphere
Public & personnel health & safety were not jeopardized
WARRERJ.D. Public Service Co. of Colorado 00/03/18 1p

D000000000 GEORGE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

0004010407 Forwards proposed rule entitled: "Fire Protection Program
for Nuclear Power Plants Operating Prior to 7/9/10" Rule
adds new Section 95.40 & App B to 10CFR95 & is expected
to be published in FR by end of May
EDWARDSJ.D. Division of Licensing 00/03/29 4pp

0004010403 Forwards revised Pages 1-14 & new Page 14a for proposed
rule 10CFR95.40 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 7/9/10" transmittal by NRC 000001
14a page 14a not encl
EDWARDSJ.D. Division of Licensing 00/03/29 73pp

0004010408 Forwards revision to safeguards contingency plan Plan
withheld (ref 10CFR7901)
PARKERJ.D. State Power Co. 00/03/20 1p

0004010407 Forwards revision to nuclear security training &
qualification plan Plan withheld (ref 10CFR7901)
PARKERJ.D. State Power Co. 00/03/20 1p

0004010404 Forwards comments & requests for add info re guard training
& qualification plan Plan withheld (ref 10CFR7901)
PARKERJ.D. State Power Co. 00/03/12 2pp

0004010409 Forwards cover for re 000409 revision to nuclear security
training & qualification plan Plan withheld (ref 10CFR7901)
PARKERJ.D. State Power Co. 00/03/19 1p

G Adjudicatory correspondence

0004010404 Forwards Lincoln County, NC Board of County Commissioners
7/9/10 & 8/24/10 resolutions affirming position that upon
nuclear fuel should be transported from Germany to acquire
an interstate highway
HUGHESJ.D. North Carolina, State of 00/04/17 3pp

0004010407 Advises that unit is in submit proposed findings of fact by
000510W-NRC parties by 000309 & NRC by 000506
HUGHESJ.D. Nebraska & Liberman 00/04/29 1p

0004010407 Forwards applicants proposed findings of fact & conclusions
of law in form of initial decision
HUGHESJ.D. Nebraska & Liberman 00/04/19 1p

0004010408 Submittal of proposed findings of fact & conclusions of law
in form of initial decision
HUGHESJ.D. State Power Co. HUGHESJ.D. Nebraska & Liberman
00/03/19 1p

0004010408 Proposed initial decision containing findings of fact &
conclusions of law approved by the authority storage of
Spent spent fuel at McGuire Environs radiological monitoring
program will be maintained & Certificate of Suit
HUGHESJ.D. State Power Co. HUGHESJ.D. Nebraska & Liberman
00/03/19 8pp

0004010417 Response in opposition to Caroline Environ Study Group
000509 proposed elements of fact & conclusions of law toward
initial decision No good reason presented for not approving
application re spent fuel shipment to McGuire Certificate of Suit
HUGHESJ.D. State Power Co. HUGHESJ.D. Nebraska & Liberman
00/03/19 2pp

0004010417 Forwards proposed findings of fact & conclusions of law in
form of initial decision approving license amendment to
authorize (1) spent fuel transportation to & storage at
McGuire
HUGHESJ.D. Hearing Branch 4 00/03/17 1p

0004010418 Proposed findings of fact & conclusions of law in form of
initial decision approving license amendment to authorize (1) spent
fuel transportation to & storage at McGuire
Proposed findings of fact & conclusions of law
HUGHESJ.D. 9. HUGHESJ.D. Hearing Branch 4 00/03/17 15pp

H General correspondence

0004010403 Forwards county board resolution requesting NRC to consider
using onsite storage of radioactive waste rather than
shipping through county. Also forwards board resolution
requesting public input re DOT regulations
WARRERJ.D. McKinley County, NC 00/03/23 3pp

P Operating license stage documents & correspondence

0004010407 Responds to technical assistance request for proposed Tech
Spec changes for BSW operating plants Forwards requirements
for add info
HUGHESJ.D. TH-2 Bulletin 2 Orders 7/9/10/1 13pp

0004010409 Forwards schedules for unit responses to NRC 7/9/10/1 for re
C. Michaelson concerns on what is Unit 10054
CAPRAJ.D. TH-2 Bulletin 2 Orders 7/9/10/1 1p

0004010403 Forwards documents for Auxiliary Site Branch review of
reactor facility. Pump reliability analysis for BSW operating
plants info encl
CAPRAJ.D. Light Water Reactors Branch 3 00/04/17 3pp

0004010408 Forwards revision to 000501 month approval request for
shipment of spent fuel-charging delays for shipment
Revision withheld (ref 10CFR7901)
PARKERJ.D. State Power Co. 00/04/17 1p

0004010408 Forwards add TH-2 related requirements to operating
reactors license requirements for TH Action Plan include
staff training, licensing, exam & license dissemination
of operating experience Response requested within 30 days
HUGHESJ.D. Division of Licensing 00/03/27 15pp

0004010412 Request comments on NRC 0000-0077. "Potential for Low Pressure
Leakage & Fueling Tearing on PWR Steam Generation &
Reactor Control Pump Support" Proposed review procedure &
implementation schedule add
HUGHESJ.D. Division of Licensing 00/03/19 7pp

0004010417 Forwards HED-1055, "Revised Design Methodology" Revision 1.
revises request allowing inclusion design of unreacted fuel
creditification of certain areas & supersede prior error
correction Root methods introduced for use by Aug 1981
PARKERJ.D. State Power Co. 00/03/20 1p

0004010417 "Revised Design Methodology" Revision 1
State Power Co. HED-1051 00/03/20 3pp

0004010412 Requests submittal of amendments to license updating requirements
of Reg Guide 1.6, Revision 4 Response requested within 60
days of receipt of info
HED-1051 Operating Reactors Branch 4 00/03/29 2pp

DOCKETED ITEMS

55

0004260574 Electrical Instrumentation and Control Aspects of Low Temp
Deregulation Initiating Sys. Informal reply
MERRIS, D A BNL, Inc. / IN A-256 00/05/03 12p

0004040044 Requests add info to respond to NRC 000507 ltr re TH-2
Lessons Learned Requirements info needed includes areas re
shift manning, safety & relief valves & outage of BECs
Responses should be submitted by 00/05/02
PARRER, M D Duke Power Co 00/05/02 2pp

0004260124 Advises that 000720 request for Tech Spec change will be
included in overall review of App 1 submittals. Mark-up of
000502 CTS represents NRC review. Radiological CTS should
be submitted based on monitoring within 90 days
REIS, R W Operating Reactors Branch 4 00/05/02 2pp

0004101044 Forwards "Generic Startup Physics Test Program, May 1980,"
estimating tests to be included during startup following
future refueling operations
PARRER, M D Duke Power Co 00/05/04 1p

--0006101050 "Generic Startup Physics Test Program, May 1980" - Modify
Unit 1 specific reactivity decreasing acceptance criteria for mid
drop measurements substitution or RMS criteria for location
of highest peak requirement in power distribution testing
4 Duke Power Co 00/05/01 2pp

0004100351 Forwards summary of events involving partial or total loss
of offsite power to facilities & responses to NRC questions.
per NRC 000505 ltr
PARRER, M D Duke Power Co 00/05/04 3pp

0004100322 Forwards results of analysis required by Items 6 & 9 of NRC
790303 ltr on degraded grid voltage Undervoltage trip
circuit not to be removed for 12 months. Undervoltage &
automatic corrective controls will be established by 00/07/01
PARRER, M D Duke Power Co 00/05/04 17pp

0004050342 Responds to NRC 000502 ltr requesting evidence re TH-2
related requirements. Lists 12 on schedule of reactor
control pumps during LOCA should be revised
REIS, R W Operating Reactors Branch 4 00/05/10 2pp

0004170029 Forwards corrected version of "Genomic Nuclear Station
Generic Startup Physics Test Program"
PARRER, M D Duke Power Co 00/05/01 1p

--0004170028 Corrected version of "Genomic Nuclear Station Generic Startup
Physics Test Program."
4 Duke Power Co 00/05/01 17pp

0004170450 Advises that responses are being prepared by low pressure
customers per 000510 request work will be completed by
00/05/06
PARRER, M D Duke Power Co 00/05/01 1p

0004260081 Responds draft NRC licensing position. "Safety
Considerations for Temporary Waste Storage" used to
evaluating low level waste storage criteria. Requests review
for waste storage additions in existing operating units
REIS, R W Operating Reactors Branch 4 00/05/02 10pp

0004180478 Forwards response to NRC 000507 ltr re add requirements
from TH Action Plan. Response includes implementation
schedule & summary stating unit commitments re
requirements
PARRER, M D Duke Power Co 00/05/03 3pp

0004260460 Responds to NRC 000502 request for info concerning problem
of low pressure turbine disc cracking. Forwards detailed
responses to site specific questions
PARRER, M D Duke Power Co 00/05/03 8pp

0004260023 Requests that NRC complete review & approval of Category 3
Items 2, 3, 26, 2, 7A & 2.1. NRC Review needed to facilitate
implementation of Category 3 items prior to 00/05/01
PARRER, M D Duke Power Co 00/05/02 1p

0004260362 Forwards proposed Tech Spec revision in response to NRC
000510 ltr discussing term "operable" as applied to Tech
Spec requirements. No license fees provided since proposed
submitted in response to NRC request
PARRER, M D Duke Power Co 00/05/04 2pp

--0004260364 Proposed Tech Spec interpreting term "operable" as applied
to various Tech Spec requirements
4 Duke Power Co 00/05/04 1p

0004260456 Advises that startup testing summary for Cycle 4 will be
completed & transmitted by 00/07/01
PARRER, M D Duke Power Co 00/05/04 1p

0 Inspection reports, IC Bulletins & correspondence

0004260330 Forwards waste packaging ltr re 000313-04
No noncompliance noted
REIS, R W Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/05/07 2pp

--0004260344 Waste packaging ltr re 000313-04 No noncompliance
Noted Major areas inspected: Environmental vehicles
inspected for compliance w/307 & NRC regulations including
shipping paper & 201 placarding requirement
REIS, R W Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/05/08 2pp

0004260454 Forwards IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/05/03 2pp

--0004260452 IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/05/03 2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/09
2pp

0004170045 Forwards IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

0004260451 Forwards IC Bulletin 00-15, "Heavy Unit Design" Requires
action & written response. IC ltr re 000313-04 No noncompliance noted
REIS, R W Region 2, Atlanta, Office of the Director 00/05/08
2pp

DOCKETED ITEMS

57

0004070145 Forwards draft TR1-2 related requirements to operating reactor. Licensee requirements per TR1 Action Plan include staff training, increasing staff, increase documentation of operating procedures. Response required within 30 days
PARKER, M. O. Date Power Co. 00/05/07 10pp

0004130102 Requests comments on NRC-00577, "Tutorial for Low Pressure Turbine 1, Unit 1, Testing on 199 Steam Generator & Reactor Core Control Pump Systems." Proposed review procedure & implementation schedule only
PARKER, M. O. Date Power Co. 00/05/09 32pp

0004140217 Forwards NRC 1001, "Refined Design Methodology," Revision 1, replacing original including inclusion design of unneeded fuel. Includes clarification of action areas & Superimposed error corrections. Ref. methods intended for use by Aug 1981
PARKER, M. O. Date Power Co. 00/05/20 1p

0004040401 "Refined Design Methodology," Revision 1
+ Date Power Co. 00/05/20 00/05/20 10pp

0004050061 Indicates that not approved by NRC on 7/12/83 is complete & acceptable procedure necessary to eliminate exception to LCRS. This has been implemented
PARKER, M. O. Date Power Co. NRC 00/05/29 1p

0004130032 Requests submittal or intent to license updating requirements of Reg Guide 1.1 to Revision 4. Response required within 60 days of receipt to 1p
REIN, R. W. Operating Reactors Branch 4 00/05/29 2pp

0004060503 Requests add info to respond to NRC 00087 re TR1-2 Licensee Limited requirements list needed includes areas re staff training, safety & other areas. A subset of SCED Response should be submitted by 00/06/02
PARKER, M. O. Date Power Co. 00/06/02 2pp

0004020011 In Answer that 000338 request for Tech Spec change will be included in overall review of Unit 1 submittal. Review of 000338 to comments NRC. Nuclear Regulatory Commission should be submitted, based on 00/06/02 00 days
REIN, R. W. Operating Reactors Branch 4 00/06/02 2pp

0004130104 Forwards "Generic Reactor Physics Test Program May 1980," delineating tests to be included during startup following future refueling operations
PARKER, M. O. Date Power Co. 00/06/04 1p

0004130109 "Generic Reactor Physics Test Program May 1980" - Modifications 1 specific re: degraded grid voltage Under-voltage trip setpoint will be changed for starting transformers & administrative controls will be established by 00/06/04
+ Date Power Co. 00/06/04 10pp

0004100291 Forwards summary of events involving partial or total loss of effluent pump to Facilities P responses to NRC questions
PARKER, M. O. Date Power Co. 00/06/04 5pp

0004130032 Forwards results of analysis required by Items 5 & 9 of NRC 700800 re degraded grid voltage Under-voltage trip setpoint will be changed for starting transformers & administrative controls will be established by 00/06/04
PARKER, M. O. Date Power Co. 00/06/04 17pp

0004140112 Forwards add pages re 000312 proposed changes to Tech Spec to support of Cycle 7 operation
PARKER, M. O. Date Power Co. 00/06/09 1p

0004140029 Add pages for proposed Tech Spec re Sections 3.5.2 & 3.5.3 re emergency reactor coolant sys pressure, coolant outlet temp, & reactor inlet pressure
+ Date Power Co. 00/06/09 7pp

0004040145 Response to NRC 000603 1p requesting guidance re TR1-2 related requirements. Includes 1p schedule of reactor coolant pump during LOCA should be revised
REIN, R. W. Operating Reactors Branch 4 00/06/10 2pp

0004170029 Forwards corrected version of "Generic Nuclear Station Reactor Startup Physics Test Program"
PARKER, M. O. Date Power Co. 00/06/11 1p

0004170024 Corrected version of "Generic Nuclear Station Reactor Startup Physics Test Program"
+ Date Power Co. 00/06/11 10pp

0004170029 Forwards that responses are being prepared re low pressure turbines per 000603 request. Work will be completed by 00/06/11
PARKER, M. O. Date Power Co. 00/06/11 1p

0004060051 Forwards draft NRC licensing position "Safety Considerations for Temporary Diesel Storage," used in evaluating low level onsite storage criteria. Requests review for onsite storage additions in existing operating units
REIN, R. W. Operating Reactors Branch 4 00/06/12 10pp

0004180470 Forwards response to NRC 00087 re re add requirements from TR1 Action Plan. Response includes implementation schedule & summary showing unit commitments re requirements
PARKER, M. O. Date Power Co. 00/06/13 3pp

0004040405 Response to NRC 000512 request for info concerning problem of low pressure turbine drive coupling. Forwarders detailed responses to site specific questions
PARKER, M. O. Date Power Co. 00/06/14 0pp

0004060033 Requests that NRC complete review & approval of Category B Items 2 & 3 of 2.1 "A" & 2.1 "B" Review needed to facilitate installation of Category B mode prior to 00/06/14
PARKER, M. O. Date Power Co. 00/06/20 1p

0004130060 Forwards proposed Tech Spec revision in response to NRC 000512 for licensing term "acceptable" as applied to Tech Spec requirements. No license fees provided since proposal submitted in response to NRC request
PARKER, M. O. Date Power Co. 00/06/20 2pp

0004060026 Prepared Tech Spec interpreting term "acceptable" as applied to current Tech Spec requirements
+ Date Power Co. 00/06/20 1p

0004060074 "Electrical, Instrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys." informal report
MORSE, U. N. CDR, Inc. FIN #025 00/06/21 10pp

0 Inspection reports: IF Bulletin & correspondence

0004060146 Forwards IE Insp Rpts 30-269/83-13, 30-270/83-08 & 30-287/83-04 on 000320-21. No nonconformance noted
LWIS, C. R. Region 2, Atlanta, Office of the Director Nuclear Support Branch 00/06/23 2pp

0004060192 IE Insp Rpts 30-269/83-13, 30-270/83-08 & 30-287/83-04 on 000320-21. No nonconformance noted. Major areas inspected plant operations, relief activation, failure, no previous trip findings & review of LWRs
MARTIN, R. D. Region 2, Atlanta, Office of the Director Nuclear Support Branch 00/06/23 2pp

0004060192 Forwards IE Bulletin 00-12, "Passing Wall Design" Requires action & analysis response IE info 00-12
"Overloading of Structural Elements Due to Pipe Support Load" met
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/23 2pp

0004060193 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys. Reliability." Requires action & response within 30 days
IE info 00-12, "Loss of Decay Heat Removal Capability at Reactor-Driven Unit 1 While in Refueling Mode" and 00-12, "Decay Heat Removal Sys. Reliability." Requires action & response within 30 days
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/23 2pp

0004170058 Forwards IE info 00-12, 70-27, "w/notes sheet requests add info re turbine drive coupling. Review schedule to be developed to perform full ultrasonic test of at least one low pressure turbine before next major outage
REIN, R. W. Operating Reactors Branch 4 00/06/23 3pp

0004000110 Forwards IE Circular 80-11, "Emergency Diesel Generator Lake 31 Cooler Failures" No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/23 2pp

0004180224 rec receipt of IE Insp Rpts 30-269/83-13, 30-270/83-08 & 30-287/83-04. No nonconformance noted
PARKER, M. O. Date Power Co. 00/06/23 1p

DOCKETED ITEMS

000420076 Forwards revised pages to Director's Decision 80-00-09 Decision about NRC's denied petition requesting certain activities re storage of spent fuel at site Corrections overruled
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
00/05/03 1p

000420080 Advises that version of 80-00-09 signed is not version concurred on. Forwards cover lit. encls. about licensing changes & the revision of Director's Decision Corrections should be issued by 000512
MURRAY, J. P. Office of the Executive Legal Director 00/05/07 4pp

000420082 Notifies that Dir. of Nuclear Reactor Regulation Director's denial under 10CFR 206 of request re spent fuel storage is final
CULLEN, J. J. Office of the Secretary of the Commission 00/05/29 1p

000420099 Responds to 000503 request for advanced notice of activities re facility which involve NRC or State of MD Public Use Commission. NRC is not involved in proceeding. Notification request should be directed to MD Public Use Commission
MURRAY, J. P. Office of the Executive Legal Director 00/06/06 1p

000420054 Requests advance notice of meetings, conferences, discussions, hearings or appearances re facility involving NRC or State of MD Public Use Commission. Also requests all relevant testimony & correspondence received by NRC
WETTERMAN, M. J. Counsel, Moore & Corbin 00/05/03 2pp

000420097 Forwards NRC's proposed findings of fact & conclusions of law in form of initial decision. Licensee reserves right to file reply brief after NRC of proposed findings & conclusions of law by other parties
WETTERMAN, M. J. Counsel, Moore & Corbin 00/06/03 1p

000420053 Proposed findings of fact & conclusions of law in form of initial decision. Board will not receive decisions reached during Commission's 60-day review from safety or environment standpoint. Certificate of the act
WETTERMAN, M. J. Public Service Electric & Gas Co. of New Jersey
WETTERMAN, M. J. Counsel, Moore & Corbin 00/06/10 7pp

000420050 Proposed findings of fact & conclusions of law in form of initial decision re amendment to License 000-70-00. NRC reserved per NRC alternatives of storage at other sites need not be considered. Amendment should be issued as in final draft order.
RODRIGUEZ, J. E. Hearing Branch 3 PATON, M. D. Hearing Branch 4
00/05/03 4pp

000420057 Forwards corrected Page 59 to NRC 000423 Findings of fact & conclusions of law re CL amendment proceeding
RODRIGUEZ, J. E. Hearing Branch 2 00/06/04 1p

000420053 Corrected Page 59 to NRC 000423 Findings of fact & conclusions of law re CL amendment proceeding
RODRIGUEZ, J. E. Hearing Branch 2 PATON, M. D. Hearing Branch 4
00/06/04 1p

H General correspondence

000420099 Responds to Dir. to DOE re continuing inventory about relationship of Morris Creek Project to Facilities. NRC has no info re relationship. Facilities use water from DE River.
DENTON, H. R. Office of the Executive Director for Operations
00/05/03 4pp

J Insurance & indemnity information

000420097 Forwards Endorsements 21.4 & 1 to NAEU Policies MF-90-03-00 & 03-72, respectively.
CORRELL, A. A. Marsh & McLennan, Inc. & M & N Nuclear Consultants, Inc.
00/06/04 4pp

000420057 Forwards enclosed Amendment to Indemnity Agreement 3-74, deleting item 3 & substituting license numbers
GRIFFITHS, R. Public Service Electric & Gas Co. of New Jersey
00/06/02 2pp

F Operating license stage documents & correspondence

000420010 Forwards and NRC-2 related requirements to operating license. Licensees request for NRC Action Plan include shift meeting, licensing requirements, license discontinuation of operating requirements. Response requested within 30 days
BARNHART, S. C. Division of Licensing 00/03/07 10pp

000420012 Requests comments on NUREG-0977, "Potential for Low Structure Fragments & Laminar Flowing on PWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule 2001
EIDENHUT, C. C. Division of Licensing 00/03/14 72pp

000420051 Notice of partial refund of Class 12 fee reinitiated under 10CFR application for Amendment No. Tech Specs re secondary water chemistry. Class 12 fee was applicable
MILLER, W. B. License Fee Management Branch 00/05/03 1p

000420048 Comments to implement NUREG-0440 re add TRS-2 related requirements per 000507 ltr
LIEBERZILL, P. P. Public Service Electric & Gas Co. of New Jersey
00/06/07 1p

000420041 Forwards auxiliary feedwater pump test results
LIEBERZILL, P. P. Public Service Electric & Gas Co. of New Jersey
00/06/10 1p

000420040 Forwards response to NRC 700921 request for info re auxiliary feedwater flow requirements. Design heat resulting from reactor trip is anticipated by evaporating water in steam generators & venting generated steam
LIEBERZILL, P. P. Public Service Electric & Gas Co. of New Jersey
00/06/11 21pp

D Inspection reports, EC Bulletins & correspondence

000420047 Ask receipt of EC 000203 ltr forwarding notice of violation, notice of proposed imposition of civil penalties & order modifying license effective immediately. Forwards penalty payment & response. Not withheld (ref 10CFR 270)
BARNHART, S. C. Public Service Electric & Gas Co. of New Jersey
00/04/14 1p

000420010 Forwards IF Inspect 80-272/00-00 on 000311-14 No noncompliance noted
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/17 2pp

000420047 IF Inspect 80-272/00-00 on 000311-14 No noncompliance noted. Major areas inspected: refueling station testing, control rod drive assemblies & position indication, core power distribution & in-core/out-core detector calibr.
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
WETTERMAN, M. J. Region 1, Philadelphia, Office of the Director 00/04/10 7pp

000420053 Forwards IF Inspect 80-272/00-07 & 80-311/00-03 on 000303-29 No noncompliance noted
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/29 2pp

000420054 IF Inspect 80-272/00-07 & 80-311/00-03 on 000303-29 No noncompliance noted. Major areas inspected: plant operations logs & records, LERs, periodic reports, small break LDBA principles & previous inspection
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
WETTERMAN, M. J. Region 1, Philadelphia, Office of the Director 00/04/20 10pp

000420041 Forwards IF Inspect 80-272/00-07 & 80-311/00-03 on 000303-29 No noncompliance noted
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/29 2pp

000420013 IF Inspect 80-272/00-07 & 80-311/00-03 on 000303-29 No noncompliance noted. Major areas inspected: plant operations including facility tours, log & record reviews, licensee reports review & review of periodic reports
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
WETTERMAN, M. J. Region 1, Philadelphia, Office of the Director 00/04/22 10pp

000420055 Ask receipt of 000408 ltr supplementing 770940 ltr informing NRC of steps taken to correct violations noted in IF Inspect 80-272/00-07
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/04/30 1p

000420041 Ask receipt of 000410 ltr informing NRC of steps taken to correct violations noted in IF Inspect 80-272/00-07
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/05/14 1p

000420010 Notice of violation from Inspect on 000203-0301
BARNHART, S. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/03/19 1p

0006000090 Forwards IE Circular 80-10, "Grid Bling Damage in Westinghouse Fuel Assembly Rooms" to utility customer. Forwarded 03/01/80 H. H. Region I, Philadelphia, Office of the Director 00/05/00 1p

0006000231 Responds to violation noted in IE Insp Repts 80-072/80-04 & 80-211/80-01 on 800128-01, 0001-04-07 & 01-03 corrective actions master equipment list will expand existing methods of compliance with requirements of 10 CFR program. Reg. 2 comments 0006000231 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/03 0pp

0006000333 Forwards partial response to IE Bulletin 79-008, "Swarm Qualification of Class IE Equipment - Reactor Sink at approx 92% complete in identifying components. Qualification data sheets approx 400 complete 0006000333 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/04 2pp

0006000509 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical and Control Systems Tanks - Facilities have had vacuum breakers installed on holdup tanks to prevent collapse in event vacuum is generated 0006000509 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/06 1p

0006000490 Responds to IE Bulletin 80-19, "Steam Heat Removal By Containment - Sequence of events at Service Sinks which resulted in automatic transfer of section to empty containment sump will not occur at facilities 0006000490 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/09 App

0006000593 Submits supplemental reply revising 790919 response to IE Insp Rept 80-023/79-10 Implementation of revisions to 80-013 & 80-04 has shown that revisions are sufficient to prevent recurrence of problem identified in Insp 0006000593 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/12 1p

0006000571 Responds to MRC 800527 for violation of noncompliance noted in IE Insp Rept 80-023/80-10 Corrective actions responsibility for Reg. A, B & C containment tank leak tests assigned to one group. Revision & approval procedure streamlined 0006000571 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/17 2pp

B. Periodic operating reports & related correspondence

0006160107 Forwards NPSRC discharge monitoring repts for Apr 1980. operating repts of industrial waste treatment plant & wastewater treatment repts w/ie operating & wastewater treatment repts 0006160107 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/03 2pp

0006160126 NPSRC discharge monitoring repts for Apr 1980 0006160126 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/03 12pp

0006160091 Forwards monthly operating repts for May 1980 0006160091 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/10 1p

0006160012 Monthly operating repts for May 1980 0006160012 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/10 37pp

C. Reportable occurrences, IEAs & related correspondence

0006000454 80 79-00/03P on 790710, Westinghouse informed that reactor trip & auxiliary feedwater initiation could be delayed in event of main feedwater rupture inside containment. Caused by possible buildup of steam generator level ref. ing 0006000454 H. H. Public Service Electric & Gas Co. of New Jersey 79/07/10 1p

0006000812 Responds to MRC 800321 for violations resulting from IE Insp 79-71 Corrective actions counseled individuals involved in incident & will require 80-10 safety hearing rules. To insure only shift supervisors authorized to approve tags 0006000812 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/06 0pp

0006160231 PWD-1-80-002 on 800529, human security guard passed out while resting in guard house during night Ambulance called (indicating he was not patient to offsite hosp for observation 0006160231 H. H. HELL, M. J., ROSS, J. L., J. Region I, Philadelphia, Office of the Director 00/06/23 1p

0006000344 Forwards supplemental LER 79-035/013-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/05/00 1p

0006000371 Supplemental LER 79-035/013-0 on 790806 during review of reports within sample stress calculations, start/stopable rejection note found. Caused by use of computer code which calculated piping response w/algorithmic summation method 0006000371 H. H. Public Service Electric & Gas Co. of New Jersey 00/05/00 0pp

0006170073 Forwards LER 80-036/013-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/12 1p

0006170073 LER 80-036/013-0 on 800516, while performing routine surveillance, level transmitter for steam generator level channel 10 for low level trip setpoint was found out of spec. Caused by failed solenoid within circuitry 0006170073 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/12 0pp

0006170044 Forwards LER 80-035/008-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/12 0pp

0006170047 LER 80-035/013-0 on 800516, during containment entry, steam valve coming from area where reactor coolant sample lines pass through containment wall caused by failure of sample line & seal unit on containment Penetration unit repaired 0006170047 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/12 1p

0006170072 Forwards LER 80-038/013-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/17 0pp

0006170035 LER 80-038/013-0 on 800519, while reviewing records, discovered that surveillance requirement 4.3.3.2 was not completed during required interval. Caused by lack of timely review Surveillance completed 0006170035 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/17 1p

0006180486 Forwards LER 80-037/013-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/10 0pp

0006180492 LER 80-037/013-0 on 800521, evaluation of need to perform test of fire pump diesel engine was not made as required every 18 months by Tech Specs. Caused by facility working days corrected to ensure timely review 0006180492 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/10 1p

0006000270 Forwards supplemental LER 79-040/013-0 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/23 0pp

0006000079 Supplemental LER 79-040/013-0 on 790710, during refueling operation, scan of concrete anchors for safety-related pipe supports revealed deficiencies. Corrective action performed per Design Change Package 18C-993 0006000079 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/00 1p

0006000421 Forwards supplemental LER 79-015/040-1 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/02 0pp

0006000424 Supplemental LER 79-015/040-1 on 790106, during preparation of annual nonradioactive environment operating repts, average 1978 suspended solids concentration in discharge exceeded limit caused by abnormally high denitrifier regeneration. 0006000424 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/02 1p

0006000439 Forwards supplemental LER 79-030/013-1 LER1221, P. P. Public Service Electric & Gas Co. of New Jersey 00/06/22 0pp

0006000465 Supplemental LER 79-030/013-1 on 790101, during Mode A operation, while heating up to enter Mode B, high flow through RCP leads & other alarms indicating RCP leakage were observed. Cause undetermined. Instructions have been revised 0006000465 H. H. Public Service Electric & Gas Co. of New Jersey 00/06/23 1p

- 8006110028 Affidavit pointing out error in previous affidavit filed w/ NRC response to intervenors' joint motion to require Imperial Valley earthquake data does not invalidate Mount Diablo response spectra for Facility Certificate of Use and License. **DOUGLAS, P. T. / ROTHMANN, R. / Office of Nuclear Reactor Regulation, Director** 80/06/19 7pp
- 8006100319 Advises ARLAB that research as-built audit demonstrates significant breakdown in unit QA program Breakdown is identified because as suspected 5 anchors were misapplied 100% reworked in response to NRC 1976 & 78 audits **FLIECHOW, R. / Fliechower, O. R** 80/06/10 2pp
- 8006100322 Response to Items 2,3,4 & 5 of E-110011 79-84. "Seismic Analysis for as-Built Safety-Related Piping Sys - Plant procedures for as-built documentation will ensure strict conformity between key construction & design documents **LEON, S. P. / Pacific Sea & Electric Co** 80/06/17 3pp
- 8006100332 Notifies ARLAB that CA Governor Ed Brown intends to participate in hearing on security plan issue Brown was admitted to proceeding as participant by ARLB 791024 order **SHAW, H. H. / Hill Christopher & Phillips / ALTMAN, J. A. / GOVERNOR'S OFFICE, California, State of** 80/06/11 2pp
- 8006100338 Seeks name of ally appearing on behalf of CA Governor Ed Brown for security plan hearing Brown was admitted to proceeding as participant by ARLB 791024 order Certificate of Use and License **SHAW, H. H. / Hill Christopher & Phillips** 80/06/11 4pp
- 8006100371 Memorandum & order CL-80-04 re Intervenor San Luis Obispo Mothers for Peace access to unit physical security plan. Intervenor ARLAB-810 guidelines for making plans available/ use exception Addendum of Commissioner Bradford end **SHULZ, G. J. / Office of the Secretary of the Commission** 80/06/11 3pp
- 8006100409 Memorandum directed to parties advising that further participation in proceeding does not violate Commission regulations or due process requirements. Authority will continue to take part in seismic issues **HEWES, J. R. / Commission** 80/06/16 2pp
- 8006100809 Agrees to intervenor objection to H Nordlinger assignment as counsel re security plan proceeding per H Nordlinger commitment to intervenor **DOUGHERTY, L. / Office of the General Counsel** 80/06/17 1p
- 8006100844 Discusses forwarding of public comments re operation of Facilities. Messages tend to be repetitive. Falls to see need to serve on all parties. Ltrs not already in public record should be placed in PDR & sent PDR in San Luis Obispo-CA **DOUGHERTY, L. / Office of Nuclear Reactor Regulation, Director** 80/06/17 1p
- 8006100857 Memorandum advising parties that author did not participate in Commissioner Kennedy decision re recusancy & Commissioner Hendrix decision to take part in proceeding. Author will take part in other license application matters **DOUGHERTY, L. / Office of the General Counsel** 80/06/18 1p
- 8006100918 Forwards Director's decision per 2.306 & PR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental environ statements as Class 9 accidents at Diablo Canyon. Renee Bisco & Palo Verde **DOUGHERTY, H. H. / Office of Nuclear Reactor Regulation, Director** 80/06/19 2pp
- 8006100919 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at Facilities. No special circumstances exist which would warrant reopening proceedings. Request denied **DOUGHERTY, H. H. / Office of Nuclear Reactor Regulation, Director** 80/06/19 2pp
- 8006100918 Director's decision per 2.306 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents **DOUGHERTY, H. H. / Office of Nuclear Reactor Regulation, Director** 80/06/19 1pp
- 8006100918 Notice of issuance of Director's decision per 2.306 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents **DOUGHERTY, H. H. / Office of Nuclear Reactor Regulation, Director** 80/06/19 2pp
- 8006100919 Decision ARLB-596 granting intervenors' motion to reopen record to admit Imperial Valley earthquake data. Holds decision re reopening appeal in abeyance until data is evaluated. New data may affect key seismic findings **SHAW, H. H. / Atomic Safety and Licensing Appeal Panel** 80/06/24 2pp
- 8006100930 Response stating no objection to Governor Ed Brown of State of CA participation in security plan hearing before ARLAB re DL processing Certificate of Use and License **TOURTELLOTT, J. / Hearing Branch 4** 80/06/25 4pp
- 8006100932 Order directing parties to inform ARLAB by 80/07/07 of option that should be selected from Commission 800611 ruling. CL-80-24 remaining prohibited info issue to ARLAB. Requests State of CA views, although not yet participant in DL issue **SHAW, H. H. / Atomic Safety and Licensing Appeal Panel** 80/06/25 3pp
- H General correspondence
- 8006100934 Advises that 800512 ltr is being forwarded to Washington, DC headquarters for inclusion in appropriate public docket file **MANHETT, J. R. / Region 5, San Francisco, Office of the Director** 80/06/10 1p
- 8006100937 Suggests that facility DL be granted as expeditiously as possible. Remaining delay will cause rotating outages & inconveniences. Unused facility burns abundant nuclear fuel & wastes precious oil **DOUGHERTY, L. / Affiliation Unknown** 80/06/12 2pp
- 8006100951 Suggests further seismic research before consideration of DL for facility. Feasibility exists for major earthquake in San Luis Obispo area. Options opening of plant **LEON, S. P. / Affiliation Unknown** 80/06/19 1p
- 8006100956 Requests specific info re granting of DL for facility per H Schneiderman inquiry. Consultant believes secured plant wastes millions of dollars of oil every month & should be opened w/o further delay **LEON, S. P. / House of Rep** 80/06/08 1p
- 8006100971 Forwards 800402 transcript of in camera hearing re security plan in San Luis Obispo-CA. Applicant concerned that no special handling or identification made for security info. Requests that NRC inform court reporters. His email **HORTON, D. / Affiliation Unknown** 80/06/28 1p
- 8006100982 Requests that facility DL not be granted. Too many unanswered questions still remain. Re analysis of effects of Class 9 accident has been made **MANHETT, J. R. / Affiliation Unknown** 80/06/22 1p
- 8006100988 Urges early licensing of facility to save ratepayers billions of CA added cost per imported oil & to save US undesirable consequences of importing approx 25 million barrels of oil per yr **SHAW, H. H. / Affiliation Unknown** 80/06/27 1p
- 8006100992 Advises that 800402 ltr is being forwarded to Washington, DC headquarters for inclusion in appropriate public docket file **MANHETT, J. R. / Region 5, San Francisco, Office of the Director** 80/06/28 1p
- 8006100997 Requests that NRC consider feasibility of converting facility to natural or methane gas. Inherent risk exists for nearby communities. Nuclear accident triggers major earthquake or vice versa **ELANCY, P. / Affiliation Unknown** 80/06/02 1p
- 8006100998 FOIA request for documents re JH Hendrix participation in facility licensing proceeding. Request denied. Fault or offshoots existing & known studies **DOUGHERTY, H. H. / Center for Law in the Public Interest** 80/06/18 2pp
- 8006100999 Opposes licensing of facility due to known fault & 800998 earthquake proving that fault is active. Facility licensing would be relatively inexpensive **SHAW, H. H. / Affiliation Unknown** 80/06/29 1p
- 8006100999 Opposes licensing of facility due to location near Horst fault. Earthquake in CA is very real danger **DOUGHERTY, L. / Affiliation Unknown** 80/06/02 1p

DOCKETED ITEMS

- 0006100389 Requests that NRC reopen seismic hearings before granting Facility OL due to recent Houghs Fault earthquake. Plant was not designed to bear force of earthquake Fault might be reable
ALLDATA A Affiliation Unknown 00/04/02 1p
- 0006200340 Responds to email 000418 1p to President Carter expressing concern re licensing delay public caused by Houghs Fault Affair & subsequent application of "lessons learned"
Facility is one of four high priority plants
BUTLER H B Office of Nuclear Reactor Regulation, Director 00/04/02 2pp
- 0006100502 Requests that OL be denied due to earthquake along Houghs Fault
BENNETT J J, BENNETT R Affiliation Unknown 00/04/02 1p
- 0006100507 Urges that OL be denied due to 000329 earthquake on Houghs Fault
JENNINGS E Affiliation Unknown 00/04/04 1p
- 0006300347 Forwards comments ARNOLD 000507 comments re wind speed exemptions used in development of nuclear emergency regulations NRC plans for public evaluation based on absolute safety
OWASTEN A Senate 00/04/04 App
- 0006100440 Opposes issuance of OL due to prevalence of seismic activity in area
BANDERON J L Affiliation Unknown 00/04/05 1p
- 0006300443 Forwards RM Lundy 000608 ltr expressing concern for plant safety due to proximity to earthquake fault Requests responses directed to consultant
LUNDY MARSHALL J House of Rep. 00/04/05 3pp
- 0006100450 Opposes issuance of OL due to proximity of active fault
STEELE P, STEELE R Affiliation Unknown 00/04/07 1p
- 0006300424 Forwards updated description of civil corporate structure, requesting establishment of nuclear power generation dept. of nuclear safety review group & full oversight group for power generation into FEMA
CHANCE P A Pacific Gas & Electric Co 00/04/08 14pp
- 0006100514 Opposes licensing of facility due to location near Houghs Fault NRC criteria recommend that nuclear reactors should not be sited nearer than 12 1/2 miles to earthquake fault
Facility is located proximately on fault
CARLSON R Affiliation Unknown 00/04/10 1p
- 0006300463 Responds to ltr re position on new power testing permit for Facilities Proposed study on consider alternative approaches to safety problems will not result in delay in licensing but will give better info on which to base decisions
PARKER L E House of Rep. 00/04/12 App
- 0006100541 Opposes granting of OL due to proximity to Houghs Fault Plant should be converted to non-nuclear fuel immediately
ROMANKE P Affiliation Unknown 00/04/16 1p
- 0006300562 Responds to FRDA request for documents re JM Hendrie participation in facility licensing proceeding-Houghs Fault or offshore fueling & USB studies Forwards documents listed in app A & 00062-79/007
FELTON J M Division of Rules and Records 00/04/24 App
- 0 Inspection reports, 1E Bulletins & correspondence
- 0006100597 Forwards 1E Insp Rept 00-275/00-04 on 000418-17 No noncompliance noted
EDWARDS J L, REGAN S San Francisco, Reactor Operations Nuclear Support Branch 00/03/02 App
- 0006100603 1E Insp Rept 00-275/00-07 on 000418-17 No noncompliance noted Rejar area inspected preoperational testing, fire protection & operator training
STERNBERG D H, VOLZKE T Region 3, San Francisco, Office of the Director 00/03/02 App
- 0006200108 Forwards 1E Insp Rept 00-275/00-04 on 000418-18 No noncompliance noted
EDWARDS J L, REGAN S San Francisco, Fuel Facility & Materials Safety Branch 00/03/16 App
- 0006250012 1E Insp Rept 00-275/00-04 on 000418-18 No noncompliance noted Rejar area inspected variations protection & emergency response organization, staffing & training & radiation protection equipment
EDWARDS J L, REGAN S San Francisco, Fuel Facility & Materials Safety Branch 00/03/16 App
Office of the Director 00/03/16 App
- 0006100207 Forwards 1E Insp Rept 00-275/00-12 on 000418-18 No noncompliance noted Encl withheld (ref 00072 700)
KORSETHAUS L B Region 3, San Francisco, Safeguards Branch 00/04/24 App
- 0 Reportable occurrences, 1EIs & related correspondence
- 0006300348 PW-10-00-003 on 000402 Contractor received bomb threat for facility from unknown caller Licensee advised & search conducted
SCHULTZ R D, HERNIMAN J L Region 3, San Francisco, Office of the Director 00/04/02 App
- 000610-277 PEACH BOTTOM ATOMIC POWER REACTION UNIT 2
F Security, medical, emergency & fire protection plans
- 0006000407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 190001" Note added new Section 30.40 & App B to 10CFR50 & is expected to be published in FR by end of May
EISENHART D G Division of Licensing 00/03/19 App
- 0006100323 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 190001", transmitted by NRC 000519 (tr Page 14a not encl)
EISENHART D G Division of Licensing 00/05/22 App
- 0006300101 Forwards 000403 corporate mgt meeting w/col in King of Prussia, PA to discuss proposals for facility health physics staffing
EDWARDS J L, REGAN S Philadelphia, Office of the Director 00/03/29 1p
- 0006100204 Admins schedule for completion of rule re fire protection program in response to NRC 700023 (tr All work will be completed in accordance w/schedule specified in Table 3) of 700023 fire protection rule
SANTOPETERA L Philadelphia Electric Co 00/04/04 App
- 0006100094 Forwards plant security personnel training & qualification plan BL Delivered affidavit encl Plan withheld
EDWARDS J L Philadelphia Electric Co 00/04/09 App
- 0006000002 Forwards comments & requests for add info re safeguards contingency plan Encl withheld (ref 00072 700)
REID R H Operating Reactors Branch 4 00/04/12 App
- 0 Adjudicatory correspondence
- 0006000043 Request for extension until 000610 for parties, except NRC, to submit post-hearing memoranda re reason record lengthy & interviews have other commitments made prior to Feb 1993
Certificate of Rev encl
NEFFS B C Citizens For Safe Environment 00/03/30 App
- 0006000043 Correction to license 000328 brief on disposition of alleged deficiency 1 Certificate of Rev encl
EDWARDS J L Philadelphia Electric Co 00/04/16 App
Philadelphia Edison Co 00/04/16 App
Public Service Electric & Gas Co of New Jersey 00/05/20 App

DOCKETED ITEMS

8004170792 Forwards Waste Packaging Insp Rept 80-13 on 800312-14 re noncompliance noted
 CRITHL S H Region 3, Philadelphia: Fuel Facility & Materials Safety Branch 80/04/24 2pp

--8004170798 Waste Packaging Insp Rept 80-13 on 800312-14 re noncompliance noted Rept 80-13 inspected radiolabel w/DOT & NRC regulations re shipping power & placarding requirements
 ROTHMAN, J P, & BROWN, M H Region 3, Atlanta: Fuel Facility & Materials Safety Branch 80/03/28 4pp

8004170243 Forwards Waste Packaging Insp Rept 80-09 on 800221-25
 No noncompliance noted
 CRITHL S H Region 3, Philadelphia: Fuel Facility & Materials Safety Branch 80/04/24 2pp

--8004170297 Waste Packaging Insp Rept 80-09 on 800221-25
 No noncompliance noted Major areas inspected vessels placarding, packaging conditions & packaging markings
 BROWN, M H Region 3, San Francisco: Fuel Facility & Materials Safety Branch 80-09-01 T. THOMAS, D Region 3, San Francisco: Office of the Director 80/03/25 2pp

8004170261 Forwards Waste Packaging Insp Rept 80-03 on 800227-29
 No noncompliance noted
 CRITHL S H Region 3, Philadelphia: Fuel Facility & Materials Safety Branch 80/04/24 2pp

--8004170371 Waste Packaging Insp Rept 80-03 on 800227-29
 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & DOT marking & labeling
 ROTHMAN, J P, & BROWN, M H Region 3, Philadelphia: Fuel Facility & Materials Safety Branch 80/03/27 7pp

8004030121 Forwards response to permit of IE Bulletin 80-07 dealing w/ plants new in schedule referring outage Visual Insp performed w/condenser TV camera Results of Insp were acceptable & no reportable cracks were found
 DALYBOW, M L Philadelphia Electric Co 80/05/02 3pp

8005050061 Responds to IE Bulletin 80-07, item 3, re BWR jet pump assembly failure Procedures for daily surveillance of jet pump parameters implemented Unit 3 jet pump beam to be adjusted during next outage
 DALYBOW, M L Philadelphia Electric Co 80/05/07 2pp

8005060027 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations cited in IE Insp Repts 80-277/85-04 & 80-278/85-04
 CRITHL S H Region 3, Philadelphia: Office of the Director 80/05/12 1p

--8005060029 Responds to NRC 800403 ltr re violations noted in IE Insp Repts 80-277/85-04 & 80-278/85-04 Corrective actions
 DALYBOW, M L Philadelphia Electric Co 80/04/28 4pp

8004060040 Forwards IE Insp Repts 80-277/85-04 & 80-278/85-04 on 800222-23 & 25-26 & notice of violations
 CRITHL S H Region 3, Philadelphia: Office of the Director 80/04/02 2pp

--8004060044 Notice of violation from Insp on 800222-23 & 25-26
 Region 3, Philadelphia: Office of the Director 80/03/27 2pp

--8004060047 IE Insp Repts 80-277/85-04 & 80-278/85-04 on 800222-23 & 25-26 Noncompliance noted inadequate approved procedures for isolation valves & failure to follow procedures re mode & blocking & permit use
 CRITHL S H Region 3, Philadelphia: Reactor Operations Nuclear Support Branch 800300M, E. S. COWELL, C J Region 3, Philadelphia: Office of the Director 80/03/27 10pp

A Periodic operating reports & related correspondence

8004170445 Forwards monthly operating repts for May 1980
 COONEY, M J Philadelphia Electric Co 80/06/10 1pp

--8004170446 Monthly operating repts for May 1980
 ALDELM H Philadelphia Electric Co 80/06/10 4pp

8004190379 Forwards "Annual Plant Prod Rept 1979"
 ALDELM H Philadelphia Electric Co 80/06/12 1p

--8004190348 "Annual Plant Prod Rept 1979"
 ALDELM H Philadelphia Electric Co 80/06/12 30pp

B Reportable occurrences, LERs & related correspondence

8004150882 RD 2-85-10/3P on 800330-0407 & 17-22, radioactive water was released to circulating water sys caused by flooding of annual condenser steam space permitting radioactive water to leak through defective condenser tube to water sys
 ALDELM H Philadelphia Electric Co 80/06/04 2pp

8004030222 PSC-1-80-090 on 800416, licensee reported possible whole body radiation exposure of 3 1/2 hr of contractor employee during 2nd quarter of 1980 Basimeter found offscale & worker actually received only 1.524 rem on 800429
 ARLEY, S B, & BROWN, J P, CRITHL S H Region 3, Philadelphia: Office of the Director 80/06/10 1p

8004200230 Forwards LER 80-316/017-2
 COONEY, M J Philadelphia Electric Co 80/06/17 3pp

--8004200201 LER 80-316/017-2 on 800426, unit at power, leak developed in a line of condenser caused by leak of proper procedure during shutdown condition allowing steam level to rise
 COONEY, M J Philadelphia Electric Co 80/06/17 1p

U Congressional/Executive Correspondence

8004270241 Responds to 800424 ltr re arrangements made for recent meeting at Facility Public announcement for meeting was issued 800331 Public announcement & mailing list for meeting sent
 CRITHL S H Office of the Executive Director for Operations 80/06/02 10pp

--8004270146 Expresses concern re arrangements for 800424 meeting at Facility Adequate notice of meeting was not provided
 DARRAGH, P D Senate 80/04/24 1p

8004270147 Responds to 800506 ltr re arrangements made for recent meeting at Facility Public announcement was issued well in advance of meeting Public announcement & mailing list sent
 CRITHL S H Office of the Executive Director for Operations 80/06/02 17pp

--8004270150 Comments on arrangements made for recent meeting at Facility NRC should schedule another meeting to obtain further public comments & analysis on emergency response plan
 LORIG, C House of Rep. Appropriations 80/05/26 3pp

800427-270 FRANCH 800300M ATOMIC POWER STATION, UNIT 3

B Security, medical, emergency & fire protection plans

8004070047 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Rule adds new Section 80.48 & App B to 80CFR80 & is expected to be published in FR by end of May
 CRITHL S H Division of Licensing 80/06/19 40pp

8004200463 Comments revised Pages 1-14 & new Page 14e for proposed rule 80CFR80 "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Transmitted by NRC 800519 ltr Page 14e not sent
 CRITHL S H Division of Licensing 80/05/22 70pp

8004200191 Confirms 800503 corporate mgt meeting with Union of Plastics PA to discuss proposals for Facility health physics staffing
 CRITHL S H Region 3, Philadelphia: Office of the Director 80/05/29 1p

DOCKETED ITEMS

0004130024 Submit schedule for completion of work to fire protection program in response to NRC 790503. All work will be completed in accordance with schedule attached in Table D of 790503. Fire protection NRC
04-790503, J. L. Prohaska Electric Co. 04/04/04 Doc

HOA130122 Request comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Separator & Reactor Coolant Pump Supports" Proposed review procedure & implementation. Schedule and signment. S. D. Division of Licensing 00/05/19 72us

DO0410094 Forwards plant security personnel training & qualification
plan SL Galtroff affidavit and Plan withheld
ref 100PM2 7901
BRASLEY, G. J. Philadelphia Electric Co 00/06/09 3pp

8005050379 Forwards application for amend to Licensee EPR-44 & EPR-06 & related Tech Specs pages Application requests changes to Tech Specs re organization for plant operations & composition of plant operation review committee For encl

8006290002 Fernando comments & requests for addl info re safeguards contingency plan Encl withheld inef SOCFR2 7901
FRIB,R H Donatino Bauctors Branch 4 RO/06/12 See

==00660000 Application For amend to Licenses SPR-44 & SPR-86 changing
Task Space re organization for conduct of plant operations &
expansion of plant operation review committee Certificate
of Rev and
BAUER, E. O., BRADLEY, E. J., BOYER, V. S. Philadelphia Electric Co
Philadelphia, Pa.

0 Adjudication correspondence

DDOAGS0245 Request for extension until: DDAGG for parties except NRC.
submit post-hearing memoranda re: radar issue Record length
5 interviews have other commitments made prior to Feb 1980
Certificate of Rev and
HHS/DOJ, C. Citizens for Safe Environment, 8/10/80, App

--80860036 Revised Tech Spec Pages 245 & 246 re 80860 application for
 amend to License D93-44 & D93-56
 to Philadelphia Electric Co. 05/06/03 2pg

800436262 Corrosten to licensees' 938459 brief on disposition of alleged deficiencies I Certificate of Rev and
GILBERG, J E Metropolitan Edison Co RADER, F H Philadelphia Electric Co RADER, H M Public Service Electric & Gas Co of New Jersey 80/05/20 See

SC60120279 Advised that high range effluent noble gas monitor sgs meets
criteria of Leased Landed Tsh Permit 43403-9400
requirements w/exception of ANSI MS28-1977 which requires
sgs presently unacceptable
DALTR0PP.G & Philadelphia Electric Co 80064/04 Spp

NO00000007 Response to interagency-York Committee for Safe Environments
Citizens for Safe Environments request for extension until
NO0001 to file proposed findings of fact in generic radon
proceeding Many delays in proceeding are cause for concern
CONVERT 3 Philadelphia Electric Co. CONNERT 3 Conn. Nuore
Corpor. TWA0000-0107 Metropolitan Edison Co. 00/03/02 lipp

000420034 Ltr to all SAR licensees forwarding "For Comment" edition
of NRSB-08-09, "SAR Production Notice & Control Rad Drive
Return Line Recall Checking." Comments will be evaluated by
NRS prior to final implementation. No end!
EISCHNUT, J D Division of Licensing 08/06/09 J2pp

0054020000 Order granting extension until 000631H for York Committee to
Gaffa Environ & Citizens for Radio Environ to file proposed
findings of fact & conclusions of law HRC findings due on
000703 & intervenors' & applicants' responses on 000710
01000P-C J Atomic Safety and Licensing Appeal Panel 00/05/20
000

REIS:J @ Operating Reactors Branch 4 09/06/12 lly

0004260007 Memorandum 4 order advising that Hearing issue is no longer germane to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 000700

010HDP-C J Atomic Safety and Licensing Appeal Panel 00/0A/03
Duc

historical data base on turbine return steam chemistry &
safety related impact. No available revealed.
GACTROFF, D L. Philadelphia Electric Co. 80/06/12 14pp

if General correspondence

000221 response to Nicholson cancer case
SALTROFF, E L. Philadelphia Electric Co 03/04/90 8pp

0006370002 Discusses 000470 ltr to NRC expressing concern re arrangements for recent meeting at plant. Meetings between NRC & licensees are open to public in most cases. Public announcement was issued on 000031, well before meeting date. BENTON, H. S. Office of Nuclear Reactor Regulation, Director of Operations. ltr.

030426000 Forward revised schedule for implementation of containment
suppression chamber mods to conform w/Hark I long-term
program acceptance criteria
MORRIS, J. B. Philadelphia Electric Co 00/04/00 Doc

6 Inspection reports, IE Bulletin & correspondence

0036270124 Response to 000901 & 00 11rs re R Echolf & W Walkers
concerns about arrangements made for recent meeting at
facility Public arrangements was issued well in advance of
meeting W/public announcement & mailing 11rs
328265W J Office of the Executive Director for Operations
00V6V02 11pp

806488067Y Forwards IE Circular 88-08: "BWR Tech Spec Inconsistency -
Nuclear Protection Sgs Response Time " No written response
required
GSEER, E H Region E, Philadelphia, Office of the Director
80/04/18 1p

0004270152 Response to 000004 ltr re arrangements made for recent meeting at Facility Public announcement was issued well in advance of meeting Public announcement & mailing list about 000004. W J Office of the Executive Director for Operations 00/04/02 japp

0066170095 Forwards Waste Packaging Insp Rept 80-20 on 800120-0001 No
exception noted
BETH D H Region 1, Philadelphia, Fuel Facility & Materials Safety
Branch 80/04/24 Zpp

==8804270155 Requests info re constituent inquiry about SRO notification
of 880428A public meeting
MATHIAS, C W. Reside. 88/03/09 is

noncompliance noted. Major areas inspected: waste shipment & packages, vehicle placarding, packaging conditions & labels. BOWEN, H. K., Region 2, San Francisco, Fuel Facility & Materials Safety Branch. THOMAS, R. D., Region 3, San Francisco, Office of the Director. BROWNE, W. S., Advanced Fuel & Spent Fuel Licensing Branch. 80/00/31 10pp

* Operating license stage documents & correspondence

6604090145 Forwards addl TMI-2 related requirements to operating
reactors. Licensee requirements for TMI Action Plan include
shift training, licensing exam & licensee dissemination
of operating experience. Response requested within 30 days
E1583409, D.D. Division of Licensing 804/825/07 159p

806619040 Forwarder Waste Packaging insp Rept 80-04 on 800121-25
No noncompliance noted
881THQH Region 1: Philadelphia, Feed Facility & Materials Safety
Branch 80/04/24 2ss

8806000514 Summary of 880422-2D meeting w/Hark I owners group in San Jose, CA re confirmatory analysis & testing programs concerning Mark I containment long-term program
GRINDS, C I Assistant Director for Plant Systems 88/06/09 Hqs

No noncompliance noted Major Areas Inspected: vehicle
 placarding, packaging conditions & packaging marking
 ESDS-H-E Region 5, San Francisco, Fuel Facility & Materials
 Safety Branch, FERGUSON, THERMAL D Region 5, San Francisco,
 Office of the Director, OROCKO, San

DOCKETED ITEMS

- 80040500121 Forwards response to purchase of IE Bulletin 89-07 dealing w/ plants now in scheduled refueling outage Visual inspection performed underwater TV camera results of inspection acceptable & no repairable items were found
GALTSOFF, S. L. Philadelphia Electric Co 80/05/02 3pp
- 80040500122 Response to IE Bulletin 89-07 Item 3 Line BWH jet pump assembly Procedures for daily verifications of jet pump parameters implemented Unit 3 jet pump beams to be inspected during each outage
GALTSOFF, S. L. Philadelphia Electric Co 80/05/07 2pp
- 80040500127 Ask receipt of 8004023 letter informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-04 & 50-278/80-04
GREGG, S. W. Region 1 Philadelphia Office of the Director 80/05/12 1p
- 80040500129 Response to PRC 8004023 letter re violations noted in IE Insp Repts 50-277/80-04 & 50-278/80-04 Corrective actions taken
GALTSOFF, S. L. Philadelphia Electric Co 80/04/20 6pp
- 80040500142 Forwards IE Insp Repts 50-277/80-04 & 50-278/80-04 re 8004023-23 & 25-29 & notice of violation
GREGG, S. W. Region 1 Philadelphia Office of the Director 80/04/03 2pp
- 80040500144 Notice of violation from Insp on 8004023-23 & 25-29
Region 1 Philadelphia Office of the Director 80/03/27 3pp
- 80040500147 IE Insp Repts 50-277/80-04 & 50-278/80-04 re 8004023-23 & 25-29 Remedial actions taken/inspected approved procedures for radiological values & facilities re follow procedures re made & briefing & permit
GREGG, S. W. Region 1 Philadelphia, Reactor Operations Nuclear Support Branch 8004023-23 & 25-29, C. J. Region 1 Philadelphia Office of the Director 80/03/27 10pp
- 80040500157 Advice that response to IE Bulletin 79-08 will be submitted by 800517 Environ profiles for LCR & high energy line break requires further refinement by Benthel
GALTSOFF, S. L. Philadelphia Electric Co 80/05/18 1p
- 80041000121 Forwards request for add refs re cracking in low pressure turbine discs Records development of ultrasonic insp for next fuel outage IE Info Notice 79-37 & summary of 800109 meeting w/CE incl
REID, R. H. Operating Reactors Branch 4 80/05/13 2pp
- B Periodic operating reports & related correspondence**
- 80041700145 Forwards monthly operating repts for May 1980
COONEY, M. J. Philadelphia Electric Co 80/06/10 1p
- 80041700146 Monthly operating repts for May 1980
ALLEN, M. H. Philadelphia Electric Co 80/06/10 3pp
- 80041900129 Forwards "Annual Plant Rep Regt 1979"
ALLEN, M. H. Philadelphia Electric Co 80/06/13 1p
- 80041900145 "Annual Plant Rep Regt 1979"
ALLISON, W. T. Philadelphia Electric Co 80/06/12 5pp
- C Reportable occurrences, LERs & related correspondence**
- 80042000144 IE 79-26/1P re 791002, reactor anchor load program identified failure in support associated w/ log 2 were spray discharge line caused by improper installation of anchor with replacement of two failed bolts & its program
WARRINER, T. Philadelphia Electric Co 79/10/03 3pp
- D Congressional/Executive Correspondence**
- 80042700145 Response to 800404 letter re arrangements made for recent meeting at Facility Public announcement for docketing was made
80042700146 Public announcement & mailing list for meeting and
EISENHART, D. J. Office of the Executive Director for Operations 80/04/02 10pp
- 80042700148 Response to 800404 letter re arrangements for 800404 meeting at Facility Adequate notice of meeting was not provided
EISENHART, D. J. Senate 80/04/24 1p
- 80042700149 Response to 800404 letter re arrangements made for recent meeting at Facility Public announcement was issued well in advance of meeting Public announcement & mailing list and
EISENHART, D. J. Office of the Executive Director for Operations 80/04/03 17pp
- 80042700150 Comments on arrangements made for recent meeting at Facility NRC about schedule another meeting to obtain further public comments & analysis on emergency response plan
LOHMEYER, C. House of Rep. Appropriations 80/03/06 3pp
- DOCKET NO. 230 SUNNY POWER STATION, UNIT 1**
P. Security, medical, emergency & fire protection plans
- 80040900140 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 30.40 & App E to 10CFR30.0 is expected to be published in FR by end of May
EISENHART, D. J. Division of Licensing 80/05/19 46pp
- 80041000121 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 80/05/19 for Page 10a not rec'd
EISENHART, D. J. Division of Licensing 80/05/22 73pp
- 80041000124 Response to NRC 800515 request for all review of guard training & specification plan Adequate response
GREGG, S. W. Virginia Electric & Power Co 80/05/29 1p
- 80041000127 Forwards review of add info provided in 8004023-112 & 800414 letter re fire protection program Status of review also incl. Units should attempt to improve schedule to complete work by 80/11/01
WARRINER, S. A. Operating Reactors Branch 1 80/05/29 4pp
- 80041000128 Forwards amended security plan Plan withheld (incl 10CFR 70.0)
GREGG, S. W. Virginia Electric & Power Co 80/06/03 1p
- P. Operating license change documents & correspondence**
- 80040900148 Forwards add TH1-2 related requirements re operating Reactors Licensee requirements for the Action Plan include shift making, licensing forms & licensee dissemination of operating experience Reviews requested within 30 days
EISENHART, D. J. Division of Licensing 80/05/07 190pp
- 80041000127 Application to amend Licensee EPR-02 & NRC-37, clarifying term "operable," submitted as proposed Tech Spec Change 1A, in response to NRC 800410 IE Certificate of Suit
FERGUSON, J. W. Virginia Electric & Power Co 80/05/10 3pp
- 80041000129 Tech Spec Change Request 1A for Tech Specs 1-2-3, 2-0-1-3, 3-0-4, 7-0-3, 7-1-0, 7-0-3, 30-4-3, 30-4-3, 31-3-3, 31-5-3, 31-6-1 & 31-6-2, 31-6-3, 31-6-4, 31-6-5, 31-6-6, 31-6-7, 31-6-8, 31-6-9, 31-6-10, 31-6-11, 31-6-12, 31-6-13, 31-6-14, 31-6-15, 31-6-16, 31-6-17, 31-6-18, 31-6-19, 31-6-20, 31-6-21, 31-6-22, 31-6-23, 31-6-24, 31-6-25, 31-6-26, 31-6-27, 31-6-28, 31-6-29, 31-6-30, 31-6-31, 31-6-32, 31-6-33, 31-6-34, 31-6-35, 31-6-36, 31-6-37, 31-6-38, 31-6-39, 31-6-40, 31-6-41, 31-6-42, 31-6-43, 31-6-44, 31-6-45, 31-6-46, 31-6-47, 31-6-48, 31-6-49, 31-6-50, 31-6-51, 31-6-52, 31-6-53, 31-6-54, 31-6-55, 31-6-56, 31-6-57, 31-6-58, 31-6-59, 31-6-60, 31-6-61, 31-6-62, 31-6-63, 31-6-64, 31-6-65, 31-6-66, 31-6-67, 31-6-68, 31-6-69, 31-6-70, 31-6-71, 31-6-72, 31-6-73, 31-6-74, 31-6-75, 31-6-76, 31-6-77, 31-6-78, 31-6-79, 31-6-80, 31-6-81, 31-6-82, 31-6-83, 31-6-84, 31-6-85, 31-6-86, 31-6-87, 31-6-88, 31-6-89, 31-6-90, 31-6-91, 31-6-92, 31-6-93, 31-6-94, 31-6-95, 31-6-96, 31-6-97, 31-6-98, 31-6-99, 31-6-100, 31-6-101, 31-6-102, 31-6-103, 31-6-104, 31-6-105, 31-6-106, 31-6-107, 31-6-108, 31-6-109, 31-6-110, 31-6-111, 31-6-112, 31-6-113, 31-6-114, 31-6-115, 31-6-116, 31-6-117, 31-6-118, 31-6-119, 31-6-120, 31-6-121, 31-6-122, 31-6-123, 31-6-124, 31-6-125, 31-6-126, 31-6-127, 31-6-128, 31-6-129, 31-6-130, 31-6-131, 31-6-132, 31-6-133, 31-6-134, 31-6-135, 31-6-136, 31-6-137, 31-6-138, 31-6-139, 31-6-140, 31-6-141, 31-6-142, 31-6-143, 31-6-144, 31-6-145, 31-6-146, 31-6-147, 31-6-148, 31-6-149, 31-6-150, 31-6-151, 31-6-152, 31-6-153, 31-6-154, 31-6-155, 31-6-156, 31-6-157, 31-6-158, 31-6-159, 31-6-160, 31-6-161, 31-6-162, 31-6-163, 31-6-164, 31-6-165, 31-6-166, 31-6-167, 31-6-168, 31-6-169, 31-6-170, 31-6-171, 31-6-172, 31-6-173, 31-6-174, 31-6-175, 31-6-176, 31-6-177, 31-6-178, 31-6-179, 31-6-180, 31-6-181, 31-6-182, 31-6-183, 31-6-184, 31-6-185, 31-6-186, 31-6-187, 31-6-188, 31-6-189, 31-6-190, 31-6-191, 31-6-192, 31-6-193, 31-6-194, 31-6-195, 31-6-196, 31-6-197, 31-6-198, 31-6-199, 31-6-200, 31-6-201, 31-6-202, 31-6-203, 31-6-204, 31-6-205, 31-6-206, 31-6-207, 31-6-208, 31-6-209, 31-6-210, 31-6-211, 31-6-212, 31-6-213, 31-6-214, 31-6-215, 31-6-216, 31-6-217, 31-6-218, 31-6-219, 31-6-220, 31-6-221, 31-6-222, 31-6-223, 31-6-224, 31-6-225, 31-6-226, 31-6-227, 31-6-228, 31-6-229, 31-6-230, 31-6-231, 31-6-232, 31-6-233, 31-6-234, 31-6-235, 31-6-236, 31-6-237, 31-6-238, 31-6-239, 31-6-240, 31-6-241, 31-6-242, 31-6-243, 31-6-244, 31-6-245, 31-6-246, 31-6-247, 31-6-248, 31-6-249, 31-6-250, 31-6-251, 31-6-252, 31-6-253, 31-6-254, 31-6-255, 31-6-256, 31-6-257, 31-6-258, 31-6-259, 31-6-260, 31-6-261, 31-6-262, 31-6-263, 31-6-264, 31-6-265, 31-6-266, 31-6-267, 31-6-268, 31-6-269, 31-6-270, 31-6-271, 31-6-272, 31-6-273, 31-6-274, 31-6-275, 31-6-276, 31-6-277, 31-6-278, 31-6-279, 31-6-280, 31-6-281, 31-6-282, 31-6-283, 31-6-284, 31-6-285, 31-6-286, 31-6-287, 31-6-288, 31-6-289, 31-6-290, 31-6-291, 31-6-292, 31-6-293, 31-6-294, 31-6-295, 31-6-296, 31-6-297, 31-6-298, 31-6-299, 31-6-300, 31-6-301, 31-6-302, 31-6-303, 31-6-304, 31-6-305, 31-6-306, 31-6-307, 31-6-308, 31-6-309, 31-6-310, 31-6-311, 31-6-312, 31-6-313, 31-6-314, 31-6-315, 31-6-316, 31-6-317, 31-6-318, 31-6-319, 31-6-320, 31-6-321, 31-6-322, 31-6-323, 31-6-324, 31-6-325, 31-6-326, 31-6-327, 31-6-328, 31-6-329, 31-6-330, 31-6-331, 31-6-332, 31-6-333, 31-6-334, 31-6-335, 31-6-336, 31-6-337, 31-6-338, 31-6-339, 31-6-340, 31-6-341, 31-6-342, 31-6-343, 31-6-344, 31-6-345, 31-6-346, 31-6-347, 31-6-348, 31-6-349, 31-6-350, 31-6-351, 31-6-352, 31-6-353, 31-6-354, 31-6-355, 31-6-356, 31-6-357, 31-6-358, 31-6-359, 31-6-360, 31-6-361, 31-6-362, 31-6-363, 31-6-364, 31-6-365, 31-6-366, 31-6-367, 31-6-368, 31-6-369, 31-6-370, 31-6-371, 31-6-372, 31-6-373, 31-6-374, 31-6-375, 31-6-376, 31-6-377, 31-6-378, 31-6-379, 31-6-380, 31-6-381, 31-6-382, 31-6-383, 31-6-384, 31-6-385, 31-6-386, 31-6-387, 31-6-388, 31-6-389, 31-6-390, 31-6-391, 31-6-392, 31-6-393, 31-6-394, 31-6-395, 31-6-396, 31-6-397, 31-6-398, 31-6-399, 31-6-400, 31-6-401, 31-6-402, 31-6-403, 31-6-404, 31-6-405, 31-6-406, 31-6-407, 31-6-408, 31-6-409, 31-6-410, 31-6-411, 31-6-412, 31-6-413, 31-6-414, 31-6-415, 31-6-416, 31-6-417, 31-6-418, 31-6-419, 31-6-420, 31-6-421, 31-6-422, 31-6-423, 31-6-424, 31-6-425, 31-6-426, 31-6-427, 31-6-428, 31-6-429, 31-6-430, 31-6-431, 31-6-432, 31-6-433, 31-6-434, 31-6-435, 31-6-436, 31-6-437, 31-6-438, 31-6-439, 31-6-440, 31-6-441, 31-6-442, 31-6-443, 31-6-444, 31-6-445, 31-6-446, 31-6-447, 31-6-448, 31-6-449, 31-6-450, 31-6-451, 31-6-452, 31-6-453, 31-6-454, 31-6-455, 31-6-456, 31-6-457, 31-6-458, 31-6-459, 31-6-460, 31-6-461, 31-6-462, 31-6-463, 31-6-464, 31-6-465, 31-6-466, 31-6-467, 31-6-468, 31-6-469, 31-6-470, 31-6-471, 31-6-472, 31-6-473, 31-6-474, 31-6-475, 31-6-476, 31-6-477, 31-6-478, 31-6-479, 31-6-480, 31-6-481, 31-6-482, 31-6-483, 31-6-484, 31-6-485, 31-6-486, 31-6-487, 31-6-488, 31-6-489, 31-6-490, 31-6-491, 31-6-492, 31-6-493, 31-6-494, 31-6-495, 31-6-496, 31-6-497, 31-6-498, 31-6-499, 31-6-500, 31-6-501, 31-6-502, 31-6-503, 31-6-504, 31-6-505, 31-6-506, 31-6-507, 31-6-508, 31-6-509, 31-6-510, 31-6-511, 31-6-512, 31-6-513, 31-6-514, 31-6-515, 31-6-516, 31-6-517, 31-6-518, 31-6-519, 31-6-520, 31-6-521, 31-6-522, 31-6-523, 31-6-524, 31-6-525, 31-6-526, 31-6-527, 31-6-528, 31-6-529, 31-6-530, 31-6-531, 31-6-532, 31-6-533, 31-6-534, 31-6-535, 31-6-536, 31-6-537, 31-6-538, 31-6-539, 31-6-540, 31-6-541, 31-6-542, 31-6-543, 31-6-544, 31-6-545, 31-6-546, 31-6-547, 31-6-548, 31-6-549, 31-6-550, 31-6-551, 31-6-552, 31-6-553, 31-6-554, 31-6-555, 31-6-556, 31-6-557, 31-6-558, 31-6-559, 31-6-560, 31-6-561, 31-6-562, 31-6-563, 31-6-564, 31-6-565, 31-6-566, 31-6-567, 31-6-568, 31-6-569, 31-6-570, 31-6-571, 31-6-572, 31-6-573, 31-6-574, 31-6-575, 31-6-576, 31-6-577, 31-6-578, 31-6-579, 31-6-580, 31-6-581, 31-6-582, 31-6-583, 31-6-584, 31-6-585, 31-6-586, 31-6-587, 31-6-588, 31-6-589, 31-6-590, 31-6-591, 31-6-592, 31-6-593, 31-6-594, 31-6-595, 31-6-596, 31-6-597, 31-6-598, 31-6-599, 31-6-600, 31-6-601, 31-6-602, 31-6-603, 31-6-604, 31-6-605, 31-6-606, 31-6-607, 31-6-608, 31-6-609, 31-6-610, 31-6-611, 31-6-612, 31-6-613, 31-6-614, 31-6-615, 31-6-616, 31-6-617, 31-6-618, 31-6-619, 31-6-620, 31-6-621, 31-6-622, 31-6-623, 31-6-624, 31-6-625, 31-6-626, 31-6-627, 31-6-628, 31-6-629, 31-6-630, 31-6-631, 31-6-632, 31-6-633, 31-6-634, 31-6-635, 31-6-636, 31-6-637, 31-6-638, 31-6-639, 31-6-640, 31-6-641, 31-6-642, 31-6-643, 31-6-644, 31-6-645, 31-6-646, 31-6-647, 31-6-648, 31-6-649, 31-6-650, 31-6-651, 31-6-652, 31-6-653, 31-6-654, 31-6-655, 31-6-656, 31-6-657, 31-6-658, 31-6-659, 31-6-660, 31-6-661, 31-6-662, 31-6-663, 31-6-664, 31-6-665, 31-6-666, 31-6-667, 31-6-668, 31-6-669, 31-6-670, 31-6-671, 31-6-672, 31-6-673, 31-6-674, 31-6-675, 31-6-676, 31-6-677, 31-6-678, 31-6-679, 31-6-680, 31-6-681, 31-6-682, 31-6-683, 31-6-684, 31-6-685, 31-6-686, 31-6-687, 31-6-688, 31-6-689, 31-6-690, 31-6-691, 31-6-692, 31-6-693, 31-6-694, 31-6-695, 31-6-696, 31-6-697, 31-6-698, 31-6-699, 31-6-700, 31-6-701, 31-6-702, 31-6-703, 31-6-704, 31-6-705, 31-6-706, 31-6-707, 31-6-708, 31-6-709, 31-6-710, 31-6-711, 31-6-712, 31-6-713, 31-6-714, 31-6-715, 31-6-716, 31-6-717, 31-6-718, 31-6-719, 31-6-720, 31-6-721, 31-6-722, 31-6-723, 31-6-724, 31-6-725, 31-6-726, 31-6-727, 31-6-728, 31-6-729, 31-6-730, 31-6-731, 31-6-732, 31-6-733, 31-6-734, 31-6-735, 31-6-736, 31-6-737, 31-6-738, 31-6-739, 31-6-740, 31-6-741, 31-6-742, 31-6-743, 31-6-744, 31-6-745, 31-6-746, 31-6-747, 31-6-748, 31-6-749, 31-6-750, 31-6-751, 31-6-752, 31-6-753, 31-6-754, 31-6-755, 31-6-756, 31-6-757, 31-6-758, 31-6-759, 31-6-760, 31-6-761, 31-6-762, 31-6-763, 31-6-764, 31-6-765, 31-6-766, 31-6-767, 31-6-768, 31-6-769, 31-6-770, 31-6-771, 31-6-772, 31-6-773, 31-6-774, 31-6-775, 31-6-776, 31-6-777, 31-6-778, 31-6-779, 31-6-780, 31-6-781, 31-6-782, 31-6-783, 31-6-784, 31-6-785, 31-6-786, 31-6-787, 31-6-788, 31-6-789, 31-6-790, 31-6-791, 31-6-792, 31-6-793, 31-6-794, 31-6-795, 31-6-796, 31-6-797, 31-6-798, 31-6-799, 31-6-800, 31-6-801, 31-6-802, 31-6-803, 31-6-804, 31-6-805, 31-6-806, 31-6-807, 31-6-808, 31-6-809, 31-6-810, 31-6-811, 31-6-812, 31-6-813, 31-6-814, 31-6-815, 31-6-816, 31-6-817, 31-6-818, 31-6-819, 31-6-820, 31-6-821, 31-6-822, 31-6-823, 31-6-824, 31-6-825, 31-6-826, 31-6-827, 31-6-828, 31-6-829, 31-6-830, 31-6-831, 31-6-832, 31-6-833, 31-6-834, 31-6-835, 31-6-836, 31-6-837, 31-6-838, 31-6-839, 31-6-840, 31-6-841, 31-6-842, 31-6-843, 31-6-844, 31-6-845, 31-6-846, 31-6-847, 31-6-848, 31-6-849, 31-6-850, 31-6-851, 31-6-852, 31-6-853, 31-6-854, 31-6-855, 31-6-856, 31-6-857, 31-6-858, 31-6-859, 31-6-860, 31-6-861, 31-6-862, 31-6-863, 31-6-864, 31-6-865, 31-6-866, 31-6-867, 31-6-868, 31-6-869, 31-6-870, 31-6-871, 31-6-872, 31-6-873, 31-6-874, 31-6-875, 31-6-876, 31-6-877, 31-6-878, 31-6-879, 31-6-880, 31-6-881, 31-6-882, 31-6-883, 31-6-884, 31-6-885, 31-6-886, 31-6-887, 31-6-888, 31-6-889, 31-6-890, 31-6-891, 31-6-892, 31-6-893, 31-6-894, 31-6-895, 31-6-896, 31-6-897, 31-6-898, 31-6-899, 31-6-900, 31-6-901, 31-6-902, 31-6-903, 31-6-904, 31-6-905, 31-6-906, 31-6-907, 31-6-908, 31-6-909, 31-6-910, 31-6-911, 31-6-912, 31-6-913, 31-6-914, 31-6-915, 31-6-916, 31-6-917, 31-6-918, 31-6-919, 31-6-920, 31-6-921, 31-6-922, 31-6-923, 31-6-924, 31-6-925, 31-6-926, 31-6-927, 31-6-928, 31-6-929, 31-6-930, 31-6-931, 31-6-932, 31-6-933, 31-6-934, 31-6-935, 31-6-936, 31-6-937, 31-6-938, 31-6-939, 31-6-940, 31-6-941, 31-6-942, 31-6-943, 31-6-944, 31-6-945, 31-6-946, 31-6-947, 31-6-948, 31-6-949, 31-6-950, 31-6-951, 31-6-952, 31-6-953, 31-6-954, 31-6-955, 31-6-956, 31-6-957, 31-6-958, 31-6-959, 31-6-960, 31-6-961, 31-6-962, 31-6-963, 31-6-964, 31-6-965, 31-6-966, 31-6-967, 31-6-968, 31-6-969, 31-6-970, 31-6-971, 31-6-972, 31-6-973, 31-6-974, 31-6-975, 31-6-976, 31-6-977, 31-6-978, 31-6-979, 31-6-980, 31-6-981, 31-6-982, 31-6-983, 31-6-984, 31-6-985, 31-6-986, 31-6-987, 31-6-988, 31-6-989, 31-6-990, 31-6-991, 31-6-992, 31-6-993, 31-6-994, 31-6-995, 31-6-996, 31-6-997, 31-6-998, 31-6-999, 31-7-000, 31-7-001, 31-7-002, 31-7-003,

DOCKETED ITEMS

69

- 0006100324 Progress multi-phase plan to address NRC concerns re
structure amplified response to low being used to
analyze piping age in low head & high head safety injection
lines List of Multistructure problems & sample problem encl
SOLVIA-B R Virginia Electric & Power Co 00/06/06 18pp
- 0006100325 Discusses 000502 meeting w/NEC re test results of
containment spray test mode Delta curves re post-LOCA pump up
to time & proposed Test Mode changes forwarded 000606 "Regis"
encl Request: Final test will be sent 000608
SOLVIA-B R Virginia Electric & Power Co 00/06/11 2pp
- 0006100326 Forwarded "Crackle Feed Design Analysis, Design Change 77-9
Containment Spray Reg. Mod." & "Refueling Water Storage Tank
Control Addition Tank Shutdown Test, 000400" Regis
available in Central Files only
SOLVIA-B R Virginia Electric & Power Co 00/06/10 1p
- 0006100327 Forwarded "Low Head Safety Injection Pump Performance Test
Mark Number 2-B1-01-R" & "Vibration Test of Low Head
Safety Injection Pump Mark Number 2-B1-01-R" available in
Central Files only
SOLVIA-B R Virginia Electric & Power Co 00/05/10 1p
- 0006100328 Forwarded "A-Inch Cavitation Venturis Performance Tests."
Hydraulic Program Reg 24 Complete response to NRC 70001
request for addl info re AGSI mode
SOLVIA-B R Virginia Electric & Power Co 00/04/19 2pp
- 0006100329 Confirm agreement to review criteria for central red bank
activity under the Revised Table A 2 of 10-00-00-00
"Central Red Reactivity Worth Determination by Red Bank
Technique" encl
TSP/DA-W R Virginia Electric & Power Co 00/04/26 1pp
- 0006100330 Forwarded history of experienced total & partial power
outages at facilities per NRC 000307 request
SOLVIA-B R Virginia Electric & Power Co 00/06/06 4pp
- B Inspection reports, IE Bulletin & correspondence
- 0006100331 Forwarded waste packaging insp report on 000313-14
No noncompliance noted
STORR-J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/04/07 2pp
- 0006100334 Waste packaging insp report on 000313-14 No noncompliance
noted Major areas inspected license-shipper vehicles
inspected for compliance w/ DOT & NRC regulations including
shipping paper & DOT placarding requirements
POITEN-J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 00/03/28 4pp
- 0006100335 Forwarded IE Insp Repts 00-200/00-09 & 00-201/00-10 on
000603-09 No noncompliance noted
MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/04/20 2pp
- 0006100336 IE Insp Repts 00-200/00-09 & 00-201/00-10 on 000603-09 No
noncompliance noted Major areas inspected control shams,
action on previous ins findings & quality records
RAJESH-J R Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 0004/20 J. P. HOSKINS-C P Region 2, Atlanta,
Office of the Director 00/04/20 3pp
- 0006100337 Forwarded IE Insp Repts 00-200/00-13 & 00-201/00-10 on
000610-10 No noncompliance noted
LEHMAN-C E Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/05/06 2pp
- 0006100338 IE Insp Repts 00-200/00-12 & 00-201/00-10 on 000415-10 No
noncompliance noted Major areas inspected recovery test
program & interlock pump & valve testing program
WRIGHT-C M Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 0005/01 B R Region 2, Atlanta, Office of the Director
00/05/01 4pp
- 0006100339 Forwarded IE Insp Repts 00-200/00-14 & 00-201/00-10 on
000610-10 No noncompliance noted
MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/06 2pp
- 0006100340 IE Insp Repts 00-200/00-14 & 00-201/00-10 on 000428-10 No
noncompliance noted Major areas inspected installed
equipment review per IE Bulletin 79-010 responses
CHANDLER-T E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 0005/01 C R Region 2, Atlanta, Office of the
Director 00/05/01 4pp
- 0006100341 Forwarded IE Bulletin 00-12, "Steamer Wall Design" Requires
action & written response IE Info Notice 79-20.
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
O'REILLY-J P Region 2, Atlanta, Office of the Director 00/03/08
2pp
- 0006100342 Forwarded IE Bulletin 00-12, "Steamer Wall Design" Requires
action & written response IE Info Notice 79-20.
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
O'REILLY-J P Region 2, Atlanta, Office of the Director 00/03/08
2pp
- 0006100343 Forwarded IE Insp Repts 00-200/00-11 & 00-201/00-10 on 000425-10 No
noncompliance noted Major areas inspected steam generator
alignment & action on previous insp findings
O'BRIEN-J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 0004/00 C R Region 2, Atlanta, Office of the Director
00/03/09 2pp
- 0006100344 Forwarded IE Circular 00-11, "Steaming Diesel Generator Lube
Oil Cooler Failures" No written response required
O'REILLY-J P Region 2, Atlanta, Office of the Director 00/03/13
2pp
- 0006100345 Forwarded IE Insp Repts 00-200/00-10 & 00-201/00-10 on
000429-09 No noncompliance noted
MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/03/20 2pp
- 0006100346 IE Insp Repts 00-200/00-11 & 00-201/00-10 on 000429-09 No
noncompliance noted Major areas inspected IE Bulletin 79-02
& 79-10 & licensee actions on previous insp findings
CHANDLER-T E Region 2, Atlanta, Office of the Director
0004/00 A R Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/03/20 2pp
- 0006100347 Forwarded notice of violation & notice of proposed
imposition of civil penalties re failure of surveys to
detect package on 000414 exhibiting high radiation levels
STELLO-V Office of Inspection & Enforcement, Office of the
Director 00/05/20 2pp
- 0006100348 Notice of violation from insp on 000429-09 Noncompliance
noted findings of survey to detect package for transport on
000414 exhibiting high radiation levels
Office of Inspection & Enforcement, Office of the Director
00/05/20 1p
- 0006100349 Notice of violation from insp on 000429-09 Noncompliance
noted findings of survey to detect package for transport on
000414 exhibiting high radiation levels
Office of Inspection & Enforcement, Office of the Director
00/05/20 1p
- 0006100350 Forwarded IE Insp Repts 00-200/00-09 & 00-201/00-10 on
000603-09 No noncompliance noted
MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/04/20 2pp
- 0006100351 IE Insp Repts 00-200/00-09 & 00-201/00-10 on 000603-09 No
noncompliance noted Major areas inspected control shams,
action on previous ins findings & quality records
RAJESH-J R Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 0004/20 J. P. HOSKINS-C P Region 2, Atlanta,
Office of the Director 00/04/20 3pp
- 0006100352 Forwarded IE Insp Repts 00-200/00-13 & 00-201/00-10 on
000610-10 No noncompliance noted
LEHMAN-C E Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/05/06 2pp
- 0006100353 IE Insp Repts 00-200/00-12 & 00-201/00-10 on 000415-10 No
noncompliance noted Major areas inspected recovery test
program & interlock pump & valve testing program
WRIGHT-C M Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 0005/01 B R Region 2, Atlanta, Office of the Director
00/05/01 4pp
- 0006100354 Forwarded IE Insp Repts 00-200/00-14 & 00-201/00-10 on
000610-10 No noncompliance noted
MURPHY-C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/06 2pp
- 0006100355 IE Insp Repts 00-200/00-14 & 00-201/00-10 on 000428-10 No
noncompliance noted Major areas inspected installed
equipment review per IE Bulletin 79-010 responses
CHANDLER-T E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 0005/01 C R Region 2, Atlanta, Office of the
Director 00/05/01 4pp
- 0006100356 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100357 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100358 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100359 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100360 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100361 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100362 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100363 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100364 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100365 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100366 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100367 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100368 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100369 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100370 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100371 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100372 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100373 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100374 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100375 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100376 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100377 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100378 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100379 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100380 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100381 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100382 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100383 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100384 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100385 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100386 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100387 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100388 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100389 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100390 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100391 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100392 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100393 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100394 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100395 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100396 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100397 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100398 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100399 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p
- 0006100400 Forwarded IE Bulletin 79-12, "Cracking in Feedwater
Piping" Forwarded MOW-0020, "Metallurgical Investigation of
Cracks in Steam Generator Feedwater Lines of Serry Station"
encl
SOLVIA-B R Virginia Electric & Power Co 00/04/03 1p

0004200709 Ask receipt of 000322 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-280/00-04 & 90-281/00-04
 0004200709 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/04 1p

0004202016 Forwarded IE Insp Repts 90-280/00-04 & 90-281/00-04 on 00042015-10 notice of violation
 0004202016 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/01 2pp

0004202610 Notice of violation from Insp on 000419-10
 0004202610 R. E. Region 2, Atlanta, Office of the Director 00/04/30 1p

0004203212 IE Insp Repts 90-280/00-04 & 90-281/00-04 on 000415-10 Noncompliance noted nonfunctional fire door between emergency substation room & hot slag cable vault & failure to implement fire protection procedures
 0004203212 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/30 17pp

0004203403 Ask receipt of 000303 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-280/00-04 & 90-281/00-04
 0004203403 R. E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/05 1p

0004203610 Forwarded to NRC 000418 ltr re violation noted in IE Insp Repts 90-280/00-04 & 90-281/00-04 Corrective actions designated emergency contractors were restrained per emergency plan
 0004203610 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/03/10 2pp

0004203919 Forwarded IE Insp Repts 90-280/00-04 & 90-281/00-04 on 00042014-14 notice of violation
 0004203919 R. E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/10 2pp

0004204010 Notice of violation from Insp on 000310-14
 0004204010 R. E. Region 2, Atlanta, Office of the Director 00/04/11 1p

0004205202 IE Insp Repts 90-280/00-04 & 90-281/00-04 on 00042014 Noncompliance noted failure to conduct restraining fire investigation emergency directors per emergency plan
 0004205202 R. E. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00042014-14
 0004205202 R. E. Region 2, Atlanta, Office of the Director 00/04/11 12pp

0004206094 Ask receipt of 000322 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-280/00-12 & 90-281/00-14
 0004206094 R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/06 1p

0004206094 Forwarded response to NRC 000420 ltr re violation noted in IE Insp Repts 90-280/00-12 & 90-281/00-14 Enc'd withheld (ref 10CFR79.70)
 0004206094 R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/06 1p

0004206103 Forwarded IE Insp Repts 90-280/00-12 & 90-281/00-14 on 0004205204 & 0310-0403 notice of deviation Notice of violation withheld (ref 10CFR79.70)
 0004206103 R. E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/28 2pp

0004206104 Notice of deviation from Insp on 0004205204 & 0310-0403
 0004206104 R. E. Region 2, Atlanta, Office of the Director 00/04/23 1p

0004206107 IE Insp Repts 90-280/00-12 & 90-281/00-14 on 0004205204 & 0310-0403 Noncompliance noted facilities not built as described in FHR & one apparent case of noncompliance in plant security Permits withheld (ref 10CFR79.70)
 0004206107 R. E. Region 2, Chicago, Reactor Operations Nuclear Support Branch 0004205204 & 0310-0403
 0004206107 R. E. Region 2, Chicago, Office of the Director NRC 00/04/23 4pp

0004206220 Forwarded response to IE Bulletin 90-05 re vacuum conditions resulting in damage to hotdog tanks Two potential problem areas involving burner evaporator bottoms tank & boric acid storage tanks identified
 0004206220 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/24 3pp

0004206223 Forwarded response to IE Bulletin 90-09 Hydrogenation reactor Model 201/92 & 201/92 are not used at Facility
 0004206223 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/10 3pp

0004206225 Forwarded response to IE Bulletin 90-12 re decay heat removal gas separation Current procedure provide Adequate safeguards for containment or diversity by requirements but will be changed if substation is operable
 0004206225 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/11 4pp

0004206249 Response to IE Bulletin 90-04 requesting review of drawings for all servicing safety-related functions at substation level, verification of controls & proposed design mods
 0004206249 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/11 10pp

0004206444 Response to NRC 000428 ltr re violations noted in IE Insp Repts 90-280/00-14 & 90-281/00-14
 0004206444 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/20 3pp

0004206673 Forwarded payment for civil penalty proposed in 0004206444 arising from IE Insp Repts 90-280/00-14 & 90-281/00-14
 0004206673 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/20 3pp

0004206836 Response to NRC 000427 ltr re violations noted in IE Insp Repts 90-280/00-14 & 90-281/00-14
 0004206836 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/22 4pp

R. Periodic operating reports & related correspondence

0004207013 Forwarded monthly operating reports for May 1990
 0004207013 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/12 1p

0004207017 Monthly operating reports for May 1990
 0004207017 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 4pp

S. Separable occurrences, LERs & related correspondence

0004206845 EN-00-019 notice of violation & notice of proposed action based on civil penalties will be issued on or about 0004205202 action based on two alleged items of noncompliance
 0004206845 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 0004205202
 0004206845 R. E. Region 2, Atlanta, Office of Inspection & Enforcement, Office of the Director 00/05/03 1p

0004206826 Forwarded LERs 90-025/00L-0 & 90-026/01L-0
 0004206826 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/03 1p

0004206848 LER 90-025/00L-0 on 0004205202 during performance of payment test 14.4 unit at cold shutdown, leakage determined to exceed allowable rate Caused by normal wear from operational use All valves w/leakage repaired or replaced
 0004206848 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/03 2pp

0004206856 LER 90-026/01L-0 on 0004205202 during routine chemistry sampling of boric acid storage tank A to injection tank boric acid concentration found above limit Caused by addition of excessive amount of boric acid prior to sampling
 0004206856 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/03 2pp

0004206818 Forwarded LERs 90-027/00L-0 & 90-028/01L-0
 0004206818 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 1p

0004206823 LER 90-026/00L-0 on 0004205202 while releasing waste gas decay tank 1004-10 operator observed that tank was still filled up to inactive gaseous waste Caused by inlet valve to tank inadvertently left opened Release terminated
 0004206823 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 1p

0004206828 LER 90-027/00L-0 on 0004205202 discharge valve for 1-LM-P-5A was inadvertently left open causing unannounced release from 1-LM-P-5A gravity flow Caused by discharge valve 1-LM-P-5A inadvertently left opened Release terminated
 0004206828 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 2pp

0004206844 RE several lines in low head & high safety injection system not available for relief of fluid from below 70 ft
 0004206844 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 10pp

0004206849 Proposed multi-phase plan to address NRC concerns re amplified response spectra curves used as basis for analyses
 0004206849 R. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 11pp

DOCKETED ITEMS

71

- 0005170442 LER 00-001/02L-0 on 000506 during power operation low temp heat tracing alarm revealed reduction of heat tracing circuit 2 on panel B Alarm caused by defective circuit breaker Breaker replaced & heat tracing operability verified
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 2pp
- 000418470 Forwards LER 00-003/01T-0
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 1p
- 0005180476 LER 00-003/01T-0 on 000506 assumed value for spray nozzle thermal effectiveness for outside recirculation spray test was less conservative than assumed in NRC mod analysis
Caused by error in NRC calculations
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 2pp
- 000406427 Forwards LER 00-006/01T-0
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 1p
- 0006014034 LER 00-006/01T-0 on 000611: Heatingshouse determined that following secondary side high energy line rupture, potential exists for damaging of one or more charging pumps Damage could result of RCS pressure approaches 2-300 psig
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 3pp
- 0004770279 Forwards LERs 00-004/02L-0 & 00-005/02L-0
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 2pp
- 0006020207 LER 00-004/02L-0 on 000605: unit critical at 02 power, any readings for circuit 22A, Panel 2 found below acceptance criteria Cause not stated Heat tracing gear completely replaced No addl action required
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 3pp
- 0006020274 LER 00-005/02L-0 on 000605: unit critical at 02 power, any readings for circuit 22A, Panel 2 found below acceptance criteria Cause not stated Heat tracing gear completely replaced No addl action required
MELSON, J. L. Virginia Electric & Power Co. 00/06/12 3pp
- DOCKET 50-281 SURRY POWER STATION UNIT 2
Security, medical, emergency & fire protection plans
- 0004095407 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 1980" - Rule adds new Section 50.08 & App G to 10CFR50 & is expected to be published in FR by end of May
EIERHART, D. S. Division of Licensing 00/05/19 4pp.
- 0004100663 Forwards Revised Pages 1-4 & new Page 14 for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 1980" - Unpublished by NRC 000619
(in Page 14a not avail)
EIERHART, D. S. Division of Licensing 00/05/22 7pp.
- 0006040274 Responds to NRC 000318 request for still review of guard training & qualification plan Anticipates Forwards response by 000714
MELSON, J. L. Virginia Electric & Power Co. 00/05/29 1p
- 0006040467 Forwards review of addl info provided in 700009, 0113 & 000114 for fire protection program Status of review also not avail should attempt to improve schedule to complete also by 000101
MELSON, J. L. Operating Reactors Branch 1 00/05/29 4pp
- 0006050320 Forwards amended security plan Plan withheld (ref 10CFR2.700)
MELSON, J. L. Virginia Electric & Power Co. 00/06/03 1p
- # Demanding license stage documents & correspondence
- 0006050140 Forwards addl TH-2 related requirements to operating reactors Licensee requirements for TH-2s: Fire Plan, Loss of Shift, Molding, Licensing exam, & license dissemination & of operating experiences Response requested within 30 days
EIERHART, D. S. Division of Licensing 00/05/27 15pp.
- 0006060470 Forwards Amend 08 to License DPR-27, safety evaluation & review of insurance & availability
SCHWENDE, A. Licensing Branch 1 00/05/16 2pp
- 0006050440 Amend 08 to License DPR-27, changing heat flow heat channel factor Co 2.19 based on LOCA-RDOR analysis w/RR when generator tube plugging limit
SCHWENDE, A. Licensing Branch 1 00/05/16 18pp
- 0006050443 Safety evaluation supporting Amend 08 to License DPR-27, Office of Nuclear Reactor Regulation, Director 00/05/16 3pp
- 0006050448 Notice of issuance & availability of Amend 08 to License DPR-27
SCHWENDE, A. Licensing Branch 1 00/05/16 2pp
- 0006010277 Application to amend Licenses DPR-02 & DPR-37, clarifying term "operable," submitted as proposed Tech Spec Change 06 in response to NRC 000410 1st Certificate of Dvc acc'd
FERGUSON, J. H. Virginia Electric & Power Co. 00/05/16 2pp
- 0006130599 Tech Spec Change Request 06 for Tech Specs 1 & 2-0.2.0-1-3 2-0.4.3 7-2.3 9-1.3.9-2.3 10-3.3 10-4.3 11-3.3 11-5 12-10.1 & 3 21-10.1 21-5, revising term "operable" & clarifying applicability
+ Virginia Electric & Power Co. 00/05/16 2pp
- 0006130130 Requests comments on NRC00-0077, "Potential for Low Pressure Temperature & Low Level Turbine on PAR Urban Generator & Reactor Coolant Pump Supports" - Proposed review procedure & implementation schedule not
EIERHART, D. S. Division of Licensing 00/05/19 7pp.
- 0006130173 Advises that, contrary to date stated in 000408 1st temporary post-assessment containment atmospheric gas will be installed by 000606, per NRC00-0078 Permanent gas will be installed by 01001 Slutchev and
MELSON, J. L. Virginia Electric & Power Co. 00/05/20 4pp
- 0006020026 Forwards comments on proposed amend to Tech Spec Unit 1 such as response to comments on offsite dose calculation Manual & process control program re certification of reactors within 45 days
MELSON, J. L. Operating Reactors Branch 1 00/06/01 45pp
- 0006110363 Provides commitment to meet addl TH-2 related requirements, identified in NRC 000307 1st, providing emergency procurement schedules do not impact implementation of hardware changes
MELSON, J. L. Virginia Electric & Power Co. 00/06/06 1p
- 0006130234 Proposes multiphase plan to address NRC concerns re multi-structure amplified response spectra being used to analyze piping sys in low head & high head safety injection lines Link of multi-structure problems & sample problem not
MELSON, J. L. Virginia Electric & Power Co. 00/06/06 18pp
- 0006170499 Discusses 000302 meeting w/NRC re test results of containment spray sys mod. Data curves re post-LOCA spray pit re time & proposed Tech Spec changes forwarded 000609 by NRC request final report will be sent 000610
MELSON, J. L. Virginia Electric & Power Co. 00/06/11 3pp
- 0006180247 Revises "Repl on Reanalysis of Safety-Related Sys. Surry Power Station, Unit 2." Revision 3 Original submitted contained errors
MELSON, J. L. Chance Services, Inc. (subs of Enerspec Corp) 00/06/12 3pp
- 0006180253 "Repl on Reanalysis of Safety-Related Sys. Surry Power Station, Unit 2." Revision 1 resubmitted due to errors in original submitted
+ Chance Services, Inc. (subs of Enerspec Corp) 00/06/11 150pp
- 0006170548 Forwards "Caustic Feed Design Analysis, Design Change 77-9 Combustion Spray Sys Mod." & "Refueling Water Storage Tank - Chemical Addition Tank Drawdown Test, 000435" Repl available in Central Files only
MELSON, J. L. Virginia Electric & Power Co. 00/06/10 1p
- 0006180662 Forwards "Low Head Safety Injection Pump Performance Test, Part Number 2-01-P-18," & "Vibration Test of Low Head Safety Injection Pump, Part Number 2-01-P-18," available in Central Files only
MELSON, J. L. Virginia Electric & Power Co. 00/06/10 1p
- 0006200007 Forwards "6-inch Cavitation Venturi Performance Test," Hydraulic Program Repl 26 Complete response to NRC 700011 request for addl info re NRC mod
MELSON, J. L. Virginia Electric & Power Co. 00/06/19 2pp

DOCKETED ITEMS

000402007 Discusses submittal of final upgraded emergency plans. Evaluation may be necessary, depending on content of pending NRC rules on emergency plans. Submittal for emergency plans examinations targeted to meet 0004001 submittal date. RAYNER, L. D. Northern States Power Co. 00/06/17 1p

0 Operating license correspondence

000402004 Addresses that State of NM 000402004 correspondence are being sent for Goettingh NRC will be prepared to discuss hearing schedule & state examinations during July 1977 prehearing conference in St. Paul, MN. BAYNE, C. A. Hearing Branch 3 00/06/17 1p

000402009 Notice & order for 000402009 conference in US Court House, St. Paul, MN re State of NM 000402009 petition to intervene in US court proceeding. Licensee & NRC shall file responses to intervention petition by 0007015. LAKE, R. M. Admin Safety & Licensing Support Branch 00/06/23 2pp

0 Operating license steps documents & correspondence

000402001 Denominating study of Prairie Island Nuclear Generating Plant, Revision 1. JMW, R. M. Nuclear Energy Service, Inc. 00/06/23 00 24/06/28 4pp

000402002 Recontaminating study of Hotchkiss Nuclear Generating Plant, Revision 1. Nuclear Energy Service, Inc. 00/06/23 00 74/06/28 4pp

000402007 Provides update on 7701203 lit re status of investigations into pressure reactor vessel nozzle cracking results. Indicates reactor vessel nozzle are not susceptible to cracking. ANDERSON, T. M. Washington Electric Corp. 00/07/01 2pp

000402008 Forwarded addl THD-2 related requirements to operating reactor. Licensee requirements for THD Island Plan include shift manning/licensing exam & licensee dissemination of operating procedures. Response prepared within 30 days. 00/08/07, 0 0 Division of Licensing 00/07/07 10pp

000402002 Requests comments on 000402002, "Potential for Low Pressure Turbine to Lubricate Bearing on Prairie Island Generator & Reactor Control Fuel Systems." Proposed review procedure & implementation schedule incl. EISENHART, D. Division of Licensing 00/05/19 7pp

000402004 Forwarded safety evaluation re degraded grid voltage protection for Class 3E at gear up & LLL, reqt. supporting main design mod. & Tech Rep. changes acceptable. RAYNER, L. D. Power Systems Branch 00/05/22 1p

000402004 Safety evaluation supporting proposed mod. & Tech Spec changes re protection of Class 3E equipment & sys from sustained degraded voltage. Power Systems Branch 00/05/22 2pp

000402002 "Technical Evaluation of Proposed Design Mod. & Tech Spec Changes on Unit Voltage Degradation for Prairie Island Nuclear Generating Plant, Units 1 & 2." WHITE, R. L. Lawrence Livermore Laboratory. P/N A-0031. UC-13-16454 00/03/31 13pp

000402002 Forwarded info re implementation of 10CFR50, App. J, containment penetration testing requirements, per 000401 request. RAYNER, L. D. Northern States Power Co. 00/05/23 3pp

000402046 Forwarded addl info in support of 000103 license amend request in response to NRC question. Analyses cover makeup water sys, structural, radiological, and chemical, radiological, mechanical, & tech changes. RAYNER, L. D. Northern States Power Co. 00/06/10 20pp

000402042 Responds to 000402 memo by submitting list of documentation & applicable elements to Facilities Group & vent valves. System mechanical operability facilities meet interim position. RAYNER, L. D. Operating Reactors Branch 0 00/06/10 3pp

000402009 Forwarded listed drawings to enable continuation of review of seismic loads. Primary Seismic Gas Pressure Isolation Valves, Group 3. R. M. RAYNER, L. D. Operating Reactors Branch 3 00/06/10 3pp

000402007 Forwarded response to NRC 000507 lit re addl THD-2 requirements re shift manning/licensing exam, operating procedures, feedback, Bulletin P Orders Test Force examinations & control room habitability. RAYNER, L. D. Northern States Power Co. 00/06/21 14pp

0 Inspection reports, IC Bulletin & correspondence

000402001 Forwarded IC Insp Repts 50-285/00-05 & 50-204/00-06 on 000402-01. No nonconformances noted. RAYNER, L. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/03 2pp

000402002 Forwarded IC Insp Repts 50-285/00-05 & 50-204/00-06 on 000402-01. No nonconformances noted. RAYNER, L. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/10 7pp

000402002 Responds to IC Bulletin 79-17, Revision 3, Item A Visual insp satisfactorily completed on Unit 1 in Apr 1980. No corrective actions necessary. RAYNER, L. D. Northern States Power Co. 00/05/08 1p

000402003 Forwarded temporary version of IC Insp Repts 50-285/00-07 & 50-204/00-07 on 000402-0002. Review of station workload incl. 10CFR50, 7001. HENDON, J. A. Region 3, Chicago, Safety Branch NRC 00/05/22 2pp

000402004 Temporary version of IC Insp Repts 50-285/00-07 & 50-204/00-07 on 000402-0002. Nonconformances noted were physical corrosion not maintained 5 alarm devices not temperature indicating function available. (per 10CFR50 7002) HENDON, J. A. Region 3, Chicago, Safety Branch NRC 00/05/21 2pp

000402004 Addl response to FOIA request for six categories of documents re OPC Forwarded documents listed in app. RAYNER, L. D. Division of Rules & Records 00/05/22 3pp

000402007 Forwarded response to updated memo received on 000301 re unit interrogatories re proposed imposition of civil penalty. Cover sheet of IC Insp Rept and 3. RAYNER, L. D. Region 3, Chicago, Office of the Director 00/03/21 2pp

000402002 Except of IC Insp Repts 50-285/75-01 & 50-204/75-01 conducted on 7/20/80 & 10-15 Nonconformances noted design change packages were not prepared by/ implemented in accordance with NRC administrative control directives. CHALLINOR, E. D. Region 3, Chicago, Office of the Director 00/05/23 5pp

000402003 Revised response to IC Bulletin 79-01B, "Environ. Specification of Class 3E Equipment." Forwarded via comment evaluation worksheet on 000402003. Forwarded 2 replacing worksheet sent in 000302 response. CHALLINOR, E. D. Northern States Power Co. 00/06/23 3pp

000402007 Responds to IC Bulletin 80-10, "Safety Heat Removal Sys. Operability." Operating procedure for reactor refueling (cavity flooded) will require new train of RHR available or accessible source of heated water to replenish and heat. CHALLINOR, E. D. Northern States Power Co. 00/06/26 2pp

0 Periodic operating reports & related correspondence

000402046 Forwarded monthly operating reports for May 1980 & corrected page for Apr 1980 monthly operating report. RAYNER, L. D. Northern States Power Co. 00/06/13 1p

000402043 Monthly operating reports for May 1980. RAYNER, L. D. Northern States Power Co. 00/06/01 3pp

000402043 Monthly operating reports for Apr 1980, corrected pages. RAYNER, L. D. Northern States Power Co. 00/06/13 1p

0 Regulatory correspondence, LCR & related correspondence

000402047 Environ. Event Repts 80-05 on 000501, daily average discharge temp exceeded ambient river water temp by 0.5 F while no cooling towers were undergoing troubleshooting & repair. The lower returnwater to river & electrical load reduced. RAYNER, L. D. Northern States Power Co. 00/05/23 1p

DOCKETED ITEMS

75

- 86040992091 Servico Event Rept 86-02 on 860313-14, claiming ion exchanger out of spec when steam generator blowdown water discharged into river. Sample of effluent revealed pH value greater than 8.5. Caused by seasonal change of river. WMSD, E.C. Northern States Power Co. 86/03/04 3pp
- 8604099004 Final Part 21 rept re mixed bed of steel supplied by US Steel from which 4-inch without 8-inch steel were dug to A234WP9 requirements. Investigation conducted & closed at 46 listed facilities. S&W, J.L. Chandler Corp. - Tube Tunnal Div. 86/03/06 3pp
- 8604099490 Forwards updated LER 86-009/03-L. PWRER, L.G. Northern States Power Co. 86/03/27 3pp
- 8604099499 Updated LER 86-009/03-L on 860310, during normal operation. Nuclear power range channel (PRC) was inoperative for few minutes high voltage supply for detector latched up due to spike on helium instrument bus. WMSD, E.C. Northern States Power Co. 86/03/27 3p
- 8604099495 FORT CALHOUN STATION, UNIT 1
F. Security, medical, emergency & fire protection plans
- 8604099487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rele adds new Section 50.48 & App R to 10CFR50 & is expected to be published in FR by end of May. EISENHUT, D.S. Division of Licensing 86/03/19 46pp
- 8604099494 Forwards supporting info re fire protection, per NRC 860414 request. Overhead drawings available in Central Files only. JONES, W.C. Omaha Public Power District 86/03/20 40pp
- 8604130043 Forwards revised Pages 3-14 & new Page 14a for proposed rule 10CFR50, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Transmitted by NRC 860319 1st Page 14a not incl. EISENHUT, D.S. Division of Licensing 86/03/22 75pp
- 8604270423 Forward request for add info to complete review of 790317 revised safeguards contingency plan. Response due within 30 days. Encl withheld (over 10CFR2.740). CLARK, R.A. Operating Reactors Branch 3 86/03/10 2pp
- H. General correspondence
- 8604280093 Responds to 860313 ltr re importance of public hearings for NRC licensing action. NRC appearance in Omaha 860315 public meeting supports more frequent meetings. Automatic ltr sent to each reactor would update status judgment of operator. EISENHUT, D.S. Operating Reactors Branch 4 86/03/22 2pp
- 8604150084 Requests that MA Tator be substituted for MR Paradis as new ltr in future; all info should be sent to MA Tator. TEBER, H.A. L&Sour, Lamb, Lashy & Huchins 86/03/28 1p
- J. Insurance & indemnity information
- 8604280256 Forwards revised cash flow projection in response to 8603029 ltr pointing out deficit cash & production cost adjustment plus a month behind cash flow costs for anticipated extended fuel outage recoverable in late 1990. PETERSON, H.L. Omaha Public Power District 86/03/18 4pp
- P. Operating license stage documents & correspondence
- 8604099485 Forwards add 7901-2 related requirements to operating reactors. Licensee requirements for the Action Plan include shift monitoring, licensing stages 1 license dissemination, & operating experience. Response requested within 30 days. EISENHUT, D.S. Division of Licensing 86/03/07 150pp
- 8604099492 Notification of 860402 meeting w/with in Bethesda, MD to discuss anticipated vented condenser & core retention devices. REYER, J.F. Reactor Systems Branch 86/03/27 3pp
- 8604310129 Requests comments on WMSD-0077, "Potential for Low Fracture Propagation & Initiator Testing." Request for comments by Reactor Coolant Pump Supports. Proposed review procedures & implementation schedule encl. EISENHUT, D.S. Division of Licensing 86/03/19 72pp
- 8604099486 Forwards Amend 4B to License 86P-40, safety evaluation & notice of issuance & availability. CLARK, R.A. Operating Reactors Branch 3 86/03/27 3pp
- 8604099485 Amend 4B to License 86P-40, adding license condition re secondary water chemistry & changing Tech Specs to allow limited testing of stack suppressors during operation. CLARK, R.A. Operating Reactors Branch 3 86/03/27 4pp
- 8604099486 Safety evaluation supporting Amend 4B to License 86P-40 & Office of Nuclear Reactor Regulation, Director 86/03/27 3pp
- 8604099486 Notice of issuance & availability of Amend 4B to License 86P-40. CLARK, R.A. Operating Reactors Branch 3 86/03/27 3pp
- 8604099486 Notification of 860405 meeting w/with in Bethesda, MD to discuss core propagation studies & asymmetric loads evaluation. WMSD, E.C. Operating Reactors Branch 3 86/03/02 1p
- 8604280423 Forwards response to NRC 860315 request for info re turbine disc integrity. JONES, W.C. Omaha Public Power District 86/03/13 4pp
- 8604280424 Forwards implementation schedules for meeting add TH requirements submitted in NRC 860307 ltr. JONES, W.C. Omaha Public Power District 86/03/17 3pp
- 8604300372 Forwards responses to NRC questions re rept, "Fort Calhoun Cycle & Small Break EESB Performance Evaluation at 1,000 MPa." submitted in support of 790777 application for amend of OL. JONES, W.C. Omaha Public Power District 86/03/26 6pp
8. Inspection reports, IE Bulletins & correspondence
- 8604099424 Forwards reply re status of responses to IE Bulletin 79-14, "Genetic Analysis for As-Built Safety-Related Piping Sys." & IE Bulletin 79-02, "Uncontrolled Extension - Low Stressed by JONES, W.C. Omaha Public Power District 86/04/12 42pp
- 8604099415 Forwards IE Insp Rept 86-039/86-08 on 860415-17 No noncompliance noted. WMSD, E.C. Region 4, Dallas, Reactor Operations Nuclear Support Branch 86/04/25 3pp
- 8604099412 IE Insp Rept 86-039/86-08 on 860415-17 No noncompliance noted. Major areas inspected: implementation of 860308-0376, size protection commitments & progress vs IE Bulletin 79-02 & 79-14. EISENHUT, D.S. Region 4, Dallas, Reactor Operations Nuclear Support Branch 86/04/24 4pp
- 8604099407 Forwards IE Bulletin 86-13, "Heavy Wall Design." Requires action & written response. IE safe notice 79-02, "Overloading of Structural Elements Due to Pipe Support Loads" encl. EISENHUT, D.S. Region 4, Dallas, Office of the Director 86/03/08 1p
- 8604099406 Forwards IE Bulletin 86-13, "Bare Heat Removal Sys. Operability." Requires action & response within 30 days. IE safe notice 86-25, "Loss of Steam Heat Removal Capability at Davis-Besse Unit 3 while in Hot-Standing Mode" encl. EISENHUT, D.S. Region 4, Dallas, Office of the Director 86/03/09 1p
- 8604099423 Forwards response to IE Bulletin 86-24, "Analysis of PMR Reactor Steam Line Break Incident." Requires action & response within 30 days. Affected steam generator blow down at 29.1 seconds & thus terminates initial RCS cooldown. WMSD, E.C. Omaha Public Power District 86/03/15 27pp
- 8604099403 Forwards IE Insp Rept 86-039/79-18 on 791225 No noncompliance noted. WMSD, E.C. Region 4, Dallas, Fuel Facility & Materials Safety Branch 86/03/19 3pp
- 8604099407 IE Insp Rept 86-039/79-18 on 791225 No noncompliance noted. Major areas inspected: program procedures & activities associated w/handling of waste. EISENHUT, D.S. Region 4, Dallas, Fuel Facility & Materials Safety Branch 86/03/19 3pp
- 8604310074 Add response to FOIA request for six categories of documents re CPC Forwards in months listed in 860315. FOLTER, J.H. Division of Policy and Records, 86/03/20 3pp

DOCKETED ITEMS

--0004130008 Forwarded LERs in response to call interrogatory 12 re violations of containment integrity & civil penalty No violation of noncompliance found re call interrogatories 12 or 14
 0004130008 F Region 4, Dallas, Office of the Director
 00/05/19 1p

--0004130009 Forwarded AD 50-205/74-14
 JPHBLS H C Omaha Public Power District 74/05/17 1p

--0004130009 AD 50-205/74-14 on 74/05/05 during routine inspection was discovered during from vent side of containment pressure indicating manometer changed by error in preparation & review of procedure for establishing containment integrity
 C Omaha Public Power District 74/05/16 4pp

0004130010 Forwarded corrected Page 6 to IE Investigation Rept
 50-205/00-10
 BRSBW D D Region 4, Dallas, Fuel Facility & Materials Safety Branch 00/05/08 1p

--0004130010 Replacement Page 6 to IE Investigation Rept 50-205/00-10
 BRSBW D D Region 4, Dallas, Fuel Facility & Materials Safety Branch 00/05/08 1p
 BRSBW D D Region 4, Dallas, Office of the Director
 BRSBW D D Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/08 1p

--0004130010 Forwarded IE Investigation Rept 50-205/00-10 on 00/05/16 & 6 letters of violation
 BRSBW D D Region 4, Dallas, Fuel Facility & Materials Safety Branch 00/05/20 2pp

--0004130014 Notice of violation from Investigation re 000413-14
 C Region 4, Dallas, Office of the Director 00/05/20 1p

--0004130018 IE Investigation Rept 50-205/00-10 on 00/05/16
 Noncompliance noted failure to perform required radiation survey
 BRSBW D D Region 4, Dallas, Fuel Facility & Materials Safety Branch 00/05/18 1p
 BRSBW D D Region 4, Dallas, Office of the Director
 BRSBW D D Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/23 10pp

8 Periodic operating reports & related correspondence

0004130048 Forwarded monthly operating report for May 1989
 JPHBLS H C Omaha Public Power District 00/05/09 1p

--0004130048 Monthly operating report for May 1989
 HEDRLS J C Omaha Public Power District 00/05/09 10pp

8 Reportable occurrences, LERs & related correspondence

0004130048 AD re 000505 during primary gas leakage loop leakage detected from reactor coolant pump RC-3C caused by corrosion damage to leakage studs studs which caused corrosion will be replaced & metallurgical exams performed
 RTEVMS G C Omaha Public Power District 00/05/23 3pp

0004130019 Forwarded LER 00-008/003-0
 RTEVMS G C Omaha Public Power District 00/05/21 1p

--0004130019 LER 00-008/003-0 on 00/05/21 during check of power supply trip indicating light-AS-1 matrix relay of reactor protective trip failed to trip clutch power supplies caused by failure of matrix tested relay in matrix circuit
 CDRS H C EDWARDS J F Omaha Public Power District 00/05/19 4pp

0004130024 Forwarded LER 00-009/097-0
 STEVMS G C Omaha Public Power District 00/05/08 1p

--0004130030 LER 00-009/097-0 on 00/05/21 during maint on stack engine process monitor new sensor with cable was required caused by use of wrong tailer procedure Training will be conducted to ensure familiarity w/procedures
 HEDRLS J C EDWARDS J F Omaha Public Power District 00/05/29 4pp

0004130048 Forwarded LER 00-010/011-0
 STEVMS G C Omaha Public Power District 00/05/23 1p

--0004130048 LER 00-010/011-0 on 00/05/23 during leak pressure test leakage discovered at gasket joint between pump casing & pump cover on reactor coolant pumps RC-3A, 3B & 3C closure studs removed by sulfuric acid leaks caused by deteriorated gaskets
 FLEWEL J C Omaha Public Power District 00/05/17 8pp

SECRET 50-004 INDIAN POINT STATION UNIT 2

F Security: medical, emergency & fire protection plans
 0004130008 50-004 INDIAN POINT STATION UNIT 2

0004130008 Forwarded proposed rule entitled, "First Protection Program for Nuclear Power Plants Operating Prior to 70/0101" re Rule added new Section 50.48 & App R re 100/05/0 & is expected to be published in FR by end of May
 RTEVMS G C Division of Licensing 00/05/19 4pp

0004130019 Forwarded comments re 000430 submittal of revised safeguards (comparing plant response requested within 30 days Comments withheld (ref 100/05/2001)
 VARS S A Operating Reactors Branch 1 00/05/20 2pp

0004130023 Forwarded revised Pages 1-14 & new Page 14a for proposed rule 100/05/0 "First Protection Program for Nuclear Power Plants Operating Prior to 70/0101" transmitted by NRC 00/05/19 1st Page 14a not sent
 RTEVMS G C Division of Licensing 00/05/22 73pp

0004130023 Advises NRC of recent developments re emergency preparedness at facilities with existing emergency plans in accordance with NRC-0004-0004, retaining USN Nuclear Inc to assist State of NY & Westchester County in revising plans
 CARILL J J Consolidated Edison Co of New York EARLY P J Power Authority of the State of New York 00/05/00 5pp

0 Adjudicating correspondence

0004130033 Order stating four-pronged approach to resolve USN petition for Unit 1 decommissioning 4 Units 2-3 shutdown adjudication before AECB informal proceeding to determine license renewal consideration & establishment of anti-siting task force
 CHILS J J Office of the Secretary of the Commission 00/05/33 8pp

0004130036 Responds to 000505 objection to scheduling meetings outside Washington, DC area meetings are occasionally held outside of Washington, DC vicinity to allow persons living near plants opportunity to attend
 RTEVMS G C Division of Licensing 00/05/02 2pp

0004130038 Notice of withdrawal from proceeding effective 00/05/08 Notice of NRC appearance & Certificate of Gov w/ci
 LEVMS H H Hearing Branch 2 00/05/06 4pp

0004130038 Forwarded response to NRC 000511 continuing order 120-day action item
 EARLY P J Power Authority of the State of New York 00/05/11 10pp

0004130047 Order granting extension until 00/07/01 from Commission to start whether to revise ALAB-426 & portions of ALAB-501
 CHILS J J Office of the Secretary of the Commission 00/05/16 1p

0004130048 Comments on Commission 000500 order re safe operation & criteria of operating CP & OL established criteria should apply & burden of proof must remain on licensee Specific design changes must be feasible
 HEDRLS J C EDWARDS J F Union of Concerned Scientists WEISS H H Shelden, Herman & Weiss 00/05/20 2pp

0004130052 Memorandum in response to Commission 000500 order initiating informal proceeding Urges development of industry-wide policy/schedule & site prior to consideration of units separately in adjudicatory hearings
 BRSBW D D Consolidated Edison Co of New York PRATT C H Power Authority of the State of New York 00/05/20 2pp

0004130056 Forwarded USN 000423 motion to disqualify Commissioner Hendrie
 HEDRLS J C EDWARDS J F Shelden, Herman & Weiss 00/05/23 1p

--0004130056 Motion to disqualify Commissioner Hendrie from further participation in NRC deliberations re USN petition for decommission of operating Reactors is based on Hendrie involvement w/ facility as member of ACES
 HEDRLS J C EDWARDS J F Union of Concerned Scientists WEISS H H Shelden, Herman & Weiss 00/05/23 10pp

--0004130052 Response to 730717 ltr re will siting criteria Indian Point site meet NRC regulations & criteria Considerable energy has been expended to assure public health & safety
 HEDRLS J C Atomic Energy Commission, Directorate of Licensing 73/09/10 2pp

DOCKETED ITEMS

77

General correspondence

000603014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas
HARRIS, A. Affiliation Unknown 05/03/19 1p

000619040 Comments on 000500 order for shutdown of plants pending adequate emergency plans to plant for severe outages
acceptable emergency plans exist Energy & economic factors should have minimal influence on decision to shut down
HOLZ, E. Affiliation Unknown 05/03/19 3pp

000620017 Requests that following items be included on correspondence distribution list: OT Perry, J.P. Manager, CN Millwright, CN Pratt & R. Patterson
BAYNE, J.P. Power Authority of the State of New York 06/06/20 2pp

Operating license & age documents & correspondence

000620010 Forwards add TRI-2 related requirements for operating reactors Licenses requirements for TRI Action Plan include shift meaning, licensing plans & license dissemination of operating experience Response requested within 30 days
EISENHART, D.G. Division of Licensing 05/03/19 10pp

000624000 Notification of 000523 meeting w/whills, contractors & consultants in Bethesda, MD to exchange technology re accident sequence & related phenomena per A. Gaborczak
000410 for to L. Peoples
LISSE, J.K. Reactor Systems Branch 05/03/19 2pp

000625012 Requests comments on NRC-0577, "Potential for Low Pressure Turbine & Lamellar Sealing on PWR Steam Generator & Reactor Coolant Pump Supports - Proposed Review Procedure & Implementation Schedule and
EISENHART, D.G. Division of Licensing 05/03/19 7pp

000626012 Notification of 000523 meeting w/whills in Bethesda, MD re severe accident mitigation features for facilities
OLSHAN, L. RECOVER, R. Operating Reactors Branch 1 05/03/20 1p

000629010 Forwards request for add info re QA program Response should be submitted within 30 days
VERONA, A. Operating Reactors Branch 1 05/03/20 3pp

000629034 Response to NRC 000425 for re confirmation under requirement of obtaining APSC reliability improvements by 000613
Confirm schedule commitments Provides detailed description of proposed improvements By will be operative by 000613
EARLY, P. J. Power Authority of the State of New York 06/03/20 2pp

000630024 Forwards responses to 000406 for re QA program review Responses do not constitute proper format for formal QA
exam items
BERRY, T. J. Power Authority of the State of New York 05/05/20 8pp

000630035 Forwards supplemental info re degraded grid voltage & adequacy of station electric distribution sys voltages
EARLY, P. J. Power Authority of the State of New York 06/03/20 17pp

000630037 Forwards add info re electrical override/backup aspects of containment purge sys per 000411 request Overrule findings available in Central Files only
EARLY, P. J. Power Authority of the State of New York 05/06/02 17pp

000631040 Forwards slides used by whills during 000502 meeting re technology exchange in area of mitigation feature for severe accidents at facilities
GOSBERG, D. Westinghouse Electric Corp 05/06/03 1p

000631045 Forwards "Mitigation of Severe Accident Study Rept" Rept includes presentations made to NRC & ACRS on 000502 & 000503, respectively & consists of state-of-the-art analyses conducted within 60-day period
GALLIL, M. J. Consolidated Edison Co. of New York EARLY, P. J. Power Authority of the State of New York 05/06/06 3pp

000631048 Informs that Section 4 of Rept submitted on 000605 was inadvertently stamped proprietary Class 2 Rept is nonproprietary
GALLIL, M. J. Consolidated Edison Co. of New York EARLY, P. J. Power Authority of the State of New York 05/06/06 1p

000631049 Response to 000502 for transmitting reft covering work performed by various consultants Entire Westinghouse reft nonproprietary
PEOPLE, D. L. Commonwealth Edison Co 05/06/03 3pp

000631046 "Mitigation of Severe Accident Study Rept" consisting of refts re evaluation of residual risk, steam explosion, containment response for Class 2 accidents & containment containment work sys conceptual designs
Westinghouse Electric Corp 05/03/20 40pp

000631049 Forwards Con Ed 000505 & Power Authority of State of NY 000507 ltr re economic effects of extended shutdown for consideration by NRC Staff force
GALLIL, M. J. Consolidated Edison Co. of New York EARLY, P. J. Power Authority of the State of New York 05/06/06 15pp

000627047 Summary of 000520 Technology Exchange Meeting 3 w/whills in Bethesda, MD re accident mitigation features for facilities
LISSE, J.K. Reactor Systems Branch 05/06/12 27pp

000633045 Forwards response to TRI-2 related requirements per 000507 request
BAYNE, J. P. Power Authority of the State of New York 05/06/16 13pp

000635000 Notification of 000503 meeting w/whills, contractors & consultants in Bethesda, MD for presentation in area of severe accident sequences for facilities Agenda encl
HEYER, J. P. Reactor Systems Branch 05/06/16 2pp

000625003 Notification of 000503 meeting w/whills & consultants in Bethesda, MD to discuss technology exchange re containment structural response, failure pressures & failure modes
HEYER, J. P. Reactor Systems Branch 05/06/17 2pp

000625034 Notification of 000520 meeting w/whills in Bethesda, MD re discuss re-evaluation of operational QA program
LISSE, M. L. Quality Assurance Branch 05/06/17 2pp

000626014 Advises that 000611 responses to NRC 000211 confirmatory order included typographical error in item 7 & 8 Schedule date of 000611 is incorrect Item 7 & 8 Finality Study & schedule for finalization to be completed by Dec 1/01
BAYNE, J. P. Power Authority of the State of New York 05/06/20 2pp

000627017 Forwards response to NRC 000503 request for info on facility QA program Responses not considered part of present NRC-approved QA program commitments
GOSBERG, D. J. Power Authority of the State of New York 06/06/20 20pp

Inspection reports, IE Bulletin & correspondence

000630033 Forwards response to IE Bulletin 00-04 Analysis results show that steamline break w/whills of auxiliary feedwater reactor protection sys would not result in containment
overpressurization
GOSBERG, D. J. Power Authority of the State of New York 05/05/08 8pp

000610011 Act receipt of 000407 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 00-08/79-03
GOSBERG, D. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 05/03/09 1p

000610032 Response to NRC 000914 for re violations noted in IE Insp Rept 00-28/79-23 Corrective actions: licensed operations personnel have been instructed in procedures Containables have been removed from diesel generator room
BAYNE, J. P. Power Authority of the State of New York 05/06/07 2pp

000610032 Forwards IE Insp Rept 00-28/79-23 on 770700-1027 & notices of violation
GOSBERG, D. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 05/03/14 2pp

000610032 Notice of violation, A from Insp on 770700-1027 Partial withheld due to 100796 7901
* Region 1, Philadelphia, Office of the Director 05/03/27 1p

000610032 Notice of violation, A from Insp on 770700-1027
* Region 1, Philadelphia, Office of the Director, 05/03/27, 1p

DOCKETED ITEMS

--866120147 IE Insp Rept 80-284/39-32 on 790930-1027 Noncompliance noted failure to adhere to procedures & failure to remove identified contamination. Facilities withheld info 10CFR 7501
 866120147 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 NUREG Support Branch 80/05/27 1pp

866120049 Forwards IE Circular 80-12, "On-Ship Damage to Working-Steam Fuel Assemblies." No written response received 80/05/18
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1p

866118083 Forwards interim status report to IE Bulletin 79-14, "Belmont Analysis for an Built-Safe-Related Piping Sys." Line walks of all 194 electric pump ducts analyzed lines & 117 dynamically analyzed lines in accessible areas completed 80/05/17
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866120030V Responses to Item 7 of IE Bulletin 80-12, "Decay Heat Removal Sys Operability." Procedures & equipment capabilities have been reviewed & analyzed & found adequate during various modes of operation
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

8. Periodic monitoring reports & related correspondence

866117431 Forwards data specified in Section 401 Certification for May 1980 to NE State Dept of Environment Conservation
 866117431 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/10 1p

--866130436 Circulating water temp-gens electrical output & river water discharge info for May 1980
 * Consolidated Edison Co. of New York 80/05/10 1pp

866130324 Forwards "Quarterly Rept on Belmont Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project, Dec 1979-Feb 1980"
 866130324 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/13 1p

--866130326 "Quarterly Rept on Belmont Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project, Mar 1979-Feb 1980"
 * Consolidated Edison Co. of New York 80/05/12 1pp

866130531 Forwards monthly operating report for May 1980 & associated pages for operating report for Mar & Apr 1980
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/13 1p

--866130531 Monthly operating report for May 1980
 866130531 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866130426 Forwards daily fish counts from intake screens for May 1980
 866130426 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/13 1p

--866130427 Daily fish counts from intake screens for May 1980
 * Consolidated Edison Co. of New York 80/05/13 1pp

8. Reportable occurrences, LERs & related correspondence

866130547 PWR-1-80-018 re 800519, four separate steam pump threats were received from calls received by Westcott-Potomac River & Bay by Supervision's Dept. Town of Westcott-Potomac River search procedures initiated at both plants
 866130547 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/20 1p

866130517 PWR-1-80-014 re 800603, Evening Star of Buchanan, NY received phone call from unidentified male advising that Bureau of Liberty bonded & facility would be seek search of facilities reported no evidence of bond
 866130517 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/14 1p

866130522 PWR-1-80-015 on 800604, Daily News, NY City newspaper received phone call from unidentified male advising that Bureau of Liberty bonded & facility would be seek search of facilities reported no evidence of bond
 866130522 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/14 1p

866130530 RD re 800614, while sys was in incident mode, testing was performed on control room air filtration sys test indicated total air filter flow was greater than extrapolated max flow value although operating control room air filtration charcoal
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/16 1p

866130544 Forwards LER 80-007/03-3
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1p

--866130547 LER 80-007/03-3 re 800523, while operating at 70% power, movements of electrical lines near 100% power test 80/05/12 indicated undesirable or unsafe wire damage value caused by dirty contacts on associated relays
 866130547 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1p

T Hearing transcripts on non-qualified matters

866130547 Transcript of 800530 Affirmation Session 80-06 in Washington, DC
 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

--866130512 Recommendations Approval of recall revised draft order Encl PA Bradford, separate statement to be approved to order
 866130512 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

--866130512 Responses to 800524 1st re J. JOHNSON re problems of evaluating large populations in short period of time Program of operating emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant
 866130512 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

--866130512 Elaborates on concerns expressed in 800524 1st re need for coordinated evaluation plans around nuclear power sites. Problems of evaluating large populations in short time have been determined. Reactions to concerns re issues
 866130512 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866130537 800537 NUCLEAR STATION, UNIT 3

P Security, medical, emergency & fire protection plans

866130537 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Rule adds new Section 39.48 & App B to 10CFR 50 & is expected to be published in FR by end of May
 866130537 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866130537 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR 50, "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Transmitted by NRC 80/05/18 1st Page 14a not encl
 866130537 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866130510 Forwards revision to safeguards contingency plan Plan withheld info 10CFR 7501
 866130510 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/20 1p

866130510 Forwards revision to nuclear security training & qualification plan Plan withheld info 10CFR 7501
 866130510 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/20 1p

866130510 Forwards comments & requests for addl info re guard training & qualification plan Encl withheld info 10CFR 7501
 866130510 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/28 1pp

866130530V Forwards report 1st re 800519 revision to nuclear security training & qualification plan Plan withheld info 10CFR 7501
 866130530V J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/10 1p

9. Adjudicatory correspondence

866130544 Forwards Lincoln County, NC Board of County Commissioners 70/001 & 800480 resolutions affirming position that agent nuclear Plant should be transported from Durham to Redwine on interstate highway
 866130544 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/17 1pp

866130544 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision
 866130544 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/19 1pp

--866130544 Substantive of proposed findings of fact & conclusions of law in form of initial decision
 866130544 J. JOHNSON, Jr. Region 1, Philadelphia, Office of the Director
 80/05/19 1pp

- 0004040228 Proposed initial decision containing findings of fact & conclusions of law approving amendment to subcritical storage of spent fuel at McGuire Division radiological monitoring program shall be maintained M/Certificate of Govt. REGANRY, J. H. Duke Power Co. REGANRY, J. H. Debusse & Liskman 8/10/81/17 3pp
- 0004100117 Response in support of Carolina Environ. Study Group 000502 proposed elements of fact & conclusions of law toward initial decision No good reason presented for not approving application re spent fuel shipment M/Certificate of Govt. REGANRY, J. H. Duke Power Co. REGANRY, J. H. Debusse & Liskman 8/10/81/17 3pp
- 0004100293 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amendment to McGuire Division spent fuel transportation to & storage at McGuire RETCHICH, C. D. Hearing Branch 4 8/10/81/17 3p
- 0004100408 Proposed findings of fact & conclusions of law in form of initial decision approving license amendment to McGuire Division spent fuel transportation to & storage at McGuire Proposed transcript corrections & Certificate of Govt. RETCHICH, C. D. HOFPLING, H. A. Hearing Branch 4 8/10/81/17 10pp
- 16 General correspondence
0004070309 Forwards county board resolution requesting NRC to consider using onsite storage of radioactive waste rather than shipping through county Also forwards board resolution requesting public input re EOT regulations HOFPLING, H. A. Greenville County, NC 8/10/81/23 3pp
- P Operating license stage documents & correspondence
- 0004040327 Response to technical assistance request for proposed Tech Spec changes for BSM operating plants Foreword requirements for add'l info. JORALL, G. L. TIS 2 Ballietts & Greaves 7/10/81/29 13pp
- 0004090509 Forwards schedules for still responses to NRC 7/11/81 1tr re C. H. Hilsburg comments on small press LOGAN, C. P. TIS-2 Ballietts & Greaves 7/11/81/10 3p
- 0004040329 Foreword documents for Auxiliary BSM Branch review of auxiliary feedwater reliability analysis for BSM operating plants W/O encs. CAPRA, R. A. Light Water Reactors Branch 3 8/10/81/17 3pp
- 0004000542 Forwards resolution to 800527 route approval request for shipment of spent fuel changing dates for shipment Revision withheld (ref 10CPH2 790) PARKER, W. D. Duke Power Co. 8/10/81/17 3p
- 0004060145 Forwards add'l TIS-2 related requirements to operating reactors Licenses requirements for TIS Action Plan include shift meeting, increasing exam & license administration of operating experience Response requested within 30 days EIRB/0407, D. O. Division of Licensing 8/10/81/57 10pp
- 0004100122 Request comments on NRC-0377, "Potential for Low Pressure Response & Low Level Tearing on RWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule encl. EIRB/0407, D. O. Division of Licensing 8/10/81/19 7pp
- 0004040217 Forwards NPS-1001, "Revised Design Methodology," Revision 3, replacing original entirely Includes details of unreviewed fuel cycle clarification of certain areas & topographical error correction RPS method intended for use by Reg 3981 PARKER, W. D. Duke Power Co. 8/10/81/20 3p
- 0004040221 "Revised Design Methodology," Revision 3
+ Duke Power Co. NPS-1001 8/10/81/21 35pp
- 0004100222 Request submittal of amendment to license updating requirements of Reg 3981 10-Revision 4 Response required within 60 days of receipt of 1st REID, N. W. Operating Reactors Branch 4 8/10/81/29 3pp
- 0004030574 "Extensive Instrumentation & Control Aspects of Low Temp Superpressure Refrigeration," Internal rep. WREDS, D. A. OHS, Inc. T-1M-A-PSO 0004030574 8/10/81/31 12pp
- 0004040334 Request add'l info to respond to NRC 800507 1tr re TIS-2 Lessons Learned requirement info needed includes areas re shift meeting, safety & relief valves & outage of ECCS Response should be submitted by 8/10/81 PARKER, W. D. Duke Power Co. 8/10/81/02 2pp
- 0004030134 Advices that 800320 request for Tech Spec change will be included in overall review of Reg 3 subcritical storage of 800593 ETR represents NRC review Radiological ETR should be resubmitted based on markings within 90 days REID, N. W. Operating Reactors Branch 4 8/10/81/02 2pp
- 0004101044 Forwards "Generic Startup Physics Test Program, May 1980," delineating tests to be included during startup following failure refueling operations PARKER, W. D. Duke Power Co. 8/10/81/04 1p
- 0004101058 "Generic Startup Physics Test Program, May 1980" Modification Unit 2 Specific Impl. decreasing acceptance criteria for rod drop measurements substitution of NRC criteria for location of highest peak requirement in power distribution setting + Duke Power Co. 8/10/81/04 1pp
- 0004100351 Forwards summary of events involving partial or total loss of offsite power to facilities & responses to NRC questions. per NRC 800502 1tr PARKER, W. D. Duke Power Co. 8/10/81/04 3pp
- 0004100322 Forwards results of analysis required by Items 6 & 9 of NRC 790300 1tr on degraded grid voltage Under-voltage trip setpoint will be changed for startup transformers & administrative controls will be established as 800520 PARKER, W. D. Duke Power Co. 8/10/81/04 1pp
- 0004060149 Response to NRC 800400 1tr requesting guidance re TIS-2 related requirements Automatic trip schedule of reactor coolant pumps during LOCA should be revised REID, N. W. Operating Reactors Branch 4 8/10/81/10 3pp
- 0004100429 Forwards corrected version of "McGuire Nuclear Station Generic Startup Physics Test Program" PARKER, W. D. Duke Power Co. 8/10/81/11 3p
- 0004100324 Corrected version of "McGuire Nuclear Station Generic Startup Physics Test Program"
+ Duke Power Co. 8/10/81/11 14pp
- 0004100482 Advices that responses are being prepared re low pressure turbines per 800512 request Work will be completed by 8/10/81 PARKER, W. D. Duke Power Co. 8/10/81/11 3p
- 0004030221 Forwards draft NRC licensing position, "Safety Considerations for Temporary Onsite Storage," used in evaluating low level onsite storage criteria Requests revision for onsite storage additions in monthly operating reports REID, N. W. Operating Reactors Branch 4 8/10/81/12, 13pp
- 0004100478 Forwards response to NRC 800507 1tr re add'l requirements for TIS Action Plan Response contains implementation schedule & summary stating unit commitments re requirements PARKER, W. D. Duke Power Co. 8/10/81/13 3pp
- 0004040445 Response to NRC 300512 request for info concerning problem of low pressure turbine disc cracking Forwards detailed responses to five specific questions PARKER, W. D. Duke Power Co. 8/10/81/16 8pp
- 0004040525 Requests that NRC complete review & approval of Category B Items 2 & 3, 20.1.1.7a & 2.1.8a Review needed to facilitate installation of Category B work prior to 8/10/81 PARKER, W. D. Duke Power Co. 8/10/81/20 3p
- 0004030242 Forwards proposed Tech Spec revision in response to NRC 800410 1tr discussing term "operable" as applied to Tech Spec requirements No license fees provided since proposal submitted in response to NRC request PARKER, W. D. Duke Power Co. 8/10/81/26 2pp
- 0004030334 Proposed Tech Spec interpreting term "operable" as applied to various Tech Spec definitions
+ Duke Power Co. 8/10/81/26 1p

DOCKETED ITEMS

3 Inspection reports, IE Bulletins & correspondence

0304040144 Forwarded IE Insp Repts 30-249/80-15, 30-270/80-08 & 30-287/80-09 on 800503-25 re noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 03/04/82 2pp

8005040152 IE Insp Repts 30-249/80-15, 30-270/80-08 & 30-287/80-09, on 800503-25 re noncompliance noted Major areas inspected plant operations, outage activities, failures on previous insp findings & review of LERs
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 03/04/82 1, 2, 3, 4, 5, 6, 7 Region 2, Atlanta, Office of the Director 03/04/82 2pp

8004060305 Forwarded IE Bulletin 80-11, "Reactor Hall Design." Requires action & written response IE Info Bulletin 79-28.
"Overloading of Structural Elements Due to Pipe Support Loads" w/c
D'NEELY, J F Region 2, Atlanta, Office of the Director 05/05/80 2pp

8004030295 Forwarded IE Bulletin 80-12, "Decay Heat Removal Eya Operability." Requires action & response within 30 days
IE Info Bulletin 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 3 While in Refueling Mode" w/c
D'NEELY, J F Region 2, Atlanta, Office of the Director 05/05/80 2pp

8004170045 Forwarded IE Info Bulletin 79-27 updates about Requests add info re turbine direct Recommendations that should be developed re perform full ultrasonic test of at least one low pressure turbine before next major outage
REID, R W Operating Reactors Branch 4 03/05/82 3pp

8004080110 Forwarded IE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures." No written response required
D'NEELY, J F Region 2, Atlanta, Office of the Director 03/05/82 2pp

8004080214 Act receipt of IE Insp Repts 30-249/80-15, 30-270/80-08 & 30-287/80-09 re noncompliance noted
PARKER, W O Duke Power Co 02/03/82 1p

8004040107 Act receipt of 800502 supplemental responses, informing NRC of reevaluation of noncompliance & deviation noted in IE Insp Repts 30-249/79-37, 30-270/79-34 & 30-287/79-37. Stated position stands due to negative nature of incidents
D'NEELY, J F Region 2, Atlanta, Office of the Director 03/05/82 1p

8004040117 Supplements response to NRC 000407 1p re noncompliance & deviation noted in IE Insp Repts 30-249/79-37, 30-270/79-34 & 30-287/79-37. Disagrees w/ violation because event was not controllable by normal operating procedures
PARKER, W O Duke Power Co 03/05/82 2pp

8004040148 Forwarded response to IE Bulletin 80-12 re decay heat removal w/c reliability. Control room has indication of each pump discharge pressure & each drain flow monitors are installed on low flow on either drain or if pump is on
PARKER, W O Duke Power Co 03/05/82 2pp

8005080190 Act receipt of IE Insp Repts 30-249/80-15, 30-270/80-11 & 30-287/80-09 on 800403-25 re noncompliance noted
PARKER, W O Duke Power Co 03/05/82 1p

8005020099 Forwarded IE Insp Repts 30-249/80-15, 30-270/80-11 & 30-287/80-09 on 800403-25 re noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 03/05/82 3pp

8005030020 IE Insp Repts 30-249/80-15, 30-270/80-11 & 30-287/80-09 on 800403-25 re noncompliance noted Major areas inspected containment integrated leakage rate testing
MARTIN, R D Region 2, Atlanta, Office of the Director 03/05/82 1, 2, 3, 4, 5, 6, 7 Region 2, Atlanta, Office of the Director 03/05/82 2pp

8004030023 advises that response to IE Bulletin 80-04 will be provided by 03/07/82 due to need for detailed review of engineered safeguards correspondence
PARKER, W O Duke Power Co 03/05/82 1p

3 Reportable occurrences, LERs & related correspondence

8005020041 Forwarded LER 30-037/02L-0
PARKER, W O Duke Power Co 03/05/82 1p

8005020043 LER 30-037/02L-0 on 800403-vent gas particulate & iodine monitors suspended inoperable due to failure to perform periodic surveillance on schedule. Caused by personnel error. Status Board for periodic surveillance items will be kept
LEWIS, R C Duke Power Co 03/05/82 2pp

8004110091 Forwarded LER 03-008/02L-0
PARKER, W O Duke Power Co 03/05/82 2pp

8004110094 LER 30-008/02L-0 on 03/05/82, shutdown was initiated when reactor protection was tripped. Due to failure to perform failure caused by blown fuses. Power to ac vital instrumentation restored manually & fuses replaced
LEWIS, R C Duke Power Co 03/05/82 1p

8004250295 RO on 800414, once through steam generator tube leak indicated by increased count rate on RIA-5D & grab samples. Caused by leak in steam generator. A Secondary gas contamination procedure initiated
MARTIN, R D Duke Power Co 03/05/82 1p

8004250149 RO 287/00-0 addl info has been reviewed which clarifies occurrence. Channel D was not inoperable as indicated, while unit was still capable of performing function & requirements of Tech Spec loss of power was met RO
PARKER, W O Duke Power Co 03/05/82 2pp

DOCKET 30-209 THREE ISLANDS NUCLEAR REACTOR

3 Security, medical, emergency & fire protection plans

8004020214 Forwarded draft security plan. Plan withheld (ref 105787 7701)
CHURCH, L D Reed College 03/04/82 1p

3 Operating license stage documents & correspondence

8004020076 Tech Spec change request to License 8-112 to change wording of Paragraph 5-2 to "at least monthly" instead of "at least weekly when reactor is operational" re sampling of pool water for conductivity
CHURCH, L D Reed College 03/05/82 2pp

DOCKET 30-209 THREE ISLAND NUCLEAR STATION UNIT 1

3 Security, medical, emergency & fire protection plans

8004030224 Discusses Emergency Preparedness Task Force review of proposed emergency plan. Emergency plan should be reviewed against NUREG-0496 evaluation criteria. Plan should be provided by 800502
REID, R W Operating Reactors Branch 4 03/04/82 2pp

8004170044 Requests that response to NRC 701129 request for info re evaluation time estimates be based on NRC guidance w/c addl
REID, R W Operating Reactors Branch 4 03/05/82 1p

8004120528 Requests that FEMA review of state & local emergency plan be provided consistently w/c schedule to avoid potential delays in licensing decisions
MARTIN, R D Commission 03/05/82 2pp

8004080106 Requests that badges assigned by Unit 1 & 2 security be returned immediately to unit security unit. In the Middlebrook. Please to employment termination
MARTIN, R D Metropolitan Edison Co 03/05/82 1p

8005050467 Forwarded proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 10-418 & App B to 10CFR50 & is expected to be published in FR by end of May
GREGORY, D O Division of Licensing 03/05/82 4pp

8004120463 Forwarded revised Pages 1-14 & new Page 14a per proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Transmitted by NRC 03/05/82 1p Page 14a not sent
GREGORY, D O Division of Licensing 03/05/82 7pp

8004250293 Forwarded addl info re Award as to License 80R-80, re response to NRC 800415 request. Position w/c remains open 30 days. Amend 44 addl addl will be completed prior to 03/01/82. Alternate shutdown capability will be completed by 03/03/82
MARTIN, R D Metropolitan Edison Co 03/05/82 3pp

- 000410070 Forwarded until 000527 1st to PA Dept of Environ Resources re request for open hearing permit in order to conduct training for TH First brigade personnel due to small amount of fuel involved, emergency impact will be minimal
HERBERT J. D. Metropolitan Edison Co 00/05/04 3pp
- 000410182 Forwarded until 000527 1st sent to PA Dept of Environ Resources requesting permit to conduct fire fighting brigade training (excludes minimal) environ impact due to small amount of fuel, gasoline & lumber used
HERBERT J. D. Metropolitan Edison Co 00/05/04 4pp
- 000410217 Forwarded approved emergency plans in accordance w/guidance set forth in "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants." NUREG-0486
HERBERT J. D. Metropolitan Edison Co 00/05/10 12pp
- 0004103010 CPU Nuclear Deep emergency plan for TH nuclear station Unit 1, Revision 2
Metropolitan Edison Co 00/06/03 30pp
- 000410320 Commonwealth of PA disaster operations plan Annex E, fixed nuclear facility incidents
Pennsylvania, State of 00/06/03 20pp
- 000410321 Commonwealth of PA Dept of Health radiation emergency plan
Pennsylvania, State of 00/06/03 17pp
- 000410323 Draft York County protective action plan for TH nuclear plant
York, PA 00/06/04 16pp
- 000410324 Cumberland County TH emergency response plan
Cumberland County, PA 00/06/03 23pp
- 000410326 Draft Lancaster County emergency evacuation plan for TH
Lancaster County, PA 00/06/03 17pp
- 000410327 Lebanon County Emergency Mgt Agency emergency operations plan, "Radiation Incident - TH"
Pennsylvania, State of 00/06/03 100pp
- 000410329 Dauphin County fixed nuclear facility incident response plan
Dauphin County, PA 00/06/03 180pp
- 0 Adjudication correspondence
- 000410420 Response to People Against Nuclear Energy 000321 Interrogatories for which extension until 000509 had been agreed upon includes info re psychological distress issue w/merit qualifications, Certificate of Rev & Forwarding to ZAHLEB, R. E. Metropolitan Edison Co ZAHLEB, R. E. Shaw, Pittman, Potts & Troubridge 00/06/03 3pp
- 000410504 Response in opposition to Amended 000426 motion for reconsideration of ASLE 000409 order re interrogatory motion to compel licensee answers to interrogatories Proposed procedure does not promote disclosure w/Certificate of Rev
BLANE, E. L. Metropolitan Edison Co BLANE, E. L. Shaw, Pittman, Potts & Troubridge 00/05/03 4pp
- 000410515 Supplemental response to PA Public Util Commission Interrogatory 8 of first set of interrogatories identifies ASLE cash flow forecasts placed in licensee discovery
ZAHLEB, R. E. Metropolitan Edison Co ZAHLEB, R. E. Shaw, Pittman, Potts & Troubridge 00/05/03 3pp
- 000410623 Status report in response to ASLE 000421 memorandum & order on Shell motion to compel licensee answers to Contention 1 re interrogatories Details areas of agreement between licensee & Shell w/Certificate of Rev & cover 1st encl
BLANE, E. L. Metropolitan Edison Co BLANE, E. L. Shaw, Pittman, Potts & Troubridge 00/05/07 7pp
- 000410190 Forwarded box containing documents in response to 000324 requests 1 st responses w/affidavit in answer to Anti-Nuclear Group representing York Interrogatories Related correspondence
GERTON, K. M. Pennsylvania, State of 00/05/07 3pp
- 000410314 Followup to responses to Anti-Nuclear Group representing York Interrogatories includes info re PERM report on mass core capacity Affidavit & Certificate of Rev encl Related correspondence
DOUGHERTY, J. L. Pennsylvania, State of 00/05/07 3pp
- 000406283 Addl response to SC Shellly fourth set of Interrogatories re Contention 15 includes info re plant operators' roles as part of operating procedures & design of control room
Certificate of Rev & cover 1st encl Related correspondence
ZAHLEB, R. E. Metropolitan Edison Co ZAHLEB, R. E. Shaw, Pittman, Potts & Troubridge 00/05/09 12pp
- 000406475 Motion for sanctions against Environ Coalition on Nuclear Power Union dismissal of intervenor as party in proceeding for failure to comply w/ASLE 000411 memorandum & order re Licensee 000310 Interrogatories Certificate of Rev encl
TROBRIDGE, D. F. ZAHLEB, R. E. Metropolitan Edison Co TROBRIDGE, D. F. Shaw, Pittman, Potts & Troubridge 00/05/09 11pp
- 000410004 Second motion to compel intervenor Chesapeake Energy Alliance response to 000310 Interrogatories Intervenor 000426 response in compliance w/ASLE 000416 order failed to supply requested info Certificate of Rev encl
TROBRIDGE, D. F. Metropolitan Edison Co TROBRIDGE, D. F. Shaw, Pittman, Potts & Troubridge 00/05/12 7pp
- 000410049 Addl response to intervenor SC Shellly 000295 fourth set of interrogatories re Contention 15 Includes info re security staffing, security audits & acts of sabotage Certificate of Rev & Affidavit encl
BLANE, E. L. Metropolitan Edison Co BLANE, E. L. Shaw, Pittman, Potts & Troubridge 00/05/12 10pp
- 000410410 Followup Interrogatories directed to licensee Requests documentation & covers pipe cracking in buried under mgs Certificate of Rev encl Related correspondence
ASLEB, A. Three Mile Island Alert ASLEB, A. Midoff, Reagan, Gelkovich & Adler 00/05/12 3pp
- 000410527 Notice of appearance in proceeding Certificate of Rev encl
BERNHEIM, D. L. Metropolitan Edison Co BERNHEIM, D. L. Shaw, Pittman, Potts & Troubridge 00/05/14 4pp
- 000410520 Forwarded JS Thorge 000999 affidavit in support 000509 licensee response to People Against Nuclear Energy Interrogatories Rev list encl Related correspondence
BERNHEIM, D. L. Shaw, Pittman, Potts & Troubridge 00/05/14 4pp
- 000410529 Advises that licensee assets used in operation accelerated retraining program have been placed in licensee discovery reading room in response to Interrogatory 4 re Amended fourth set of Interrogatories Related correspondence
BLANE, E. L. Shaw, Pittman, Potts & Troubridge 00/05/14 3pp
- 000410611 Confirms 000313 belcom All documents re Contention 2, 16 & 17 will be made available for ins & copying re 000527
Coalition Against Nuclear Outage Related correspondence
BRAPP, B. A. Pennsylvania Power & Light Co 00/05/14 3p
- 000410614 Response in opposition to TH Alert 000512 followup Interrogatories Intervenor did not comply w/discovery schedule & questions do not relate to Contention 9 re status w/Certificate of Rev Related correspondence
BLANE, E. L. Metropolitan Edison Co BLANE, E. L. Shaw, Pittman, Potts & Troubridge 00/05/15 3pp
- 000410017 Response to Chesapeake Energy Alliance 000426 supplemental interrogatories includes info re EPIC008 info re outage & other functional matters Certificate of Rev encl Related correspondence
ZAHLEB, R. E. Metropolitan Edison Co ZAHLEB, R. E. Shaw, Pittman, Potts & Troubridge 00/05/15 3pp
- 000410105 Affidavit in support of Licensee 000509 addl response to SC Shellly fourth set of interrogatories re Interrogatories 19-20B, 19-21D, 19-22A, 19-22B, 19-23A, 19-24A, 19-24B, 19-24C, 19-24D, 19-24E, 19-24F, 19-24G, 19-24H, 19-24I, 19-24J, 19-24K, 19-24L, 19-24M, 19-24N, 19-24O, 19-24P, 19-24Q, 19-24R, 19-24S, 19-24T, 19-24U, 19-24V, 19-24W, 19-24X, 19-24Y, 19-24Z, 19-24AA, 19-24AB, 19-24AC, 19-24AD, 19-24AE, 19-24AF, 19-24AG, 19-24AH, 19-24AI, 19-24AJ, 19-24AK, 19-24AL, 19-24AM, 19-24AN, 19-24AO, 19-24AP, 19-24AQ, 19-24AR, 19-24AS, 19-24AT, 19-24AU, 19-24AV, 19-24AW, 19-24AX, 19-24AY, 19-24AZ, 19-24BA, 19-24BB, 19-24BC, 19-24BD, 19-24BE, 19-24BF, 19-24BG, 19-24BH, 19-24BI, 19-24BJ, 19-24BK, 19-24BL, 19-24BM, 19-24BN, 19-24BO, 19-24BP, 19-24BQ, 19-24BR, 19-24BS, 19-24BT, 19-24BU, 19-24BV, 19-24BW, 19-24BX, 19-24BY, 19-24BZ, 19-24CA, 19-24CB, 19-24CC, 19-24CD, 19-24CE, 19-24CF, 19-24CG, 19-24CH, 19-24CI, 19-24CJ, 19-24CK, 19-24CL, 19-24CM, 19-24CN, 19-24CO, 19-24CP, 19-24CQ, 19-24CR, 19-24CS, 19-24CT, 19-24CU, 19-24CV, 19-24CW, 19-24CX, 19-24CY, 19-24CZ, 19-24DA, 19-24DB, 19-24DC, 19-24DD, 19-24DE, 19-24DF, 19-24DG, 19-24DH, 19-24DI, 19-24DJ, 19-24DK, 19-24DL, 19-24DM, 19-24DN, 19-24DO, 19-24DP, 19-24DQ, 19-24DR, 19-24DS, 19-24DT, 19-24DU, 19-24DV, 19-24DW, 19-24DX, 19-24DY, 19-24DZ, 19-24EA, 19-24EB, 19-24EC, 19-24ED, 19-24EE, 19-24EF, 19-24EG, 19-24EH, 19-24EI, 19-24EJ, 19-24EK, 19-24EL, 19-24EM, 19-24EN, 19-24EO, 19-24EP, 19-24EQ, 19-24ER, 19-24ES, 19-24ET, 19-24EU, 19-24EV, 19-24EW, 19-24EX, 19-24EY, 19-24EZ, 19-24FA, 19-24FB, 19-24FC, 19-24FD, 19-24FE, 19-24FF, 19-24FG, 19-24FH, 19-24FI, 19-24FJ, 19-24FK, 19-24FL, 19-24FM, 19-24FN, 19-24FO, 19-24FP, 19-24FQ, 19-24FR, 19-24FS, 19-24FT, 19-24FU, 19-24FV, 19-24FW, 19-24FX, 19-24FY, 19-24FZ, 19-24GA, 19-24GB, 19-24GC, 19-24GD, 19-24GE, 19-24GF, 19-24GG, 19-24GH, 19-24GI, 19-24GJ, 19-24GK, 19-24GL, 19-24GM, 19-24GN, 19-24GO, 19-24GP, 19-24GQ, 19-24GR, 19-24GS, 19-24GT, 19-24GU, 19-24GV, 19-24GW, 19-24GX, 19-24GY, 19-24GZ, 19-24HA, 19-24HB, 19-24HC, 19-24HD, 19-24HE, 19-24HF, 19-24HG, 19-24HH, 19-24HI, 19-24HJ, 19-24HK, 19-24HL, 19-24HM, 19-24HN, 19-24HO, 19-24HP, 19-24HQ, 19-24HR, 19-24HS, 19-24HT, 19-24HU, 19-24HV, 19-24HW, 19-24HX, 19-24HY, 19-24HZ, 19-24IA, 19-24IB, 19-24IC, 19-24ID, 19-24IE, 19-24IF, 19-24IG, 19-24IH, 19-24II, 19-24IJ, 19-24IK, 19-24IL, 19-24IM, 19-24IN, 19-24IO, 19-24IP, 19-24IQ, 19-24IR, 19-24IS, 19-24IT, 19-24IU, 19-24IV, 19-24IW, 19-24IX, 19-24IY, 19-24IZ, 19-24JA, 19-24JB, 19-24JC, 19-24JD, 19-24JE, 19-24JF, 19-24JG, 19-24JH, 19-24JI, 19-24JJ, 19-24JK, 19-24JL, 19-24JM, 19-24JN, 19-24JO, 19-24JP, 19-24JQ, 19-24JR, 19-24JS, 19-24JT, 19-24JU, 19-24JV, 19-24JW, 19-24JX, 19-24JY, 19-24JZ, 19-24KA, 19-24KB, 19-24KC, 19-24KD, 19-24KE, 19-24KF, 19-24KG, 19-24KH, 19-24KI, 19-24KJ, 19-24KL, 19-24KM, 19-24KN, 19-24KO, 19-24KP, 19-24KQ, 19-24KR, 19-24KS, 19-24KT, 19-24KU, 19-24KV, 19-24KW, 19-24KX, 19-24KY, 19-24KZ, 19-24LA, 19-24LB, 19-24LC, 19-24LD, 19-24LE, 19-24LF, 19-24LG, 19-24LH, 19-24LI, 19-24LJ, 19-24LK, 19-24LL, 19-24LM, 19-24LN, 19-24LO, 19-24LP, 19-24LQ, 19-24LR, 19-24LS, 19-24LT, 19-24LU, 19-24LV, 19-24LW, 19-24LX, 19-24LY, 19-24LZ, 19-24MA, 19-24MB, 19-24MC, 19-24MD, 19-24ME, 19-24MF, 19-24MG, 19-24MH, 19-24MI, 19-24MJ, 19-24MK, 19-24ML, 19-24MM, 19-24MN, 19-24MO, 19-24MP, 19-24MQ, 19-24MR, 19-24MS, 19-24MT, 19-24MU, 19-24MV, 19-24MW, 19-24MX, 19-24MY, 19-24MZ, 19-24NA, 19-24NB, 19-24NC, 19-24ND, 19-24NE, 19-24NF, 19-24NG, 19-24NH, 19-24NI, 19-24NJ, 19-24NK, 19-24NL, 19-24NM, 19-24NN, 19-24NO, 19-24NP, 19-24NQ, 19-24NR, 19-24NS, 19-24NT, 19-24NU, 19-24NV, 19-24NW, 19-24NX, 19-24NY, 19-24NZ, 19-24OA, 19-24OB, 19-24OC, 19-24OD, 19-24OE, 19-24OF, 19-24OG, 19-24OH, 19-24OI, 19-24OJ, 19-24OK, 19-24OL, 19-24OM, 19-24ON, 19-24OO, 19-24OP, 19-24OQ, 19-24OR, 19-24OS, 19-24OT, 19-24OU, 19-24OV, 19-24OW, 19-24OX, 19-24OY, 19-24OZ, 19-24PA, 19-24PB, 19-24PC, 19-24PD, 19-24PE, 19-24PF, 19-24PG, 19-24PH, 19-24PI, 19-24PJ, 19-24PK, 19-24PL, 19-24PM, 19-24PN, 19-24PO, 19-24PP, 19-24PQ, 19-24PR, 19-24PS, 19-24PT, 19-24PU, 19-24PV, 19-24PW, 19-24PX, 19-24PY, 19-24PZ, 19-24QA, 19-24QB, 19-24QC, 19-24QD, 19-24QE, 19-24QF, 19-24QG, 19-24QH, 19-24QI, 19-24QJ, 19-24QK, 19-24QL, 19-24QM, 19-24QN, 19-24QO, 19-24QP, 19-24QQ, 19-24QR, 19-24QS, 19-24QT, 19-24QU, 19-24QV, 19-24QW, 19-24QX, 19-24QY, 19-24QZ, 19-24RA, 19-24RB, 19-24RC, 19-24RD, 19-24RE, 19-24RF, 19-24RG, 19-24RH, 19-24RI, 19-24RJ, 19-24RK, 19-24RL, 19-24RM, 19-24RN, 19-24RO, 19-24RP, 19-24RQ, 19-24RR, 19-24RS, 19-24RT, 19-24RU, 19-24RV, 19-24RW, 19-24RX, 19-24RY, 19-24RZ, 19-24SA, 19-24SB, 19-24SC, 19-24SD, 19-24SE, 19-24SF, 19-24SG, 19-24SH, 19-24SI, 19-24SJ, 19-24SK, 19-24SL, 19-24SM, 19-24SN, 19-24SO, 19-24SP, 19-24SQ, 19-24SR, 19-24SS, 19-24ST, 19-24SU, 19-24SV, 19-24SW, 19-24SX, 19-24SY, 19-24SZ, 19-24TA, 19-24TB, 19-24TC, 19-24TD, 19-24TE, 19-24TF, 19-24TG, 19-24TH, 19-24TI, 19-24TJ, 19-24TK, 19-24TL, 19-24TM, 19-24TN, 19-24TO, 19-24TP, 19-24TQ, 19-24TR, 19-24TS, 19-24TT, 19-24TU, 19-24TV, 19-24TW, 19-24TX, 19-24TY, 19-24TZ, 19-24UA, 19-24UB, 19-24UC, 19-24UD, 19-24UE, 19-24UF, 19-24UG, 19-24UH, 19-24UI, 19-24UJ, 19-24UK, 19-24UL, 19-24UM, 19-24UN, 19-24UO, 19-24UP, 19-24UQ, 19-24UR, 19-24US, 19-24UT, 19-24UU, 19-24UV, 19-24UW, 19-24UX, 19-24UY, 19-24UZ, 19-24VA, 19-24VB, 19-24VC, 19-24VD, 19-24VE, 19-24VF, 19-24VG, 19-24VH, 19-24VI, 19-24VJ, 19-24VK, 19-24VL, 19-24VM, 19-24VN, 19-24VO, 19-24VP, 19-24VQ, 19-24VR, 19-24VS, 19-24VT, 19-24VU, 19-24VV, 19-24VW, 19-24VX, 19-24VY, 19-24VZ, 19-24WA, 19-24WB, 19-24WC, 19-24WD, 19-24WE, 19-24WF, 19-24WG, 19-24WH, 19-24WI, 19-24WJ, 19-24WK, 19-24WL, 19-24WM, 19-24WN, 19-24WO, 19-24WP, 19-24WQ, 19-24WR, 19-24WS, 19-24WT, 19-24WU, 19-24WV, 19-24WW, 19-24WX, 19-24WY, 19-24WZ, 19-24XA, 19-24XB, 19-24XC, 19-24XD, 19-24XE, 19-24XF, 19-24XG, 19-24XH, 19-24XI, 19-24XJ, 19-24XK, 19-24XL, 19-24XM, 19-24XN, 19-24XO, 19-24XP, 19-24XQ, 19-24XR, 19-24XS, 19-24XT, 19-24XU, 19-24XV, 19-24XW, 19-24XX, 19-24XY, 19-24XZ, 19-24YA, 19-24YB, 19-24YC, 19-24YD, 19-24YE, 19-24YF, 19-24YG, 19-24YH, 19-24YI, 19-24YJ, 19-24YK, 19-24YL, 19-24YM, 19-24YN, 19-24YO, 19-24YP, 19-24YQ, 19-24YR, 19-24YS, 19-24YT, 19-24YU, 19-24YV, 19-24YW, 19-24YX, 19-24YY, 19-24YZ, 19-24ZA, 19-24ZB, 19-24ZC, 19-24ZD, 19-24ZE, 19-24ZF, 19-24ZG, 19-24ZH, 19-24ZI, 19-24ZJ, 19-24ZK, 19-24ZL, 19-24ZM, 19-24ZN, 19-24ZO, 19-24ZP, 19-24ZQ, 19-24ZR, 19-24ZS, 19-24ZT, 19-24ZU, 19-24ZV, 19-24ZW, 19-24ZX, 19-24ZY, 19-24ZZ

DOCKETED ITEMS

- 8005040203 Memorandum in support of TH1 Alert responses to licensee interrogatories re Contention 3 Explain intervenor efforts in providing info on systematic fashion despite delay in obtaining SDI Certificate of Rev and
HIDOFF, R. P. Three Mile Island Alert HIDOFF, R. P. Hidoff, Reager, Belkowitz & Adler 8/10/83 2p
- 8005040403 Followup responses to State of PA second set of interrogatories includes info re name of base where cases of hypothyroidism were reported related correspondence AMSDOT Affiliation Unknown 8/10/83 12p
- 8005040405 Response to demand second set of interrogatories includes info as state 1978 comprehensive hypothyroid screening program and other related issues related correspondence TROMBETTA, D. R. Pennsylvania, State of. 8/10/83 2p
- 8005040603 Response to demand followup second set of interrogatories includes info re thyroid relation w/background radiation Affidavit & Certificate of Rev and
CANTRELL, K. W. Pennsylvania, State of. 8/10/83 2p
- 8005100805 Supplemental response to licensee interrogatories re Contention 3 States criteria used to identify work orders included in Attachment A of TH1 Alert 800506 response Certificate of Rev and
HIDOFF, R. P. Three Mile Island Alert HIDOFF, R. P. Hidoff, Reager, Belkowitz & Adler 8/10/83 2p
- 8005040501 Memorandum & order substantiating 800513 prehearing conference rulings & agreements Addresses schedule for prehearing events following safety evaluation, pleadings & discovery matters & award of intervenors' costs/fees
BRIGHT, T. H. Atomic Safety and Licensing Board Panel 8/10/83 2p
- 8005100909 Motion for further spec of excursions due to thermal std applied by AGLB when ruling on admissibility Upon issuance of order requiring spec by 800509 from all intervenors
TROMBETTA, D. R. Metropolitan Edison Co TROMBETTA, D. R. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005040913 Forward PA Public Util Commission final order in consolidated TH1 SDPA, Electric Co proceedings Also forwards decision opinion by Chairman Shuman
SHUMAN, L. P. General Public Utilities - CPU Service Corp 8/10/83 2p
- 8005040303 Motion for order to compel licensee substantive responses to intervenor TH1 Alert 800513 followup interrogatories Licensee raised no objection to initial questions when proposed Certificate of Rev and
ADLER, T. A. Three Mile Island Alert ADLER, T. A. Hidoff, Reager, Belkowitz & Adler 8/10/83 2p
- 8005040506 Memorandum & order on hydrogen control system/revise Commission 800514 memorandum & order, CLT-80-16, deciding not to activate issue from TH0059 notice & order for hearing Parties may submit comments & pleadings within 10 days
BRIGHT, T. H. Atomic Safety and Licensing Board Panel 8/10/83 2p
- 8005100900 Forward PA Consumer Advocate 800520 petition for reconsideration of Commission memorandum & order, CLT-80-19, which denied financial assistance to participating intervenors
BLANK, J. R. Pennsylvania, State of. 8/10/83 1p
- 8005100503 Petition by PA Consumer Advocate for reconsideration of Commission memorandum & order, CLT-80-19, which denied financial assistance to participating intervenors Petitioner is assisted by statute to define controversy Intervenor
BLANK, J. R. CONSUM, M. Pennsylvania, State of. 8/10/83 2p
- 8005040402 Further responses to AGLB 800501 memorandum & order re Class 3 & death DCL TH1-1 Potential Core Damage Accident Sequences & Preventive & Mitigative Measures, a complete answer issues & news to TH1-2 incident w/Certificates of Rev
CUTCHER, L. H. Hearing Branch 3 8/10/83 2p
- 8005101016 Expresses concern w/undue reliance of TH1 Alert legal response to licensee interrogatories & 800520 memo re TH1-1 matter Appropriate relief from AGLB, including possible move to judicial branch, is sought Certificate of Rev and
BLANK, J. R. Metropolitan Edison Co BLANK, J. R. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005100917 Opposes TH1 Alert 800529 motion to compel followup discovery of licensee on grounds of uselessness & irrelevancy of interrogatories Certificate of Rev and
BLANK, J. R. Metropolitan Edison Co BLANK, J. R. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005100930 Motion for reconsideration of Commission 800514 memorandum & order, CLT-80-16 Order resolved factual issues w/o benefit of record & was giving opportunity to parties to present cases
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Sheldon, Herman & Weiss 8/10/83 2p
- 8005100900 Request for late filing of USJ motion for reconsideration of Commission 800514 memorandum & order, CLT-80-16 Intervenor was involved in other proceedings Certificate of Rev and
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Sheldon, Herman & Weiss 8/10/83 2p
- 8005101014 Forwards affidavit supporting licensee supplemental response to interrogatories on Contention 3 served on 800519 Certificate of Rev and
BERNARDINI, D. L. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005100371 Opposition to licensee motion to require further specificity of contentions Licensee seeks to extend discovery w/o affording respondent opportunity to in compel testimony
BRIGHT, T. H. Atomic Safety and Licensing Board Panel 8/10/83 2p
- 8005100506 Forwards CPU 800514 cost & earnings forecast reflecting recent NJ & PA rate order impact on revenues to Intervenor & of PA Public Util Commission
HORNSTEIN, J. G. Metropolitan Edison Co 8/10/83 2p
- 8005100909 Memorandum & order permitting TH1 Alert to reply to licensee 800514 response raising issues re intervenor 800529 motion to compel discovery Response should address intervenor's questions to be filed within 10 days
BRIGHT, T. H. Atomic Safety and Licensing Board Panel 8/10/83 1p
- 8005100330 Request denial of licensee motion for further specificity of intervenor TH1 Alert contentions & reaffirmation of AGLB 800525 order SDI will contain info essential to development of contentions Certificate of Rev and
ADLER, T. A. Three Mile Island Alert ADLER, T. A. Hidoff, Reager, Belkowitz & Adler 8/10/83 2p
- 8005100301 Motion to defer ruling on hydrogen control contentions by suspending effectiveness of AGLB 800520 memorandum & order pending NRC review of USJ motion for reconsideration of CLT-80-16 Certificate of Rev and
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Sheldon, Herman & Weiss 8/10/83 2p
- 8005100920 Forward PA Public Util Commission 800520 order re issue of financial competence
BRIGHT, T. H. Atomic Safety and Licensing Board Panel 8/10/83 2p
- 8005100504 Forwards under separate cover Revision 2 to licensee emergency plan, including current emergency plan of State of TH1 & Death/Injury/Loss/Life/Losses & Commercial entities re nuclear hearing Certificate of Rev and
ZAPHER, R. E. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005100509 Supplemental responses to interrogatories includes info re schematic diagram depicting TH1-2 vent header or gasflow radiance disposal app RM Kaizer Affidavit & Certificate of Rev and
TROMBETTA, D. R. Metropolitan Edison Co TROMBETTA, D. R. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p
- 8005100943 Memorandum by svc list notifies that licensee unable to perfect spec described in 800509 memorandum Amended Certificate of Rev and
ZAPHER, R. E. Shaw, Pittman, Potts & Trowbridge NRC 8/10/83 1p
- 8005100504 Amended Certificate of Rev Doc described in Certificate of Rev attached to licensee 800509 memorandum not executed due to unforeseen difficulties in production of emergency plans
ZAPHER, R. E. Metropolitan Edison Co ZAPHER, R. E. Shaw, Pittman, Potts & Trowbridge 8/10/83 2p

- 0006100902 Response stating no objection to UCB 000606 motion to defer ruling on hydrogens control contentions & suspend AGLB 000622 under Contention position on granting 15 additional days for parties to comment on order w/ Certificate of Rev and 17048R1002, D.F. Metropolitan Edison Co. 17048R1002, D.F. Shaw, Pittman, Potts & Taubridge 00/06/12 App
- 0006100404 Response to license 000603 motion for further spec of contention 13 Urges denial of remaining requests Certificate of Rev and 17048R1002, D.F. Antitrust Division 00/06/12 App
- 0006100401 Memorandum & order declining to dismiss Environ Coalition on Nuclear Power as party in response to applicant 000609 motion dismiss majority of intervenor contentions for failure to comply w/ discovery requests JORDAN, L.W., LITTLE, L.W., SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/12 App
- 0006100507 Response to AGLB 000503 prehearing conference questions re intervenor ability to answer interrogatories Opposes NRC & license pattern of procedural harassment Certificate of Rev and 17048R1002, D.F. Environmental Coalition on Nuclear Power 00/06/03 App
- 0006200309 Notification of 000617 meeting w/Off of Executive Legal Director & Div of Licensing personnel in Bethesda, MD to discuss questions & answer format for restart testimony Appropriate relief requested & designated witnesses from MD should attend NRCWAT Assistant Director for Operating Reactors 00/06/12 App
- 0006100402 Order granting UCB 000404 motion for late filing of petition for reconsideration of Commission 000416 decision, CL-00-16 Motion are afforded until 000605 to respond to motion. Decision shall be stayed until further orders re restart CHILDS, J. Commission 00/06/12 App
- 0006100620 First answers to license interrogatories includes info re historical of corrective action problem Representing intervenor & Certificate of Rev and 17048R1002, D.F. AGLB, T.A. Three Mile Island Area AGLB, T.A. Hecoff, Reager, Bellows & Adler 00/06/10 App
- 0006100405 Preliminary response to 000610 000409 motion re AGLB 000603 under Requests 30-day extension to respond to substitution of Commission 13 Opposes extension of discovery on hydrogen control contentions Certificate of Rev and 17048R1002, D.F. Metropolitan Edison Co. 17048R1002, D.F. Shaw Pittman, Potts & Taubridge 00/06/10 App
- 0006100403 Response in opposition to Consumer Advocate of PA 000500 petition for reconsideration of Commission 000516 order denying financial witnesses Commission authority properly exercised per applicable policy Certificate of Rev and 17048R1002, D.F. Hearing Branch 1 00/06/10 App
- 0006200303 Certifies rev of 000616 TH-1 restart evaluation of license condition 10 & long-term risks of 700516 order on 000616 SHINJI, M. Antitrust Division 00/06/10 App
- 0006100303 Memorandum & order granting UCB 000304 motion seeking suspension of AGLB 000302 memorandum & order re hydrogens control contentions, pending ruling on UCB motion for reconsideration of CL-00-16 SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/17 App
- 0006000303 January 000616 "Further Commission Guidance for Power Reactor Status of Policy." & Commission 000409 statement of intervenor policy. Nuclear Power Plant Accident Compensation under NRC's of WAT SHINJI, M. Antitrust Division 00/06/17 App
- 0006200407 Order suspending requirement for taking any steps predicated upon issue of emergency planning Extension revision to emergency plan 000606 Class 9 sequence & 000616 NRC under 000302 schedule two hydrogens CHILDS, J. Atomic Safety and Licensing Board Panel 00/06/17 App
- 0006200517 Memorandum & order requiring further spec of Antinuclear Organ Representing York-Nebraska, 000617 UCB & TH-1 Alert contentions by 000701, following issuance of safety evaluation SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/23 App
- 0006200194 Memorandum on NRC reph: "TH-1 Potential Core Damage Accident Sequences & Preventive & Mitigative Measures" Accepts reph in lieu of response to AGLB 000201 order. Further safety concerns to be resolved by written testimony SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/23 App
- 0006200263 Memorandum & order setting schedule of events between 000616 safety evaluation & 000612 final prehearing conference re AGLB 000502 memorandum & order Motion for summary disposition may be filed by 000303 Certificate of Rev and 17048R1002, D.F. Atomic Safety and Licensing Board Panel 00/06/23 App
- 0006200307 Motion for further clarification of Environ Coalition on Nuclear Power Contentions 2-9 & 2-1 in manner consistent w/AGLB 000205 & 29 orders re emergency planning contentions in restart proceeding Certificate of Rev and 17048R1002, D.F. Metropolitan Edison Co. 17048R1002, D.F. Shaw, Pittman, Potts & Taubridge 00/06/23 App
- 0006200507 Response in support of UCB 000604 motion for reconsideration of Commission decision CL-00-16 re hydrogens control criteria Urges waiver of hydrogen design basis assumptions if Commission adheres to decision Certificate of Rev and 17048R1002, D.F. Metropolitan Edison Co. 17048R1002, D.F. Shaw, Pittman, Potts & Taubridge 00/06/24 App
- 0006200612 Response to intervenor H Lewis Interrogatories per NRC Commission's stated in NRC 000504 & 21 responses to H Lewis motions to compel discovery Includes corrected version of NRC previous Answer 20 w/affidavits & Certificate of Rev SHINJI, M. Antitrust Division 00/06/25 App
- 0006200304 Response in opposition to UCB 000604 motion for reconsideration of CL-00-16 Commission adequately & properly exercised authority re certified questions Waiver of regulation not warranted Certificate of Rev and 17048R1002, D.F. Hearing Branch 3 00/06/25 App
- 0006200408 Memorandum requesting license to notify AGLB & parties whether App A of civil June 1980 emergency plan re implementation will be submitted in restart proceeding SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/25 App
- 0006200407 Memorandum & order denying TH-1 Alert 000309 motion to compel license answers to follow emergency plan re hydrogen control contentions & irrelevancy re restart proceeding SHINJI, M. Atomic Safety and Licensing Board Panel 00/06/25 App
- H General correspondence
- 0006100500 Comments submitted on behalf of Polaris Corp re restart of facility Return to use will reduce cost of replacement power to utility customers POLARIS, J. Affiliation Unknown 00/06/20 App
- 0006100405 Urges licensing of nuclear power plants that meet new NRC rules GDFP/REN, H.C. Affiliation Unknown 00/06/20 App
- 0006100317 Comments on decreased income from investment in utility due to NRC attempt to protect ratepayers rather than ratepayers who live have been lost resulting from nuclear power plant failures CHILDS, J. Affiliation Unknown 00/06/27 App
- 0006100404 Requests hearings re restart of facility if expedited Order unreasonable & unfair to stockholders & users of utility electric SHINJI, M. Affiliation Unknown 00/06/24 App
- 0006100301 Urges NRC to return TH-1 to operation due to high energy costs & threat to industrial & commercial development AGLB/REN, H.C. Northampton County, Pa. 00/06/20 App
- 0006200188 Act receipt of 10 expressing concern about delay in TH-1 restart Commission ordered that TH-1 remain in cold shutdown condition until further order by NRC & stated that shutdown being held prior to restart of facility SHINJI, M. Office of Nuclear Reactor Regulation, Director 00/06/30 App
- 0006200302 Provides status & history of motions re facility restart in response to request for reply to H Order re Preparations for restart hearing required more than guidelines re Commission 700809 order hearing estimated to begin Oct 1980. CHILDS, J. Office of the Executive Director for Operations, 00/06/16 App
- 0006200106 Provides H Order 000303 10 re facility restart per response SHINJI, M. Senate 00/06/13 App

- 0004030300 Forwards NJ Utility Association resolution requesting that NRC expedite TH1-1 restart due to accident not provided by JPLM.
LAWRENCE, D. F. New Jersey Utilities Association 00/06/19 4pp
- I Financial Information
- 0004100300 Forwards GPU 000504 cash & earnings forecast reflecting recent NJ & PA rate order impact in response to
Interrogating of PA Public Util. Commission
HERSCHEIN, J. Metropolitan Edison Co 00/06/06 5pp
- 0004107011 Forwards 780927 operating agreement & 701020 Memorandum of Agreement re sharing of facility tank costs between
New Ed-JPL & Pennsic
OENITZ, E. L. General Public Utilities - GPU Service Corp 00/06/11 17pp
- 0004030301 Forwards "General Public Utilities - Cash & Earnings Forecast-June 1990-Dec 1991"
HERSCHEIN, J. Metropolitan Edison Co 00/06/16 15pp
- 0004030303 Forwards "General Public Utilities Cash & Earnings Forecast" for Jan 1990-Dec 1991 per letters between AIL & NRC
HERSCHEIN, J. Metropolitan Edison Co 00/06/16 1pp
- 0004240304 "General Public Utilities Cash & Earnings Forecast" for Jan 1990-Dec 1991
* Metropolitan Edison Co 00/06/16 10pp
- J. Insurance & Liability Information
- 0004100303 Grants extension until 000601 for compliance w/Price-Anderson Act financial protection requirements
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 00/04/08 1p
- 0004030300 Confirms that effective 7/06/01, supplemental limit of NRC Policy HP-200 was amended in accordance w/000329 ltr to Penn & Delaware Companies that effective 000601, liability limit will be restored ltr to March & Coleman and
QUANTROCCO, J. American Nuclear Insurers 00/05/29 3pp
- 0004030411 Forwards endorsement to NRCU Policy HP-73
GERTZ, H. E. General Public Utilities - GPU Service Corp 00/06/30 2pp
- 0004030416 Responds to NRC 000406 ltr re financial protection Nuclear liability insurance pools will provide twenty million dollars primary insurance for TH1-2 as well as reinsuring that amount expended for claims & expenses
HERSCHEIN, J. Metropolitan Edison Co 00/06/30 3pp
- 0004100400 Forwards 000610 ltr to NRC w/endorsements that pools propose to use similar to enhanced coverage contained in 000320 ltr to C. William Endorsements sent to NRC for consideration of financial endorsement at plant
QUANTROCCO, J. American Nuclear Insurers 00/06/10 5pp
- 0004030616 Responds to 000520 ltr re compliance w/financial protection requirements for Unit 2 since endorsement for add NRC million met restriction, unable to determine compliance info re alternatives to insurance requested
BOLT, D. H. J. Utility Finance Branch 00/06/13 2pp
- F Operating license stage documents & correspondence
- 0004030100 Responds to 000521 ltr re all possible financial failure financial failure provides grounds for license revocation. No contingency plans completed to cover possibility of financial failure
ARCAINE, J. P. Commission 00/06/07 2pp
- 0004030102 Inquires as to aftermath of unit financial failure.
BARNARD, S. R. Pennsylvania, State of 00/06/01 2pp
- 0004030102 Requests comments on NUREG-0037, "Potential for Low Pressure Temperature & Low Pressure Turbine on Fuel Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule and
COBB, M. J. Division of Licensing 00/05/19 72pp
- 0004030815 Informs that unit provided info toward closing out facility restart open items at 000520 meeting & committed to confirm info & provide add'l input at 000523 formal submittal
Request DER inputs by 000529
SILVER, H. Operating Reactors Branch 4 00/05/20 1p
- 0004030105 Financials Amend 10 to restart reqt
HERSCHEIN, J. Metropolitan Edison Co 00/05/23 1p
- 0004030201 Amend 10 to restart reqt providing add'l info
* Metropolitan Edison Co 00/05/23 24pp
- 0004030203 Radiation protection plan, App 7A, Revision 3
PORTER, H. E. HERSCHEIN, J. Metropolitan Edison Co 00/05/20 10pp
- 0004030210 Operational QA program, Revision 8
KATOWSKI, R. C. LEROY, D. L. HERSCHEIN, J. Metropolitan Edison Co 00/04/10 112pp
- 0004030423 Requests add'l fee re 000411 Tech Spec change Request Y1 accomplished by Class II Amend Fee Proposed action involves Class III fee
000405, R. M. License Fee Management Branch 00/05/07 1p
- 0004030500 Forwards schedules for future work to support TH1-1 restart safety evaluation
HERSCHEIN, J. Metropolitan Edison Co 00/05/20 2pp
- 0004030502 Forwards answer to five informal questions re corrective actions for 000504 Crystal River accident. Operators will be trained re integrated control system/nuclear instrumentation power failures
HERSCHEIN, J. Metropolitan Edison Co 00/05/29 2pp
- 0004030528 Forwards response to NRC 000503 ltr re loss of effector power issue. One partial loss of effector power has occurred as described in LER 77-16 dated 7/7/03. No total loss of effector power events experienced
HERSCHEIN, J. Metropolitan Edison Co 00/05/30 2pp
- 0004030500 Responds to NRC 000410 ltr re use of term "operable" as applied to single failure criterion for safety sys in power reactors. Requests extension until 000730 for TH1-1 Tech Spec change no change required for TH1-2
HERSCHEIN, J. Metropolitan Edison Co 00/05/30 1p
- 0004030506 Responds to 000410 ltr re use of term "operable" applying to performing review of Unit 1 Tech Spec to determine need for and Unit 2 operating under recovery Tech Specs
HERSCHEIN, J. Metropolitan Edison Co 00/05/30 2pp
- 0004030601 Forwards NRC 000527 ltr, Amend 20 to License DFN-30, safety evaluation & notice of issuance & availability
REINH, M. Operating Reactors Branch 4 00/05/30 4pp
- 0004030602 Advises that NRC has issued amend to License DFN-30, consisting of revisions to & addition of Tech Specs re ventilation filter gas for control room auxiliary & fuel handling logic & reactor side purge
TOURTELLOTT, J. Hearing Branch 4 00/05/07 1p
- 0004030603 Amend 20 to License DFN-30, updating Tech Specs to include revised requirements for installation of in emergency control room & reactor side
REINH, M. Operating Reactors Branch 4 00/06/03 10pp
- 0004030607 Safety evaluation supporting Amend 20 to License DFN-30
* Operating Reactors Branch 4 00/05/03 3pp
- 0004030643 Notice of issuance & availability of Amend 20 to License DFN-30
REINH, M. Operating Reactors Branch 4 00/06/03 2pp
- 0004100311 Forwards response to NRC 000519 ltr re all Tech Spec Change Request 77a which modified piping girder/bends
corrosion requirements
HERSCHEIN, J. Metropolitan Edison Co 00/06/04 2pp

B Reportable occurrences, LERs & related correspondence

0004030024 PWD-THI-00-002 on 000403, worker experiencing chest pains left site in ambulance. Diagnosis was possible heart attack. Unknown if individual was in Metropolitan area.
 HANSEN, R. J. - PHILADELPHIA, R. H. - COLLINGS, J. T. Region I, Philadelphia, Office of the Director 00/05/23 1p

0004040404 Forwards revised LER 00-001/04-1
 HERGENROT, J. D. Metropolitan Edison Co 00/05/30 1p

--0004040409 Revised LER 00-001/04-2 on 000403, results of load study performed on EG buses determined overload could exist on B1 & B10 buses upon loss of EG channel 1 one of four situations Covered by load study design
 MITCHELL, D. G. Metropolitan Edison Co 00/05/30 2pp

0004050004 PWD-THI-00-003 on 000500, Catalytic electrodes left site in ambulance after falling 18 ft from ladder in control room. Individual was not in controlled area.
 HANSEN, R. J. - PHILADELPHIA, R. H. - COLLINGS, J. T. Region I, Philadelphia, Office of the Director 00/05/30 1p

0004120406 AD-00-10/10 on 000403, BWR IR informed unit of potential reportability of steam generator tube rupture safety analysis. Caused by noncompliance error re PWR corrective action will be addressed in followup rep.
 TOOLE, R. J. Metropolitan Edison Co 00/05/06 1p

0004200362 PWD-THI-00-004 on 000404, while performing maint on river water chlorination sys, chlorinator bldg chlorine monitor alarmed. Licensee technicians visiting portion of chlorination was playing around alarm & caused chlorine odor.
 HANSEN, R. J. - PHILADELPHIA, R. H. - COLLINGS, J. T. Region I, Philadelphia, Office of the Director 00/04/06 1p

0004200473 Forwards LER 00-001/03-0
 HERGENROT, J. D. Metropolitan Edison Co 00/04/25 1p

--0004200478 LER 00-001/03-0 on 000407, reactor bldg beam surveillance late data was recorded. Cause problems w/availability of contractor equipment. Surveillance continuing.
 MITCHELL, D. G. Metropolitan Edison Co 00/04/25 2pp

DOCKET 50-292 PILGRIM NUCLEAR POWER STATION, UNIT 1
 * Security, medical, emergency & fire protection plans

0004340081 "Intermittent Safe Shutdown Capability in Event of Fire in Cable Spinning Room"
 * Boston Edison Co 00/01/31 9pp

0004390407 Forwards approved rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 70000." Rule adds new Section 30.4R & App R to 10CFR30.0 & is expected to be published in FR by end of May.
 EISENHART, E. G. Division of Licensing 00/05/19 4pp

0004410003 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR30.0 "Fire Protection Program for Nuclear Power Plants Operating Prior to 70000." Transmitted by NRC 000519 13p Page 14a and end.
 EISENHART, E. G. Division of Licensing 00/03/22 7pp.

0004500024 Forwards three copies of "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Generating Station," prepared by Franklin Research Center.
 ANDERSON, M. J. C. Boston Edison Co 00/09/29 1p

--0004500043 "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Generating Station," for 000323 testing.
 * Franklin Institute/Franklin Research Center P-0519-1 00/01/31 0pp

--0004500043 "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Generating Station," final rep for 70000 testing.
 * Franklin Institute/Franklin Research Center P-0519-2 00/03/31 0pp

--0004500047 "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Generating Station," final rep for 70000 testing.
 * Franklin Institute/Franklin Research Center P-0519-3 00/03/31 0pp

0004610000 Forwards revised cover sheet for Security Training & Qualification Plans 1-3 Cover sheets withheld (ref 10CFR 790)
 ANDERSON, M. J. C. Boston Edison Co 00/06/04 1p

M Antitrust correspondence

0004240409 Under granting MA Municipals 791011 withdrawal of intervention. Whether NRC now DOJ objects No further antitrust proceedings required.
 CUSICK, J. J. Office of the Secretary of the Commission 00/04/19 2pp

* Operating license stage documents & correspondence

0004090165 Forwards add THI-2 related requirements to operating license. Licensee requirements for THI actions during shift meetings. Licensing exam & license dissemination of operating experience. Response requested within 30 days.
 EISENHART, E. G. Division of Licensing 00/05/07 13pp

0004020014 Summary of 000402-23 meeting w/Mark I owners group in San Jose, CA re conformity analysis & testing programs concerning Mark I containment long-term system.
 ANDERSON, M. J. C. Boston Edison Co 00/05/09 8pp

0004100129 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Low Temperature Cracking in PWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule encl.
 EISENHART, E. G. Division of Licensing 00/05/19 7pp

0004020345 Forwards supplemental response to NRC 790120 ltr re containment purge & vent sys. Testing performed during 000404 testing supported original conclusion that max leakage occurs at max differential pressure.
 ANDERSON, M. J. C. Boston Edison Co 00/05/27 2pp

0004020304 Requests delay until 000701 for submittal of proposed Tech Spec revision clarifying term "operable," requested by NRC 000410.
 ANDERSON, M. J. C. Boston Edison Co 00/05/27 1p

0004200407 Discusses analysis of containment purge & vent valve operability. Dynamic & pressure loads acting on device & when valve closed cause stress while valve is closing during design basis LCCA. If valve opening maintained at 42 F.
 ANDERSON, M. J. C. Boston Edison Co 00/05/27 2p

0004200310 Informs that response to NRC 000216 ltr re proposed radiological effluent & ambient monitoring Tech Specs will not be available until Jul 1999.
 ANDERSON, M. J. C. Boston Edison Co 00/05/28 1p

0004100280 Responds to NRC 000423 ltr re effect of dc power supply failure on BCCB performance. Results of evaluation to be transmitted by 000601.
 ANDERSON, M. J. C. Boston Edison Co 00/06/02 1p

0004030044 Ltr to all MAH licensees forwarding "For Comment" edition of NUREG-0410, "SWR Deaerator Nozzle & Control Rod Drive Return Line Nozzle Checking." Comments will be evaluated by NRC prior to final implementation. W/O encl.
 EISENHART, E. G. Division of Licensing 00/04/05 2pp

0004200177 Responds to NRC 000507 ltr re five addl THI-2 related requirements for operating reactors. Well-defined criteria is needed to ensure timely implementation of recommendations. Implementation schedules may vary. Flexibility.
 ANDERSON, M. J. C. Boston Edison Co 00/06/18 1p

0 Inspection reports, IE Submittals & correspondence

0004500323 Forwards waste packaging insp rpt on 000313-14. No noncompliance noted.
 STORIN, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/07 2pp

--0004500344 Waste packaging insp rpt on 000320-14. No noncompliance noted. Major areas inspected: licensee-shopper vehicles. Inspected for compliance w/OSHA & NRC regulations including shipping paper & DOT licensing requirements.
 POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/03/28 4pp

0004500668 Forwards IE Investigation Rpt 50-292/00-12 on 000404-07 & 19-20. No noncompliance noted.
 MARTIN, H. G. Region I, Philadelphia, Safeguards Branch 00/04/18 2pp

DOCKETED ITEMS

87

- 8004050149 IE Investigation Rept 80-293/80-12 on 800308-07 & 19-80 No noncompliance noted Area investigated allegations that spent fuel rods had been illegally stored at Germantown, SE low level waste burial ground
JOHNS, J. H. Region 1, Philadelphia, Safeguards Branch
MOLTER, C. E. Region 1, Philadelphia, Office of the Director 05/04/87 12pp
- 0004050157 Forwards IF Insp Rept 80-293/80-10 on 800308-07 No noncompliance noted
MARTIN, M. S. Region 1, Philadelphia, Safeguards Branch 05/04/87 2pp
- 8004050158 IE Insp Rept 80-293/80-10 on 800308-07 No noncompliance noted Major areas inspected Full scope walk control & accounting including facility organization & operations Details withheld (ref 10CFR8 790)
JOHNS, J. H. Region 1, Philadelphia, Safeguards Branch
MOLTER, C. E. Region 1, Philadelphia, Office of the Director 05/04/87 1p
- 0004050191 Forwards IE Investigation Rept 80-293/80-12 on 800308-07 & 19-80 in response to allegations re illegal shipments of spent fuel
MARTIN, M. S. Region 1, Philadelphia, Safeguards Branch 10/04/86 1p
- 8004050195 IE Investigation Rept 80-293/80-12 on 800308-07 & 19-80 No noncompliance noted Major areas inspected examination of personnel documents & records 5 physical inventory of all fuel assemblies
MOLTER, C. E. Region 1, Philadelphia, Office of the Director
JOHNS, J. H. Region 1, Philadelphia, Safeguards Branch 05/04/86 12pp
- 0004050202 Forwards bk Circular 80-06 "NRC Tech Spec Incompleteness - Reactor Protection Sys Response Time" No written response required
MOLTER, C. E. Region 1, Philadelphia, Office of the Director 05/04/86 1p
- 0004050203 Forwards waste packaging insp rept on 800313-14 No noncompliance noted
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 05/04/86 1p
- 8004050207 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles including shipping paper requirements, DOT placarding requirements, radiation levels & marking & labeling
SMITH, G. H. Region 2, Atlanta, Fuel Facility & Materials Safety Branch
PORTER, J. P. Region 3, Atlanta, Office of the Director 05/03/86 4pp
- 0004050209 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted
SMITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 05/04/86 1p
- 8004050213 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected licensee-shipper vehicle, including shipping paper requirements, DOT placarding requirements, radiation levels & marking & labeling
SMITH, G. H. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 05/03/86 7pp
- 0004050244 Forwards IE Insp Rept 80-293/80-13 on 800308-0401 No noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 05/04/86 2pp
- 8004050245 IE Insp Rept 80-293/80-12 on 800301-0401 No noncompliance noted Major areas inspected refueling activities
BRUNNER, E. J. Region 1, Philadelphia, Office of the Director
MARTIN, T. T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 05/04/86 4pp
- 0004050242 Response to IE Bulletin 80-08 Facility has field head penetration connections w/containment boundary built welds includes penetration closure & subsequent field head outer shell repair particle count performed during vent
AMORINO, G. C. Boston Edison Co. 05/05/86 3pp
- 0004050243 Ack receipt of 800309 1st Informing NRC of licensee statements made in 3K Insp Rept 80-293/80-12 Connected pages w/ 1st & 2nd
MARTIN, M. S. Region 1, Philadelphia, Safeguards Branch 05/05/86 2pp
- 8004050247 Response to NRC 800408 1st Northeast Nuclear Energy Co (secretly identified as well) licensed to operate Indian Creek Plant
NEUBILL, G. E. GAITHER, B. C. Northeast Nuclear Energy Co (aka of Northeast Utilities) 05/05/86 2pp
- 0004050256 Add response to PSIA request for all categories of documents re CPC Forward documents listed in app
NEUBILL, G. E. Division of Rules and Records 05/05/86 3pp
- 0004050257 Requests provision of personnel for field survey re plant breaker review low tide on 800500 will allow map of top of structure Bika must be necessary to recommend final approval of design & placement
NEUBILL, G. E. Hydrologic & Geotechnical Engineering Branch 05/05/86 2pp
- 0004050259 Submit response to IE Bulletin 80-07, "Bum Jet Pump Assembly Failure" Visual inspection insp & ultrasonic testing revealed deficiencies on jet pumps 1,2 & 3D jet pump replaced to limit data hole breasted for surveillance
AMORINO, G. C. Boston Edison Co. 05/04/86 2pp
- R Periodic operating reports & related correspondence
- 0004050244 Forwards monthly operating rept for May 1980
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050246 Monthly operating rept for May 1980
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 0004050240 Forwards monthly operating rept for May 1980
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050243 Monthly operating rept for May 1980
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- B Reportable occurrences, LGRs & related correspondence
- 0004050240 FMO-1-80-070 on 050515, NRC was notified that ChemNuclear transfer trailer hauling low specific activity radioactive waste from transfer engine determined (apparently) the loss of contents or radiological problems identified
NEUBILL, G. E. Region 1, Philadelphia, Office of the Director 05/03/86 1p
- 0004050235 Forwards LGR 80-017/032-0
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050231 LGR 80-017/032-0 on 800505, during 24-h performance test of closed generator per IE Bulletin 79-03 three attempts made before satisfactory calibration on 050510 caused by failure of potential transformer in high voltage chassis
NEUBILL, G. E. Boston Edison Co. 05/04/86 2pp
- 0004050232 Forwards LGR 80-018/034-0
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050233 LGR 80-018/034-0 on 800505, while performing surveillance test of 7 3/4 isolation valves, 8005-11, 12 & 23 declared inoperable cause not stated Valve in each affected sample line closed & position recorded daily
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 0004050234 Forwards LGR 80-019/035-0
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050235 LGR 80-019/035-0 on 800509, during startup of FMRB, NRC was declared inoperable caused by wiring adjacent to installation of alternator shutdown panel & weak exhaust leakage interference having & leakage required
NEUBILL, G. E. Boston Edison Co. 05/04/86 2pp
- 0004050231 Forwards LGR 80-020/036-0
NEUBILL, G. E. Boston Edison Co. 05/04/86 1p
- 8004050237 LGR 80-020/036-0 on 800504, during refueling outage 4, 14 primary containment isolation valves found to have test leakage over requirements caused by normal deterioration of disc to seat mating surface
NEUBILL, G. E. Boston Edison Co. 05/04/86 2pp

DOCKET NO-299 NICHOLSON STATE UNIV RESEARCH RECTOR

Q Inspection report, DE Bulletin & correspondence

--000600043 "Liquid Enrichment Exam"
Commonwealth Edition Co 00/12/06 15p

000600040 Forwards DE Insp Rept NO-294/05-02 on 000400-0501
No correspondence noted
DAVIDA B A Region 3, Chicago, Fuel Facility & Materials Safety
Branch 00/05/14 2p

--000600026 Affidavit describing decontamination techniques that will be
employed in spent fuel replacement job to reduce total vol
of radioactive waste
THOMPSON M Commonwealth Edition Co 00/05/03 2p

000600047 IE Insp Rept NO-294/05-02 on 000400-0501 No correspondence
noted Major areas inspected emergency plan & procedures,
coordination w/support agencies, survey instrumentation &
radiation monitoring program
ERRIO T H Region 3, Chicago, Office of the Director OMED-R J
Region 3, Atlanta, Office of the Director 00/05/14 App

000610000 Brief in support of NRC's NO00214 initial decision authorizing
installation of fuel facilities for which intervenor filed 15
exceptions Intervenor offered no reason to support alleged
error in decision
STEFANOW J P HULLS M J Commonwealth Edition Co 00/05/03 P P
John, Lincoln & Beale 00/05/03 44p

000600039 Ask receipt of 000301 ltr informing NRC of steps taken to
correct noncompliance noted on NRC 000406 ltr
DAVIDA B A Region 3, Chicago, Fuel Facility & Materials Safety
Branch 00/05/22 1p

000600037 Discusses C. Guig's ltr to NRC requesting stay in proceeding
re proposed amend to increase spent fuel storage capacity
Reg's objection inaccurate ACRB found that adequate design
& safety features preclude 100%-gr-waste accident
STEFANOW J P John, Lincoln & Beale 00/05/12 2p

--000600015 Response to item of noncompliance noted in NRC 000426 ltr
Corrective actions reactor safety committee meetings
have been timing since 7/01/11
TERRY G H CARROLL J T Michigan State Univ 00/05/00 1p

000600001 B Order for 000701 oral argument in NRC Public Hearing Room,
Bethesda, MD Oral hour of argument & rebuttal will be granted
to each party
STERN C J Atlantic Safety and Licensing Appeal Panel 00/05/23
1p

DOCKET NO-299 ILLINOIS NUCLEAR POWER STATION, UNIT 1

P. Reactor, medical, emergency 5 fire protection plans

000610035 Response to 000605 objection to scheduling meetings outside
Washington, DC area Meetings are increasingly held outside
of Washington, DC vicinity to allow persons living near
plants opportunity to attend
STERN C J Division of Licensing 00/05/02 2p

000610008 Requests that NRC review of state & local emergency plan
be provided comments w/anal schedule to avoid potential
delay in licensing decisions
JACARNE J F Commission 00/05/13 2p

H General correspondence

000609007 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 1970" State
adds new Section 20.30 & App B to 000900 & is expected
to be published in FR by end of May
STERN C J Division of Licensing 00/05/19 44p

0006020014 Requests public debate re evacuating large populations near
plant plants Oppose plants located in densely populated
areas
HARRIS Affiliation Unknown 00/03/19 1p

000610003 Forwards revised Pages 1-34 & page 54a for proposed
rule 000900, "Fire Protection Program for Nuclear Power
Plants Operating Prior to 1970," transmitted by NRC 000919
1st Page 10a not sent
STERN C J Division of Licensing 00/05/22 72p

P Operating license stage documents & correspondence

000610009 Advises that NRC review of 000900 safeguards contingencies
plan indicates need for add revisions Specific comments
withheld (ref 000900 7000
WARRA B A Operating Reactors Branch 1 00/05/07 2p

000610004 "Evaluation of Licensee Compliance w/Catagory A
Items of NRC Recommendations Resulting From TH-2 Lessons
Learned" All Category A requirements satisfied
SCHWENK A A Operating Reactors Branch 3 (PRe 000426) 00/05/29
2p

--000610000 "Evaluation of Licensee Compliance w/Catagory A Items of NRC
Recommendations Resulting From TH-2 Lessons Learned"
Division of Operating Reactors 00/05/20 1p

000607004 Forwards add fire protection info as suppl to until 000400
ltr re safe shutdown analysis which takes plant to hot
shutdown Addl info provides for taking plant to cold
shutdown
PODFLESS D L Commonwealth Edition Co 00/05/20 1p

000602040 Notifies that new telephone app called Health Physics
Assess OPM has been installed at site Ops intended for
use during emergency to link all power plants & NRC
Emergency Notification Sys hotline will also be used
JACARNE J F Region 3, Chicago, Office of the Director 00/04/11
2p

000610022 Forwards Revision 3 to draft emergency plan Emergency plan
station annexes also sent
PODFLESS D L Commonwealth Edition Co 00/04/04 2p

000609013 Forwards add TH-2 related requirements to operating
reactor Licensee requirements for TH Action Plan include
shift training/licensing exam & licensee dissemination
of operating experience Response requested within 30 days
STERN C J Division of Licensing 00/05/07 100p

--000610040 Draft emergency plan annex
Commonwealth Edition Co 00/07/21 20p

000609042 Notification of 000603 meeting with in Bethesda, MD to
discuss filtered sealed containment app & core retention
devices
HARRIS J F Reactor Systems Branch 00/05/27 2p

--000610047 Revision 1 to draft emergency plan
Commonwealth Edition Co 00/07/21 17p

000604005 Response to NRC 000425 NO-620, 08 15 ltr requesting addl
info re spent training & qualification plans Requests that
response submital date be extended to 000604
PODFLESS D L Commonwealth Edition Co 00/06/13 1p

000600002 Notification of 000520 meeting w/atl contractors &
consultants in Bethesda, MD to exchange technology re
accident sequence & related phenomena per A Schwenk
000410 ltr to L. Peoples
LOHAR B A Reactor Systems Branch 00/05/15 2p

Q Adjudicatory correspondence

000610026 Forwards will advisability of TR Trams & RH Sherman
proposed pending minor changes in spent fuel cell
maintenance job procedures Changes relate to intervenor
argument on appeal Related correspondence
STEFANOW J P John, Lincoln & Beale 00/05/08 2p

000610012 Requests comments on NRC's 0005-05/7, "Potential for Low Pressure
Toughness & Lateral Loading as Potential Reactor &
Reactor Containment Pump Support" Proposed review procedure &
implementation schedule sent
STERN C J Division of Licensing 00/05/19 72p

--000600042 Affidavit recommending that posttest heat soak per test
procedure NRC-040 equivalent be substituted for ultrasonic
test soak technique in spent fuel pit corrosion
surveillance program
HARRIS B A Commonwealth Edition Co 00/05/25 7p

000610017 Forwards request for addl items required to complete upgrade
review of 00 program Response should be provided along
w/response to 000400 request
WARRA B A Operating Reactors Branch 1 00/05/20 4p

DOCKETED ITEMS

89

0004202077 Notification of 000403 meeting w/units in Bethesda,MD to discuss upgraded QA program
BPMALUJ A Quality Assurance Branch 00/05/21 2pp

0004202072 Notification of 000403 meeting w/units in Bethesda,MD re severe accident mitigation features for facilities
CLSWALN L, REVEREJ F Operating Reactors Branch 00/05/23 1p

0004204007 Advise that interim reliability evaluation program resulting from TNC action plan will be implemented Requests attendance at 000404 meeting in Bethesda,MD to discuss details
EISENHUTJ B B Division of Licensing 00/05/23 3pp

0004145007 Forward revised Tech Spec Pages 94,325A,75, B, 88 issued w/ Amendments 54 & 51 to Licenses 0004-29 & 0004-28 respectively
WARRA S A Operating Reactors Branch 00/05/29 2pp

--0004145008 Corrected Pages 94,325A,75 & 88 to Amendments 51 & 54 to Licenses 0004-28 & 0004-29, respectively
+ Operating Reactors Branch 00/04/28 4pp

0004202077 Update to 000402 application to amend License 0004-29 & 0004-28 incorporating administrative changes to App A Tech Specs
NAUGHTONJ W F Commonwealth Edison Co 00/05/30 2pp

--0004202077 Revised Page 309 to App A Tech Specs & 0 for administrative controls. Allow them what they want or lead health physicist to fulfill qualifications of radiation protection manager
+ Commonwealth Edison Co 00/05/30 2pp

0004202077 "Lost of Offsite Power Scenarios for Westinghouse Zion 1 PAB," preliminary assessment report
FLETHURJ C B, 000402E J J, DELANEYJ H N ESB, Inc FIN A-1402
0004202077 00/05/31 2pp

0004202076 Application for amend to License 0004-29 & 0004-28, modifying allowed outage time per 000402 preliminary order
NAUGHTONJ W F Commonwealth Edison Co 00/04/30 3pp

0004202073 Forward response to NRC 000506 request for history of total & partial power outages & attendant degraded voltage. No complete loss of offsite power has occurred but one partial loss incident was reported to NRC
NAUGHTONJ W F Commonwealth Edison Co 00/04/30 2pp

0004120404 Forward allow used by units during 000403 meeting re technology exchange in area of mitigation feature for severe accidents at facilities
GIEREJ D Westinghouse Electric Corp 00/04/30 1p

0004170491 Forward "Mitigation of Severe Accident Study Rept." Rept includes presentations made to NRC & ACRS on 000403 & 000506, respectively & consists of state-of-the-art analyses conducted within 60-day period
CAMILLIJ J Consolidated Edison Co of New York S&P, P J Power Authority of the State of New York 00/04/05 2pp

--0004170492 Response to 000508 ltr transmitting report covering work performed by various consultants Rept Westinghouse rept reoperating
PEOPLES D L Commonwealth Edison Co 00/04/07 3pp

--0004170493 "Mitigation of Severe Accident Study Rept." consisting of repts re evaluation of validated risk-state analyses, containment response for Class V accidents & post-accident containment venting w/ 000403 & 000506
+ Westinghouse Electric Corp 00/03/21 400pp

0004130165 Forward check inadvertently left off package submitted on 000403 MFC and
FLETHURJ C B Commonwealth Edison Co 00/04/06 1p

0004160071 Forward response to NRC Questions 28 - 40 re Facility QA program per 000408 & 000506 requests
PEOPLES D L Commonwealth Edison Co 00/04/07 12pp

0004140169 Notification of 000403 meeting w/units in Bethesda,MD to discuss interim reliability evaluation program
CLSWALN L, Operating Reactors Branch 00/04/09 3pp

0004170027 Forward commitments to comply w/requirements & schedules in NRC 000507 ltr re Unit 1 TNC-2 related requirements. Bredem Unit 1 is currently undergoing extensive w/d & decontamination therefore no response is provided
PEOPLES D L Commonwealth Edison Co 00/04/12 10pp

0004202047 Summary of 000402 Technology Exchange Meeting 3 w/units in Bethesda,MD re accident mitigation features for facilities
LMDUJ A Reactor Systems Branch 00/04/12 23pp

0004202088 Notification of 000403 meeting w/units, contractors & consultants in Bethesda,MD for presentation in area of core-melt accident sequences for facilities Agenda mail
REVEREJ F Reactor Systems Branch 00/04/16 2pp

0004202055 Notification of 000407 meeting w/units & consultants in Bethesda,MD to discuss technology exchange re containment structural response, failure pressures & failure mode
REVEREJ F Reactor Systems Branch 00/04/17 2pp

0004202027 Request re-evaluation of original proposal for submitting schedule for implementing ATHS instrumentation mode identified in NRC04-240 Revised schedule & justification should be submitted in 30 days
WARRA S A Operating Reactors Branch 00/04/19 2pp

0004273004 Forward Revised Revisions 11 & 12 consisting of Page 1-7 of "Cell-A," "Core Ed QA Program for Nuclear Generating Stations - Revised Revision 11 includes basis on which equivalent education requirements will be established
PEOPLES D L Commonwealth Edison Co 00/04/23 1p

0004273029 Forward response to NRC 000506 question on adequacy of station electric distribution app voltages lowest bus voltage when starting largest non-class IE load was calculated when all other loads were running. Matter closed
NAUGHTONJ W F Commonwealth Edison Co 00/04/23 2pp

6. Inspection reports, IE histories & correspondence

0004170727 Forward IE insp Repts 00-295/00-03 & 00-304/00-02 on 000407-0008 & notice of violation
HEBERMANJ P Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/26 2pp

--0004170728 Notice of violations from insp on 000407-0008
+ Region 3, Chicago, Office of the Director 00/04/10 1p

--0004170728 IE Insp Repts 00-295/00-03 & 00-304/00-02 on 000407-0008
Noncompliance noted in submittal margin inspections while in cold shutdown were below Tech Spec limits
EISENHUTJ B B Region 3, Chicago, Office of the Director 00/04/18 4pp

0004170841 Forward IE Insp Repts 00-295/00-06 & 00-304/00-09 on 000408-11 & 0417-10 re noncompliance noted Major areas impacted small
HEBERMANJ P Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/30 2pp

--0004170842 IE Insp Repts 00-295/00-06 & 00-304/00-09 on 000408-11 & 0417-10 re noncompliance noted Major areas impacted small
LOEHLERJ J, 000402E J J Region 3, Chicago, Office of the Director 00/04/25 2pp

0004190238 Forward IE Insp Repts 00-295/00-04 & 00-304/00-02 on 000408 re noncompliance noted
EISENHUTJ B B Region 3, Chicago, Fuel Facility & Materials Safety Branch 00/05/09 3pp

--0004190237 IE Insp Repts 00-295/00-04 & 00-304/00-03 on 000408 re noncompliance noted Major areas impacted small
Noncompliance from previous collection/effluent samples & examination of spent samples
EISENHUTJ B B, 000402E J J Region 3, Chicago, Office of the Director 00/05/04 4pp

0004230165 Forward IE Insp Repts 00-295/00-07 & 00-304/00-06 on 000414-30 re noncompliance noted
HEBERMANJ P Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/05/13 2pp

--0004230177 IE Insp Repts 00-295/00-07 & 00-304/00-06 on 000414-30 re noncompliance noted
EISENHUTJ B B, 000402E J J Region 3, Chicago, Office of the Director 00/05/12 2pp

0004170075 Add response to NRC request for six categories of documents re CFC Forward documents listed in app
FELTONJ W Division of Rules and Records 00/05/23 3pp

*

DOCKETED ITEMS

- 0006130097 Forwards response to updated memo received on 000563 re visit interdependencies re proposed imposition of civil penalties. Cause sheet of IE Insp rept encl
KOPPELBER, J. J. Commonwealth Edison Co. 00/03/20 2pp
- 0006130102 Discusses three safety-related events occurring at Facility. Civil penalties for noncompliance items will be imposed. Forwards notice of violation/notice of proposed imposition of civil penalties & history of enforcement action
KOPPELBER, J. J. Office of Inspection & Enforcement, Office of the Director 77/09/20 2pp
- 0006130104 Notice of violation from Insp on 770705-08, 14, 15 & 20
KOPPELBER, J. J. Office of Inspection & Enforcement, Office of the Director 77/09/20 2pp
- 0006130108 Notice of proposed imposition of civil penalties in amount of \$21,000 re noncompliance discovered during Insp on 770705-08, 14, 15 & 20 History of escalated enforcement action encl
KOPPELBER, J. J. Office of Inspection & Enforcement, Office of the Director 77/09/20 2pp
- 0006130106 Immediate action 31r re IE physical security insp on 000512-15 & 17D Licensee is expected to undertake actions outlined in issue Encl withheld (ref 10CFR2 790)
KOPPELBER, J. J. Commonwealth Edison Co. 00/03/23 1p
- 0006130297 Advises that responses to IE Bulletin 79-04/Revision 1, were found acceptable Evaluation encl
WAGNER, D. A. Operating Reactors Branch 2 00/03/28 17pp
- 0006130398 Forwards response to IE Bulletin 00-04, "Engineered Safety Feature (ESF) Reset Controls." Proposed memo identified only if present sys design may compromise protective action of equipment
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/10 9pp
- B. Reportable occurrences, LERs & related correspondence**
- 0006130582 Forwards RO re diesel driven fire pump
WAGNER, D. A. Commonwealth Edison Co. 00/05/03 1p
- 0006130609 RO on 000409, 14 & 23, 03 diesel driven fire pump failed to auto start & tripped on overcurrent after being started. Cause by worn water pump drive belt & speed switch. Engine cooling sys started & depleted w/low pressure & demineralized water
SCHNEIDER, H. Commonwealth Edison Co. 00/03/20 2pp
- 0006131497 Forwards LER 00-021/03L-0
WAGNER, D. A. Commonwealth Edison Co. 00/03/22 1p
- 0006130636 LER 00-021/03L-0 on 000423 while operating at 98% power, weekly surveillance requiring performance testing of safeguards logic & high pressure logic was performed 11 days late. Cause by transcription error. Testing was performed
KOPPELBER, J. J. Commonwealth Edison Co. 00/03/23 1p
- 0006170479 Forwards LER 00-023/01T-0
WAGNER, D. A. Commonwealth Edison Co. 00/06/06 1p
- 0006170475 LER 00-023/01T-0 on 000523 charging pump 10CFR21 concern discovered through Westinghouse generic notification. Cause by design flaw insufficient at high pressure Standing order issued to open relief valve when needed
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/06 2pp
- 0006170490 Forwards LER 00-022/03L-0
WAGNER, D. A. Commonwealth Edison Co. 00/06/06 1p
- 0006170232 LER 00-025/03L-0 on 000510 while performing periodic tests, function generator 1AM-441B output was found out of tolerance. Cause by instrument drifting. Unit isolated
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/09 1p
- 0006170250 Forwards LER 00-027/01T-0
WAGNER, D. A. Commonwealth Edison Co. 00/06/10 1p
- 0006170236 LER 00-027/01T-0 on 000601 while in cold shutdown, bleed rates for steam generator scrubbers under noted load found consistently below min limit. Cause by weak bleed valve. Compensator springs installed w/higher spring rates
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/12 2pp
- 0006170254 Forwards LER 00-024/03L-0
WAGNER, D. A. Commonwealth Edison Co. 00/06/13 1p
- 0006170259 LER 00-024/03L-0 on 000615 while performing PT-10, safeguards activation tests, 16 vcc pump failed to start from train A of safeguards. Cause by contacts for safeguards activation mating information contact contacts adjusted
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/13 1p
- 0006130403 Forwards updated LER 00-024/PPS-1
WAGNER, D. A. Commonwealth Edison Co. 00/06/18 1p
- 0006130407 Forwards updated LER 00-024/PPS-1
WAGNER, D. A. Commonwealth Edison Co. 00/06/18 1p
- 0006130412 Updated LER 00-024/PPS-1 on 000618 while performing PT-10, safeguards activation tests, 16 vcc water pump failed to start from train A. Cause by type N-2 switch contacts making intermittent contact. Permanent and being evaluated
KOPPELBER, J. J. Commonwealth Edison Co. 00/06/18 2pp
- DOCKET 00-06A REGIONS FERRY NUCLEAR POWER STATION, UNIT 3**
F. Security, medical, emergency & fire protection plans
- 0006130447 Requests 000590-01 meeting to visit technical support kit, operational support kit & emergency operations facility re compliance w/00060-0008 Public comment letter received at 000521 evening meeting. Meeting notice & agenda encl
KOPPELBER, J. J. Operating Reactors Branch 2 00/05/14 2pp
- 0006130407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50.48 & App B to 10CFR50 & is expected to be published in FR by end of May
KOPPELBER, J. J. Division of Licensing 00/05/19 46pp
- 0006130563 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 000519 (1r Page 14a not encl)
KOPPELBER, J. J. Division of Licensing 00/05/22 73pp
- 0006130632 Submits application to NRC classification of emergency planning requirements. Locating emergency operations facility within emergency planning zone adds to number of people to be evacuated & creates weakness inside zone
KOPPELBER, J. J. Alabama, State of 00/05/29 2pp
- 0006130635 Forwards 000521 revisions to training & qualification plan & responses to NRC 00-030 comments. Encl withheld (ref 10CFR2 790)
KOPPELBER, J. J. Tennessee Valley Authority 00/06/02 1p
- 0006130213 Forwards revisions to safeguards contingency plan. Plan withheld (ref 10CFR2 790)
KOPPELBER, J. J. Tennessee Valley Authority 00/06/03 1p
- 0006170880 Requests participation in NRC study of people-related problems in nuclear safeguards. Involves collection of data on licensee security forces & practices including visit to facility to interview security mgr personnel
KOPPELBER, J. J. Operating Reactors Branch 2 00/06/03 2pp
- P. Operating license stage documents & correspondence**
- 0006190165 Forwards addl TMI-2 related requirements to operating Reactors Licensee requirements for TMI Action Plan include shift training, licensing exams & licensee licensing requirements of operating experiences. Response requested within 30 days
KOPPELBER, J. J. Division of Licensing 00/08/07 139pp

DOCKETED ITEMS

8 Reportable occurrences, LERs & related correspondence

0004040209 Forwards LER 90-017/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/02 1p

--0004040323 LER 90-017/03L-0 on 000404, after running B1 4 1 1 & 4. Last page of 01 was missing. Last page had not been performed. 3 of last 4 months, to one fire protection issue not tested. Monthly caused by misplacement. Page violated.
* Tennessee Valley Authority 00/06/02 2pp

0004040404 Forwards LER 90-012/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/06 1p

--0004040424 LER 90-012/03L-0 on 000404, while performing B1 4 2 A-2, L1B-3 switch 2 & L1B-3 switch 2 failed to operate. Caused by stuck switch contacts. Switch contacts cleaned & checked for proper setpoint.
* Tennessee Valley Authority 00/06/06 2pp

0004050024 Final Part 25 high re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch lines were cut to ADSMPT requirement. Investigations conducted & closed at AS listed facilities.
BOWEN, J L Chembrun Corp., Tube Turn Div 00/06/06 2pp

0004070001 Forwards LER 90-014/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/10 1p

--0004070092 LER 90-014/03L-0 on 000407, during normal operation, reactor core isolation cooling tripped on overpressure due to loss of speed control. Caused by failure in EDM has failure due to end of life EDM has replaced & CALHOUN.
* Tennessee Valley Authority 00/06/06 2pp

0004070096 Forwards LER 90-012/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/11 1p

--0004070102 LER 90-012/03L-0 on 000407, 25 PWR pump cooling water flow inadequate per TB 3 3 2 ICL 1 & 3 3 3 3. Caused by apparent restriction in cooling water piping. Piping changed & flushed.
* Tennessee Valley Authority 00/06/10 2pp

0004070403 Forwards LER 90-012/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/11 1p

--0004070412 LER 90-012/03L-0 on 000407, following completion of flow test on diesel generator heat exchanger, 20 cooling water found inadequate per TB 3 3 2 2. Apparently caused by restriction in cooling water piping. Water lines flushed.
* Tennessee Valley Authority 00/06/11 2pp

0004080020 Forwards LER 90-012/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/12 1p

--0004080020 LER 90-012/03L-0 on 000408, L1B-3 switch 2 failed to operate. Cause attributed to stuck switch contacts. LER switches inside level indicating switch replaced & checked for proper setpoint & repeatability.
* Tennessee Valley Authority 00/06/12 2pp

0004080409 Forwards LER 90-012/03L-0
CALHOUN, J R Tennessee Valley Authority 00/06/17 1p

--0004080409 LER 90-012/03L-0 on 000409, reactor low pressure switch PS-3-742 G1 1, found out of tolerance. Caused by instrument setpoint drift. Barton 200 pressure switch inspected, reusable & functionally tested for repeatability.
* Tennessee Valley Authority 00/06/17 2pp

DOCKET 90-297 NORTH CAROLINA STATE UNIV. PLANT REACTOR

F Security, medical, emergency & fire protection plans

0004100367 Ack receipt of NRC 000519 ltr re physical protection requirements. Physical security plan submitted & implemented in 1994. Actions objective of 10CFR73.47(a)(1), (1)(F) & (1)(G); therefore new plan is not necessary.
DRAKE, T C, North Carolina State Univ 00/06/04 1p

DOCKET 90-298 COOPER NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

0004040407 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 199101." Rule adds new Section 90.14 & App R to 10CFR90.5 & is expected to be published in FR by end of May.
EISENHART, D O Division of Licensing 00/06/14 4pp

0004100403 Forwards revised Pages 3-14 & new Page 14a for proposed rule 10CFR90.5 "Fire Protection Program for Nuclear Power Plants Operating Prior to 199101." Transmitted by NRC 000510 ltr Page 14a not sent.
EISENHART, D O Division of Licensing 00/06/22 73pp

0004090318 Forwards revised pages to safeguard contingency plan. Revision 1 Revision withheld (ref 10CFR2 790).
PILANT, J H Nebraska Public Power District 00/06/30 1p

0004100501 Forwards add info re guard training & qualification plan in response to NRC 000404 ltr info withheld (ref 10CFR2 790).
PILANT, J H Nebraska Public Power District 00/06/05 1p

F Operating license stage documents & correspondence

0004090505 Forwards add TMI-2 related requirements to operating reactor licenses requirements for TMI Action Plan. Include shift training, licensing exam & license dissemination of operating experience. Response requested within 30 days.
EISENHART, D O Division of Licensing 00/06/07 103pp

000405014 Summary of 000402-23 meeting w/ NRC 1 owners group in San Jose, CA re certification analysis & testing program concerning Mark I containment leakage program.
SERINCE, C I Assistant Director for Plant Systems 00/06/09 9pp

0004100122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule sent.
EISENHART, D O Division of Licensing 00/06/19 72pp

0004100501 Responds to NRC 000410 ltr requesting amendment to radiological Tech Spec to clarify meaning of term "previous" Previous discussions with Inspector concluded open, suitable adequate clarification & no add revision is necessary.
PILANT, J H Nebraska Public Power District 00/06/30 1p

0004100575 Discusses effect of dc power supply failure on ECCS operation. Forwards listing of ECCS ops available w/ various single failures. Loss of equipment due to water spillage has been satisfactorily addressed.
PILANT, J H Nebraska Public Power District 00/06/08 2pp

0004060604 Ltr to all NRC licensees forwarding "For Comment" edition of NUREG-0419, "TMI Precursor Events & Control Rod Drive Return Line Nozzle Cracking." Comments will be evaluated by NRC prior to final implementation. NRC 0005 0005.
EISENHART, D O Division of Licensing 00/06/05 23pp

0004080500 Advises that it intends to respond to 000507 request re TMI-2 requirements within schedule. Unit presently evaluating alternatives within framework of NRC summary group.
PILANT, J H Nebraska Public Power District 00/06/10 2pp

0004200402 Requests expeditious deletion of Tech Spec 2 1 1/3 1 1 re max change of temp across condenser (as indicated on encl).
PILANT, J H Nebraska Public Power District 00/06/20 2pp

--0004200406 Deletes Tech Spec 2 1 1/3 1 1 re max change of temp across condenser.
* Nebraska Public Power District 00/06/20 2pp

G Inspection reports, IF Bulletins & correspondence

0004200519 Forwards 10 Insp Report 90-298/00-04 on 000511-12 & 24-27 re noncompliance noted. Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/06/17 2pp

--0004200524 10 Insp Report 90-298/00-04 on 000511-12 & 24-27 re noncompliance noted. Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/06/17 2pp

- 0004000115 Forwards IE Circular 00-06, "SWR Tech Spec Inconsistency - Reactor Protection Sys Response Time - No written response received".
0004000115 Region 4, Dallas, Office of the Director 00/04/00 1p
- 0004000130 Forwards IE Insp Rpt 00-270/79-18 on 7/10/00. No noncompliance noted.
0004000130 Region 4, Dallas, Fuel Facility & Materials Safety Branch 00/04/00 2pp
- 0004000135 IE Insp Rpt 00-270/79-18 on 7/10/00. No noncompliance noted. Major areas inspected: regulations, instructions & operating procedures, training & audit program.
0004000135 Region 4, Dallas, Fuel Facility & Materials Safety Branch 0004000135 Region 4, Dallas, Office of the Director 00/04/00 3pp
- 0004000146 Responds to IE Bulletin 00-07, "SWR Jet Pump Assembly Failure - Confirms 000500 Telco's reporting completion of ultrasonic tests. No crack indications were found."
0004000146 Nebraska Public Power District 00/05/00 1p
- 0004000188 Forwards IE Insp Rpt 00-288/00-06 on 0004000115-21-23 & 29-30. No noncompliance noted.
0004000188 Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/00 2pp
- 0004000209 IE Insp Rpt 00-270/00-06 on 0004000115-21-23 & 29-30. No noncompliance noted. Major areas inspected: O&M, calibration, inventory, major procedures & IE Bulletin 79-08.
0004000209 T. F. SPANGLER, D. O., COMSOLC, C. L. Region 4, Dallas, Office of the Director 00/05/00 0pp
- 0004000297 Forwards IE Bulletin 00-11, "Masonry Wall Design" Replaces action & written response. IE Info Notice 79-08.
0004000297 "Overloading of Structural Elements Due to Pipe Rupture" Rpt. encl.
0004000297 Region 4, Dallas, Office of the Director 00/05/00 1p
- 0004000307 Forwards IE Bulletin 00-15, "Decay Heat Removal Sys Operability." No written response required. IE Info Notice 00-08, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl.
0004000307 Region 4, Dallas, Office of the Director 00/05/00 1p
- 0004000344 Discusses violation noted in IE Insp Rpt 00-288/79-20 & 30-270/00-06 Package & vehicle not identical except in case of bulk shipment of ion specific activity radioactive waste. Cites appropriate corrective actions requested.
0004000344 Division of Fuel Facility & Materials Safety 00/05/00 2pp
- R. Periodic operating reports & related correspondence
0004000377 Forwards monthly operating rpt for May 1990.
0004000377 Nebraska Public Power District 00/06/00 1p
- 0004000502 Monthly operating rpt for May 1990.
0004000502 MALLINDER, P. L. Nebraska Public Power District 00/06/00 4pp
- 0004000501 POINT BEACH NUCLEAR PLANT, UNIT 2
Fire protection, medical, emergency & fire protection plans
0004000501 1p
- 0004000577 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site. It is intended for use during emergencies to link all power plants & NRC. Emergency notification sys testing will also be used.
0004000577 Region 3, Chicago, Office of the Director 00/06/00 0pp
- 0004000587 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 7/9/00." Rule adds new Section 50.46 & App. 3 to 10CFR50 & is expected to be published in FR by end of May.
0004000587 Division of Licensing 00/05/00 4pp
- 0004000602 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 7/9/00." Transmitted by NRC 0006/19 1st Page data not encl.
0004000602 Division of Licensing 00/05/00 73pp
- 0004000602 Forwards add info re design of flood water suppression sys. 4 dry hydrant lines & control room light fixtures for fire protection safety evaluation. Notification requested by 0007/06. If design data are required.
0004000602 Wisconsin Electric Power Co 00/06/00 10pp
- 1
P. Operating license stage documents & correspondence
0004000602 1p
- 0004000602 Forwards add TRU-2 related requirements to operating Reactors Licensee requirements for TRU Action Plan include shift training, licensing exams & licensee dissemination of operating emergency Response requested within 30 days.
0004000602 Division of Licensing 00/06/00 13pp
- 0004000602 Notifies that Facility will use Gen Nuclear, Inc Model CRM 6-00-2 radioactive shipping cask for delivery of malle to Lavalley.
0004000602 Wisconsin Electric Power Co 00/05/00 1p
- 0004000602 Requests comments on NRC-00-077, "Potential for Low Pressure Temperature & Lamellar Tearing on FWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule encl.
0004000602 Division of Licensing 00/05/00 72pp
- 0004000602 Forwards Amends 45 & 50 to Licenses 000-24 & 000-27, respectively. Safety evaluation & notice of issuance & availability.
0004000602 Operating Reactors Branch 3 00/05/00 3pp
- 0004000602 Amends 45 & 50 to Licenses 000-24 & 000-27, respectively. Incorporating Tech Specs contained in App. A & B in license Amends add limiting conditions for operation & surveillance requirements for low temp outgassing sys.
0004000602 Operating Reactors Branch 3 00/05/00 3pp
- 0004000602 Safety evaluation supporting Amends 45 & 50 to Licenses 000-24 & 000-27, respectively.
0004000602 Office of Nuclear Reactor Regulation, Director 00/05/00 72pp
- 0004000602 Notice of issuance & availability of Amends 45 & 50 to Licenses 000-24 & 000-27, respectively.
0004000602 Operating Reactors Branch 3 00/05/00 2pp
- 0004000602 Forwards safety evaluation supporting design aspects of containment purge valve isolation override & other engineered safety features activating signals except radiation monitors which initiate containment purge isolation.
0004000602 Operating Reactors Branch 3 00/05/00 2pp
- 0004000602 Safety evaluation supporting design aspects of containment purge valve isolation override & other engineered safety features activating signals except radiation monitors which initiate containment purge isolation.
0004000602 Operating Reactors Branch 3 00/05/00 1p
- 0004000602 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override Containment Purge Valve Isolation & Other Engineered Safety Features Signals for Point Beach Nuclear Power Station, Units 1 & 2."
0004000602 SSB, Inc. P.O. Box 2001 000180-4129 34/09/20 10pp
- 0004000602 Forwards description of proposed rule to (a) amend the power supplies in response to NRC 000421 1st Rule will be completed by 010100. Diagram of proposed supply sys to white & yellow instrument buses encl.
0004000602 Wisconsin Electric Power Co 00/05/00 4pp
- 0004000602 Advises that will be forwarding under separate cover, set of piping & instrumentation diagrams for plant isolation. Diagrams also forwarded via package.
0004000602 Wisconsin Electric Power Co 00/06/00 1p
- 0004000602 Discusses 000400/08-1000 re power plant staffing. USIL has neither utility nor NRC staff. No indication of people to implement sys which NRC has developed. Lists 1000-related aspects which have been overlooked.
0004000602 Affiliation Unknown 00/06/00 0pp
- 0004000602 Withdraws 000401 request for NRC contractor to visit Facility to perform interviews & other activities associated with NRC contract UO 000527. Re requested postponement or cancellation of visit due to high level of plant activities.
0004000602 Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/00 1p

0004180008 Responds to 000314 request that NRC contractor be allowed to wait facility to meet outstanding staff & test emergency procedures. Requests postponement or cancellation of visit to inspect safety of activities at plant.
BURETTE D Wisconsin Electric Power Co 00/03/27 2pp

0004200460 Forwards response to NRC 000500 ltr re five addl 10E-2 related requirements for operating reactors. Assumes that implementation of add requirements was not meant to impede completion of previous commitments.
FAY C W Wisconsin Electric Power Co 00/04/11 1pp

D Inspection reports, IE Bulletin & correspondence

0004260594 Forwards SE Insp Rpts 00-264/00-07 & 00-301/00-04 on 000408-10 No noncompliance noted.
BAYDA A B Region 3, Chicago, Fuel Facilities & Materials Safety Branch 00/05/02 2pp

0004260801 IE Insp Rpts 00-264/00-07 & 00-301/00-04 on 000408-10 No noncompliance noted. Major areas inspected: radiation protection program associated with refueling outage including radiation protection procedures & training exposure control. MILLER D E, LOVENSBALE F C Region 3, Chicago, Office of the Director. FISHKILL L H Region 3, Chicago, Fuel Facilities & Materials Safety Branch 00/05/02 7pp

0004260872 Forwards IE Insp Rpts 00-264/00-07 & 00-301/00-04 on 000408-10 & 0408 No noncompliance noted.
HEIDMANN S F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/05/14 2pp

0004260888 IE Insp Rpts 00-264/00-07 & 00-301/00-04 on 000408-10 & 0408 No noncompliance noted. Major areas inspected: plant procedures & operator training. Dr. BOGGS meeting was held to review plant performance.
MARRICHIN F, CHETEL J D, REINHARDT F W Region 3, Chicago, Office of the Director 00/05/14 2pp

0004260904 Forwards proprietary response to IE Insp Rpts 00-264/00-04 & 00-301/00-05 Revision to modified amended security plan with ltr (ref 10E2 750).
BURETTE D Wisconsin Electric Power Co 00/05/29 2pp

0004260930 Responds to IE Bulletin 00-05, "Component Actuator Seizures." No safety-related sig or comment seen. All-90 00-301/00-05 review hydrocarbon actuator.
FAY C W Wisconsin Electric Power Co 00/05/29 1p

0004260946 Responds to SE Bulletin 00-12, "Decay Heat Removal Sys Operability." Plant design does not provide for automatic activation of ECCS recirculation or automatic testing of containment recirculation pump valves.
FAY C W Wisconsin Electric Power Co 00/06/05, 3pp.

0004260972 Forwards response to NRC request for info re Facility Max 1992 add current info provided re number of add current indications recorded in Steam Generator A & B hot leg & distribution by size & height above subcooled.
FAY C W Wisconsin Electric Power Co 00/06/09 2pp

0004260984 Ack receipt of 000509 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 00-264/00-06 & 00-301/00-05.
HINDS A Region 3, Chicago, Safeguards Branch 00/06/10 1p

0004260987 Responds to NRC 000592 ltr re violations noted in IE Insp Rpts 00-264/00-06 & 00-301/00-05. Corrective actions withheld (ref 10E2 750).
BURETTE D Wisconsin Electric Power Co 00/05/09 1p

0004260988 Forwards IE Insp Rpts 00-264/00-06 & 00-301/00-07 on 000408-10 No noncompliance noted.
HINDS A Region 3, Chicago, Safeguards Branch 00/06/10 2pp

0004260993 IE Insp Rpts 00-264/00-06 & 00-301/00-07 on 000408-10 No noncompliance noted. Major areas inspected: main control & controllability, organizational arrangements & control, storage & inventory. React details withheld (ref 10E2 750).
HINDS A Region 3, Chicago, Safeguards Branch. FENLEY D O, PATTERSON J F Region 3, Chicago, Office of the Director 00/06/10 1p

E Periodic operating reports & related correspondence

0004170473 Forwards monthly operating rpts for May 1980.
FAY C W Wisconsin Electric Power Co 00/06/10 1p

F Reportable occurrences, LERs & related correspondence

0004260932 Discusses review of 000520 steam generator leak occurrence & results of subsequent insp concludes that generators adequately inspected & are safe for continued operation. Safety evaluation encl.
FAY C W Materials Engineering Branch 00/05/23 2pp

0004260934 Safety evaluation of steam generator tube degradation. Generators adequately inspected & reasonable assurance of continued safe operation exists.
Materials Engineering Branch 00/05/23 14pp

G Operator Examinations

0004180071 Requests concurrence that operating training program is equivalent to some min concept or background studies so justify arbitrary requirement. Reply requested by 000701.
FAY C W Wisconsin Electric Power Co 00/06/04 2pp

0004260932 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

0004260947 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 7001D1." Rule adds new Section 50.49 & App A to 10CFR50 & is expected to be published in FR by end of May.
EISENHUT D G Division of Licensing 00/05/19 44pp

0004260952 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50, "Fire Protection Program for Nuclear Power Plants Operating Prior to 7001D1." Transmitted by NRC 000519 ltr (Page 14a not encl).
EISENHUT D G Division of Licensing 00/05/22 73pp

0004260959 Advice of extension until 000001 for development of emergency response TLOs per 000307 draft emergency plan. Rites are being surveyed for proper location of deployment.
EISENHUT D H Florida Power Corp 00/05/28 2pp

0004260960 Requests that response to NRC 000322 ltr re safeguards contingency plans be provided by 000430.
EISENHUT D H Operating Reactors Branch 4 00/05/29 2pp

0004260961 Advice that fire protection program made will not be completed by Oct 1990 due to NRC delay in responding to Unit 701206 & 000119 submittals on safety evaluation items.
EISENHUT D H Florida Power Corp 00/06/11 3pp

H General correspondence

0004260968 Responds to 000509 ltr requesting response to F Bulletin questions about impact of 000207 accident on environment. Facility will not be authorized to restart until post-accident remedial actions are satisfactorily completed.
EISENHUT D J Office of the Executive Director for Operations 00/06/10 1p

0004260975 Requests response to encl F Robinson inquiry re impact of 000509 accident on environment.
EISENHUT D H 00/05/29 2pp

0004260983 Add response to PSA request for 29 categories of documents re Facility 000509-0029, "Safeguards Summary Event List, Revision 3," is available in PSD.
PELTON J H Division of Rules and Records 00/06/20 1p

I Financial Information

0004260945 Forwards internal cash flow projection for yr ending 7/01/91. Re rating requirements of 10CFR140.22 Confirmation requested.
LANGE D J Florida Power Corp 00/06/20 2pp

J Insurance & Indemnity Information

0004260919 Forwards Endorsement 42 to AMI Policy No 199.
FELDER J H Marsh & McLennan, Inc., R & R Nuclear Consultants, Inc. 00/06/09 2pp

- 0004005814 Forwards IE Insp Rept 50-302/00-10 on 000001-0411 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/07 2pp
- 0004005925 IE Insp Rept 50-302/00-10 on 000001-0411 No noncompliance noted Major areas inspected retesting insp findings, Post retesting, retesting activities, maintenance activities & IE Bulletin 79-018
MARTIN, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 0004005925 J Region 2, Atlanta, Office of the Director 00/05/07 4pp
- 0004005938 Forwards IE Bulletin 00-11, "Hexonary Mail Design" Requires action & written response IE Refs Notice 79-005
"Downloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/08 3pp
- 0004005987 Forwards IE Bulletin 00-10, "Decay Heat Removal Sys Operability" Requires action & response within 30 days
IE Insp Notice 00-05, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/07 2pp
- 0004006003 Forwards IE Circular 00-11, "Emergency Diesel Generator Load Oil Cooler Failures" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/13 3pp
- 0004006017 Forwards IE Insp Rept 50-302/00-00 on 000414-19 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/12 2pp
- 0004006023 IE Insp Rept 50-302/00-00 on 000414-19 No noncompliance noted Major areas inspected retesting & followup on licensee identified items
O'BRYEN, B J, GUTHER, T Region 2, Atlanta, Office of the Director
MARTIN, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/13 4pp
- 0004006073 Forwards IE Insp Rept 50-302/00-00 on 000403-0582 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/16 2pp
- 0004006076 IE Insp Rept 50-302/00-02 on 000408-0502 No noncompliance noted Major areas inspected retesting/surveillance activities & IE Bulletin 79-01
O'BRYEN, B J, GUTHER, T Region 2, Atlanta, Office of the Director
MARTIN, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/16 4pp
- 0004006403 Forwards supplemental response to violation noted in IE Insp Rept 50-302/00-10 URG 000408-0502 memo distributed to all plant personnel, re-emphasized intent of temporary process change & limits to change
HAWKINS, J A Florida Power Corp 00/05/07 3pp
- 0004100681 Ark receipt of 000506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/00-10
GUTHRIE, P Y Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/05/29 1p
- 0004100683 Responds to NRC 000418 ltr re violations noted in IE Insp Rept 50-302/00-10 corrective actions personnel operating
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/29 1p
- 0004100687 Forwards IE Insp Rept 50-302/00-10 on 000010-01 & notice of violation
GUTHRIE, P Y Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/18 3pp
- 0004100691 Notice of violation from Insp on 000018-01
Region 2, Atlanta, Office of the Director 00/04/17 1p
- 0004100692 IE Insp Rept 50-302/00-10 on 000018-01 Noncompliance noted, contamination of protective clothing, ready for use in excess of procedural limits
LEWIS, R C Region 2, Atlanta, Office of the Director 000406-A F, Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/17 2pp
- 0004100705 Responds to IE Bulletin 00-12, "Decay Heat Removal Sys Operability" Conduct of operations has been revised to establish administrative controls to be followed prior to voluntarily entering degraded mode of operation
WRIGHT, R N Florida Power Corp 00/04/06 3pp
- 0004100707 Forwards revised response to IE Bulletin 79-01, "Temp Effects on Level Measurements" Emergency procedures have been revised to alert operators of possible erroneous level indication during post-accident conditions
WRIGHT, R N Florida Power Corp 00/04/06 2pp
- 0004100708 Ark receipt of 000425 ltr re Reactor area welds FM-120B, FM-124 & 125 & FM-126 to 123 Agree up/replace to monitor welds through normal inspection insp program provided welds are scheduled for insp during early insp period
MARTIN, R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/07 1p
- 0004100712 Responds to NRC concerns re Insp Followup Item 79-05-01 Results of supplemental insp of 16 welds disclosed no evidence of any-related indication Progress Insps of welds FM-120B, FM-124 & 125 & FM-126 to 123 during inspection Insp
HAWKINS, J A Florida Power Corp 00/04/23 2pp
- 0004100714 Ark receipt of 000711 needed to complete response to IE Bulletin 00-05, "Vacuum Condition Resulting in Damage to Chemical Vent Control Sys Holdup Tanks"
WRIGHT, R N Florida Power Corp 00/04/11 2pp
- 0004100746 Responds to issue of noncompliance in IE Insp Rept 50-302/00-10 corrective action results of 11 nuclear grade review committee meetings held during 1978 into/field & document control program altered
HAWKINS, J A Florida Power Corp 00/04/11 3pp
- 0004100757 Responds to IE Bulletin 00-05, "Evan of Containment Liner Penetration Welds" No "Fixed head" design or design illustrated in ASME Boiler & Pressure Vessel 1974 Code, Minion 1970 addenda, Figure 1E-1300 are used
GUTHRIE, P Y Florida Power Corp 00/04/12 1p
- 0004100758 Forwards response to IE Bulletin 00-06, "Engineered Safety Features (ESF) Heat Controls" Surveillance Procedure SW-417 has been modified to demonstrate that ESF equipment remains in emergency mode upon removal of actuating signal
GUTHRIE, P Y Florida Power Corp 00/04/12 12pp
- 0004100765 Forwards response to IE Bulletin 00-05, "Vacuum Condition Resulting in Damage to Chemical Vent Control Sys Holdup Tanks" All age reviewed to identify leaks which can receive gas leakage & to verify potential sealing problem
GUTHRIE, P Y Florida Power Corp 00/04/17 4pp
- 0004100770 Forwards response to IE Bulletin 00-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environment" Secondary age leakage during review caused some age radioactivity
GUTHRIE, P Y Florida Power Corp 00/04/20 4pp
- R Periodic operating reports & related correspondence
- 0004100787 Forwards monthly operating report for May 1980
GUTHRIE, P Y Florida Power Corp 00/04/10 1p
- 0004100821 Monthly operating report for May 1980
GUTHRIE, P Y Florida Power Corp 00/06/02 3pp
- S Reportable occurrences, IEIS & related correspondence
- 0004100878 Forwards draft for use in responding to request for info re Feb 1980 accident
HAWKINS, J A Florida Power Corp 00/04/16 3pp
- 0004040343 PW-11-00-005 on 000018-01 potential leaks found on 24 central rod driven seal tube to Reactor vessel Flange connections Reseals replaced Repair actions being advocated until full issue process reaches State of FL resolved
GUTHRIE, P Y, GUTHER, T Region 2, Atlanta, Office of the Director 00/05/16 1p
- 0004040354 PW-11-00-006 on 000018-01 contaminated yellow trash bag affixed up/reactive shifter was found in waste lumber
Lead Survey revealed two similar bags in dump bags removed & dump burning performed Investigation underway
O'BRYEN, B J, GUTHRIE, T Region 2, Atlanta, Office of the Director 00/05/16 1p

0004050406 Forward LER 80-019/04T-0
HAWKES, J. A. Florida Power Corp. 00/06/20 1p

0004050404 Forward LER 79-076/01T-1
HAWKES, J. A. Florida Power Corp. 00/06/20 1p

--0004050403 LER 79-074/01T-1 on 790017 & 22, reported that unplanned release of radioactive liquid was discharged to settling pond, contrary to RTR. Caused by penetrational deficiency. Liquid was inadvertently released by pump pump automatic activation. LANCASTER, K. F. Florida Power Corp. 00/06/20 2pp

0004050404 Forward LER 80-020/04L-0 on 000520, straggled threads & galled threads were identified on nut rings. Exam will determine galling extent. Corrective actions will extend outage. Unit issued stress release. HAWKES, J. A. Florida Power Corp. 00/06/20 1p

0004050506 Forward supplemental LER 79-084/03L-1
HAWKES, J. A. Florida Power Corp. 00/06/24 1p

--0004050401 Supplemental LER 79-086/03L-1 on 790018, channel D reactor bldg high pressure bistable tripped. Caused by corrosion. Building on reactor bldg pressure switch. Switch was released & returned to auto. LANCASTER, K. F. Florida Power Corp. 00/06/17 2pp

0004050503 Forward LER 80-019/04T-0
HAWKES, J. A. Florida Power Corp. 00/05/29 1p

DOCKET 80-030 210N NUCLEAR POWER STATION, UNIT 2
F. Security, medical, emergency & fire protection plans

--0004050504 LER 80-019/04T-0 on 000517, crack indication discovered during loop of fuel assembly. HJ38E upper and flanking hold-down spring investigation of cause underway. When determined, report w/corrective actions will be sent. LANCASTER, K. F. Florida Power Corp. 00/05/23 2pp

0004050493 Forward LER 80-021/03L-0
HAWKES, J. A. Florida Power Corp. 00/05/29 1p

0004050502 Responds that FEMA review of state & local emergency plan is provided consistent w/req. schedule to avoid potential delays in licensing decisions. HAWKES, J. F. Commission. 00/05/13 2pp

--0004050500 LER 80-021/03L-0 on 000516, during loop of feedwater swing-disc check valve FW-43, valve hinge pin was discovered missing. Caused by deficiency during initial assembly of valve by manufacturer. Valve is being repaired. LANCASTER, K. F. Florida Power Corp. 00/05/23 2pp

0004050407 Forward proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790010." Rule added new Section 50.40 & 49.40 to 10CFR50 & is expected to be published in FR by end of May. HAWKES, J. F. Division of Licensing. 00/05/17 4pp

0004050505 Forward LER 80-020/03L-0
HAWKES, J. A. Florida Power Corp. 00/05/29 1p

0004050408 Forward revised Pages 1-14 & new Page 14e for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790010," transmitted by NRC 000510. 14r Page 14a not sent. HAWKES, J. F. Division of Licensing. 00/05/22 7pp

--0004050508 LER 80-020/03L-0 on 000501, during review of surveillance procedures, discovered that procedure for weekly battery check SP-510 was not performed for wk of 000406. Caused by damaged hydrotester used to perform surveillance. LANCASTER, K. F. Florida Power Corp. 00/05/23 2pp

0004050501 Forward deficiency report re extensive cracking in valve disc on air valves.
HAWKES, J. A. Florida Power Corp. 00/05/30 1p

0004050509 Advises that NRC review of 000504 safeguards contingency plan indicates need for add'l revisions. Specific comments withheld (ref 000702 790). HAWKES, J. A. Operating Reactors Branch. 00/05/27 2pp

--0004050504 Deficiency report re extensive cracking in valve disc on air valves mfg by Dresser Industries. Corrective action is being determined by manufacturer & will be accomplished prior to restart. Florida Power Corp. 00/05/30 1p

0004050504 Forward add'l fire protection info on app'l to 000403. 14r re safe shutdown analysis which takes plant to cold shutdown. Add'l info provides for taking plant to cold shutdown. PROPLED, D. L. Commonwealth Edison Co. 00/05/30 1p

0004050509 Comments on 80 report to Congress for fiscal quarter 0590. Requests change of wording re ballast cooling pump. MICHELS, S. C. Director's Office. 00/06/04 1p

0004050503 Forward Revision 1 to draft emergency plan. Emergency plan station annex also sent. PROPLED, D. L. Commonwealth Edison Co. 00/06/04 2pp

0004050508 Part 21 report revising 000500 report re cracking of disc guides of air main steam safety valves mfg by Dresser Industries. Correct valve type is 3070M. Corrective action is being determined. HAWKES, J. A. Florida Power Corp. 00/06/03 2pp

--0004050504 Draft emergency plan annex
+ Commonwealth Edison Co. 00/07/31 37pp

0004050508 Forward LER 80-022/04L-0
HAWKES, J. A. Florida Power Corp. 00/06/04 1p

--0004050507 Revision 1 to draft emergency plan
+ Commonwealth Edison Co. 00/07/31 137pp

--0005010104 LER 80-022/04L-0 on 000508, samples not obtained for Apr from test wells 1 & 4. 6 pit results not reported for waste water tanks. Tank well 10-10 discharge canal. Caused by elimination of tank well sites due to canal mod & loss of pit data. LANCASTER, K. F. Florida Power Corp. 00/05/30 2pp

0004050504 Responds to NRC 890425, 30, 0001, 09 & 30 list requesting add'l info re guard training & qualification plans. Requests that response submittal date be extended to 000504. PROPLED, D. L. Commonwealth Edison Co. 00/06/10 1p

0004050506 Forward LER 80-023/03L-0
HAWKES, J. A. Florida Power Corp. 00/06/12 1p

§ Adjudicatory correspondence

--0004050403 LER 80-023/03L-0 on 000517, radioactive mail in form of bagged contaminated waste & poly wrapped scrap lumber was taken to site dump. Caused by apparent communication problem between health physics personnel & bldg servicers. LANCASTER, K. F. Florida Power Corp. 00/06/04 2pp

0004050503 Forward all affidavits of TR Team & RE Shannon describing planned minor changes in spent fuel rack replacement job procedures. Changes relate to inventory equipment an appeal. Related correspondence. STEPTOE, P. Brian Lincoln & Seale. 00/05/03 2pp

0004050509 Forward LER 80-024/04L-0
HAWKES, J. A. Florida Power Corp. 00/06/19 1p

--0004050402 Affidavit recommending that penetrant test exam per unit Procedure 0001-01 be substituted for ultrasonic test exam technique in spent fuel pit corrosion surveillance program. HAWKES, J. E. Commonwealth Edison Co. 00/06/23 7pp

--0004050406 LER 80-024/04L-0 on 000520, discovered that 1-101 channel cartidges for wk ending 000401 was inadvertently discarded. Caused by personnel error. Responsible personnel were instructed on proper procedure. LANCASTER, K. F. Florida Power Corp. 00/06/19 2pp

--0004050403 "Liquid Penetrant Exam"
+ Commonwealth Edison Co. 78/12/06. 13pp.

--0004050406 Affidavit describing decontamination techniques that will be employed in spent fuel rack replacement jobs to reduce total vol of radioactive waste. TRAPP, T. R. Commonwealth Edison Co. 00/06/08 2pp.

DOCKETED ITEMS

- 0006170018 Brief in support of AGLD 000214 initial decision authorizing suspension of new reactor for which intervenor filed 10 exceptions. Intervenor offered no reason to support alleged errors on decision.
STEPHEN P. P. WILLIAM, H. J. Commonwealth Edison Co STEPHEN P. P. William, Lincoln & Deale 00/05/05 4pp
- 0006140037 Discusses C. Oberg for to NRC requesting stay in proceedings re proposed amend to increase spent fuel storage capacity. Oberg anticipates inaccurate AGLD. Would like adequate design & safety features preclude loss-of-coolant accident.
STEPHEN P. P. William, Lincoln & Deale 00/05/12 2pp
- 0006140034 Order for 0006708 oral argument in NRC Public Hearing Room, Bethesda, MD One hour of argument & rebuttal will be granted to each party.
STEPHEN P. P. WILLIAM, H. J. Atomic Safety and Licensing Appeal Panel 00/03/23 1p
- 0005190010 Responds to 000505 objection to scheduling meetings outside Washington, DC area. Meetings are occasionally held outside of Washington, DC in order to allow persons living near plants opportunity to attend.
EISENBERG, B. S. Division of Licensing 00/06/02 3pp
- 0006260014 Ack receipt of 000497 petition requesting NRC to suspend license amend permitting reacting & completion of facility fuel pool. Petitioner has evidence from Sales Unit 2 of Washington, DC regarding the petition to suspend license amend for reacting & completion of fuel pool. Petitioner has add evidence for review.
DEWITT, H. R. Office of Nuclear Reactor Regulation, Director 00/06/13 1p
- 0006260014 PR notice of request for action under 10CFR 2.204 re Petition to suspend license amend for reacting & completion of fuel pool. Petitioner has add evidence for review.
DEWITT, H. R. Office of Nuclear Reactor Regulation, Director 00/06/13 1p
- H General correspondence
- 0006140014 Requests public debate re evacuating large populations near power plants. Opposes plants located in densely populated areas.
HARRIS, N. Affiliation Unknown 00/03/19 1p
- P. Operating license change documents & correspondence
- 0006140048 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site. Also directed for use during emergencies to link all power plants & NRC. Emergency Notification Sys hotline will also be used.
EISENBERG, B. S. Region 3, Chicago, Office of the Director, 00/04/10 2pp
- 0006140028 Comments on petition for releasing Site Unit 2 in poor place to experiment w/reactor fuel due to population density within 20-mile radius of radioactive waste.
DEWITT, H. R. Affiliation Unknown 00/03/07 3pp
- 0006140016 Forwards add TH-2 related requirements to operating reactor license requirements for TH Action Plan include shifts, meetings, licensing, safety & license dissemination of operating procedures. Response requested within 30 days.
EISENBERG, B. S. Division of Licensing 00/05/07 12pp
- 0006140002 Notification of 000520 meeting w/ utility, contractors & consultants in Bethesda, MD to exchange technology re accident sequences & related phenomena per A. Schreiber.
LORIN, J. H. Reactor Systems Branch 00/05/15 3pp
- 0006130126 Requests comments on NUREG-0593, "Potential for Low Pressure Turbines in Landfill Treatment on MSR Bypass Generator & Reactor Coolant Pump Systems." Proposed review procedure & implementation schedule encl.
EISENBERG, B. S. Division of Licensing 00/05/15 72pp
- 0006130171 Forwards request for add items required to complete upgrade review of 04 program. Response should be provided along w/response to 000408 request.
WARRICK, J. A. Operating Reactors Branch 00/05/20 4pp
- 0006120097 Notification of 000605 meeting w/ utility in Bethesda, MD to discuss upgraded 04 program.
WARRICK, J. A. Quality Assurance Branch 00/05/21 3pp
- 0006120172 Notification of 000606 meeting w/ utility in Bethesda, MD re severe accident mitigation features for facilities.
LORIN, J. H. Operating Reactors Branch 00/05/23 1p
- 0006100493 Notification of 000603 meeting w/ utility in Bethesda, MD to discuss filtered vented containment sys & core retention devices.
FEDERLE, D. L. Reactor Systems Branch 00/05/27 3pp
- 0006140057 Forwards revised Tech Spec Pages 94, 320a, 79 & 80 issued w/ Comments 24 & 25 to Licensee DPH-29 & DPH-40, respectively.
WARRICK, J. A. Operating Reactors Branch 00/05/29 2pp
- 0006140040 Corrected Pages 94, 320a, 79 & 80 to Amends 31 & 34 to Licensee DPH-29 & DPH-40, respectively.
Operating Reactors Branch 00/05/29 4pp
- 0006140037 Update to 000624 application to amend Licensee DPH-29 & DPH-40, incorporating administrative changes to App A-Tech Spec.
FEDERLE, D. L. Commonwealth Edison Co 00/05/30 2pp
- 0006140024 Revised Page 300 to App A, Tech Specs & C for administrative controls. Allow either rad-then supervisor or lead health physicist to fulfill qualifications of radiation protection manager.
Commonwealth Edison Co 00/05/30 3pp
- 0006140024 Application for amend to Licensee DPH-29 & DPH-40, modifying allowed outage time per 000529 confinement order. Combined Class 1 & 311 Fee encl.
WARRICK, J. A. Commonwealth Edison Co 00/06/03 3pp
- 0006140038 Forwards response to NRC 000506 request for history of total & partial power outages & attendant degraded voltage. No complete loss of offsite power has occurred, but one partial loss incident was reported to NRC.
WARRICK, J. A. Commonwealth Edison Co 00/06/05 2pp
- 0006140044 Forwards slides used by utility during 000603 meeting re technology exchange in area of mitigation features for severe accidents at facilities.
WARRICK, J. A. Westinghouse Electric Corp 00/06/03 1p
- 0006170151 Forwards "Mitigation of Severe Accident Study Rept." Rept includes presentations made to NRC & AGND on 000620 & 000625, respectively, & consists of state-of-the-art analyses conducted within 60-day period.
CAGILL, N. J. Consolidated Edison Co of New York 00/06/05 3pp
- 0006170459 Response to 000588 re transmitting rept covering work performed by various consultants. Entire Washington rept retransmitted.
FEDERLE, D. L. Commonwealth Edison Co 00/06/09 3pp
- 0006170465 "Mitigation of Severe Accident Study Rept." consisting of rept on evaluation of residual risk, steam explosions, containment response for Class V accidents & post-accident containment vent sys conceptual design.
Westinghouse Electric Corp 00/06/09 42pp
- 0006130165 Forwards check inadvertently left off package submitted on 000623 w/ re encl.
FEDERLE, D. L. Commonwealth Edison Co 00/06/06 1p
- 0006140071 Forwards response to NRC Questions 2B - 40 re facility 04 program per 000408 & 00020 requests.
FEDERLE, D. L. Commonwealth Edison Co 00/06/09 13pp
- 0006190307 Forwards comments to comply w/requirements & schedule in NRC 000507 1st re add TH-2 related requirements. Dresden Unit 1 is currently undergoing extensive mod & reconstruction therefore no response is provided.
FEDERLE, D. L. Commonwealth Edison Co 00/06/12 10pp
- 0006270047 Summary of 000520 Technology Exchange Meeting 3 w/utility in Bethesda, MD re accident mitigation features for facilities.
LORIN, J. H. Reactor Systems Branch 00/06/12 27pp
- 0006250080 Notification of 000610 meeting w/ utility, contractors & consultants in Bethesda, MD for presentation in area of comments contained sequences for facilities. Agenda encl.
WARRICK, J. A. Reactor Systems Branch 00/06/16 3pp
- 0006140025 Notification of 000607 meeting w/ utility & consultants in Bethesda, MD to discuss technology exchange re containment structural response, failure pressure & failure modes.
FEDERLE, D. L. Reactor Systems Branch 00/06/17 3pp

DOCKETED ITEMS

99

- 0004300207 Requests reevaluation of original proposal for submitting schedule for implementing AMS instrumentation nodes identified in NUREG-0440 Revised schedule & justification should be submitted in 30 days
VARMA, S A Operating Reactors Branch 1 00/06/19 App
- 0004700306 Forwards revised Revision 11 & 12 consisting of Page 1-7 of 0004300207
0004300207 "Comm Co 04 Program for Nuclear Generating Stations" Revised Revision 11 includes basis on which equivalent education requirements will be established
PODLES, D L Commonwealth Edison Co 00/06/20 1p
- 0004700307 Forwards response to ABC 000402 questions on adequacy of station electric distribution sys voltage level but voltage when starting largest non-Class 1E load was established when all other loads were running Motor started
MAGNITON, M F Commonwealth Edison Co 00/06/20 App
- 0 Inspection reports, IE Bulletin 5 correspondence
0004700307 Forwards IE Insp Rpts 90-295/80-02 & 90-304/80-02 on 000207-0208 & notice of violation
HEIDMANN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/06 App
- 0004700307 Notice of violation from Insp on 000607-0208
Region 3, Chicago, Office of the Director 00/04/18 1p
- 0004700308 IE Insp Rpts 90-295/80-02 & 90-304/80-02 on 000207-0208
Noncompliance noted min shutdown margin requirements while in cold shutdown mode below Tech Spec limits
NOLLEN, J F, LITTLE, W S Region 3, Chicago, Office of the Director 00/04/18 App
- 0004700309 Forwards IE Insp Rpts 90-295/80-04 & 90-304/80-05 on 000210-11 & 0917-18 No noncompliance noted
HEIDMANN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/30 App
- 0004700309 IE Insp Rpts 90-295/80-06 & 90-304/80-06 on 000310-31 & 0417-18 No noncompliance noted Major areas inspected small areas LOCA procedure
NOLLEN, J F, LITTLE, W S Region 3, Chicago, Office of the Director 00/04/30 App
- 0004700309 Forwards IE Insp Rpts 90-295/80-04 & 90-304/80-05 on 000310-31 & 0417-18 No noncompliance noted
HEIDMANN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/30 App
- 0004700309 IE Insp Rpts 90-295/80-04 & 90-304/80-05 on 000310-31 & 0417-18 No noncompliance noted
HEIDMANN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/04/30 App
- 0004700309 Forwards IE Insp Rpts 90-295/80-07 & 90-304/80-06 on 000414-30 No noncompliance noted
HEIDMANN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/05/12 App
- 0004700307 IE Insp Rpts 90-295/80-07 & 90-304/80-06 on 000414-30 No noncompliance noted Region areas inspected license actions in compliance with 000329 corrective order
LITTLE, W S, NOLLEN, J F Region 3, Chicago, Office of the Director 00/05/12 App
- 0004700306 add response to PSDA request for six categories of documents re CPC Forwards documents listed in app
FELTON, J H Division of Rules and Records 00/05/23 App.
- 0004700309 Forwards response to updated memo received on 000310 re all interrogatories re proposed imposition of civil penalties
Grove street of IE Insp rept 0001
NOLLEN, J F Region 3, Chicago, Office of the Director 00/05/21 App
- 0004700309 Discusses three safety-related events occurring at facility
Civil penalty for noncompliance items will be imposed
Forwards notice of violation notice of proposed imposition of civil penalties & history of enforcement action
VANDERBILT, D Office of Inspection & Enforcement, Office of the Director 77/09/30 App
- 0004700304 Notice of violation from Insp on 770209-08, 14, 15 & 21
Office of Inspection & Enforcement, Office of the Director, 77/09/30 App
- 0004700308 Notice of proposed imposition of civil penalties in amount of \$21,000 re noncompliance observed during Insp on 770209-08, 14, 15 & 21 History of escalated enforcement action
0001
Office of Inspection & Enforcement, Office of the Director 77/09/30 App
- 0004700306 Immediate action for re IE physical security Insp on 000310-31 & 19-20 License is expected to undertake actions outlined in ENCL ENCL withheld (ref 000310-31)
NOLLEN, J F Region 3, Chicago, Office of the Director 00/05/23 1p
- 0004700307 Advises that responses to IE Bulletin 79-04a/Revision 1, were found acceptable Evaluation met
VARMA, S A Operating Reactors Branch 1 00/05/20 17pp
- 0004700308 Forwards response to IE Bulletin 80-04, "Engineered Safety Features (ESF) Reset Controls" Proposed mode identified only if present sys design was comprehensive protective action of equipment
PODLES, D L Commonwealth Edison Co 00/05/10 App
- 0 Reportable occurrences, LERs & related correspondence
0004700307 PNO-111-80-04 on 000515, license reported that cracks had been found in A & C sections of low pressure turbine Section A will be replaced with new turbine
NOLLEN, J F, LITTLE, W S Region 3, Chicago, Office of the Director 00/05/16 1p
- 0004700309 PNO-111-80-04 on 000516, crack was discovered in keypad of Gise 1 at generator end of C section low pressure turbine section turbine will be replaced & G section will be examined as of 000519
NOLLEN, J F, LITTLE, W S Region 3, Chicago, Office of the Director 00/05/19 1p
- 0004700309 Forwards LER 90-019/03L-0
NOLLEN, J F Commonwealth Edison Co 00/05/27 1p
- 0004700309 LER 90-019/03L-0 on 000487, during safeguards activation test, 2A containment spray pump stop valve 200V-CB0202 failed to close. Caused by malfunction of torque switch New torque switch installed
GARCIA, E Commonwealth Edison Co 00/05/27 1p
- 0004700309 Forwards LER 90-020/03L-0
NOLLEN, J F Commonwealth Edison Co 00/06/03 1p
- 0004700309 LER 90-020/03L-0 on 000507, maint personnel found steam generator 2A pressure channel 2F-316 low by 2.05, exceeding channel actuator caused by instrument drift of transmitter. Transmitter recalibrated
NOLLEN, J F Commonwealth Edison Co 00/06/03 1p
- DOCKET 90-308 KANANIS NUCLEAR POWER PLANT
F Security, medical, emergency & fire protection plans
0004700307 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC. Emergency Notification Sys bulletin will also be used
NOLLEN, J F Region 3, Chicago, Office of the Director 00/04/18 App
- 0004700407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101". Rule adds new Section 30-40 & App R to 10CFR50 & is expected to be published in FR by end of May
EISENHUT, D Division of Licensing 00/05/19 46pp
- 0004700403 Forwards revised Pages 1-10 & new Page 16 for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101", transmitted by NRC 000519
the Page 16 not sent
EISENHUT, D Division of Licensing 00/05/20 73pp
- P. Operating license stage documents & correspondence
0004700403 Forwards added TH-0 & related requirements to operating license stage documents for TH-0 Action Plan. Includes added forwarding, licensing stage & license dissemination of operating emergency Response requested within 30 days
EISENHUT, D Division of Licensing 00/05/27 136pp

DOCKETED ITEMS

0004040588 Ask receipt of 800414 for Confirmation until intent to proceed
 after release for Cycle 4 & that "Release Safety
 Evaluation/Review Cycle 4" has been filed
 WMS&B & A Operating Reactors Branch 1 80/05/09 1p

0004120012 Requests comments on NUREG-0577, "Potential for Low Fracture
 Toughness & Laminar Flowing on PWR Steam Generator &
 Reactor Coolant Pump Supports" Proposed review procedure &
 implementation schedule only
 EISENHART, D Division of Licensing 80/05/19 7pp

0004120014 Summary of 800428 meeting until no planned addition of
 restraints to primary coolant loop to limit & support LOCA
 loads Restructurable loop used designed to carry max loads of
 3000 kips satisfactorily for cold leg
 LICCINRMS, R Operating Reactors Branch 1 80/05/23 4pp

0004240029 Confirm distribution of info to PWR & BWR to assist in
 technical evaluation of electrical instrumentation & control
 design aspects of overdrive containment purge valve isolation
 & other engineered safety feature signals
 LICCINRMS, R Operating Reactors Branch 1 80/05/25 1p

0004170426 Informs NRC of proposed need to limit containment purge &
 vent valve opening to 10 degrees until full pressurizing of
 containment that NRC authors unless informed to contrary by
 800412
 HATHWELL, E Wisconsin Public Service Corp 80/05/11 2pp

0004280443 Responds to concerns re maintenance operation of
 containment purge & vent valves under LOCA conditions
 blocking devices installed to limit opening of valves
 Discusses basis for need
 HATHWELL, E Wisconsin Public Service Corp 80/05/19 2pp

6 Inspection reports, IE Bulletin & correspondence

0004200099 Forwards IE Insp Rept 80-005-00-06 on 800420-04
 No noncompliance noted
 HATHWELL, E P Region 3, Chicago, Reactor Operations Nuclear Support
 Branch 80/05/12 2pp

0004200097 IE Insp Rept 80-035-00-06 on 800421-24 No noncompliance
 noted Major areas inspected plant operations IE Bulletin &
 circular Follow-up fine protection/prevention program &
 nonroutine events
 HATHWELL, E P Region 3, Chicago, Office of the
 Director 80/05/09 4pp

0004200066 Forwards IE Insp Rept 80-005-00-06 on 800326-00 & notice
 of deviation
 HATHWELL, E P Region 3, Chicago, Reactor Operations Nuclear Support
 Branch 80/05/20 2pp

0004200068 Notice of deviation from Insp on 800326-00
 & Region 3, Chicago, Office of the Director 80/05/19 1p

0004200077 IE Insp Rept 80-005-00-06 on 800329-20 Noncompliance noted
 Failure to implement approved Westinghouse guidelines
 EISENHART, D P Region 3, Chicago, Office of the
 Director 80/05/19 2pp

0004200074 Responds to IE Bulletin 80-03 Review of schematic & logic
 diagrams for all applicable components involving safety-
 related functions verified that components will remain in
 emergency mode following emergency safety feature reset
 HATHWELL, E Wisconsin Public Service Corp 80/05/17 2pp

0004200188 Responds to IE Bulletin 80-12 re decay heat removal sys
 operability One loss of decay heat removal incident occurred in
 Dept 1974 Operating procedures have been reviewed for
 safeguarding against loss of RHR capability
 HATHWELL, E Wisconsin Public Service Corp 80/06/20 4pp

8 Periodic operating reports & related correspondence

0004160076 Forwards monthly operating report for May 1980
 HATHWELL, E Wisconsin Public Service Corp 80/06/09 1p

0004160097 Monthly operating report for May 1980
 RUTER, S H Wisconsin Public Service Corp 80/06/02 4pp

9 Reportable occurrences, LERs & related correspondence

0004200414 Forwards LERs 80-023/03L-0 & 80-023/03L-0
 HATHWELL, E Wisconsin Public Service Corp 80/06/14 1p

0004200419 LER 80-023/03L-0 on 800519 during refueling outage,
 pressurizer pressure transmitter fused out of calibration
 MALEPA, J D Wisconsin Public Service Corp 80/06/10 1p

0004200473 LER 80-023/03L-0 on 800507 during refueling outage, channel
 of steam line isolation val failed out of calibration
 Instrument drift instrument reliability
 MALEPA, J D Wisconsin Public Service Corp 80/06/25 1p

DOCKET 30-006 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency A fire protection plans

0004000201 Notice that new telephone sys called Health Physics
 Network (HPN) has been installed at site NRC intends for
 use during emergency to link all power plants & NRC
 Emergency Notification Sys hotline unit also be used
 HATHWELL, D Region 3, Chicago, Office of the Director 80/04/18
 2pp

0004000487 Forwards proposed rule entitled, "Fire Protection Program
 for Nuclear Power Plants Operating Prior to 1970" Rule
 effective under Section 50.48 & App 9 to 10CFR50.5 is expected
 to be published in FR by end of May
 EISENHART, D Division of Licensing 80/05/19 4pp

0004130043 Forwards revised Pages 1-4 & new Page 10a for proposed
 rule 10CFR50 "Fire Protection Program for Nuclear Power
 Plants Operating Prior to 1970", transmitted by NRC 800519
 1p Page 10a not sent
 EISENHART, D Division of Licensing 80/05/02 7pp

0004070028 Forwards revised Page 1 omitted from 800910 Revision 1 to
 outline force training & qualification plan ENR withheld
 (per 10CFR2.790)
 HATHWELL, D Northern States Power Co 80/05/27 1p

0004170028 Receipt of proposed IE contractor review of emergency
 operating procedures on 800509-13 Data will be used to
 provide composite picture of emergency procedures & will not
 result in issue of noncompliance
 HATHWELL, E P Region 3, Chicago, Reactor Operations Nuclear Support
 Branch 80/05/23 2pp

0004200037 Discusses substantial of final upgraded emergency plans
 Extension may be necessary depending on content of pending
 NRC rules on emergency plans Schedule for emergency plan
 revision targeted to meet 800501 submittal date
 HATHWELL, D Northern States Power Co 80/05/17 1p

6 Adjudicatory correspondence

0004200046 Advises that State of NY 800426 commitments are being sent
 for scheduling NRC will be prepared to discuss hearing
 schedule & state commitments during July 1979 prehearing
 conference in St Paul, MN
 EARTH, C A Hearing Branch 2 80/05/19 1p

0004000419 Notice & order for 800048 prehearing conference in St
 Paul, MN re State of NY 800426 petition to
 intervene in O. amend proceedings License & NRC shall file
 responses to intervention petition by 800703
 LADON, R Atomic Safety and Licensing Board Panel 80/06/25 2pp

P Operating license stage documents & correspondence

0004180011 Examining study of Prairie Island Nuclear Operating
 Plant, Revision 1
 JAMESBY, J Nuclear Energy Service, Inc 81/06/23 R1 7/9/82
 47pp

0004000165 Forwards add TH1-2 related requirements to operating
 reactors Licensee requirements for TH1 Action Plan include
 shift training, licensing exam & license dissemination
 of operating experience Response requested within 30 days
 EISENHART, D Division of Licensing 80/05/27 150pp

0004130123 Requests comments on NUREG-0577, "Potential for Low Fracture
 Toughness & Laminar Flowing on PWR Steam Generator &
 Reactor Coolant Pump Supports" Proposed review procedure &
 implementation schedule only
 EISENHART, D Division of Licensing 80/06/19 7pp

0004200044 Forwards safety evaluation re degraded grid voltage
 protection for Class IE at power up & LLL re: supporting
 mod design mod & Tech Data changes acceptable
 RORR, F Power Systems Branch 80/05/02 1p

DOCKETED ITEMS

101

--0004200046 Safety evaluation supporting proposed Mode & Tech Spec changes re protection of Class IE equipment & sys from sustained negative voltage
A. Power Station Branch 00/05/02 2pp

--0004200050 Technical Evaluation of Proposed Design Mode & Tech Spec changes on Grid Voltage Degradation for Prairie Island Nuclear Generating Plant Units 1 & 2
HITTE, R. L. Lawrence Livermore Laboratory FIN A-0031
UCIS-16A54 00/05/01 15pp

0004200400 Forwards info re implementation of 10CFR50 App J containment penetration testing requirements per 800311 request
HAYES, L. D. Northern States Power Co 00/05/00 8pp

0004200406 Forwards addl info on support of 800311 license amend request in response to NRC questionnaires cover design water sys, structural, chemical, radiological, radiological, safety/procedures & rack disposal
HAYES, L. D. Northern States Power Co 00/06/10 20pp

0004200412 Responds to 000402 memo by submitting list of decommission & applicable comments on facilities purge & vent valves
long-term mechanical operability facilities meet industry position
HARTIN, R. Operating Reactors Branch 3 00/06/10 2pp

0004200509 Forwards listed drawings to enable continuation of review of generic issue. Primary coolant gas pressure isolation
Valves (Events 3) & info sent
HARTIN, R. E. Operating Reactors Branch 3 00/06/10 2pp

0004200737 Forwards response to NRC 800507 ltr on addl TMI-2 requirements re shift training, licensing exam, operating experience feedback, Bulletin & Orders Task Force recommendations & control room habitability
HAYES, L. D. Northern States Power Co 00/06/11 14pp

B Inspection reports: IE Bulletin & correspondence

0004200738 Forwards IE Insp Rpts 90-282/00-05 & 90-306/00-06 on 800301-31 No noncompliance noted
HEDRMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/04 2pp

--0004200752 IE Insp Rpts 90-282/00-05 & 90-306/00-06 on 800301-31 No noncompliance noted
Major areas inspected plant operation, main following of LERS, & review of license small break LOCA procedures
PESERAKOS, C. J., DANSON, E. R. Region 3, Chicago, Office of the Director
HEDRMAN, R. F., Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/18 2pp

0004200800 Responds to IE Bulletin 79-01, Revision 1, Item & Visual trap self-indicator completed on Unit 1 in Apr 1980 No corrective action necessary
GILBERT, D. E. Northern States Power Co 00/05/06 1p

0004200836 Forwards nonproprietary version of IE Insp Rpts 90-282/00-07 & 90-306/00-07 on 800408-0002 Notice of violation withheld (ref 10CFR 7901)
HEDRMAN, R. F. Region 3, Chicago, Safeguards Branch NRC 00/06/02 2pp

--8004200844 Nonproprietary version of IE Insp Rpts 90-282/00-07 & 90-306/00-07 on 800408-0002 Noncompliance noted some vital area physical barriers not maintained & alarm devices not tamper-indicating details withheld (ref 10CFR 7901)
HEDRMAN, R. F., Region 3, Chicago, Safeguards Branch NRC 00/06/02 2pp

0004200876 Addl response to FOIA request for six categories of documents re GPS Forwards documents listed in app
FELT, J. M. Division of Rules and Records 00/01/02 3pp

--8004200899 Forwards response to updated memo received on 800313 re utility self-regulator re proposed imposition of civil penalty.
Cover sheet of IE Insp rpt sent.
REFFLER, J. O. Region 3, Chicago, Office of the Director 00/03/01 8pp

--8004201012 Excerpt of IE Insp Rpts 90-282/79-01 & 90-306/79-01 conducted on 750294-06 & 10-10 Noncompliance noted, design changes were not prepared & not implemented in accordance w/ license administrative control directives
HOLMES, N. C., HARTER, D. R. Region 3, Chicago, Office of the Director
JEROME, R. J. Region 3, Chicago, Reactor Operations Nuclear Support Branch 73/03/28 3pp

0004200890 Reviews response to IE Bulletin 79-01: "Devlin Classification of Class IE Equipment" Forwards sys component evaluation worksheet on Kavita Cable Revision & replacing worksheet sent to 800312 response
GILBERT, D. E. Northern States Power Co 00/05/02 2pp

0004200908 Responds to IE Bulletin 80-10, "Decont Heat Removal Sys Operational" - Operating procedure for reactor refueling (curry Flooded) will require use train of RW available w/ accessible source of heated water to establish any lost
GILBERT, D. E. Northern States Power Co 00/06/06 2pp

B Periodic operating reports & related correspondence

0004200948 Forwards monthly operating rpts for May 1980 & corrected page to Apr 1980 monthly operating rpts
HAYES, L. D. Northern States Power Co 00/06/10 1p

--0004200951 Monthly operating reports for May 1980
HARTIN, R. A. Northern States Power Co 00/06/01 8pp

--0004200952 Monthly operating reports Apr 1980 corrected pages
HARTIN, R. A. Northern States Power Co 00/06/10 1p

B Reportable occurrences, LERs & related correspondence

0004200960 PWS-111-80-097 on 800319, Facility was shut down due to leakage on reactor coolant seal 2 and radiation release
Status informed No press releases planned
GARDNER, R. R., HEDRMAN, R. F. Region 3, Chicago, Office of the Director 00/05/19 1p

0004200977 Envision Event Rpt 80-01 on 800301, daily average discharge into adjacent ambient river water temp by 3.7 F while two existing basins were undergoing imp-drawing & repair One basin returned to svc & electrical load reduced
HARD, E. C. Northern States Power Co 00/03/03 1p

0004200989 Envision Event Rpt 80-02 on 800313-14, recleaning ion exchanger out of svc when steam generator blowdown water discharged into river Sample of outfall revealed pH value greater than 8 Caused by seasonal change of river
HARD, E. C. Northern States Power Co 00/06/04 2pp

0004200993 Final Part 21 rpts re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mg to ASME requirements Investigations conducted & closed at 6 listed facilities
BEATY, J. L. Centron Corp - Tulsa Term Div 00/06/06 2pp

0004200999 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

8004200948 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule under Section 50.40 & App B to 10CFR50 is expected to be published to FR by end of May
EISENHART, D. C. Division of Licensing 00/05/19 4pp

0004200963 Forwards revised Pages 1-3 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmittal by NRC 800504
1st Page 14a not sent.
EISENHART, D. C. Division of Licensing 00/05/02 3pp

8004200955 Recommends that FDA receive notice of decisions made at for licensing similar re use of potassium iodide for radiation emergencies Ideas will be incorporated into state contingency plan
COTTE, L. A. Maine, State of 00/06/20 1p

0004200959 Advises that 790101 changes to approved security plan are consistent w/ 10CFR50.54 provisions Plan withheld (ref 10CFR 7901)
CLARK, R. A. Operating Reactors Branch 3 00/05/29 2pp

0004200986 Informs that next revision in facility emergency plan will be submitted by 800001
HEDRMAN, R. F. Maine Yankee Atomic Power Co 00/06/18 1p

DOCKETED ITEMS

B Administrative correspondence

EC04060417 Motion for extension until 06/06/11 to respond to Bensville NE Power EC04060402 specific contentions reviewed on 06/05/11. Licensee is presently involved in various cases. Intervenor has no objection to Motion for Certificate of Dismissal. G. Bensville NE Maine Yankee Atomic Power Co. EC04060417 0
Reps: K Gray 06/05/06 2pg

EC04060501 Response to Intervenor Bensville NE Power Contentions (a) through (f) through 11 to (i) filed 5/27/11. It is noted that should be identified notice of appearance of EJ Hais on behalf of NRC & Certificate of Dismissal. 20pg
RE: Hais, J. Hearing Branch 3 06/05/11 20pg

EC04060514 Response to Bensville NE Power specific contention Object to certain contentions on grounds that spent fuel pool operation case is not forum for relicensing issues already resolved under DC license re Certificate of Dismissal. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/04/11 11pg

EC04060526 Motion to postpone first prehearing conference until 06/06/11. Licensee is presently involved in considering alternate proposals & topicizing NRC suggestion re DC incident Certificate of Dismissal. G. Bensville NE Maine Yankee Atomic Power Co. EC04060526 0
Reps: K Gray 06/04/11 2pg

H General correspondence

EC04060529 Response to EC050711 re shaping situation for nuclear power plant emergency preparedness. NRC is seeking closure w/EPMA to develop coordinated federal guidelines. Criteria for interim use outlined in NRC-050711-001. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060529 Urges that all federal guidelines re drafting preemption nuclear emergency plans for nuclear power facilities be completed & promulgated quickly. Final design requirements should ensure that all states can accomplish objectives. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060529 Forwarded until 06/06/11 & 05/29 responses to execution time estimates in 7/20/11 request. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

J Insurance & indemnity information

EC04060529 Advice of investigation into P. Blythe claim re radiation contamination when air filter separated from face mask during employment. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

P Operating license stage documents & correspondence

EC04060514 Forwarded until 06/06/11 re related requirements to operating license. Licensee is presently involved in various cases. Intervenor has no objection to Motion for Certificate of Dismissal. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Requests comments on NRC-050711, "Potential for Low Fracture Fatigue and Lateral Tearing on PWR Reactor and Reactor Coolant Pump Supports". Proposed review procedures & implementation schedule until 06/06/11. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060529 Describes proposed hydrogen monitoring system to be implemented in response to NRC 791030. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060529 Response to NRC 050588. It is requested or partial loss of off-site power means until 06/06/11. It is requested to identify set of questions contained in NRC 791127. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060529 Notification of 05/04/11 meeting w/ NRC in Bethesda, MD to discuss effects of fuel assembly loading on reactor parameters & chemical treatment for removing crud. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060514 Forwarded "End-of-Cycle & Fuel & CEA Eddy Current Insp Rept 1980 NE Yankee Refueling Outage." & "NE Yankee End-of-Cycle & Summary of Fuel Insp Results." per NRC 050507 request. Repts withheld (ref 100712 790). G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Forwarded Implementation schedule & summary status of licensee in response to NRC 050507. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Forwarded "End of Cycle & Fuel & CEA Eddy Current Insp Rept 1980 NE Yankee Refueling Outage." & "End of Cycle & Summary of Fuel Insp Results." per NRC 050507 request. Repts withheld (ref 100712 790). G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 "End of Cycle & Fuel & CEA Eddy Current Insp Rept 1980 NE Yankee Refueling Outage." & "End of Cycle & Summary of Fuel Insp Results." per NRC 050507 request. Repts withheld (ref 100712 790). G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 "End of Cycle & Fuel & CEA Eddy Current Insp Rept 1980 NE Yankee Refueling Outage." & "End of Cycle & Summary of Fuel Insp Results." per NRC 050507 request. Repts withheld (ref 100712 790). G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060529 Forwarded proposed Tech Specs Change No. 1, Rept 2 consisting of add change to the Licensee's 1980-01-01-01 administrative controls. Shop delineation efforts & plant organizational structures & titles associated with operations. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

EC04060529 Proposed Tech Specs for administrative controls. Changes more clearly delineate efforts & plant organizational structures & titles associated with each position. G. Bensville NE Maine Yankee Atomic Power Co. EC04060529 0
Reps: K Gray 06/05/11 2pg

K Inspection reports, IE Bulletin & correspondence

EC04060514 Forwarded IE Insp Rept 80-039/80-03 re 06/03/79-81. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 IE Insp Rept 80-039/80-03 re 06/03/79-81. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Act receipt of 06/04/11 re informing NRC of steps taken to correct violations noted in IE Insp Rept 80-039/80-03. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Response to NRC 050528. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Forwarded IE Insp Rept 80-039/80-03 re 06/03/79-81. It is requested that the Licensee conduct necessary evaluation of acceptability of proposed system requested. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Notice of Violation from Insp re 06/03/79-81 & 03/04/79. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 IE Insp Rept 80-039/80-03 re 06/03/79-81 & 03/04/79. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Response to IE Bulletin 80-07, "Hydrant Actuator Reliability." Determination made that no safety-related issues or concerns were identified. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Response to IE Bulletin 80-07, "Hydrant Actuator Reliability." Determination made that no safety-related issues or concerns were identified. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

EC04060514 Response to IE Bulletin 80-07, "Hydrant Actuator Reliability." Determination made that no safety-related issues or concerns were identified. G. Bensville NE Maine Yankee Atomic Power Co. EC04060514 0
Reps: K Gray 06/05/11 2pg

DOCKETED ITEMS

103

0004170705 Act receipt of 000307 ltr informing NRC of implementation of IE Bulletin 79-19 related training program
DHITHO H H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 00/03/21 1p

--0004170739 Responds to NRC 000310 ltr re questions on implementation re training requirements in IE Bulletin 79-19 & IE Insp Rept 50-309/79-19 Corrective actions training program is underway & will be fully implemented by Jul 1980
H000V.D E Maine Yankee Atomic Power Co 00/03/07 3pp

--0004170954 Forwards IE Insp Rept 50-309/79-19 on 791529 & 03 No 000310 letter noted
DHITHO H H Region I, Philadelphia, Office of the Director 00/03/13 2pp

--0004170950 IE Insp Rept 50-309/79-19 on 791529 & 03 No 000310 letter noted
DHITHO H H Region I, Philadelphia, Office of the Director 00/03/13 2pp

0004130076 addl response to PRA request for all categories of documents re OPC Forward documents listed in app
H000V.D E Division of Rules and Records 00/06/20 3pp

--0004130077 Notice of violation from Insp on 790220-29 & 1010-11
H000V.D E Region I, Philadelphia, Office of the Director 79/12/28 2pp

0004030170 Forwards Inservice Insp exam rept for 000112-0309
H000V.D E Maine Yankee Atomic Power Co 00/05/20 1p

--0004030182 Inservice Insp exam rept for 000112-0309 Describes exams performed during 1980 refueling outage
H000V.D E Maine Yankee Atomic Power Co 00/05/20 30pp

0004030043 Forwards IE Circular 80-13, "Cold Strap Damage in Westinghouse Fuel Assemblies" Re written response required
DHITHO H H Region I, Philadelphia, Office of the Director 00/05/20 1p

0004030373 Act receipt of 000403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/79-02
DHITHO H H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 00/05/28 1p

--0004030379 Responds to NRC 000407 ltr re violations noted in IE Insp Rept 50-309/79-02 Corrective actions modified Procedure C-52C, mgt, equipment & vss purchase requiring evaluation to determine whether addl procedures needed
H000V.D E Maine Yankee Atomic Power Co 00/04/23 1p

--0004030582 Act receipt of 000307 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/79-02
DHITHO H H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/07 1p

--0004030440 Responds to NRC 000321 ltr re violations noted in IE Insp Rept 50-309/79-02 Corrective actions incorporated procedure for operation of low level radwaste compactor into Health Physics Procedure W-1
H000V.D E Maine Yankee Atomic Power Co 00/03/07 2pp

--0004030446 Forwards IE Insp Rept 50-309/79-02 on 000321-23 & notice of violation
DHITHO H H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 00/02/21 2pp

--0004030491 Notice of violation from Insp on 000321-25
H000V.D E Region I, Philadelphia, Office of the Director 80/02/14 1p

--0004030492 IE Insp 50-309/79-02 on 000321-23 Noncompliance noted failure to establish/review & implement procedure for bailing machine
H000V.D E Region I, Philadelphia, Fuel Facility & Materials Safety Branch 00/02/14 2pp

0004030083 Informs that still in process of addressing IE Bulletin 79-024 Response has required diversion of engineering resources from identified safety issues
H000V.D E Maine Yankee Atomic Electric Co 00/08/29 2pp

0004030409 Discusses IE Bulletin 79-024, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Bulletin describes minor design deficiencies, rather than generic problems
H000V.D E Maine Yankee Atomic Electric Co 00/05/29 2pp

000410002 Forwards response to IE Bulletin 79-010, "Environ Qualification of Class IE Equipment" Periodic reviews will be forwarded
VANDEBUREN E C Maine Yankee Atomic Power Co 00/05/02 2pp

--000410008 "Environ Qualification of Safety-Related Electrical Equipment at Maine Yankee Atomic Power Co"
VANDEBUREN E C Maine Yankee Atomic Power Co 00/05/02 19pp

0004030110 Responds to IE Bulletin 80-12 Procedure for plant condition control provisions for blocking safety injection substation app, which automatically blocks containment spray/containment isolation & ECCS recirculation
VANDEBUREN E C Maine Yankee Atomic Power Co 00/04/09 2pp

Re periodic operating reports & related correspondence

0004030021 Forwards "Biological Monitoring Rept. 1979"
DHITHO H H Maine Yankee Atomic Power Co 00/03/27 1p

--0004030029 "Biological Monitoring Rept. 1979"
H000V.D E Maine Yankee Atomic Power Co 00/04/20 40pp

0004030300 Forwards discharge monitoring rept for Apr 1980
DHITHO H H Maine Yankee Atomic Power Co 00/05/20 2pp

--0004030309 Discharge monitoring rept for Apr 1980
VANDEBUREN E C Maine Yankee Atomic Power Co 00/05/19 2pp

0004170089 Forwards monthly operating rept for May 1980
H000V.D E Maine Yankee Atomic Power Co 00/06/12 1p

--0004170694 Monthly operating rept for May 1980
H000V.D E Maine Yankee Atomic Power Co 00/06/12 2pp

Re periodic operating reports & related correspondence

0004030333 Forwards LER 80-012/031-0
H000V.D E Maine Yankee Atomic Power Co 00/06/03 1p

--0004030387 LER 80-012/031-0 on 000403, during monthly surveillance test procedure, low power safety injection loop 3 broken stop valve failed to operate as required caused by header weld in coupling of operating extension shaft
BRINKLEY J E Maine Yankee Atomic Power Co 00/04/03 1p

0004100189 Forwards LER 80-012/031-0
H000V.D E Maine Yankee Atomic Power Co 00/06/04 1p

--0004100200 LER 80-012/031-0 on 000403, during routine power operation, auxiliary operator noticed S-schering pump was not lined up
Unlabeled degree of separation caused by personnel error
Surveillance test procedure revised
BRINKLEY J E Maine Yankee Atomic Power Co 00/04/04 1p

0004100204 On 00-014/017-0 preliminary results from vessel wall irradiated surveillance capsule indicates higher shifts than originally predicted. Followup rept will be forwarded when all data is received & evaluation made
H000V.D E Maine Yankee Atomic Power Co 00/06/04 1p

DOCKET 50-011 GALEN NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

0004100017 Forwards clarification of NRC requirements for emergency response facilities defined in 790923 ltr. Addl specific criteria for facilities under development
H000V.D E Division of Operating Reactors 00/04/20 2pp

0004100208 Requests that FEMA review of state & local emergency plan be provided consistent w/ state schedule to avoid potential delays in licensing decisions
H000V.D E Commission 00/05/13 2pp

0004190449 Informa NRC of decision to delay activation of Delaware Training Facility as a result of emergency operations facility used upon issues have been addressed satisfactorily
SCHEIDT, F W Public Service Electric & Gas Co. of New Jersey
00/05/13 1p

G Adjudicatory correspondence

0004200203 Order granting extension until 00/04/02 for Commission to select whether to review Brenner's decision 00-00-07, taken under 10CFR 2.206
CHILK, M J Office of the Secretary of the Commission 00/05/03 1p

0004200376 Forwards revised pages to Director's Decision 00-00-19 Decision issued 00/04/20 denied petition requesting certain actions re storage of spent fuel at site Corrections attached
DEITON, H R Office of Nuclear Reactor Regulation, Director
00/05/03 1p

0004200380 Advises that version of 00-00-19 signed in not version concerned as Forwards cover 10 CFR 2.206 sheet listing changes & two revisions of Director's Decision Corrections should be issued by 00/05/02
FERRARI, J P Office of the Executive Legal Director 00/05/07 5p

0004200402 Notifies that OIC of Nuclear Reactor Regulation Director's denial under 10CFR 2.206 of request re spent fuel storage is final
CHILK, M J Office of the Secretary of the Commission 00/05/09 1p

0004200509 Responds to 00/05/02 request for advance notice of activities re facility which involve NRC or State of NJ Public Serv. Commission NRC is not involved in promoting Notification request should be directed to NJ Public Serv. Commission
SHAFER, H K Office of the Executive Legal Director 00/05/06 1p

0004200567 Requests advance notice of meetings, conferences, depositions, hearings or appearances re facility involving NRC or State of NJ Public Serv. Commission Also requests all relevant correspondence & correspondence received by NRC
METTERBAHN, J J Carver, Hance & Carver 00/05/03 2pp

H General correspondence

0004200589 Responds to ltr to DOE re commission inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Facilities use water from SE River Basin
STICKLER, J Office of the Executive Director for Operations
00/05/06 4pp

0004200642 Advises that NRC 00/05/02 extension of time to consider OIC of Nuclear Reactor Regulation denial of request for stay of OI issuance has stayed Denial in final action
CHILK, M J Office of the Secretary of the Commission 00/05/10 1p

J Insurance & indemnity information

0004200697 Forwards Endorsements 31.4 & 1 to NREL Policies NF-00-XB-00 & 38-72 respectively
SCHWARTZ, A Harris & McLennan, Inc. & N & Nuclear Consultants, Inc
00/05/06 4pp

0004200707 Forwards executed Amend 1 to Indemnity Agreement 3-74, dating Jan 3 & substituting license numbers
SCHWARTZ, A Public Service Electric & Gas Co. of New Jersey
00/05/12 2pp

P Opening license stage documents & correspondence

0004200765 Forwards add TH1-2 related requirements re operating reactor Licensee requirements for TH1 Action Plan include shift meeting, licensing exams & license dissemination of operating experience Requests requested within 30 days
KIMMONT, S G Division of Licensing 00/05/07 10pp

0004201210 Requests comments on NUREG-1575, "Potential for Low Pressure Hydrogen & Low-Pressure Boiling in PWR Steam Generator & Reactor Coolant Pump Systems" Proposed review procedure & implementation schedule encl
KIMMONT, S G Division of Licensing 00/05/19 72pp

0004200304 Notifies NRC 00/05/14 request for amend to License DPR-75 re relief from Tech Spec shift marking requirements Requests received by
SCHWARTZ, F W Public Service Electric & Gas Co. of New Jersey
00/05/27 1p

0004200364 Requests that audit of installed electric gas & equipment be performed per 75C129 1st revision sample may be limited to 50 of installed equipment & cables
SCHWARTZ, A Licensing Branch 2 00/05/29 2pp

0004200397 Notification of 00/04/02 meeting w/ULI in Bethesda, MD to discuss licensee proposed engineered safety feature design for automatic shutdown from injection mode to re-injection mode
KERRIGAN, J Licensing Branch 2 00/05/03 2pp

0004200403 Forwards request for Class III amend to License DPR-75 consisting of Tech Spec changes re special test exception, position indication system shutdown section
LIMBIZI, P P Public Service Electric & Gas Co. of New Jersey
00/05/06 1p

0004200410 Requests Class III amend to License DPR-75, allowing generation of Tech Spec 3.1.3.2 position indication system shutdown during performance of red drag time measurements & cables when operable during red withdrawal
SCHWARTZ, A Public Service Electric & Gas Co. of New Jersey
00/05/06 2pp

0004200414 Revised Tech Spec for License DPR-75 re position indication system shutdown
Public Service Electric & Gas Co. of New Jersey 00/05/06 2pp

0004200450 Commits to implement NUREG-0640 re add TH1-2 related requirements per 10CFR 2.206
LIMBIZI, P P Public Service Electric & Gas Co. of New Jersey
00/05/07 1p

0004200566 Notification of 00/04/02 meeting w/ULI in Bethesda, MD to discuss licensee request for Tech Spec change on control rod position indication
KERRIGAN, J Licensing Branch 3 00/05/09 2pp

0004200587 Notifies licensee that insp ports must be installed in steam generators & Row 1 tubes must be plugged prior to startup after first refueling No info presented that potential existing near top of Row 1 U-tubes can be avoided
SCHWARTZ, A Licensing Branch 2 00/05/09 2pp

0004200603 Forwards Amend 1 to License DPR-75, safety evaluation & notice of issuance & availability
SCHWARTZ, A Licensing Branch 2 00/05/11 2pp

0004200610 Amend 1 to License DPR-75, updating limitations of Tech Spec 3.1.3.2 during performance of individual full-length rod testing & red position indication eye callin
SCHWARTZ, A Licensing Branch 2 00/05/11 2pp

0004200644 Safety evaluation supporting Amend 1 to License DPR-75
Office of Nuclear Reactor Regulation, Director 00/05/11 2pp

0004200649 Notice of issuance & availability of Amend 1 to License DPR-75
SCHWARTZ, A Licensing Branch 2 00/05/11 2pp

0004200700 Notification of 00/05/10 meeting w/ULI in Bethesda, MD to discuss auxiliary feedwater sys
KERRIGAN, J Licensing Branch 2 00/05/10 2pp

0004200708 Notification of 00/05/10 meeting w/ULI in Bethesda, MD to discuss issuance of full power license for facilities
SCHWARTZ, A Licensing Branch 1 KERRIGAN, J Licensing Branch 3 SCHWARTZ, E H Licensing Branch 2 00/05/10 4pp

Q Inspection Reports, IE Submittals & correspondence

0004200806 Forwards SE Insp Rept 50-311/80-06 an 00/02/77-80 No non-compliance noted
CARLSON, T T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/05/16 2pp

--000403090 IE Insp Repts 90-311/89-04 on 800307-08 No noncompliance noted Major areas inspected ultrasonic scan of reactor pressure vessel surface including observations & discussions of licensee
TRIMBLE, C Region 1, Philadelphia: Reactor Construction & Engineering Support Branch, HOBBS/FAITH, E A Region 1, Philadelphia: Office of the Director 80/04/14 3pp

800410050 Forwards IE Insp Repts 90-272/80-07 & 90-311/89-03 on 800308-29 No noncompliance noted
DRUMMOND, E J Region 1, Philadelphia: Reactor Operations Nuclear Support Branch 80/04/29 2pp

--000410050 IE Insp Repts 90-272/80-07 & 90-311/89-03 on 800302-29 No noncompliance noted Major areas inspected plant operations.
Pages 1 & 2: Reactor pressure vessel; small areas LSCA
80/04/29 5 previous insp items
KELNICK, R R Region 1, Philadelphia: Reactor Operations Nuclear Support Branch 80/04/29 5 Region 1, Philadelphia: Office of the Director 80/04/23 18pp

8004100123 Forwards IE Insp Repts 90-272/80-07 & 90-311/89-03 on 800308-29 No noncompliance noted
DRUMMOND, E J Region 1, Philadelphia: Reactor Operations Nuclear Support Branch 80/04/29 2pp

--0004100123 IE Insp Repts 90-272/80-07 & 90-311/89-03 on 800302-29 No noncompliance noted Major areas inspected plant operations
including Facility Security & record review; licensee events review & review of periodic tests
KELNICK, R R Region 1, Philadelphia: Office of the Director 80/04/23 18 Region 1, Philadelphia: Reactor Operations Nuclear Support Branch 80/04/23 18pp

800403009 Forwards IE Circular 80-13, "Grid Stray Damage in Bernheim Reactor Assembly." No written response required
GRIER, B H Region 1, Philadelphia: Office of the Director 80/05/20 1p

8004100231 Responds to violations noted in IE Insp Repts 90-272/80-04 & 90-311/89-01 on 800120-01; 800121-04-07 & 11-12 corrective actions master equipment list will expand existing portions of compliance requirements of SR program and comments
SCHWEDER, P M Public Service Electric & Gas Co. of New Jersey 80/04/03 8pp

800403002 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Oil Cooled Dry Helium Tanks."
Facilities have had vacuum breakers installed on helioid tanks to prevent collapse in event vacuum is generated
SCHWEDER, P M Public Service Electric & Gas Co. of New Jersey 80/04/04 1p

8004030490 Responds to IE Bulletin 80-12, "Decay Heat Removal Sys Operability." Sequence of events at Davis-Besse which resulted in automatic transfer of suction to empty containment sump will not occur at facilities
SCHWEDER, P M Public Service Electric & Gas Co. of New Jersey 80/04/09 4pp

G Reportable occurrences, LERs & related correspondence

8004040443 Forwards LER 80-001/02L-0
LIBERTE, P P Public Service Electric & Gas Co. of New Jersey 80/04/16 3pp

--8004040447 LER 80-001/02L-0 on 800500: when OL received: fire barriers were open due to recent removal of electrical cable-traps & working cables. Cause not stated. Barriers were verified sealed prior to core load
LIBERTE, P P Public Service Electric & Gas Co. of New Jersey 80/04/19 1p

8004030479 Forwards LER 80-002/03L-0
LIBERTE, P P Public Service Electric & Gas Co. of New Jersey 80/04/25 3pp

--8004030487 LER 80-002/03L-0 on 800500: during routine surveillance, emergency diesel SG could not be fully loaded. Cause of three pin chucks on Fuel Injectors Pins were checked & diesel tested satisfactorily. Insp report has been initiated
LIBERTE, P P Public Service Electric & Gas Co. of New Jersey 80/04/25 1p

U Congressional/Executive Correspondence

8004120074 Responds to 800409 Ltr requesting info re new safety aids w/ which facilities must comply prior to CL issuance
response to permit improved safety recommendations
revised License to Load Fuel & Test Island 800419
GREGG, M J Office of the Executive Director for Operations 80/05/22 2pp

--8004120074 Responds info re new "safety aids" w/which facilities must comply prior to CL issuance
800419 U Senate: Governmental Affairs 80/04/09 1p

SECRET 90-212 SHAWNEE 9003 NUCLEAR GENERATING STATION

Re: Security, medical, emergency & fire protection plans

8004070447 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." This adds new Section 30.48 & App E to 10CFR50 & is expected to be published in FR by end of May
LIBERTE, P P Division of Licensing 80/05/19 4pp

8004100163 Forwards revised Pages 1-14 & new Page 16 for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Transmitted by MEC 800519 for Page 16a not sent
LIBERTE, P P Division of Licensing 80/05/22 73pp

Q Adjudicatory correspondence

8004040070 Discusses mail needed to respond to CA Energy Commission Investigator's & Friends of the Earth complaint list of RM feedback transcripts up to 791024 regarding that project managers complete summaries of transcripts by 791127
CAPLAN, A THD-C Discipline & Orders 79/11/23 2pp

8004100449 Motion by CA Energy Commission for extension until 800801 to file proposed findings of fact & conclusions of law
Supports 800715 for Licensee Findings; 800802 for NRC Findings & 800808 for Licensee reply. Support of Doc 800804-C California: State of 80/06/04 3pp

8004040138 Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental adverse statements on Class V accidents at Shale Canyon, Ramoth Dene & Palm Verde
DRUMMOND, E J Office of Nuclear Reactor Regulation: Director 80/06/19 2pp

--8004060139 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class V accidents at facilities. No special circumstances exist which would warrant reopening proceedings. Request denied
DRUMMOND, E J Office of Nuclear Reactor Regulation: Director 80/06/19 2pp

--8004060181 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re impact of Class V accidents at facilities. No special circumstances exist which would warrant reopening review proceedings
DRUMMOND, E J Office of Nuclear Reactor Regulation: Director 80/06/19 17pp

--8004060182 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class V accidents
DRUMMOND, E J Office of Nuclear Reactor Regulation: Director 80/06/19 2pp

I Financial information

8004030300 Annual Financial Rept 1979
Sacramento Municipal Utility District 79/12/30 81pp

8004030307 Forwards Annual Financial Rept 1979
MATTING, J J Sacramento Municipal Utility District 80/04/09 1p

P Operating license stage documents & correspondence

8004060203 Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for BML operating plants. Info on
CAPLAN, R A Light Water Reactors Branch 3 80/01/17 3pp

- 00042003040 Forwarded 000314 memo re 760500 treatment at facility known as "light bulb incidents." Transient could have led to results as various on the Requests comments on memo. whereabout on safety problems in (Item 1-3) EISENHART, D. G. Division of Operating Reactors 04/04/03 4pp
- 0004200074 Advice of alternate sequence of events for 760500 incident at facility that could have resulted in outcome as various as the Priority should be given to study of sequences in which successful core cooling may be in location. EISENHART, D. G. 04/04/03 4pp
- 0004200165 Forwarded addl FRG-D related requirements to operating Reactors Licensee requirements for the Action Plan include shift meeting, licensing exams & licensee determination of operating experience. Response requested within 30 days EISENHART, D. G. Division of Licensing 04/02/03 13pp
- 0004200132 Requests comments re NUREC-0377, "Potential for Low Fracture Toughness and Laminar Tearing on PWR Reactor Vessel & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule etc. EISENHART, D. G. Division of Licensing 04/04/03 7pp
- 0004200340 Notification of 000507 hot test of seal injection & makeup system. Injection was & HPIB while performing SP 207.04 at hot shutdown trip. In returning to power. No leakage found. HATTINGE, J. J. Sacramento Municipal Utility District 04/05/02 1p
- 0004200465 Response to 000398 1hr re facility compliance w/Category A. NUREC-0378 items. Day will draw liquid samples from RGS cold leg & from containment vessel via decay heat test. Analysis described in 000411 list. HATTINGE, J. J. Sacramento Municipal Utility District 04/05/03 3pp
- 0004200131 Forwarded Revision 1 to "GENE Eads Class Valve Testing Requirements" pp 4-8 & 4-9. In program changes resulting from 77010 operational review. Re implementation of University testing program. Requests add relief due to changes. HATTINGE, J. J. Sacramento Municipal Utility District 04/05/03 5pp
- 0004200488 Forwarded position on selected NUREC-0660 action items as requested by NRC 000507 1hr. HATTINGE, J. J. Sacramento Municipal Utility District 04/06/03 4pp
- 9 Inspection reports, IE Bulletins & correspondence**
- 0004200500 Ack receipt of 791212 memo forwarding revision to SRM mpt. "Analysis Summary in Support of Early Reactor Coolant Pump Trip" Informal copy of mpt not incorporated into evaluation of IE Bulletin 79-002 (NARS-0400) CAPRA, R. A. TRN-2 Bulletin & Orders 79/12/12 1p
- 0004200403 Forwarded 791202 revision to "Analysis Summary in Support of Early Reactor Coolant Pump Trip" mpt should be used as evidence responses to IE Bulletin 79-002 (NARS-0400) JENSEN, L. Division of Reactor Operations 79/12/12 1p
- 0004200445 Forwarded IE Insp Rept 30-312/80-14 re 000335-27 No noncompliance noted. EISENHART, D. G. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 02/04/28 3pp
- 0004200503 IE Insp Rept 30-312/80-14 re 000325-27 No noncompliance noted. Major areas inspected activities performed in response to IE Bulletin 79-002 & 79-003 & exam of weld cracking problem during valve installation. EISENHART, D. G. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 04/04/28 3pp
- 0004200432 Response to Item 4 of IE Bulletin 79-003, Revision 2: "Cracking in Feedwater Stop Piping." Visual exam of all main & auxiliary feedwater stop piping supports & welds. Inspected during refueling outage to verify operability. HATTINGE, J. J. Sacramento Municipal Utility District 03/04/29 1p
- 0004200174 Forwarded IE Insp Rept 30-312/80-12 re 000407-00 & 10 No noncompliance noted. EISENHART, D. G. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 03/05/12 3pp
- 0004200171 IE Insp Rept 30-312/80-12 re 000407-00 & 10 No noncompliance noted. Major areas inspected activities performed in response to IE Bulletin 79-018. EISENHART, D. G. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 03/05/09 4pp
- 0004200114 Forwarded IE Insp Rept 30-312/80-09 re 000407-01 No noncompliance noted. EISENHART, D. G. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 03/05/14 3pp
- 0004200124 IE Insp Rept 30-312/80-09 re 000407-01 No noncompliance noted. Major areas inspected fire protection measures, waste management & administrative record-keeping & handling of equipment & fallout on IE bulletins & circulars. FALLENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 03/05/14 3pp
- 0004200181 Forwarded IE Insp Rept 30-312/80-16 re 000408-30 No noncompliance noted. EISENHART, D. G. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 03/05/09 3pp
- 0004200184 IE Insp Rept 30-312/80-16 re 000408-30 No noncompliance noted. Major areas inspected long-term shutdown activities & loss of non-nuclear instrumentation power. FALLENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 04/05/14 3pp
- 0004200512 Ack receipt of 000423 1hr responding to items of noncompliance in 000401 notice of violation & payment of civil penalties in amount of \$25,000 in response to 000401 notice of proposed citation. STELLIG, V. Office of Inspection & Enforcement, Office of the Director 03/05/07 1p
- 0004200503 Forwarded IE Circular 00-15: "Eradicating Damage in Westinghouse Fuel Assemblies." No written response required. EISENHART, D. G. Region 5, San Francisco, Office of the Director 03/05/02 1p
- 0004200339 Forwarded 000508 1hr re Region 5 re utility responses to IE Bulletin 79-018: "Reactor Qualification of IE Electrical Equipment." HATTINGE, J. J. Sacramento Municipal Utility District 04/05/04 1p
- 0004200241 Forwarded response to IE Bulletin 79-018: "Environ Qualification of IE Electrical Equipment." Responses, including equipment required to function under postulated accident conditions, available in Central File only. HATTINGE, J. J. Sacramento Municipal Utility District 03/05/05 3pp
- 0004200505 Ack receipt of 000402 1hr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-312/80-10. EISENHART, D. G. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 03/05/12 1p
- 0004200503 Response to NRC 000402 1hr re violation noted in IE Insp Rept 30-312/80-10 corrective actions held training sessions w/atomic operators & reviewed & updated relief procedures. HATTINGE, J. J. Sacramento Municipal Utility District 03/05/02 2pp
- 0004200507 Forwarded IE Insp Rept 30-312/80-10 re 000500-31 & notice of violation. EISENHART, D. G. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 03/04/22 3pp
- 0004200504 Notice of violation from Insp re 000500-31 re Region 5, San Francisco, Office of the Director 03/04/22 1p
- 0004200506 IE Insp Rept 30-312/80-10 re 000500-31 Noncompliance noted. Several of objects over fuel transfer test life approved procedures. FALLENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 04/05/02 3pp
- 8 Periodic operating reports & related correspondence**
- 0004200404 Forwarded monthly operating report for May 1960. EISENHART, D. G. Sacramento Municipal Utility District 03/04/03 4pp

DOCKETED ITEMS

107

--000410041 Monthly operating rep for May 1980
0200000 R C Sacramento Municipal Utility District 00/04/05
4p

G Reportable occurrences, LERs & related correspondence

--0004000361 Forwards LER 00-029/001-0
0000000 J J Sacramento Municipal Utility District 00/05/00 2pp

--0004000087 LER 00-005/001-0 on 000502, review of applicability of 3E
Info Notice 00-13 revealed 2P 0P upper RMR switches in
safety-related touchswitch Eight created in van followers
Canted by exposure to hydrazine in ref process
0000000 R W Sacramento Municipal Utility District 00/05/00
1p

0004100102 Ref review of safety feature activation sqs indicates that
inverter A or B are removed from van single failure of
cable inverter during accident until prevent sqs operation
Inverter will be treated as safety feature equipment
000010045 J V Sacramento Municipal Utility District 00/04/04
1p

0004000037 Forwards following LER 79-021/001-1
0000000 H C Sacramento Municipal Utility District 00/04/06 3pp

--0004000028 Followup LER 79-021/001-1 on 791216 error in ref heat
balance revealed no error for effective full power days
calculation caused by possible reaction upon on flow nozzle
Nozzle will be replaced during next refueling outage
0000000 R W Sacramento Municipal Utility District 00/05/06
1p

0004000094 Forwards LER 00-000/017-0
0000000 J J Sacramento Municipal Utility District 00/04/19 1p

--0004000405 LER 00-000/017-0 on 000409, review of safety features
activation sqs revealed that if one inverter was out of svc.
Failure of remaining inverter would disable sqs Operational
restrictions placed on inverter operability
0000000 R W Sacramento Municipal Utility District 00/04/19
1p

0004000028 Forwards LER 00-000/043-0
0000000 J J Sacramento Municipal Utility District 00/04/19 1p

--0004000033 LER 00-029/047-0 on 000319, May 1980 effluent monitoring
charts indicated effluent oil exceeded 8 B Tech Spec limit
Caused by pH fluctuations in division water column
phenomena in summer months
0000000 R W Sacramento Municipal Utility District 00/04/19
1p

T Hearing transcripts on non-antitrust matters

0004000100 Forwards NRC proposed transcript corrections per ASLE order
re post-hearing schedule in proceeding Certificate of Doc
ent
BLAKE R L Hearing Branch 1 00/05/00 3pp

--0004000191 Proposed corrections to 000008-0303-06-0008-11-0416-10-0457
0000-10 & 0010-14 transcripts
4 Hearing Branch 1 00/05/00 24pp

0004100004 Forwards stipulated note to parties, proposed transcript
corrections & stipulated add proposed transcript
corrections Perkins suggest that ASLE issue order adopting
000000 corrections on amended Certificate of Doc ent
BATTER J A Shaw Pitman, Potte & Tombridge 00/04/09 4pp

--0004010041 Stipulated note to licensee, NRC & CA Energy Commission
proposed transcript corrections
4 Shaw Pitman, Potte & Tombridge 00/04/09 3pp

--0004010039 Stipulated add proposed transcript corrections
4 Shaw Pitman, Potte & Tombridge 00/04/09 1p

0004010013 ARKANSAS NUCLEAR ONE, UNIT 1

P Security, medical, emergency & fire protection plans

0004000027 Forwards request for add info re security personnel
training & qualification plan DRI withheld (ref
100000 7903)
REID R H Operating Reactors Branch 4 00/05/19 3pp

0004000407 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790101" Rule
adds new Section 50 48 & App R to 100000 & is expected
to be published in FR by end of May
EISENHUT, D D Division of Licensing 00/05/00 4pp

0004100003 Forwards revised Pages 1-14 & new Page 14a for proposed
rule 100000 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790101" transmitted by NRC 000019
1tr Page 14a not sent
EISENHUT, D D Division of Licensing 00/05/00 7pp

0004100042 Forwards revisions to proposed rule, safeguards contingency
plan per RM Rule 000411 request filed withheld (ref
100000 7901)
TRIEMLE, D C Arkansas Power & Light Co 00/05/00 1p

0004000010 Ack receipt of NRC 000019 1tr requesting info on security
personnel training & qualification plan Requests copy of
draft NUREG-5674 dealing with security plan responses to ICR
TRIEMLE, D C Arkansas Power & Light Co 00/05/00 1p

H General correspondence

0004070171 Responds to 000406 request to comment on R Laceruel concerns
re spent fuel storage pool expansion Unit indicated that
no plans for expansion anticipated until 1982 or 1983 NRC
approved & public consideration would precede expansion
BIRCH, W J Office of the Executive Director for Operations
00/04/09 2pp

P Operating license change documents & correspondence

0004000039 Forwards until 791001 1tr re auxiliary emergency feedwater
control sqs being developed by BW appears to be fully
responsive to NUREG-007B concerns re separation from ICR &
operator capability
CAPRA, R A TRI-C Substitions & Drains 7910/10 1p

0004000083 Forwards documents for Auxiliary Sys Branch review of
emergency feedwater reliability analysis for ASB separation
control sqs
CAPRA, R A Light Water Reactors Branch 0 00/05/17 3pp

0004000105 Forwards add TRI-C related requirements re operating
licensee requirements for RMI Action Plan include
shifts, monitoring, licensing exams & licensee dissemination
of operating experience Response requested within 30 days
EISENHUT, D D Division of Licensing 00/05/07 10pp

0004100122 Requests comments on NUREG-0777, "Technical for Low Pressure
Youghaas & Lumbard Tearing on PWR Steam Generator &
Reactor Containment Pump Reports" Proposed review procedure &
implementation schedule ent
EISENHUT, D D Division of Licensing 00/05/19 72pp

0004070002 Requests meeting w/011 on 000404 in Bethesda, MD to discuss
interim reliability evaluation program Program is associated
with reliability engineering & risk assessment Task included in
NUREG-5660, "TRI Action Plan"
EISENHUT, D D Division of Licensing 00/05/23 3pp

0004100412 Summary of 000002 meeting w/011 re 000010 reactor
containment pump test task
VIGORIS, D C Operating Reactors Branch 4 00/04/02 4pp

0004000105 Notification of 000412 meeting w/011 in Bethesda, MD to discuss
interim reliability evaluation program
CLAMMALL, M Operating Reactors Branch 1 00/04/09 2pp

0004100106 Forwards response to NRC 000019 1tr re loss of offsite power events
TRIEMLE, D C Arkansas Power & Light Co 00/06/11 3pp

0004100028 Responds to NRC 000005 1tr re loss of offsite power events
Details of 790220, 1985 & 000407 events indicate weather
conditions were responsible on all scenarios Only monitoring
losses of power were experienced
TRIEMLE, D C Arkansas Power & Light Co 00/06/11 3pp

0004000008 Forwards Amend 45 to Licensee DPE-01, safety evaluation &
notice of issuance & availability
REID, R H Operating Reactors Branch 4 00/06/12 2pp

--0004000020 Amend 45 to Licensee DPE-01, modifying Tac Specs re
surveillance requirements for hydraulic systems
REID, R H Operating Reactors Branch 4 00/06/12 3pp

DOCKETED ITEMS

- 000420297 Safety evaluation supporting Amend 45 to License SPR-01
* Operating Reactors Branch 4 00/06/12 3pp
- 000420298 Notice of issuance & availability of Amend 45 to License SPR-01
RISB-R M Operating Reactors Branch 4 00/06/12 2pp
- 000420300 Discusses license plans to increase onsite waste storage
Request review of onsite storage additions in monthly
operating report following period in which evaluation was
completed NRC onsite storage licensing pavilion unit
RISB-R M Operating Reactors Branch 4 00/06/12 10pp
- 000420303 Forward safety evaluation supporting still justification of
continued operation of facility reactor vessel
surveillance program conducted at Davis-Besse Unit 1 Related
Tech Specs should be proposed
RISB-R M Operating Reactors Branch 4 00/06/12 2pp
- 000420305 Safety evaluation supporting still justification of continued
facility operation reactor vessel surveillance program
conducted at Davis-Besse Unit 1 Related Tech Specs should be
proposed
* Operating Reactors Branch 4 00/06/12 2pp
- 000420306 Submit response to 000007 request for amendment to TH-2
related requirements Response to Item 11 K 2 23,29, & 44
will be delayed because unit did not receive errata sheets
until 000416
TRISLE-D C Arkansas Power & Light Co 00/06/12 3pp
- 000420308 Discusses fees for review of APL-TRF-1A, QA Manual-
Operations * Requests payment upon receipt of invoice.
RISLE-R M License Fee Management Branch 00/06/12 3p
- Q Inspection reports, IE Bulletins & correspondence
- 000420310 NRC/PIE NRC that limited response to IE Bulletin 99-27,
"Loss of Non-Class IE Instrumentation & Control Power Sys
Bus During Operation." will be submitted by 000420 Response
will be limited to as power supply to INH buses
TRISLE-D C Arkansas Power & Light Co 00/06/01 1p
- 000420351 Responds to IE Bulletin 99-27, "Loss of Non-Class IE
Instrumentation & Control Power Sys Bus During Operation."
Review identified need to increase reliability of as power
supply to non-accrual instrumentation sys
TRISLE-D C Arkansas Power & Light Co 00/04/23 3pp
- 000420356 Forward IE Insp Repts 50-313/80-06 & 50-368/80-04 on
000320-0421 & notice of violation
NHSB-D L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 00/05/05 3pp
- 000420362 Notice of violation from Insp on 000320-0421
* Region 4, Dallas, Reactor Operations Nuclear Support Branch
00/05/02 3pp
- 000420364 IE Insp Repts 50-313/80-06 & 50-368/80-04 on 000320-0421
An acceptance noted no control of combustibles & finding
that waste control operator entered high radiation area w/o
using radiation survey instrument
NHSB-RM-T F Region 4, Dallas, Reactor Operations Nuclear
Support Branch 00/05/02 10pp
- 000420399 Forward IE Bulletin 98-11, "Heavy Metal Design * Requires
action & written response IE Info Notice 98-28,
"Overloading of Structural Elements Due to Pipe Support
Loaders and
SEYFRIE-K V Region 4, Dallas, Office of the Director 00/05/08
1p
- 0004205037 Forward IE Bulletin 98-12, "Deag Heat Removal Sys
Operability * Requires actions 5 response within 30 days
IE Info Notice 98-25, Loss of Deag Heat Removal Capability
at Davis-Besse Unit 1 While in Defueling Mode" encl
SEYFRIE-K V Region 4, Dallas, Office of the Director 00/05/09
1p
- 0004205091 Responds to violations noted in IE Insp Repts 50-313/80-06
& 50-368/80-04 Corrective actions due to high radiation
areas locked or repaired & locked combustibles removed from
activated areas & maint personnel notified
TRISLE-D C Arkansas Power & Light Co 00/05/26 4pp
- 0004206104 Ack receipt of 000006 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-313/80-06 &
50-368/80-04
NHSB-D L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 00/06/06 1p
- 000420616 Response to NRC ltr re violations noted in IE Insp Repts
50-313/80-06 & 50-368/80-04 Corrective actions revised
Procedures 1204 23 & 2044 15 requiring specific sign-off for
each test rate test following containment activities
TRISLE-D C Arkansas Power & Light Co 00/05/09 3pp
- 000420619 Responds to IE Bulletin 98-12, "Deag Heat Removal Sys
Operability * Analysis of procedures for sequencing
against loss of sys capability should be completed by
000512
CANNASH-W Arkansas Power & Light Co 00/06/12 3pp
- 000420619 Forward evaluation of 000411, 0004 25 responses to IE
Bulletin 99-25A & B Requests that unit conform to
provisions or provide sufficient justification for proposed
deviations from guidance
NDMA-T M Reactor Systems Branch 00/06/13 22pp
- R Periodic operating reports & related correspondence
- 000420619 Forward "Annual Evaporator Monitoring Rept."
TRISLE-D C Arkansas Power & Light Co 00/05/12 1p
- 000420619 "Annual Evaporator Monitoring Rept." Overdue drawing sheet
* Arkansas Power & Light Co 00/05/12 400pp
- 000420621 Forward results of intake impingement monitoring during
spring month of Apr 1999
TRISLE-D C Arkansas Power & Light Co 00/05/29 1p
- 000420622 Results of intake impingement monitoring during month of Apr
1999 Computer cards encl
* Arkansas Power & Light Co 00/05/29 10pp
- 000420624 Forward monthly operating report for May 1999
TRISLE-D C Arkansas Power & Light Co 00/06/12 1p
- 000420629 Monthly operating report for May 1999
BRACKETT-L S Arkansas Power & Light Co 00/06/12 7pp
- B Reportable occurrences, LERs & related correspondence
- 000420634 LER 99-0140-021C on 000305, following purge of reactor bldg,
fans were left on by continue ventilation EPA officials
indicated that no radon levels were detected officials
will sample indicated that 4 out of 8 had traces of rad-222
NHSB-RM-T F, NDSB-D L Region 4, Dallas, Office of the
Director 00/05/11 1p
- 000420634 Forward updated LER 99-017/021-1
TRISLE-D C Arkansas Power & Light Co 00/05/23 1p
- 000420639 Updated LER 99-017/021-1 on 78911, during monthly test,
signal generator 3 tripped on low oil pressure after approx
2 minutes of operation Caused by inadequate corrosion
inhibitor resulting in exfoliation type solder compression
SHWELT-R N Arkansas Power & Light Co 00/05/20 1p
- 000420639 Submit followup actions to RCP seal failure on 000310 in
response to NRC request Following resolution to seal shutdown
RCP Seal C cartridge was removed & transferred from
containment bldg to hot instrument shop
TRISLE-D C Arkansas Power & Light Co 00/05/20 2pp
- 000420637 Forward LER 00-016/021-0
TRISLE-D C Arkansas Power & Light Co 00/06/03 1p
- 000420639 LER 00-016/011-0 on 000224, during investigation per IE
Bulletin 00-08 discrepancy in records of weld temps found
Caused by failure to properly review weld record
documentation for particular weld during case
SHWELT-R N Arkansas Power & Light Co 00/06/03 1p
- 000420639 Forward request for add info re reactor coolant pump seal
leak event on 000310
RISB-R M Operating Reactors Branch 4 00/06/09 4pp
- 000420642 Forward LER 00-017/021-0
TRISLE-D C Arkansas Power & Light Co 00/06/12 1p
- 000420642 LER 00-017/021-0 on 000319, while opening reactor bldg bypass
valves, worker 7410 would not operate caused by lost still
being connected to August Damper panel & hand removed
BRACKETT-L S Arkansas Power & Light Co 00/06/12 1p

DOCKETED ITEMS

109

DOCKET NO-319 890405 C COOL NUCLEAR POWER PLANT, UNIT 1
F. Security, medical, emergency & fire protection plans

8906070407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 196101" Rule adds new Section 30.40.5 and 30.40.6 to 10CFR50 and is expected to be published in FR by end of May
EISENHART, D. Division of Licensing 89/05/19 4pp

8906030071 Notification of 890507 meeting w/utl in Bethesda, MD to review design of proposed technical support for emergency operations facility
HUTNER, S. Operating Reactors Branch 1 89/05/21 3pp

8906130643 Forwards proposed Pages 1-14 & new Page 14 for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 196101," transmitted by NRC 890519 (for Page 14a not sent)
EISENHART, D. Division of Licensing 89/05/22 7pp

H. General correspondence

8906070181 Response to 890409 request for info on M. Williams inquiry about amount of nuclear waste disposed on State of MD Spent fuel from four operating NRC reactors stored onsite NRC evaluated status of waste sgt in 1977 Unrelated PR exempts EISENHART, D. Office of the Executive Director for Operations 89/06/09 10pp

J. Insurance & indemnity information

8906280355 Forwards payment for indemnity fee for 890528-810428
W. am 1
DOLAN, J. E. Indiana & Michigan Electric Co. 89/05/16 1p

F. Operating license stage documents & correspondence

8906070143 Forwards addl TRS-2 related requirements to operating reactor Licensee requirements for TRS Action Plan include shift training, licensing stage 1 license determination of operating experience, training required within 30 days
EISENHART, D. Division of Licensing 89/05/07 10pp

8906130122 Request comments on NURE-0077, "Potential for Low Fracture Toughness & Lamellar Tearing in PWR Steam Generator & Reactor Endcap Support" Proposed review procedures & implementation schedule sent
EISENHART, D. Division of Licensing 89/05/19 72pp

8906130148 Forwards Amends 37 & 30 to Licensee 89F-30 & 89F-74, respectively, safety evaluation 1 notice of issuance & availability
WARRIN, S. A. Operating Reactors Branch 1 89/05/23 2pp

--8906130148 Amends 37 & 30 to Licensee 89F-30 & 89F-74, respectively, providing one time only extension of time for testing Unit 2 ice condenser lower skirt doors & revising withdrawal schedule for reactor vessel surveillance capsule
WARRIN, S. A. Operating Reactors Branch 1 89/05/23 14pp

--8906130201 Safety evaluation supporting Amends 37 & 30 to Licensee 89F-30 & 89F-74, respectively
Office of Nuclear Reactor Regulation, Director 89/05/23 3pp

--8906130204 Notice of issuance & availability of Amends 37 & 30 to Licensee 89F-30 & 89F-74, respectively
WARRIN, S. A. Operating Reactors Branch 1 89/05/23 2pp

8906030204 Forwards remittance in response to 890409 for requesting processing fee for NRC review of unit 790201 submitted Request that NRC review & reconsider whether fee is necessary
HUTNER, S. B. Indiana & Michigan Electric Co. 89/05/28 2pp

8906030202 Forwards addl info & Tech Specs re unit 791227 response to NRC 790808 for an adequacy of station electrical distribution system voltage
DOLAN, J. E. Indiana & Michigan Electric Co. 89/05/28 11pp

--8906030301 Tech Spec 3/A & 3/B re alternative ac power sources
Indiana & Michigan Electric Co. 89/05/28 2pp

8906050207 Response to NRC 890418 ltr re evaluation of ultimate strength of facility containment bligs Requests updates of ongoing NRC work in hydrogen generation & containment capacity studies & opportunity to comment on results
DOLAN, J. E. Indiana & Michigan Electric Co. 89/05/30 8pp

8906130309 Reopens licensee shall 890528 request to use divers to cut studs welded to bottom liner & supports in replacement of studs in spent fuel pool in subject to payment of fees should be submitted within 15 days
MILLER, G. License Fee Management Branch 89/06/02 1p

8906040037 Confirms 890702 meeting w/utl in New York, NY to discuss proposed evaluation of several operational & QA problems Problems were previously discussed at 890415 unit meeting
KEPPLER, J. D. Region 3, Chicago, Office of the Director 89/06/10 1p

8906130407 Response to A Schweser 890429 ltr request re Facility 05 low pressure turbine Discussed k100 specific & generic questions re 05 low pressure turbine/ventilator 170418
DOLAN, J. E. Indiana & Michigan Electric Co. 89/06/16 3pp

8906060407 Forwards proposed Tech Spec 3 D 5 in response to NRC 890410 request
DOLAN, J. E. Indiana & Michigan Electric Co. 89/06/16 1p

--8906060401 Proposed Tech Spec 3 D 5 re criteria for operability Related Tech Specs sent
Indiana & Michigan Electric Co. 89/06/16 7pp

8906260177 Withdraws 790219 & 890522 Tech Spec change requests re rod position indication yds & steam generator water level low reactor trip/announced safety Features activation waypoints Rod position indication yds change unnecessary
DOLAN, J. E. Indiana & Michigan Electric Co. 89/06/17 3pp

8906060495 Notifies that fourth reducing outage initiated on 890630 Startup date for Cycle 3 operation scheduled for 89/07/30
DOLAN, J. E. Indiana & Michigan Electric Co. 89/06/18 2pp

8906260402 Forwards response to NRC 890507 ltr re addl TRS-2 related requirements for reactor safety training experience to plant staff will be reviewed Licensee will provide info to Washington for generic rpt
HARTER, R. B. Indiana & Michigan Electric Co. 89/06/20 3pp

G. Inspection reports, IE Bulletin & correspondence

8906170204 Forwards IE Insp Repts 89-315/89-07 & 89-316/89-06 of meeting on 890415 NRC noncompliance noted
NEPPLER, J. F. Region 3, Chicago, Office of the Director 89/06/28 2pp

--8906170202 IE Insp Repts 89-315/89-07 & 89-316/89-06 of meeting on 890415 NRC noncompliance noted Major areas inspected implementation of unit 36 program & regulatory performance re personnel error & adherence to procedure 315D-B-C & 316D-B-C Region 3, Chicago, Office of the Director
NEPPLER, J. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 89/06/28 2pp

8906170240 Disallows NRC 791220 issuance of info Notice 79-07 re tracks in log and 2 spare sections of drive in Washington low pressure turbines Addl info concerning info notice requested Response due within 30 days of receipt of ltr
SCHMIDTKE, A. Licensing Branch 2 89/06/29 3pp

8906130108 Forwards IE Insp Repts 89-315/89-04 & 89-316/89-03 on 890411-0021 & notice of violation
HUTNER, S. B. Region 3, Chicago, Reactor Operations Nuclear Support Branch 89/05/28 2pp

--8906130103 Notice of violation from Insp on 890411-0021
Region 3, Chicago, Office of the Director 89/06/30 1p

--8906130108 IE Insp Repts 89-315/89-04 & 89-316/89-03 on 890411-0021 Noncompliance noted spent fuel pit concentration found to be below min level re 890317
HARTER, R. B. & 890417, H. E. & 890417, D. C. Region 3, Chicago, Office of the Director 89/06/30 10pp

8906030301 Forwards remaining responses to IE Bulletin 79-013 re vendor qualification of Class 8E equipment W. am 1
HUTNER, R. B. Illinois Power Co. 89/05/27 4pp

DOCKETED ITEMS

0050400017 Provides supplemental response to BE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Forwards modified list of equipment to reflect refs to qualification charts. List proves adverse environ qualification.
HUNTEN, R S Indiana & Michigan Electric Co 85/05/07 100pp

0050200096 Forwards IE Insp Repts 50-315/00-06 & 50-316/00-05 on 000421-25 Re noncompliance noted
HOPPLEN, J G Region 3, Chicago, Office of the Director 80/05/13 3pp

0050200199 IE Insp Repts 50-315/00-06 & 50-316/00-05 on 000421-25 Re noncompliance noted. Major areas inspected: radiological environ protection
HUNTEN, R S Indiana & Michigan Electric Co Region 3, Chicago, Office of the Director 80/05/12 3pp

0050300076 Ack response to PDR request for six categories of documents re CPC Forwards documents listed in app
FELTON, J M Division of Rules and Records 80/05/03 3pp

0050400077 Forwards response to updated memo received on 009363 re unit interrogative re proposed inspection of civil penalty
Cover sheet of IE Insp Rept 0050400077
HOPPLEN, J G Region 3, Chicago, Office of the Director 80/05/21 3pp

0050400111 IE Insp Rept 50-315/77-26 on 771204-07 Noncompliance noted. Both containment spray tank and vent
HUNTEN, R S Indiana & Michigan Electric Co 78/01/04 3pp

0050300113 RO on 771110 while performing routine surveillance test. Heat exchanger inlet valve was discovered closed. Caused by personnel error. Valves were opened upon discovery
HUNTEN, R S Indiana & Michigan Electric Co 77/11/38 1p

0050400118 Confirms 771118 verbal rept re closed containment spray tank exchanger inlet valves. Followup rept will be provided by 771204
HUNTEN, R S Indiana & Michigan Electric Co 77/11/18 1p

0050400194 Ack receipt of 005012 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-315/00-05 & 50-316/00-04. Corrective action will be completed during future insp
HUNTEN, R S Region 3, Chicago, Safeguards Branch 80/06/03 1p

0050400203 Forwards response to NRC 005017 ltr re noncompliance identified in IE Insp Repts 50-315/00-05 & 50-316/00-04
Response withheld (ref 10CFR2 790)
HUNTEN, R S Indiana & Michigan Electric Co 80/05/12 1p

0050400303 Ack receipt of 005028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/00-01 & 50-316/00-04
HUNTEN, R S Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/05 1p

0050400386 Response to NRC 005038 ltr re violations noted in IE Insp Repts 50-315/00-01 & 50-316/00-04. Corrective action. Class I component list will be continually updated as add compliance areas identified
HUNTEN, R S Indiana & Michigan Electric Co 80/05/28 3pp

0050400402 Response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Forwards corrected form add pages to attachments 3 & 4 re unit 000357 record set of responses
HUNTEN, R S Indiana & Michigan Electric Co 80/06/05 05pp

B. Material operating reports & related correspondence

0050400521 Forwards monthly operating rept for May 1980
HUNTEN, R S Indiana & Michigan Electric Co 80/06/11 1p

0050400520 Monthly operating rept for May 1980
HUNTEN, R S Indiana & Michigan Electric Co 80/06/03 7pp

0050400522 Forwards LER 80-011/03L-0
HUNTEN, R S Indiana & Michigan Electric Co 80/06/25 1p

0050400523 LER 80-011/03L-0 on 000351, unit in shutdown mode, containing atmosphere air particulate & gamma radiation monitoring. Air pump tripped on low flow caused by inoperative flowmeter. Flowmeter replaced
HUNTEN, R S Indiana & Michigan Electric Co 80/06/25 3pp

DOCKET 50-316. DOWNS. C. COOL NUCLEAR POWER PLANT, UNIT 2

P. Security, medical, emergency & fire protection plans

0050400647 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50.48 & App B to 10CFR50.6 is expected to be published in FR by end of May
HUNTEN, R S Division of Licensing 80/05/19 44pp

0050400691 Notification of 000527 meeting w/Unit in Bethesda, MD re review design of proposed technical support & emergency operations facility
HUNTEN, R S Operating Reactors Branch 1 80/05/21 3pp

0050400692 Forwards revised Pages 1-16 & new Page 14a for proposed Rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 000319 ltr Page 14a not avail
HUNTEN, R S Division of Licensing 80/05/28 73pp

P. Operating license stage documents & correspondence

0050400715 Forwards addl TH-2 related requirements to Operating Reactors Licensee requirements for the Active Plan include addl licensing events & licensed classification of operating experience responses requested within 30 days
HUNTEN, R S Division of Licensing 80/05/07 100pp

0050400722 Requests comments on NUREG-0577, "Potential for Low Pressure Toughness & Laminar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule addl
HUNTEN, R S Division of Licensing 80/05/19 73pp

0050400792 Forwards Amends 27 & 28 to License 50F-58 & 50F-74, respectively. Safety evaluation & notice of intent & availability
HUNTEN, R S Operating Reactors Branch 1 80/05/23 3pp

0050400794 Amends 27 & 28 to License 50F-58 & 50F-74, respectively, providing one time only extension of low flow testing Unit 2 re condenser steam inlet doors & providing withdrawal schedule for reactor vessel surveillance capsule
HUNTEN, R S Operating Reactors Branch 1 80/05/23 14pp

0050400793 Safety evaluation supporting Amends 27 & 28 to License 50F-58 & 50F-74, respectively
Office of Nuclear Reactor Regulation, Director 80/05/23 3pp

0050400806 Notice of issuance & availability of Amends 27 & 28 to License 50F-58 & 50F-74, respectively
HUNTEN, R S Operating Reactors Branch 1 80/05/23 2pp

0050400848 Advises that unit 791218 application accepted as being supplementary to 790919 application based on addl info provided by OIC of Nuclear Reactor Regulation. No addl fees required
HUNTEN, R S License Fee Management Branch 80/05/27 1p

0050400854 Forwards notification in response to 005040 ltr requesting processing fee for NRC review of unit 000354 submittal
Requests that NRC review & reconsider whether fee is necessary
HUNTEN, R S Indiana & Michigan Electric Co 80/05/28 2pp

0050400933 Forwards addl info & Tech Specs re unit 791217 response to NRC 790918 ltr re adequacy of station electrical distribution bus voltage
HUNTEN, R S Indiana & Michigan Electric Co 80/05/28 11pp

0050400934 Tech Spec 3/4 & 3 re alternative ac power sources
Indiana & Michigan Electric Co 80/05/28 3pp

0050400937 Response to NRC 000118 ltr re evaluation of ultimate strength of facility containment bldg. Requests updates of existing NRC unit re hydrogen mitigation & containment capacity studies & opportunity to comment on results
HUNTEN, R S Indiana & Michigan Electric Co 80/05/30 2pp

DOCKETED ITEMS

111

0004170209 Forwards licensee that 000324 request to use divers to cut studs welded to bottom liner & supports in replacement of racks in spent fuel pool is subject to payment of fees for study to be submitted within 15 days
MILNER, D V License Fee Management Branch 00/06/02 1p

0004170207 Confirms 000702 meeting w/att in New York, NY to discuss proposed resolution of several operational & SA problems
Problems were previously discussed at 000410 mtg meeting
HALLER, J D Region 3, Chicago, Office of the Director 00/06/00 1p

0004170207 Forwards proposed Tech Spec 3 0 5 in response to NRC 000410 request
COLMAN, J E Indiana & Michigan Electric Co 00/06/01 1p

0004170204 Proposed Tech Spec 3 0 5 re criteria for operability Related
Tech Spec mtg
Indiana & Michigan Electric Co 00/06/01 7pp

0004170217 Withdrawn 79019 A 000323 Tech Spec change requests re red position indication vs steam generator under level low low reactor trip/engineered safety features activation sequence red position indication vs change unnecessary
COLMAN, J E Indiana & Michigan Electric Co 00/06/01 7pp

0004170202 Forwards response to NRC 000307 ltr re add TH-2 related requirements Procedures for feedback of operating experience to plant staff will be reviewed. Licensee will provide info to investigators for generic report
HALLER, J D Indiana & Michigan Electric Co 00/06/02 4pp

0 Inspection reports, IE Bulletin & correspondence

0004170244 Forwards IE Insp Repts 00-015/00-07 & 00-016/00-06 of meeting on 000410 SA noncompliance noted
HALLER, J D Region 3, Chicago, Office of the Director 00/06/02 2pp

0004170202 IE Insp Repts 00-015/00-07 & 00-016/00-06 of meeting on 000410 SA noncompliance noted Major areas inspected
Implementation of utility SA program & regulatory performance re personnel record & adherence to procedure
HALLER, J D Region 3, Chicago, Office of the Director
HALLER, J D Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/02 2pp

0004170208 Forwards IE Insp Repts 00-015/00-04 & 00-016/00-03 on 000411-0221 & notice of violation
HALLER, J D Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/02 2pp

0004170213 Notice of violation from Insp on 000411-0221
Region 3, Chicago, Office of the Director 00/06/02 1p

0004170218 IE Insp Repts 00-015/00-04 & 00-016/00-03 on 000411-0221
Noncompliance noted spent fuel pit concentration found to be below min level on 000411
HALLER, J D Region 3, Chicago, Office of the Director 00/06/02 1pp

0004170208 Forwards remaining responses to IE Bulletin 79-019 re
environment qualification of Class IE equipment W/enc
HALLER, J D Illinois Power Co 00/05/07 4pp

0004170219 Provides supplemental response to IE Bulletin 79-019, "Environ Qualification of Class IE Equipment" - Furnace modified list of equipment to reflect refs to qualification charts list proves adverse environ qualification
HALLER, J D Indiana & Michigan Electric Co 00/05/07 100pp

0004170219 Forwards IE Insp Repts 00-015/00-06 & 00-016/00-03 on 000411-0221
SA noncompliance noted
HALLER, J D Region 3, Chicago, Office of the Director 00/05/03 2pp

0004170219 IE Insp Repts 00-016/00-04 & 00-016/00-03 on 000411-0221 No noncompliance noted Major areas inspected radiological
environment protection
HALLER, J D Region 3, Chicago, Office of the Director 00/05/02 4pp

0004170204 Act receipt of 000302 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 00-015/00-07 & 00-016/00-06 Corrective action will be examined during future Insp
HALLER, J D Region 3, Chicago, Safeguards Branch 00/06/02 1p

0004170204 Forwards response to NRC 000417 ltr re noncompliance identified in IE Insp Repts 00-015/00-07 & 00-016/00-06
Response withdrawn after 100402 7pp
HALLER, J D Indiana & Michigan Power Co 00/03/02 1p

0004170203 Act receipt of 000320 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-015/00-07 & 00-016/00-06
HALLER, J D Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/03 1p

0004170206 Response to NRC 000305 ltr re violations noted in IE Insp Repts 00-015/00-07 & 00-016/00-06 Corrective actions Class I component list will be continuously updated as add components are identified
COLMAN, J E Indiana & Michigan Power Co 00/05/02 2pp

0004170202 Response to IE Bulletin 79-019, "Environ Qualification of Class IE Equipment" Forwards corrected w/enc add pages to Attachments 3 & 4 to 000307 second set of responses
HALLER, J D Indiana & Michigan Electric Co 00/06/02 33pp

0 Periodic operating reports & related correspondence

0004170208 Forwards monthly operating report for May 1990
HALLER, J D Indiana & Michigan Electric Co 00/06/01 1p

0004170204 Monthly operating report for May 1990
HALLER, J D Indiana & Michigan Electric Co 00/06/02 4pp

0 Reportable occurrences, LERs & related correspondence

0004170212 RO 00-016/00-010 during investigation per IE Bulletin 00-06, discovered reactor bldg flood heat exchanger unit P-10-01-1 had not been repaired to correct failure defect
Unit defect will be repaired prior to power operation
O'HANLON, J P Arkansas Power & Light Co 00/05/02 1p

0004170204 Forwards LER 00-022/00L-0 & updated LER 79-04/00L-1
HALLER, J D Indiana & Michigan Electric Co 00/06/02 1p

0004170212 LER 00-022/00L-0 on 000303 radiation monitor R-11 alarmed during normal operation Sample pump for R-11 & R-12 would not remain running caused by use of pump pump replaced & air sampler tested Entire set will be replaced
HALLER, J D Indiana & Michigan Electric Co 00/06/02 1p

0004170213 Updated LER 79-04/00L-1 on 79/10/0 hydrogen recombiner 1 failed to increase temp to 1,200 F within 10 sec caused by incorrect electrical connection of one heater element wiring controller & controller gain & bias adjusted
HALLER, J D Indiana & Michigan Electric Co 00/06/02 1p

0004170208 Forwards updated LER 00-022/00L-1
HALLER, J D Indiana & Michigan Electric Co 00/06/04 1p

0004170203 Updated LER 00-022/00L-1 on 000303 radiation monitor R-11 alarmed during normal operation Sample pump for R-11 & R-12 would not remain running caused by use of pump pump replaced & air sampler tested Entire set will be replaced
HALLER, J D Indiana & Michigan Electric Co 00/06/04 1p

0004170208 Forwards updated LER 00-022/00L-1
HALLER, J D Indiana & Michigan Electric Co 00/06/04 1p

0004170217 LER 00-022/00L-0 on 000303 during normal operation low flow alarm for containment SPD R-11 & R-12 was received Sample pump would not restart & R-11 & R-12 were declared inoperable caused by inaccurate flow meter. Water replaced
HALLER, J D Indiana & Michigan Electric Co 00/06/02 2pp

0004170208 Forwards LER 00-022/00L-0
HALLER, J D Indiana & Michigan Electric Co 00/06/04 1p

0004170204 LER 00-022/00L-0 on 000303 turbine drive auxiliary feedwater pump in normal standby position alarm received Unit pump tripped Problem caused by control linkage disconnection from tripping valve
LEAHY, R B Indiana & Michigan Electric Co 00/06/02 1p

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

0004040152 Forwards request for add info re incombustible fire protection items per review required by 790113 DER Response should include commitments necessary to resolve all items by 001001 to be submitted within 30 days
CLARK,R A Operating Reactors Branch 3 00/05/19 23pp

0004040407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Under 1000 PSI" Rule add new Section 30.49 & App R to 10CFR50 & is expected to be published in FR by end of May
EISENHUT,D G Division of Licensing 00/05/19 44pp

0004040503 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" transmitted by NRC 000319
100 Page 14a not encl
EISENHUT,D G Division of Licensing 00/05/19 73pp

0004040527 Responds to NRC 000323 ltr re LNG contingency plan informs NRC that due to difficult time consulting nature of cable routing installation of monitor expected to be completed & not operational by 000410
LUNFALL,A E Baltimore Gas & Electric Co 00/05/20 1p

0004040617 Requests extension to 000719 for submission of guard training & qualification plan revisions & add info requested by NRC 000513 ltr
EISENHUT,D G Baltimore Gas & Electric Co 00/06/02 1p

0004040629 Forwards revised emergency response plan & plan upgraded per info 000502-03 re fire protection safety evaluation & plan to draft NUREG encl
LUNFALL,A E Baltimore Gas & Electric Co 00/06/10 43pp

0004040744 Revised emergency response plan
4 Baltimore Gas & Electric Co 00/06/20 39pp

0004040820 Forwards response to item 3 1 3.3 1 1.3 2 2.3 4 4 3 3 3 3 of NRC 000519 ltr re fire protection safety evaluation & amendments to GL Certification statement for fire detection & suppression alarm sys encl
LUNFALL,A E Baltimore Gas & Electric Co 00/06/20 10pp

J Insurance & indemnity information

0004040838 Forwards Endorsements 12 & 13 to MLIA Policy NS-340
SHENKEL,L B Baltimore Gas & Electric Co 00/06/13 3pp

K Operating license stage documents & interdependencies

0004040838 Comments on proposed rule 10CFR50 items of lesser importance should not be used w/requirements to report items of actual potential hazard to public Separate & distinct reporting mechanism should be established
HUBBELL,L B Baltimore Gas & Electric Co 00/05/02 3pp

0004040916 Forwards add TH1-2 related requirements to operating reactor license requirements due TH1 Action Plan include shifts morning, evening exams & licensee determination of operating experience Response requested within 30 days
EISENHUT,D G Division of Licensing 00/05/07 15pp

0004041012 Requests comments on NUREG-0577, "Potential for Low Pressure Tightness & Leakage Testing on PWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule encl
EISENHUT,D G Division of Licensing 00/05/19 7pp

0004040929 Confirms 000502 telcon re plans to establish adequate neutron monitoring program in support of required entries into reactor bldg ALPHA evaluation must be established & documentation submitted by Region 1
GRUBER,B H Region 1 Philadelphia, Office of the Director 00/05/02 3pp

0004040930 Advises that interim reliability evaluation program resulting from TH1 action plan will be implemented Requests attendance at 000401 meeting in Bethesda, MD to discuss details
EISENHUT,D G Division of Licensing 00/05/02 3pp

0004050114 Responds to NRC ltr re request for add info on partial loop operation info required in support of 790405 application for amend to OLA to allow operation w/less than four reactor coolant pumps
LUNFALL,A E Baltimore Gas & Electric Co 00/05/07 10pp

0004050217 Notification of 000405 meeting w/att in Bethesda, MD to discuss interdependencies in off-site power sources for facilities
CHERN,E L Operating Reactors Branch 3 00/05/07 3pp

0004050244 Notification that implementation of emergency procedures & reviewing re accidents & transients will be completed within three months of NRC review & approval of guidelines submitted re 000401
LUNFALL,A E Baltimore Gas & Electric Co 00/05/05 3pp

0004050207 Submits add info requested by NRC re application for amend of license 30R-551 & 30R-552 Electropolishing method will be used in decontaminating main steamlines of spent fuel pool structure indicates no problem exists w/increased loads
ASH,E F Baltimore Gas & Electric Co 00/05/20 1p

0004050104 Discusses review of 000321 proposal Proposal is satisfactory re NUREG-0578 Category B requirements for high temp effluent monitors Monitors should be provided for release gas monitoring from C-1000 w/cubic container
CLARK,R A Operating Reactors Branch 3 00/04/04 3pp

0004050145 Notification of 000410 meeting w/att in Bethesda, MD to discuss interim reliability evaluation program
LUNFALL,A E Operating Reactors Branch 1 00/04/09 3pp

0004050101 Submits trip report of participation in MD Commission on Environmental Cooperation 000403 meeting in Annapolis, MD re nuclear waste mgt & disposal
CHERN,E L Operating Reactors Branch 3 00/06/13 2pp

0004050101 Requests participation in MD Commission on Environmental Cooperation 000403 & 17 meeting in Annapolis, MD re nuclear waste mgt problem Specific questions encl
EISENHUT,D G Maryland, State of 00/05/20 3pp

0004050101 Confirms arrangements for participation in MD Commission on Environmental Cooperation meeting in Annapolis, MD re spent fuel storage Revised agenda encl
EISENHUT,D G Office of State Program, Director 00/05/20 3pp

0004050101 Testimony at MD Commission on Environmental Cooperation 000403 hearing in Annapolis, MD re spent fuel storage Outline of EL Comm comments encl
LUNFALL,A E Georgia, State of 00/06/03 0pp

0004050107 Testimony at MD Commission on Environmental Cooperation 000403 hearing re spent fuel storage Background info for hearing encl
CHERN,E L Energy Dept of 00/06/03 41pp

0004050300 Responds to NRC 000513 ltr requesting info re possibility of tracking in low pressure turbine disk site specific generic information water chemistry & steam generator chemistry is provided
LUNFALL,A E Baltimore Gas & Electric Co 00/06/16 3pp

0004050001 Notification of 000405 meeting w/att in Bethesda, MD to discuss structural design of proposed mode to spent fuel pool
CHERN,E L Operating Reactors Branch 3 00/06/16 1p

0004050330 Forwards nonproprietary info re LOCA portion of application for amend to OLA Affidavit encl Proprietary version withheld (re 10CFR2 7901)
CLARK,R A Baltimore Gas & Electric Co 00/04/17 7pp

0004050270 Submits responses to add TH1-2 related requirements per 000507 request
LUNFALL,A E Baltimore Gas & Electric Co 00/06/10 3pp

Q Inspection reports, IG Submittal & correspondence

0004050110 Forwards 16 Insp Rpts 50-317/86-03 & 50-318/86-03 on 000310-2E Mo examinations held
EISENHUT,D G Region 1 Philadelphia, Reactor Operations Nuclear Support Branch 00/04/25 3pp

DOCKETED ITEMS

- 8004170441 Revised emergency response plan
* Baltimore Gas & Electric Co 80/04/30 250p
- 8004180250 Forwards response to item 3 of 13.3.2.1-3 of 3.3.2.4 & 3.3.2.5 of NRC 50.6141 for fire protection safety evaluation & amendments to GL Certification statement for fire detection & suppression alarm systems
LUNDAVALL, A E Baltimore Gas & Electric Co 80/04/20 10pp
- ✓ Insurance & indemnity information
- 8004180338 Forwards Entersystems 12 & 13 to RELIA Policy 98-348
CHENHART, E L Baltimore Gas & Electric Co 80/04/13 3pp
- ✓ Operating license stage documents & correspondence
- 8004180359 Comments on proposed rule 10CFR390 items of lesser importance should not be mixed with requirements to report items of actual potential hazard to public. Separate & distinct reporting mechanisms should be established.
RUSSELL, L B Baltimore Gas & Electric Co 80/05/02 2pp
- 8004180665 Forwards add THO-2 related requirements to operating reactor license requirements for the Action Plan include shifts meaning, licensing issues & license dissemination of operating experience responses requested within 30 days
WIDEMUTH, D G Division of Licensing 80/05/02 150p
- 8004180912 Requests comments on NUREG-0577, "Potential for Low Pressure Rupture & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Requests - Proposed Review Procedure & Implementation Schedule" encl
WIDEMUTH, D G Division of Licensing 80/05/19 72p
- 8004180985 Confirms 800592 action plan to establish adequate neutron monitoring program in support of required entries into reactor blog ALARA evaluation must be established & documentation submitted by Region 1
O'BRIEN, B H Region 1, Philadelphia, Office of the Director 80/05/28 2pp
- 8004180985 Advises that interim reliability evaluation program resulting from the action plan will be implemented. Requests attendance at 800504 meeting in Bethesda, MD to discuss details
WIDEMUTH, D G Division of Licensing 80/05/28 2pp
- 8004180985 Responds to ABC list & request for addl info on partial loop operation info required in support of 790405 application for amend to GL to allow operation unless than four reactor coolant pumps
LUNDAVALL, A E Baltimore Gas & Electric Co 80/05/27 10pp
- 8004180985 Notification of 800505 meeting w/etl in Bethesda, MD to discuss improvements in offsite power sources for facilities
CHENHART, E L Operating Reactors Branch 3 80/05/27 3pp
- 8004180985 Notifies that implementation of emergency procedures & retreating re accidents & emergencies will be completed within three months of NRC review & approval of guidelines submitted on 800401
LUNDAVALL, A E Baltimore Gas & Electric Co 80/05/30 3pp
- 8004180985 Submits addl info requested by NRC re Application for amend of License 09N-35 & 09N-36 for electric generating method will be used to decommissioning reactor. Summary of spent fuel pool structure indicates no problem exists with increased loads
ABRAHAM, F Baltimore Gas & Electric Co 80/05/30 1p
- 8004180985 Comments review of 800502 proposal. Proposal is satisfactory w/ NUREG-0570 Category 1 requirements for high pressure effluent monitors. Monitors should be provided for release rate measuring from 5-1000 w/40% reaction
CLARK, R A Operating Reactors Branch 3 80/05/04 0pp
- 8004180985 Summary of Startup Testing for Third Cycle
LUNDAVALL, A E Baltimore Gas & Electric Co 80/06/12 3pp
- 8004180985 Summary of Startup Testing for Third Cycle
* Baltimore Gas & Electric Co 80/06/12 7pp
- 8004180985 Submits trip report of participation in MD Commission on Intergovernmental Cooperation 800403 meeting in Annapolis, MD re nuclear waste mgmt & disposal
CHENHART, E L Operating Reactors Branch 3 80/06/13 2pp
- 8004180985 Requests participation in MD Commission on Intergovernmental Cooperation 800403 & 12 meeting in Annapolis, MD re nuclear waste mgmt & disposal
KASTNER, J H Maryland, State of 80/06/08 2pp
- 8004180985 Confirms arrangements for participation in MD Commission on Intergovernmental Cooperation hearing in Annapolis, MD re spent fuel storage. Revised agenda encl
CHENHART, E L Office of State Programs, Director 80/06/09 5pp
- 8004180985 Testimony at MD Commission on Intergovernmental Cooperation of EL Center comments encl
LANS, G M Georgia, State of 80/06/03 3pp
- 8004180985 Testimony at MD Commission on Intergovernmental Cooperation 800403 hearing in Annapolis, MD re spent fuel storage. Background info for hearing encl
CHITZ, H G Energy Dept of 80/06/03 4pp
- 8004180985 Notification of 800408 meeting w/etl & NEN in Bethesda, MD to discuss structural design of proposed need to spent fuel pool
CHENHART, E L Operating Reactors Branch 3 80/06/04 1p
- 8004180985 Forwards nonproprietary info re LSCA portion of application for amend to GL Affidavit encl. Proprietary version withheld
Group 100502 PMS
CLARK, R A Baltimore Gas & Electric Co 80/06/17 7pp
- 8004180985 Submits responses to addl THO-2 related requirements per 800507 request
LUNDAVALL, A E Baltimore Gas & Electric Co 80/06/18 3pp
- ✓ Inspection reports, IE Docketing & correspondence
- 8004180985 Forwards IE Insp Repts 50-317/80-03 & 50-318/80-03 on 800313-03 re noncompliance noted
BRUNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/25 3pp
- 8004180985 IE Insp Repts 50-317/80-03 & 50-318/80-03 on 800313-03 re noncompliance noted. Major areas inspected: control room & accessible portions of auxiliary, turbine, etc. & intake bldgs. Violation pertains physical security & fire protection
ARCHITZEL, M Region 1, Philadelphia, Office of the Director
MCARD, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/24 3pp
- 8004180985 Forwards IE Insp Repts 50-317/80-04 & 50-318/80-04 on 800313-04 & notice of violation. Notice of violation withheld (ref 100502 PMS)
MATTIA, W D Region 1, Philadelphia, Safeguards Branch 80/05/08 2pp
- 8004180985 IE Insp Repts 50-317/80-04 & 50-318/80-04 on 800313-04 re noncompliance noted. Failure to report changes to security plan & failure to positively control access to vital areas. Details withheld (ref 100502 PMS)
SERLIN, J M Region 1, Philadelphia, Safeguards Branch
BARTLEY, R J, HOSBORN, L M Region 1, Philadelphia, Office of the Director 80/05/01 2pp
- 8004180985 Responds to IE Docketing 79-00A re longitudinal weld defects in 4NRE 5A-2E Type-304 stainless steel pipe stress calculations performed on specified pipe. Results indicated no pipes loaded to max value greater than code allowable
LUNDAVALL, A E Baltimore Gas & Electric Co 80/05/30 1p
- 8004180985 Updates response to IE Docketing 79-01D, "Environ Qualification of Class IE Equipment - Forwards list of safety-related equipment installed below threshold in ps 10 intake. Outstanding items items to be completed by 800530
LUNDAVALL, A E Baltimore Gas & Electric Co 80/05/27 3pp
- 8004180985 Forwards IE Circular 90-13, "Orbit Drap Damage in Westinghouse Fuel Assembly - RE written response required
O'BRIEN, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8004180985 Forwards response to IE Docketing 80-19, "Decay Heat Removal Gas Operability - Summary of Decay Heat Incident would not cause loss of shutdown cooling w/air blading of gas at facilities
GIBBS, J W Baltimore Gas & Electric Co 80/06/09 3pp
- 8004180985 Forwards addl response to IE IE Notice 79-04 providing verification of accuracy of electric distribution systems. Voltage tests Results confirm calculations
CLARK, R A Baltimore Gas & Electric Co 80/06/20 2pp

DOCKETED ITEMS

119

0004000676 Response to 000500 ltr re compliance w/financial protection requirements for Unit 2 Reactor enhancement for add 420 million not received. NRC unable to determine compliance info re alternatives to insurance requested
BARRYMAN, J Utility Finance Branch 00/04/13 2pp

0 Advisory Committee on Reactor Safeguards reports & correspondence

7004000476 Forward recommendations for studies to improve reactor safety in areas of accident analysis, reduction of accident probability, operating procedure review of design, content & operation, decay heat removal system in BWRs & other items
CARROLL, M W ACSS - Advisory Committee on Reactor Safeguards 7/0/04/14 4pp

0004130181 Summary of ACSS Ad Hoc Subcommittee on TH-2 Accident Investigations 000409 meeting in Washington, DC re accident implications as relating to CP Regulations List of attendees incl:
ACSS - Advisory Committee on Reactor Safeguards 00/04/29 32pp

Operating license stage documents & correspondence

0004130503 Discrepancy need to upgrade reliability of power operated relief valve & define function of valve reliability can be understood & demonstrated by testing studies would include input from HERS vendor & valve manufacturer
DIAH, R C Operating Reactors Branch 4 (P) 00/04/20 00/05/19 4pp

0004130109 Submit info re LAR primary coolant sys pressure isolation valves are significant contributor to risk from Event 5 accident. Submit data required to determine whether license should be modified
EISENHUT, D O Division of Operating Reactors 00/03/03 40pp

0004130377 Lists sys mods necessary to support fast purge of reactor & identify to license database is systematic hydrogen control package preferred due to fewer mods required
GREENBURG, M TH Program Office 00/04/20 3pp

0004000509 Activities that consent period for HERS-0462 extended until 00/05/16 Ack receipt of 000411 comments
ALBRECHT, J F Consentation 00/03/05 1p

0004000993 Requests extension of consent period to reflect UCB study on Air-QD cooling
THOMPSON, W B Pennsylvania, State of 00/04/11 3pp

0004000507 Forward A Chl 000420 ltr recommending Hitachi staff member for temporary position w/Unit 2 cleanup staff Response should be directed to A Chl at Hitachi re F Hasebe participation
LAPL, K W J Office of International Programs Director 00/05/06 1p

0004000533 Ack receipt of 000212 ltr re H Hasebe re TH cleanup program Progress meeting F Hasebe as participant Background & qualification and Request details about cleanup program
CHL, A Japan 00/04/20 2pp

0004000100 Response to 000321 ltr re still possible financial failure Financial failure provides grounds for license revocation No contingency plans completed to cover possibility of financial failure
BERRYMAN, J F Consentation 00/05/07 2pp

0004000302 Inquiries as to aftermath of still financial failure
BERRYMAN, J F Pennsylvania, State of 00/03/21 2pp

0004000145 Forward add TH-2 related requirements to operating Reactors License Requirements for TH Action Plan include add training, licensing, name & license administration of operating experience Response requested within 30 days
EISENHUT, D O Division of Licensing 00/03/07 15pp

0004000232 Response to questions posed by JF Abernethy re proposed purging of facility containment bldg atmosphere Response that slow purging method be used to assure that doses to public are low
DEBIA, M W Office of Nuclear Reactor Regulation, Director, DEW-00-132C 00/03/08 1pp

0004000407 "Detonations of A-05 from TH Nuclear Plant," reph to Governor of Pa.
HENDON, R W, BERRYMAN, J, EISENHUT, D Union of Concerned Scientists 00/05/19 7pp

0004000131 Requests drawings & specs for evaluation of EPICOR-11 liners re waste handling, storage, transportation & disposal info & info should be received by 000500 to resolve safety
Forwarded BUL reph
COLLINS, J T TH Program Office 00/05/13 3pp

0004000117 Forwarded BUL reph to disposal of first stage EPICOR-11 organic resin wastes Other reactor operators should be alerted for solidification efforts
BERRYMAN, J F Division of Waste Management 00/05/03 2pp

0004000118 Forwarded "Status Report on Leachability Structural Integrity & Radiation Stability of Ion Exchange Resins Solidified in Cement & Cement Additives"
BERRYMAN, J F, BERRYMAN, J E, BERRYMAN, J E Brookhaven National Laboratory 00/05/03 1p

0004000119 "Status Report on Leachability Structural Integrity & Radiation Stability of Organic Ion Exchange Resins Solidified in Cement & Cement Additives"
BERRYMAN, J E, BERRYMAN, J E, BERRYMAN, J E Brookhaven National Laboratory 00/05/03 2pp

0004000321 Reviewer that NRC will assess submitted repts & data re animal health effects re site vicinity Requests draft pathological specimen reph re 000406 Paper will be used in larger reph being prepared by NRC
HALL, D R Assistant Director for Environmental Technology 00/05/16 1p

0004000319 Approves 000420 request to use Mine Safety & Appliances Co breathing units in lieu of BSC Service BSC Pan Air 40 units One entry may be made into reactor bldg Related correspondence
COLLINS, J T TH Program Office 00/05/16 4pp

0004000409 Requests add info to complete review of 000410 reph as summarized demeritized sys re summarized demeritized sys
COLLINS, J T TH Program Office 00/05/16 1pp

0004130510 Forwarded request for add info re evaluation of unit EPICOR technical evaluation reph re summarized demeritized sys
COLLINS, J T TH Program Office 00/05/16 1pp

0004130819 Response to 000420 request for add to reactor bldg re use of Mine Safety & Appliances Co breathing units Grants approval to make 000420 entry into reactor bldg Local officials should be given reph notification
COLLINS, J T TH Program Office 00/05/16 4pp

0004000384 Forwarded Vilas Industries 000500 memo re present status of fuel handling & auxiliary bldg decontamination program
BERRYMAN, J F General Public Utilities - GCU Service Corp 00/05/19 17pp

0004130122 Requests comments on HERS-0377, "Potential for Low Pressure Toughness & Lateral Tearing on RW Drain Generator & Reactor Coolant Pump Support - Proposed review procedure & implementation schedule incl
EISENHUT, D O Division of Licensing 00/05/19 72pp

0004000377 Forwarded staff reph, "Assess the Questions about Removing Nupton from TH-2 Reactor D16" Rept responds in question answer format to frequently asked questions about venting
BERRYMAN, J F TH Program Office 00/05/20 1p

0004000202 Requests guidance for implementing 000407 interim criteria for radiological effluents from TH-2 data gathering & ambient operations
BERRYMAN, J F TH Program Office 00/05/20 2pp

0004000204 Submit J. Cochran 000507 statement re TH-2 containment atmospheric cleanup Public health risks insignificant
BERRYMAN, J F TH Program Office 00/05/20 1p

0004000329 Forwarded "Analysis of Hypothetical Accidents Technical Evaluation Rept. Submerged Demeritized Sys. App 1" calculations supporting statements in "Technical Evaluation Rept." Chapter 7
HDEY, P A Metropolitan Edison Co 00/05/27 2pp

0004000307 "Analysis of Hypothetical Accidents Technical Evaluation Rept. Submerged Demeritized Sys. App 1"
HDEY, P A Metropolitan Edison Co 00/05/27 15pp

0004000349 Requests specific info for status & schedule of installation re implementation of new sensitive instrument for monitoring of RCU water chemistry & corrosion control
COLLINS, J T TH Program Office 00/05/27 4pp

- 0004126079 Act receipt of 0004099 for describing cryogenic separation process for removal of H₂SO₄ from reactor-bldg air. Enhancement alternatives are being evaluated. Proposal being considered on comment on NRC/05/04/02. SIVKIN, J. J. Int. Program Office. 05/05/07 1p
- 0004126079 Describes cryogenic separation process developed for removal of H₂SO₄ from reactor containment bldg. Basic process scheme is to limit cryogenic air separation plant to bldg atmosphere in closed recirculation. LEPAGE, M. Milne Corp. 05/04/05 3pp
- 0004090262 Forwards recovery operations plan change Request 1 re elimination of RCP diesel & 12.24v line surveillance requirements Request made subsequent to Tech Spec Change Request 20. HONEY, G. K. Metropolitan Edison Co. 05/05/06 2pp
- 0004090228 Forwards final version of "Resin Solidification Test Program for EPICOR II Resins." a. Withman Nuclear & Development Corp. (a/c Withman Corp.) 05/05/06 41pp
- 0004090231 Final version of "Resin Solidification Test Program for EPICOR II Resins." a. Withman Nuclear & Development Corp. (a/c Withman Corp.) 05/05/06 41pp
- 0004090104 Informs that since proposed cleanup was not NRC approved, installation & purchase of equipment at unit risk. Contingency plan re transfer of untreated water to waste tanks should be quickly completed. DEBARTH, R. Office of Nuclear Reactor Regulation, Director. 05/05/06 4pp
- 0004120250 Advises that approval of submerged denitrifier was for decontaminating containment sump water must be preceded by NRC engineering. NRC Unit 1 sump of contaminated water to transfer untreated water to suitably shielded waste tanks. DEBARTH, R. Office of Nuclear Reactor Regulation, Director. 05/05/06 3pp
- 0004090338 Recovery operation plan Tech Spec Change Request 1 re elimination of balance of plant diesel & 12.24v line surveillance requirements Replacement Pages 4-8-1 to 4-8-3. 05 plan only. HONEY, G. K. Metropolitan Edison Co. 05/05/06 2pp
- 0004090207 Reviews submittal date to second quarter of 1981 for long-term solid radioactive storage facility recommendations. Recommendations will be in form of design criteria document. HONEY, G. K. Metropolitan Edison Co. 05/05/06 1p
- 0004090200 Responds to NRC 000410131 re use of term "operable" as applied to single failure criterion for safety systems in power reactors. Requests extension until 000920 for Unit-1 Tech Spec change No change required for Unit-2. HONEY, G. K. Metropolitan Edison Co. 05/05/06 1p
- 0004090204 Responds to NRC 000513 request for info re design & cost for EPICOR II lines & resins. Info will be provided by 000530. HONEY, G. K. Metropolitan Edison Co. 05/05/06 1p
- 0004090264 Responds to NRC 000410131 re use of term "operable" applying to single failure criterion for safety systems in power reactors. Performing review of Unit 1 Tech Spec to determine need for Unit 2 operating under recovery Tech Spec. HONEY, G. K. Metropolitan Edison Co. 05/05/06 2pp
- 0004120204 Notifies that data for submittal of recommendations for long-term solid radioactive storage facility has been changed to second quarter 1981. HONEY, G. K. Metropolitan Edison Co. 05/05/06 2pp
- 0004120217 Responds to NRC 000513 request for info re design, cost & preparation of specific data concerning EPICOR II lines & resin tanks will be provided by 000530. HONEY, G. K. Metropolitan Edison Co. 05/05/06 2pp
- 0004090261 Ack receipt of Council Resolution 118 sent to Commissioner. Assumes that resolution will be considered NRC is currently preparing final nuclear assessment of alternatives to decontaminating facility. DEBARTH, R. Office of Nuclear Reactor Regulation, Director. 05/05/06 1p
- 0004090265 Forwards copy of Council Resolution 118, adopted 000537. Resolution memorializes General of Pa. & NRC re prompt further venting of radioactivity into various W/G acid. SCHMIDT, D. J. Philadelphia, PA. 05/05/06 1p
- 0004090204 Provides add'l info re questions on NRC-proposed purging of containment bldg atmosphere. Recommendations were given in NRC-90-120C Supplemental view purge info incl. DEBARTH, R. Office of Nuclear Reactor Regulation, Director. 05/05/06 3pp
- 0004090348 "Comparison of Controlled Purge & Application of Selective Absorption Process Alternatives for Decontamination of TH-2 Reactor Bldg Atmosphere." Preliminary Draft. THOMAS, C. D., VOLLEBAUGH, G. C., CLINE, J. E. Science Applications, Inc. 05/05/01 49pp
- 0004090207 "Review Assessment of Radiological Effluents From Sump Gathering & Heat Operation on The Unit 2." a. Int. Program Office. NRC/05/06/05 05/05/06 10pp Available at NRC.
- 0004110070 Notifies that filter housing purge test has been modified to add dynamic test w/rapid closing of inlet to filter housing/automatic fan shut off. Performing at negative 15 inches water gauge. HONEY, G. K. Metropolitan Edison Co. 05/06/03 1p
- 0004110020 Advises that filter housing testing program has been modified to add dynamic test w/rapid closing of inlet to filter housing/automatic fan shut off. Performing at negative 15 inches water gauge. HONEY, G. K. Metropolitan Edison Co. 05/06/03 2pp
- 0004110018 Advises that response to 000516 request re submerged denitrifier was technical evaluation requested by 000516. HONEY, G. K. Metropolitan Edison Co. 05/06/04 1p
- 0004110014 Advises of intent to remove plant ventilation stack cap & discontinue use of supplemental ventilation sump sump. Auxiliary sump on or about 000516. Airborne radioactivity levels have decreased to point that use no longer justified. HONEY, G. K. Metropolitan Edison Co. 05/06/04 3pp
- 0004110045 Forwards "Transient Boron Concentration Analysis in TH-2 Mini-Degay Heat Removal Sys. (MDHRS)", providing results of analysis of transient & steady state effects on boron concentration. Unit can be maintained in use in operation. HONEY, G. K. Metropolitan Edison Co. 05/06/04 1p
- 0004110048 "Transient Boron Concentration Analysis in TH-2 Mini-Degay Heat Removal Sys. (MDHRS)." a. Withman Nuclear & Development Corp. 05/06/04 18pp.
- 0004110017 Responds to "Resin Solidification Test Program." in response to 791201. It is proposed method for solidification of EPICOR-II resins. Program summary & 000516 scope of work with Nuclear & Development Corp. and. HONEY, G. K. Metropolitan Edison Co. 05/06/05 10pp
- 0004110017 "Resin Solidification Test Program." a. Metropolitan Edison Co. 05/06/05 4pp
- 0004120274 Forwards EPICOR-II solidification program summary, description of scope of work withman Nuclear & Development Corp. & Withman Corp. "Resin Solidification Test Program." per mail 791201 considered. HONEY, G. K. Metropolitan Edison Co. 05/06/05 13pp
- 0004120277 "Resin Solidification Test Program." a. Withman Nuclear & Development Corp. (a/c Withman Corp.) 05/06/05 4pp
- 0004120256 Forwards "TH-2 Planning Study for Phase II - Reactor Secondary Assembly, Fuel Removal & Dry Cleanup." Report available in Central Files only. LEPAGE, M. J. Metropolitan Edison Co. 05/06/06 1p
- 0004120292 Forwards Data re General Public Utility info capabilities, peak load, reserve capacity, net gen requirements & interchange. BUNICK, S. General Public Utilities - GCU Service Corp. 05/06/01 3pp
- 0004090204 Advises that work efforts are proceeding on generating design criteria for interim solid radioactive storage facility. Facility will provide area to enable low level radioactive prior to offsite shipment design will be submitted Jul 1980. HONEY, G. K. Metropolitan Edison Co. 05/06/02 1p
- 0004090204 Forwards Tech Spec Change Request 25, requesting amend to App A of License 059-73 Amend delete requirement for specially furnished interlock between HP-8-225 & HP-8-226 & purge exhaust ductwork. ANSLAN, C. K. Metropolitan Edison Co. 05/06/23 3pp

DOCKETED ITEMS

8504020219 PHO-THI-90-021 on 850520, licensee determined that containment integrity not maintained for period of 2-5 minutes caused by purge valve on sulfur dioxide loop. Permitting flow from atmosphere into reactor lid. COFFEY, R. J. BARRY, M. J. COLLINS, J. T. Region I, Philadelphia. Office of the Director 85/05/23 1p

8504130236 PHO-THI-90-022 on 850523, worker experiencing chest pain left site in ambulance. Diagnosis was possible heart attack. Unknown if individual was in radiological area. COFFEY, R. J. BARRY, M. J. COLLINS, J. T. Region I, Philadelphia. Office of the Director 85/05/23 1p

8504030445 Forwards LER 80-015/03L-0
HANEY, D. K. Metropolitan Edison Co 85/05/28 1p

8504030470 LER 80-015/03L-0 on 850428, sulfur acid was tank barrel misconnected, exceeded Tech Spec. Caused by connecting effects from evaporation due to use of air sparger mixing apparatus. Water added & use of air sparger discontinued. CHAPLIN, R. D. Metropolitan Edison Co 85/05/28 2pp

8504060520 Forwards LER 80-016/03L-0
HANEY, D. K. Metropolitan Edison Co 85/05/30 1p

8504060571 LER 80-016/03L-0 on 850501, during recovery mode operation, fuel oil tank level found below Tech Spec requirement. Caused by misreading of level during previous check. Oil added & temp frequency increased. CHAPLIN, R. D. Metropolitan Edison Co 85/05/30 2pp

8504100524 Forwards LER 80-018/03L-0
HANEY, D. K. Metropolitan Edison Co 85/06/10 1p

8504100527 LER 80-018/03L-0 on 850509, while loading white balance of plant diesel generator, oscillations observed in generator frequency, followed by total loss of frequency indication. Caused by mechanical shock blowing fan power. Power replaced. CHAPLIN, R. D. Metropolitan Edison Co 85/06/10 1p

8504250199 PHO-Y-90-020 on 850610, 12M drum of low level redwaste received, had broken locking ring & four bad loose locking rings. No significant radioactive contamination. WA cancelled burial permit & buried unit from use of site. THOMAS, R. D. Region 3, San Francisco. Office of the Director 85/06/10 1p

8504250224 Forwards LER 80-019/03L-0
HANEY, D. K. Metropolitan Edison Co 85/06/17 1p

8504250235 LER 80-019/03L-0 on 850518, during recovery mode, 8E size through steam generator level instrumentation became inoperable. Apparently caused by dirt in root valve. Sensing line backflushed, returned to use on 850520. CHAPLIN, R. D. Metropolitan Edison Co 85/06/17 2pp

8504240504 Forwards LER 80-020/03L-0
HANEY, D. K. Metropolitan Edison Co 85/06/17 1p

8504240520 LER 80-020/03L-0 on 850518, during recovery mode operation, fuel handling flow exhaust flow discovered below limits. Caused by failure of universal coupling on manual inlet damper for fans. Damper to be cleaned damper to close. CHAPLIN, R. D. Metropolitan Edison Co 85/06/17 2pp

T Hearing transcript on non-antitrust matters

8504160505 Transcript of 850521 public meeting in Washington, DC re TH1-2 action plan. Pg 1-24
* Commission 85/05/23 72pp

8504160520 Transcript of 850520 public meeting in Washington, DC re TH1 venting. Pg 1-49
* Commission 85/06/05 314pp

8504250119 Transcript of 850416 Affirmation Session 85-28 re TH1 action plan in Washington, DC. Pg 1-4
* Commission 85/06/16 4pp

A. Congressional/Executive Correspondence

8504200119 Act receipt of 850520 & 50 lbs providing availability list of critical components for selective absorption systems & assessment of 150 time needed to install systems at Facility for 85-28 removal. Ltrs will be considered w/related comments. HANSEN, J. F. Commission 85/05/14 1p

8504200114 Forward availability list of critical components for selective absorption systems & assessment of 150 time needed to install systems at Facility for 85-28 removal. Discussed in report prepared by Committee & AGO.
ENTRLE, A. E. House of Rep. Science & Technology 85/05/08 2pp

8504200117 Comments on 85-28 removal time requirements identified by TH1 overstated. Selective absorption systems discussed in act. Ltrs could be installed & operating within 6 months.
ENTRLE, A. E. House of Rep. Science & Technology 85/05/09 1pp

8504200207 Helms requested info for 850520 hearing re TH1-2 cleanup. Congressman Ernst 850520 Ltr is incorrect in stating that TH1 cleanup was never afforded serious consideration by NRC. Chronology of NRC cleanup efforts being prepared.
HANEY, D. K. TH1 Program Office 85/05/19 2pp

8504200201 Recommendations that necessary preparations begin so that Citizens Advisory Panel for consulting & advising NRC re decontamination & decommissioning of TH1-2 can be established. Proposed legislative amendment.
HANEY, D. K. U.S. House of Rep. 85/05/12 2pp

8504130170 Act receipt of 850519 ltr commenting on report to Governor of PA on 85-28 removal methods & providing Water Cons. proposal. For cryogenic separation process. Concerns & info will be considered w/related comments prior to final decision.
HANEY, D. K. Commission 85/05/21 1p

8504130173 Discusses report to Governor of PA re 85-28 removal methods. Report should have NRC in decision making for 85-28 removal.
ENTRLE, A. E. House of Rep. Science & Technology 85/05/15 2pp

8504130176 Forwards discussion re possibility of separating installation & use of cryogenic process possibly applicable for removal of 85-28 from reactor. Report should be given fair consideration.
ENTRLE, A. E. House of Rep. Science & Technology 85/05/15 2pp

DOCKET 90-201 REWIN 3 WATCH NUCLEAR PLANT, UNIT 1

For information, medical, emergency & fire protection plans

8504250287 Forwards proposed rule entitled: "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101". Rule added new Section 30.40 & 40.5 to 10CFR30 & is expected to be published in FR by end of FY.
FERRELL, D. D. Division of Licensing 85/05/19 4pp

8504150543 Forwards revised Pages 1-14 & new Page 14a for proposed rule (10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101") transmitted by NRC 850519.
ICR Page 14a not null.
FERRELL, D. D. Division of Licensing 85/05/22 72pp

8504250261 Forwards revised guard training & qualification plan. Plan withheld after 10CFR2 7901.
HANEY, M. A. Georgia Power Co 85/05/20 1p

8504250262 Requests review of emergency plan against evaluation criteria of NUREG-0348. Act info required before Emergency Preparedness Review Team can conclude that program is acceptable. Revised plan should be provided by 850718.
REID, R. W. Operating Reactors Branch 4 85/06/04 2pp

I. Financial Information

8504170210 Forwards Annual Financial Report 1979
WILSON, M. A. Georgia Power Co 85/05/11 1pp

8504170214 Annual Financial Report 1979
* The Southern Co 85/05/10 43pp

8504170218 Annual Financial Report 1979
* Georgia Power Co 85/05/20 30pp

P. Operating license stage documents & correspondence

8504200119 Forwards addl TH1-2 related requirements to operating reactors. License requirements for TH1 Action Plan include shift training, licensing exams & license dissemination of operating experience. Response requested within 30 days.
FERRELL, D. D. Division of Licensing 85/05/07 150pp

- 0006020184 Summary of 000422-23 meeting with 1 source group in San Juan, CA re conformity analysis 1 testing program
Examining Mark 1 containment long-term program
0006020184 Assistant Director for Plant Systems 00/05/09 App
- 0006020182 Requests comments on NRC-0077, "Potential for Low Pressure Troughs & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Headers - Proposed review procedure & implementation schedule incl
ETSD0007.0 0 Division of Licensing 00/05/09 72pp
- 0006020176 Advances that responses to SE generic analysis re effect of reactor supply failure on ECCS performance will be provided by 000604 per NRC 000428 request
MID000.0 A Georgia Power Co 00/05/09 1p
- 0006020170 Forwards unique analysis report comparing effects of at power failure of ECCS performance w/SE generic analysis
MID000.0 A Georgia Power Co 00/05/09 3pp
- 0006020164 Ltr to all NRC licensees forwarding "For Comment" edition of ASME-DIV. 1, "ASME Pressure Vessel & Control Rod Drive Return Line Morale Cracking." Comments will be evaluated by NRC prior to final implementation. W/ re
ETSD0007.0 0 Division of Licensing 00/05/09 20pp
- 0006020140 Submits info re turbine rotor disc cracking in response to NRC 000312 request Unit 1 has experienced approx 80 turbine trips 1 approx flow over-speed Unit 2 has experienced approx 20 turbine trips & approx flow over-speed
MID000.0 A Georgia Power Co 00/05/10 4pp
- 0006020130 Forwards Amend 75 to License EPR-97, safety evaluation & notice of issuance & availability
REID.0 M Operating Reactors Branch 4 00/06/10 2pp
- 0006020128 Amend 75 to License EPR-97, changing Tech Specs to remove current restriction on operating limit on critical power
REID.0 M Operating Reactors Branch 4 00/06/10 4pp
- 0006020128 Safety evaluation supporting Amend 75 to License EPR-97
Office of Nuclear Reactor Regulation, Director 00/06/10 1pp
- 0006020122 Notice of issuance & availability of Amend 75 to License EPR-97
REID.0 M Operating Reactors Branch 4 00/06/10 2pp
- 0006020109 Forwards Amend 75 to License EPR-97 & notice of issuance & availability
REID.0 M Operating Reactors Branch 4 00/06/10 2pp
- 0006020107 Amend 75 to License EPR-97, requiring direct fuel sampling at least once every 90 days
REID.0 M Operating Reactors Branch 4 00/06/10 3pp
- 0006020107 Notice of issuance & availability of Amend 75 to License EPR-97
REID.0 M Operating Reactors Branch 4 00/06/10 2pp
- 0006020092 Forwards draft NRC licensing position: "Safety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating reports
REID.0 M Operating Reactors Branch 4 00/06/10 10pp
- 0 Inspection reports, IF Bulletins & correspondence
- 0006020093 Forwards IF Circular 00-08, "SMR Tech Spec Inconsistency - Reactor Protection Sys Response Time" No written response required
O'REILLY.0 F Region 2, Atlanta, Office of the Director 00/04/10 2pp
- 0006020077 Forwards IE Insp Repts 00-321/00-12 & 00-366/00-12 on 000305-19 & notice of violation
O'REILLY.0 F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/12 2pp
- 0006020073 Notice of violation from insp on 000305-19
Region 2, Atlanta, Office of the Director 00/04/02 1p
- 0006019777 IE Insp Repts 00-321/00-12 & 00-366/00-12 on 000310-19 Noncompliance noted failure to start turbine monitoring when required
O'REILLY.0 F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/12 2pp
- 0006019777 Forwards IE Insp Repts 00-321/00-12 & 00-366/00-12 on 000402-04 No noncompliance noted
MID000.0 E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/09 2pp
- 0006019704 IE Insp Repts 00-321/00-12 & 00-366/00-12 on 000402-04 No noncompliance noted Major areas inspected installed equipment per IE Bulletin 79-010 responses
O'REILLY.0 F Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/09 2pp
- 0006019675 Forwards IE Bulletin 00-11, "Passing Wall Design" Requires action & written response IE Info Notice 79-20
"Overloading of Structural Elements Due to Pipe Support Load" incl
O'REILLY.0 F Region 2, Atlanta, Office of the Director 00/05/08 2pp
- 0006019626 Forwards IE Bulletin 00-12, "Sway Heat Removal Eye Operability" No written response required IE Info Notice 00-20, "Loss of Decay Heat Removal Capability at Swinburne Unit 1 while in Refueling Mode" NRC
O'REILLY.0 F Region 2, Atlanta, Office of the Director 00/05/09 2pp
- 0006019036 Forwards IE Insp Repts 00-321/00-11 & 00-366/00-21 on 000419-10 No noncompliance noted
LEWIS.0 E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/12 2pp
- 0006014007 IE Insp Repts 00-321/00-21 & 00-366/00-21 on 000419-10 No noncompliance noted Major areas inspected surveillance activity on pipe supports & restraint apparatuses test results installed restraints & restraints
LEWIS.0 E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/06 3pp
- 0006013018 Requests info re ultimate stage of low pressure turbines to learn more about underlying causes for indications found & probable rate of growth, indications & effects on turbine disk integrity
REID.0 M Operating Reactors Branch 4 00/05/13 4pp
- 0006013019 Forwards IE Circular 00-15, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required
O'REILLY.0 F Region 2, Atlanta, Office of the Director 00/05/13 2pp
- 0006013027 Inform NRC that limit switches used for position indication were not included in 45-day response to IE Bulletin 79-010
Written notification of switches should be addressed AC in process of specifying qualified replacement switches
MID000.0 A Georgia Power Co 00/05/13 1p
- 0006010028 Ack receipt of 000428 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 00-321/00-06 & 00-366/00-06
LEWIS.0 E Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/05/21 1p
- 0006009335 Response to NRC 000331 ltr re deviations noted in IE Insp Repts 00-321/00-06 & 00-366/00-06 Corrective action, revised procedures (00-1) & 00-1002 & 00-1003 & 00-1004 to eliminate unwanted operator action section
MID000.0 A Georgia Power Co 00/04/08 2pp
- 0006009340 Forwards IE Insp Repts 00-321/00-06 & 00-366/00-06 on 000419-21 & notice of violation
LEWIS.0 E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/03/01 2pp
- 0006009342 Notice of deviation from insp on 000319-21, 000419-21
Region 2, Atlanta, Office of the Director 00/03/08 1p
- 0006009347 IE Insp Repts 00-321/00-06 & 00-366/00-06 on 000319-21, 000419-21
Noncompliance noted failure to ensure that licensed operators have conducted to safety immediate emergency procedure action
MID000.0 F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/03/08 2pp

--0004030482 LER 80-044/02L-0 on 000094, during normal full power operation, primary containment bagged concentration exceeded allowable limit. Caused by operator failure to initiate divergent makeup to dropfill prior to reaching limit.
* Georgia Power Co 00/05/02 2pp

0004030361 PNO-10-00-095 on 000034, facility shut down to repair leakage past vent of LPCI valve. Licensee previously closed adjacent valve to stop leakage.
TAVEL, P. A. / GARCIA, R. C. Region 2, Atlanta, Office of the Director
00/05/02 1p

0004030348 LER 80-021/100-003 on 000034, discovered that loss of essential motor control cut 10A(820-2011) or loss of signal generator 1A during loss of offsite power will cause RWB & core spray & loops to be inoperable. Caused by faulty valve.
HARRY, H. Georgia Power Co 00/05/02 2pp

0004030347 Forwards LER 80-040/03L-0
HARRY, H. Georgia Power Co 00/05/02 1p

--0004030349 LER 80-040/03L-0 on 000094, while performing ABMS inventory pump operability test on plant wet water pump 10, discovered that max allowable flow was 3400 gpm. Caused by faulty pressure indicator on pump discharge.
* Georgia Power Co 00/05/02 2pp

0004030374 R0-021/100-084 on 000036, need revision of cables HQ-1173-010 to HQ-1173-010 found routed w/ I & II type cables/terminals. Caused by design & installation error. Design Change Request 00-165 submitted for cable re-routing.
HARRY, H. Georgia Power Co 00/05/00 1p

0004030387 Forwards LER 80-047/02L-0
HARRY, H. Georgia Power Co 00/06/02 1p

--0004030323 LER 80-047/02L-0 on 000403, during review of normal surveillance testing data sheets, RWB groups A & C flow rate did not meet Tech Spec requirements. Cause not stated. RWB pump surveillance procedure will be revised.
BARRY, S. J. Georgia Power Co 00/06/02 2pp

0004030302 R0-031/100-050 on 000031, standby TM on T22-077, 1-inch instrument line from recirculation loop appeared locked up during visual inspection. Caused by shaker corrosion. Shakers failing surveillance test will be replaced prior to startup.
HARRY, H. Georgia Power Co 00/06/02 2pp

0004170474 Forwards LER 80-050/02L-0
HARRY, H. Georgia Power Co 00/06/03 1p

--0004170480 LER 80-050/02L-0 on 000014, while performing reactor startup, reactor core isolation cooling turbine tripped while attempting pump trip. Cause unknown. Trip may have been due to oversized. Special committee will perform in-depth study.
HARRIS, T. Georgia Power Co 00/06/03 2pp

0004170473 Forwards LER 80-053/01T-0
HARRY, H. Georgia Power Co 00/06/04 1p

--0004170479 LER 80-053/01T-0 on 000034, during normal operation, discovered that loss of power to essential motor control cut 10A(820-2011) or loss of signal generator 1A during loss of offsite power will cause RWB & core spray & loops to be inoperable. Caused by faulty valve.
000035 C. L. Georgia Power Co 00/06/04 2pp

0004190378 Forwards LER 80-051/03L-0
HARRY, H. Georgia Power Co 00/06/04 1p

--0004190388 LER 80-051/03L-0 on 000034, while investigating testing Sagout-run of testing that began into primary containment not responded acoustically as required. Caused by installation error. Testing will be re-performed per seismic specs.
000035 C. L. Georgia Power Co 00/06/04 2pp

0004190364 Forwards LER 80-054/01T-0
HARRY, H. Georgia Power Co 00/06/10 1p

--0004190374 LER 80-054/01T-0 on 000034, while repairing RWB inboard control valve, engineering staff confirmed that cable separation problem existed & contained atmospheric control gas. Caused by design & installation error.
000035 C. L. Georgia Power Co 00/06/00 2pp

0004190477 Forwards LER 80-053/02L-0
HARRY, H. Georgia Power Co 00/06/11 1p

--0004190419 LER 80-052/02L-0 on 000030, during unit startup, RWB pump was in progress prior to declaring RWB1 operable. Caused by ineffective pump generator on Woodward turbine control. Pump generator & RWB control box replaced.
HARRIS, T. Georgia Power Co 00/06/11 2pp

0004030441 Forwards LER 80-055/01T-0
HARRY, H. Georgia Power Co 00/06/11 1p

--0004030447 LER 80-055/01T-0 on 000031, w/units 1 & 2 cold shutdown loop of mechanical shutdown was performed & 45 out of 61 shutdowns were found locked up. Caused by internal corrosion. Shutdowns replaced.
* Georgia Power Co 00/06/11 2pp

0004030397 R0-021/100-032 on 000612, w/facility in cold shutdown, investigation began to determine cause of pavement deflection which occurred beneath stress actuator pad at intake structure. Cause of fill separation from pipe unknown.
HARRY, H. Georgia Power Co 00/06/12 2pp

0004030452 Forwards LER 80-037/03L-0
HARRY, H. Georgia Power Co 00/06/12 1p

--0004030461 LER 80-037/03L-0 on 000028, while performing procedure HQ-1-1114, RWB shutdown cooling mode shutdown cooling suction valve failed to open. Caused by faulty actuator. Contact block. Contact block replaced.
HARRIS, T. Georgia Power Co 00/06/13 2pp

0004030344 PM-00-03 notice of violation & notice of proposed imposition of civil penalty will be issued on or about 000617. Action based on alleged noncompliance w/ radiation levels in truck cab. Will issue non compliance.
BROCKWELL, T. M. / THOMPSON, P. Office of Inspection & Enforcement, Office of the Director 00/06/17 1p

DOCKET NO. 000

0004030344 NUCLEAR POWER STATION

A. Application/Construction stage documents & correspondence

0004030310 Advances RWB & RWB applicants of RWB decision to modify

implementation plan presented in Section 4 of RWB-0377 re

adequacy of applicable support structures. General operating

reactor review procedure & acceptance criteria. encl

0004030310 D. D. Division of Licensing 00/06/00 13pp

0004030320 Notification of RWB12 meeting w/units in Bethesda, MD to discuss specific T-quencher load definition.
HARRIS, T. M. Licensing Branch 1 00/05/00 2pp

0004030301 Summary of 000410 meeting w/Mark 11 support group re suspension point temp response to safety/relief actions. Study concluded that limit on temp not needed. Requests that applicants submit detailed info for evaluation.
HARRIS, T. M. Containment Systems Branch 00/05/00 2pp

0004030304 Forwards requests for add info to complete review of application. W/ encl
HARRIS, T. M. Licensing Branch 1 00/06/00 1p

0004030307 Summary of 000006-09 meeting w/units in Long Island, NY re status of facility. encl
HARRIS, T. M. Licensing Branch 1 00/06/00 2pp

0004030304 Forwards "For Comment" edition of RWB-0214, "RWB Feedwater Header & Control Rod Drive Return Line Nozzle Cracking". Report provides RWB resolution of design/technical activity. 4-10 size encl.
HARRIS, T. M. Division of Licensing 00/06/00 3pp

0004170041 Forwards responses to RWB 790327 & 000003 info requests. Info provided to be included in future RWB need.
HARRIS, T. M. Long Island Lighting Co 00/06/00 20pp

0004190421 Notification of 000613 meeting w/RWB Licensing Resolution Group in Bethesda, MD to discuss progress.
HARRIS, T. M. Licensing Branch 1 00/06/09 10pp

0004030301 Summary of 000014 meeting w/units in Bethesda, MD re organization & objectives of RWB licensing resolution group. Agenda & viewpoint encl.
HARRIS, T. M. Operating Reactors Branch 4 00/06/17 11pp

DOCKETED ITEMS

D NRC Draft/Final Environmental Statements, supply & correspondence

800427040 FEO for facility
* Office of Nuclear Reactor Regulation, Director NUREG-0285
7/19/73 24pp Available at NRC

F Security, medical, emergency & fire protection plans

8005130017 Forward clarification of NRC requirements for emergency response facilities defined in 70CFR 117. Add specific criteria for facilities under development
EIGENFUT, D. G. Division of Operating Reactors 80/04/23 41pp

G Regulatory correspondence

8004130038 Notice of Appearance in proceeding Certificate of Euc encl
CULWORTH, J. J. Suffolk County, NY 80/03/08 3pp

8004060070 Forward ACR 800030 memorandum & under re TH-1 hydrogen control containment & NRC PAF notice on interim policy statement re nuclear power plant accident considerations under NRC s/s encl
ROSENBERG, B. H. Hearing Branch 4 80/04/04 1p

8004060042 Forward documents on loan basis in response to request to assist NY Goldsmith in developing Suffolk County position on certain containment s/s encl
ROSENBERG, B. H. Hearing Branch 4 80/04/05 5pp

8004100011 Forward NUREG-0650, "NRC Action Plan Developed as Result of TH-3 Accident," Vols 1 & 2 to be used for Shoreham Operations Coalition Contention 2 s/s encl
ROSENBERG, B. H. Hearing Branch 4 80/04/04 1p

8004100070 Forward Shoreham Operations Coalition & NRC stipulation in response to NLR 800401 under pending extension until 800506 for intervenor to submit particularized contentions. Stipulation contains request for addl time
LATHAM, B. M. Tunney, Latham & Benditt 80/04/06 1p

8004100125 Forward NRC, util & intervenor Suffolk County 00610 third stipulation re certain Suffolk County contentions
ROSENBERG, B. H. Hearing Branch 4 80/04/11 1p

8004100142 Third stipulation re certain Suffolk County contentions. Specific contentions that have been resolved, contentions that have been argued & contentions that are retained, pending NRC action
ROSENBERG, B. H. Suffolk County, NY REVLEY, W. T. Long Island Lighting Co 80/04/10 3pp

8004100020 Forward first stipulation re Shoreham Operations Coalition contentions & request for addl time
ROSENBERG, B. H. Hearing Branch 4 80/04/12 3pp

8004100097 First stipulation re Shoreham Operations Coalition contentions & request for addl time. Particularized certain contentions. Further meeting necessary to formulate others. Requests addl-time extension to reach final agreement
LATHAM, B. M. Shoreham Operations Coalition ROSENBERG, B. H. Hearing Branch 4 80/04/12 5pp

H General correspondence

8004000425 Requests verification of address Related correspondence
REVLEY, W. T. Huston & Williams 80/06/12 1p

I Antismear correspondence

8004000240 Request update of antismear info per AEC Reg Guide 9.3
BALTIMORE, J. Utility Finance Branch 80/05/16 1p

J Inspection reports, IC Bulletin & correspondence

8004000390 Forward IE Insp Rept 80-322/80-04 on 800318-0322 No noncompliance noted
ROSENBERG, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/17 2pp

8004030010 IE Insp Rept 80-322/80-04 on 800318-0322 No noncompliance noted. Major areas inspected: observation of work, review of safety records & action on previous Insp findings
ROSENBERG, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/17 2pp

8004050028 Forward IE Insp Rept 80-322/80-06 on 800317-20 No noncompliance noted
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/14 2pp

8004050035 IE Insp Rept 80-322/80-05 on 800317-20 No noncompliance noted. Major areas inspected: observation of work, review of safety records & action on previous Insp findings
ROSENBERG, E. J. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/14 2pp

8004050055 Forward IE Insp Rept 80-322/80-06 on 800318-0407 No noncompliance noted
ROSENBERG, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/19 2pp

8004050060 IE Insp Rept 80-322/80-06 on 800318-0407 No noncompliance noted. Major areas inspected: work activities, preoperational testing, procedure review & previous Insp findings
ROSENBERG, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/19 2pp

8004050067 Requests to IE Bulletin 80-08, "Inadequate Air for Nuclear Supplied Equipment." Improved interference fit spargers & thermal sleeves nfp for facility, but not yet installed
ROSENBERG, J. P. Long Island Lighting Co 80/05/29 2pp

8004050073 Requests substantial of info re actions taken to preclude occurrence of shelling of jet pump hydrogen beam duct (located in IE Bulletin 80-07) Unit should also provide commitment to accept long-term solution
ROSENBERG, J. P. Assistant Director for Licensing 80/06/04 2pp

8004170001 "On Program Plan for Insurance Insp Program," Revision 7 per NRC Request 521 is
ROSENBERG, J. P. Long Island Lighting Co 80/06/09 2pp

8004170004 "On Program Plan for Insurance Insp Program," Revision 7
* Nuclear Energy Service, Inc 80/05/09 14pp

S Separable occurrences, LDR & related correspondence

8004000034 Final Part 21 report re mixed bed of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were nfp to A234WP9 requirement. Investigation conducted & closed at US Steel facilities
Crawford, C. J. Chatham Corp - Tube Turns Div 80/04/04 2pp

DOCKET 80-322 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8004030175 Forward NRC Engineering Branch input re water chemistry program for Unit 2
KIMBROUGH, P. Assistant Director for Engineering 80/04/07 1p

8004030175 Advise SRR & PRR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicant support structures. General operating reactor review procedure & acceptance criteria encl
EIGENFUT, D. G. Division of Licensing 80/05/20 13pp

8004030145 Advise that installation of Insp parts & plugging of first rod guide tube support pin replacement has been completed for Unit 1 & will be done for Unit 2
CRANE, F. A. Pacific Gas & Electric Co 80/05/22 2pp

8004030150 Discusses undersized cracking in reactor vessel nozzles. Requests addl info re nozzle base metal matl spec. Type & grade, clad process type, electrode size & number of clad layers & heat input for each clad
ROSENBERG, B. H. Licensing Branch 3 80/05/23 3pp

8004030160 Forward "Description of Ops Interaction Program for Seismicity-Induced Events," as suppl to 800507 repts
CRANE, F. A. Pacific Gas & Electric Co 80/05/27 1p

8004030171 "Description of Ops Interaction Program for Seismicity-Induced Events"
* Pacific Gas & Electric Co 80/05/27 7pp

DOCKETED ITEMS

127

8006030030 Requests meeting w/NRC to discuss 800507 request for add'l info re automatic shutdown of ECCS info not sufficient to conclude that shutdown is either necessary or desirable
CRANE, P. A. Pacific Gas & Electric Co. 80/05/28 3pp

8006130119 Notification of 800604 meeting w/USI in Bethesda, MD to discuss mgmt organization short staffing requirements & lay off program
DUGALDY, C. C. Licensing Branch 3 80/06/02 App

8006170403 Comments on receipt Licensing NRC should expedite licensing of nuclear power plants that meet NRC site to meet future US energy needs
HENDRICKSON, A. Application Unknown 80/06/02 1p

8006180080 Requests Amend R3 to application for OL re Chapters 4A.5 & B of HRRG reg Certificate of Doc. entl
CRANE, P. A. Pacific Gas & Electric Co. 80/06/06 3pp

8006180044 Amend R3 to application for OL re Chapters 4A.5 & B of HRRG reg
LONG, R. E. CRANE, P. A. Pacific Gas & Electric Co. 80/06/06 47p

8006180227 Notification of 800617-19 meeting w/USI in San Luis Obispo, CA to adjust seismicity interaction program
DUGALDY, C. C. Licensing Branch 3 80/06/06 App

8006240100 Requests request for additional info re shielding design review, containment monitors & today sampling & analysis
HENDRICKSON, A. Licensing Branch 3 80/06/06 App

8006190488 Advises that 12-inch containment pressure/vacuum relief valves will be limited prior to fuel loading to prohibit opening more than 30 degrees Limit effective until valve can be closed from more open position following postulated LOCA
CRANE, P. A. Pacific Gas & Electric Co. 80/06/12 1p

8006200295 Discusses reorganization of Div of Nuclear Reactor Regulation & advises that mgmt licensing matters w/respect to Facilities have been assigned to 3 Backlog Reorganization Charts
TODD, R. L. Assistant Director for Licensing 80/06/13 12pp

8006240416 Advises NRC that 800529 rept. "Response to NUREG-0570 Short-Term Licensee Learning Requirements" is still comprehensive response to TMI-2 incident & superseded Jul 1979 voluntary rept
CRANE, P. A. Pacific Gas & Electric Co. 80/06/18 1p

8006250228 Responds to NRC 800123 ltr requesting consultation per Section 7 of Endangered Species Act of 1973 re effects of facility operation on five endangered species Operation not likely to jeopardize species documents monitoring
MARTIN, D. H. Interior, Dept. of Fish & Wildlife Service 80/06/19 16pp

F. Priority; medical, emergency & fire protection plans

8006190217 Requests clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development
ESBENHART, D. Division of Operating Reactors 80/06/25 41pp

8006120528 Requests that FEMA review of state & local emergency plan be provided consistent w/fed schedule to avoid potential delays in licensing decisions
HARRIS, J. P. Commission 80/05/13 3pp

8006290047 Advises that safeguards contingency plan submitted on 800519 is acceptable & approve Plan w/hold
LIFE 120273 760
CRANE, P. A. Licensing Branch 3 80/06/03 App

8006160039 Discusses location of principal near-site emergency operations facilities location factor is not critical parameter in selection of location approval of location at San Luis Obispo County Sheriff's office requested
CRANE, P. A. Pacific Gas & Electric Co. 80/06/07 3pp

0. Adjudicatory correspondence

8006090194 Motion for stay of proceedings pending review of affidavit of nondisclosure submitted per present notice Affidavit limited per ASLAW 800411 record preparing a conference paper is unadvisable, violating guarantees of free speech
JOHN, V. L. BALDWIN, H. A. San Luis Obispo Mothers for Peace 80/04/22 3pp

8006090196 Executed affidavit of nondisclosure re documents & info obtained from PSM Certificate of Doc. entl
JOHN, V. L. San Luis Obispo Mothers for Peace 80/05/06 3pp

8006090197 Response in opposition to Hendrickson 800602 memorandum re participation in proceeding re regulations re current participation of employee who had investigatory role on same as related case Hendrickson of appearance & Certificate of Doc. entl
FLIESSCHNER, D. JOHNSTON, R. P. San Luis Obispo Mothers for Peace 80/05/05 16pp

8006100417 Response in opposition to Intervenor San Luis Obispo Mothers for Peace motion to stay proceedings & petition for review of nondisclosure affidavit Petitioner failed to satisfy burden of proof Certificate of Doc. entl
JOHNSTON, R. P. JOHNSTON, R. P. Pacific Gas & Electric Co. 80/05/05 3pp

8006200528 Advises that ASLAW no longer requires executed Affidavit since original notarized affidavit of nondisclosure has been received
TODD, R. L. Atomic Safety and Licensing Appeal Panel 80/05/06 1p

8006060031 Connects HP Johnston 800505 notice of appearance improperly listing CLP for law in Public Interest as client San Luis Obispo Mothers for Peace, Brown & Clifford
Elliott, J. H. Public Interest Club et al are actual clients
FLIESSCHNER, D. FLIESSCHNER, D. 80/05/23 1p

8006240312 Opposes on behalf of San Luis Obispo Mothers for Peace, 800519 notice of intent to amend Nondisclosure participation in CL proceeding Potential conflict of interest may arise due to prior involvement w/HRRG consultant witnesses
JOHN, V. L. JOHNSTON, R. P. 80/05/23 3pp

8006110210 Motion to revise NRC 800505 response to joint intervenors' motion to reopen 800505 record Presents R. L. Hoffman & PT HRC 800519 joint affidavit as revision to 800505 joint affidavit Change involved does not invalidate design
MARTIN, D. H. Hearing Branch 4 80/06/04 3pp

8006110228 Affidavit pointing out error in previous affidavit filed w/ NRC response to intervenors' joint motion to reopen original Valley earthquake data does not invalidate Nondisclosure response spectra for Facility Certificate of Doc. entl
JOHN, V. L. HOFFMAN, R. L. Office of Nuclear Reactor Regulation, Director 80/05/19 7pp

8006180219 Advises ASLAW that recent as-built audit demonstrates significant breakdown in still ASLAW program Breakdown is significant because plus supports & actions were apparently LOCA misinterpreted in response to NRC 1974 & 78 audits
FLIESSCHNER, D. FLIESSCHNER, D. 80/06/10 3pp

8006180322 Responds to Items 2, 3 & 4 of IE Bulletin 79-1A "Nuclear Analysis for as-Built Safety-Related Filing Box" Plant procedures for as-built documentation will assure strict compliance between mgmt documentation & design documents
LOPPE, R. F. Pacific Gas & Electric Co. 80/06/17 3pp

8006120323 Notifies ASLAW that CA Governor RO Brown intends to participate in hearing re security plan issue Brown was admitted to proceeding as participant by ASLAW 791116 order
BROWN, H. H. Hill Christopher & Phillips BALDWIN, H. A. OROLOGI, B. California, State of 80/06/11 3pp

8006120324 Explains names of attorneys appearing on behalf of CA Governor RO Brown for security plan hearing Brown was admitted to proceeding as participant by ASLAW 791116 order Certificate of Doc. entl
BROWN, H. H. Hill Christopher & Phillips 80/06/11 App

8006190371 Memorandum E order CL-80-26 re Intervenor San Luis Obispo Mothers for Peace access to still physical security plan Hendrickson ASLAW-810 guidelines for making plans available under exemption Add views of Commissioner Bradford entl
CIBLIK, D. J. Office of the Secretary of the Commission 80/06/11 3pp

DOCKETED ITEMS

- 8006195607 Memorandum directed to parties advising that author participating in proceeding does not violate Commission regulations or due process requirements. Author will continue to take part in relevant issues.
MEMRIE, J. H. Commission 80/06/16 3pp
- 8006190889 Agreement in intervenor objection to R. Nordlinger assignment as counsel re security plan proceedings per R. Nordlinger
Commission to Intervenor
BICHART, L. Office of the General Counsel 80/06/17 1p
- 8006200474 Suggestions forwarding of public concerns re operation of Facilities. Requests tend to be repetitive. Failure to use need to serve on all parties. LTRs not already in public record should be placed in PDR & local PDR in San Luis Obispo, CA.
BICKER, E. S. Atomic Safety and Licensing Board Panel 80/06/17 1p
- 8006200357 Memorandum advising parties that author did not participate in Commission's hearing decision re emergency & Commission's hearing decision to take part in proceeding. Author will take part in other license application matters.
BICHART, L. Office of the General Counsel 80/06/18 1p
- 8006200150 Forward Director's decision per 2 206 & FR notice in response to Friends of the Earth 7/10/88 petition to require preparation of supplemental environmental statements on Class V accidents at Diablo Canyon, Rancho Santa Fe, Palo Verde.
BENTON, H. H. Office of Nuclear Reactor Regulation: Director 80/06/19 2pp
- 8006200159 Responds to 7/10/88 petition requesting preparation of supplemental EIS re impact of Class V accidents at Facilities. No special circumstances exist which would warrant expediting proceedings. Request denied.
BENTON, H. H. Office of Nuclear Reactor Regulation: Director 80/06/19 3pp
- 8006200161 Director's decision per 2 206 denying Friends of the Earth 7/10/88 petition to require preparation of supplemental EIS on Class V accidents. No special circumstances exist which would warrant expediting proceedings.
BENTON, H. H. Office of Nuclear Reactor Regulation: Director 80/06/19 13pp
- 8006200163 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 7/10/88 petition to require preparation of supplemental EIS re Class V accidents.
BENTON, H. H. Office of Nuclear Reactor Regulation: Director 80/06/19 3pp
- 8006200287 Decision ALAB-090, granting intervenors' motion to remain seated to admit Imperial Valley earthquake data. Heide decision on remaining appeal in absence until data is evaluated. How data may affect key seismic findings.
STROM, C. J. Atomic Safety and Licensing Appeal Panel 80/06/24 2pp
- 8006270309 Responses stating no objection to Governor RO Brown of State of CA participation in security plan hearing before ASLAB re O. proceeding Certificate of Rev. etc.
TOWNS, L. D. T. Hearing Branch 4 80/06/25 3pp
- 8006300432 Order directing parties to inform ASLAB by 8/30/87 of option that should be selected from Commission 80063111 ruling: CLS-80-24, remanding protected info issue to ASLAB. Requests State of CA views, although not yet participated in OI issue.
STROM, C. J. Atomic Safety and Licensing Appeal Panel 80/06/25 2pp
- H General correspondence
- 8006400504 Advises that 800518 lit is being forwarded to Washington, DC Headquarters for inclusion in appropriate public docket #119.
BENNETT, J. C. Region 5, San Francisco, Office of the Director 80/06/15 1p
- 8006400397 Suggests that Facility GL be granted an expediently as possible. Further delay will cause existing safety & maintenance. Unusual Facility. Some abundant nuclear fuel & waste problems exist.
BENNETT, J. H. Affiliation Unknown 80/06/12 3pp
- 8006400913 Suggests further seismic research before consideration of GL for Facility. Possibility exists for major earthquake in San Luis Obispo area. Opposes opening of plant.
LIND, D. Affiliation Unknown 80/06/09 1p
- 8006400516 Requests specific info on granting of GL for Facility per W. Schneider. Intervenor. Commitment believes unmet plant wastes millions of barrels of oil every month & should be turned off until further delay.
LADD, M. H. H. H. House of Rep 80/06/08 1p
- 8006400519 Factuals. Framework of in contra. Working on security plan in San Luis Obispo, CA. Applicant concerned that no special handling or identification made for security info. Requests that NRC inform about regulations. (Rev. etc.)
BENTON, H. H. Affiliation Unknown 80/06/28 1p
- 8006400522 Requests that Facility GL not be granted. Too many unanswered questions still remain. No analysis of effects of Class V accident has been made.
Affiliation Unknown 80/06/22 1p
- 8006400528 Urges early licensing of facility to have main paying citizens of CA added cost for impact. Also to be aware of undesirable consequences of importing approx 20 million barrels of oil per yr.
BENNETT, J. A. Affiliation Unknown 80/06/29 1p
- 8006400538 Advises that 800518 lit is being forwarded to Washington, DC Headquarters for inclusion in appropriate public docket #119.
BENNETT, J. C. Region 5, San Francisco, Office of the Director 80/06/28 1p
- 8006400537 Suggests that NRC consider feasibility of reworking facility as natural or perhaps gas inherent risk exists for reworking. Application if nuclear accident triggers major earthquake or vice versa.
CLANCY, P. Affiliation Unknown 80/06/02 1p
- 8006400543 FOIA request for documents re JR hearing participation in Facility. Denial proceedings. Hearing. Fault or offshore faulting to USER states.
JOHNSON, M. P. Center for Law in the Public Interest 80/06/19 2pp
- 8006400578 Opposes licensing of Facility due to Hager fault & 800528 earthquake proving that fault is active. Facility licensing would be financially irreparable.
BENNETT, J. H. Affiliation Unknown 80/06/28 1p
- 8006400579 Opposes licensing of Facility due to location near Hager fault. Earthquake in CA is very real danger.
BLOPP, J. D. J. Affiliation Unknown 80/06/02 1p
- 8006400599 Requests that LVC remain seismic hearings before granting Facility GL. Do not mention Hager fault. Earthquake Plant was not designed to bear force of earthquake. Fault might be capable.
BENNETT, J. H. Affiliation Unknown 80/06/02 1p
- 8006400540 Responds to 800518 lit by President Gerber expressing concern re licensing delays. Delays caused by post-TMI events. Subsequent application of "lessons learned" = Facility is one of four high priority plants.
BENTON, H. H. Office of Nuclear Reactor Regulation: Director 80/06/22 2pp
- 8006400596 Requests that GL be denied due to earthquake along Hager fault.
BENNETT, J. H. Affiliation Unknown 80/06/03 1p
- 8006400597 Urges that GL be denied due to 800528 earthquake on Hager fault.
BENNETT, J. H. Affiliation Unknown 80/06/04 1p
- 8006400597 Forward consultant. Action 800597 comments re wind speed assumptions used in development of nuclear emergency regulations. NRC plans for public evacuation based on absolute fantasy.
CRAWFORD, A. Senate 80/06/04 3pp
- 8006400439 Opposes issuance of GL due to prevalence of seismic activity.
BENNETT, J. H. Affiliation Unknown 80/06/05 1p
- 8006400465 Forwarded to Ladd 800508 lit expressing concern for plant safety due to proximity to earthquake faults. Requests response directed to consultants.
LADD, M. H. H. H. House of Rep 80/06/09 2pp
- 8006400490 Opposes issuance of GL due to proximity of active fault.
STELLER, J. STELLER, H. Affiliation Unknown 80/06/07 1p

DOCKETED ITEMS

8006180424 Forwards updated description of utility corporate structure, reflecting establishment of nuclear power generation dept & or atomic safety review group & mgt oversight group for information into PS&R

P. Operating license stage documents & correspondence

0000170001d Opposes licensing of Facility due to location near West
Fault NRC criteria recommend that nuclear reactors should
not be sited nearer than 12 1/2 miles to earthquake fault
Planting is located practically on fault
CAUTION-2 OFF-LOADING UNKNOWN MD/CAJSD 28

0006120580 "Degraded Grid Protection for Class EE Power Sys at
Brunswick Nuclear Electric Plant, Units 1 & 2." technical
evaluation rept
CLEVELAND, C / KONG Leach, Inc. File A-6256 0006120580 00/02/87
1000

9006090165 Forwards add TRI-2 related requirements to operating
reactors Licensee requirements for TRI Action Plan include
shift training, licensing exams & licensee dissemination
of operating experiences Response requested within 30 days
E12CHPUS.B 0 Division of Licensing 06/05/07 100pg

HC06292462 Responds to live position on low power testing permit for facilities Proposed study to consider alternative approaches to energy problems will not result in delay in licensing, but will give better info on which to base decisions
PANETTA, L E House of Rep 80/06/12 2pp

006A030514 Summary of 006422-23 meeting w/Hart I owners group in San Jose, CA re confirmatory analysis & testing programs concerning Hart I containment long-term program
CRIMES, C I Assistant Director for Plant Systems 00/05/99 200

ROCKWORTH: Opposes granting of CL due to proximity to Hageri Fault
Plant should be converted to non-nuclear fuel immediately
ROBATEL 2 Affiliation Unknown. RD/DA/16. 1x

CRIPBLC I Assistant Director for Plans Systems 03/05/07 Epp

0306300602 Responds to FOIA request for documents re JF Rendell
participation in facility licensing proceeding, Hengri fault
or offshore faulting & USGS studies. Forwards documents
listed in App A & USGS-75/087. H/A encls
FELTOL-JB Division of Rules and Records 05/05/24 Jpp

REGISTRATION OF A PROFESSIONAL CORPORATION
 DIVISION OF LICENSING
 80/038/19 72pg

9. Inspection records, IE Bulletin & correspondence

000190126 Responds to 000218 Its re NRC position on still approach of applying AIF position paper for procurement of off-themselves items NRC does not concur w/still approach Procurement of spare or replacement parts subj to ON controls
HANSARD P Quality Assurance Branch 00/03/23 Doc

00061002997 Fernando response to SE Ballistics 79-Cda & 79-Cda.Revision
1. "Review of Operational Errors & Eqs Misalignments During
THI Incident - Operating procedures have been revised to
incorporate Westinghouse's new group guidelines
GBMW.P & Pacific Gas & Electric Co 80/05/00 App

HANDS: M P Quality Assurance Branch 80/08/23 2pg

N. Remarkable occurrences, sites & related correspondence

--0036036475 Proposed revision to Tech Spec Table 3.7.3-1 for safety-related hydraulic smoothers
* Carolina Power & Light Co 05/03/27 lp

NO6250368 PAS-V-95-005 on 06/04/02, contractor received bomb threat for Facility from unknown caller. License advised to search conducted SCHWEDER, M B, HORDERHAUER, L R Region 5, San Francisco. Office of the Director 06/04/02 SP

000400000 Discusses analysis of dc power supply failure on SCOB performance requested in NRC 000425-1tr Analysis rept will be submitted by 000000. Analysis of mdrn equipment

DOCKET 30-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

UTLEY, E. E. Carolina Power & Light Co. 88/89/29 1p.

F Security, medical, emergency & fire protection plans

0506050281 Forwards revised response to 791231 ltr re implementation of short-term Lessons Learned Task Force Item 2.2.1. Commit & detail turnover procedures
UTLW: E E Carolina Power & Light Co 83/05/30 See

0086090487 Forsman proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 1980" Re: adds new Section 50.08 & App N to 10CFR50 & is expected to be published in FR by end of May
E39264UJ.S.S. Division of Licenses 02/03/19 46cc

0004000404 Ltr to all BIR licensees forwarding "For Comment" edition of NUREG-0419, "BWR Feedwater Nozzle and Control Rod Drive System Line Nozzle Cracking: Comments will be collected by

0006130063 Forward revised Pages 1-14 & new Page 14a for proposed rule 10CFR30 "Five Protection Program for Nuclear Power Plants Operating Prior to 70101," transmitted by NRC 000019
 14a Page 14a not ext
 00000401.D & Division of Licensing 00/00/00 73pp

Return Lane Road Cracking - Comments will be evaluated by NSC prior to final implementation M/D and

0006090362 Forwards request for addl info re review of safeguards
contingency plan submitted 790382 Info should be submitted
within 30 days to maintain review schedule Request withheld
(ref 16092 790)
EPSCLE.T A Operating Reactors Branch 2 00/05/87 Zpp

EO0670080: Notices of fee requirements for TCMSE route approval
request Invoice will be sent under separate cover
MILLER-W D License Fee Management Branch 00/06/06 1p

DO06200070 Requests participation in NRC study of people/male
problems in nuclear safeguards involves collection of data
on licensee security forces & practices including visit to
facility to interview security mgt personnel
BPP0LETD,T A. Operating Reactors Branch 2 00/06/00 2pp

EO6240875 Advises that Ofc of Controller has been notified re issue
invoice re 790628 request for route approval to cover

0006240015 Forward descriptions of plant emergency fire to week
and-of-gr requirements & commitments Util not planning to
construct new facilities Existing bldgs will serve
functions
URLEY,E E Carolina Power & Light Co 00/06/10 10pp

Miller-M D License Fee Management Branch 80/06/06 1p

1. Financial information.

80G270004 Forwards Amends 28 & 30 to Licenses DFR-71 & DFR-62,
respectively, safety evaluation & notice of issuance &
availability
BPPDLITD-T A Operating Research Branch 2 80/26/11 3pp

0006120011 Responds to 000508 request for comment on still 8-7
 registration statement Review identified no inaccurate
 statements re NRC regulatory requirements or financial info
 filed w/NRC
 CHRISTOPHER E. Hearings Division 00/05/99 3p

--0004370037 Amend 28 & 31 to Licenses DFR-71 & DFR-62, respectively, changing Tech Specs to establish revised safety & operating limits for operation in Fuel Cycle 4 & revising table of

--0006270037 Safety evaluation supporting Amends 20 & 51 to Licensee
0000-21 & 0000-12 respectively April 2, to the association

--0006270032 Notice of issuance & availability of America 20 & 31 56

DOCKETED ITEMS

- 000403389 Application for award to Licensee 000-71 & 000-02-clarifying term available to Reliance to 000-02 response re single failure criteria for safety sign in power reactors
UTL/IE/C Carolina Power & Light Co 00/06/10 App
- 000403390 Revised Tech Spec re single failure criteria for safety sign in power reactors
* Carolina Power & Light Co 00/04/10 App
- 000404078 Forwards info re IE turbine disks in response to SRC 000514 IE. Source correction cracks have not been observed. Water erosion found in frequency of disks is being studied. Erosion process should not require replacement of disks
UTL/IE/C Carolina Power & Light Co 00/06/00 14pp
- 0 Inspection reports, IE Bulletins & correspondence
- 000405070 Forwards IE Insp Repts 00-324/00-04 & 00-325/00-10 on 000317-00 re noncompliance noted
NRC/IE/C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/14 App
- 000405075 IE Insp Repts 00-324/00-04 & 00-325/00-10 on 000317-01 re noncompliance noted. Major areas inspected. Inspective Insp work observation & data review. Inspective Insp program review & terms and work observation
NRC/IE/C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/14 App
Region 2, Atlanta, Office of the Director 00/04/14 App
- 000405090 IE Circular 00-00, "Surf Tech Spec Inconsistency - Reactor Protection Sys Response Time" No written response required
NRC/IE/C Region 2, Atlanta, Office of the Director 00/04/10 App
- 000405098 Forwards Waste Packaging Insp Rept 00-06 re 000414-15 re noncompliance noted
NRC/IE/C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/09/01 App
- 000405099 Waste Packaging Insp Rept 00-06 on 000414-15 re noncompliance noted. Major areas inspected. Shipping paper requirements, DOT placarding requirements, radiation levels & removable contamination
TRUP/O L, NRC/IE/C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/05/01 App
- 000405093 Forwards IE Bulletin 00-11, "Hexag Heat Design " Requires action & written response IE Info Notice 79-26, "Overloading of Structural Elements Due to Pipe Support Loads" encl
NRC/IE/C Region 2, Atlanta, Office of the Director 00/08/08 App
- 000405093 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-00, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 while in Refueling Mode" encl
NRC/IE/C Region 2, Atlanta, Office of the Director 00/05/07 App
- 000410091 Acc receipt of 000501 supplemental response providing new completion dates for remaining safety & non-safety-related sig descriptions per IE Insp Repts 00-324/79-02 & 00-325/79-02
UTL/IE/C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/10 App
- 000410097 Advises that nine safety-related sig descriptions completed, nine remain in draft form & work on plant floor in progress. Reverts will be completed by 000630. Other sig descriptions will be completed by 010400
TOLL/IE/C Carolina Power & Light Co 00/05/01 App
- 0004300120 Forwards IE Circular 00-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required
NRC/IE/C Region 2, Atlanta, Office of the Director 00/05/13 App
- * add info re cracks on keypad & term house low pressure turbines
UTL/IE/C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/16 App
- 00-324/00-14 & 00-325/00-17 as re
Reactor Operations Nuclear Support
- 000430036 IE Insp Repts 00-324/00-14 & 00-325/00-17 on 000331-0002 re noncompliance noted. Major areas inspected. Control room observations, radiation & fire protection
UTL/IE/C Region 2, Atlanta, Office of the Director 00/05/02 App
Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/02 App
- 000430036 Responds to IF Bulletin 00-06. Adequate response cannot be prepared as requested schedule 30-day extension noted
NRC/IE/C Region 2, Atlanta, Office of the Director 00/05/02 App
UTL/IE/C Carolina Power & Light Co 00/05/02 App
- 000430037 Forwards revised "Inservice Insp Program Pump & Valve Testing," & related drawings. Info re steamy gas treatment not included. Drawings available in Central Files only
UTL/IE/C Carolina Power & Light Co 00/05/07 App
- 000430037 IE "Inservice Insp Program Pump & Valve Testing " * Carolina Power & Light Co 00/05/07 App
- 000430038 Responds to IE Insp Repts 00-324/00-10 & 00-325/00-11. Procedures will be implemented by 000501 to ensure that all procedures are revised to reflect newly installed valves within two wks of being declared operational
TOLL/IE/C Carolina Power & Light Co 00/06/10 App
- 000430047 Forwards notice of violation & notice of proposed imposition of civil penalties re 000222 unmonitored, uncontrolled release of airborne radioactive mist to environment from facilities
NRC/IE/C Office of Inspection & Enforcement, Office of the Director 00/05/11 App
- 000430050 Notice of violation from Insp on 000303-14 & 0402-03. Noncompliance noted. Failure to determine magnitude of release of airborne radioactive mist from auxiliary boiler stack & failure to report release to NRC within 14 days
* Office of Inspection & Enforcement, Office of the Director 00/06/11 App
- 000430057 Notice of proposed imposition of civil penalties in amount of \$24,000 re 000303 unmonitored, uncontrolled release of airborne radioactive mist to environment from facilities
* Office of Inspection & Enforcement, Office of the Director 00/06/11 App
- R Periodic operating reports & related correspondence
- 000410092 Forwards monthly operating repts for May 1980
TOLL/IE/C Carolina Power & Light Co 00/06/04 App
- 000410093 Monthly operating repts for May 1980
UTL/IE/C Carolina Power & Light Co 00/06/03 App
- 0 Reportable occurrences, LERs & related correspondence
- 0004040307 Forwards updated LER 79-09/03/01-2
TOLL/IE/C Carolina Power & Light Co 00/05/15 App
- 0004040309 Updated LER 79-09/03/01-2 on 791120 during startup, node 42-03 & 24-07 re overtravel alarm when auto-ratch to switch 40. Caused by incorrect placement of unaccepting pin in spur DWH & unaccepting pins will be used to prevent problem
TOLL/IE/C Carolina Power & Light Co 00/05/15 App
- 0004040331 Forwards "Microbiological Analysis of Brunswick Steam Electric Plant Reflow on 000321-22" Includes effluents dose calculations
TOLL/IE/C Carolina Power & Light Co 00/05/27 App
- 0004040332 "Microbiological Analysis of Brunswick Steam Electric Plant Reflow on 000321-22" Includes effluents dose calculations
* Carolina Power & Light Co 00/05/27 App
- 0004040333 Responds to 000322 letter & submits info re steam discharge val plant rather failure on 791114 Insp of level switches revealed float ball on rad block switch roughed & float ball stem on high level switch bent. Ball & ball stem replaced
TOLL/IE/C Carolina Power & Light Co 00/05/28 App
- 0004040345 Forwards LER 00-007/03/01-2
TOLL/IE/C Carolina Power & Light Co 00/03/30 App

DOCKETED ITEMS

131

- 800403099 Forwards LER 80-037/03L-0 on 800502 while removing control rod drive pins for mechanical breaking fall on cable for intermediate range monitor blocking vegetation from intermediate Cause not stated Connection replaced
TOLL180M.A.C Carolina Power & Light Co 80/05/20 1p
- 800403099 Forwards LER 80-038/03L-0
TOLL180M.A.C Carolina Power & Light Co 80/06/00 1p
- 800403095 LER 80-043/03L-0 on 800507 during current refueling outage. standby gas treatment apparatusing test was not performed for required 800505 date caused by administrative oversight. satisfactorily performed on 800507
TOLL180M.A.C Carolina Power & Light Co 80/06/00 1p
- 800403094 Final Part 21 report re mixed batch of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were app to ASME requirements. Investigations conducted & closed at 46 listed facilities
SEAY, J. L. Chemtran Corp., Lake Towne Dam 80/06/06 3pp
- 800403090 Forwards LER 80-064/03L-0
TOLL180M.A.C Carolina Power & Light Co 80/06/11 1p
- 800403090 LER 80-064/03L-0 on 800516 during source range monitor (SRM) operability PT 3 7 15/01 on 8/06 out indication of SRM A was received & SRM C produced erratic indications caused by broken drive circuit fuse & multibyte & drive detection
TOLL180M.A.C Carolina Power & Light Co 80/06/11 2pp
- 800424013 8N-80-020 on 800613 order imposing civil penalties issued based on six alleged items of noncompliance in 800502 uncontrolled/uncontrolled release of airborne radon
BROCKMUT, T. H. & THOMPSON, S. Office of Inspection & Enforcement, Office of the Director 00/06/11
- 800403090 RD while performing required steps per E Bulletin 79-010, determined that documentation did not exist to prove that splice connecting Automatic Valve Co solenoids are environmentally qualified. Splices being evaluated
TOLL180M.A.C Carolina Power & Light Co 80/06/12 2pp
- 800403097 RD 2-80-04 on 800611. Step per E Bulletin 79-010 revealed lack of airborne radon qualification documentation of splices connecting solenoid pigtail leads in safety-related valves to power cables
TOLL180M.A.C Carolina Power & Light Co 80/06/12 2pp
- 800403095 Forwards LER 80-081/03L-0
TOLL180M.A.C Carolina Power & Light Co 80/06/13 1p
- 800403094 LER 80-081/03L-0 on 800514 during performance of reactor low pressure channel collar functional test multibyte 1 & 2 of 2-0817-79-010 were found out of collar caused by instrument drift Bulletin available
TOLL180M.A.C Carolina Power & Light Co 80/06/13 2pp
- DOCKET 80-025 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
F. Security, medical, emergency & fire protection plans
- 800403047 Forwards proposed rules entitled, "Fire Protection Program For Nuclear Power Plants Operating Prior To 790101." Rule added new Section 80 FR 4 App R to 10CFR50 & is expected to be published in FR by end of May
EISENHART, D. Division of Licensing 80/05/19 4pp
- 800403040 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program For Nuclear Power Plants Operating Prior To 790101," transmitted by NRC 800519 1st Page 14a not sent
EISENHART, D. Division of Licensing 80/05/22 7pp
- 800403040 Forwards request for add info re review of safeguards contingency plan submitted 790323 info should be submitted within 30 days to maintain review schedule Request withheld (ref 10CFR 7901)
IFPOLL180.T.A. Operating Reactors Branch 2 80/05/27 3p
- 800403090 Requests participation in NRC study of preplanned releases in nuclear safeguards involves collection of data on licensee security forces & practices. Includes visit to facility to interview security staff personnel
IFPOLL180.T.A. Operating Reactors Branch 2 80/06/02 3pp
- 800403015 Forwards descriptions of plant emergency site to meet ASME/ASCE requirements & subsequently ULLI not planning to construct new facilities Requiring 31603 with new functions
UTLEY, E. E. Carolina Power & Light Co 80/06/08 10pp
- I. Financial Information
800403015 Responses to 800508 request for comment on staff S-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements on financial info filed with NRC
CHRISTENSEN, E. Hearings Division 80/06/29 1p
- P. Operating License change documents & correspondence
800403050 "Upgraded Grid Protection for Class II Power Sys on Brunswick Steam Electric Plant Units 1 & 2." technical evaluation report
CLEVELAND, G. J. 8006 Reactions, Inc. File #4-4254 800412050 80/07/09 10pp
- 8006070165 Forwards addl TMI-2 related requirements to upgrading reactor license requirements for TMI Action Plan include staff training/licensing items & licensee demonstration of operating experience Response requested within 30 days
EISENHART, D. Division of Licensing 80/07/07 13pp
- 800403051 Summary of 800422-80 meeting with NRC & source group in San Jose, CA re conformity analysis & testing programs concerning Mark I containment integrity program
GRINER, C. J. Assistant Director for Plant Systems 80/07/09 4pp
- 800403050 Requests comments on NUREG-0977, "Potential for Low Fracture Toughness & Localized Tearing in Port Steam Generator & Reactor Coolant Pump Supports." Prepared review procedure & implementation schedule sent
EISENHART, D. Division of Licensing 80/07/19 72pp
- 800403030 Application for amend to License 80N-71 regarding Tech Spec changes to complete second refueling 4 begin Cycle 3 operation. "Supplemental Reactor License Submittal for Brunswick Steam Electric Plant Unit 1 Reactor" sent
UTLEY, E. E. Carolina Power & Light Co 80/07/23 1pp
- 800403027 Tech Spec changes to Section 3/4 2 re power distribution & average power linear heat generation rate
Carolina Power & Light Co 80/07/23 9pp
- 800403024 "Supplemental Reactor License Submittal for Brunswick Steam Electric Plant Unit 1 Reactor 2"
ENGLER, R. & General Electric Co. ASG-04239 80/07/31 32pp
- 800403016 Responses to 800318 1st re NRC position on utility approach of applying AEP position paper for procurement of off-the-shelf items NRC does not accept utility approach Procurement of spare or replacement parts only to be controlled
HAGGARD, P. Quality Assurance Branch 80/07/31 2pp
- 800403030 Discusses analysis of 60 power supply failure on 8006 performance requested in NRC 800408 1st Analysis report will be submitted by 800829 Analysis of ECCB equipment qualification re flooding will be submitted by 800917
UTLEY, E. E. Carolina Power & Light Co 80/07/31 1p
- 800403025 Forwards revised response to 791201 1st re implementation of short-term Lessons Learned Tech Spec Item 2 & 3. Shift & relief turnover procedures
UTLEY, E. E. Carolina Power & Light Co 80/08/00 2pp
- 800403030 Application to amend Tech Specs implementing temporary change in support values of three BEEP-1 safety relief valves (P&ID sent)
UTLEY, E. E. Carolina Power & Light Co 80/08/03 2pp
- 800403020 Revised Page 3/4 2 to Tech Spec for reactor coolant sys. implementing temporary change in support values of three BEEP-1 safety relief valves
Carolina Power & Light Co 80/08/03 1p
- 800403027 Requests that NRC review of outage-related technical issues as requested so that appropriate license amendments can be issued prior to scheduled 800820 criticality
UTLEY, E. E. Carolina Power & Light Co 80/08/04 1p

9004180265 Response to IE Insp Repts 90-024/02L-0 90-025/02L-1
Pressure will be regulated to 900251 to ensure that all
procedures are revised to reflect newly installed valves
within two wks of being declared operational
TOLL1808A C Carolina Power & Light Co 90/06/80 2pp

9004180407 Forwarded notice of violation & notice of proposed
imposition of civil penalties re 900220 unmonitored:
uncontrolled release of airborne radioactive matri from environ
from facilities
BTL1808A C Office of Inspection & Enforcement, Office of the
Director 90/06/81 2pp

--9004180451 Notice of violation from Insp on 900210-14 & 9450-39
Investigation asked failure to determine magnitude of
release of airborne radioactive matri from auxiliary boiler
stack & failure to repair & closure to NRC within 14 days
* Office of Inspection & Enforcement, Office of the Director
90/06/81 4pp

--9004180557 Notice of proposed imposition of civil penalties in amount
of \$24,000 re 900222 unmonitored/uncontrolled release of
airborne radioactive matri to environ from facilities
* Office of Inspection & Enforcement, Office of the Director
90/06/81 1p

H Periodic operating reports & related correspondence

9004180592 Forwarded monthly operating reports for May 1980
TOLL1808A C Carolina Power & Light Co 90/06/80 1p

--9004180593 Monthly operating reports for May 1980
TOLL1808A C Carolina Power & Light Co 90/06/80 2pp

H Repairable occurrences, LCM & related correspondence

9004180620 Forwarded "Meteorological Analysis of Brunswick Steam
Electric Plant Release on 900221-22" Includes offsite dose
calculations
TOLL1808A C Carolina Power & Light Co 90/05/87 20pp

--9004180622 "Meteorological Analysis of Brunswick Steam Electric Plant
Release on 900221-22" Includes offsite dose calculations
* Carolina Power & Light Co 90/06/87 24pp

9004180650 Response to 900550 notice & submittal info re screen discharge
valve float switch failure on 77011 Insp of level switches
revealed float ball on rod broke switch crushed & float ball
stem on high level switch bent ball & ball stem replaced
TOLL1808A C Carolina Power & Light Co 90/05/80 2pp

9004180633 Forwarded LER 90-047/02L-0
TOLL1808A C Carolina Power & Light Co 90/05/80 1p

--9004180637 LER 90-047/02L-0 on 900501, RHR flow indicator LE11-F1-0338
on remote shutdown panel closed & 200 gpm safety shut down
Caused by malfunctioning indicator indicator indicator & transducer
calibrator & was returned to svc
TOLL1808A C Carolina Power & Light Co 90/05/80 2p

9004180659 Forwarded LER 90-020/02L-0
TOLL1808A C Carolina Power & Light Co 90/05/80 1p

--9004180615 LER 90-020/02L-0 on 900501, during normal operation, 1A
reactor recirculation pump tripped on motor generator set
low oil pressure Caused by PCS-1239 controlling recirculating
during normal periods & possible setback drift
TOLL1808A C Carolina Power & Light Co 90/05/80 2pp

9004180614 90 090422, fire protection alarm for Zone 9, 50-ft elevation
of reactor bldg, annunciated & would not reset Caused by
contamination detector reacting to steam from local steam
line leak will be repaired
TOLL1808A C Carolina Power & Light Co 90/06/80 1p

9004180632 Forwarded LER 90-049/02L-0
TOLL1808A C Carolina Power & Light Co 90/06/80 1p

--9004180630 LER 90-049/02L-0 on 900501, during routine surveillance,
position 80 bar read 14-15 did not indicate. Problem caused
by ground in prototype inlet piping Problem under
investigation
TOLL1808A C Carolina Power & Light Co 90/06/80 1p

9004180614 Forwarded LER 90-048/02L-0
TOLL1808A C Carolina Power & Light Co 90/06/80 1p

--9004180198 LER 90-048/02L-0 on 900501, during normal surveillance, calibrator
adjustment screw cap on reactor level instrument was leaking
water Caused by nonoperable switch 2 Calibrator adjustment screw
cap gasket was replaced & switch 2 contacts cleaned
TOLL1808A C Carolina Power & Light Co 90/06/80 2pp

9004180604 Final Part B1 report re mixed heat of steel supplied by WB
Steel 1980 which 4-inch, stainless & 2-inch bars were off to
ASTM578 requirements Investigations conducted & closed at
WB limited for 111148
SEAVER, L. Johnston Corp. Tube Turns Div 90/06/80 2pp

9004180447 Forwarded LER 90-052/02L-0
TOLL1808A C Carolina Power & Light Co 90/06/81 1p

--9004180449 LER 90-052/02L-0 on 900504, during normal surveillance,
primary containment oxygen analyzer, 1-02C-0501-1239-0 found
giving erratic indications Caused by degradation in magnetic
analyzer sample cell limit replaced & returned to svc
TOLL1808A C Carolina Power & Light Co 90/06/81 2pp

9004180410 90-060-020 on 900413, error involving civil penalties issued
based on all alleged items of noncompliance re 900222
unmonitored/uncontrolled release of airborne radonets
BISCHKE, P. M. - THOMPSON, D. Office of Inspection & Enforcement,
Office of the Director 90/06/81

9004180409 90 while performing required insps per IE Bulletin 79-016,
determined that documentation did not exist to prove that
applies connecting Automatic Valve Co solenoids are
appropriately qualified Appliance being evaluated
TOLL1808A C Carolina Power & Light Co 90/06/82 2pp

9004180567 90 2-80-16 on 900413, insps per IE Bulletin 79-016
lack of environ qualification documentation of appliance
connecting solenoid pigtail leads on safety-relief valves to
power cables
TOLL1808A C Carolina Power & Light Co 90/06/82 2pp

9004180408 Forwarded LER 90-051/02L-0
TOLL1808A C Carolina Power & Light Co 90/06/83 1p

--9004180409 LER 90-051/02L-0 on 900413, during normal surveillance,
containment atmosphere dilution tank vol observed less than
required limit Caused by inability to open CAC tank annual
valve isolation valve, CAC-30-44
TOLL1808A C Carolina Power & Light Co 90/06/83 2pp

DOCKET 90-327 RESONANCE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

9004180327 Discusses review of F800 Table 17 D-1, "Critical Structures,
Sys & Components" re operational On program Forwarded
request for addl info to be transmittal to unit
HARRIS, P. Quality Assurance Branch 90/06/80 4pp

F Security, medical, emergency & fire protection plans

9004180317 Forwarded clarification of NRC requirements for emergency
response facilities defined in 790101 14d addl specific
criteria for facilities under development
B1804847, D 0 Division of Operating Reactors 90/04/80 4pp

9004180394 Forwarded addl info to training & qualification plan info
withheld (ref 100P80 7903)
HILLS, L. H. Tennessee Valley Authority 90/06/80 2pp

9004180307 Forwarded revised schedule for responses to Auxiliary Sys
State fire protection review questions Prepared Train B
circuit reusue scheme shown on envl dated 01 overline
drawings Drawings available in Central Files only
HILLS, L. H. Tennessee Valley Authority 90/06/81 10pp

9004180430 Forwarded TVA radiological emergency plan & TN multi-
jurisdictional radiological emergency response plan Three
crack refs 08C1
HILLS, L. H. Tennessee Valley Authority 90/06/81 40pp

--9004180415 TVA radiological emergency plan
* Tennessee Valley Authority 90/06/81 20pp

--9004180416 TN multi-jurisdictional radiological emergency response
plan
* Tennessee, State of 90/06/81 40pp

DOCKETED ITEMS

H General correspondence

8006020157 Responds to 800506-110 to President Carter re licensing
 subject plant. Provides statement made by President on
 7/1/2007 NRC is in process of preparing action plan specifying
 actions for review & approval
 800506-110 Office of Nuclear Reactor Regulation, Director
 80/06/21 2pg

X Utility Final Safety Analysis Report (FSAR) & amendments

8006102059 Application for Amend A5 to Licensee SPN-72 & CRRH-73,
 including revision to Chapter 3 of FSAR
 HILLS.L.R Tennessee Valley Authority 80/06/06 3pg

--8006102062 Revisions to Chapter 3 of FSAR, providing responses to NRC
 requests for add info re Foundation engineering classed
 generators & in-service inop programs. Committee Amend A5 to
 Licensee SPN-72 & CRRH-73
 * Tennessee Valley Authority 80/06/06 4pg

8006102091 Forwards proposed revisions to Facility FSAR, Sections 3 & 4
 re licensee inop program. Requests request for relief from
 ARMC Section 11, covering third party inspectors, practices
 regarding wells in piping & steam generator nozzles
 HILLS.L.R Tennessee Valley Authority 80/06/06 8pg

O Advisory Committee on Reactor Safeguards reports & correspondence

8006230227 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant Unit
 1 & 2 800428 meeting in Washington, DC to continue review
 of TWA application for license to operate
 HILLS.L.R Office of the Secretary of the Commission 80/04/04
 3pg

8006190204 Notice of indefinite postponement of ACRS Subcommittee
 800428 meeting re Sequoyah Nuclear Plant Unit 1 & 2
 HILLS.L.R ACRS - Advisory Committee on Reactor Safeguards
 80/04/14 1p

8006290874 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant
 800428 meeting in Washington, DC to review DC application
 Name closed systems may be needed to explore matters
 involving proprietary info
 HILLS.L.R Office of the Secretary of the Commission 80/03/12
 2pg

8006240395 Notice of ACRS 800428-87 meeting in Washington, DC to discuss
 Facility DC Name closed systems necessary to prevent
 frustration of responsibilities
 HILLS.L.R Office of the Secretary of the Commission 80/03/19
 4pg

8006060628 Transcript of ACRS Subcommittee on Sequoyah Nuclear Power
 Station meeting on 800428 in Washington, DC 1-123
 Naming section diagrams & related matter and
 * ACRS - Advisory Committee on Reactor Safeguards 80/06/02
 300pg

P Operating license stage documents & correspondence

8004090645 Forwards add TH-2 related requirements to operating
 reactors license requirements for TH Action Plan include
 shift meeting, licensing exams & license classification
 of operating experience. Response requested within 30 days
 81800407,0-0 Division of Licensing 80/03/07 10pg

8006060696 Advises that Ofc of Nuclear Reactor Regulation will take
 lead in reviewing DC prior to authorization of full power
 objectives include clarification of TH-related
 requirements, review of Tech Specs & movement toward SIS
 80060606,0-0 Office of Nuclear Reactor Regulation, Director
 80/06/06 2pg

Advises that Commission intends to use Facility DC as model
 for clarity & enforceability. Project manager should
 not expect in conjunction with a group working on
 a paper re Tech Spec Name and
 of the Secretary of the Commission 80/06/11

opposition to make Facility DC model license for
 utility. DC should also be involved to help
 fixing Tech Specs to fit Facility Marked-up

on 80/03/18 2pg

--80060606112 Progress that Facility DC be used as model license for
 clarity & enforceability. Tech Spec Name and
 would review full power license prior to Commission NRC
 is requested to call Commission's response by 800318
 80060606,0-0 Division of Licensing 80/03/11 1p

8006101222 Progress commit on HUSO-2077, "Potential for Low Pressure
 Turbines & Lamellar Tearing on PWR Steam Generator &
 Reactor Coolant Pump Supports" - Proposed review procedure &
 implementation schedule and
 81800607,0-0 Division of Licensing 80/05/19 7pg

8006202076 Forwards "Flood Insurance Study" & seven overall drawing
 in response to 800505-110 re hydrologic engineering
 questions re Executive Order 11800
 HILLS.L.R Tennessee Valley Authority 80/05/20 5pg

--8006032283 "Flood Insurance Study," Hamilton County, TN
 * Having 5 Urban Development, Dept of Federal Disaster Assistance
 Act 7/02/2008 4pg

8006030417 Forwards proposal for seismic margin program, required by
 HUSO-2011. Program provides basis for NRC to complete
 evaluation of seismic qualification of structures &
 equipment necessary for safe shutdown
 HILLS.L.R Tennessee Valley Authority 80/05/27 3pg

8006030178 Application for amend to License SPN-77. Proposed Tech Spec
 changes and consisting of add to several action statements
 to allow entry into Mode 3 & 4 before completion of action
 listed in 800411 800420 110
 HILLS.L.R Tennessee Valley Authority 80/03/20 1p

--8006020183 Proposed Tech Spec changes re mode 3 to several action
 statements to allow entry into Mode 3 & 4 before completion
 of actions listed in 800411 800420 110
 * Tennessee Valley Authority 80/03/20 8pg

8006107070 Submits status report. Is currently in cold shutdown. All
 inputs & are required longer re-work will be completed by
 800428 Initial criticality is estimated to be 800428 due up
 of the term power physics tests will be completed
 800428 Licensing Branch 2 80/06/06 2pg

8006190618 Advises that Washington responded to NRC questions re
 Barton 10 transmitters in 800321 TH-AM-TM-2240 info
 applicable to unusual behavior of transmitters at plant
 during qualification testing
 HILLS.L.R Tennessee Valley Authority 80/06/13 1pg

8006030031 Application to amend License SPN-77, clarifying meaning
 of term "separable" & application to single failure criterion
 for safety systems & qualification and
 HILLS.L.R Tennessee Valley Authority 80/06/12 1p

--8006020026 Proposed Tech Spec 3/4 0 re limiting conditions for
 operation for Licensee SPN-77
 * Tennessee Valley Authority 80/06/13 10pg

8016020028 Notification of 800419 meeting with in Bethesda, MD to
 discuss issuance of full power license for facilities
 80060200,0-0 Licensing Branch 1 80060200,0-0 Licensing Branch
 0 80060200,0-0 Licensing Branch 2 80/06/16 4pg

8006240202 Forwards revised response to Question 13 1d re employee
 access to high radiation areas. Revision includes description
 of administrative procedures controlling access to areas
 adjacent to fuel transfer tube
 HILLS.L.R Tennessee Valley Authority 80/06/17 2pg

8006240572 Requests change to Tech Specs to permit plant startup w/
 inoperable banger SCV-110 located on pressurizer relief
 line
 HILLS.L.R Tennessee Valley Authority 80/06/20 1p

8006230387 Forwards add info requested by NRC re changes to Tech Spec
 2 1 re reactor trip systems instrumentation signals & 3 1
 re boron concentration - refueling
 HILLS.L.R Tennessee Valley Authority 80/06/23 11pg

8006200591 Forwards revised responses to Questions Q31 127-040 60 &
 Q31 129 w/ NRC 7/20/01 110 re seismic qualification of Class
 1 electrical equipment. Repts re cable samples & IEEE-303-
 1974 qualification and
 HILLS.L.R Tennessee Valley Authority 80/06/23 10pg

--8016030287 "Delphi Pneumatic Test Procedure"
 18016,0-0 Comp-Inc - Delphi Systems Inc 75/04/10 2pg

DOCKETED ITEMS

--60363D5400 "Radiation Testing of Cell Number 825, Final Rept -
WILLIS, B E PRT Corp 78/08/20 7pp

--0026300409 "Seismic Vibration Test of EIO Series Transmitters"
SEARS, J. A., MCANULTY, R. W., MANDILL, R. Acton Environ. Testing Corp
7/6/03/02 30pp

--B064200414 "Test Procedure for Seismic Vibration Qualification Test of
EIO Series HCA/BRW Transmitters"
SEARS, J. A., MCCALLAN, D. Acton Services Testing Corp 70/09/00
25pp

```
--B006300428 "Page 6 Differential Pressure Transmitters Type ELO Series"
SCHREIBER, M., CARABDELL, J., TOLP, D.L. Achen Environ Testing Corp
72/10/31 10pp
```

---S00630042# "Double-Insulation Test of Electrical Cables Under Simulated
LECA/BBE By Sequential Exposure to Environments of Radiation,
Thermal Aging, Steam Chemical Spray"
* Inspec, Inc. (subs. of Mansfield Enterprises, Inc.)
78/04/30 42pp

0066300240 Application to amend License DPM-22, modifying Tech Spec
3.4.16, re RCS structural integrity to permit plant startup
with repairable pipe damage on pressurizer relief line
Forwards proposed changes to Tech Specs
NULG.L.M Tennessee Valley Authority ED/DA/20 2x

--0056000287 Proposed changes to Tech Specs Section 3.4.10 re RCS structural integrity, permitting plant headup w/improperable pipe hanger on pressurizer relief line. Reasons & justifications for proposed changes sent to Tennessee Valley Authority 08/04/24 day

D Inspection results, IF Bulletin & correspondence

8036090316 Forwarded to Insp Rept 58-207/88-13 on 800301-21 to notice
of violation
LAWRENCE C. Region 2, Atlanta Reactor Operations Nuclear Support

--6606090519 Notice of violation from Insp on 660306-01
* Region 2, Atlanta, Office of the Director 66/04/28 1p

--8004090521 IE Insp Rept 50-327/00-13 on D08001-31 Noncompliance noted
Failure to maintain & implement procedure required by Task
Specs re fuel loading
BANCE, M C Region 2: Atlanta, Reactor Operations Nuclear Support
Branch COTLE, M F Region 2: Atlanta, Office of the Director
00/04/28 Ynp

0004060009 Forwards IE Bulletin 80-11, "Masonry Wall Design - No action
or written response required IE Info Review 79-28.
"Overloading of Structural Elements Due to Pipe Support
Loads" end
OWELL, V. J. P. Region 2, Atlanta, Office of the Director 80/25/08

0005040267 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability." No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/09
Sent

0004520034 Forwarded IC Circular 00-11, "Emergency Diesel Generator Lube Oil Cooler Failures." No written response required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 00/03/13
Jaa

0004170193 Ack receipt of G05506 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-327/50-10 4
50-328/50-24
HUFFNY, C E Region 2, Atlanta, Reactor Construction & Engineering
Management Branch, 65/05/93, Doc

--BBS6170211 Response to HQC 000414 ltr re deviations noted in IE invs
Repts 00-027/NO-10 & 00-080/NO-04 corrective actions
detailed instructions 1 procedures prepared Plant Fire
brigade reconnected & Security instruction 12 revised
MILG.L. M. Tennessee Valley authority 00/05/036. dsm

==2606570215 Forwards IE loop Repts 58-267/80-10 & 90-328/80-06 on
800218-21 & notice of deviation
NAMPNT, C & Region 2, Atlanta, Reactor Construction & Engineering
General Branch 05/05/14 Doc

--8006570222 Notice of deviation from rule on 800318-21
* Region 2, Atlanta, Office of the Director 80/04/11 1p

--8004170228 18 Insp Repts 50-5017/80-10 & 50-328/80-50 on 800318-21
Noncompliance noted fire fighting procedures not provided
for all safety-related areas
CONCERN T F Region 2, Atlanta. Reactor Construction & Engineer
Support Branch NILLER, M H Region 2, Atlanta, Office of the
Director 80/04/11 2pm

6062320219 Ack receipt of 606232 ltr informing MRC of steps taken to correct violations noted in SE Insp Rpts 90-327/90-14 & 90-328/90-00
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/56/03 2pg

--8804230367 Responds to NRC 880501 lit re violations noted in IR Insp
Repts 30-327/88-14 & 30-328/88-08 Corrective actions
Surveillance instruction 114 will be revised to require
stationing of Class 2 pressure retaining bolting
NLLS, L. M. Tennessee Valley Authority 02/08/23 3pp

--B094230273 Forwards 1C Insp Repts 50-327/90-14 & 50-328/90-08 on
B02331-8403 & notice of violation
MURPHY, C E Region 2, Atlanta, Reacher Construction & Engineering
Support Branch 00/05/01 Gpo

-8006200041 Notice of violation from Insp as 800001-0403
 * Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/04/00 is

--00A0230380 IE Insp Repts 90-0277/86-04 & 56-268/66-08 on R00031-04
Noncompliance noted failure to comply w/requirements/inadequate
insp requirements & failure of records to adequately define
practical exam criteria
HEDOT, A R Region 2: Atlanta, Reactor Construction & Engineering
Support Branch, TAC&L, D Region 3: Atlanta, Office of the
Director 03/04/98 gss

EOSS000099 Ack receipt of EOSS002: Re Informing ARE of steps taken to correct violations noted in IE Ensp Repts EO-007/79-DA & EO-026/79-19
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch HQ/GS/DA Exp

003670089 Response to IR Insp Regis 90-027/90-14 & 90-328/90-28 All
Section 3 of facility surveillance instructions 114 reviewed
for compliance w/section XI of ASME boiler & pressure vessel
code
HALL, L. N Tennessee Valley Authority 80/Dw/09 10

0006240006 Response to SE Bulletin 00-02 re decay heat removal system reliability. Furnishes results of Swedish Nuclear Administrative procedural changes instituted to require at least two independent means of supplying adequate heat removal.

CRSRL:J1 Tennessee Valley Authority 00/06/09 300

8004245260 Forwards response to EK Bulletin 80-25 re vacuum conditions resulting in damage to holdup tanks. Freeze protection for refueling water storage tank at Sequoyah & Watts Bar is provided by redundant heaters & tank insulation.

HILL, L. R. Tennessee Valley Authority 80/06/24 800

MODA190586, Forwarding response to NRC 808328 Re re noncompliance noted
in EE Insp Rept 80-037480-13 Corrective actions detailed
review of 430 supports on safety sys outside containment
initiated & Insp of piping configurations undertaken
MILLS, L. M Tennessee Valley Authority 88/05/12 3pp

■ Periodic operating expense & related correspondence

6004390000 "HFSEB Discharge Monitoring Rept for Feb 1980."
* Tennessee Valley Authority 80/03/01 106pgs

8004530295- Forwards monthly operating rept for May 1960
 ENLANTINE, J H Tennessee Valley Authority 80VCR/60 1p

--BDOw(20294 Monthly operating rept for May 1980
* Tennessee Valley Authority 02/06/83 9pp

■ Reportable occurrences, LBRs & related correspondence

MO0410250 RD on MO0427, 2-inch containment spray test lines analyzed using incorrect outside diameter for pipe resulting in analytical model being more rigid than actual pipe. Caused by error in input not found during checking.

DALENTAGLE, J. M. Tennessee Valley Authority 03/25/02 2c

DOCKETED ITEMS

- 0004110318 RC 88RC-90-007/00049 on 000914, insufficient clearance found between Support Guide 3-B11-314 & 4-inch safety inspection pipe. Apparently caused by incorrect installation due to misinterpretation of spec Guide support required. BAILENTINE, J. D. Tennessee Valley Authority 00/05/19 1p
- 0004030097 Forwarded LER 00-045/017-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/27 1p
- 0004030408 LER 00-049/017-0 on 000514, support guide, 1-B11-03, found w/o clearance at top & bottom of 4-inch safety inspection pipe. Insulator installation caused by misinterpretation of installation spec. Support modified. SHARTS, J. D. Tennessee Valley Authority 00/05/22 2pp
- 0004030480 Forwarded LER 00-047/017-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/27 1p
- 0004030490 LER 00-047/017-0 on 000513, two support members found to be reversed for bangers. Caused by confusion of side by side lines during installation. A subsequent reversal Support removed & reinstalled in proper orientation. SHARTS, J. D. Tennessee Valley Authority 00/05/27 2pp
- 0004030492 Forwarded LER 00-043/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/28 1p
- 0004030507 LER 00-043/031-0 on 000490, flow switches PS-90-012 & 141 found inoperable. Caused by debris collecting on switch preventing activation. Switch cleaned & returned to operable status. Design change request initiated. WISSE, J. M. Tennessee Valley Authority 00/05/28 1p
- 0004030503 Forwarded LER 00-051/017-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/28 1p
- 0004030540 LER 00-051/017-0 on 000508, during 8E Bulletin 79-14 support legs discovered that 1-COVER-308 was improperly designed. Pipe legs had moved out of hanger due to thermal expansion. Caused by design error. Legs lengthened. SHARTS, J. D. Tennessee Valley Authority 00/05/28 2pp
- 0004030587 Forwarded LER 00-041/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/29 1p
- 0004030640 LER 00-041/031-0 on 000430, while in Mode 3, valve 0-FCV-32-10 isolated on low essential air pressure. Causing valves 1-FCV-00-136, 115, 109, 114, 114 & 110 to close. Cause unknown. HERRIFF, J. R. Tennessee Valley Authority 00/05/29 1p
- 0004030656 Forwarded final interim deficiency report re design of spent fuel pool gates not meeting Seismic Category I requirements. NILL, L. M. Tennessee Valley Authority 00/05/29 1p
- 0004030691 First interim deficiency report re spent fuel pool gates not designed to Seismic Category I requirements. Cause not stated. Evaluation being conducted. Complete corrective action will be forwarded by Unit 1 initial criticality. Tennessee Valley Authority 00/05/29 1p
- 0004030694 Forwarded LER 00-048/017-0
CALHOUN, J. R. Tennessee Valley Authority 00/05/29 1p
- 0004030692 LER 00-048/017-0 on 000515, w/Unit 1 in Mode 3, test switches on containment purge exhaust radiation monitors were discovered to be in test position. Monitor inoperable. Caused by personnel error. Monitors restored. DART, D. W. Tennessee Valley Authority 00/05/28 2pp
- 0004030412 Forwarded LER 00-050/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/02 1p
- 0004030414 LER 00-050/031-0 on 000505, flow switches PS-90-025 & PS-90-124 found inoperable, which resulted in placing plant into Action 20. Caused by debris collecting on flow switch, preventing activation. Switch cleaned & returned to svc. HERRIFF, J. R. Tennessee Valley Authority 00/06/02 2pp
- 0004030520 Forwarded final deficiencies report re Rodin fire dampers. NILL, L. M. Tennessee Valley Authority 00/06/02 1p
- 0004030535 Final deficiency report re Rodin fire dampers. Rodin developed alternate fix to correct problem w/external spring closure & potential for jammed blades. Tennessee Valley Authority 00/06/02 2pp
- 0004100275 Forwarded LER 00-038/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/04 1p
- 0004100274 LER 00-038/031-0 on 000506, w/c big vent monitor was declared inoperable when alarm would not clear in conjunction w/traffic signals. Readings probably caused by high frequency welding. Design change has been initiated. HERRIFF, J. R. Tennessee Valley Authority 00/06/04 2pp
- 0004100173 Forwarded LER 00-036/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/05 1p
- 0004100163 LER 00-036/031-0 on 000508, common circuit breaker feeding radiation monitors found open. Causing loss of electrical power. Caused by personnel overloading circuit breaker. W/c closed. Personnel instructed on proper procedure. HERRIFF, J. R. Tennessee Valley Authority 00/06/05 2pp
- 0004100319 Forwarded LER 00-046/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/06 1p
- 0004100327 LER 00-046/031-0 on 000508, all tubes of ice condenser were giving open HCR alarm. Problem caused by worn air leaking into lower portion of ice condenser. Affected tubes were bleached. RECORD, B. J. Tennessee Valley Authority 00/06/06 2pp
- 0004100360 Forwarded LER 00-054/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/06 1p
- 0004100374 LER 00-054/031-0 on 000509, design review revealed discrepancies between as-installed insulation weights & those actually used during piping site analysis. Caused by unavailability of drawings. PRIMO, D. C. Tennessee Valley Authority 00/06/06 2pp
- 0004030024 Final Part 20 report re mixed bed of steel supplied by UM Steel from which 4-inch elbows & 2-inch tees were used to ASME-B required. Investigations conducted & closed at 4 listed facilities. SEAY, J. L. Chemtreat Corp., Tube Turns Co. 00/06/06 3pp
- 0004100509 Mix of pipe of noncompliance w/effluent limitations of NPDES permit. Operational sewage treatment plant effluent sample collected on 000505 recorded as mercuric. Caused by accumulation of effluent on sand filter. EL-AHRY, M. Y. Tennessee Valley Authority 00/06/10 1p
- 0004100554 Forwarded LER 00-057/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/10 1p
- 0004100561 LER 00-057/031-0 on 000912, while 7T-102 net of w/c, some time blew loose at compression fitting. Fitting channel out of w/c & leaving less than three operable channels. Resultant high pressure forced line from fitting. CURTIS, J. M. Tennessee Valley Authority 00/06/10 1p
- 0004100506 Forwarded LER 00-059/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/11 1p
- 0004100541 LER 00-059/031-0 on 000514, during routine exam of process instruments, cooling tower blowdown effluent flow monitor found indicating flow greater than pumps could deliver. Cause not stated. Flow element will be removed & inspected. CURTIS, J. M. Tennessee Valley Authority 00/06/11 1p
- 0004100485 Forwarded LER 00-063/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/11 1p
- 0004100493 LER 00-063/031-0 on 000513, operator mistakenly tripped normal feeder from 9 kV unit. Heard 28-Hz w/c pulsing. Synchroscope switches to "off" position. Loss of power to 9 kV shutdown stand down. Resulted. Caused by operator error. RECORD, B. J. Tennessee Valley Authority 00/06/11 2pp
- 0004100501 Forwarded LER 00-044/017-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/11 1p
- 0004100524 LER 00-044/017-0 on 000509, four Rodin Hg Co fire dampers were identified that could potentially fail due to problem in spring closure mechanism. Caused by design error in reinforcing bracket. All four dampers modified. CHAFFIN, E. A. Tennessee Valley Authority 00/06/11 2pp
- 0004100527 Forwarded LER 00-062/031-0
CALHOUN, J. R. Tennessee Valley Authority 00/06/11 1p

==E006170973 LEN 80-042704 -p en 800503, while in Mode 3,2 per
containment purge sys lines disassembled open caused by
instrument deficiency G04 30 24 allowing operator to open
four purge valves Valves closed upon disc0497q
RECORD 8 J Tennessee Valley Authority 80/04/11 3p

```
--R004240396 Supplemental LEM 00-045/P01-1 an 000309 gate between spent
fuel pool & tank loading area found not to be designed or
constructed to Category 3 requirements Caused by overlooking
loading effects in seismic analysis
MSEHR, B R Tennessee Valley Authority 00/06/18 2pg
```

0006170543 Forwards LCR 80-052/03L-0
CALHOUN, J R Tennessee Valley Authority 80/06/12 1p

8006240028 Forwards final deficiency rept re spent fuel pool gates
HOLLIS L B Tennessee Valley Authority 80/04/18 1p

--0000170504Y LBN 80-056/03-0 on 000014. Radiation monitor BM-
declared inoperable due to erratic upscale readings. Cause
by which in accordance to continuous advance operating mo-
of filter paper drive mechanism
HENTFORD, J.H. Tennessee Valley Authority 00/04/12 1

--S000248000 Final deficiency report re spent fuel pool gates BA aspects of gate integrity will be verified. Nighttime constraints will be attached to pool well gate to prevent damage to spent fuel elements during seismic event
w Tennessee Valley Authority 00/04/10 Doc

800417059V NPDES noncompliance notification on 803605, pH value
drainage discharge 807 exceeded max permit limitations.
Cause is unknown investigation will be made & corrective
measures taken if problem recurs
SL-ARBY, H. T. Tennessee Water Authority 80/06/12 16

00024007R Second interim deficiency rept re UMI hydraulic isolation
valve accumulator weighing up. Review of rept proposed by
Westinghouse is not complete. Next rept will be submitted by
000729
NELS, L. M. Tennessee Valley Authority 00/06/10 1a

NO6618048H Fernando LER 00-047/03L-0
CALMOUNT, J. B. Tennessee Valley Authority 00/04/12 1a

0006049452 Forwards LBR 00-072/00L-0
CALHOUN-J R Tennessee Valley Authority 00/06/19 1p

--3004180487 LER 82-047/01L-C on 800555, while central room emergency air
clearup fan #3 was out of service train ventilation was
rendered inoperable caused by need to replace substitute
equivalent motor motor original was returned to svc
WATSON, U. A. Tennessee, Madison, Arkansas. 8005419 is

--B006240423 LER 00-072/DGL-0 on 806526.essential raw cooling water
effluent monitors 00-RE-00-2347141 declared inoperable. Caused
by springs high rad spikes & high rad alarm Champaign of
valley & further investigations planned
WCFERD66, J. H. Tennessee Valley Authority 80/04/19 in

8906100530 Forwarded L&R 80-055/03L-0
CALHOUN, J B Tennessee Valley Authority 06/04/12 1a

BO96260160 Forwards suppl info for deficiency reph re GSA movements of
steel containment vessel
MILLIE L N Yreaville Valley Authority 80/06/18 tp

--B00A180033 LFW 80-035/COL-0 on 800315, during Mode 3 testing, loop 2
hot leg resistance temp detector found in 8700R by 3
degrees Caused by higher-than-normal resistance between
resistance temp detector & process instrument rack
PBYE, N. K. Tennessee Valley Authority 80/04/12 to

--@0042060162 Suppl info for final deficiency rpt re SEA assessments of
total containment vessel All add lines reworked New
supports & changes to existing supports needed for RMS spray
header piping

8036200-51 Forwards LFR 80-066/03L=0
CALHOUN, J B Tennessee Valley Authority 80/06/13 1a

0086240374 Forwarded LER 00-074/03L-0

--8006200457 LFE 89-044/00L-0 in 800314, containment isolation valves
PCV1-7, -14, -25 & -32 determined not protected against steam
get resulting from crack in loop 1 main steam riser. Caused
by design error. Action initiated to install proper supports
SUNCOASTING, J. D. Tennessee Valley Authority, HOPKINS, Tex.

00062001NH Forwards LER 00-048/DIT-0
CALIFORNIA R Tennessee Valley Authority 00/04/13 1a

9004240410 Forwards LCR 00-061/07L-0

--300420ZMKT LCR 80-044/01-0 on 800535, informed that wide range steam generator level transmitters not qualified to withstand post-accident operation caused by design error. All level transmitters being obtained for installation.

--0606240420 LER 80-061/00L-5 on 060528, auxiliary bldg vent radiation
meter, 0-99-70-102, declared inoperable due to spurious
high red spikes caused by defective 24-volt power supply
Power source replaced and meter returned to use

8006200479 Forwarded LFR 88-071/93L-D
CALHISLE, J D Tennessee Valley Authority 80/96/16 1a

606436516 Forwards LER 60-077/63L-0

--B064209484 LCB B0-071A02L-0 on 090917, rupture disk on toxic acid evaporator found ruptured, providing path for contents of waste gas decay tank to escape into room Cause unknown Event not immediately discovered due to no radioactivity in tanks RECORD D. J. Tennessee Valley Authority 09090616 288

--@06308523 L&R-BD-077/00L-B an D00525.8 train RMR & B train containment spray pumps were inoperable because valve F0V-63-73 failed to open Caused by valve failing to activate interlock limit switch

0006240429 Fernando LER 80-070/03L-0
CALHOUN, J R Tennessee Valley Authority 80/06/16 1a

V. Operator Examinations

--0006240433 LER 00-070/031-0 on 090917 during shutdown from
refueling water storage tank water level fell below required
limit caused by failure to initiate early makeup Makeup
immediately initiated
0000000 D J. Tennessee Valley Authority 00/06/16 224

BOB446161 Act receipt of BOB414 ltr requesting review of add training
for future applicants for license Concern w/proposal to
license new senior operators at Sequoyah for participation
as licensed personnel at Watts Bar
RCHUNCEB.A Licensing Branch 2 05/06/00 Rep

0036240363 Forwards LER 00-075/01T-D
CALHOUN, J R Tennessee Valley Authority 00/06/17 1a

SECRET 50-226 BROWNSVILLE NUCLEAR PLANT, UNIT 2

--0006240369 LCR 88-075/017-0 on 600524, auxiliary essential P pump 3-B failed during surveillance testing caused by personnel error in calculating pump differential pressure instrumentation velocity & pump restarted
SRL:BNM6 J in Tennessee Nuclear Authority 88/06/17 2p

0006030417 Forwards proposed for seismic margin program required by NURMS-O&I Program provides basis for HRO to complete examination of seismic qualification of structures &

0055240380 Forwards supplemental LER 60-245/01Y-1
CALHOUN, J R Tennessee Valley Authority 60/06/17 1a

HELEN L. B. helen.l.barnes@man.ac.uk <http://www.man.ac.uk/~helen.barnes>

V. Greater Examination

86-1109- 87- 8800- 8900- 9000- 9100- 9200- 9300- 9400- 9500- 9600- 9700- 9800- 9900

000870327 Discusses review of FRM Table 17 2-1, "Critical Structures, Sys & Components," re operational QA program. Forwards request for add'l info to be transmitted to client.
HARRIS P Quality Assurance Branch 80/26/05 dcm

N. Hoffman, *Final Report: Analysis Report 1988*, 5, Appendix.

8060110259 Application for Amend 65 to Licenses CPH-72 & CPH-73
containing revisions to Chapter 3 of FRM
MILLS, L. W. Tennessee Valley Authority 86/04/06 Doc

#004250000 Notification of 003419 meeting w/rtile in Batheeda,MO to
discuss issuance of full power license for facilities
ORDNERICH, A W Licensing Branch 1 800/641A 5pp

--R004110042 Revisions to Chapter 3 of PSAN, providing responses to PRC requests for addl info re radiation engineering direct generators & interconnect w/ program. Constitutes Award 45 to Licenses DPS-72 & CPAN-73
* Tennessee Valley Authority 6/27/04 0042

2026240223 Forwarded revised response to Question 12 14 re employee access to high radiation areas Revision includes description of administrative procedures controlling access to areas adjacent to fuel transfer bays

PHILMIL 04 Tennessee Valley Authority 00/06/97 2pg

80264190295 Forwarded proposed revisions to facility PSAR, Question 5 WA
re insurance and program Review request for relief from
AFPE Section 11 covering third party inspectors, pressure
retaining welds in piping 5 steam generator nozzles
MILLS, A. Tennessee Valley Authority 85/DA/12 5pp

9. *Advisory Committee on Teacher Education* reports & recommendations

0036200091 Forwards revised responses to Questions Q31, Q37, Q40 & Q51. ISV at NRC 740803. ISV re witness qualification of Class SE electrical equipment. Repts re cable samples & IEEE-Q20-8774 qualification encl.
MILLER, L. Tennessee Valley Authority 80/06/23 10pg

EO0623022? Notice of ACRS Subcommittee on Sequoyia Nuclear Plant Unit
1 & 2 800428 meeting in Washington, DC to continue review
of TVA application for license to operate
HDYLE-2 C Office of the Secretary of the Commission 80/04/04
Re.

==0006300097 "Delphi Pneumatic Test Procedure"
LSWR.0 Comstock, Delphi Systems Div 28/06/18 Doc

0006190006 Notice of indefinite postponement of ACES Subcommittee
ACCSWG meeting re Bhopal Nuclear Plant Units 1 & 2
HOYLE, J C ACES - Advisory Committee on Reactor Safeguards
0006190006

--8006300400 -Radiation Testing of Cell Number 885.Final
HILLIS, D E JET Corp 79/08/23 Tex

0036290074 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant
0006022 meeting in Washington, DC to review OL application
Some closed sessions may be needed to explore matters
involving proprietary info
HOYLE, J C Office of the Secretary of the Commission 00/05/
200

---0005300469 *Seismic Vibration Test of Eto Seiges Transmitters*
SEARS, J A Atlas Electronic Testing Corp 76/03/22 30pg

0054060608 Transcript of ACRS Subcommittee on Sequoyah Nuclear Power
Station meeting on 080602 in Washington, DC Pg 1-235
Starting session Viewgraphs A related notes and
ACRS - Advisory Committee on Reactor Safeguards 08/06/02
000000

--8004300414 "Test Procedure for Seismic Vibrations, Qualification Test of EIG Series PCA/BM Transmitters"
SEARS J A Acton Environ Testing Corp 73/09/26 25pp

--8004300422 "Data & Differential Pressure Transmitters Type EIG Series"
SCHREINER W Acton Environ Testing Corp 73/10/26 1Doc

■ **Beobachtung:** Lerne aus diesen Dokumenten & Erfahrungen

--G06C32042W "Qualification Test of Electrical Cables Under Simulated
LCCA/DSE By Sequential Exposure to Environments of Radiation,
Thermal Aging, Steam & Chemical Spray"
* Includes: Ins. Cables of Mansfield Enterprises, Inc. 1
78/06/20. 02w

000430070 Domestic exemption from corporate income tax

F. Security, medical, emergency & fire protection plans

8. *Intuition pumps*. 10. *Methods*. 8. *consequences*.

0005100317 Forward clarification of HRC requirements for emergency response facilities defined in 7YOV13 1tr Add specific criteria for facilities under development
EIS/MS/UT, S & Division of Operating Reactors 00/04/25 Also

6005345159 Forwarded IE Bulletin 80-11, "Maserns Mail Design " No action
as written response required IE Info Notice 79-25.
"Overloading of Structural Elements Due to Pipe Support
Loads" and
C'RELLER, J P Region 2, Atlanta, Office of the Director 80/05/88

006120000 Requests that FEMA review of state & local emergency plan be provided consistent with schedule to avoid potential delays to licensing decisions
006120000 F Commission 05/05/10 Doc

00046101333 Forwards IE Insp Rept 10-028/00-09 on 090421-23 No
noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engg
Support Branch 80/03/08 Jon

8064048994 Forwards add info to training & qualification plan inf
withheld (ref 806982 7Y0)
MILLER, R Tennessee Valley Authority 80/04/02 Doc

--8006180397 IE Insp Rept 30-328/00-09 ex 800421-23 No noncompliance noted Major areas inspected licenses identified items & QA audits
CAMERON, F S Region 2, Atlanta, Reactor Construction &
Engineering Support Branch MACFARLAND, C R Region 2, Atlanta,
Office of the Director 00/25/00 See

803413007 Forwards revised schedule for response to Auxiliary B
Granch fire protection review questions Proposed Train B
circuit route schedule shown as still marked as overall
drawings drawings available on Central Files only
MILWAUKEE N Tennessee Valley Authority 05/06/01 10pp

8004090267 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys
Operability." No written response required IE Info Notice
80-00, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" and
"FUELUX-1" Region 2, Atlanta, Office of the Director 80/05/09
D.

8004260164 Forwarded TVA radiological emergency plan & TN multi-jurisdictional radiological emergency response plan Three cross state and
MILLER, N Tennessee Valley Authority 80/06/17 ADM

0006120004 Forwarded IC Circular 00-11, "Emergency Diesel Generator Lub Oil Cooler Failures." No written response required.
0006120004 P Region 2, Atlanta, Office of the Director 00/05/12
D-2

—2006268165 TVA radiological emergency plan
• Tennessee Valley Authority 80/DA/89 350pp

---B036266166 TN multi-jurisdictional radiological emergency response
plan
* Tennessee, State of B0/04/19 400xx

DOCKETED ITEMS

139

- 000470193 As receipt of 000504 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-327/00-10 & 50-328/00-06
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/23 2pp
- 000617021 Response to NRC 000414 ltr re deviations noted in IE Insp Repts 50-327/00-10 & 50-328/00-06 Corrective actions completed instructions & procedures prepared Plant Fire Brigade reconstituted & Security Instructions 3D revised
MILLER, L H Tennessee Valley Authority 00/05/06 4pp
- 0006170218 Forwarded IE Insp Repts 50-327/00-10 & 50-328/00-06 on 00/03/18-23 7 notice of deviation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/03/14 2pp
- 0006170228 Notice of deviation from map on 00/03/18-21
Region 2, Atlanta, Office of the Director 00/04/01 1p
- 0006170229 IE Insp Repts 50-327/00-10 & 50-328/00-06 on 00/03/18-21 Noncompliance noted fire fighting procedures not provided for all safety-related areas
CONLID, R E Region 2, Atlanta, Reactor Construction & Engineering Support Branch MILLER, L H Region 2, Atlanta, Office of the Director 00/04/11 7pp
- 000620024V As receipt of 000523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/00-14 & 50-326/00-00
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/03 2pp
- 0006200247 Response to NRC 000501 ltr re violations noted in IE Insp Repts 50-327/00-14 & 50-326/00-00 Corrective actions Surveillance Instruction 154 will be revised to require examination of Class 2 pressure maintained boiling
MILLER, L H Tennessee Valley Authority 00/05/20 3pp
- 0006200278 Forwarded IE Insp Repts 50-327/00-14 & 50-326/00-00 on 00/03/18-2402 3 notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/01 2pp
- 0006200284 Notice of violation from Insp on 00/03/18-0402
Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/28 1p
- 0006200285 IE Insp Repts 50-327/00-14 & 50-326/00-00 on 00/03/18-0403 Noncompliance noted failure to comply w/procedure/discovery insp requirements & failure of records to adequately define practices exam criteria
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch DAWG, L D Region 2, Atlanta, Office of the Director 00/04/08 4pp
- 000620029V As receipt of 000502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/99-24 & 50-323/99-19
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/04 2pp
- 0006170362 Response to IE Insp Repts 50-327/00-14 & 50-328/00-06 All of Section 3 of Facility surveillance instructions 154 revised for compliance w/Section XI of ASME boiler & pressure vessel code
MILLER, L H Tennessee Valley Authority 00/06/09 1p
- 0006200360 Forwarded response to IE Bulletin 00-03 re vacuum conditions resulting in damage to boiler tanks Revises protection for relieving reactor storage tank at Surgecock & Watts Bar 1A provided by redundant venters & tank insulation
MILLER, L H Tennessee Valley Authority 00/06/09 6pp
- 0 Periodic operating reports & related correspondence
- 0006200405 "MPOES Discharge Monitoring Rept for Feb 1980"
Tennessee Valley Authority 00/03/01 100pp
- 0 Reportable occurrences, LERs & related correspondence
- 0006200392 Forwarded final deficiency rept re temp effect on main steam safety valve setpoint
MILLER, L H Tennessee Valley Authority 00/05/27 1p
- 0006200390 Final deficiency rept re temp effect on main steam safety valve setpoint
MILLER, L H Tennessee Valley Authority 00/05/27 1p
- 0006200396 Forwarded final deficiency rept re missed piping rupture protective device
MILLER, L H Tennessee Valley Authority 00/05/29 1p
- 0006200400 Final deficiency rept re pipe rupture protective device omitted from drawing of 3-inch upper head injection line & steam generator blowdown line Device will be installed Drawings will be reviewed re reflect change
Tennessee Valley Authority 00/05/29 1p
- 0006200402 Forwarded final deficiency rept re design of spent fuel pool gates not meeting Seismic Category I requirements
MILLER, L H Tennessee Valley Authority 00/05/29 1p
- 0006200403 Final interim deficiency rept re spent fuel pool gates not designed to Seismic Category I requirements Cause not stated Evaluation being conducted Complete corrective action will be forwarded by Unit 1 interim criticality
Tennessee Valley Authority 00/05/29 1p
- 0006200423 Forwarded final deficiency rept re Rustin fire dampers
MILLER, L H Tennessee Valley Authority 00/06/02 1p
- 0006200426 Final deficiency rept re Rustin fire dampers, Rustin designed alternate riser to bypass & bypass w/inversion spring closure & potential for jammed blades
Tennessee Valley Authority 00/06/02 3pp
- 0006200424 Final Part 21 rept re plant head of steel supplied by UR Steel from which 4-inch elbows & 2-inch tees were sig to 42399R requirement investigation conducted & closed at 42399R facility
SEAF, J L Centre Corp., Tube Turn Div 00/06/06 3pp
- 0006150057 Notices of noncompliance w/effluent limitations of NPSR permit Operational sewage treatment plant effluent sample collected on 00/05/01 exceeded AS significant Cause was accumulation of effluent in sand filter
EL-MERHI, R T Tennessee Valley Authority 00/06/10 1p
- 0006170445 Forwarded final interim deficiency rept re design criteria for secondary side pipe breaks Next rept will be submitted by 00/06/11
MILLER, L H Tennessee Valley Authority 00/06/11 1p
- 0006170452 Final interim deficiency rept re design criteria for secondary side pipe breaks Criteria does not provide for propagation of main steam crack to other liner Evaluation underway of pipe rupture interaction
Tennessee Valley Authority 00/06/11 1p
- 0006170457 Forwarded revision to 000527 final deficiency rept re temp effect of main steam valve setpoint
MILLER, L H Tennessee Valley Authority 00/06/11 1p
- 0006170462 Revision to 000527 Final deficiency rept re temp effect of main steam valve setpoint Drawing modification to air conditioning sys for valve room being modified to provide warmer temp range of 80-120 F
Tennessee Valley Authority 00/06/11 1p
- 0006170597 MPOES noncompliance notification on 000609, 01 value of vent discharge Discharge 007 exceeded max permit limitations, Cause as proposed investigation will be made & corrective measures taken if problem recurs
EL-MERHI, R T Tennessee Valley Authority 00/06/12 1p
- 0006200328 Forwarded final deficiency rept re spent fuel pool gates
MILLER, L H Tennessee Valley Authority 00/06/10 1p
- 0006200329 Final deficiency rept re spent fuel pool gates 0A aspects of gate integrity will be verified Midnight restraints will be attached to steel wall gate to prevent damage to spent fuel elements during seismic event
Tennessee Valley Authority 00/06/10 2pp
- 0006200372 Escalated interim deficiency rept re LH hydraulic isolation valve assembly weighing sig Review of mod proposed by Westinghouse is not complete Next rept will be submitted by 00/07/04
MILLER, L H Tennessee Valley Authority 00/06/10 1p

0004292600 Forwards suppl info for devicency rept re DCA movements of steel containment vessel
HILLER, L H Tennessee Valley Authority 00/04/10 1p

--0004292602 Suppl info for final devicency rept re DCA movements of steel containment vessel All addl items requested New supports & changes to existing supports needed for RMR spray headst piping
* Tennessee Valley Authority 00/06/18 1p

DOCKET 50-309 RELEASE PLANT, UNIT 1

A Application/construction stage documents & correspondence

0004230110 Advances RMR & RMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0077 re adequacy of applicable support structures General operating reactor review procedure 5 acceptance criteria and
EISENHART, D D Division of Licensing 00/05/20 12pp

0004200042 Notification of 000410 meeting w/utl in Bethesda, MD to discuss resumption of schedule for licensing review
HODG, D S Operating Reactors Branch 3 00/04/02 3pp

0004250010 Notification 000410 meeting w/utl in Bethesda, MD to discuss resumption of schedules for Facility licensing review
HODG, D S Licensing Branch 2 00/04/08 7pp

0004200041 Forwards new application page as replacement for original submitted 000302 Replacement page necessitated by clerical error committing of incorrect amend number
COOK, J H Consumers Power Co 00/04/11 2pp

--0004200045 Amend 79 to application for CP 6 GL-revising application page to correct Amend number
COOK, J H Consumers Power Co 00/04/15 1p

0004200040 Forwards requests for addl field explanations & info Corps of Engineers has requested addl borings & soil data to permit verification of soil conclusions re plant fill settlement problem & foundation design
SINGH, J P Assistant Director for Components & Structures Engineering 00/06/10 7pp

--0004200045 Forwards revised Encl 1 to 000307 request for addl borings & soil data
HICHLINSTEIN, P Army Dept of Corps of Engineers 00/04/10 App

0004240009 Advises NRC that still has developed tentative timetable for submitting cost & cost schedule revisions Info will be incorporated into Revision 11 of revision rept & submitted to NRC by 000415
COOK, J H Consumers Power Co 00/04/20 1p

F Security, nuclear, emergency & fire protection plans

0004250017 Forwards clarification of NRC requirements for emergency response facilities defined in 700913 for addl specific criteria for facilities under development
EISENHART, D D Division of Operating Reactors 00/04/25 41pp

0004200030 Notification of 000410 meeting w/utl in Bethesda, MD to discuss Facility security plan
HODG, D S Licensing Branch 3 00/04/02 3pp

G Administrative correspondence

0004200045 Response in apposition to R Sinclair 000402 motion to produce documents Revisions right to move for protective order if compelled to produce Request to too broad & outside scope of proceeding Certificate of DCA encl
FARNELL, A S Consumers Power Co FARNELL, A S John, Lincoln & Beale 00/05/07 App

0004250044 Answer in support of NRC 000420 motion for issuance of amended notice of hearing to 701208 order modifying CP
Seccore NRC request to serve copies of amend which granted to all GL proceeding parties Certificate of DCA encl
FARNELL, A S Consumers Power Co FARNELL, A S John, Lincoln & Beale 00/05/10 2pp

0004250050 Advises that CP answer to NRC motion for amended notice of hearing & CPC answer to notice of hearing re CP and have been informally served
SMITH, L H Atomic Safety and Licensing Board Panel 00/05/10 3p

0004180086 Forwards display advertisement re hearing on order for use of CP Advertisement will be printed in local newspapers FR notice of hearing & amended notice of hearing were published
HODG, D S Operating Reactors Branch 3 00/05/10 1p

0004100281 Requests permission for Reptation interview consultants to attend 000410 meeting in Bethesda, MD
HARRIS, L H Affiliation Unknown 00/04/09 1p

0004100282 Response to CPC 000307 motion for partial consolidation of discovery issues re permission to postpone further response until determination of intervention Upon permission for 000307 filing if postponement denied w/Certificate of DCA
FARM, W D Hearing Branch 4 00/04/10 App

0004230050 Petition to intervene re order for mod of CP Alleges insufficient evidence of atomic energy use which will create adverse economic effects on Cities of Midland, Saginaw & Bay City Certificate of DCA encl
GILBERT, C Affiliation Unknown 00/04/10 3pp

0004200423 Requests admittance as intervener in hearing re CP and Reptation on previous decision accepted
HARRIS, L H Reptation Intervener 00/04/23 1p

H General correspondence

0004100070 Requests that future correspondence be mailed to JH Cook at 1545 West Russell Road, Jackson, MI
COOK, J H Consumers Power Co 00/04/05 1p

0004100285 Praises NRC position re inst p testing of safety-related addl concrete tests & objectives due to rejections taken to concrete core Requests info re implications in NRC 000302 for re test that exceptions in GC requirements made
HARRIS, L H Reptation Intervener 00/04/05 2pp

0004100047 Notices of inability to attend 000410 meeting in Bethesda, MD due to lack of timely info Requests that timely notification be given in future
HARRIS, L H Reptation Intervener 00/04/14 1p

0004200072 Forwards Encl Marshall 000410 for re const of Facility Requests copy of rept
SUDHAKAR, D Senate, Finance 00/04/10 1p

--0004200079 Urges Commission to take action re halt Facility const Civilian rights are being overlooked by imposing future restrictive abuses & conditions in violation of Constitution Encl will be sent to all senators & news media
HARRIS, L H Affiliation Unknown 00/04/10 2pp

H Utility Final Safety Analysis Report (FSAR) & amendments

0004200050 Forwards Revision 2R to FSAR & supplemental piping & instrument ref drawings Amend 77 to combined CP & GL application encl Drawings available in Control Files only
COOK, J H Consumers Power Co 00/03/30 1p

--0004200050 Amend 77 to combined CP & GL application, revising & adding info to FSAR
COOK, J H Consumers Power Co 00/04/30 1p

--0004200012 Revision 2R to FSAR, providing changes in various sections resulting from routine design developments & re-analysis program Constitutes Amend 77 to combined CP & GL application
* Consumers Power Co 00/04/30 500pp

0004200050 Forwards Certificate of DCA for Amend 70 to CP & GL application, revising of Revision 2R to FSAR
FARNELL, A S Consumers Power Co 00/04/09 2pp

0004200091 Forwards Certificate of DCA for 000410 for submitting Amend 70 to application for CP & GL, consisting of Revision 2R to FSAR
DRAVINS, J P Consumers Power Co 00/04/20 3pp

H Administrative correspondence

0004200090 Responds to HODG 000410 for setting status of proposed settlement reiteration ARJ enable to predict date of formal decision but decision process is entering final phase
CLARK, H H Atomic Safety and Licensing Board Panel 00/04/10 1p

DOCKETED ITEMS

141

0 Inspection reports, IE Bulletins & correspondence

000170155 Forwards IE Insp Repts 50-329/80-10 & 50-330/80-10 on 50-331/80-10 & notice of violation
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/08 2pp

--000170150 Notice of violation from Insp on 000031-00
Region 3, Chicago, Office of the Director 00/04/08 1p

--000170162 IE Insp Repts 50-329/80-10 & 50-330/80-10 on 000031-00
Remedial action noted failure to properly follow work procedure for final fit-up of internal core support assembly
NRP, R C Region 3, Chicago, Office of the Director 00/04/08 2pp

000164007 Advice that complete review of release ASME safety-related pipes was submitted in 170716 response to IE Bulletin 70-03
Actions & conclusions described close out IE Bulletin 70-03
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/07 1p

000164023 Forwards corrected pages to IE Insp Repts 50-329/80-09 & 50-330/80-10
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/07 1p

000164026 Corrected Pages 1 & 2 to IE Insp Repts 50-329/80-09 & 50-330/80-10 on 000031-00
FIDRELLI, G Region 3, Chicago, Office of the Director 00/05/07 2pp

000164034 Forwards IE Insp Repts 50-329/80-11 & 50-330/80-12 on 000130-0000
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/16 2pp

--000164020 IE Insp Repts 50-329/80-11 & 50-330/80-12 on 000130-0000
Remedial action noted major area impacted localization of safety-related piping & materials & review of records
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/16 1p
Region 3, Chicago, Office of the Director 00/05/16 3pp

000164038 Forwards IE Insp Repts 50-329/80-14 & 50-330/80-15 on 000502
NRP, R C Region 3, Chicago, Office of the Director 00/05/08 2pp

--000164012 IE Insp Repts 50-329/80-14 & 50-330/80-15 on 000502
Remedial action noted major area impacted reactor vessel head anchor bolts & Region 3 findings on allegations re welding & ventilation installation
NRP, R C Region 3, Chicago, Office of the Director 00/05/08 1p
Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/08 2pp

000164013 Responds to IE Bulletin 70-04, "Longitudinal Weld Defects in ASME SA-516, Type 204 Machine Steel Pipe" Further review of manufacturers of ASME SA-516, Type 204 Series welded pipe indicates up to 100,000 ft in inventory
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/04 1p

000164039 Forwards interim response to IE Bulletin 00-09, "Vacuum Conditions Resulting in Damage to Chemical Valve Control Gas Hydrogen Tanks" & Vacuum relief valves will be covered by periodic metal program List of Insp results email
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/09 2pp

000164037 Adv receipt of 000515 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-01 & 50-330/80-01
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/10 1p

--000164037 Responds to NRC 000418 ltr re violations noted in IE Insp Repts 50-329/80-01 & 50-330/80-01 Corrective actions being placed on implementing design changes No tags prior to scheduled turnover
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/15 3pp

000164035 Adv receipt of 000502 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-329/80-09 & 50-330/80-10
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/11 1p

--000164042 Responds to NRC 000426 ltr re violation noted in IE Insp Repts 50-329/80-09 & 50-330/80-10 Corrective actions remedial actions re failure to approve acceptable criteria and for reactor vessel head anchor bolts
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 3pp

0 Remedial action reports & related correspondence

000164049 Forwards Design, BOP & CPC remedial action reports, Design remedial action report log sheets & BOP requests & CPC corrective action reports for month ending 000001
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 400pp

0 Remedial action reports, LERs & related correspondence

000164058 Part 21 report re classification of dampers General Power Corp Classification dampers on non-safety-related equipment Dampers do not have potential to create substantial safety hazard & do not fall under Part 21 reporting requirements
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/03 2pp

000164064 Final Part 21 report re steel heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were cut to ASME-BPVC requirements Investigation conducted & closed at ASME facilities
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/06 3pp

000164066 Interim deficiency report re internal restraint coatings having loss of adhesion between successive layers of coating per Procedure 7 testing methods for removal of failed coatings under production heat rate will be sent by 000918
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/11 2pp

000164060 Adv receipt of 000516 interim report re reactor vessel broken anchor bolts
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/11 1p

000164062 Adv receipt of 000502 Interim deficiency report re NRCB equipment identification will review final report on anchor bolts
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/11 1p

000164068 Interim deficiency report re Unit 1 reactor vessel broken anchor bolts Forwards Addendum 1, "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Bolts" Next report will be sent by 000601
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 2pp

--000164068 Addendum 1, "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Bolts" For Design Corp
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 2pp

000164064 Interim deficiency report re component qualification test documentation re-review Unit development program & schedule to complete review & provide associated documentation requested interim or final report will be sent by 000919
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 60pp

000164067 Interim deficiency report re potential overpressure condition in helium center support BOP analysis of nozzle loads for effects on support structure in complete loads are confirmed to exceed allowable loads Before plan
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/19 1p

0 Operator Examinations

000164061 Adv receipt of 000414 ltr requesting review of add'l training for future applicants for License Course of proposal to license nine senior operators as Supervisors for participation as licensed personnel at Watts Bar
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/03 2pp

DOCKET NO. 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

000164010 Advices NRC & FWR applicants of NRC decision to modify implementation plan presented in Section 4 of NRC-0077 re compliance of applicable vintage electric control General operating reaction review procedure & acceptance criteria add'l
FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/09 13pp

0004200062 Notification of 000432 meeting w/utill in Batheeds,ND to discuss resumption of schedule for licensing review
Agency C background info and
H000, B 0 Operating Reactors Branch 3 00/06/02 3pp

0004200010 Notification 000432 meeting w/utill in Batheeds,ND to discuss resumption of schedule for facility licensing review
H000, B 0 Licensing Branch 2 00/06/02 7pp

0004200031 Forwards new application page as replacement for original submitted 000032 Replacement page requested by clerical error submitting of Intersect Amend number
C004, J M Consumers Power Co 00/06/01 2pp

--0004200030 Amend 7B to application for CP & R, reviewing application page to current Amend Number
C004, J M Consumers Power Co 00/06/01 1p

0004200042 Forwards "Independent Pipeline Analysis, Highland Unit 2 (Current Design Info)," in response to NRC 000403 request Oversee drawings and
C004, J M Consumers Power Co 00/06/01 100pp

0004200040 Forwards request for add field explanations to info Corps of Engineers has requested add borings & soil data to permit verification of soil conditions re plant fill
retreatment problem & Foundation design
R0000, J P Assistant Director for Components & Structures Engineering 00/06/03 7pp

--0004200043 Forwards Revised Unit 1 to 000027 request for add borings & soil data
M000, J000, P. Army, Dept of, Corps of Engineers 00/04/00 6pp

0004200049 Advise NRC that util has developed tentative timetable for obtaining cost & cost schedule revisions info will be incorporated into Revision 1B of revision rept submitted to NRC by 000013
C004, J M Consumers Power Co 00/06/02 1p

F Security, medical, emergency & fire protection plans

0004200057 Forwards clarification of NRC requirements for emergency response facilities derived from 790123 (re add) specific criteria for facilities under development
E000000, B 0 Divisions of Operating Reactors 00/06/00 4pp

0004200030 Notification of 000011 meeting w/utill in Batheeds,ND to discuss facility security plan
H000, B 0 Licensing Branch 3 00/06/01 3pp

G Applications correspondence

0004200045 Response in opposition to H Sinclair 000402 motion to produce documents Reserves right to move for protective order if compelled to produce Request is too broad & outside scope of proceeding Certificate of Suit and
F0000, A 0 Consumers Power Co F0000, A 0 Idaho, Lincoln & Seale 00/06/02 4pp

0004200044 Answer in support of NRC 000430 motion for issuance of amended notice of hearing re 791290 order modifying CP & R. Re NRC request for serve copies of amendment granted to all CL protesting parties Certificate of Suit and
F0000, A 0 Consumers Power Co F0000, A 0 Idaho, Lincoln & Seale 00/06/03 3pp

0004200045 Advise that CPC answer to NRC motion for amended notice of hearing & CPC answer to notice of hearing re CP and have been informally served
SMITH, I W Atomic Safety and Licensing Board Panel 00/09/00 1p

0004200084 Forwards display advertisement re hearing on order for mod of CP advertisement will be printed in local newspapers for notice of hearing & amended notice of hearing was published
000030 & 000032 respectively
R000000, A Licensing Branch 3 00/06/00 1p

0004200045 Petition to Intervene re order for mod of CP Alleges insufficient exercise of eminent domain use which will create adverse economic effects on Cities of Highland, Regina & Big City Certificate of Suit and
DILBERT, C Affiliates Unknown 00/06/01 3pp

0004200043 Requests assistance as intervenor in hearing re CP has Admitted on previous occasions accepted
MARSHALL, H H Register Inter-veners 00/05/03 1p

H General correspondence

0004200073 Requests that future correspondence be mailed to JH Coe at 1945 West Marshall Road Jackson, MI
C004, J M Consumers Power Co 00/06/00 1p

0004200028 Proves NRC position re map & testing of safety-related soil concrete items & objections set to expedition taken to concrete cracks Requests info re implications in NRC 000252
It is still that exceptions to GC requirements that timely
MARSHALL, H H Register Inter-veners 00/06/00 3pp

0004200049 Notification of inability to attend 000112 meeting in Batheeds,ND due to lack of timely info Requests that timely notification be given re future
MARSHALL, H H Register Inter-veners 00/06/01 1p

0004200072 Forwards LH Marshall 000410 ltr re costs of Facility Requests corp of Reils
000000000, C Division, Finance 00/06/01 1p

--0004200075 Urges Commission to take action to hold facility until Citizens rights are being oversteered by imposing future restrictive changes & conditions in violation of Constitution Ltr will be sent to all senators & news media
MARSHALL, H H Affiliates Unknown 00/06/00 1p

K Utility Final Safety Analysis Report (FSAR) & amendments

0004200030 Forwards Revision 2B to FSAR & supplemental piping & instrument ref drawings Amend 77 to combined CP & CL application and Drawings available in Control Files only
C004, J M Consumers Power Co 00/06/00 1p

--0004200029 Amend 77 to combined CP & CL Application, revising & adding info to FSAR
C004, J M Consumers Power Co 00/05/00 1p

--0004200012 Revision 2B to FSAR, providing changes in various sections resulting from routine design developments & re-review program Committee denied 77 to combined CP & CL application
Consumers Power Co 00/05/00 500pp

0004200042 Forwards Certificate of Suit for Amend 7B to CP & CL applications, consisting of Revision 2B to FSAR
BACON, J L Consumers Power Co 00/06/00 2pp

0004200049 Forwards Certificate of Suit for 000011 re submitting Amend 7B to application for CP & CL, consisting of Revision 2B to FSAR
R000000, J P Consumers Power Co 00/06/00 4pp

H Affidavit correspondence

0004200040 Responds to 000030 re seeking status of proposed settlement consideration ARB unable to predict date of formal decision but decision process is under final phase
CL/PSL, H K Atomic Safety and Licensing Board Panel 00/06/01 1p

G Inspection reports, IE Deliberations & correspondence

0004200060 Forwards IE Insp Rpt 90-030/00-09 re 000028-07 NE re compliance noted
F0000, L 0 Region 3, Chicago, Reactor Construction & Engineering Report Branch 00/06/00 3pp

--0004200094 IE Insp Rpt 90-030/00-09 re 000028-07 NE noncompliance noted Rege are inspecting containment pressurizing work procedures, work activities & quality records
MARSHALL, H H Region 3, Chicago, Reactor Construction & Engineering Support Branch GALLAGHER, J Region 3, Chicago, Office of the Director 00/06/00 4pp

8604170759 Forwards IE Insp Repts 30-329/80-10 & 30-329/80-10 on 860201-29 re notice of violation
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/04/04 3pp

8604170758 Notice of violation from Insp on 860201-29
Region 3, Chicago, Office of the Director 86/04/02 1p

8604170749 IE Insp Repts 30-329/80-10 & 30-329/80-10 on 860201-29
Noncompliance noted failure to properly follow work
procedure for trail fit-up of internal case support
anchor bolts
FIORELLI, S Region 3, Chicago, Office of the Director 86/04/02 3pp

8604040407 Advances that complete review of certain NRC safety-related
pipes was submitted in 76016 response to IE Bulletin 79-03A
Additional conclusions described close out IE Bulletin 79-03A
HOMBL, R H Consumers Power Co 86/05/07 1p

8604040223 Forwards corrected pages to IE Insp Repts 30-329/80-09 &
30-329/80-10
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/03/12 1p

8604040226 Corrected Pages 1 & 2 to IE Insp Repts 30-329/80-09 &
30-329/80-10 on 860201-29
CDSR, J M; KOPPEL, R C Region 3, Chicago, Office of the Director 86/04/04 2pp

8604030306 Forwards IE Insp Repts 30-329/80-11 & 30-329/80-12 on
860430-0192 No noncompliance noted
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/03/15 3pp

8604030310 IE Insp Repts 30-329/80-11 & 30-329/80-12 on 860430-0192
No noncompliance noted Major areas inspected Installation of
safeguards benders & restrainers P review of EC records
DOWLING, D H Region 3, Chicago, Reactor Construction &
Engineering Support Branch 7414 T Region 3, Chicago, Office of
the Director 86/03/15 3pp

8604300129 Forwards IE Insp Repts 30-329/80-14 & 30-329/80-18 on
860302 No noncompliance noted
KOPPEL, R C Region 3, Chicago, Office of the Director 86/05/22
3pp

8604300132 IE Insp Repts 30-329/80-14 & 30-329/80-18 on 860302 No
noncompliance noted Major areas inspected reactor vessel
bottom anchor bolts & Region 2 findings on alignment re
heating & ventilation installation
WASP, R C Region 3, Chicago, Office of the Director FIORELLI, S
Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/03/21 3pp

8604300133 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects
in AGRC 0A-315 Type 304 Stainless Steel Pipe" Further
review of manufacturers of AGRC 0A-315 Type 304 Series
welded pipe indicates ref in UTs 860507 it is incorrect
CDSR, J M Consumers Power Co 86/04/04 1p

8604300135 Forwards Interim response to IE Bulletin 80-03, "Vacuum
Conditions Existing in Storage to Chemical Vial Control Gas
Holdup Tanks" Vacuum relief valves will be covered by
periodic maintenance program List of test results sent
CDSR, J M Consumers Power Co 86/04/29 3pp

8604300137 Ack receipt of 860515 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-329/80-01 &
30-329/80-01
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/04/11 1p

8604300137 Responds to NRC 860416 ltr re violations noted in IE Insp
Repts 30-329/80-01 & 30-329/80-01 Corrective actions described
will be placed on implementing design changes 90 days prior
to scheduled turnover
CDSR, J M Consumers Power Co 86/05/13 3pp

8604300135 Ack receipt of 860502 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 30-329/80-09 &
30-329/80-10
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/04/11 1p

8604300140 Responds to NRC 860486 ltr re violation noted in IE Insp
Repts 30-329/80-09 & 30-329/80-10 Corrective actions
nonconformance re: re failure to approve acceptable
criteria met for reactor vessel inspection was issued
CDSR, J M Consumers Power Co 86/05/22 3pp

8 Periodic operating reports & related correspondence

8604300429 Forwards Bachelier, S&A CPC nonconformance repts. Bachelier
nonconformance rpt log sheets & QA requests & CPC
corrective action repts for month ending 860501
CDSR, J M Consumers Power Co 86/04/18 3pp

9 Reportable occurrences, LSRs & related correspondence

8604300208 Part 21 rpt re classification of damage Bachelier Corp
classifies damage as non-safety-related equipment damage
do not have potential to create substantial safety hazard &
do not fail under Part 21 reporting requirements
BLAND, D E American Marring & Ventilating, Inc 86/04/03 3pp

8604300204 Final Part 21 rpt re mixed heat of steel supplied by US
steel from which 4-inch elbows & 2-inch tees were mfg to
ASMEBPS requirement Investigations conducted & closed at
40 limited facilities
BLAY, J L Chemron Corp - Tube Tubes Div 86/04/06 3pp

8604300206 Interim deficiency rpt re internal containment coatings
having loss of adhesion between successive layers of coating
sys Procedures & testing methods for removal of failed
coatings under preparation Next rpt will be sent by 860515
CDSR, J M Consumers Power Co 86/04/11 3pp

8604300205 Ack receipt of 860516 Interim rpt re reactor vessel broken
anchor bolts
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/04/11 1p

8604300205 Ack receipt of 860522 Interim deficiency rpt re NRCB
component identification Will review final rpt re matter
upon receipt
FIORELLI, S Region 3, Chicago, Reactor Construction & Engineering
Support Branch 86/04/11 1p

8604300205 Interim deficiency rpt re Unit 1 reactor vessel broken
anchor bolts Forwards Addendum 1, "Investigation of
Failure of Midland Reactor Pressure Vessel Anchor
Bolts" Next rpt will be sent by 860501
CDSR, J M Consumers Power Co 86/04/12 3pp

8604300205 Addendum 1, "Investigation of Pressure Failure of Midland
Reactor Pressure Vessel Anchor Bolts" For Bachelier Corp
+ Tideline Engineering Services 75-0889-1 A221 86/04/06
2pp

8604300205 Interim deficiency rpt re component qualification test
documentation re: Unit 1 development program & schedule
re complete review & provide associated documentation
requested Interim or Final rpt will be sent by 860515
CDSR, J M Consumers Power Co 86/04/15 3pp

8604300227 Interim deficiency rpt re potential overstressed condition
in station cooler supports BMD analysis of nozzle loads for
effects on structure & piping to complete loads are confirmed
to exceed allowable loads Redesign planned
CDSR, J M Consumers Power Co 86/04/14 1p

DOCKET 30-331 EXHIBIT AGRICULTURAL ENERGY CENTER

F Security, medical, emergency & fire protection plans

8604300247 Notice that new telephone sys called Health Physics
Network (HPN) has been installed at site Site intended for
use during emergencies to link all power plants & NRC
Emergency Notification Sys hotline will also be used
KOPPEL, R C Region 3, Chicago, Office of the Director 86/04/10
3pp

8604300144 Forwards review of emergency plan against criteria contained
in NRCB-600-1 Per Bachelier Corp & US Steel reviewed to
incorporate NRC review & recommended by 860423
IFPD, ITGT, A Operating Reactors Branch 2 86/05/15 1pp

8604300148 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790101" Rule
adds new Section 50.40 & App R to 10CFR50 & is expected
to be published in FR by end of May
EIDENHOF, D Division of Licensing 86/05/17 4pp

8604300148 Forwards fire protection revision Item 3.3 re fire barrier
penetration test data.
HALL, R E Brookhaven National Laboratory 86/05/22 3pp

0004130343 Forwards revised Pages 1-12 A New Page 14a For proposed rule (00CFR2 "Fire Protection Program for Nuclear Power Plants Operating Prior to 1960-01." transmitted by NRC 000519 for Page 14a not met.)
E180401.D G Division of Licensing 00/05/22 7pp

0004130112 Requests participation in study of people-related problems in nuclear emergency NRC representatives will visit facility & interview security staff personnel
JPM2110.T A Operating Reactors Branch 2 00/06/03 2pp

0004130103 Reconciler comments made during 000400 meeting Revised emergency plan will be submitted by 000700 Response by NRC 000307 for re radiological & environmental monitoring will be provided by 000402
N007.L D Issue Electric Light & Power Co 00/06/04 1p

0004130102 Forwarded status summary of fire protection safety evaluation open items, NRC positions on issues & DR evaluation of fire protection review
JPM2110.T A Operating Reactors Branch 2 00/06/06 2pp

0004130109 Forwards partial response to 791009 the re alternate safe shutdown capability Response partial & should be considered preliminary Detailed analysis in process of final review. Final review of analysis should be completed within two weeks
N007.L D Issue Electric Light & Power Co 00/06/06 3pp

0004130100 Submits special report re standby diesel generator day tank room fire protection sprinkler sys Resp describes sprinkler mode & corrective actions taken during sys inoperability to ensure plant safety & restore sprinkler sys capability
H0020.L D Issue Electric Light & Power Co 00/06/09 2pp

0004130107 Summary of 000329 meeting w/AFIL in Bethesda, MD re emergency preparedness for facility
H0020.T A Operating Reactors Branch 2 00/06/11 1p

0004130103 Forwards page changes to modified amended security plan changes withheld 0004 (00CFR2 7901)
N007.L D Issue Electric Light & Power Co 00/06/17 1p

9 Additional correspondence

0004130101 Order granting extension until 000625 for Commission to elect whether to review Director's 000213 decision denying petition re NRC's commitment under 00CFR2 206
C0114.D J Office of the Secretary of the Commission 00/06/21 1p

P Operating license status documents & correspondence

0004130105 Forwards addl This-2 related requirements to operating reactors license requirements for This Action Plan include shift training, licensing exams & license dissemination of operating experience Response requested within 30 days
E180401.D G Division of Licensing 00/06/07 10pp

0004130104 Summary of 000402-23 meeting w/Mark J owners group in San Jose, CA re coordination analysis & testing programs concerning Mark J containment long-term program
E180401.D G Assistant Director for Plant Systems 00/06/07 2pp

0004130102 Requests comments on NUREG-0577, "Potential for Low Pressure Turbine & Low Pressure Turbine on PWR Steam Generator & Reactor Coolant Pump Supports." Proposed review procedure & implementation schedule sent
E180401.D G Division of Licensing 00/05/19 7pp

0004130104 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-5510, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Comments will be evaluated by NRC prior to final implementation ltr sent
E180401.D G Division of Licensing 00/06/05 20pp

0004130102 Safety evaluation supporting average power range monitor channel gain adjustments during reactor startup & approach to full power
e Operating Reactors Branch 2 00/05/11 2pp

0004130107 Submits schedule for response to NRC 000425 ltr re effect of re power supply failure on SCOD performance Response will be provided by 000701
N007.L D Issue Electric Light & Power Co 00/06/16 1p

0004130101 Responds proposed changes to Facility Tech Spec per NRC 000410 request & 100700 79 & 100700 75 requirements
N007.L D Issue Electric Light & Power Co 00/06/17 2pp

0004130104 Proposed reactor Tech Spec change 121, amending App A of License 100-00 Reflected request for more detailed definition of "operable." Deletes single recirculation loop ltr issued amend 7 updates Facility sharing section
e Issue Electric Light & Power Co 00/06/17 20pp

Q Inspection reports, IF Bulletins & correspondence

0004130102 Forwards IF Circular 00-06, "BWR Tech Spec Inconsistency - Reactor Protection Sys Response Time." No written response required
H0020.L D Region 3, Chicago, Office of the Director 00/06/19 1p

0004130101 Forwards IF Insp Rept 90-021/00-06 as 000407-10 No noncompliance noted
E180401.D G Region 3, Chicago, Reactor Construction & Construction Support Branch 00/05/09 2pp

0004130104 IF Insp Rept 90-021/00-06 as 000407-10 No noncompliance noted Major areas inspected specs, procedures, observation of SCOD, electrical, force mode & all-scan view of jet pump
E180401.D G Region 3, Chicago, Reactor Construction & Engineering Support Branch 20/06/11 Region 3, Chicago, Office of the Director 00/05/02 2pp

0004130105 Forwards supplementary response to IE Bulletin 79-06 re availability, partially completed due to personnel assignment Evaluation of alarm sys in inoperable areas of plant identified two areas where alarm is not available
N007.L D Issue Electric Light & Power Co 00/06/06 2pp

0004130102 Forwards response to Item 3 of IE Bulletin 79-06, "BWR Loss Flow Control Blades." Shutdown margin test verified that full withdrawal of any control blade from steam-force case will not result in criticality
N007.L D Issue Electric Light & Power Co 00/05/00 2pp

0004130102 Forwards request for addl info re turbine disc cracking to learn more about underlying reasons for indications & probable growth rate IE Info Notice 79-07 & summary of 000400 meeting w/GE sent
JPM2110.T A Operating Reactors Branch 2 00/05/16 2pp

0004130102 Ack receipt of 000508 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-021/00-06
H0020.L D Region 3, Chicago, Fuel Facility & Materials Safety Branch 00/05/01 1p

0004130104 Responds to NRC 000421 ltr re violations noted in IE Insp Rept 90-021/00-06 Corrective actions plant managers given training on notification of unplanned releases & tech sampling requirements
N007.L D Issue Electric Light & Power Co 00/05/08 2pp

0004130105 Ack receipt of 000430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-021/00-06
H0020.L D Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/05/02 2pp

0004130105 Responds to NRC 000408 ltr re violations noted in IE Insp Rept 90-021/00-06 Corrective actions plant managers were advised of requirements of Tech Spec 6.0.0 that temporary procedure changes be only when in nature
H0020.L D Issue Electric Light & Power Co 00/04/20 2pp

0004130105 Responds to IE Bulletin 00-06, "Engineered Safety Features (ESF) React Controls." Test procedures are being developed to test engineered safety features equipment Parameters available drawings & drawings available in General Files only
N007.L D Issue Electric Light & Power Co 00/06/17 20pp

0004130104 "Reactor Core Cooling Sys" Sheet 42
e Docketed Corp 1094 73/10/04 1p

- 0006040402 "Reactor Core Cooling Sys " Sheet 38
+ Bechtel Corp 7884 74/01/75 1p
- 0006040495 "Nuclear Steam Supply Shutoff Sys " Sheet 24
ACTUAL REVISION STATUS LER 886, 800354-1
+ Bechtel Corp 7885 74/04/75 1p
- 0006040431 "Nuclear Steam Supply Shutoff Sys " Sheet 10
ACTUAL REVISION STATUS LER 886, 800291-1
+ Bechtel Corp 7884 73/11/77 1p
- 0006040435 "Elementary Diagram Nuclear Steam Supply Shutoff Sys "
Sheet 7
+ General Electric Co 74/05/76 1p
- 0006040477 "Elementary Diagram Nuclear Steam Supply Shutoff Sys "
+ General Electric Co 73/08/76 1p
- B Periodic operating reports & related correspondence**
- 0006170041 Forwards monthly operating report for May 1980
NINCKE, D L Iowa Electric Light & Power Co 80/05/13 1p
- 0006170044 Monthly operating report for May 1980
WV SICHEL, J Iowa Electric Light & Power Co 80/04/13 7pp
- C Reportable occurrences, LERs & related correspondence**
- 0006110039 BO as 800527, during refueling outage loop of reactor core
isolation cooling turbine-governor and pump and journal
bearing upper case found partially wiped Cause
undetermined Governor and pump and journal replaced
NINCKE, D L Iowa Electric Light & Power Co 80/05/23 2pp
- 0006030277 Forwards LER 80-018/017-0
NINCKE, D L Iowa Electric Light & Power Co 80/03/27 1p
- 0006030290 LER 80-018/017-0 as 800519, all drain petcocks on hydraulic
pump found open when all isolation in slight leak Cause
unknown Petcocks closed & all sealed
TODRES, D W Iowa Electric Light & Power Co 80/05/27 2pp
- 0006030297 Forwards LER 80-018/017-0
NINCKE, D L Iowa Electric Light & Power Co 80/05/27 1p
- 0006030441 LER 80-018/017-0 as 800520, three 3-amp fuses servicing A, B &
C annunciator cabinets in panel 1023 blew during shift alarm
testing Resulted in loss of both channels of core spray
warning alarm detection alarm was Cause unknown
TODRES, D W Iowa Electric Light & Power Co 80/05/27 2pp
- 0006030447 Forwards LER 80-017/038-0
NINCKE, D L Iowa Electric Light & Power Co 80/03/27 1p
- 0006030473 LER 80-017/038-0 as 800430, a reactor circulation pump motor
generator set tripped Cause by electrical short in motor
Cage of stator winding Motor removed & repaired
TODRES, D W Iowa Electric Light & Power Co 80/05/27 1p
- 0006030339 Forwards updated LER 78-014/015-1
NINCKE, D L Iowa Electric Light & Power Co 80/03/22 1p
- 0006030345 Updated LER 78-021/038-1 as 780301, during performance
improved maintenance control rod drive hydraulic system
and water level switches would not respond Cause by switch
electric fluid becoming stuck
DUDOST, E L Iowa Electric Light & Power Co 80/05/02 1p
- 0006030371 Forwards updated LER 78-014/015-1
NINCKE, D L Iowa Electric Light & Power Co 80/03/22 1p
- 0006030399 Updated LER 79-018/031-1 as 790725, during normal operation,
plant heat rate & efficiencies determined to be better
than normally expected Investigation revealed leaking
instrument casing measurement error
DUDOST, E L Iowa Electric Light & Power Co 80/05/02 2pp
- 0006170043 Forwards updated LER 78-014/015-1
NINCKE, D L Iowa Electric Light & Power Co 80/05/29 1p
- 0006070045 Updated LER 79-034/013-1 as 790703, results of testing re
SE Bulletin 79-02 indicated potential generic problem
w/switch bolts not meeting seismic design criteria Cased by
faulty installation & inadequate design
DUDOST, E L Iowa Electric Light & Power Co 80/03/29 2pp
- 0006030432 NO as 800515, standby diesel generator day tank room
april tank was removed from use for mod Mod work took longer
than anticipated & april tank was inoperable for more than 14
days Fire watch established until mod completion
NINCKE, D L Iowa Electric Light & Power Co 80/03/09 2pp
- 0006070039 Forwards LER 80-021/031-0
NINCKE, D L Iowa Electric Light & Power Co 80/03/20 1p
- 0006070241 LER 80-021/031-0 as 800524, while performing NPCL operability
testing, NPCL turbine would not reach rated speed within
required time Cause by component failure Leadbar hydraulic
seal in stop valve replaced w/URWMAH seal
TODRES, D W Iowa Electric Light & Power Co 80/03/20 1p
- 0006070344 Forwards LER 80-025/031-0
NINCKE, D L Iowa Electric Light & Power Co 80/03/20 1p
- 0006070247 LER 80-020/031-0 as 800523, during normal surveillance
testing of emergency bus time delay relay, seven Gould TR-
270 under-voltage relays found to have excessive delays
Cause by instrument drift Relay recalibrated
DUDOST, E L Iowa Electric Light & Power Co 80/03/20 1p
- 0006070371 Forwards updated LER 79-004/030-1
NINCKE, D L Iowa Electric Light & Power Co 80/05/20 1p
- 0006070274 Updated LER 70-204/026-1 as 790315, subsequent to startup,
driveline to suppression chamber differential pressure failed
to achieve set within required time Cause by leakage
through containment purge butterfly valve
DUDOST, E L Iowa Electric Light & Power Co 80/05/20 1p
- EGMGT 80-023 JAMES R. FITZPATRICK NUCLEAR POWER PLANT**
- F Security, medical, emergency & fire protection plans**
- 0006070407 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790301,"
adds new Section 35.46 & App B to 10CFR50 & is expected
to be published in FR by end of May
EIDENRUT, D G Division of Licensing 80/03/19 1p
- 0006070407 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790301,"
adds new Section 35.46 & App B to 10CFR50 & is expected
to be published in FR by end of May
EIDENRUT, D G Division of Licensing 80/03/19 1p
- 0006130043 Forwards revised Pages 1-14 & new Page 14a for proposed
rule 10CFR50 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790301," transmitted by NRC 930819
the Page 14a not sent
EIDENRUT, D G Division of Licensing 80/03/22 7pp
- 0006090044 Forwards request for add info re 800430 Revision 1 of
safeguards contingency plan request withheld
rev 10CFR50 7901
IMPOLITO, T A Operating Reactors Branch 2 80/03/28 2pp
- 0006190314 Requests participation in NRC study of people-related
problems in nuclear safeguards involving collection of data
on licensee security forces & practices including visit to
facility for interview with security staff personnel
IMPOLITO, T A Operating Reactors Branch 2 80/03/23 2pp
- 0006030440 Responds to NRC 800430 for re cooperation w/people-related
security problem study Interested in participating during
Fall 1980 after refueling outage & for as long as info is
received
MAYHEW, H J Power Authority of the State of New York 80/03/23
2pp
- H General correspondence**
- 0006020180 Requests that following names be included on correspondence
distribution list OT Gerry, JP Byrne, DR Wierwille, CH Pratt &
RJ Pastoral
MAYHEW, H J Power Authority of the State of New York 80/03/20
2pp
- F Operating license stage documents & correspondence**
- 0006090140 Forwards add TH-3 related requirements to operating
reactors Licensee requirements for TH Action Plan include
shift training, licensing exams & licensee distribution
of operating experience Response requested within 30 days
EIDENRUT, D G Division of Licensing 80/06/07 13pp

- 0004030014 Summary of 000402-23 meeting w/mark 1 owners group in San Jose, CA re confirmation of analysis & testing program concerning Mark 1 containment long-term program
GRIFFIN, C. Assistant Director for Plant Operation 00/05/07 0pp
- 0004100122 Requests comments on NUREG-1877, "Potential for Low Fracture Toughness & Lateral Tearing on PWR Steam Generator & Reactor Containment Pump Supports." Proposed review procedure & implementation schedule met
BLOOMBERG, D. Division of Licensing 00/05/19 72pp
- 0004030040 Ltr to all NRC licensees forwarding "For Comment" edition of NUREG-0418, "RSP Fuelwater System & Control Bus Drive Motors Like Noise Crazing." Comments will be evaluated by NRC prior to final implementation W/o etc
BLOOMBERG, D. Division of Licensing 00/05/03 20pp
- 0004100137 Advises that will will provide required info re effect of dc power supply failure on EOCB performance by 000715
BARNHART, J. Power Authority of the State of New York 00/05/09 22
- 0004100499 Response to NRC 000501-13 requests for info re containment vent & surge gasp. Licensee will install steps to limit travel of SG & SG-1 containment vent & surge gasp isolation valves to less than 50 degrees open
BARNHART, J. Power Authority of the State of New York 00/05/13 0pp
- 0004040501 Requests discussion w/NRC re alternatives to strict interpretation of addl TRS-1 related requirements as forwarded by NRC 000507 ltr. Flexibility necessary in implementation schedule for good cause shown
BARNHART, J. Power Authority of the State of New York 00/05/17 2pp
- 0 Inspection reports, IE Bulletin & correspondence
- 0005050403 Discusses IE Insp Rept 00-033/78-14 re collection storage & audit of QA records. NRC review previously scheduled. Licensee requests suspension of implementation requirements until NRC ruling on proposed 5-yr schedule
LEONARD, J. D. Power Authority of the State of New York 79/09/06 2pp
- 0006050408 Discusses IE Insp Rept 00-033/78-14 re collection storage & audit of QA records. NRC review 3-yr extension to implement computerized records not yet. Licensee alternative corrective action.
GRIFFIN, C. Region 1, Philadelphia, Office of the Director 79/09/20 2pp
- 0006050505 Discusses IE Insp Rept 00-033/78-14 re collection storage & audit of QA records. Full implementation of computerized records not yet. Licensee alternative corrective action.
LEONARD, J. D. Power Authority of the State of New York 79/06/22 2pp
- 0005030330 Forwards waste packaging Insp rpt on 000310-14. No noncompliance noted
STERN, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/04/07 2pp
- 0005020341 Waste packaging Insp rpt on 000310-14. No noncompliance noted. Major areas inspected: membership vehicle inspection for compliance w/DOE & NRC regulations including labeling, packaging & DOT placarding requirements.
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/03/28 4pp
- 0006050607 Forwards IE Circular 00-06, "Bus Tech Spec Inconsistency - Reactor Protection Sys Response Time." No written response required.
GRIFFIN, C. Region 1, Philadelphia, Office of the Director 00/04/10 0p
- 0006100607 Forwards waste packaging Insp rpt on 000310-14. No noncompliance noted
STERN, J. P. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/24 2pp
- 0006100611 Waste packaging Insp rpt on 000310-14. No noncompliance noted. Major areas inspected: membership vehicle inspection for compliance w/DOE & NRC regulations including labeling, packaging & DOT placarding requirements.
POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/03/28 4pp
- 0004030072 Re receipt of 000402-5 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 00-033/00-01
GRIFFIN, C. Region 1, Philadelphia, Office of the Director 00/05/03 1p
- 0004030076 Response to NRC 000310-14 re violations noted in IE Insp Rept 00-033/00-01. Corrective actions: failure to perform scheduled margin test discussed w/operations superintendent & shift supervisor on duty at time of event.
BARNHART, J. Power Authority of the State of New York 00/04/02 2pp
- 0004030081 Advises that corrective action per 000403-01 taken. Violation noted in IE Insp Rept 00-033/00-01 has commenced. Margin activity will be discussed w/operating shifts by 000501.
BARNHART, J. Power Authority of the State of New York 00/04/02 2pp
- 0004030085 Forwards IE Insp Rept 00-033/00-01 on 000304-00 & 15 & notice of violations
BARNHART, J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/03/11 2pp
- 0004030088 Notice of violation from Insp on 000304-00 & 15 & 100310-01
BARNHART, J. Region 1, Philadelphia, Office of the Director 00/03/04 1p
- 0004030092 IE Insp Rept 00-033/00-01 on 000304-00 & 15. Noncompliance noted: failure to comply w/tech spec prior to making control rod inoperable & to control release of liquid w/raft outside Tech Spec range.
BARNHART, J. Region 1, Philadelphia, Office of the Director 00/03/04 2pp
- 0004030094 Response to IE Bulletin 00-07 re BWR jet pump assembly failure. Containment operation to end of reactor fuel cycle is justified. Delta evaluation does not indicate significant degradation or impossibility of any jet pump.
BARNHART, J. Power Authority of the State of New York 00/03/07 2pp
- 0004030108 Forwards IE Insp Rept 00-033/00-01 on 000301-0404. No noncompliance noted.
BARNHART, J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/03/07 2pp
- 0004030109 IE Insp Rept 00-033/00-01 on 000301-0404. No noncompliance noted. Major areas inspected: previous Insp (rempl.) operations & IE Bulletin 79-02.
BARNHART, J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 00/03/07 2pp
- 0004030109 Forwards request for addl info re turbine disc integrity. Response requested within 30 days of receipt of ltr. Recommends development of schedule for performing full ultrasonic insp of two pressure turbine during next outage.
FISHER, T. A. Operating Reactors Branch 2 00/03/16 3pp
- 0004030190 "Raman Purify System Commission Check" & General Electric Co. 00R-72081 79/08/31 11pp
- 0004100676 Addl response to PDA request for six categories of documents re SFC. Forwards documents listed in app.
FISHER, T. A. Division of Rules and Records 00/05/03 0pp
- 0006100596 Discusses IE Insp Rept 00-033/75-03 on 750204-0388. Forwards notice of violation. Except only one.
FISHER, T. A. Atomic Energy Commission, Directorate of Reactor Operations 75/04/18 2pp
- 0006100612 Advises that AE has undertaken revision of resp. responding to IE Bulletin 79-018, "Environ. Qualification of Class II Equipment." Experts to submit response by 000607.
BARNHART, J. Power Authority of the State of New York 00/03/23 2pp
- 0006020020 Confirms areas needing clarification in response to IE Bulletin 79-018 per 000314 site Insp. Request within response within 240 hours of receipt of ltr if actual plans & actions differ from description requirements.
GRIFFIN, C. Region 1, Philadelphia, Office of the Director 00/05/20 2pp

8806030210 Forwarded response to NRC 880501 for re adequacy of station electrical distribution and voltage bus voltage condition will be maintained only during operation time of under-voltage relay & will have no effect on plant safety
DUNN, C. N. Duquesne Light Co 80/06/17 7pp

G Inspection reports, EE Bulletins & correspondence

8806100274 Forwarded IE Insp Rept 80-334/80-11 on 880415-14 NRC compliance note regarding action operating manual change notice issued to provide additional check of alarm/trip setpoint. Computer scheduling card format will be changed
DUNN, C. N. Duquesne Light Co 80/06/17 7pp

8806100276 IE Insp Rept 80-334/80-11 on 880415-17 NRC noncompliance noted Major areas inspected welding & nondestructive test associated with infiltration spray & low head safety injection system mod
TRIPP, L. E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, NRC/04/28 4pp

8806030318 Ask receipt of 880203 for re number of inspections being performed inspections are intended to occur infrequently & will involve minimal duplication of inspection efforts
STELLIS, V. Office of Inspection & Enforcement, Office of the Director 80/05/05 2pp

8806030321 Response to NRC 791284 for re performance & approval function based use of checks & balance via SE audit is desirable, though possibly too demanding on bay personnel
SCHAFER, S. G. Duquesne Light Co 80/05/05 3pp

8804030317 Provides add info re extension of time to complete response to item 4-IE Bulletin 79-018 Pursuing program to establish uniform conditions which Class IE electrical equipment may experience following NDS & to determine aging factors
KIMM, C. N. Duquesne Light Co 80/05/05 2pp

8806030317 Forwarded IE Insp Rept 80-334/80-08 on 880324-28 NRC noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/09 2pp

8806030343 IE Insp Rept 80-334/80-08 on 880326-28 NRC noncompliance noted Major areas inspected QA program review, QA/QC administrative design change & mod control, measurement & test & previous Insp items
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, NRC/05/09 2pp

8806030356 Ask receipt of 880429 for re violations noted in IE Insp Rept 80-334/80-01 on 880324-28 NRC noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Office of the Director 80/05/10 1p

8806030362 Response to NRC 880403 for re violations noted in IE Insp Rept 80-334/80-01 on 880324-28 NRC noncompliance noted Major areas inspected QA program review, QA/QC administrative design change & mod control, measurement & test & previous Insp items
DUNN, C. N. Duquesne Light Co 80/06/29 4pp

8806030364 Forwarded IE Insp Rept 80-334/80-01 on 880414-28 NRC noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/03 2pp

8806030366 Notice of violation from Insp on 880414-28 NRC noncompliance noted
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/03 2pp

8806030368 IE Insp Rept 80-334/80-01 on 880414-28 NRC noncompliance noted inadequate implementation of administrative controls for jumpers/lines leads & verification monitor inspection set in view of each pipe limits
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, NRC/06/03 2pp

8806101194 "Insp Rept Inside Rectification Spray Pumps"
STERNER, J. D. Duquesne Light Co 80/05/31 7pp

8806100401 Response to IE Bulletin 80-09, "Hydro-motor Actuator Deficiencies" NRC hydro-motor actuators installed at plant
DUNN, C. N. Duquesne Light Co 80/06/06 1p

8806100275 Response to IE Bulletin 80-06 Test for demonstration that all equipment remains in emergency mode upon removal of emergency manual tripping of various isolating or actuation signals will be completed prior to scheduled start-up in Jul
DUNN, C. N. Duquesne Light Co 80/06/06 4pp

8806030382 Response to IE Bulletin 80-04, "Engineered Safety Feature (ESF) Start Controls" Lists equipment that does not remain in emergency mode & lists proposed corrective action & implementation schedule
DUNN, C. N. Duquesne Light Co 80/06/06 4pp

8806100400 Response to IE Bulletin 80-10, "Cooling Heat Removal Sys Operability" Review of LERs completed Operating manual procedures will be modified prior to starting Facility will be adequately safeguarded against degradation
DUNN, C. N. Duquesne Light Co 80/06/06 4pp

8806030429 Response to NRC 880501 for re violation noted in IE Insp Rept 80-334/80-04 Corrective actions noted work request initiated to repair fire doors, closure linkages adjusted prior replaced with new-duty mechanism
DUNN, C. N. Duquesne Light Co 80/06/10 2pp

H Periodic operating reports & related correspondence

8806030374 Forwarded NRCED discharge monitoring report for Apr 1985
DUNN, C. N. Duquesne Light Co 80/03/20 2pp

8806030385 NRCED discharge monitoring report for Apr 1985
DUNN, C. N. Duquesne Light Co 80/06/20 12pp

8806030390 Monthly operating report for Feb 1985
DUNN, C. N. Duquesne Light Co 80/06/02 1p

8806030391 Monthly operating report for Feb 1985
DUNN, C. N. Duquesne Light Co 80/06/07 4pp

8806030401 Monthly operating report for Mar 1985
DUNN, C. N. Duquesne Light Co 80/06/10 1p

8806030402 Monthly operating report for May 1985
DUNN, C. N. Duquesne Light Co 80/06/02 4pp

I Reportable occurrences, LERs & related correspondence

8806120560 RD on 880514, during routine driven fire pump test, high temp alarm received Pump shut down three times upon activation. Cause not stated Pump out of test & temporary fire pump started up
MELINSKY, J. A. Duquesne Light Co 80/05/30 1p

8806030359 Forwarded LER 80-026/03L-0
MELINSKY, J. A. Duquesne Light Co 80/05/31 1p

8806030362 LER 80-026/03L-0 on 880430, pump being used to start liquid waste discharge observed to have higher than normal flow. Caused by leaking of effluent valves. Corrective actions scheduled to be completed as soon as possible
MELINSKY, J. A. Duquesne Light Co 80/05/31 4pp

8806120565 RD on 880501, during routine containment inventory, finding was high point vent tripping found During repair, discharge valve closed during loss of NRP flow caused by false high pressure signal due to instrument loop de-managing
MELINSKY, J. A. Duquesne Light Co 80/05/31 2pp

8806030406 Forwarded LER 80-027/03L-0
MELINSKY, J. A. Duquesne Light Co 80/06/20 2pp

8806030415 LER 80-027/03L-0 on 880430, during waste on diesel generator, high oil cooler temperatures of river water. Discharge valve valve was disengaged in cooler. Caused by unseated hinge pin. Guides on valve valves will be replaced
MELINSKY, J. A. Duquesne Light Co 80/06/20 2pp

8806030358 Forwarded LER 80-026/03L-0 & 80-026/03L-0
MELINSKY, J. A. Duquesne Light Co 80/06/02 1p

--0006060374 LER 00-020/017-0 on 00060104, overstrain condition was confirmed to exist during postulated seismic event up to 1000 ft. A component cooling water system line 00-020/017-0 was found to be overstressed during the event analysis.
LACEY, H. S. Duquesne Light Co 00/06/02 1p

--0006060389 LER 00-020/017-0 on 00060104, plant operators testing diesel-driven fire pump when high level alarm was received & elevated overheat caused by in 00060104 fire pump. High level alarm was received & elevated overheat caused by in 00060104 fire pump. High level alarm was received & elevated overheat caused by in 00060104 fire pump.
LACEY, H. S. Duquesne Light Co 00/06/02 1p

0006060373 Forwarded LERs 00-020/021-0 & 00-020/021-0
MELTHER, J. A. Duquesne Light Co 00/06/02 2pp

--0006060382 LER 00-020/021-0 on 00060104, during control board insul. eval. control tank outlet valve was found stuck caused by shorts. Control board is in lock position. Shorted wire replaced.
LACEY, H. S. Duquesne Light Co 00/06/02 1p

--0006060389 LER 00-020/021-0 on 00060104, power was lost to vital bus inverter 4 due to blown main power supply fuse. Cause unknown. Fuse & rectifier replaced. Frequency adjusted.
LACEY, H. S. Duquesne Light Co 00/06/02 1p

0006060412 FWD-1 00-020-0 on 00060104, skills enhanced NRC of tornado watch in vicinity of plants. Forecast included potential for severe thunderstorms, large hail & damaging winds. Licenseses implemented emergency procedures.
MCCABE, C. Region 1, Philadelphia, Office of the Director 00/06/02 2pp

0006060408 Forwarded LER 00-040/017-0
MELTHER, J. A. Duquesne Light Co 00/06/04 3pp

--0006060412 LER 00-040/017-0 on 00060104, questions on quality of radiographs at facility led to radiograph rolap printed by personnel. error in interpretation of radiograph prints. Defects repaired & re-radiographed.
LACEY, H. S. Duquesne Light Co 00/06/04 2pp

0006060421 Forwarded LER 00-031/017-0
MELTHER, J. A. Duquesne Light Co 00/06/04 2pp

--0006060426 LER 00-031/017-0 on 00060104, again finding leaking RHR sys. leak valve seal. Evaluation commenced to re-energize RHR. Isolation valve in case of gross failure. Cause of de-energized process control signal & vent work leak.
LACEY, H. S. Duquesne Light Co 00/06/04 2pp

0006060441 NO on 00060104, meteorological instrumentation computer channel found not responding properly to automatic callor signal. Cause by output resistors had been removed during 00060104 move. Resistors removed & gas calibrator verified.
MELTHER, J. A. Duquesne Light Co 00/06/04 2pp

0006060459 Forwarded LERs 00-034/021-0, 00-020/021-0 & 00-034/021-0
MELTHER, J. A. Duquesne Light Co 00/06/04 2pp

--0006060463 LER 00-034/021-0 on 00060104, during air flow surveillance test on fire suppression system, 300 ft of sprinkler nozzle found plugged. Caused by rust & unidentified metal. Nozzle will be cleaned & gas blown down again.
LACEY, H. S. Duquesne Light Co 00/06/04 1p

--0006060471 LER 00-034/021-0 on 00060104, during real time surveillance test, internal pressure found to be less than design. High level alarm caused by rust & unidentified metal. Nozzle will be cleaned & gas blown down again.
LACEY, H. S. Duquesne Light Co 00/06/04 1p

--0006060474 LER 00-034/021-0 on 00060104, during real time surveillance test, internal pressure found to be less than design. High level alarm caused by rust & unidentified metal. Nozzle will be cleaned & gas blown down again.
LACEY, H. S. Duquesne Light Co 00/06/04 1p

0006060485 Forwarded LER 00-034/021-0
MELTHER, J. A. Duquesne Light Co 00/06/04 2pp

--0006060486 LER 00-034/021-0 on 00060104, gasous waste tank 04-TM-1A pressure decreased from 10 to 5 psig. Cause by leak in flanges of flow orifice & pressure transmitter. Tanks manually isolated until leak & testing can be completed.
LACEY, H. S. Duquesne Light Co 00/06/04 1p

0006060479 Forwarded LER 00-020/017-0 re status of work being performed on safety-related tanks. Repair to one of three tanks within one week. Tank inspected to date should be performed.
LACEY, H. S. Duquesne Light Co 00/06/02 1pp

0006060480 NO 00-020/017-0 during review of radiographs of reactor containment. After seven weeks, portion of one weld in code acceptable. Authenticity of seven weld radiographs questionable. Investigation continuing.
MELTHER, J. A. Duquesne Light Co 00/06/02 1p

SECRET 00-020/017-0 LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

0006060482 Forwarded proposed rule exhibited, "Fire Protection Program for Nuclear Power Plants Operating Prior to 1980" = Rule adds new Section 20.40 & App. A to 10CFR20.40 & is expected to be published in FR by end of May.
LISBON, D. D. Division of Licensing 00/05/97 4pp

0006060483 Forwarded revised Pages 3-14 & new Page 14a for proposed rule 10CFR20.40 "Fire Protection Program for Nuclear Power Plants Operating Prior to 1980" = Transmitted by NRC 000597. 14a Page 14a not incl.
LISBON, D. D. Division of Licensing 00/05/97 7pp

0006060484 Forwarded security plan, Revision 2
Plan withdrawn (ref 10CFR20.40)
MELTHER, J. A. Florida Power & Light Co 00/06/06 1p

0006060485 Forwarded safeguards contingency plan, Revision 1, in response to NRC 000518 request for add info. Revision withdrawn (ref 10CFR20.40)
MELTHER, J. A. Florida Power & Light Co 00/06/06 1p

J. Insurance & indemnity information

0006060486 Forwarded Endorsement 20 to NELA Policy NF-027
FIELDER, J. Marsh & McLennan, Inc. & N. H. Nuclear Consultants, Inc. 00/05/97 2pp

0006060487 Forwarded Endorsement 20 to NELA Policy NF-027
FIELDER, J. Marsh & McLennan, Inc. & N. H. Nuclear Consultants, Inc. 00/05/97 2pp

N. Antitrust correspondence

0006060488 Notice by Orlando Utilities Commission to withdraw intervention & request to institute proceedings re Commission 700727 under City of Orlando jurisdiction & will 000606 settlement resolved issues. Affidavit & Certificate of Sec.
HISE, W. C. Orlando, FL. HISE, W. C. Univ. W. C. 00/06/02 4pp

P. Operating license change documents & correspondence

0006060489 Forwarded add TMI-2 related requirements to operating license. License requirements for TMI-2. Action Plan include staff training, licensing issues & license discontinuation of operating experience. Response requested within 30 days.
LISBON, D. D. Division of Licensing 00/05/97 19pp

0006060490 Request comments re NRC 0007-0077, "Potential for Low Pressure Hydrogen Gas in the Reactor Core" = Proposed rule will require reactor core pump supports to be designed to withstand a low pressure hydrogen gas. Implementation schedule incl.
LISBON, D. D. Division of Licensing 00/05/97 7pp

0006060491 Advice that vendor analyses supporting proposed add to automatic initiation of auxiliary feedwater sys. flow will be delayed. Substantiated expected by 000606. Operational delay will include safety analysis. (transmittal)
MELTHER, J. A. Florida Power & Light Co 00/05/97 2pp

0006060492 Forwarded flow C-E report re code for calculating PWR screen activities. Control element assembly group withdrawal & three-part report for automatic combination for uncertainties. Preparatory version withdrawn (ref 10CFR20.40)
MELTHER, J. A. Florida Power & Light Co 00/05/97 1p

--0006060493 "CRM Method of Analyzing Sequential Control Element Assembly Group Withdrawal Report for Aging Protected Sys." = nonproprietary version
A. C. C. Engineering, Inc. CRM-106/11-10 00/05/97 10pp

--000400319 "PERTA One Dimensional Two Group Space-Time Kinetics Code for Calculating PWR Steady State Activities"
BETHUNE, U. Combustion Engineering, Inc. CEH-122(F)-NP 7/11/75
15pp

--000400321 "Statistical Combination of Uncertainties Methodology-Part 1 C-E Calculated Local Power Densities & Thermal Head/Co Pressure LBRD for St Lucia Unit 1." noncompliance version
Combustion Engineering, Inc. CEH-122(F)-NP PT3 7/12/75
16pp

--000400326 "Statistical Combination of Uncertainties Methodology-Part 2 Combination of Bys Parameter Uncertainties in Thermal Margin Analyses for St Lucia Unit 1." noncompliance version
Combustion Engineering, Inc. CEH-122(F)-NP PT2 8/05/75
16pp

--000400329 "Statistical Combination of Uncertainties Methodology-Part 3 C-E Calculated Reactor Power Indicate Building & Liner Heat Rate Limiting Conditions for Operation For St Lucia Unit 1." noncompliance version
Combustion Engineering, Inc. CEH-122(F)-NP PT3 8/05/75
16pp

0004010120 Dismisses still 7/10/79 submittal re degraded grid voltage
Forwards request for addl info
CLARK, R. A. Operating Reactors Branch 3 8/05/79 3p

0004010471 Forwards info re ENI-related requirements in response to
NRC 800407 1tr
WRIGHT, R. E. Florida Power & Light Co. 8/06/79 3pp

0004010629 Notification of 800405 meeting w/ENR & E in Bethesda, MD
to discuss history, indications & analysis of voiding &
corrective actions re 800405 event at facility
COWLES, L. C. Operating Reactors Branch 3 8/06/79 2pp

0004010709 Discusses main steam line break analysis results show that
just containment pressure is not influenced by assumed
addition of auxiliary feedwater induced steam generator
Forwards assumptions used in analysis
WRIGHT, R. E. Florida Power & Light Co. 8/06/80 10pp

0004010721 Application for amend to App A of License DPE-57, modifying
definition of operability & applicability of limiting
conditions for operation to coincide w/words in STD per
NRC 800410 1tr
WRIGHT, R. E. Florida Power & Light Co. 8/06/80 2p

--0004010714 Safety evaluation supporting amend to App A of License
DPE-57
Florida Power & Light Co. 8/06/80 1p

--0004010719 Revised Tech Spec per proposed amend to App A of License
DPE-57, modifying definitions of operability & applicability
of limiting conditions for operation to coincide w/words in
STD
Florida Power & Light Co. 8/06/80 3p

0 Inspection reports, IE Bulletin & correspondence

0004010008 Forwards IR Insp Rept 80-035/80-09 on 800408-10 No
noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch, 8/05/80 2pp

--0004010008 IE Insp Rept 80-035/80-09 on 800408-10 No noncompliance
noted Major areas inspected: installed equipment review per
IE Bulletin 79-018
COWLES, L. C. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch, 8/05/80 2pp
WRIGHT, R. E. Region 2, Atlanta, Office of the Director, 8/05/80 2pp

0004010008 Forwards IE Bulletin 80-11, "Hanging Wall Design" Requires
action & written response IE Info Notice 79-03
"Overloading of Structural Elements Due to Pipe Support
Load" encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 8/05/80 2pp

0004010008 Forwards IE Bulletin 80-12, "Steam Head Removal Sys
Operability." Requires action & response within 75 days
IE Info Notice 80-02, "Loss of Steam Head Removal Capability
at Davis-Besse Unit 1 While in Refueling Mode" encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 8/05/80 2pp.

0004010017 Forwards IE Circular 80-11, "Emergency Diesel Generator Unit
Oil Cooler Failures." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 8/05/80 2pp

0004010009 Forwards IE Insp Rept 80-035/80-10 on 800409-0502
No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch, 8/05/80 2pp

--0004010027 IE Insp Rept 80-035/80-13 on 800409-0802 No noncompliance
noted Major areas inspected: insurance insp & licensee
response to IE Bulletin 79-07
COWLES, L. C. Region 2, Atlanta, Office of the Director, 8/05/80 2pp
WRIGHT, R. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch, 8/05/80 4pp

0004010033 Ack receipt of 000118, 00021 & 000118 informing NRC of
steps taken to correct violations noted in IE Insp Rept
80-035/79-28, 80-031/79-28, 80-035/79-33 & 80-039/79-33
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch, 8/05/80 3p

--0004010021 Response to NRC 7/10/79 1tr re violations noted in IE Insp
Rept 80-035/79-35, 80-031/79-35, 80-035/79-33 & 80-039/79-33
Corrective actions & procedures will be reviewed w/ full
compliance achieved by 8/07/80
WRIGHT, R. E. Florida Power & Light Co. 8/05/80 1p

--0004010025 Response to NRC 7/10/79 & 800220 1tr re violations noted in
IE Insp Rept 80-035/79-35, 80-031/79-35, 80-035/79-33 &
80-039/79-33 Corrective actions & procedures will be reviewed w/ full
compliance achieved by 8/07/80
WRIGHT, R. E. Florida Power & Light Co. 8/05/80 2pp

0004010104 Ack receipt of 000118 1tr informing NRC of steps taken to
correct violations noted in IE Insp Rept 80-035/79-35
LEWIS, C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 8/05/80 2p

--0004010106 Response to NRC 800410 1tr re violations noted in IE Insp
Rept 80-035/80-09 Corrective actions inherent measures taken
to apply audible plus count to refueling area
WRIGHT, R. E. Florida Power & Light Co. 8/05/80 2pp

--0004010171 Forwards IE Insp Rept 80-035/80-08 on 800401-07 & notice
of violation
WRIGHT, R. E. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch, 8/06/80 2pp

--0004010173 Notice of violation from Insp on 800401-07
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
8/06/80 1p

--0004010179 IE Insp Rept 80-035/80-08 on 800401-05 Noncompliance noted
Failure to have plus monitor indication audible in
containment during zero alterations
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
8/06/80 4pp

0004010004 Forwards response to IE Bulletin 80-15 Failure of sig single
active component during decay heat removal sys operation
will not result in loss of cooling
WRIGHT, R. E. Florida Power & Light Co. 8/06/80 4pp

0004010007 Response to IE Bulletin 80-05 Existing measures for return
protection are adequate & no further mods are required
WRIGHT, R. E. Florida Power & Light Co. 8/06/80 1pp

R. Periodic operating reports & related correspondence

0004010467 Forwards monthly operating reports for May 1980
SCHEIDT, A. D. Florida Power & Light Co. 8/06/80 1p

--0004010479 Monthly operating report for May 1980
SCHEIDT, A. D. Florida Power & Light Co. 8/06/80 4pp

R. Reportable occurrences, LBRD & related correspondence

0004010025 RD 325-80-27 on 800510-C-E Informed until that partial
draining of RCS while in Mode 3 in condition not analyzed
for boron dilution event Plant operating procedures revised
to increase shutdown margin
MURPHY, C. E. Florida Power & Light Co. 8/05/80 1p

0004010445 Forwards LBR 80-087/087-0
SCHEIDT, A. D. Florida Power & Light Co. 8/05/80 1p

DOCKETED ITEMS

161

--80062344Y LER 80-027/077-0 on 800514, during shutdown for maint. NERS notified that partial draining of RCS while in Mode 5 is condition that has not been analyzed for boron dilution event. Procedures revised to increase min shutdown margin.
SCHPPMHA-A Florida Power & Light Co 80/05/21 3pp

006110037 Forwards LER 80-033/011-0
SCHNIST-A D Florida Power & Light Co 80/05/26 1p

--800611004Z LER 80-028/011-0 on 800512, during planned secondary shutdown for turbine maintenance header could not depressureize following steam stop closure due to observed bypass valve stem. Stem underrun. Valve stem replaced.
SCHPPMHA-A Florida Power & Light Co 80/05/26 3pp

006170579 Forwards LER 80-019/031-0
SCHMET-A D Florida Power & Light Co 80/05/31 1p

--800617048Z LER 80-019/031-0 on 800501, during normal refueling operations, leak check of personnel air lock indicated leakage in excess of Tech Specs. Caused by defective air lock handwheel shaft packing gland. Packing glands adjusted.
SCHPPMHA-A Florida Power & Light Co 80/05/31 1p

006170542 Forwards LER 80-021/031-0
SCHMET-A D Florida Power & Light Co 80/06/04 1p

--800617051 LER 80-021/031-0 on 800507, during normal surveillance & post-maint testing, IA signal generator failed to synchronize to emergency bus. Caused by frequency parameter relay being set incorrectly. Relay setpoint corrected.
SCHPPMHA-A Florida Power & Light Co 80/06/06 1p

006170647 Forwards LER 80-020/031-0
SCHMET-A D Florida Power & Light Co 80/06/06 1p

--800617062 LER 80-020/031-0 on 800507, during startup following refueling, auxiliary feed pump governor found out of adjustment. Caused by drifting of speed setting potentiometer. Potentiometer readjusted.
SCHPPMHA-A Florida Power & Light Co 80/06/06 1p

006170648Z Forwards LER 80-023/031-0
SCHMET-A D Florida Power & Light Co 80/06/10 1p

--800617047 LER 80-023/031-0 on 800511, during power ascension, central element assemblies 19 & 38 dropped to full insertion. Caused by failure of 19-inch power control valve. Both central element assemblies were restored.
SCHPPMHA-A Florida Power & Light Co 80/06/10 1p

800620449 LER 80-025/027-0 on 800611, ground occurred on bus 1B dc causing containment isolation valve (CIV) to fail closed. Apparently caused by water in solenoid. From steam leak. Cockham continuing. Damaged valve seals will be replaced.
WETNY-C D Florida Power & Light Co 80/06/11 3pp

006170648Z Forwards LER 80-024/031-0
SCHMET-A D Florida Power & Light Co 80/06/13 1p

--800620476 LER 80-024/031-0 on 800614, while shut down for refueling, periodic leak of engineered safety features showed 10 diesel generators load sequence timers were out of tolerance. Caused by support drift. Maladjustment valve caused other problems.
SCHPPMHA-A Florida Power & Light Co 80/06/15 3pp

DOCKET 30-034 MILLSTONE NUCLEAR POWER PLANT, UNIT 2

/ Security, medical, emergency & fire protection plans

006180426 Forwards request for addl info re facilities' emergency plans. Plans should be evaluated against NUREG-0454 & encl. copies of 800508.
CHITCHELW-B D Operating Reactors Branch 3 80/05/12 3pp

800620449 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 760101." Rule added to new Section 19 of 10 CFR 50.155 & is expected to be published in FR by end of May.
BIRNBAUM-D D Division of Licensing 80/05/17 4pp

006180445 Forwards revised Pages 1-18 & new Page 19a for proposed rule 10CFR50.155 "Fire Protection Program for Nuclear Power Plants Operating Prior to 760101," transmitted by NRC 800519. 19a Page 19a not encl.
BIRNBAUM-D D Division of Licensing 80/05/22 7pp

800640437 Submits info to reaffirm adequacy of current fire protection plans re fuel cell. EER construction. One auxiliary driving encl.
CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) / CDANIEL-W D Connecticut Yankee Atomic Power Co 80/05/21 3pp

H General correspondence

006170464Z Advances of personnel change. Ed Precita notified of open as station superintendent on 800601.
PRECCIA-W D Northeast Utilities 80/06/02 1p

P Operating license stage documents & correspondence

800620165 Forwards addl TRN-0 related requirements to operating Reactors Licenses requirements for TRN Action Plan include shift training, licensing exams & licensee dissemination of operating experience. Response requested within 30 days.
EISENHUT-D D Division of Licensing 80/05/07 15pp

800610122Z Requests comments on NUREG-0577, "Potential for Low Pressure Surgeheat & Low-Level Flooding of PWR Steam Generator & Reactor Coolant Pump Supports." Proposed testing procedure & implementation schedule encl.
EISENHUT-D D Division of Licensing 80/05/19 7pp

800620203Z Application to amend License BRN-45 by incorporating revisions to Tech Specs for Millstone 2 in response to NRC 800410 request. Proposed changes are necessary for safe operation of Facility. Millstone 2 is only unit at Tech Specs.
CDANIEL-W D Connecticut Yankee Atomic Power Co / CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/21 3pp

--800620201Z Proposed revisions to Tech Specs for Millstone 2, incorporating requirements of NRC 800410. 1tr to all power reactor licenses.
CDANIEL-W D Connecticut Yankee Atomic Power Co (subs of Northeast Utilities) 80/05/21 7pp

800640406 Forwards proprietary version of basic safety report addendum, "Nuclear Uncertainties," implementing test Section 4.0. Describes power peaking factor uncertainty analysis used in revised fuel design. Report withheld (ref 800508).
CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/28 3pp

800610444Z Forwards Amend SR to License DFR-43 & notice of issuance & availability.
CLARK-R A Operating Reactors Branch 3 80/05/29 3pp

--800610441Z Amend SR to License DFR-43, changing Tech Specs to permit storage of fuel assemblies containing 2 B2s by weight.
CLARK-R A Operating Reactors Branch 3 80/05/29 3pp

--800610418Z Notice of issuance & availability of Amend SR to License DFR-43.
CLARK-R A Operating Reactors Branch 3 80/05/29 3pp

800620474 Forwards addendum to "Basic Safety Rpt" re nuclear uncertainties, uncertainties in reactivity.
CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/30 1p

--800603047Z Addendum to "Basic Safety Rpt" re nuclear uncertainties, uncertainties in reactivity.
CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/31 23pp

800610407 Modification of 800434 meeting agenda & meetinghouse in Bethesda, MD to discuss core power distribution, subcooled nucleate boiling, uncertainty analysis & proposed Tech Spec changes re Cycle 4 reload. Unavailability of fuel.
CDANIEL-W D Operating Reactors Branch 3 80/05/20 3pp

800610307 Disagrees small break LOCA ECCS performance results. Primarily effect function of gas characteristics such as ECCS 4B & 4C. Injection timing, injection location, pressure & core power level. Supporting info encl.
CDANIEL-W D Northeast Utilities 80/06/02 14pp

800610445 Provides descriptive info & design assessment of proposed low level refueling facility available to NRC review. Required Facility will be operational late 1980.
CDANIEL-W D Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/02 7pp

DOCKETED ITEMS

800610041 LWR 80-01/02-1 re 800508: following shutdown, broken saddle clamp pins found on hydraulic master hanger 800502. Gases of fatigue & high impact leading bolts replaced with high strength bolts for high temp use
CLM/RN, R. Northwest Nuclear Energy Co. (subs. of Duke) Nuclear Division
CLM/RN, R. 80/05/08 1p

DOCKET 80-038 NORTH ANNA POWER STATION, UNIT 1

P. Security, medical, emergency & fire protection plans

800600051 Forwards request for addl info needed to complete NRC review of guard training & qualification plan, submitted by unit 7001010 for info request submitted (ref 80CFR 750)
CLM/RN, R. Operating Reactors Branch 3 80/05/19 3pp

800600047 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101" Rule adds new Section 20.4B A App R to 10CFR 70.4 is expected to be published in FR by end of May
EISENHART, D G Division of Licensing 80/05/19 46pp

800610055 Forwards revised Pages 1-14 & new Page 14c for proposed rule 10CFR 70.4 "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101," transmitted by NRC 800519 for Page 14c not sent
EISENHART, D G Division of Licensing 80/05/22 70pp

800600056 Response to NRC 800504 ltr re guard training & qualification program Response will be forwarded by 800714
BYLVA, D R Virginia Electric & Power Co 80/05/28 1p

800610055 Forwards Revision 1 to emergency plan Section 4 will require not resulting from 800510 meeting w/NRC & will be forwarded upon completion Commonwealth of VA 800510 ltr sent
BYLVA, D R Virginia Electric & Power Co 80/05/08 3pp

800610007 Revision 1 to emergency plan
+ Virginia Electric & Power Co 80/06/09 100pp

800600469 Forwards addl changes to station emergency plan, completing response to DLR 800512 comments
BYLVA, D R Virginia Electric & Power Co 80/06/20 2pp

800600478 Emergency plan, Revision 2
+ Virginia Electric & Power Co 80/06/18 27pp

800600089 Forwards Revision 2 to emergency plan, discussed w/NRC on 800520 Also forwards Sheriff of Henrico County, VA 800520 ltr of agreement & list of changes to emergency plan
BYLVA, D R Virginia Electric & Power Co 80/06/25 1p

800600084 Revision 2 to emergency plan Sheriff of Henrico County, VA 800520 ltr of agreement & list of changes sent
BYLVA, D R Virginia Electric & Power Co 80/06/25 20pp

G. Adjudicatory correspondence

800610028 Notifies that time has elapsed for Commission consideration of petition for review of ALP-984 Since Commission has not granted petition, petition is deemed denied
CHILDS, J J Office of the Secretary of the Commission 80/05/29 1p

800610049 Recommends that ALAD composition be changed to remove imbalance between lawyer & technical members & that unnecessary legalistic burdens, procedures & requirements be eliminated
BEAL, E V B Valentine B Deal 80/06/09 4pp

800610047 Advises of change in info in 800324 ltr Westinghouse exit event & probability analyses will not be ready until Oct 1985 Exit analyses will require not addl exit event exit tables withheld (ref 10CFR 750)
CHILDS, J J Henken S Williams 80/06/20 2pp

800600043 Ack receipt of 800629 ltr re turbine nozzle loose delay in Westinghouse analyses to not matter of serious concern to ALAD ALAD must be promptly notified if disk cracking map is postponed beyond Dec 1985
BEAL, E V B Atomic Safety and Licensing Appeal Panel 80/06/24 1p

F. Operating license stage documents & correspondence

800600045 Forwards addl TH-2 related requirements to operating reactor license requirements for THE Action Plan include shift morning, licensing team & license administration of operating assistance Response requested within 30 days
EISENHART, D G Division of Licensing 80/05/07 180pp

800600025 Forwards Amend 18 to License NPF-1, safety evaluation & notice of issuance & availability
CLM/RN, R. Operating Reactors Branch 3 80/05/19 3pp

800600029 Amend 18 to License NPF-4, correcting administrative error previously existing in Tech Spec re max response time supported from onset of detected degraded reactor power sys
CLM/RN, R. Operating Reactors Branch 3 80/05/19 3pp

8006070534 Safety evaluation supporting Amend 18 to License NPF-4 + Office of Nuclear Reactor Regulation Director 80/05/19 2

800600057 Notice of issuance & availability of Amend 18 to License NPF-4
CLM/RN, R. Operating Reactors Branch 3 80/05/19 3pp

800610022 Requests comments on NRC 80-0577, "Potential for Low Fract Temperature & Similar Tempering on PWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule incl
EISENHART, D G Division of Licensing 80/05/19 72pp

8006000173 Advises that, contrary to date stated in 800428 1m, permit permanent replacement atmospheric sys will be installed by 800630 per NRC 80-0578 Permanent sys will be installed by 800630 (updates incl)
BYLVA, D R Virginia Electric & Power Co 80/05/20 4pp

800600023 Application to amend DL w/ Tech Spec Change 3B, removing Reactor 103, installed in safety injection sys in subgrade area from Tech 3 to 4 Proposed Change 3B & Class III fee incl
BYLVA, D R Virginia Electric & Power Co 80/06/02 3pp

800600027 Proposed Change 3B to Tech Spec, removing Reactor 103 & Tech 3 to 4
+ Virginia Electric & Power Co 80/06/02 1p

800600056 Confirms 800620 action authorizing amend to DL Tech Spec License NPF-4 is amended, deleting subsec 103, on Page 3/4 7-34 Formal copies of amend & PB notice forthcoming
BYLVA, D R Assistant Director for Operating Reactors 80/06/02 3pp

800610065 Provides comment to most addl TH-2 related requirement identified in NRC 800307 ltr, providing equipment protection schedules do not impact implementation of hardware changes
BYLVA, D R Virginia Electric & Power Co 80/06/26 1p

800610033 Proposes multiphase plan to address NRC concerns re multi-phase amplified response spectra being used to analyze piping sys in low head & high head safety injection lines List of multi-phase problems & sample problem incl
BYLVA, D R Virginia Electric & Power Co 80/06/06 10pp

800600033 Forwards "North Anna Operational Background Chemistry Review" addl info re increasing Westinghouse boric acid treatment program to be forwarded within few days
BYLVA, D R Virginia Electric & Power Co 80/06/18 1p

800600043 "North Anna Operational Background Chemistry Review" SANSWALA, G. - PMA, V L NRC App 80/06/30 46pp

800600028 Confirms agreement to revise criteria for retrieval test & reactivity with tests Modified Table A 2 of VEP-FR-06, "Control Rod Reactivity Test Determination by Rod Swap Technique" sent
BYLVA, D R Virginia Electric & Power Co 80/06/26 4pp

800600045 Forwards history of experienced total & partial power outages at facilities re Westinghouse NRC 800307 request
BYLVA, D R Virginia Electric & Power Co 80/06/26 4pp

B. Inspection reports, IE Bulletin & correspondence

800610081 Forwards IE Item Repts 90-026/03-16 & 90-039/03-17 on 800323-061 re non-compliance noted
EISENHART, D G Reactor & License Branch Operations Nuclear Support Branch 80/06/29 2pp

DOCKETED ITEMS

0004120134 IE Insp Repts 90-039/00-04 & 90-039/00-17 on 000303-0411 No noncompliance noted Major areas inspected short-term Lessons Learned (NR020-0070), 001-2 Action plan (NR020-0060) & plant readiness for fuel loading
 0004120135 J Region 2, Atlanta, Reactor Operations Nuclear Support Branch N100-HS Region 2, Atlanta, Office of the Director 00/05/02 1pp

0004120136 Forwards IE Insp Repts 90-039/00-18 & 90-039/00-19 on 000412-14 No noncompliance noted
 000412-14 Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/02 2pp

0004120138 IE Insp Repts 90-039/00-18 & 90-039/00-19 on 000412-14 No noncompliance noted Major areas inspected initial fuel loading of Unit 2
 000412-14 Region 2, Atlanta, Reactor Operations Nuclear Support Branch N100-HS Region 2, Atlanta, Office of the Director 00/05/02 2pp

0004120139 Forwards IE Bulletin 90-11, "Housing Hall Design - Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and
 000412-14 Region 2, Atlanta, Office of the Director 00/05/02 2pp

0004120140 Forwards IE Insp Repts 90-039/00-17, 90-04/00-02 & 90-04/00-03 on 000409-10 No noncompliance noted
 000412-14 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/02 2pp

0004120141 IE Insp Repts 90-039/00-17, 90-04/00-02 & 90-04/00-03 on 000409-10 No noncompliance noted Major areas inspected
 IE Repts 79-12 & 001-03 activities re checks in berated water tank & containment filter penetration tests
 000412-14 Region 2, Atlanta, Reactor Construction & Engineering Support Branch N100-HS Region 2, Atlanta, Office of the Director 00/05/02 4pp

0004120142 Forwards IE Bulletin 90-12, "Decay Heat Removal Sys Operability" - Requires action & response within 30 days
 IE Info Notice 00-04, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While on Refueling Mode" and
 000412-14 Region 2, Atlanta, Office of the Director 00/05/02 2pp

0004120143 Forwards IE Circular 90-11, "Emergency Diesel Generator Lube Oil Cooler Failures" - No written response required
 000412-14 Region 2, Atlanta, Office of the Director 00/05/02 2pp

0004120144 Response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bus During Operation"
 No equipment on other instrument & control power buses is needed to maintain hot or cold shutdown condition
 000412-14 Region 2, Atlanta, Office of the Director 00/05/02 3pp

0004120145 Forwards response to IE Bulletin 90-05 re vacuum conditions resulting in damage to backup tanks The potential problem areas involving borne evaporator bottom tank & borate acid storage tanks identified
 000412-14 Region 2, Atlanta, Office of the Director 00/05/02 2pp

0004120146 Forwards response to notice of violation contained in IE Insp Repts 90-039/00-20 & 90-039/00-21 Corrective action
 all equipment will respond to safeguards engineered activation events in PWR
 000412-14 Region 2, Atlanta, Office of the Director 00/05/10 2pp

0004120147 Forwards response to IE Bulletin 90-09 Hydraulic actuator
 Repts 90-09 & 90-09 one not used at facility
 000412-14 Region 2, Atlanta, Office of the Director 00/05/10 2pp

0004120148 Forwards response to IE Bulletin 90-12 re decay heat removal sys operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if subsystem is operable
 000412-14 Region 2, Atlanta, Office of the Director 00/06/11 4pp

0004120149 Response to IE Bulletin 90-06 requesting review of drawings for all area working safety-related functions of schematic level verification of controls & proposed design made
 Actions & schedules delineated in Item 2
 000412-14 Region 2, Atlanta, Office of the Director 00/06/12 10pp

Re Periodic operating reports & related correspondence

0004120150 Forwards "Special Tests & Design Changes 1979"
 000412-14 Region 2, Atlanta, Office of the Director 00/06/05 1p

0004120151 "Special Tests & Design Changes 1979"
 000412-14 Region 2, Atlanta, Office of the Director 00/06/05 2pp

0004120152 Forwards monthly operating repts for May 1980
 000412-14 Region 2, Atlanta, Office of the Director 00/06/07 1p

0004120153 Monthly operating repts for May 1980
 000412-14 Region 2, Atlanta, Office of the Director 00/06/07 1p

Re Repeatable occurrences, LIRs & related correspondence

0004120154 PWS-11-00-093 on 000503, safety injection activation occurred within electrical but was lost while plant was shutdown
 Following completed Reaction Trip Caused by C Steam Generator Feedwater Regulating Valve Failure to open
 000412-14 Region 2, Atlanta, Office of the Director 00/05/03 1p

0004120155 Forwards R3 90-04/01/0-04-b follow-up repts
 000412-14 Region 2, Atlanta, Office of the Director 00/05/07 1p

0004120156 R3 90-04/01/0-0 on 000503, activation of EOSE was initiated by high steam flow fault-to-low steam flow fault
 EOSE was de-energized at time of EOSE initiation caused by frequency oscillations in dc to ac inverter for Vessel Bus 1-11
 000412-14 Region 2, Atlanta, Office of the Director 00/05/07 2pp

0004120157 Forwards LER 90-04/03/0-0
 000412-14 Region 2, Atlanta, Office of the Director 00/05/09 1p

0004120158 LER 90-04/03/0-0 on 000503, during review of operations periodic test schedule quarterly inspection done of 8 LWRs
 pump check valves determined not performed within required interval caused by inadvertent deletion from schedule
 000412-14 Region 2, Atlanta, Office of the Director 00/05/09 2pp

0004120159 Forwards LER 90-04/07/0-0
 000412-14 Region 2, Atlanta, Office of the Director 00/06/04 1p

0004120160 LER 90-04/07/0-0 on 000503, safety injection occurred due to high steam flow signal caused by 8 LWRs
 In lieu of Vessel Bus 1-11 which removes power from feedwater flowsteam flow comparators for steam generators
 000412-14 Region 2, Atlanta, Office of the Director 00/06/04 4pp

0004120161 R3 several items in low head & high safety injection sys were not analyzed for effects of fluid head below 70 P
 Review of new nozzle loads should lead on pump exceeded
 under allowable load Multibeam program proposed
 000412-14 Region 2, Atlanta, Office of the Director 00/06/06 10pp

0004120162 Proposes multi-phase plan to address ARC concerns re simplified response spectra curves used as basis for analysis
 when playing sys is subjected to more than one spectra
 000412-14 Region 2, Atlanta, Office of the Director 00/06/06 11pp

0004120163 Forwards LER 90-04/03/0-0
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 1p

0004120164 LER 90-04/03/0-0 on 000510, while performing monthly surveillance test 1-PT-04 on solid waste protection tests
 A protective P-11 failed caused by failure of logic card
 universal card will logic card replaced
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 2pp

0004120165 Forwards LER 90-04/03/0-0
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 1p

0004120166 LER 90-04/03/0-0 on 000510, control power fuses for containment particulate & gas radiation monitors blew when restarting sample pump possibly caused by current feedback from motor contactor
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 2pp

0004120167 Efficiency repts re safeguards area exhaust sys Exhaust sys modified to ensure operability following seismic event Red consisted of installing mechanical means of opening central area exhaust ductwork on auxiliary bldg roof
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 2pp

0004120168 Update 791031, 1115, 50 & 1020 repts re safeguards area exhaust sys not being entirely seismic-resistant designed
 essential equipment which might not receive adequate cooling affected equipment modified to ensure operability
 000412-14 Region 2, Atlanta, Office of the Director 00/06/09 2pp

- 0004050033 "LECA." revised emergency procedures
HARVEY, S. L. / CANTWRIGHT, H. Virginia Electric & Power Co. 00/05/32 2pp
- 0004050034 "Less of Bromine Containment." revised emergency procedures
HARVEY, S. L. / KELLUM, J. D. Virginia Electric & Power Co. 00/05/32 2pp
- 0004050037 "Steam Generator Tube Rupture." revised emergency procedures
HARVEY, S. L. / CANTWRIGHT, H. Virginia Electric & Power Co. 00/05/32 2pp
- 0004050041 "Isotopic Injection." revised emergency procedures
HARVEY, S. L. / KELLUM, J. D. Virginia Electric & Power Co. 00/05/32 2pp
- 0004100001 Notification of 000405 meeting w/Util in Louisa, VA to discuss use of assembly utility
OSBORN, R. A. M. Licensing Branch 1 00/05/30 3pp
- 0004200002 Forwards request for addl info re high range monitors to continue review of PWR Requests submitted by 000410
OSBORN, R. A. M. Licensing Branch 1 00/05/32 4pp
- 0004200002 Forwards request for addl info re containment sump performance Requests info be submitted by 000420
OSBORN, R. A. M. Licensing Branch 1 00/05/31 7pp
- 0004300025 Summary of 000420 meeting w/Util & OEM re revision qualification of safety-related electrical equipment
OSBORN, R. A. M. Licensing Branch 1 00/06/02 3pp
- 0004700041 Requests that Tests M.9a & 9b be deleted from proposed test program. Request to adapt TNA results from tests by simulator to augment operator training Test similar to Test 9b will be performed using decay heat
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/05 2pp
- 0004800004 Approves request to withhold 000429 application supplementing 791107 submittal re solid tube wear (ref 000470)
WYLVIA, S. R. Licensing Branch 1 00/06/05 2pp
- 0004800002 Provides commitment to meet addl TH1-2 related requirements. Identified in MEC 000507 lit/providing equipment procurement schedule do not impact implementation of hardware changes
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/06 3p
- 0004800034 Proposes multiphase plan to address MEC demands re multistructure amplified response spectra being used to analyze piping sys in low head & high head safety injection lines. List of multistructure problems & sample problem encl
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/06 10pp
- 0004800046 Confirms compliance w/TH1-2 Bulletin & Orders Test Force final recommendations (Items 3, D, V through 3, D, 12). Proportional integral differential controller on pressure/steam apparatus relief valve modified
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/09 2pp
- 0004800049 Forwards addl info re MUREP-0376, Item 2 I & A, Integrity Sys. Outside Containment. Likely to Contain Radiactive Matter. Latest test results indicate elimination of leakage after seal & complete leakage evaluation for MUREP-0440
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/09 2pp
- 0004800048 Forwards evaluation of battery room ventilation sys which checks into control room. Other hydrogen accumulation not loss of battery electrolyte will pose safety hazard or control room habitability problem
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/10 7pp
- 0004800041 Forwards Final Procedures 0-0T-0, 2-0T-1, 3-0T-4 & 4-0T-9 for special (low power) test program incorporating Westinghouse & NRC vendor comments. Also forwards variation of Tests 2 & 3
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/12 3pp
- 0004800045 "Natural Circulation Verification." final procedure for special (low power) test program
HARRIS, G. A. Virginia Electric & Power Co. 00/06/12 40pp
- 0004800041 "Effect of Steam Generator Secondary Side Isolation on Natural Circulation." final procedure for special (low power) test program
HARRIS, G. A. Virginia Electric & Power Co. 00/06/12 46pp
- 0004800042 "Coldroom Capability of Chemical & Vol Control Sys." final procedure for special (low power) test program
HARRIS, G. A. Virginia Electric & Power Co. 00/06/12 10pp
- 0004800043 "Natural Circulation w/Isolated Loss of Power Conditions." final procedure for special (low power) test program
HARRIS, G. A. Virginia Electric & Power Co. 00/06/12 16pp
- 0004800043 Forwards description of containment high range radiation monitors required per MUREP-0376, Item 2 I & A, in response to MEC 000507 lit. For floor plan drawing encl
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/16 4pp
- 0004800048 Notification of 000410 meeting w/Util in Bethesda, MD to discuss issuance of full power license for facilities
OSBORN, R. A. M. Licensing Branch 1 / KELLUM, J. D. Licensing Branch 2 / STANLEY, S. R. Licensing Branch 3 00/06/16 4pp
- 0004800049 Submits appl to Util 000410 lit re proposed indicator circuit relating for facility control room. Further discussions have decided relamping unnecessary. Lamp failures will be replaced per 000410 lit info
OSBORN, R. A. M. Virginia Electric & Power Co. 00/06/17 1p
- 0004800043 Forwards safety analysis & discussion of required exemptions to Test Spec for special low power test program. Requests amend to license which would permit performance of special test program by temporarily accepting certain Tech Specs
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/18 10pp
- 0004800049 Forwards request for addl info re review of PWR re branch technical position. RSD 3-1 Requests advisement if info will not be available by 000430
WYLVIA, S. R. Licensing Branch 1 00/06/18 5pp
- 0004800043 Notification of 000426 meeting w/Util in Louisa County, VA to discuss battery room ventilation sys
OSBORN, R. A. M. Licensing Branch 1 00/06/18 4pp
- 0004800048 Forwards "Electrical Equipment Qualification, MUREP-0288 Review." in response to MEC 000519 lit & 000520 meeting in Bethesda, MD. Not in complete except for info not yet supplied by vendor
OSBORN, R. A. M. Virginia Electric & Power Co. 00/06/20 1p
- 0004800049 "Electrical Equipment Qualification, MUREP-0288 Review." *
* Virginia Electric & Power Co. 00/06/20 300pp
- 0004800049 Forwards response to request for addl info re review of PWR Oversight drawings encl
WYLVIA, S. R. Virginia Electric & Power Co. 00/06/23 13pp
- 0004800049 "Typical Arrangement Containment Sump Screens" *
* Virginia Electric & Power Co. 00/06/23 3pp
- 0004800049 "Machine Location - Reactor Containment, Plan Elevation 201 Ft. 10 Inches - Sheet 1" *
* Stone & Webster Engineering Corp. 79/10/11 1p
- 0004800049 "Machine Location - Reactor Containment, Plan Elevation 202 Ft. 10 Inches - Sheet 2" *
* Stone & Webster Engineering Corp. 79/10/11 1p
- 0004800049 "Machine Location - Reactor Containment, Plan Elevation 241 Ft. 10 Inches - Sheet 3" *
* Stone & Webster Engineering Corp. 79/10/11 1p
- 0004800049 "Machine Location - Reactor Containment, Plan Elevation 256 Ft. 10 Inches - Sheet 4" *
* Stone & Webster Engineering Corp. 00/04/12 1p

DOCKETED ITEMS

152

- 0604050014 "Machine Location - Reactor Containment, Sections 1-3, 7-9, 10-B, 11, 9-9 - Sheet 5
* Stone & Webster Engineering Corp 7/9/81/11 1p

--0604050018 "Machine Location - Reactor Containment, Sections 3-2, 5-3 & 4-6 - Sheet 7
* Stone & Webster Engineering Corp 7/9/81/11 1p

--0604050014 "Machine Location - Reactor Containment, Sections 3-2 & 4-6 - Sheet 7
* Stone & Webster Engineering Corp 7/9/81/11 1p

0604050010 Forwards comprehensive of auxiliary feedwater sys WDRF as required by NUREG-0440 Sheets supplemental info requested by NRC Unit 2 auxiliary feedwater sys is essentially identical to Unit 1 sys
EVLVIA, D R Virginia Electric & Power Co 8/04/84 80pp

0604050050 Forwards revisions to Procedures 2-BT-6, 2-BT-9 & 2-BT-11 re NRC's electrical verification training plan for conduct of tests submitted
EVLVIA, D R Virginia Electric & Power Co 8/04/84 2pp

--0604050057 Changes to Procedure 2-BT-6, "Natural Circulation Verification"
* Virginia Electric & Power Co 8/04/84 1p

--0604050059 Changes to Procedure 2-BT-9, "Natural Circulation Verification" and List of Circulation Verification
* Virginia Electric & Power Co 8/04/84 1p

--0604050012 Changes to Procedure 2-BT-11, "Effect of Mean Operator Secondary Side Isolation on Natural Circulation"
* Virginia Electric & Power Co 8/04/84 1p

0604050080 Confirm agreement re review criteria for control rod bank reactivity worth tests Modified Table A of WDP-80-20, "Control Rod Reactivity Worth Determination by Rod Step Technique" and TDRMAG-11
Virginia Electric & Power Co 8/04/84 8pp

0 Inspection reports, IE Bulletins & correspondence

0604050018 Forwards IE Insp Repts SO-338/80-16 & SO-339/80-17 on 800303-0411 No noncompliance noted
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/82 2pp

--0604050018 IE Insp Repts SO-338/80-16 & SO-339/80-17 on 800303-0411 No noncompliance noted Major areas inspected short-term Lessons Learned (800303-0791) 2-2 action plan (800303-0801) & plant readiness for fuel loading
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/82 13pp

0604050062 Forwards IE Insp Repts SO-338/80-16 & SO-339/80-17 on 800413-16 No noncompliance noted
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/82 2pp

--0604050068 IE Insp Repts SO-338/80-16 & SO-339/80-17 on 800413-16 No noncompliance noted Major areas inspected Initial fuel loading of Unit 2
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/82 13pp

0604050018 Forwards IE Bulletin 80-11, "Emergency Diesel Generator Load On Control Failures - No written response required IE Info Notice 80-25, "Overloading of Structural Elements Due to Pipe Rupture Load" and
O'REILLY, J P Region 2, Atlanta, Office of the Director 8/04/80 5pp

0604050016 Forwards IE Insp Rept SO-339/80-18 on 800413-18 No noncompliance noted
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/80 2pp

--0604050018 IE Insp Rept SO-339/80-18 on 800413-18 No noncompliance noted Major areas inspected containment & startup testing procedures
LEWIS, R C Region 8, Atlanta, Reactor Operations Nuclear Support Branch 8/04/80 2pp

0604050016 Forwards IE Bulletin 80-11, "Emergency Diesel Generator Load On Control Failures - No written response required IE Info Notice 80-25, "Overloading of Structural Elements Due to Pipe Rupture Load" and
O'REILLY, J P Region 2, Atlanta, Office of the Director 8/04/80 5pp

0604050016 Forwards IE Bulletin 80-11, "Emergency Diesel Generator Load On Control Failures - No written response required IE Info Notice 80-25, "Overloading of Structural Elements Due to Pipe Rupture Load" and
O'REILLY, J P Region 2, Atlanta, Office of the Director 8/04/80 5pp

0604050040 Response to IE Bulletin 79-37, "Loss of Non-Class IE Instrumentation & Control Power May Be During Operation"
No equipment on other instrument & control power buses is required to maintain hot or cold shutdown conditions
EVLVIA, D R Virginia Electric & Power Co 8/03/80 54pp

0604050038 Forwards response to IE Bulletin 80-06 re vacuum conditions resulting in damage to backup tanks The potential problem areas involving boron expander, boron tank & boron acid storage tanks identified
EVLVIA, D R Virginia Electric & Power Co 8/04/80 3pp

0604050038 Forwards response to notice of violation contained in IE Insp Repts SO-308/80-46 & SO-320/80-11 corrective action
all equipment will respond to safeguards engineered activation results in PDB
EVLVIA, D R Virginia Electric & Power Co 8/04/80 5pp

0604050038 Forwards response to IE Bulletin 80-07 Hydrogen actuator Models AM-70 & NM-90 are not used at facility
EVLVIA, D R Virginia Electric & Power Co 8/04/80 3pp

0604050025 Forwards response to IE Bulletin 80-04 re decay heat removal sys operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if reduction in operability is inoperable
EVLVIA, D R Virginia Electric & Power Co 8/04/81 4pp

0604050049 Response to IE Bulletin 80-04 requesting review of drawings for all act safety safety-related functions at schematic level; verification of controls & proposed design made. Actions & schedule identified in Item 2
EVLVIA, D R Virginia Electric & Power Co 8/04/82 10pp

0604050012 Forwards Headquarters rept re low pressure turbine disc ultrasonic insp performed to address concerns about disc-in-shaft being detected at other facilities
EVLVIA, D R Virginia Electric & Power Co 8/04/81 42pp

0 Periodic operating reports & related correspondence

0604050016 Forwards monthly operating reports for May 1980
EVLVIA, D R Virginia Electric & Power Co 8/04/80 1p

--0604050016 Monthly operating reports for May 1980
HARVEY, S L Virginia Electric & Power Co 8/04/80 2pp

0 Reportable occurrences, LERs & related correspondence

0604050016 Part 21 rept re defective emergency diesel generator exhaust silencer support sys dynamic design calculated where support plate drawings did not indicate base plate 011
Insured NRC of defective pump neither occurred design calculations Covered by deficiency in sys stress analysis
MILP, A Stone & Webster, Inc 8/04/82 2pp

0604050031 SO 80-10/81-01 on 800406, during review of MCS piping, loading on the head safety injection pump positive was determined to exceed design stress allowed by deficiency in piping sys stress analysis
* Virginia Electric & Power Co 8/04/80 1p

0604050016 Forwards LER 80-05/81-01
CARTWRIGHT, W R Virginia Electric & Power Co 8/04/80 1p

--0604050016 LER 80-01/81-01 on 800323, during review of MCS piping for fluid temp below 70-F, determined that loadings on both low head safety injection pump neither exceeded design stress allowable Covered by deficiency in sys stress analysis
CARTWRIGHT, W R Virginia Electric & Power Co 8/04/80 3pp

0604050018 No general limits in low head & high safety injection sys were not analyzed for effects of fluid temp below 70-F
Review of new source loads about load on pump scheduled under allowable load Multiple program program provided
EVLVIA, D R Virginia Electric & Power Co 8/04/80 80pp

0004040089 Responds to 000327 1ir re President Carter re qualification of design personnel. Qualifications were adequate for performance of job function, although until failed to establish personnel requirements.
HARRIS, H. D. Division of Reactor Construction Inspection
00/04/02 3pg

0004270126 Responds to 000421 1ir re HQ Nelson concerns about NRC investigation of alleged problems at coast site.
Investigation revealed that certain unit activities failed to comply w/reqs. Some piping suspension design deficient.
DREMB, M. J. Office of the Executive Director for Operations
00/04/02 3pg

--0004270129 Requests response to encl HQ Nelson 000414 1ir re NRC investigation of alleged problems at coast site.
PITRELL, C. D. House of Reps
00/04/01 3pg

0004290090 Responds to 000329 1ir re Representative P. Findley re investigation at coast site. Investigation prompted by ABC television allegations of unqualified personnel employed as designers. NRC investigation & util response encl.
STELL, G. V. Office of Inspection & Enforcement, Office of the Director
00/04/03 3pg

1 Financial Information

0004170404 Forwards Northern HI Electric Cooperative, Inc., Wolverine Electric Cooperative & Detroit Edison Annual Financial Results 1979.
THOMAS, E. D. LeBoeuf, Lamb, Leiby & MacKay
00/04/03 1p

--0004170405 Annual Financial Result 1979
re Northern Michigan Electric Cooperative, Inc.
00/02/22 3pg

--0004170407 Annual Financial Result 1979
re Wolverine Electric Cooperative
00/02/01 2pg

--0004170408 Annual Financial Result 1979
re Detroit Edison Co.
00/02/29 4pg

2 Operating license stage documents & correspondence

0004030031 Summary of 000427-23 meeting w/Mark I owners group in Gen. Jose-Car. re confirmatory analysis & testing program concerning Mark I containment long-term program.
GRIFFIN, C. J. Assistant Director for Plant Systems
00/04/09 4pg.

3 Inspection reports, SE Bulletins & correspondence

0004040023 Responds to IC Bulletin 90-02, "Inadequate QA for Nuclear Support Equipment." Thermal storage for production valves was mfg by Marvin Engineering. Spargers were not mfg by Marvin. Of supportive list encl.
HINES, E. Detroit Edison Co.
00/04/03 3pg

0004020026 Forwards IC Insp Rept 90-341/00-09 on 000421-22 No noncompliance noted.
HARRIS, H. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch
00/04/04 2pg

--0004020026 IC Insp Rept 90-341/00-09 on 000421-22 No noncompliance noted. Major areas inspected: preoperational testing QA program & action on previous insp findings.
LITTLE, W. & SHANAHAN, R. Region 3, Chicago, Office of the Director
00/04/02 3pg

0004030030 Forwards IC Insp Rept 90-341/00-07 on 000430-0502 No noncompliance noted.
SHANAHAN, R. Region 3, Chicago, Fuel Facility & Materials Safety Branch
00/03/26 2pg

--0004030033 IC Insp Rept 90-341/00-07 on 000430-0502 No noncompliance noted. Major areas inspected: review preoperational testing QA program & confirmatory measurements.
SHANAHAN, R. Region 3, Chicago, Office of the Director
00/03/16 4pg

0004030048 Forwards IC Insp Rept 90-341/00-00 on 000500 No noncompliance noted.
HARRIS, J. O. Region 3, Chicago, Office of the Director
00/03/21 3pg

--0004030048 IC Insp Rept 90-341/00-00 on 000500 No noncompliance noted. Major areas discussed: communications between licensee & Region 3 re public affairs.
HARRIS, J. O. Region 3, Chicago, Office of the Director
0004030048 Region 3, Chicago, Reactor Construction & Engineering Support Branch
00/03/20 2pg

0004240481 Bulletin addl info requested by NRC 000326 1ir re IC Insp Rept 90-341/79-29 Procedures developed include deviation from NRC request; corrective action; project addl response & reorganization.
HARRIS, E. Detroit Edison Co.
00/04/09 3pg

0004290081 Forwards response to IC Bulletin 90-09, "Hydrometer Actuator Deficiencies." Present preoperational testing program sufficient to demonstrate functional adequacy.
HARRIS, E. Detroit Edison Co.
00/04/13 4pg

0004300066 Forwards 000509 internal memo in response to IC Bulletin 90-09 Present preoperational testing program is sufficient to demonstrate hydrometer actuator adequately test program not required.
HARRIS, E. Detroit Edison Co.
00/04/13 4pg

0004370082 Forwards attachment to util response to IC Insp Rept 90-341/00-00 Attachment was added from original response due to error.
PITRELL, C. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch
00/04/17 3pg

4 Repairable occurrences, LERs & related correspondence

0004270082 Forwards final deficiency report re use of improper seismic design criteria for design of SA Level 1 20-inch & 30-inch instrumentation & control tubing.
HARRIS, J. O. Detroit Edison Co.
00/04/10 1p

--0004270082 Final deficiency report re use of improper seismic design criteria for design of SA Level 1 20-inch & 30-inch instrumentation & control tubing. Improperly designed tubing was already installed with reactive appropriate notes.
HARRIS, J. O. Detroit Edison Co.
00/04/10 3pg

0004290033 Ack receipt of 000503 interim deficiency report re cut reinforcing bar Mill review final report on matter upon receipt.
PITRELL, C. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch
00/04/11 1p

0004290038 Ack receipt of 000504 interim deficiency report re defective Westinghouse switches. Mill review final report on matter upon receipt.
PITRELL, C. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch
00/04/11 1p

0004290037 Ack receipt of 000504 interim deficiency report re seismic Category 1 instrumentation & control tubing. Mill review final report on matter upon receipt.
PITRELL, C. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch
00/04/11 1p

0004270020 Interim deficiency report re seismic equipment installed over or in close proximity to safety-related equipment. Repair of affected equipment not yet begun. Final report will be delayed until 000715.
HARRIS, J. O. Detroit Edison Co.
00/03/12 1p

0004270030 Forwards final deficiency report re defective Westinghouse switches.
HARRIS, J. O. Detroit Edison Co.
00/04/13 1p

--0004270034 Final deficiency report re defective Westinghouse switches located in distribution cabinets. Failure of switches limited to manual operation of opening & closing & was detected during normal start-up testing. Switches replaced.
HARRIS, J. O. Detroit Edison Co.
00/03/19 1p

SECRET 90-346 THOMAS NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

9 Security: medical, emergency & fire protection plans

0004090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 1960." Rule adds new Section 20.49 & App. B to 10CFR20 & is expected to be published in FR by end of May.
GRIFFIN, C. J. Division of Licensing
00/03/19 4pg.

DOCKETED ITEMS

8006130063 Forwards revised Pages 1-16 of new Page 14a for proposed rule 100FR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 7/10/01." Transmitted by NRC 8/20/01
1st Page 14a not sent
EISENHUT, D. O. Division of Licensing 8/20/01 73pp

8006130063 Requests will draft responses to NRC 8/16 DOE review of facility security plan Requests 800500, 8/27 meeting w/NRC & OR DOE to discuss various concern responses & proposed security plan revision Plan withheld (ref 100FR50 740)
GRIFFIN, J. Portland General Electric Co 8/16/01 2pp

8006130063 Requests presence of C. Gustin at util & OR DOE meeting in Portland, OR Requests meeting w/NRC & OR DOE to coordinate responses to areas of concern prior to 8/27/01
GOSWAMI, C. Portland General Electric Co 8/16/01 3p

6 Adjudicatory correspondence

8006170139 Forwards list of requests for design changes associated w/ control bldg design under processing Util will inform ASLS of further activities per 740520 processing conference
M/Certificate of Rev Related correspondence
JOHNSON, R. W. Portland General Electric Co 8/16/01 5pp

8006130063 Forwards technical report re effects of volcanism & landslides from Mount St Helens on facility RD McMahon affidavit sent
DETHMANN, R. Office of Nuclear Reactor Regulation, Director 8/16/01 3pp

8006130059 Technical report re possible impact of Mount St Helens on facility in form of affidavit filed w/ASLS in spent fuel pool proceeding
MORRISON, R. 7/20/01 12 20pp

8006130052 Expresses concern for public health & safety due to proximity of volcanic activity at Mount St Helens to facility Requests shutdown & relocation of Ferromobile mall to event of impending disaster
WHITE, D. Lane County, OR 8/16/01 1p

8006130033 Forwards State of OR proposed findings of fact & conclusions of law re design made for facility & memo of points & authorities in support of State of OR proposed findings of fact & conclusions of law
GUTHRIER, P. M. Oregon, State of 8/16/01 1p

8006130039 State of OR proposed findings of fact & conclusions of law re design made for facility If proposed findings are included by ASLS in initial decision State of OR will concur w/proposed findings & conclusions
GUTHRIER, P. M. Oregon, State of 8/16/01 7pp

8006130044 Memo of points & authorities in support of State of OR proposed findings of fact & conclusions of law Proposed findings are intended to increase likelihood that made to facility will meet seismic safety standards
GUTHRIER, P. M. Oregon, State of 8/16/01 19pp

8006130050 Order instituting proceedings to 800500-3483 & 9454-17 evidentiary hearing transcripts Pg 3, 640-4, 828
MILLER, H. E. Atomic Safety and Licensing Board Panel 8/16/01 47pp

8006130047 Responses to NRC & State of OR proposed findings of fact & conclusions of law Reporting requirements will extract from current license responsibilities & should not be imposed NRC address to Paragraphs 2.7.2 & Certificate of Rev sent
CARRA, V. A. ASLRAN, H. Portland General Electric Co. CARRA, V. Lewisville-Newman-Reis, Asst/Asst & Toll 8/16/01 13pp

8006130043 Admits & corrects error in NRC 800500 proposed findings of fact & conclusions of law on control bldg malfunctions in Paragraph 34 on Page 134
GRIFFIN, J. Hearing Branch 8 8/16/01 3pp

8006130043 Order requesting licensee to supply affidavit re licensee 800519 re: as discovery of inadequate connection in auxiliary bldg will cause of occurrence & other related matters should be identified Certificate of Rev sent
MILLER, H. E. Atomic Safety and Licensing Board Panel 8/16/01 5pp

8006130021 Certifies use of licensee for w/NRC 80-07 on 800602
JOHNSON, R. W. Portland General Electric Co 8/16/01 2pp

8006130023 Requests to NRC 800402 order requesting licensee to supply info by affidavit re LER 80-07 submitted 8/20/01 to Region 3
License plan to complete asap by 8/20/01 Certificate of Rev sent
ASLRAN, H. Lewisville-Newman-Reis, Asst/Asst & Toll 8/16/01 3pp

8006130139 States no objections to NRC 800520 proposed correction of Paragraph 34 on Page 134 of NRC 800519 proposed findings
Concerns analysis of displacements at interface between control & turbine bldg Certificate of Rev sent
ASLRAN, H. Lewisville-Newman-Reis, Asst/Asst & Toll 8/16/01 2pp

H General correspondence

8006130039 Expresses concern re proximity of facility to Mount St Helens volcano Facility should be closed down
MORRISON, R. Portland General Electric Co 8/16/01 3pp

I Financial information

8006170025 Forwards Chase Manhattan Bank 800505 acknowledgment re extension of credit until 8/16/01 TR Bulletin 800519 1st re secondary financial protection also sent
MORRISON, R. Portland General Electric Co 8/16/01 3pp

8006170045 Reconfirm obligation on behalf of Eugene Water & Electric Board concerning retrospective premiums under Price Anderson Act & Washington Power Administration obligated to pay retrospective premium
HUTTELL, D. Energy Dept of 8/16/01 3pp

P Operating license stage documents & correspondence

8006130058 Forwards add TH1-2 related requirements to operating reactor License requirements for TH1 Action Plan include ASLT making licensing exam & licensee demonstration of operating experience Response requested within 30 days
EISENHUT, D. O. Division of Licensing 8/16/01 12pp

8006130033 Forwards request for add info re review of 7/10/01 & 800520 1st re concerning adequacy of station electric distribution w/ -utility Reports should be submitted within 45 days to maintain review schedule
CLARK, R. A. Operating Reactors Branch 3 8/16/01 4pp

8006130047 Forwards request for add info re NRC requirements for auxiliary feedwater system Response requested within 45 days to maintain review schedule
CLARK, R. A. Operating Reactors Branch 3 8/16/01 7pp

8006130039 Storage summary of 800501-62 meeting w/util & Bechtel re wall assessment which attached being structurally inadequate to resist earthquake Purpose was to develop evaluation criteria for existing walls List of attendees sent
TAYLOR, L. C. H. Operating Reactors Branch 3 8/16/01 3pp

8006130122 Requests comments on NUREG-0597, "Potential for Low Pressure Toughness & Lamination Tearing on PWR Steam Generator & Reactor Control Pump Supports." Proposed review procedure & implementation schedule sent
EISENHUT, D. O. Division of Licensing 8/16/01 72pp

8006130033 Forwards request for design changes re rod program described in text re design made including piping supports to avoid piping sys for response spectra
MORRISON, R. P. Portland General Electric Co 8/16/01 2pp

8006130043 Ask receipt of 800527 ltr describing program for removal of Bus 3 & 2-Urbid supply from 8 steam generator. Proposed steam generator evaluation program found acceptable Provides schedule for reporting results of Washington lab analysis
CLARK, R. A. Operating Reactors Branch 3 8/16/01 3pp

8006130043 Informs that interim procedural changes for nonconservative features identified in rod drop analysis will remain in effect until longer term solution has been developed use Washington topical rep due mid-1993
GOSWAMI, C. Portland General Electric Co 8/16/01 3pp

8006130021 Forwards application to amend license 80F-1, providing increased operational flexibility to dual stream generator tube corrosion-submitted as Revision 1 to License Change Application DR Certificate of Rev sent
GOSWAMI, C. Portland General Electric Co 8/16/01 2pp

DOCKETED ITEMS

- B004230544 "Schematic Diagram Hot Water Pumps - Sheet 2"
 * Bechtel Corp 6470 77/02/10 1p
- B004230545 "Schematic Diagram Containment Isolation Valves." as-built Sheet 2
 * Bechtel Corp 6470 77/01/10 1p
- B004230546 "Schematic Diagram Main Steam Line Isolation Valves." as-built Sheet 2
 * Bechtel Corp 6470 77/01/10 1p
- B004230548 "Schematic Diagram Steam Generator Blowdown Isolation Valve." as-built
 * Bechtel Corp 6470 77/01/10 1p
- B004230549 "Schematic Diagram Feedwater Control Valves." as-built Sheet 1
 * Bechtel Corp 6470 77/01/10 1p
- B004230550 "Schematic Diagram Containment Sump Pumps Discharge Isolation Valve R04385." as-built Sheet 2
 * Bechtel Corp 6470 77/01/10 1p
- B004230551 "Schematic Diagram Hot Water Pumps - Sheet 1"
 * Bechtel Corp 6470 77/02/10 1p
- B004230552 "Schematic Diagram Safety Injection Pumps"
 * Bechtel Corp 6470 73/08/17 1p
- B004230553 "Schematic Diagram Chemical & Vol Control Sys Valves." as-built Sheet 12
 * Bechtel Corp 6470 77/01/10 1p
- B004230555 "Schematic Diagram Containment Spray Pumps." as-built
 * Bechtel Corp 6470 77/01/10 1p
- B004230557 "Schematic Diagram Chemical & Vol Control Sys Valves." as-built Sheet 11
 * Bechtel Corp 6470 77/01/10 1p
- B004230558 "Schematic Diagram Containment Isolation Valves." as-built Sheet 1
 * Bechtel Corp 6470 77/01/10 1p
- B004230559 "Schematic Diagram Chemical & Vol Control Sys Valves." as-built Sheet 12
 * Bechtel Corp 6470 77/01/10 1p
- B004230561 "Schematic Diagram Engineered Safeguards Initiation on Preferred or Standby Power." as-built Sheet 2
 * Bechtel Corp 6470 79/06/10 1p
- B004230562 "Schematic Diagram Chemical & Vol Control Sys Valves." as-built Sheet 10
 * Bechtel Corp 6470 77/01/10 1p
- B004230563 "Schematic Diagram Safety Injection Sys Valves." as-built Sheet 6
 * Bechtel Corp 6470 77/01/10 1p
- B004230564 "Schematic Diagram Safety Injection Sys Valves." as-built Sheet 6
 * Bechtel Corp 6470 77/01/10 1p
- B004230565 "Schematic Diagram Steam Generator Blowdown Isolation Valve." as-built
 * Bechtel Corp 6470 77/01/10 1p
- B004230566 "Schematic Diagram Main Steam Line Isolation Valves." as-built Sheet 2
 * Bechtel Corp 6470 77/01/10 1p
- B004230567 "Schematic Diagram Safety Injection Sys Valves." as-built Sheet 3
 * Bechtel Corp 6470 77/01/10 1p
- B004230568 "Schematic Diagram Containment Vent Radiation Monitor Isolation Valve." as-built
 * Bechtel Corp 6470 77/01/10 1p
- B004230569 "Schematic Diagram Component Cooling Water Dye Containment Isolation Valve." as-built Sheet 4
 * Bechtel Corp 6470 77/01/10 1p
- B004230570 "Schematic Diagram Engineered Safeguards Initiation on Preferred or Standby Power." as-built Sheet 1
 * Bechtel Corp 6470 79/01/30 1p
- B004230571 "Schematic Diagram Heating & Ventilation Motor Control Dye CS-2 Control Valve." as-built Sheet 4
 * Bechtel Corp 6470 77/01/10 1p
- B004230572 "Schematic Diagram Engineered Safeguards Component Cooling & Hot Water Solenoid Valves." as-built Sheet 1
 * Bechtel Corp 6470 77/01/10 1p
- B004230574 "Schematic Diagram Hot Water to Auxiliary Feedwater Pump Cooler Valves." as-built
 * Bechtel Corp 6470 79/01/04 1p
- B004230577 "Schematic Diagram Containment Spray Valve." as-built Sheet 4
 * Bechtel Corp 6470 77/01/10 1p
- B004240002 Forwards list of requests for design changes per mod program described in "Report on Design Mode for Trojan Central Bay (PGE-1000) - Items are made involving piping supports necessary to qualify piping as response spectra
 R04385E & F Portland General Electric Co 80/04/10 3pp
- B004230990 Forwards application to amend License NP-1, submitted as License Change Application 50, Revision 2, incorporating Tech Specs for alternate shutdown capability, min shift crew & revisions to Fire protection Certificate of Dye seal
 000040C Portland General Electric Co 80/04/19 2pp
- B004230992 Application to amend License NP-1, submitted as License Change Application 50, Revision 2, incorporating Tech Specs for alternate shutdown capability, min shift crew & revisions to Fire protection Certificate of Dye seal
 000040C Portland General Electric Co 80/04/19 2pp
- B004230997 Tech Specs 3/4 7 & 8 & 9 & 10 & 11 & 12 & 13 & 14 & 15 & 16 & 17 & 18 & 19 & 20 & 21 & 22 & 23 & 24 & 25 & 26 & 27 & 28 & 29 & 30 & 31 & 32 & 33 & 34 & 35 & 36 & 37 & 38 & 39 & 40 & 41 & 42 & 43 & 44 & 45 & 46 & 47 & 48 & 49 & 50 & 51 & 52 & 53 & 54 & 55 & 56 & 57 & 58 & 59 & 60 & 61 & 62 & 63 & 64 & 65 & 66 & 67 & 68 & 69 & 70 & 71 & 72 & 73 & 74 & 75 & 76 & 77 & 78 & 79 & 80 & 81 & 82 & 83 & 84 & 85 & 86 & 87 & 88 & 89 & 90 & 91 & 92 & 93 & 94 & 95 & 96 & 97 & 98 & 99 & 100 & 101 & 102 & 103 & 104 & 105 & 106 & 107 & 108 & 109 & 110 & 111 & 112 & 113 & 114 & 115 & 116 & 117 & 118 & 119 & 120 & 121 & 122 & 123 & 124 & 125 & 126 & 127 & 128 & 129 & 130 & 131 & 132 & 133 & 134 & 135 & 136 & 137 & 138 & 139 & 140 & 141 & 142 & 143 & 144 & 145 & 146 & 147 & 148 & 149 & 150 & 151 & 152 & 153 & 154 & 155 & 156 & 157 & 158 & 159 & 160 & 161 & 162 & 163 & 164 & 165 & 166 & 167 & 168 & 169 & 170 & 171 & 172 & 173 & 174 & 175 & 176 & 177 & 178 & 179 & 180 & 181 & 182 & 183 & 184 & 185 & 186 & 187 & 188 & 189 & 190 & 191 & 192 & 193 & 194 & 195 & 196 & 197 & 198 & 199 & 200 & 201 & 202 & 203 & 204 & 205 & 206 & 207 & 208 & 209 & 210 & 211 & 212 & 213 & 214 & 215 & 216 & 217 & 218 & 219 & 220 & 221 & 222 & 223 & 224 & 225 & 226 & 227 & 228 & 229 & 230 & 231 & 232 & 233 & 234 & 235 & 236 & 237 & 238 & 239 & 240 & 241 & 242 & 243 & 244 & 245 & 246 & 247 & 248 & 249 & 250 & 251 & 252 & 253 & 254 & 255 & 256 & 257 & 258 & 259 & 260 & 261 & 262 & 263 & 264 & 265 & 266 & 267 & 268 & 269 & 270 & 271 & 272 & 273 & 274 & 275 & 276 & 277 & 278 & 279 & 280 & 281 & 282 & 283 & 284 & 285 & 286 & 287 & 288 & 289 & 290 & 291 & 292 & 293 & 294 & 295 & 296 & 297 & 298 & 299 & 300 & 301 & 302 & 303 & 304 & 305 & 306 & 307 & 308 & 309 & 310 & 311 & 312 & 313 & 314 & 315 & 316 & 317 & 318 & 319 & 320 & 321 & 322 & 323 & 324 & 325 & 326 & 327 & 328 & 329 & 330 & 331 & 332 & 333 & 334 & 335 & 336 & 337 & 338 & 339 & 340 & 341 & 342 & 343 & 344 & 345 & 346 & 347 & 348 & 349 & 350 & 351 & 352 & 353 & 354 & 355 & 356 & 357 & 358 & 359 & 360 & 361 & 362 & 363 & 364 & 365 & 366 & 367 & 368 & 369 & 370 & 371 & 372 & 373 & 374 & 375 & 376 & 377 & 378 & 379 & 380 & 381 & 382 & 383 & 384 & 385 & 386 & 387 & 388 & 389 & 390 & 391 & 392 & 393 & 394 & 395 & 396 & 397 & 398 & 399 & 400 & 401 & 402 & 403 & 404 & 405 & 406 & 407 & 408 & 409 & 410 & 411 & 412 & 413 & 414 & 415 & 416 & 417 & 418 & 419 & 420 & 421 & 422 & 423 & 424 & 425 & 426 & 427 & 428 & 429 & 430 & 431 & 432 & 433 & 434 & 435 & 436 & 437 & 438 & 439 & 440 & 441 & 442 & 443 & 444 & 445 & 446 & 447 & 448 & 449 & 450 & 451 & 452 & 453 & 454 & 455 & 456 & 457 & 458 & 459 & 460 & 461 & 462 & 463 & 464 & 465 & 466 & 467 & 468 & 469 & 470 & 471 & 472 & 473 & 474 & 475 & 476 & 477 & 478 & 479 & 480 & 481 & 482 & 483 & 484 & 485 & 486 & 487 & 488 & 489 & 490 & 491 & 492 & 493 & 494 & 495 & 496 & 497 & 498 & 499 & 500 & 501 & 502 & 503 & 504 & 505 & 506 & 507 & 508 & 509 & 510 & 511 & 512 & 513 & 514 & 515 & 516 & 517 & 518 & 519 & 520 & 521 & 522 & 523 & 524 & 525 & 526 & 527 & 528 & 529 & 530 & 531 & 532 & 533 & 534 & 535 & 536 & 537 & 538 & 539 & 540 & 541 & 542 & 543 & 544 & 545 & 546 & 547 & 548 & 549 & 550 & 551 & 552 & 553 & 554 & 555 & 556 & 557 & 558 & 559 & 560 & 561 & 562 & 563 & 564 & 565 & 566 & 567 & 568 & 569 & 570 & 571 & 572 & 573 & 574 & 575 & 576 & 577 & 578 & 579 & 580 & 581 & 582 & 583 & 584 & 585 & 586 & 587 & 588 & 589 & 590 & 591 & 592 & 593 & 594 & 595 & 596 & 597 & 598 & 599 & 600 & 601 & 602 & 603 & 604 & 605 & 606 & 607 & 608 & 609 & 610 & 611 & 612 & 613 & 614 & 615 & 616 & 617 & 618 & 619 & 620 & 621 & 622 & 623 & 624 & 625 & 626 & 627 & 628 & 629 & 630 & 631 & 632 & 633 & 634 & 635 & 636 & 637 & 638 & 639 & 640 & 641 & 642 & 643 & 644 & 645 & 646 & 647 & 648 & 649 & 650 & 651 & 652 & 653 & 654 & 655 & 656 & 657 & 658 & 659 & 660 & 661 & 662 & 663 & 664 & 665 & 666 & 667 & 668 & 669 & 670 & 671 & 672 & 673 & 674 & 675 & 676 & 677 & 678 & 679 & 680 & 681 & 682 & 683 & 684 & 685 & 686 & 687 & 688 & 689 & 690 & 691 & 692 & 693 & 694 & 695 & 696 & 697 & 698 & 699 & 700 & 701 & 702 & 703 & 704 & 705 & 706 & 707 & 708 & 709 & 710 & 711 & 712 & 713 & 714 & 715 & 716 & 717 & 718 & 719 & 720 & 721 & 722 & 723 & 724 & 725 & 726 & 727 & 728 & 729 & 730 & 731 & 732 & 733 & 734 & 735 & 736 & 737 & 738 & 739 & 740 & 741 & 742 & 743 & 744 & 745 & 746 & 747 & 748 & 749 & 750 & 751 & 752 & 753 & 754 & 755 & 756 & 757 & 758 & 759 & 760 & 761 & 762 & 763 & 764 & 765 & 766 & 767 & 768 & 769 & 770 & 771 & 772 & 773 & 774 & 775 & 776 & 777 & 778 & 779 & 780 & 781 & 782 & 783 & 784 & 785 & 786 & 787 & 788 & 789 & 790 & 791 & 792 & 793 & 794 & 795 & 796 & 797 & 798 & 799 & 800 & 801 & 802 & 803 & 804 & 805 & 806 & 807 & 808 & 809 & 810 & 811 & 812 & 813 & 814 & 815 & 816 & 817 & 818 & 819 & 820 & 821 & 822 & 823 & 824 & 825 & 826 & 827 & 828 & 829 & 830 & 831 & 832 & 833 & 834 & 835 & 836 & 837 & 838 & 839 & 840 & 841 & 842 & 843 & 844 & 845 & 846 & 847 & 848 & 849 & 850 & 851 & 852 & 853 & 854 & 855 & 856 & 857 & 858 & 859 & 860 & 861 & 862 & 863 & 864 & 865 & 866 & 867 & 868 & 869 & 870 & 871 & 872 & 873 & 874 & 875 & 876 & 877 & 878 & 879 & 880 & 881 & 882 & 883 & 884 & 885 & 886 & 887 & 888 & 889 & 890 & 891 & 892 & 893 & 894 & 895 & 896 & 897 & 898 & 899 & 900 & 901 & 902 & 903 & 904 & 905 & 906 & 907 & 908 & 909 & 910 & 911 & 912 & 913 & 914 & 915 & 916 & 917 & 918 & 919 & 920 & 921 & 922 & 923 & 924 & 925 & 926 & 927 & 928 & 929 & 930 & 931 & 932 & 933 & 934 & 935 & 936 & 937 & 938 & 939 & 940 & 941 & 942 & 943 & 944 & 945 & 946 & 947 & 948 & 949 & 950 & 951 & 952 & 953 & 954 & 955 & 956 & 957 & 958 & 959 & 960 & 961 & 962 & 963 & 964 & 965 & 966 & 967 & 968 & 969 & 970 & 971 & 972 & 973 & 974 & 975 & 976 & 977 & 978 & 979 & 980 & 981 & 982 & 983 & 984 & 985 & 986 & 987 & 988 & 989 & 990 & 991 & 992 & 993 & 994 & 995 & 996 & 997 & 998 & 999 & 1000

DOCKETED ITEMS

DOCKET 80-344 DAVID-BESSE NUCLEAR POWER STATION, UNIT 1
F Security, medical, emergency & fire protection plans

8006050055 Notice that new telephone area called Health Physics
Section (HPS) has been installed at site R4 intended for
use during emergencies to link all power plants & NRC
Emergency Notification Sys. Unit will also be used
8006050113 J. Region 3, Chicago, Office of the Director 80/04/10
2pp

8006050048 Advice that revised 800327 emergency plan needs
revisions except for long-term unit capability for
detection of inadequate core cooling & for improved accident
sampling deficiencies should be eliminated by 801010
8006050113 J. Region 3, Chicago, Office of the Director 80/05/19 2pp

8006050047 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790101" Rule
adds new Section 50.48 & App B to 10CFR90 & is expected
to be published in FR by end of May
8006050113 J. Division of Licensing 80/05/19 4pp

8006170063 Forwards revised Pages 1-10 & new Page 14 for proposed
rule 10CFR90 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790101." Documented by NRC 800519
10 Page 24a not encl.
8006050113 J. Division of Licensing 80/05/22 7pp

8006050023 Forwards add info & revisions for safeguards contingency
plan Encls withheld (ref 80CFR2 7901)
8006050113 J. Region 3, Chicago, Office of the Director 80/06/08 3pp

8006050048 Notification of 800427 meeting until in Bethesda, MD to
discuss unit proposals for fulfilling NRC requirements re
emergency planning facilities
8006050113 J. Region 3, Chicago, Office of the Director 80/06/20 2pp

H General correspondence

8006040023 Forwards constituent J. Branch 800457 ltr requesting info re
operation of power plant Related correspondence
8006050113 J. Senate, Governmental Affairs 80/05/20 2pp

H Antitrust correspondence

8006060014 Requests that deadline for requests for hearings be extended
to 800709 re availability of transmission and extension will
allow NRC & intervenor to work out language difference between
FERC Opinion 84 & NRC 800513 order
8006050113 J. Cleveland, OH 8006050113 J. Valley, Fieldman &
Lathan, P.C. 80/06/28 2pp

8006170055 Motion for and of NRC 800513 order to require filing of
transmission schedule per FERC 800005 order Requests
hearing on 800513 order if NRC denies order Certificate of Dec
8006050113 J. Justice Dept of 80/06/09 12pp

P Operating license stage documents & correspondence

8006040020 Forwards documents for Auxiliary Sys Branch review of
auxiliary feederboard reliability analysis for 3M operating
plants W/o encls
8006050113 J. Light Water Reactors Branch 3 80/01/17 3pp

8006070015 Forwards add TRI-2 related requirements to operating
license License requirements for TRI-2 Action Plan include
shift training, licensing exams & license termination
of operating emergency Response Requests within 30 days
8006050113 J. Division of Licensing 80/05/07 10pp

8006070019 Requests extension to 800619 for completion of activities re
screening of contractor employees.
8006050113 J. Toledo Edison Co 80/05/19 1p

8006130122 Requests comments on NRC-8007, "Potential for Low Fracture
Toughness & Lateral Tearing in PWR Steam Generators &
Reactor Coolant Pump Supports" Proposed review procedure &
implementation schedule encl.
8006050113 J. Division of Licensing 80/05/19 72pp

8006190173 Confirms arrangements for 800604 meeting in Glen Ellyn, IL to
discuss unit control & outage activities
8006050113 J. Region 3, Chicago, Office of the Director 80/05/27
1p

8006190080 Notification of 800610 meeting until & 800610 in Bethesda, MD
to discuss status of findings re fuel assembly holdown
spring failures
8006050113 J. Operating Reactors Branch 4 80/06/04 2pp

8006050082 Discusses license plan to increase onsite waste storage
Requests review of onsite storage additions in monthly
operating report following period in which evaluation was
completed Draft NRC onsite storage licensing position encl.
8006050113 J. Operating Reactors Branch 4 80/06/12 10pp

8006170036 Forwards application for amend to License NPF-3, modifying
ETB
8006050113 J. Toledo Edison Co 80/06/13 1p

--8006170043 Application for amend to License NPF-3, modifying ETB
Estimate Sections 2.1.2, 2.2, 3.3, 4.0, 5.4, 1 Part A &
changes table of contents, list of figures & table, &
Section 1.0 of App B to Tech Specs
8006050113 J. Toledo Edison Co 80/06/13 2pp

--8006170072 Mod to ETB eliminating Sections 2.1.2, 2.2, 3.3, 1-4, 5.4 &
1 Part A & changing table of contents, list of figures &
table, & Section 1.0 of App B to Tech Specs
8006050113 J. Toledo Edison Co 80/06/13 7pp

8006050044 Requests to NRC 800505 request for info re loss of offsite
power two incidents of total loss & three incidents of
partial loss of offsite power have occurred at facility
Events were previously reported in LERs
8006050113 J. Toledo Edison Co 80/06/17 3pp

8006050040 Forwards info re low pressure turbine wheel cracks in
response to NRC 800513 ltr
8006050113 J. Toledo Edison Co 80/06/18 4pp

O Inspection reports, IE Bulletin & correspondence

8006170095 Forwards IE Insp Rept 80-346/80-04 on 800310-14, 17-21, 24-28
& 0401-04 Re correspondence noted
8006050113 J. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/05/01 2pp

--8006170079 IE Insp Rept 80-346/80-04 on 800310-14, 17-21, 24-28 & 0401-04
Re correspondence noted Draft report action items requested findings on
excess time findings operational safety info summary w/anal
officials & radiation protection
8006050113 J. Toledo Edison Co 80/06/29 7pp

8006050022 Forwards response to IE Bulletin 80-04 Existing PBM
analysis of reactivity increase following NRC inside or
outside containment considers 6 conservatively made all
potential water sources
8006050113 J. Toledo Edison Co 80/05/08 4pp

8006050019 Forwards supplemental response to IE Bulletin 79-27
Procedure reviewed & revised in detail operator action in
event of loss in indication s/r function
8006050113 J. Toledo Edison Co 80/05/06 2pp

8006050027 Responds to IE Bulletin 79-27, "Loss of Non-Class 3B
Instrumentation & Control Power Bus During Operation"
Design changes requested to further decrease non-nuclear
instrumentation/integrated control sys vulnerability
8006050113 J. Toledo Edison Co 80/05/04 2pp

8006070028 Forwards IE Info Notice 79-27 w/summary sheet Requests add
info re turbine disc Recommendations that schedule be developed
to perform full ultrasonic test of at least one low pressure
turbine before next major outage
8006050113 J. Operating Reactors Branch 4 80/05/13 3pp

8006050091 Forwards IE Insp Rept 80-346/80-12 on 800450-8002 & notice
of violation Notice of violation withheld (ref 10CFR2 7901)
8006050113 J. Region 3, Chicago, Headquarters Branch 80/05/21 2pp

--8006050083 IE Insp Rept 80-346/80-12 on 800450-8002 Areas inspected
physical facilities & access control Security withheld
(ref 10CFR2 7901)
8006050113 J. Region 3, Chicago, Headquarters Branch 8006050113 J.
8006050113 J. Region 3, Chicago, Office of the Director 80/05/20 1p

8006190043 Discusses NRC 800502 immediate action ltr & unit 000502
response NRC has no comments or questions re actions taken
to correct 1000 & 2 NRC comments re ltr A contained in
encl encl withheld (ref 10CFR2 7901)
8006050113 J. Region 3, Chicago, Office of the Director 80/06/09
2pp

- 000420001 Forwards response to IC Bulletin 79-12. "Decay Heat Removal Sys Operability" Review described in 000420001 revealed minor decay heat pump suction was not installed by containment isolation activation as stated in Page 2
CROUSE, R P Toledo Edison Co 00/04/05 5pp
- 000420009 Forwards to Item 48 of IC Bulletin 79-14. "Descent Analysis for As-Sent Safety-Related Piping Sys" Forwards description of results of fallowman analysis identified discrepancies for normally accessible safety-related piping
CROUSE, R P Toledo Edison Co 00/05/16 4pp
- R Periodic operating reports & related correspondence
- 000420011 Informa NRC that typographical errors were discovered in version of recently submitted "1979 Annual Environ Operating Rept" Corrected Pages 2-3 & 8-10 encl
CROUSE, R P Toledo Edison Co 00/05/27 2pp
- 000420032 Revised Pages 8-10 & 13 to "1979 Annual Environ Operating Rept" Typographical errors corrected
* Toledo Edison Co 00/05/27 2pp
- 000420034 Forwards monthly operating rept for May 1980
MURRAY, T D Toledo Edison Co 00/06/09 1p
- 000420075 Monthly operating rept for May 1980
MURRAY, T D Toledo Edison Co 00/06/09 1pp
- B Reportable occurrences, LERs & related correspondence
- 000420040 PWD-111-80-075 on 000013, licensee discovered hold down spring on fuel assembly in core was broken More logs on 000516-17 revealed 11 cracked or potentially broken springs Plant shut down since 000408 investigation continuing
MURRAY, T D, TAYLOR, L W, HEDBERG, R F Region 3, Chicago, Office of the Director 00/05/19 5pp
- 000420052 Forwards repts NF-03-00-03 & NF-02-00-01A to provide 30-day written notification of overcapacity repts w/o NF-02-00-01A
CROUSE, R P Toledo Edison Co 00/05/22 1p
- 000420077 RD on 000435, chemistry & health physics individual received dose of 4.7 rads course of exposure was unnecessarily low reading on meter on misreading of Telecheck individual was removed from working in radiation controlled area
* Toledo Edison Co 00/05/23 1p
- 000420094 Forwards revised LER 79-114/03L-1
MURRAY, T D Toledo Edison Co 00/06/05 1p
- 000420037 Revised 79-114/03L-1 on 791104, when reactor coolant pump tripped, reactor protection on sys high flow signal reduced to 79.5% full power, exceeding limit caused by procedural deficiency due to incorrect info
MURRAY, T D Toledo Edison Co 79/12/21 2pp
- 000420104 Forwards LER 00-041/03L-0
MURRAY, T D Toledo Edison Co 00/06/06 1p.
- 000420104 LER 00-041/03L-0 on 000811, during performance of DT 591 01 source range functional test, source range channel 1 found out of tolerance & declared inoperable caused by component failure in test module New module installed
MURRAY, T D Toledo Edison Co 00/06/06 3pp
- 000420105 Forwards LER 00-042/03L-0
MURRAY, T D Toledo Edison Co 00/06/06 1p
- 000420047 LER 00-042/03L on 000816, during performance of local test valve test, control leakage of 100 penetrations tested to dose exceeded combined allowable leakage caused by holdup on valve preventing good seal Valve seats will be replaced
MURRAY, T D Toledo Edison Co 00/06/06 2pp.
- 000420109 Forwards revised LER 79-124/03L-1
MURRAY, T D Toledo Edison Co 00/06/09 1p
- 000420102 Revised LER 79-124/03L-1 on 791206, during routine pump switching, component cooling water pump 1 would not start from control room caused by failure of breaker AC113 on essential switchgear bus G1 in close breaker replaced
MURRAY, T D Toledo Edison Co 00/01/08 3pp
- 000420092 Forwards LER 00-036/03L-1
MURRAY, T D Toledo Edison Co 00/06/09 1p
- 000420005 LER 00-036/03L-1 on 000407, reactor protection sys initiated high flow trip of reactor Channel 2 trip module reflected trip signals from only three of four sys channels caused by failure of trip relay G2 in Channel 2 trip module
MURRAY, T D Toledo Edison Co 00/05/06 3pp
- 000420105 Forwards revised Page 2 to LER 79-082/03L-0
MURRAY, T D Toledo Edison Co 00/06/10 1p
- 000420104 LER 79-082/03L-0 Revised Page 2 of LER 79-082/03L-0
* Toledo Edison Co 00/06/10 1p
- 000420035 EH-80-05 notice of violation & notice of proposed imposition of civil penalty will be issued on or about 000420 Action based on alleged noncompliance re employee overexposure will issue new release
MURRAY, T D, THOMPSON, D Office of Inspection & Enforcement, Office of the Director 00/06/10 1p
- COCKET 00-348 JOSEPH H FARLEY NUCLEAR PLANT, UNIT 1
F. Security, medical, emergency & fire protection plans
- 000420007 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Role added new Section 30.48 & App E to 100955 & is expected to be published in FR by end of May
CROUSE, R P Division of Licensing 00/05/19 4pp
- 000420043 Forwards revised Pages 1-14 & new Page 14a for proposed rule 100955 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 000519
LER Page 14a not encl
CROUSE, R P Division of Licensing 00/05/22 73pp
- P Operating license stage documents & correspondence
- 000420010 Forwards add TH1-2 related requirements to operating reactors Licensee requirements for TH1 Action Plan include add naming, licensing, & license identification of operating experience Response requested within 30 days
MURRAY, T D Division of Licensing 00/05/27 10pp
- 000420102 Requests comments on NRC-0077, "Potential for Low Pressure Tightness & Low Pressure Testing on PWR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule encl
MURRAY, T D Division of Licensing 00/05/19 72pp
- 000420018 Response to NRC 000408 ltr requesting add info re unit 1 feedwater sys Clarification of unit 791202 response to recommendation 20-6 encl
CLAYTON, F L Alabama Power Co 00/06/27 23pp
- 000420039 Application to amend SL authorizing changes to Tech Spec Tech Spec 2.0.5 re operability of equipment w/o certain electrical power sources is added per NRC request
CLAYTON, F L Alabama Power Co 00/06/30 3pp
- 000420030 Tech Spec 3.0.9 re operability of equipment w/o certain electrical power sources & Tech Spec 3.0.2 re ac distribution-4000bus
* Alabama Power Co 00/05/30 5pp
- 000420017 Forwards add re seismic qualification of safety-related non-NRC electrical & mechanical equipment in response to NRC 000523 request
CLAYTON, F L Alabama Power Co 00/06/09 3pp
- 000420022 "Final Seismic Response Spectra- Joseph H Farley Nuclear Unit 1 & B.M. Power Co Containment & Internal Structure"
* Bechtel Corp 79/12/31 322pp
- 000420027 "Seismic Response Spectra- Joseph H Farley Nuclear Plant, Unit 1 & B.M. Power Co Auxiliary Bldg"
* Bechtel Corp 79/03/31
- 000420047 Advances that response to 000507 request re TH1-2 related requirements will be submitted by 000420
CLAYTON, F L Alabama Power Co 00/06/12 1p

DOCKETED ITEMS

0 Inspection reports, IE Bulletins & correspondence

000406414 Forwards IE Bulletin 00-11, "Hearing Mail Design - No action on written requests required. See info Notice 79-20.
"Overriding of Structural Elements Due to Pipe Support Loads" and
0'REILLY, J.P. Region 2, Atlanta, Office of the Director 00/05/88 2pp

000406025 Ask receipt of 000403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-340/80-07 & 50-344/80-04
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/88 2pp

000406031 Responds to NRC 000410 ltr re violations noted in IE Insp Repts 50-340/80-07 & 50-344/80-04
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/88 2pp

000406034 Forwards IE Insp Repts 50-340/80-07 & 50-344/80-04 on 000404-29 & notice of violation
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/05/88 2pp

000406042 Notice of violation from Insp on 000404-29
Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/88 1p

000406050 IE Insp Repts 50-340/80-07 & 50-344/80-04 on 000404-29
Noncompliance noted unauthorized use of Scotch-Brite pads for final cleaning of stainless steel pipe surfaces & failure to perform work up approved procedure
HARTSON, M.D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/88 2pp

000406054 Forwards IE Insp Repts 50-340/80-07 & 50-344/80-04 on 000404-29 No noncompliance noted
HARTSON, M.D. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/05/88 2pp

000406056 IE Insp Repts 50-340/80-07 & 50-344/80-04 on 000404-29 No noncompliance noted Major areas inspected valuable mgt, procedural, test procedures, chemistry & health physics procedures & security training
HARTSON, M.D. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/05/88 2pp

000406071 Forwards IE Bulletin 00-12, "Scrap Heat Removal Sys Operability" Requires action & response within 30 days
IE Safe Notice 80-20, "Scrap Heat Removal Sys Operability at South-Down Unit 1 While in Refueling Mode" and
0'REILLY, J.P. Region 2, Atlanta, Office of the Director 00/03/89 2pp

000406074 Forwards IE Circular 00-11, "Emergency Diesel Generator Load Oil Cooler Failures" No written response required
0'REILLY, J.P. Region 2, Atlanta, Office of the Director 00/05/88 2pp

000406015 Forwards response to IE Bulletin 80-05 re vacuum conditions in chemical & vent control sys holding tanks Vent control tank receive leakage from RCS & provides action for changing back into RCS
CLAYTON, F.L. Alabama Power Co 00/05/88 2pp

000406082 Responds to IE Bulletin 80-12, "Scrap Heat Removal Sys Operability" Respondency may be provided by having two RRT train operators Diversity may be provided in Modes 2-5 by having operator steam generators
CLAYTON, F.L. Alabama Power Co 00/05/89 4pp

000406087 Responds to IE Bulletin 80-04 Safety-related components at schematic level have been reviewed to determine whether equipment remains in emergency mode following reset of signal
CLAYTON, F.L. Alabama Power Co 00/06/88 2pp

A Periodic operating reports & related correspondence

000406040 Alabama monthly operating report for May 1980
CLAYTON, F.L. Alabama Power Co 00/06/80 2pp

000406044 Monthly operating report for May 1980
HARTSON, M.D. Alabama Power Co 00/05/80 2pp

B Regulatory correspondence, LERs & related correspondence

000406020 Forwards LERs 00-029/02L-0 & 00-030/02L-0
CLAYTON, F.L. Alabama Power Co 00/05/88 1p

000406024 LER 00-029/02L-0 on 000430, intermediate range NIS channel 4-3S declared inoperable due to loss of power caused by loose terminal screw on 120-volt unit at panel in inboard case breaker wire reconnected
HARTSON, M.D. Alabama Power Co 00/05/88 1p

000406040 LER 00-030/02L-0 on 000501, radiation monitor R25A (fuel storage pool area) declared inoperable due to power loss caused by blown fuse connecting it to monitoring system equipment power for blown fuse replaced
HARTSON, M.D. Alabama Power Co 00/05/88 1p

000406034 Final Part II report re accident heat of steel supplied by US Steel from which 4-inch class 5 2-inch class were dug to 0234P99 requirements investigations conducted & closed at 44 listed facilities
SMITH, J. Chemtreat Corp., Tube Yarns Div 00/04/86 3pp

000406050 Forwards LER 00-031/02L-0
CLAYTON, F.L. Alabama Power Co 00/06/88 1p

000406064 LER 00-031/02L-0 on 000511, digital rod position indication sys (DRPI) declared inoperable following loss of Train A & B DRPI Caused by loss of DRPI indication during trouble clearing Train A returned to svc following card replacement
HARTSON, M.D. Alabama Power Co 00/06/88 1p

000406066 Interim deficiency report re unattached line in waste settling pond causing pH to exceed upper limit caused by discharge of clarified water which dissolved sodium sulfate layer over lime discharge terminated & acid will be added
CLAYTON, F.L. Alabama Power Co 00/06/88 2pp

000406048 Forwards LER 00-032/02L-0 & LER 00-032/02L-0
CLAYTON, F.L. Alabama Power Co 00/04/88 1pp

000406052 LER 00-032/02L-0 on 000514, 1-A diesel generator declared inoperable due to speed control failure caused by personnel error in installing dc recorder which blew as fuse replaced personnel instructed
HARTSON, M.D. Alabama Power Co 00/06/88 1p

000406056 LER 00-032/02L-0 on 000515, both chlorine detectors were inoperable caused by plastic strip lodged in B detector & cracked diaphragm in A detector Strip removed & B made operable on 000515 Pump replaced & A operable on 000516
HARTSON, M.D. Alabama Power Co 00/06/88 1p

000406046 Forwards LERs 00-034/02L-0 & 00-035/02L-0
CLAYTON, F.L. Alabama Power Co 00/06/87 1p

000406058 LER 00-034/02L-0 on 000519, diesel generator 1C was declared inoperable when generator failed to reach rated speed within time specified by Tech Spec. Problem caused by leaky check valve in fuel oil sys Valve replaced
HARTSON, M.D. Alabama Power Co 00/06/87 1p

000406076 LER 00-035/02L-0 on 000519, diesel generator 2C could not start & was declared inoperable caused by switch being inadvertently placed in run position rather than auto position Switch placed in auto
HARTSON, M.D. Alabama Power Co 00/06/88 2pp

SECRET 80-050 LIBRICH GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

000406020 Notification of delay, unit 1 late June or early July 1980, for response to NRC 790218 request for completion of final response to NRC 790218 request
STALEY, V. Philadelphia Electric Co 00/05/82 1p

000406010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NRC-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
STALEY, V. Division of Licensing 00/05/80 13pp

000406012 Summary of 000501 meeting of Unit 1 Bethesda, MD re risk evaluation study per NRC 000501 ltr
MELLO, D. Licensing Branch 2 00/05/83 2pp

DOCKETED ITEMS

167

8004230001 Summary of 800410 meeting w/Hark II owners group re suppression panel response to safety-related questions. Study concluded that limit on temp not needed. Requests that applicants submit detailed info for evaluation.
Sht Y H. Containment Systems Branch 8/05/03 2pp

8004190020 Notification of 800410 meeting w/Util & General Physics in Silver Spring, MD to observe & receive orientation on simulator.
NELLIS D. Licensing Branch 2 8/04/03 2pp

H General correspondence

8004200014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas.
HARRIS Affiliation Unknown 8/05/03 1p

8004200026 Comments on evacuation plan for Facility area Philadelphia Electric Co should not be granted license Human safety should come before economic consideration.
HARRIS Affiliation Unknown 8/05/03 1p

8004120009 Responds to ltr to DOE re constituent inquiry about relationship of Harris Creek Project to facilities NRC has no info re relationship Facilities use water from DE River Basin.
DICKENS W J Office of the Executive Director for Operations 8/05/03 2pp

8004200014 Forwards Philadelphia City Council 800529 resolution that all current facilities should cease to protect health & safety of area residents & employees.
SCHWARTZ O X Philadelphia, PA 8/04/03 5pp

G Inspection reports, IE Bulletins & correspondence

8004120048 Responds to IE Bulletin 80-02 Util feedwater heaters & thermal stresses not wfy by Harris Engineering Co Equipment not O-Listed, nor part of or welded to RCS.
HARRIS J S Philadelphia Electric Co 8/04/03 2pp

8004200091 Forwards NRC Meeting Regs 50-352/80-04 & 50-353/80-04 on 800521.
CALCONE R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 8/05/03 1p

8004200098 NRC Meeting Regs 50-352/80-04 & 50-353/80-04 on 800521.
Areas covered status of PRA, resident insp program, Os program, recent NRC insps, current organization of licensee & NRC's project status.
CALCONE R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MATTHEW J C, HOSKINS R W Region 1, Philadelphia, Office of the Director 8/05/03 2pp

G Reportable occurrences, LERs & related correspondence

8004200093 Ack receipt of 800420 ltr Forwarding final deficiency reph re electrical separation Rept will be reviewed & evaluated.
CALCONE R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 8/05/03 1p

8004200092 Final deficiency reph re electrical separation Field control identified exposed seismic Class 1 raceway/cable/tray & location box caused by SC armor SC procedure revised by indoctrination of SC engineers conducted.
Philadelphia Electric Co 8/04/03 2pp

8004110029 Forwards final deficiency reph re electrical connections on back pressure steam isolation dampers.
HARRIS J S Philadelphia Electric Co 8/04/03 1p

8004110028 Final deficiency reph re electrical connections on back pressure steam isolation dampers wfy by American Harnett & Ventilation, Inc. Mfg has agreed to 100% insp & replacement program to be completed by 8/03/03.
Philadelphia Electric Co 8/04/03 2pp

8004200094 Final Part 21 reph re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg by ASD/NPS requirement. Investigations conducted & closed at 46 listed facilities.
HARVEY J. Chemtron Corp - Tube Turns Div 8/04/04 2pp

8004200017 Forwards final deficiency reph re defect in 4 kv switchgear circuit breaker auxiliary switch crank assembly.
HARRIS J S Philadelphia Electric Co 8/04/03 1p

8004200014 Final deficiency reph re defect in 4 kv switchgear circuit breaker auxiliary switch crank assembly. This will be conducted on switchgear & rods will be secured on assembly studs to prevent loosening.
Philadelphia Electric Co 8/05/03 2pp

V Operator Examination

8004200020 Notification of 800410 meeting w/Util in Bethesda, MD to discuss current requirements for operator qualification & licensing.
NELLIS D. Licensing Branch 2 8/04/03 2pp

DOCKET 80-353 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

8004200030 Waives (of delay, until) late June or early July 1993, for response to NRC 70120 request for comparison of black response spectra w/DOE response.
HARRIS J S Philadelphia Electric Co 8/05/03 1p

8004200010 Advises OAR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of HARRIS-2007 re adequacy of applicant's proposed General operating reactor review procedure & acceptance criteria w/1.
EISENBERG D Division of Licensing 8/05/03 13pp

8004120012 Notification of 800521 meeting w/Util in Bethesda, MD re risk evaluation study per NRC 800521.
NELLIS D. Licensing Branch 2 8/05/03 2pp

8004200001 Summary of 800410 meeting w/Hark II owners group re suppression panel response to safety-related questions. Study concluded that limit on temp not needed. Requests that applicants submit detailed info for evaluation.
Sht Y H. Containment Systems Branch 8/05/03 2pp

8004190020 Notification of 800410 meeting w/Util & General Physics in Silver Spring, MD to observe & receive orientation on simulator.
NELLIS D. Licensing Branch 2 8/04/03 2pp

H General correspondence

8004200014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas.
HARRIS Affiliation Unknown 8/05/03 1p

8004200026 Comments on evacuation plan for Facility area Philadelphia Electric Co should not be granted license Human safety should come before economic consideration.
HARRIS Affiliation Unknown 8/05/03 1p

8004120009 Responds to ltr to DOE re constituent inquiry about relationship of Harris Creek Project to facilities NRC has no info re relationship Facilities use water from DE River Basin.
DICKENS W J Office of the Executive Director for Operations 8/05/03 2pp

8004200014 Forwards Philadelphia City Council 800529 resolution that all current facilities should cease to protect health & safety of area residents & employees.
SCHWARTZ O X Philadelphia, PA 8/04/03 5pp

G Inspection reports, IE Bulletins & correspondence

8004120048 Responds to IE Bulletin 80-02 Util feedwater heaters & thermal stresses not wfy by Harris Engineering Co Equipment not O-Listed, nor part of or welded to RCS.
HARRIS J S Philadelphia Electric Co 8/04/03 2pp

8004200091 Forwards NRC Meeting Regs 50-352/80-04 & 50-353/80-04 on 800521.
CALCONE R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 8/05/03 1p

8004200098 NRC Meeting Regs 50-352/80-04 & 50-353/80-04 on 800521.
Areas covered status of PRA, resident insp program, Os program, recent NRC insps, current organization of licensee & NRC's project status.
CALCONE R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MATTHEW J C, HOSKINS R W Region 1, Philadelphia, Office of the Director 8/05/03 2pp

DOCKETED ITEMS

B. Reportable occurrences, LEDs & related correspondence

0004000003 Ack receipt of 000424-11r forwarding final deficiency report re electrical pathway separation Rpt will be reviewed & evaluated
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 1p

--0004000002 Final deficiency report re electrical pathway separation Field exam identified exposed electric Class I roadway conduct & junction box Ground by GC error GC procedure revised by reclassification of GC equipment conducted
Philadelphia Electric Co 05/04/14 3pp

0004100027 Forwarded final deficiency report re electrical connections on bank pressure steam isolation dampers
BERNER, J B Philadelphia Electric Co 05/04/14 1p

--0004100026 Final deficiency report re electrical connections on bank pressure steam isolation dampers nrg by American Manning & Ventilating, Inc. nrg has agreed to 1800 nrg & replacement program to be completed by 05/12/14
Philadelphia Electric Co 05/04/14 3pp

0004200004 Final Part D1 report re mixed heat of steel supplied by US Steel from which 2-inch valves & 2-inch tees were nrg by AQHAP requirement Investigations conducted & closed at US Steel facilities
GEAR, L C Electron Corp - Tube Tubes Bay 05/05/14 3pp

0004200027 Forwarded final deficiency report re defect in 4 KV switchgear circuit breaker auxiliary switch crank assembly
BERNER, J B Philadelphia Electric Co 05/04/14 1p

--0004200026 Final deficiency report re defect in 4 KV switchgear circuit breaker auxiliary switch crank assembly Insps will be conducted on switchgear & nuts will be secured on assembly study to prevent loosening by 05/12/14
Philadelphia Electric Co 05/04/14 3pp

V. Operator Examinations

0004200098 Notification of 000410 meeting w/Mark I operators MD to discuss current requirements for operator certification & licensing
REILS, R E Licensing Branch 2 05/04/14 3pp

DOCKET 00-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

0004200014 Summary of 000402-22 meeting w/Mark I owners group in San Jose, CA re confirmatory analysis & testing program concerning Mark I containment long-term program
KIRKES, C J Assistant Director for Plant Systems 05/05/14 3pp

0004200110 Advise NRC & NRC applicants of NRC decision to modify implementation plan presented to Division 4 of NRC-357 re adequacy of applicable support structures General operating procedures & acceptance criteria w/1
KIRKES, C J Division 4 Licensing 05/05/14 1pp

0004200037 Forward "For Comment" edition of NRC-3619 Comments should be forwarded by 05/07/14 w/1
KIRKES, C J Division 4 Licensing 05/05/14 3pp

0004200062 Conversion to licensee: 000420 Brief an disposition of alleged deficiency Certificate of Rev nrg
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 3pp

Q. Adjudicatory correspondence

0004200445 Request for extension until 000420 For parties, except NRC, to submit post-hearing memoranda re radon issue Record length & intervenors have other commitments made prior to Feb 1990 Certificate of Rev nrg
KIRKES, C J Division 4 Safety Environment, 05/05/14 3pp

0004200547 Response to intervenors, York Committee for Safe Environment & Citizens for Safe Environment request for extension until 000420 to file proposed findings of fact in generic radon proceeding. Radon delays in proceeding are cause for concern
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 3pp

0004200590 Order granting extension until 000420 New York Committee for Safe Environment & Citizens for Safe Environment to file proposed findings of fact & comments of New NRC Findings due to 05/20/14 intervenors' 1 applicants' responses on 05/20/14
KIRKES, C J Atomic Safety and Licensing Appeal Panel 05/05/14 3pp

0004200597 Memorandum & order advising that Starling case is no longer germane to associated proceedings where radon issue is being determined. Biology action comes from late intervention meeting filed by 000782
KIRKES, C J Atomic Safety and Licensing Appeal Panel 05/05/14 3pp

H. General correspondence

0004200089 Response to 11r to DOE re comment on facility's impact on relationship of Merrill Creek Project to facilities NRC has no info re relationship facilities use water from DE River Basin
KIRKES, C J Office of the Executive Director for Operations 05/05/14 3pp

I. Inspection reports, IE Bulletin & correspondence

0004200475 Response to IE Bulletin 00-05, "Inadequate QA for Nuclear Supplied Equipment" Bulletin is not applicable since GE has not purchased reactor feedwater spargers & thermal sleeves for facility
MARTIN, J J Public Service Electric & Gas Co of New Jersey 05/05/14 1p

0004200023 Ack receipt of 000410 11r informing NRC of steps taken to correct violations noted in IE Insp Repts 00-354/00-01 & 00-355/00-01
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 1p

--0004200024 Response to NRC 000314 11r re violations noted in IE Insp Repts 00-354/00-01 & 00-355/00-01 Corrective actions GC procedures will be revised to address amended QA manual, Decision 4
MARTIN, J J Public Service Electric & Gas Co of New Jersey 05/04/14 3pp

--0004200024 Forwarded IE Insp Repts 00-354/00-01 & 00-355/00-01 re 000410-17 re notice of violation
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 3pp

--0004200031 Notice of violation from Insp on 000410-17
CARLSON, R T Region I, Philadelphia, Office of the Director 05/05/14 1p

--0004200023 IE Insp Repts 00-354/00-01 & 00-355/00-01 on 000410-17 Noncompliance noted failure to take prompt corrective action re protection of equipment from weather & ring grooves 1845 unprotected from damage in high activity area
KIRKES, C J NRC, W. W. WILKINSON, A. B. BATHMAN, H. Region I, Philadelphia, Office of the Director 05/05/14 3pp

Q. Reportable occurrences, LEDs & related correspondence

0004200407 Second interim report re potential deficiency re primary containment relief valves Initial analysis indicates single block mounting about inadequate Relief analysis by 000420
MARTIN, J J Public Service Electric & Gas Co of New Jersey 05/05/14 3pp

0004200025 Ack receipt of 000420 Final deficiency report re weld wire documentation
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/04/14 1p

0004200407 Ack receipt of 000420 Interim deficiency report re primary containment relief valves
CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 05/05/14 1p

DOCKET 00-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

0004200014 Summary of 000402-22 meeting w/Mark I owners group in San Jose, CA re confirmatory analysis & testing program concerning Mark I containment long-term program
KIRKES, C J Assistant Director for Plant Systems 05/05/14 3pp

000422010 Advisory NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
KISENHUT, D O Division of Licensing 00/05/92 12pp

000426057 Forwards "For Comments" edition of NUREG-0619 Comments to be forwarded by 000507 d/f encl
EISENHUT, D O Division of Licensing 00/04/92 2pp

000426092 Correction to license# 000420 brief on disposition of alleged deficiency 2 Certificate of Svc encl
SILBERG, J E Metropolitan Edison Co SILBERG, J E Metcalfe & Eddy
WAGNER, R H Connor, Moore & Conner 00/05/92 2pp

G Adjudicatory correspondence

000426045 Request for extension until 000410 for parties, except NRC, to submit post-hearing memoranda re radon issue board length
Intervenor's have other commitments made prior to Feb 1992
Certificate of NRC encl
NEPFG03, C Citizens For Safe Environment 00/05/92 4pp

000426047 Response to intervenors, Park Committee for Safe Environ & Citizens for Safe Environ request for extension until
000410 to file proposed findings of fact in generic radon proceeding May delay in processing are cause for concern
CONNER, T D Philadelphia Electric Co TRAVISSE-DIAZ, Shaw, Pittman, Fotts & Trowbridge CONNER, T D Public Service Electric & Gas Co
of New Jersey 00/05/92 11pp

000426050 Order granting extension until 000410 for Park Committee for Safe Environ & Citizens for Safe Environ to file proposed findings of fact & conclusions of law NRC findings due on
000703 & intervenor's & applicants' responses on 000718
EISENHUT, D O Atomic Safety and Licensing Appeal Panel 00/05/92 2pp

000426059 Memorandum & order advising that hearing issue is no longer germane to remanded proceedings where radon issue is being determined Ecology Action issue for late intervention must be filed by 000702
EISENHUT, D O Atomic Safety and Licensing Appeal Panel 00/05/92 3pp

H General correspondence

000426089 Responds to ltr to DOE re constituent inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Facilities use water from SE River Basin
EISENHUT, D O Office of the Executive Director for Operations 00/06/92 6pp

I Inspection reports, SE Bulletins & correspondence

000426075 Responds to SE Bulletin 90-03, "Inadequate QA for Nuclear Supplied Equipment" Bulletin is not applicable since SE has not purchased reactor feedwater heaters & thermal storage for facility
NEPFG03, T J Public Service Electric & Gas Co of New Jersey 00/05/92 1p

000426023 Ack receipt of 000418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-394/00-01 & 90-395/00-01
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/05/92 1p

000426026 Responds to NRC 000314 ltr re violations noted in IE Insp Repts 90-394/00-01 & 90-395/00-01 Corrective actions, QC procedures will be revised to address amended QA manual.
HARTMAN, T J Public Service Electric & Gas Co of New Jersey 00/04/92 2pp

000426029 Forwards IE Insp Repts 90-394/00-01 & 90-395/00-01 re 000114-17 & notice of violation
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/03/92 2pp

000426029 Notice of violation from Insp on 000114-17
Region 1, Philadelphia, Office of the Director 00/03/92 1p

000426023 IE Insp Repts 90-394/00-01 & 90-395/00-01 re 000114-17 Noncompliance noted failure to take prompt corrective action re protection of equipment from weather & rising grooves left unprotected from damage in high activity area
NEPFG03, R W - WHEELER, A A, BATESMAN, H Region 1, Philadelphia, Office of the Director 00/05/92 3pp

Q Reportable occurrences, LDRs & related correspondence

000426005 Ack receipt of 000992 final deficiency rept re weld wire documentation
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/04/92 1p

000426047 Ack receipt of 000323 interim deficiency rept re primary containment relief valves
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/04/92 1p

DOCKET 90-387 UNIV OF CALIFORNIA

A Application/Construction stage documents & correspondence

000426043 Notification of 000413 meeting w/WRM Licensing Resolution Group in Bethesda, MD to discuss progress
NEPFG03, C J Licensing Branch 1 00/04/92 10pp

DOCKET 90-358 WILLIAMS H JENSEN NUCLEAR STATION UNIT 1

A Application/Construction stage documents & correspondence

000426022 Notice that time of 000404 meeting in Bethesda, MD w/ staff to discuss steps taken to mitigate existing problem at facility intake structures has been changed
PELLITER, J Licensing Branch 2 00/05/92 1p

000426015 Advisory NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHUT, D O Division of Licensing 00/05/92 13pp

000426055 Summary of 000410 meeting w/WRM II covers group re suppression pool. Some response to safety/relief Activities Study concluded that limit on temp not needed Requests that applicants submit detailed information re existing suppression pool containment systems
BOLT, R Containment Systems Branch 00/05/92 4pp

000426057 Notice of change in date & location of 000424 meeting w/WRM in Bethesda, MD re Facility intake structure Meeting will be held on 000424 in Room 6130 of MD Natl Bank Bldg
PELLITER, J Licensing Branch 2 00/05/92 1p

000426040 Notification of 000410 meeting w/WRM in Bethesda, MD to discuss OL review schedule
PELLITER, J Licensing Branch 2 00/04/92 4pp

000426042 Submits result of audit re separation of electrical equipment & use per NRC 79132 ltr Review showed use cable in violation of separation requirements lying against fire unit cable tied back
EISENHUT, D O Cincinnati Gas & Electric Co 00/04/92 2pp

000426087 Requests advancement re submit date for info requested in NRC 000421 ltr re Category 1 station unit applied by plants under CP & OL review
EISENHUT, D O Licensing Branch 2 00/04/92 3pp

000426031 Summary of 000414 meeting w/WRM in Bethesda, MD re organization & objectives of BAS licensing resolution group Agenda & vignette encl
HILBORN, J N Operating Reactors Branch 4 00/04/92 11pp

F Security, medical, emergency & fire protection plans

000426027 Notices that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification sys hotline will also be used
NEPFG03, J O Region 3, Chicago, Office of the Director 00/04/92 8pp

0004260317 Forwards clarification of NRC requirements for emergency response facilities defined in 79013 ltr Add specific criteria for facilities under development
EISENHUT, D O Division of Operating Reactors 00/04/92 41pp

9 Reportable occurrences, LORs & related correspondence

0004090478 Part 21 repl re misoperation of N-6006 circuit breaker at
 Facility Possibility of small number of N-6006 & M-0046008
 circuit breakers assembled with oversized secondary latch
 bushing during 1957-77 Results of tests sent
 WGWG, E M Gould-Brown Dovers 00/05/15 4pp

0004200024 Final Part 21 rep'r re noted heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to 4234MPB requirement. Investigations conducted & closed at 46 listed facilities.

BD06240684 Ack receipt of B03221 Interim deficiency report re Nuklin
448474
F080811.0 Region 2, Chicago, Reactor Construction & Engineering
Support Branch BD/CA/ID 1p

MOA2003A6 Act receipt of MO0323 asbestos deficiency rept vs mishandled piping assemblies. Will complete review of matter during future Insp
PICKRELL, O Region 2, Chicago, Reactor Construction & Engineering Support Branch MO/06/10 1a

0004305043 Ack receipt of 000522 deficiency rept re control rod drive
pumps Haffner 0331 04 reviewed during future insp.
FIORIELLO, R Region 3, Chicago, Reactor Construction & Engineering
Support Branch 03/06/88 lp

80-287 80-24: SAN ANTONIO RAILROAD STATION, UNIT 2

A Application/construction stage documents & correspondence

9006220310 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and FIBERGLAS/D.O. Division of Licensee 80/05/20 1300

8906020047 Responds to 890610 ltr re environ radiological sampling
program being conducted at facilities Gasapras w/Marine
Review Committee allegations that program is inadequate
Forwards detailed responses to Marine Review Committee reft
890704M R Office of Nuclear Reactor Regulation, Director
80/03/23 2pg

--0006020884 "Detailed Responses to Marine Review Committee Rept -
* Radiological Assessment Branch 08/05/23 10pp

--0006020589 "Radiological Effluent Tech Specs For PWRs"
* Commission NUREG-0472 80/02/01 00pp

--0006020566 Informs NRC that CA Coastal Commission found program for monitoring radiological discharges from facilities to be grossly inadequate Requests that NRC work w/Southern CA Edison re correct deficiencies in monitoring program FISHCHER, M.L. California, State of 000010 is

90S4110431: Forwards request for addl info for review of FGR Approval
of CENPD-ITU re methods for determining fuel assembly loads
has been suspended pending receipt of addl info from C-E
COMMENTOR: A Licensing Branch 2 08/05/23 12pp

8006070037 Approves request for withholding until documents containing structured calculations (ref ISCAP2 990) arguments contain trade secrets & highly technical calculations that could be taken out of context or misinterpreted
SCHWENGER, A. Litigation Branch 2 00/03/20 Doe

800AC00295 Exhibit 4461 Info re Geosciences Branch Question
seismic reflection profiles within 25 km of plant. Applicant
proceeding to collect additional offshore geophysical data along
track lines. Drawings available in General Files
DISTCHL Southern California Edison Co. 800AC004 Doc

00013000DI Forwards responses to REC Questions 361-63 & 361-64 to be incorporated in Amend 19 to PSAR Geophysical data referenced in Section 2-4 of Response to Question 361-63

GD04250392: Forwards request for add info for SEC review of FBWL.
SCHWENKER, A Licensing Branch 2 GO/06/16 10pp

800A230019 Forwards addl piping design info requested by Mechanical Engineering Branch, in order to proceed w/confirmatory piping analysis
BABA, K P Southern California Edison Co 80/04/18 600

```
--800820525 *Calculation Sheet Shutdown Cooling Line.
Sheet 1 of 2
BHWL P R Rectel Corp 10378000 80/05/08 10
```

--B004230001 "Calculation Sheet Shulman Ceiling 1201-017 Histogram"
Sheet 2 of 2
R004230001.B 8 Bechtel Corp 10079003 06/06/05 tp

```
--BDD4230503B "Heresenscal Penetration.Type 1,Monter 9 " Sheet 1 of 1
* Asertak,Inc 02/04/05 1p
```

--B004230843 "Piping Assembly," Revision 4
* Combustion Engineering, Inc. 77/01/02 3p

-0000230547 "Horse Details," Revision 5
 * Combustion Engineering, Inc. 7/20/12 by

--B006230554 "Certification of Design Spec 09-1200, 825 Piping Components
For San Diego Nuclear Generating Station, Units 2 & 3"
KINNECH, D L Beckley Corp 80/00/21 375pgs

—9004230558 Package of drawings re pipe support assembly
* Bethel Corp 10079 00/06/18 100pp

0004200214 Ferrous geochemical drawings & data of area offshore from
site per 000404 commitment Discharge seismic & sub-bottom
profiles encl. available in hard copy only
DITON, Southern California Edison Co 00/06/20 75pg

---0004250321A "Shot Point Base Map"
WILLARD, D. Nelson, Inc 02/06/79 1p

--8004250210 "Shot Point Base Map"
MILLAMMO, KENNEDY, INC. 80/06/17 14

0002000440 Responses to NRC 000421 Request for info re use of concrete
masonry walls in any seismic Category I plant structures No
concrete masonry walls exist in any facility seismic
Category I plant structures
BARBARA P. Southern California Edison Co. 01/06/04 1a

F Security, medical, emergency & fire protection plans

0005100317 Forwards clarification of NRE requirements for emergency response facilities defined in 790903 Str Addl specific criteria for facilities under development
EEDGWT, D O Division of Operating Reactors 00/04/05 61pp

00060200348 Advises that addl 90 days is required to respond to comments in HQC 0004025 ltr re attl P93923 guard training & qualification plan Addl time required to establish physical exercise program Response will be submitted by 000900Z 02NOV03 to Public Complaints Office

Q. Adulteratory correspondence.

0006110084 Forwards applicants' motion for summary disposition
 Intervenor Friends of the Earth et al Contentions 5a & 4 Y re
 dewatering wells & U fuel costs
 FLOTT, D R Chiswick & Gregory 00/04/06 1p

--BDO410849 Motion for summary disposition of Intervenor Friends of the Earth et al. Contention is re desamplers wells & Contention V re oil fuel costs, admitted to proceeding by ASLS JED127 memorandum & order Proposed order encl.
P100TT.D R. Southern California Edison Co. P100TT.D R. San Diego Gas & Electric Co. P100TT.D R. Chickering & Gregory 05/06/04 Ron

—000110324 Brief in lieu of pleading in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re dewatering wells & Contention 9 re U-Pool wells. List of project wells supporting motion encl. PIQUETTE, D.R. Southern California Edison Co. PIQUETTE, D.R. San Diego Gas & Electric Co. PIQUETTE, D.R. Chickering & Gregory 08/06/06 33ee

- 000410008 Statement of mail facts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et al
Contention is on discharging waste Analysis indicates that cost savings have no adverse effect on structures
P1007T-D R Southern California Edison Co P1007T-D R San Diego Gas & Electric Co P1007T-D R Clackamas & Oregon 80/06/06 5pp
- 000410001 Statement of mail facts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et al
Contention is on U Fuel costs Applicants' projection of fuel costs includes escalation or U prices
P1007T-D R Southern California Edison Co P1007T-D R San Diego Gas & Electric Co P1007T-D R Clackamas & Oregon 80/06/06 5pp
- 000410005 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re discharging waste Subsurface cavities will be within allowable limits W/supporting documentation
WHEEL R Schell Power Corp (subs of Bechtel Corp) 80/06/06 4pp
- 000410009 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re discharging waste Cavities will have no adverse effect on structures W/supporting documentation
WHEEL R L Hamlin Laboratories 80/06/06 3pp
- 000410041 Rept on Results of Analyses Performed on Well B at 09426
Wells B & L San Diego Co
WHEEL R L Hamlin Laboratories 80/06/06 4pp
- 000410046 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re discharging waste Cavities will have no adverse effect on structures W/supporting documentation
WHEEL R L Hamlin Laboratories 80/06/06 4pp
- 000410047 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re discharging waste Supporting documentation
GUTHRIE J L Affiliation Unknown 80/06/06 4pp
- 000410050 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re discharging waste Subsurface cavities will have no adverse effect on structures
WHEEL R L Hamlin Laboratories 80/06/06 4pp
- 000410058 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re U Fuel costs W/cost component in cost-benefit analysis Relatively small W/supporting documents
WHEEL R L Hamlin Laboratories 80/06/06 4pp
- 000410059 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al
Contention is re U Fuel costs W/cost component in cost-benefit analysis Relatively small W/supporting documents
WHEEL R L Hamlin Laboratories 80/06/06 4pp
- 000410068 Motion for order establishing 000713 prehearing conference P1007T-D R Southern California Edison Co P1007T-D R San Diego Gas & Electric Co P1007T-D R Clackamas & Oregon 80/06/06 2pp
- 000410107 Brief in lieu of pleading in support of motion for order establishing 000713 prehearing conference Failure to license facility at test condition date would result in
Unwarranted addl costs W/cost order & Certificate of Use and
P1007T-D R Southern California Edison Co P1007T-D R San Diego Gas & Electric Co P1007T-D R Clackamas & Oregon 80/06/06 3pp
- 000410094 Reorder 000615 "Further Commission Decision for Power Reactor Ops/Statement of Policy"
GOMBERG R L Hearing Branch 1 80/06/06 1p
- 000410097 Motion for order 000713 prehearing conference in US District Court, San Diego, CA re further identification of issues & witness recommendations may be viewed by 000707 Public invited with opportunity for participation
GUTHRIE J L Atomic Safety and Licensing Board Panel 80/06/06 1p
- I Financial Information**
- 000410032 Forward response to Questions 1 through 9 re financial analysis contained in NRC 791221 re financial statements & Joint Financial Reports 1979 for Cities of Anaheim & Riverside, CA
AMERICAN P Southern California Edison Co 80/06/16 103pp
- 000410050 Annual Financial Rept for yr ending 790630
P1007T-D R Anaheim, CA 79/11/26 4pp
- 000410053 Annual Financial Rept for yr ending 000630 for Public Utilities Rept
P1007T-D R Anaheim, CA 79/11/26 27pp
- 000410058 Annual Financial Rept for yr ending 790630
P1007T-D R Anaheim, CA 79/11/26 7pp
- F Operating License stage documents & correspondence**
- 000410031 Requests notification of Aug 1980 issuance of SR is not achievable Fuel loading for San Onofre scheduled for 004131
P1007T-D R Southern California Edison Co 80/05/06 2pp
- G Inspection reports, IE Bulletins & correspondence**
- 000410040 Forward IE Insp Rept 50-361/80-07 on 004131-17 Re noncompliance noted
OREGON J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/07 2pp
- 000410041 IE Insp Rept 50-361/80-07 on 004131-17 Re noncompliance noted Major areas inspected preoperational test program & procedures
PAULANDERSON, R Region 5, San Francisco, Reactor Operations Nuclear Support Branch J090303, A D, CALIFORNIA J D Region 5, San Francisco, Office of the Director 80/05/08 4pp
- H Reportable occurrences, LERs & related correspondence**
- 000410027 Forward final deficiency rept re lack of measuring & test equipment retractor
PAPAY, L T Southern California Edison Co 80/05/01 1p
- 000410030 Final deficiency rept re measuring & test equipment retractor Records of equipment performance not maintained & did not transmit to Bechtel performance data reflecting condition of equipment calibr at receipt Procedures revised
Southern California Edison Co 80/05/01 2pp
- 000410059 Forward final deficiency rept re safety-related items in proximity to nonhazardous Category 1 tanks
PAPAY, L T Southern California Edison Co 80/05/01 1p
- 000410060 Final deficiency rept re inadequate design considerations for safety-related items in proximity to Category 1 tank at plant design change package issued defining necessary physical changes Review confirms limit of deficiency
Southern California Edison Co 80/05/01 2pp
- 000410099 Comments on AO rept to Congress for first quarter CY80
Suggests change of wording re saltwater dosing sys pumps
MICHAELSON, C Director's Office 80/06/06 1p
- 000410084 Final Parts 21 rept re failed 1/4" of steel supplied by UR
Reel from which 4-inch elbows & 2-inch stem were mfg to
000410088 requirement Investigations conducted & closed at 46 limited facilities
SEAR, J L Chertkov Corp - Tube Turns Inc 80/06/06 3pp
- 000410040 Forward amend to 791213 final deficiency rept re lack of qualification testing documentation for repaired power cable
PAPAY, L T Southern California Edison Co 80/06/01 1p
- 000410044 Amend to 791213 final deficiency rept re lack of qualification testing documentation for repaired power cable EC cable will be replaced New cable will undergo LCCA qualification testing Testing to be completed by Dec 1980
Southern California Edison Co 80/06/01 2pp

T Hearing transcripts on consent/assent matters

0006101045 Forwards transcript of 000520 meeting w/0101,0102 & intervenor AM Carstens in Bethesda, MD re need to obtain add'l offshore seismic profiles in vicinity of site
000520 Licensing Branch 3 00/05/20 3pp

0006101018 Transcript of 000520 meeting w/0101,0102 & intervenor AM Carstens in Bethesda, MD re need to obtain add'l offshore seismic profiles in vicinity of site Pg 1-10
* Assistant Director for Environmental Technology 00/05/20 17pp

0006070041 Summary of 000521 meeting w/0101 & consultant USNR in Bethesda, MD re need for add'l offshore exploration in vicinity of site Meeting transcript add'l
000521 Licensing Branch 3 00/05/20 3pp

0006090544 Transcript of 000521 meeting w/0101 & consultant USNR in Bethesda, MD re need for add'l offshore seismic profiles near site Pg 1-82
* Division of Licensing 00/05/21 80pp

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

0006030110 Advises SWR & PWR applicants of NRC decision to modify its emergency plan presented in Section 5 of 00060-0077 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
0006007, D O Division of Licensing 00/05/20 13pp

0006020547 Responds to 000510 ltr re environ radiological sampling program being conducted at facilities Diagrams w/airborne Review Committee comments that program is inadequate Forwards detailed responses to Marine Review Committee reph
000510, H R Office of Nuclear Reactor Regulation, Director 00/05/22 2pp

0006020554 Detailed Response to Marine Review Committee Repl
* Radiological Assessment Branch 00/05/22 10pp

0006030559 Radiological Effluents Test Report for FMRs
* Commission 00060-0472 00/02/01 50pp

000602056A Informs NRC that CA Coastal Commission found program for monitoring radiological discharges from facilities to be grossly inadequate Requests that NRC work w/Southern CA Region to correct deficiencies in monitoring program
PITCHER, H L California, State of 00/01/10 1p

0006101021 Forwards request for add'l info for review of PSAR Approval of 00060-170 re methods for determining fuel assembly loads has been suspended pending receipt of add'l info from C-E
000600000, A Licensing Branch 3 00/05/20 13pp

0006090937 Approves request for withholding until documents containing structural calculations (ref 000602 7901 Documents contain bare numbers & highly technical calculations that could be taken out of context or misinterpreted
000600000, A Licensing Branch 2 00/05/20 3pp

0006040705 Submits add'l info re downcables Branch Question 361 as re seismic reflection profile within 25 km of plant Applicants proceeding to collect add'l offshore geophysical data along track lines Drawings available in Central Files
SIEGEL, B Southern California Edison Co 00/04/06 2pp

0006100301 Forwards responses to NRC Questions 361 AS & 363 AS to be incorporated in Amend 1 to PSAR Geophysical data referenced in Section 2 4 of response to Question 361 AS encl
SIEGEL, K P Southern California Edison Co 00/04/11 250pp

0006050972 Forwards request for add'l info for NRC review of PSAR
000600000, A Licensing Branch 3 00/04/16 1pp

0006020517 Forwards add'l piping design info requested by Mechanical Engineering Branch in order to proceed w/confirmation
piping analysis
SIEGEL, K P Southern California Edison Co 00/04/18 4pp

0006020506 "Calculation Sheet Shutdown Cooling Line Histogram"
Sheet 1 of 2
SIEGEL, K P Southern California Edison Co 00/04/09 1p

0006020501 "Calculation Sheet Shutdown Cooling 1200-017 Histogram"
Sheet 2 of 2
SIEGEL, K P Southern California Edison Co 00/04/09 1p

0006030500 "Mechanical Penetration Type 3, Number 9" Sheet 1 of 1
* Analysis 00/04/05 1p

0006020503 "Piping Assembly" Revision 4
* Construction Engineering Inc 77/06/03 1p

0006030547 "Module Details" Revision 3
* Construction Engineering Inc 78/01/12 1p

0006020554 "Verification of Design Basis 00-120, RCD Piping Components For San Onofre Nuclear Generating Station, Units 2 & 3"
PITCHER, H L Southern California Edison Co 00/01/21 37pp

0006030550 Package of drawings re pipe support assembly
* Southern California Edison Co 00/04/16 100pp

0006020514 Forwards geophysical drawings & data of area offshore from site, per 000604 comment Sixty-nine seismic & sub-bottom profiles are available in hard copy only
SIEGEL, B Southern California Edison Co 00/06/20 70pp

0006020516 "Shot Point Base Map"
HILLIARD, O Nelson Inc 00/04/19 1p

0006020510 "Shot Point Base Map"
HILLIARD, O Nelson Inc 00/04/19 1p

0006040443 Responds to NRC 000491 request for info re use of concrete materials with any seismic Category 1 plant structures re concrete masonry walls exist in any facility seismic Category 1 plant structures
SIEGEL, K P Southern California Edison Co 00/04/24 1p

F Security, medical, emergency & fire protection plans

0006101017 Forwards clarification of NRC requirements for emergency response facilities defined in 700603 ltr ASB specific criteria for facilities under development
SIEGEL, K P Division of Operating Reactors 00/04/20 40pp

0006020540 Advises that add'l 90 day is required to respond to comments in NRC 000420 ltr re all 700603 guard training & qualification plan Add'l time required to establish physical exercise program Response will be submitted by 000601
SIEGEL, K P Southern California Edison Co 00/05/23 1p

G Regulatory correspondence

0006101014 Forwards applicants' notice for summary disposition of Intervenor Friends of the Earth et al Contentions 9 re U Fuel costs, submitted to proceeding by ASB 000602
SIEGEL, K P Southern California Edison Co 00/04/06 1p

0006101001 Notice for summary disposition of Intervenor Friends of the Earth et al Contentions 1a re downcabling wells & Contentions 9 re U Fuel costs, submitted to proceeding by ASB 000602
SIEGEL, K P Southern California Edison Co 00/04/06 1p

0006101008 Brief re ltr of pleading in support of applicants' notice for summary disposition of Intervenor Friends of the Earth et al Contentions 1a re downcabling wells & Contentions 9 re U Fuel costs List of project reple suppling notice encl
SIEGEL, K P Southern California Edison Co 00/04/06 1p

0006101008 Statement of well facts as to which no genuine issue exists to be heard re Intervenor Friends of the Earth et al Contentions 1a re downcabling wells & Contentions 9 re U Fuel costs List of project reple suppling notice encl
SIEGEL, K P Southern California Edison Co 00/04/06 1p

0006101003 Statement of well facts as to which no genuine issue exists to be heard re Intervenor Friends of the Earth et al Contentions 9 re U Fuel costs Applicants' projection of fuel costs includes evaluation of U prices
SIEGEL, K P Southern California Edison Co 00/04/06 1p

DOCKETED ITEMS

--000110029 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re decontaminating wells. Calculated response times within allowable limits. W/ supporting documentation. BETHSIL, R. Bethel Power Corp. Issue of Bethel Corp. 8/5/04/03 4pp

--000110029 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re decontaminating wells. Subsurface cavities will have no detrimental effect on seismic structures. BETHSIL, R. A. Woodward-Clyde Consultants, Inc. 8/5/04/03 20pp

--000110041 "Reply to Results of Analysis Performed on Well D at G0025 Unit 2 & 3, San George, CA." BETHSIL, R. A. Woodward-Clyde Consultants, Inc. 7/5/03/29 84pp

--000110041 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re decontaminating wells. Subsurface cavities will have no adverse effect on structures. W/ supporting documentation. MCNEIL, R. L. Benth Laboratories 8/5/04/04 34pp

--000110047 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re decontaminating wells. Supporting documentation. MCNEIL, R. L. Affiliation Unknown 8/5/04/02 14pp

--000110052 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re decontaminating wells. Subsurface cavities will have no adverse effect on structures. BETHSIL, R. P. American Nuclear Society 8/5/04/05 7pp

--000110058 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re U fuel casks. U fuel casks in construction. Analysis relatively small. W/ supporting documentation. BETHSIL, R. L. Southern California Edison Co. 8/5/04/05 10pp

--000110059 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention is re U fuel casks. U fuel casks adequately accounted for. U fuel casks. Certificate of DRC met. JONES, D. H. Wheeler Corp. Issue of Arthur D. Little, Inc. 8/5/04/02 13pp

000110068 Motion for order establishing 800715 prehearing conference. PIQUET, D. H. Southern California Edison Co. PIQUET, D. H. San Diego Gas & Electric Co. PIQUET, D. H. Chickering & Gregory 8/5/04/04 5pp

--000110067 Brief in lieu of pleading in support of motion for order establishing 800715 prehearing conference. Failure to license facility at cost completion date would result in increased cost. W/ draft order & Certificate of DRC. PIQUET, D. H. Southern California Edison Co. PIQUET, D. H. San Diego Gas & Electric Co. PIQUET, D. H. Chickering & Gregory 8/5/04/04 12pp

000110082 Forward 800615 "Further Commission Ordinance for Power Reactor Ch. Statement of Policy." CHANDLER, J. Hearing Branch 2 8/5/04/20 1p

000110097 Notice & order for 800737 prehearing conference in US District Court, San Diego. Give further identification of Issues & Actions Recommendations may be served by 800707. Public invited w/o opportunity for participation. BETHSIL, R. Atomic Safety and Licensing Board Panel 8/5/04/24 1p

I Financial Information

000110092 Forward responses to Questions 1 through 9 re financial analysis submitted in 800732. 1st Financial statements & Annual Financial Repts 1979 for Cities of Anaheim & Riverside. BETHSIL, R. P. Southern California Edison Co. 8/5/04/16 122pp

--000110092 Annual Financial Rept for yr ending 7/9/03. FERRERAS, A. Anaheim, CA. 7/5/11/16 87pp

--000110092 Annual Financial Rept for yr ending 8/5/03 for Public Utility Reg. HOYT, D. W. Anaheim, CA. 7/5/11/16 27pp

--000110092 Annual Financial Rept for yr ending 7/9/03. FERRERAS, A. Riverside, CA. 7/5/11/16 24pp

B Reperable documents, ESRs & related correspondence

000110037 Forward Final deficiency reft re lack of measuring & test equipment reft. PAVAN, L. T. Southern California Edison Co. 8/5/05/21 1p

--000110037 Final deficiency reft re measuring & test equipment reft. Records of equipment performance not maintained & did not transmit to Bethel performance data reflecting condition of equipment. Subst. reft re missing procedures revised. Southern California Edison Co. 8/5/05/21 2pp

000110037 Forward Final deficiency reft re safety-related lines in proximity to nonseismic Category 1 limits. PAVAN, L. T. Southern California Edison Co. 8/5/05/29 1p

--000110037 Final deficiency reft re inadequate design considerations for safety-related lines in proximity to Category 1 bank at Plant design change package reft re defining necessary physical changes. Review confirms limit of deficiency. Southern California Edison Co. 8/5/05/29 2pp

000110077 Comments on AD reft re Congress for final quarter CY00. Suggests change of wording re saltwater cooling sys pumps. MCNEIL, R. L. Director's Office 8/5/04/04 1p

000110084 Final Part 21 reft re mixed heat of steel supplied by US Steel from which 4-inch elbow & 2-inch head were mfg to 4225PSF requirement. Investigations conducted & closed at 42546 Facilities. BETH, J. L. Chubbco Corp. Tube Towns Div. 8/5/04/06 3pp

000110040 Forward amend to 791212 Final deficiency reft re lack of qualification testing documentation for repaired 60 power cable. PAVAN, L. T. Southern California Edison Co. 8/5/06/11 1p

--000110040 Amend to 791212 Final deficiency reft re lack of qualification testing documentation for repaired power cable. 60 power cable will be replaced. 60 power cable will undergo LOCA qualification testing. Testing to be completed by Dec 1993. Southern California Edison Co. 8/5/05/31 3pp

T Hearing transcript on non-abstract matters

000110425 Forward transcript of 800580 meeting w/ utility, NRC & intervenor. All Carbons in Bethesda, MD re need to obtain add'l offshore seismic profiles in vicinity of site. 800580 Licensing Branch 3 8/5/05/20 3pp

--000110425 Transcript of 800580 meeting w/ utility, NRC & intervenor. All Carbons in Bethesda, MD re need to obtain add'l offshore seismic profiles in vicinity of site. 800580 Licensing Branch 3 8/5/05/20 3pp

000110045 Summary of 800580 meeting w/ utility & consultant. 800580 in Bethesda, MD re need for add'l offshore exploration in vicinity of site. Hearing transcript sent. 800580 Licensing Branch 3 8/5/05/20 1pp

--000110045 Transcript of 800580 meeting w/ utility & consultant. 800580 in Bethesda, MD re need for add'l offshore seismic profiles near site. 800580 Licensing Branch 3 8/5/05/21 3pp

SECRET 50-540 FORMER RIVER NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

000110092 Advices RAB & RAB applicants of NRC decision to modify implementation plan presented in Section 4 of RABED-0077 re adequacy of applicable support structures. General operating practices re revised procedures & acceptable criteria. RABED-0077. D. H. Division of Licensing 8/5/05/23 13pp

B Inspection reports, IE Regulations & correspondence

000110092 Forward 16 Circular 80-15, "Grid Work Damage in Reinforced Steel Structures." 30 written reports received. 800120, D. H. Region 1, Philadelphia, Office of the Director 8/5/05/20 1p

SECRET 50-204 JOSEPH H. FARLEY NUCLEAR PLANT, UNIT 2

A Application/Construction stage documents & correspondence

0006030510 Advances SMR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of 0006030507 re sequence of applicability support structures General operating reactor review procedure & acceptance criteria and
EIS/ENR-0.0 Division of Licensing 00/05/20 13pp

0006030534 Requests branches complete review of 5-11th PMR Section 3 & 4g 0006030534H
EIS/ENR-0.0 Licensing Branch 2 00/05/20 1p

0006030532 Responds to NRC 000408 letter requesting addl info re auxiliary feedwater unit clarification of unit 791132 response to recommendation 00-4 encl
CLAYTON F L Alabama Power Co 00/05/27 23pp

0006030592 Forwards modified startup physics test program confirming nuclear design & correct core fuel loading validating analytical model providing instrumentation cable data & demonstrating abnormal core condition sensitivity
CLAYTON F L Alabama Power Co 00/05/20 10pp

0006030670 Forwards addl info requested by Hydraulic Engineering Branch re Executive Order 11900 questions re Pilecap design drawings encl
CLAYTON F L Alabama Power Co 00/05/28 8pp

0006110280 Forwards response to 000519 request for info re unit responses to radiological questions concerning PMR, PMR quantities of respiratory protection devices added to PMR Tables 10.2d & 12.2d
CLAYTON F L Alabama Power Co 00/06/03 4pp

0006110817 Forwards addl info re seismic qualification of safety-related non-MMR electrical & mechanical equipment in response to NRC 000503 request
CLAYTON F L Alabama Power Co 00/06/05 50pp

0006110502 "Final Seismic Response Spectra-Joseph H Farley Nuclear Units 1 & 2, A.M. Power Co-Containment & Internal Structures" -
Bechtel Corp 72/12/31 235pp

0006110627 "Seismic Response Spectra, Joseph H Farley Nuclear Plant, Units 1 & 2, A.M. Power Co-Auxiliary Bldg" -
Bechtel Corp 72/06/31 73pp

0006110410 Forwards info documenting control valve human factors & operations review Personnel will be available to accompany NRC representatives during review scheduled for 000618-20
CLAYTON F L Alabama Power Co 00/06/10 10pp

0006110413 Forwards unit response to NRC position re control rod guide tube support pins Although not required, unit will prepare existing guide tube support pins w/0.050 P solution heat treatment loop
CLAYTON F L Alabama Power Co 00/06/11 3pp

0006120343 Notification of 000624 meeting w/unit in Bethesda, MD re discuss applicant plan for managing plant operation & to review Q. Application Agenda encl
HINTER, L Licensing Branch 2 00/06/13 4pp

0006120414 Forwards test info re unit review of special low power testing program in response to NRC request to enhance better operator training. Test 1 should be performed prior to full power licensing of facility
CLAYTON F L Alabama Power Co 00/06/17 3pp

0006140324 Advances that ATWS emergency operating procedure has been developed in accordance w/requirements set forth in NRC 000413 11c Procedure for ATWS test runs at facility
CLAYTON F L Alabama Power Co 00/06/20 3p

F Security, medical, emergency & fire protection plans

0006150387 Forwards identification of NRC requirements for emergency response facilities defined in 790912 11c A&E specific criteria for facilities under development
EIS/ENR-0.0 Division of Operating Reactors 00/06/25 41pp

0006150520 Requests that FEMA review of state & local emergency plan be provided consistent w/rel schedule to avoid potential delays in licensing decisions
HINTER, J P Commission 00/06/13 2pp

0006200305 Ack receipt of 000505 letter requesting withdrawal of 10% of Class 1E equipment cables & associated circuits. NRCs complete Jan 1980 withdrawal will be summarized in fire protection program re-evaluation
CLAYTON F L Alabama Power Co 00/05/27 8pp

J Insurance & indemnity information

0006200342 Forwards signed copy of Amend & No Indemnity Agreement 8-81
CLAYTON F L Alabama Power Co 00/03/27 2pp

P Operating license stage documents & correspondence

0006190588 Notification of 000626 meeting w/unit in Durham, NC to discuss human factors having impact on operator effectiveness
HINTER, L Licensing Branch 2 00/06/05 4pp

0006200320 Notification of 000624 meeting w/unit to discuss outstanding issues re licensing review & plans for staffing & managing
HINTER, L Licensing Branch 2 00/06/10 2pp

0006240516 Forwards response to 791-2 action plan info addresses fuel loading, low power testing license requirements & fuel power license requirements
CLAYTON F L Alabama Power Co 00/06/20 117pp

Q Inspection reports, IE Bulletins & correspondence

0006030543 Forwards IE Insp Rpt 30-364/06-06 re 000408-11. No noncompliance noted
LORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/23 2pp

0006030543 IE Insp Rpt 30-364/06-04 re 000408-11. No noncompliance noted. Major event impacted thermal expansion & vibration testing of piping and piping supports & restraints
LORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/23 2pp

0006030548 Forwards IE Bulletin 00-11, "Managing Mail Design" No action or written response required IE Info Notice 79-26.
"Downloading of Structural Elements Due to Pipe Operator Load" encl
LORD, R C Region 2, Atlanta, Office of the Director 00/05/03 2pp

0006030553 Ack receipt of 000408 11c informing NRC of steps taken to correct violations noted in IE Insp Rpts 30-364/06-07 & 30-364/06-04
LORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/08 2pp

0006040521 Responds to NRC 000410 11c re violations noted in IE Insp Rpts 30-364/06-07 & 30-364/06-04. Corrective action cleaning stainless steel pins w/Debris-brite pads was stopped. Cleaning pads returned to warehouse
CLAYTON F L Alabama Power Co 00/06/28 2pp

0006040534 Forwards IE Insp Rpts 30-345/03-07 & 30-364/06-04 on 000304-29 re notice of violation
LORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/10 3pp

0006040542 Notice of violation from Insp on 000304-29
LORD, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/04/08 1p

0006040550 IE Insp Rpts 30-345/03-07 & 30-364/06-04 on 000304-29. Noncompliance noted unauthorized use of Scotch-brite pads for final cleaning of stainless steel pipe surfaces & failure to perform w/ approved procedure
HINTER, L Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/06/02 4pp

0006200076 Forwards IE Insp Rpts 30-345/03-07 & 30-364/06-04 on 000304-29. No noncompliance noted.
LORD, R C Region 2, Atlanta, Fuel Packaging & Materials Safety Branch 00/05/05 2pp

0006200294 IE Insp Rpts 30-345/03-07 & 30-364/06-04 on 000304-29. No noncompliance noted. Major event inspected radiology equipment, radiology test procedures, chemistry & health physics procedures & security training
LORD, R C Region 2, Atlanta, Fuel Packaging & Materials Safety Branch 00/06/02 5pp

DOCKETED ITEMS

--0006190320 IE Insp Repts 50-021/80-11 & 50-066/80-11 on 800503-0507
Noncompliance noted failure to operate ROCR properly to
limit red water, w/ROCR is undesirable, to evaluate procedure
change & to provide updated plant drawings in control room
800503-0507 F Region 2, Atlanta, Office of the Director, SAVAGE, H C
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/04/19 4pp

8005030510 Act receipt of 8005027 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-021/80-10 &
50-066/80-10
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/05/02 2pp

--8005030510 Responds to NRC 800470 ltr re violations noted in IE Insp
Repts 50-021/80-10 & 50-066/80-10 Written & approved
functional test was not necessary because operability could
have been demonstrated through existing plant procedures
MIDNER, W A Georgia Power Co 80/05/27 2pp

--8005030520 Forwards corrected cover page for IE Insp Repts 50-021/80-10
& 50-066/80-10 on 800503-0402
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/05/08 1p

--8005030520 Corrected cover page for IE Insp Repts 50-021/80-10 &
50-066/80-10 on 800503-0402
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/05/08 1p

--8005030520 Forwards IE Insp Repts 50-021/80-10 & 50-066/80-10 on
800503-0402 & notice of violation
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/04/30 2pp

--8005030520 Notice of violation from Insp on 800503-0402
Region 2, Atlanta, Office of the Director 80/04/30 1p

--8005030527 IE Insp Repts 50-021/80-10 & 50-066/80-10 on 800503-0402
Noncompliance noted failure to perform post-load testing.
SAVAGE, H C - BURNETT, P F Region 2, Atlanta, Office of the
Director 80/04/30 4pp

8005030545 Act receipt of 800514 & 27 ltrs informing NRC of steps taken
to correct violations noted in IE Insp Repts 50-021/80-10 &
50-066/80-10 50-021/80-10 & 50-066/80-10
MIDNER, W A Region 2, Atlanta, Safeguards Branch 80/04/11 1p

--8005030549 Responds to NRC 800510 ltr re violations noted in IE Insp
Repts 50-021/80-10 & 50-066/80-10 Requests that 800514 ltr
be withheld (ref 100PR2 7901)
MIDNER, W A Georgia Power Co 80/05/29 1p

--8005030550 Forwards IE Insp Repts 50-021/80-10 & 50-066/80-10 on
800503-11 & notice of violation Notice of violation
withheld (ref 100PR2 7901)
O'REILLY, J F Region 2, Atlanta, Office of the Director
80/04/18 2pp

--8005030554 IE Insp Repts 50-021/80-10 & 50-066/80-10 on 800503-11
Noncompliance noted failure to follow procedures for
dismantling safety incinerators & to perform vital area
petrols as committed Safety withheld (ref 100PR2 7901)
TODIN, V J Region 2, Atlanta, Safeguards Branch, PERMY, C D
Region 2, Atlanta, Office of the Director 80/04/08 3pp

--8005030558 Forwards IE Insp Repts 50-021/80-10 & 50-066/80-10 on
800503-20 & notice of violation Notice of violation
withheld (ref 100PR2 7901)
MIDNER, W A Region 2, Atlanta, Safeguards Branch 80/04/29 4pp

A Periodic operating reports & related correspondence

8005100454 Forwards monthly operating report for May 1980
MIDNER, W A Georgia Power Co 80/05/10 1p

--8005100477 Monthly operating report for May 1980
MIDNER, W A Georgia Power Co 80/05/10 3pp

G Reportable occurrences, LERs & related correspondence

8005030625 Forwards LER 50-076/03L-0
MIDNER, W A Georgia Power Co 80/05/03 1p

--8005030648 LER 50-076/03L-0 on 800503, during performance of control rod
driveline hydraulic control unit pressure indicator & switch
calibration procedure 800-2-5356, high percentage of pressure
switches found outside limit caused by instrument drift
MIDNER, W A Georgia Power Co 80/05/20 2pp

8005030650 Forwards LER 50-083/03L-0
MIDNER, W A Georgia Power Co 80/05/27 1p

--8005030650 LER 50-083/03L-0 on 800503, during surveillance testing found
oil barrier pressure switch 2001-00101 & 2 were not
within allowable Tech Specs caused by instrument drift
Switches recalled
MIDNER, W A Georgia Power Co 80/05/27 2pp

8005030656 Forwards LER 50-083/03L-0
MIDNER, W A Georgia Power Co 80/05/27 1p

--8005030666 LER 50-082/03L-0 on 800503, during manual reactor shutdown,
primary containment purge system operation exceeded Tech Spec
limits for primary containment integrity caused by personnel
error
MIDNER, W A Georgia Power Co 80/05/27 2pp

8005030668 Forwards LER 50-077/03L-0
MIDNER, W A Georgia Power Co 80/05/20 1p

--8005030685 LER 50-077/03L-0 on 800420, w/reactor at 100 power, a reactor
stop chiller failed to maintain average draw; temp when
chiller stopped caused by broken coils and temp was
replaced & temp decreased to within limits.
MIDNER, W A Georgia Power Co 80/05/20 2pp

8005030688 Forwards LER 50-079/03L-0
MIDNER, W A Georgia Power Co 80/05/29 1p

--8005030688 LER 50-079/03L-0 on 800503, inboard isolation valve 2041-0006
opened but failed to close automatically caused by steam
leaking around pressure seal allowing water to enter &
collapse in inboard causing windings to short out
A Georgia Power Co 80/05/29 2pp

8005030690 Forwards LER 50-083/03L-0
MIDNER, W A Georgia Power Co 80/05/29 1p

--8005030692 LER 50-083/03L-0 on 800503, while performing reactor core
isolation cooling steam line pressure instrument functional
test, submergence steam supply line isolation valve 2001-0006
failed to operate caused by failed operator torque switch
MIDNER, W A Georgia Power Co 80/05/29 2pp

8005100600 Forwards LER 50-083/03L-0
MIDNER, W A Georgia Power Co 80/05/03 1p

--8005117407 LER 50-083/03L-0 on 800514, w/reactor in startup mode,
personnel observed that indicating lights for 20 RHR pump
isolation valves were extinguished. Valves were not operate
from control switches. Caused by broken limit switch rotors
MIDNER, W A Georgia Power Co 80/05/05 2pp

8005030427 Forwards LER 50-086/03L-0
MIDNER, W A Georgia Power Co 80/05/15 1p

--8005040444 LER 50-086/03L-0 on 800503, during power increase, RBM flow
was throttled to reduce dilution flow, reducing cooling
capacity 2M temp exceeded specs caused by operator
throttling over water flow through plant
MIDNER, W A Georgia Power Co 80/05/10 2pp

8005030448 Forwards LER 50-085/03L-0
MIDNER, W A Georgia Power Co 80/05/11 1p

000404034 Forwards Bally wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS well for 000501 well charts for 000501-01, chart recorder callout results for 000501 & Lake Me levels for 000108-0001
000501-01 Northern Indiana Public Service Co 00/03/30 3pp

H General correspondence

0005200171 Responds to 000403 request to comment on 8 Locust concerns re spent fuel storage pool expansion Unit indicated that no plans for expansion anticipated until 1985 AF 1985 NRC approval & public consideration would precede expansion
000403-01 Office of the Executive Director for Operations
000404-04 2pp

0001010148 Forwards "Winter 1980 Quarterly Rep. Bally Nuclear-1 Site." Jan-Mar 1980, prepared by TX Instruments, Inc
000501-01 Northern Indiana Public Service Co 00/06/04 5p

P Operating license stage documents & correspondence

0005000165 Forwards affl TH-2 related requirements to operating reactor Licensee requirements for TH-2 Station Plan include ship's assembly, licensing issues & license dissemination of operating experience Response requested within 30 days
000501-01 Division of Licensing 00/05/07 10pp

0001010119 Forwards well charts for 000501-00, Bally wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 000502 Inlet 988 & 987 cable hung up on 000502 & water meter out of spec on 000503
000501-01 Northern Indiana Public Service Co 00/04/26 34pp

0004120123 Requests comments on NRC-0577, "Potential for Low Fracture Toughness & Corrosion Fatigue on PWR Steam Generator & Reactor Coolant Pump Supporter." Proposed review procedure & implementation schedule encl
000501-01 Division of Licensing 00/05/19 7pp

0004020028 Forwards well charts for 000503-0004 Bally wells w/o recorders, USGS wells for 000503 & pond levels, pneumatic pressure transducers & water meter readings for 000505
000501-01 Northern Indiana Public Service Co 00/06/13 34pp

0004120124 Subjects info re potential issues involving reactor cavity shields and ring & biological shielding, in response to 700310 IIR (via 700310) re safety-related components will be affected by biological shielding in event of LSCA
000501-01 Arkansas Power & Light Co 00/04/06 2pp

0004050119 Forwards well charts for 000504-01, Bally wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 000501 & USGS wells for 000501
000501-01 Northern Indiana Public Service Co 00/04/28 33pp

U Congressional/Executive Correspondence

0004030018 Forwards "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030039 Expresses concern re NRC consideration of CP renewal Encl Lake Me Federal Mar 1980 study challenges NRC 000410 brief re international relations, ash pond seepage & coast dewatering
19703-01 House of Rep 00/04/02 3p

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030070 "How Bally Nuclear Plant Could Dry Up Once Heat Exchangers" re Michigan Federation 00/05/01 2pp

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 ARKANSAS NUCLEAR ONE, UNIT 2

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0 NRC Draft/Final Environmental Statements, supply & correspondence

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 PER for AR Nuclear One, Unit 2
0 Office of Nuclear Reactor Regulation, Director
000501-01 7/26/82 12pp Available at NRC, Box 70

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

F Security, medical, emergency & fire protection plans

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 Forwards request for addl info re security personnel training & qualification plan Encl withholds info
000403 7001
000501-01 Operating Reactors Branch 4 00/05/19 3pp

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Rule adds new Section 50.40 b App B to 10CFR55 is expected to be published in FR by end of May
000501-01 Division of Licensing 00/05/19 40pp

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR55 "Fire Protection Program for Nuclear Power Plants Operating Prior to 700101." Submitted by NRC 000501 In Page 14a not encl
000501-01 Division of Licensing 00/05/19 73pp

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

0004030001 Forwards revisions to proposed addl safeguards contingencies plan per AR Reg 000401 request Plan withdrawn (no)
000501 7001
000501-01 Arkansas Power & Light Co 00/05/03 1p

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

Act received of NRC 000501 1pp requesting info on security training & qualification plan Requests copy of 00-0074 dealing with plan prior to response to 1p
000501-01 Arkansas Power & Light Co 00/04/13 1p

0004030018 "AR Nuclear 1 Steam Electric Station, Unit 2 Shorter Rept." Suppl 3 for period ending 000403
000501-01 Arkansas Power & Light Co 00/04/09 1p

B Inspection reports, IE Bulletins & correspondence

0004040034 Forwards IF Insp Repts 50-012/80-04 & 50-048/80-04 on 000322-0421 & notice of violation
000501-01 Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/03 2pp

0004040040 Notice of violation from insp on 000322-0421
000501-01 Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/02 3pp

0004040046 IE Insps Repts 50-012/80-04 & 50-048/80-04 on 000322-0421
000501-01 Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/05/02 10pp

0004040097 Forwards IE Bulletin 80-12, "Security Mail Design." Requires action & response IE Insps Repts 50-012/80-04 & 50-048/80-04 on 000322-0421
000501-01 Region 4, Dallas, Office of the Director 00/05/02 5pp

0004040017 Forwards IE Bulletin 80-12, "Security Mail Removal By Operability." Requires action & response IE Insps Repts 50-012/80-04 & 50-048/80-04 on 000322-0421
000501-01 Region 4, Dallas, Office of the Director 00/05/02 1p

- 0004050001 Response to violations noted in IE Insp Repts 50-033/00-06 & 50-368/00-56 Corrective actions taken to high radiation areas locked or repaired & locked Contamination removed from prohibited areas & maint personnel notified
TRINBLE, D C Arkansas Power & Light Co 00/03/09 4pp
- 0006040104 Act receipt of 000606 ltr inferring NRC of steps taken to correct violations noted in IE Insp Repts 50-033/00-05 & 50-368/00-03
PAGEM, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch 00/06/06 1p
- 0006040106 Response to NRC ltr re violations noted in IE Insp Repts 50-033/00-05 & 50-368/00-03 Corrective actions revised
Procedure 1004 22 C 2004 13 following specific sign-off for each load meter task including containment entries
TRINBLE, D C Arkansas Power & Light Co 00/05/09 5pp
- 0006050409 Response to IE Bulletin 00-12, "Decay Heat Manual By Operability" Analysis of procedures for safeguarding against loss of A/C capability should be completed by 000819
CHAMBERS, G M Arkansas Power & Light Co 00/06/12 3pp
- E Periodic operating reports & related correspondence**
- 0006110149 Forward "Annual Evaporator Monitoring Rept"
TRINBLE, D C Arkansas Power & Light Co 00/09/12 1p
- 0006110154 "Annual Evaporator Monitoring Rept" Overall Drawing sent
4 Arkansas Power & Light Co 00/09/12 400pp
- 0006110803 Forward monthly operating rept for May 1990
TRINBLE, D C Arkansas Power & Light Co 00/06/13 1p
- 0006110809 Monthly operating rept for May 1990
PHEDES08AFT, N Arkansas Power & Light Co 00/06/13 5pp
- F Reportable occurrences, LERs & related correspondence**
- 0006090206 Forward updated LER 00-003/02-1
TRINBLE, D C Arkansas Power & Light Co 00/06/02 1p
- 0006090204 Updated LER 00-022/02-1 on 000906, while performing testing on steam driven emergency feedwater pump; DPFA pump tripped three times due to overpressure caused by mechanical adjustment to pump & driver controller. Needed idle speed.
PHEDES08AFT, N Arkansas Power & Light Co 00/06/03 2pp
- 0006030406 Forward LER 00-025/03L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/04 1p
- 0006030407 LER 00-025/03L-0 on 000307, during Mode 1 operation, control room alarm indicated valve 20V-3557 to be open when valve was closed. Caused by position switch misalignment due to loose screw. Switch replaced.
PHEDES08AFT, N Arkansas Power & Light Co 00/06/04 1p
- 0006030205 RD 50-368/00-007 on 000503, safety injection tank boron concentrations reported out of Tech Spec. condition. Possibly caused by boron stratification. Boron concentration adjusted & cause being investigated.
KIMBLE, J F Arkansas Power & Light Co 00/06/04 2pp
- 0006100408 Forward LER 00-026/03L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/11 1p
- 0006100406 LER 00-034/03L-0 on 000116, control room Air conditioner compressor, 20E-1A tripped. Caused by valve tripping on freeze protection due to too small of load for chiller when providing cooling for core protection condenser pump.
SHINVELY, C N Arkansas Power & Light Co 00/06/11 1p
- 0006110423 Forward LER 00-027/03L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/12 1p
- 0006110434 LER 00-027/03L-0 on 000316, during Mode 1 operation, svc water sampler 30E-07-10 on loop 1 found broken. Caused by improper installation. Harpnet had had only one thread engaged & could not hold load. Harpnet reinstalled properly.
SHINVELY, C N Arkansas Power & Light Co 00/06/12 1p
- 0006100454 Forward updated LER 00-019/020-2
TRINBLE, D C Arkansas Power & Light Co 00/06/12 1p
- 0006040409 Updated LER 00-003/02-0 on 000302, while performing ID ammonia surveillance test on diesel generator. I-unit load on channel 1000. 0 vibration became apparent. Caused by broken generator motor shaft.
SHINVELY, C N Arkansas Power & Light Co 00/06/12 1p
- 0006100403 Forward LER 00-008/03L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/12 1p
- 0006100407 LER 00-008/03L-0 on 000506, during Mode 1 operation, steam generator high level pretrip/trip signal received on channel 1 CFB. Caused by power supply failure on bistable card. Card not tested & channel locked.
SHINVELY, C N Arkansas Power & Light Co 00/06/12 1p
- 0006050009 Forward LER 00-030/02L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/16 1p
- 0006050303 LER 00-030/02L-0 on 000520, during Mode 1 operation, steam driven emergency feedwater pump, DPFA tripped on overpressure following manual start signal. Investigation did not reveal cause of pump trip. Pump trip reset.
PHEDES08AFT, N Arkansas Power & Light Co 00/06/16 1p
- 0006050403 Forward LER 00-029/02L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/16 1p
- 0006050604 LER 00-029/02L-0 on 000520, during Mode 1 operation, 2 diesel generator deluge systems reviewed. Imperable. Caused by deluge valve being inattentionally removed from svc to facilitate needed fire ops mode.
PHEDES08AFT, N Arkansas Power & Light Co 00/06/16 1p
- 0006050409 Forward LER 00-037/02L-0
TRINBLE, D C Arkansas Power & Light Co 00/06/17 1p
- 0006050409 LER 00-037/02L-0 on 000503, during Mode 1 operation, safety injection tank C & D. Inj. tank to have boron concentrations of 1.71 ppm & 1.420 ppm, respectively. Caused by design error. Caused by boron stratification in safety injection tanks.
SHINVELY, C N Arkansas Power & Light Co 00/06/17 1p
- DOCKET 50-368 HILLMAN & MCCOY NUCLEAR STATION, UNIT 1**
- A Application/construction stage documents & correspondence**
- 0006050195 Forward Hattis Engineering Branch inspect re water chemistry programs file sent
PHEDES08AFT, N Arkansas Power & Light Co 00/04/07 1p
- 0006050015 Notification of cancelled 000919-20 meeting whilst in Neeklenburg County, MO to perform design review of control room
GIBBLE, R A Licensing Branch 1 00/04/20 2pp
- 0006220010 Advise BAE & PMS applicants of NRC decision to modify implementation plan presented in Section 4 of 000501-2077 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria and
EISENHART, D D Division of Licensing 00/05/20 10pp
- 0006060345 Amend 04 to CFB-02 & CFB-04 updating "Electrical Schematic" & "DC I-0 Schematic" drawings available in Central P/line only
PHEDES08AFT, N Arkansas Power & Light Co 00/05/22 700pp
- 0006050194 Notification of 000602-05 meeting whilst in Neeklenburg County, MO to perform design review of plant control room
GIBBLE, R A Licensing Branch 1 00/05/22 3pp
- 0006090206 Forward response to THL concerns, superseding previous THL submittals transmitted 7/11/19, 10/24 & 000520
PHEDES08AFT, N Arkansas Power & Light Co 00/05/23 30pp
- 0006100127 Notification of 000602 meeting whilst in Bethesda, MD to discuss facility staffing, testing & related matters
GIBBLE, R A Licensing Branch 1 00/05/20 3pp
- 0006100303 Notification of 000606 meeting whilst in Bethesda, MD to discuss facility staffing, testing & related matters
GIBBLE, R A Licensing Branch 1 00/05/20 3pp
- 0006050603 Forward request for add info re radiological assessment. Info should be provided by 000620
YOUNGBL, D B Licensing Branch 1 00/06/04 1pp

DOCKETED ITEMS

0000100054 Response to NRC 000409 for requesting independent plant-wide
audit of installation of safety-related equipment Facility
procedures provide adequate assurance that operation
procedures properly implemented Add audit unattended
PARKER, M D Site Power Co 00/04/05 2pp

Q50611027 Forwards response to HRC 000912 request for info re reaction
vessel noises
MARSS, W.G. Date Power Co 02/04/06 4pp

0006120347 Forward "Hastingshouse Multiple Aperture Small Break SCEN
Analyst." in response to NRC 000409 request multiple
aperture breaks are bounded by analysis performed in FSAN
where only single break location assumed
PARKER, M D Duke Power Co 03/06/06 Rep

---8086:00370 "Mushyhouse Multiple Aperture Small Area EDS Analyzer"
C. Dale Brown, Co. 8005411 2726

00000000 Summary of 000000 meeting w/utill in Bethel
application

0006240495 Forwards supplemental info on program to monitor & control secondary water chemistry
 sub009.U.D. Cuba Power Co 05/06/19 Dip

© 2006 BMC Subject Evaluation Board (SEB), apply to correspondence

0000000001 Forwards Page 3 to SER Ofc of Nuclear Reactor Regulation
issued evaluation in connection w/OL application 4/10 and
0000000000-1 Licensing Branch 1 05/05/00 Day

W06040649 Suppl 3 to ERM Per Facility
a. Office of Nuclear Reactor Regulation Director NUREG-0422 03
DO/DO/DO 2299 Available at N710

* Safety, medical, emergency & fire protection plans

000010017 Forwards identification of NRC requirements for emergency response facilities defined in 70CFR101 in Adol specific criteria for facilities under development
KIRKMAN, J. O. Division of Operating Reactors 00/04/95 61pp

8006360074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 10CFR2 290)
648898-000, Duke Power Co. 80/06/74 1a

BO062206128 Notification of BO0617 meeting w/OTL to evaluate upgrading
of emergency planning Region 2 BO0030 press release encl
BIRKEL, R A Licensing Branch 1 BO/06/10 App

© Advertising correspondence

000480394 Forwards Lincoln County, NC Board of County Commissioners
791001 & 000408 resolutions affirming petition that spent
nuclear fuel should be transported from Oconee to McGuire
on interstate highway
HOUSER, F R North Carolina, State of 00/04/17 Doc

4005220577 Advise that still is to submit proposed Findings of Fact by
BOESIG, non-HRC parties by 005529 & HRC by 000609
MCNARY, J M Detective & Liberman 00/04/20 1a.

BO060602M Forwards applicant proposed findings of fact & conclusions
of law in form of initial decision
MCARRY, J M DeWeese & Liberman 06/05/19 5p

--B006060000 Subelkhal of proposed findings of fact & conclusions of law
in form of initial decision
MCQARSY, J M Duke Power Co 00/03/98 1p

dition containing findings of Part 3
used to authorize storage of
Nuclear radiological monitoring
Certificates of Use

3 initial decision due

expansion of issuance of full-term GL & commencement of initial fuel loading in late summer 1992. Certificate of Bvt. MCASSTY, J H Duke Power Co. MCASSTY, J H Bebevoise & Liberman 60405-230. See

000410017 Response in opposition to Carolina Environ Study Group
000529 proposed elements of fact & conclusions of law based
initial decision No good reason presented for not approving
application re spent fuel shipment W/ Certificate of Dis
mCANNY, J R Spoke Power Co 06/06/13 Gipp

0001/00993 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize owner spend fuel transportation to & storage at McQuillan
ACTONHILL & Hearing Branch 4 00/06/17 1p

-----B00410436 Proposed Findings of Fact & conclusions of law in form of
initial decision approving license amend to authorize Ocasio
spent fuel transportation to & storage at Hudson
proposed transcript corrections & Certificate of Doc and
B00410436 Hearing Branch 4 B00410436 159pp

003A000017 Motion For extension until 8/30/10 to respond to email @00330
motion to terminate stay of ASL 790418 initial decision &
to respond to Carolina Environ Study Group motion to admit
new contentions & to reopen record re Certification of Env
HETCHEM E D Hearing Branch 4 8/26/10 Dsp

800A240438 Order granting extension until 030710 for NRC to respond to outstanding motions in DL proceeding
LADD, R W Atomic Safety and Licensing Board Panel 03/06/19 Zpp

8006254009 Request for extension until 800707 to respond to Geraldine
Environ Study Group 800607 letters to admit new contentions
& respond re: Possibility of stipulation is being
discussed w/interim Certificate of Dvc and
HCSARRY, J. J. PORTER, H. L. Data Power Co HCSARRY, J. H. Debevoise &
Liberman 80/06/24 342

g. research reports, IE Bulletin & correspondence

8006040-427 Forwarded IE Bulletin 80-33, "Masonry Wall Design - No action or written response required IE Info Notice 79-20.
"Overloading of Structural Elements Due to Pipe Support Loads" and
D'NEILLY, J P Region 2, Atlanta, Office of the Director 80/03/80
Reo

EO04010275 Forwards IE Bulletin 00-12, "Barely Heat Removal Sys
Operability." No written response required IE Info Notice
00-05, "Loss of Barely Heat Removal Capability at Davis-Besse
Unit 1 while in Refueling Mode" encl
O'NEILL, J.F. Region 2, Atlanta, Office of the Director 00/05/07
Rdb.

0004300000 Permeada DE Circular 00-11, "Emergency Diesel Generator Lube Oil Cooler Failures." No written response required.
0000000000 J.P. Region 2, Atlanta, Office of the Director 00405/13
200

8024090640 Ack receipt of IE Insp Rep# 80-387/80-03 Re proprietary info
FASSTF-M G Duke Power Co 80/05/21 1g

--8006090561 Forwarded 1E Insp Rept 56-0357/E6-03 on 030327-0104 No
noncompliance noted
LEHIS.R C Region 2, Atlanta, Reactor Operations Nuclear Supp
Branch 80/03/01 2pg

--B00490325 DE Insp Rept 50-359/26-03 on D00227-0494 Re recommendations noted Major Areas inspected preoperational testing review of licensee response to bulletins & circulars & Followup on items from previous repts
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch
EDMUND, T J & SPARKS, R J Region 2, Atlanta, Office of the Director
20/04/20 Doc

0006100227 Ack receipt of 18 Insp Rept SO-289/80-26 No proprietary info
FBI/DOJ, O. Burke Proulx Co. 00/05/20 10

--EEO410240 Forwarded LE Insp Rept 92-067/90-06 on 004620-20. No noncompliance noted
LEADS, B C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 00/09/00 Doc

```
--000100246 IE Insp Rept 80-347/80-04 on NRC423-25 Re noncompliance#
noted Major areas inspected reactor protection sys.
operational test procedure, engineered safety features test
package & signal separation criteria implementation
HARTUNG, R D Region 2, Atlanta, Reactor Operations Nuclear Support
Branch POWELL, J. Region 2, Atlanta, Office of the Director
80/08/08B Aec.
```


DOCKETED ITEMS

185

000402003a Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-10A, "Control & Program for Nuclear Generating Stations." Revised Revision 11 included items on which equivalent education requirements will be established. PEDPLEB, D. L. Commonwealth Edison Co. 00/04/23 1p

F Security, medical, emergency & fire protection plan

000402025a Notice that new telephone was called Health Physics Network. OHM has been installed at site. Re: Intended for use during emergency to link all power plants & NRC. Emergency Notification Box will also be used. PEDPLEB, J. D. Region 3, Chicago, Office of the Director 00/04/18 5p

000402047 Forwards clarification of NRC requirements for emergency response facilities defined in 10CFR131.441 specific criteria for facilities under development. CIBREHUT, S. S. Division of Operating Reactors 00/04/20 4pp

000402055a Notice until that 0007034 safeguards contingency plan needs revision & add info details of required add info and 10CFR131.441 Licensing Branch I 00/04/20 2pp

000410029 Forwards Revision 1 to draft emergency plan. Emergency plan status annex also incl. PEDPLEB, D. L. Commonwealth Edison Co. 00/04/04 3pp

--000410034 Draft emergency plan annex
* Commonwealth Edison Co. 00/07/26 50pp

--000410034 Revision 1 to draft emergency plan
* Commonwealth Edison Co. 00/07/21 12pp

000404090a Responds to NRC 0004025.00.000-09 & 00.1000000 add info re guard training & qualification plan. Requests that response submittal date be extended to 000804. PEDPLEB, D. L. Commonwealth Edison Co. 00/06/10 1p

K Utility Final Safety Analysis Report (FSAR) & amendments

000410034a Forwards Amend 49 to FSAR, including responses to seven second round questions, voluntary back & response revisions. PEDPLEB, D. L. Commonwealth Edison Co. 00/06/05 1p

--000410034a Amend 49 to FSAR. Drawings and text
* Commonwealth Edison Co. 00/04/05 100pp

Q Inspection reports, IE Bulletins & correspondence

000404038 Forwards IE Insp Repts 50-373/80-18, 50-374/80-11, 50-454/80-04, 50-455/80-04, 50-456/80-02 & 50-457/80-02 from meeting on 000326. No noncompliance noted. PEDPLEB, J. D. Region 3, Chicago, Office of the Director 00/04/24 2pp

--000404038 IE Insp Repts 50-373/80-18, 50-374/80-11, 50-454/80-04, 50-455/80-02 & 50-457/80-02 from meeting on 000326. Areas inspected status of three statements under test. PEDPLEB, J. D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/14 4pp

000413025 Forwards IE Insp Repts 50-373/80-12 & 50-374/80-08 on 000312-12 & 00/19 & notice of violation. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/26 2pp

--000413025 Notice of violation from Insp on 000312-14 & 18-19
* Region 3, Chicago, Office of the Director 00/04/14 1p

--000413029 IE Insp Repts 50-373/80-12 & 50-374/80-08 on 000312-14 & 18-19. Noncompliance noted deficient design control per small item piping connections. PEDPLEB, J. D. Region 3, Chicago, Office of the Director 00/04/14 7pp

000417036 Forwards IE Insp Repts 50-373/80-30 & 50-374/80-13 on 000401-03 & 00.8 notice of violation. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/26 2pp

--000417036 Notice of violation from Insp on 000401-03 & 08
* Region 3, Chicago, Office of the Director 00/04/22 2pp

--000417074 IE Insp Repts 50-373/80-02 & 50-374/80-13 on 000401-02 & 08. Noncompliance noted inadequate design control, lack of work procedures & lack of 50 audits. PEDPLEB, D. L. Region 3, Chicago, Office of the Director 00/04/22 4pp

000417076 Forwards IE Insp Rept 50-373/80-14 on 000303-01. No noncompliance noted. HENSHAW, F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/03/03 2pp

--000417076 IE Insp Rept 50-373/80-14 on 000303-01. No noncompliance noted. Major areas inspected procedures, preventative test program & status on previous audit findings. PEDPLEB, D. L. Region 3, Chicago, Office of the Director 00/05/02 7pp

000419017 Forwards IE Insp Rept 50-373/80-02 on 000415-16. No noncompliance noted. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/07 2pp

--000419018 IE Insp Rept 50-373/80-02 on 000415-16. No noncompliance noted. Major areas inspected instrument line leakage & nonperformance control. HENSHAW, F. Region 3, Chicago, Office of the Director 00/05/05 3pp

000419035 Forwards IE Insp Repts 50-373/80-01 & 50-374/80-14 on 000415-16. No noncompliance noted. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/09 2pp

--000419036 IE Insp Repts 50-373/80-01 & 50-374/80-14 on 000415-16. No noncompliance noted. Major areas inspected status on previously identified items, receiving documentation for reactor vessel holddown bolts & recalibrating piping status. PEDPLEB, D. L. Region 3, Chicago, Office of the Director 00/07/09 4pp

000420014 Forwards IE Insp Rept 50-373/80-19 on 000219-20, 26-29, 0304-07 & 19-22 & notice of violation. HENSHAW, F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/03/09 2pp

--000420014 Notice of violation from Insp 000219-26, 29, 0304-07 & 19-22
* Region 3, Chicago, Office of the Director 00/05/09 4pp

--000420014 IE Insp Rept 50-373/80-19 on 000219-22, 26-29, 0304-07 & 19-22. Noncompliance noted failure to have program to maintain cleanliness & inadequate procedural requirements. HENSHAW, F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/05/09 10pp

000423035 Forwards IE Insp Repts 50-373/80-19 & 50-374/80-12 on 000401-02 & 19-17. No noncompliance noted. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/13 2pp

--000423060 IE Insp Repts 50-373/80-19 & 50-374/80-12 on 000401-03 & 19-17. No noncompliance noted. Major areas inspected reactor procedures, receipt, issue, and rad control & action on previous issues. HENSHAW, F. Region 3, Chicago, Office of the Director 00/05/09 4pp

000424038 Forwards IE Insp Repts 50-373/80-03 & 50-374/80-13 on 000402-03. No noncompliance noted. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/14 2pp

--000424041 IE Insp Repts 50-373/80-03 & 50-374/80-13 on 000402-03. No noncompliance noted. Major areas inspected suppression pool test & installation of radiation seals. HENSHAW, F. Region 3, Chicago, Office of the Director 00/05/14 4pp

000426047 Ack receipt of 000403 & 0819 letters providing addl clarification re actions taken to correct noncompliance noted in IE Insp Repts 50-373/80-03 & 50-374/80-13. FIORILLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/14 1p

--000426050 Responds to 000411 request for clarification re actions taken to correct noncompliance noted in IE Insp Repts 50-373/80-03 & 50-374/80-13. Engineering change notices will be identified in monthly A/E spec violation report. PEDPLEB, D. L. Commonwealth Edison Co. 00/04/26 4pp

- 000103522 Response to 000101 request for clarification re action taken to address noncompliance noted in IE Insp Regs 50-374/00-08 & 50-374/00-08 Engineering change notice status report will be reviewed by AE for accuracy & completeness
PEOPLE'S D. L. Commonwealth Edison Co 00/05/03 3pp
- 000103014 Forward request for info on EIR meeting of jet pump hold-down teams described in IE Bulletin 00-07
YOUNG&JONES D. J. Procedures & Test Review Branch 00/06/04 2pp
- 000103024 Ack receipt of 000024 letter informing EIR of steps taken to correct violation noted in IE Insp Regs 50-374/00-08 & 50-374/00-08
FIDELLIS, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/01 1p
- 000103036 Response to NRC 000496 letter re violation noted in IE Insp Regs 50-374/00-08 & 50-374/00-08 Corrective actions design instructions are being revised to provide clearer responsibilities & work procedures
PEOPLE'S D. L. Commonwealth Edison Co 00/05/02 2pp
- 0 Reportable occurrences, LERs & related correspondence
- 000103024 Final Part 20 report re metal head of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were cut to #234000 requirement. Investigations completed & closed at AE State facilities
BAY, J. L. Chemtron Corp. Tube Tunnels Div 00/06/04 3pp
- DOCKET 50-314 LAWALE COUNTY STATE, UNIT 3
- A Application/construction stage documents & correspondence
- 000103010 Advise BWR & PWR applicants of NRC decision to modify presentation plan proposed in Section 6 of 10000-0037 re adequacy of applicable support structures General operating review procedure & acceptance criteria and
CITRON, D. Division of Licensing 00/05/02 13pp
- 000103013 Requests info re mobile heat metal melt test type & grade, vessel process type, electrode size & number of steel layers & heat input for each layer to define potential for cracking to reactor vessel nozzle
YOUNG&JONES D. J. Licensing Branch 1 00/05/02 2pp
- 000103005 Summary of 000100 meeting w/RA's II members group re suppression pool temp response to safety/trip actions. Brief included that limit on temp met needed Requests that applicable submit detailed info for evaluation
W. T. M. Containment Systems Branch 00/05/02 4pp
- 000103028 Forward "Mark II Design Assessment Rep." Revision 2. Revision updates Chapter 6 re suppression pool temp response
PEOPLE'S D. L. Commonwealth Edison Co 00/06/02 1p
- 000103028 "Mark II Design Assessment Rep." Revision 2
* Commonwealth Edison Co 00/06/02 37pp
- 000103009 Forward trip report summary of 000102 & 25 meeting w/ Barget & Lundy. IL re wall structure interaction
BOWEN, A. Licensing Branch 1 00/06/02 3pp
- 000103009 Trip report summary of 000102 & 25 meeting w/Barget & Lundy
CHAM, S. P. Structural Engineering Branch 00/06/02 2pp
- 000103017 Forward "Fin Comment" edition of NUREG-0617 Describes technical instructions & analyses performed by IE
Comments should be forwarded to NRC by 000107 info and
BIRNBAUM, D. Division of Licensing 00/06/02 3pp
- 000103010 Submit update of scheduled commercial fuel dates re facilities reflecting delays & scheduled fuel load dates. Review importance of continued licensing process for Byron & Braidwood
PEOPLE'S D. L. Commonwealth Edison Co 00/06/02 2pp
- 000103036 Forward revised Revisions 11 & 12 consisting of Page 1-2 of CEI-A, "Core EA Program for Nuclear Generating Stations." Revised Revision 13 includes basis on which equivalent violation requirements will be established
PEOPLE'S D. L. Commonwealth Edison Co 00/06/03 1p
- F Security, medical, emergency & fire protection plans
- 000103034 Identify that new telephone wall called Health Physics Emergency (HPE) has been installed at site. HPE intended for use during emergencies to limit power plants & HPE
Emergency Notification Sign Notice will also be used
PEOPLE'S D. L. Region 3, Chicago, Office of the Director 00/04/03 2pp
- 000103017 Forward clarification of NRC requirements for emergency response facilities defined in 700013 11r add specific criteria for facilities under development
EISENBERG, S. G. Division of Operating Reactors 00/04/02 4pp
- 000103034 Notice to 000324 safeguards meeting plan needs revision & add info Details of required add info sent Reg with add 000324 7001
YOUNG&JONES D. J. Licensing Branch 1 00/06/02 2pp
- 000103020 Forward Revision 1 to draft emergency plan Emergency plan revision under review
PEOPLE'S D. L. Commonwealth Edison Co 00/06/04 2pp
- 000103024 Draft emergency plan annex
* Commonwealth Edison Co 00/07/03 50pp
- 000103047 Revision 1 to draft emergency plan
* Commonwealth Edison Co 00/07/03 13pp
- 000103049 Response to NRC 000495, 50,000.00 & 25 letter requesting add info re general training & qualification of staff Requests that response submitted date be extended to 000504
PEOPLE'S D. L. Commonwealth Edison Co 00/06/03 1p
- A Utility Final Safety Analysis Report (FSAR) & amendments
- 000103034 Forward Amend 02 to FSAR, including responses to seven second round questions/voluntary part 2 response revisions
PEOPLE'S D. L. Commonwealth Edison Co 00/06/03 1p
- 000103049 Amend 02 to FSAR Overall drawings and
* Commonwealth Edison Co 00/06/03 100pp
- 0 Inspection reports, IE Bulletin & correspondence
- 000103029 Forward IE Insp Regs 50-374/00-08, 50-374/00-11, 50-457/00-02, 50-457/00-08 & 50-457/00-02 from meeting on 000328 Re noncompliance noted
MOTLEY, J. O. Region 3, Chicago, Office of the Director 00/04/04 2pp
- 000103032 IE Insp Regs 50-374/00-08, 50-374/00-11, 50-457/00-02, 50-457/00-08 & 50-457/00-02 from meeting on 000328
BOWEN, A. Licensing Branch 1 00/06/02 3pp
- 000103025 Forward IE Insp Regs 50-374/00-08 & 50-374/00-08 on 000312-14 & 10-19 & notice of violation
FIDELLIS, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/02 3pp
- 000103027 Notice of violation from Insp on 000312-14 & 10-19
* Region 3, Chicago, Office of the Director 00/04/04 1p
- 000103027 IE Insp Regs 50-374/00-08 & 50-374/00-08 on 000312-14 & 10-19 Noncompliance noted deficient design control for wall
Bare piping suspension eye
FIDELLIS, D. Region 3, Chicago, Office of the Director
DAWLESS, D. M. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/04 7pp
- 000103036 Forward IE Insp Regs 50-374/00-08 & 50-374/00-08 on 000401-03 & 08 & notice of violation
FIDELLIS, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/04/04 2pp
- 000103034 Notice of violation from Insp on 000401-03 & 08
* Region 3, Chicago, Office of the Director 00/04/02 2pp

--8064190774 IK Insp Repts 90-373/90-20 & 90-374/90-13 on 003450-02 & 00
Noncompliance noted inadequate design control, lack of work
procedures & lack of QA audit
David L. Smith, /2661 T Region 3, Chicago, Office of the
Inspector 05/04/92 oag

000498257 Forward: IE Insp Rpts 90-373/89-21 & 90-374/89-14 on
000900-10 Re noncompliance noted
FIORELLI, J. Region 3- Chicago, Reacher Construction & Engineer
Support Branch 00/98/09 2pp

--0906190266 IE Insp Repts 50-379/50-23 & 50-394/50-14 in 800400-10 H
noncompliance noted Major areas inspected action on
previously identified items: receiving documentation for
reactor vessel holddown bolts & manipulation piping status
DAVIDILSON, D H - ERS, C H Region 3, Chicago. Office of the
Director 80/03/59 4pg

0606200058 Forwards IE Insp Repts 90-373/80-19 & 90-374/80-12 en
800491-09 & 15-17 No noncompliance noted
FISHELL 1.0 Region 3, Chicago: Reactor Construction & Engineering
Support Branch 00/03/13 gpe

--B004200060 IE Insp Repts 50-373/50-14 & 50-374/50-12 on B03401-03 & 15-17 No noncompliance noted Major areas inspected: Patrol procedures, receipt insp, use of rad control & action on previous items
WILLIAMS, C C : JOHNS, C E Region 3, Chicago, Office of the Director 05/05/97 App

8006240002 Forwarded SE Issy Repts 80-373/80-23 & 80-374/80-15 on
800430-0001 No noncompliance noted
F1008LL1.0 Repton D. Chicago, Reactor Construction & Engineer
Suspect's Branch 80/05/14 290

--606240081 DE Insp Repts 50-373/50-23 & 50-374/50-15 on 056433-6801 M
noncompliance noted Major areas tagged suppression pool
and 2 installations of radiation seals
MELLAND, C E, NEESLER, J H Region 3, Chicago, Office of the
Inspector 50/03/54 4pp

8006180747 Ack receipt of 800420 & 0915 ltr providing addl clarification re actions taken to correct noncompliance noted in IE Insp Repts 80-073/80-04 & 80-074/80-03
FIORELLI, G. Region 3, Chicago, Reactor Construction & En Support Divsion 80/04/04 1p

--B0041G0550 Responds to B0041i request for clarification re actions taken to correct nonconformance noted in IE Insp Repts
 50-373/89-04 & 50-374/89-03 Engineering change notices will be identified to monthly A/E spec status report
 #B04PLM3.D L Commonwealth Edison Co 00/04/00 4pp

--0036100552 Response to EO0411 request for clarification re actions
taken to correct misclassification noted in IE Insp Repts
80-375/80-04 & 80-374/80-03 Engineering change notice status
rept will be reviewed by AE for accuracy & completeness
PEOPLE'S P L Commonwealth Edison Co 09/03/15 Geo

6062205104 Ferwerda request for info on EHR tracking of jet pump
holdings beams described in DE Bulletin 00-07
V000000000.3 J. Procedures & Test Review Search 00/06/04 20

5004250043 Ack receipt of 500529 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-373/80-12 & 50-374/80-08
FISHERLL, S. Region 3, Chicago, Reactor Construction & Engineering Research Branch. 50/38/11 1a

--BODAS2026A Responds to NRC BODAS26 ltr re violation noted in 3E Insp
Sgts 90-273/90-12 & 90-274/90-26 Corrective actions design
instructions are being revised to provide clearer
responsibilities & work procedures
MURPHY, D.L. Commonwealth Edison Co. 80/03/29 Has

A. Reportable occurrence, LRTs & related correspondence

8034200524 Final Part 21 vapt re-rolled heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to ADSQ34 requirement. Investigations conducted & closed at 46 listed facilities.

SEAT, J. L. Chenyren Corp., Lake Tunes Div 80/04/06. Dpp

DOCKET 80-376 NORTH COAST NUC PLANT

DOCA190132 Petition urging ASL to hold evidentiary hearings to request
applicant to show cause why application should not be
dismissed due to lack of intention to build Requests costs
0 damages M/Certificate of Bus & supporting documents
PERNDS: 0 Citizens for the Conservation of Natural Resources, Inc
NO/04/00 1206

--HQ06190184 Intern rpt of Committee on Future Energy Alternatives in
Puerto Rico, by Energy Engineering Board; Assembly of
Engineering Supporting Documentation and
w National Academy of Sciences 7/21/73) Ysp

000180150 Response in opposition to Intervenor Q Farnes 000420
request for issuance of order to show cause why application
should not be dismissed No time frame requirements exist for
license processing w/certificate of Sec
AT&T Lab. N. Puerto Rico Electric Power Authority AT&T Lab. N.
Lorenstein, Neuman, Nels, Estrada & Taji DO/08/19 Epp

0604060377 Order denying © Fernos & Citizens for Conservation of
Natural Resources 00043D petition requesting evidentiary
hearings re lack of intention to build ASLB has no
authority to rule on motion for show cause under
LWR000000.D, COLLEGE F., MOLFE G J Atomic Safety and License
Board Panel DO/08/20 App

SG0400000 Order directing applicant & NRC to provide memoranda by
000420 re interveners' suspicion that applicant no longer
intends to construct facility Intervenor may respond to
NRC & applicant by 000710
RTBHP.C J Atomic Safety and Licensing Appeal Panel 00/04/04
do

DOCKET 88-082 WATERPOWERS GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

9006230100 Advises OAR & PAR applicants of HRC decision to modify implementation plan presented in Section 4 of HURD-0077 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria, etc.
ELEMNT: 3 0 Division of Licenses 80/25/20. 1200

0006300510 Forwards Ruled One requests for add info re rancher app
Request based on review of SSP & NBC guidance prior to TMD-2
accident
0006300510 Licensing Branch 2 00/05/00 32pp

000610009	Website info to clarify performance/wisap requirements of NAEC code: Section 331, in response to MEC 030207 for re PSAR Code N-symbol has been applied to Quality Group A&B Component: Blade of BL 330117 for seal AGMEL, D. S. Louisiana Power & Light Co	03/06/02	2pg.
-----------	--	----------	------

--MODEM1031a Forward 1E into Regt 10-SMR/74-01 on 740109-12 No
noncompliance noted
SEATTLE: M C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 34/01/01 App

--Gjoe110325 IE Insp Rpt 50-352/79-01 on 798097-12 No noncompliance noted Major areas inspected: safety activities re SW/GO documentation of final writing & installation of reactor vessel & NRC Class 2 code commitments.

CHARMALLA A STEWART R C Region 4, Dallas, Office of the Director 7/7/01/31 dss

800429600M Forwards request for addl info re power
control sys for PWR.
SCANDENCO, A Licensing Branch 2 NO/05/10 36p

0006306637 Forwards Savannah River Lab preliminary draft review report per 000630 telcon. Info should assist in review W/o until 000640. Power Systems Branch 00/06/92 12

F. Security, medical, emergency & fire protection plans

9308130017 Forwards clarification of NRC requirements for emergency response facilities defined in 390912 bto Adol specific criteria for facilities under development
C16088/TJ, @ @ Division of Operating Reactors 03/04/22, Also

0004240635 Forward request for addl info for NRC review of MO0129
safeguards contingency plan Encl withheld (ref 100PR2 799).
TERRICO, R L, Assistant Director for Licensing 05/06/89, 2pg

DOCKETED ITEMS

K. Utility Final Safety Analysis Report (FSAR) is amended

0004170282 Forwards Amend 9 to FSAR Amend includes small break LOCA analysis, responses to Hydrology Branch & SA Branch questions, changes to Section 2.3.2.3 & 2.3.2.4 update of Table 1-7i Overlake electrical drawings and
ASME/ASME, L. Louisiana Power & Light Co. 00/06/10 1p

--0004170289 Amend 9 to applications for LO Amend includes small break LOCA analysis, responses to Hydrology Branch & SA Branch questions, changes to Section 2.3.2.3 & 2.3.2.4 update of Table 1-7i
ASME/ASME, L. Louisiana Power & Light Co. 00/06/10 3p

--0004170293 Amend 9 to FSAR Overlake electrical drawings and
L. Louisiana Power & Light Co. 00/06/10 100pp

0004180329 Certificate for Amend 9 to FSAR on 000406
L. Louisiana Power & Light Co. 00/06/10 1p

Q. Inspection Reports, IF Bulletins & correspondence

0004000048 Forwards IE Circular 00-05, "Emergency Diesel Generator
Exhausting Oil Addition & Control Supply - No action
response required
BENTLEY, V. Region 4, Dallas, Office of the Director 00/04/01
1p

0004000050 Forwards IE Insp Rpt 00-362/00-08 on 000407-10 No
noncompliance noted
SEALE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/23 2pp

--0004000057 IE Insp Rpt 00-362/00-08 on 000407-10 No noncompliance
noted Major areas inspected: control activities safety-related
cable pulling & terminations
CHODURA, M. A. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/23 1p
BENTLEY, V. Region 4, Dallas, Office of the Director 00/04/22 4pp

0004170284 Forwards IE Insp Rpt 00-362/00-08 on 000407-10 No
noncompliance noted
SEALE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/23 2pp

--0004170219 IE Insp Rpt 00-362/00-08 on 000407-10 No noncompliance
noted Major areas inspected: control activities safety-related
cable pulling & terminations
SEALE, W. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/23 1p
CHODURA, M. A. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/22 4pp

0004040166 sub resp. re 000328 ltr in response to NRC 79/024 ltr,
confirming map approval map procedures, map designed to
determine how licensee manages licensed activities following
interviews w/personnel, findings will be sent to licensee
BENTLEY, V. Office of Inspection & Enforcement, Office of the
Director 00/05/06 2pp

--0004040149 Advice that util has reviewed NRC 79/024 ltr presenting
performance appraisal Concern expressed re interviewing
cont personnel, biased regional inspectors & documenting
noncompliance aspects
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/05 1p

0004040092 Forwards IE Bulletin 80-12, "Design Heat Removal Sys
Corrosibility" re utility response required IE Info Notice
80-25, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" and
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/09
1p

0004000097 Responds to violation noted in IE Insp Rpt 00-362/00-08
Corrective actions piping & substation inspection results & each
penetration occurred of debris openings sealed per
protection
HENDERSON, G. B. Louisiana Power & Light Co. 00/05/09 2pp

--00-362/00-11 on 000428-0008 No
Reactor Operations Nuclear Support

--00-362/00-09 No noncompliance
national staffing & overall
Region 4, Dallas, Office of the

0004000109 Responds to IE Bulletin 79-08 re possible malfunction of
MPCD limit switches MPCD limit switches are installed as
Facility Licensee has installed pipeline to locate magnet
& correct defective limit switches
ASME/ASME, L. Louisiana Power & Light Co. 00/05/14 2pp

0004000040 Forwards IE Circular 00-12, "Valve-Shop-Test-Debris May
Fall Out of Place Heat Mounted Below Horizontal Axis" re
utility response required
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/14
1p

0004100449 Act receipt re 000409 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rpt 00-362/00-08
BENTLEY, V. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/05/20 1p

R. Reportable occurrences, EDOs & related correspondence

0004000024 Final Part 21 steps to avoid heat of steel supplied by US
Steel from which 4-inch elbows & 2-inch steel were wfg to
ADNHMA requirement inspections conducted & closed at
US Steel facilities
BENTLEY, V. Region 4, Dallas, Office of the Director 00/04/06 3pp

0004100313 Final rpt of Significant Control Deficiency 7 re loose
control element drive mechanism guide cones C-6 completed
corrective repairs during unit ending 000319 Guide cones were
firmly locked in place, torque & spot welded
BENTLEY, V. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/10 3pp

0004100384 Forwards final deficiency report re loose control element
drive mechanism guide cones
ASME/ASME, L. Louisiana Power & Light Co. 00/06/10 1p

--0004100375 Final deficiency re loose control element drive mechanism
guide cones C-6 secured & tightened past guide cone to
C-10. 3 inch torque value Completed spot & lock welds visually
inspected & approved
BENTLEY, V. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/10 2pp

DOCKET 80-387 BUREAUWAGAS REACTOR ELECTRIC STATION, UNIT 1

A. Applications/Construction stage documents & correspondence

0004000049 Act receipt of 000408 ltr describing results of unit
1 investigation of specific employee concerns
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/06 1p

--0004050008 Inform NRC that investigation of 129 items mentioned in
unit 1 79/025 ltr have been completed findings & actions
taken re items investigated are available at contact site &
util general eff
BENTLEY, V. Region 4, Dallas, Office of the Director 00/04/08 1p

--0004050004 Discusses util efforts to encourage employee & control worker
feedback re concerns about quality of design, quality of
workmanship at plant Personnel were sent questionnaires which
revealed 129 specific items requiring investigation
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/05 2pp

0004100387 Advice that util has consistently maintained positive
attitude in archaeological work in control area util has
allowed surveying in 1967 & funded 1970 archaeological work
Bentley has been contacted re further survey area
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/19 1p

0004000033 Forwards request for add info re refueling platform crane
rails per review of facility application for
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/00 3pp

0004100090 Summary of 000405 site visit to review reactor sys &
instrumentation list at attending and
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/20 2pp

0004000110 Advice that util has consistently maintained positive
attitude in archaeological work in control area util has
allowed surveying in 1967 & funded 1970 archaeological work
Bentley has been contacted re further survey area
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/19 1p

0004000009 Discusses summary of Case Load Personnel Panel 000320-21 with
visit to facilities re util scheduling methods & present
problems THU impacts not included in schedule 00/04/06 review
& documentation require 4 mths
BENTLEY, V. Region 4, Dallas, Office of the Director 00/05/20 2pp

DOCKETED ITEMS

189

0004000410 Requests encl add info re instrumentation & control sys to complete review of application for OL
VOLUNTEER, J J Licensing Branch 1 00/05/27 App

0004000501 Summary of 000410 meeting w/Mark II owners group re suppression pool temp response to safety/pollut actions
Stony concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation
BUT, R Encasement Systems Branch 00/05/30 App

0004000563 Forward "For Comment" edition of NUREG-0619 Describes technical issues studies & analyses performed by BE
Comments should be forwarded to NRC by 00/07/97 Wra encl
EISENHUT, S O Division of Licensing 00/05/06 App

0004110252 Forward "Design Assessment Rept, Revision 2" Propose safety variation w/checkbox (ref 000502 700)
CURTIS, H M Pennsylvania Power & Light Co 00/04/09 App

--0004110297 "Design Assessment Rept, Revision 2," nonproprietary version
Pennsylvania Power & Light Co 00/05/31 30App

0004110041 Notification of 000410 meeting w/BNR Licensing Resolution Group at Bethesda, MD to discuss progress
HILSH, J H Licensing Branch 1 00/04/09 10pp

0004300089 Forward request for addl info re instrumentation & control sys
VOLUNTEER, J J Licensing Branch 1 00/05/10 3pp

0004300321 Summary of 000314 meeting w/utills in Bethesda, MD re organization & objectives of BNR licensing resolution group
Appendix & viewpoint encl
HILSH, J H Operating Reactors Branch 4 00/05/17 31pp

B NRC Draft/Final Environmental Statements, suppl & correspondence

0004000380 Notify that Bureau of Radiological Health, PRA, has reviewed draft suppl to 0004000380 re applicable comments
HEAVER, C L HEM, Dept of, US Public Health Service 00/05/20 1p

--0004000382 Response to NRC 730619 ltr re request for comments re draft EIS Project does not appear to represent hazard to public health & safety
SEGEL, R L Health, Education & Welfare, Dept of 73/03/09 1p

0004120031 Forward comments re draft EIS for facility Remediated that PA Fish Commission be given opportunity to comment on project
KITCHEN, A O Pennsylvania, State of 00/05/20 3pp

0004000399 Submit comments re DEB draft suppl review Clean Water Act conditions & reg practices re proposed encl Document should address Flood Hazard or Aquifers overlapping
TRIEBERMAN, H B Arng, Dept of 00/05/27 3pp

0004000397 Comments on draft suppl to EIS re facility operation Provided that still implements reg plans in construction
WPA Fish & Game Commission no objections offered re cont as proposed
BARNES, J B Intervention, Dept of 00/05/29 3pp

0004000490 Forward comments on draft suppl to OSG re NUREG-0544 Encl drawings in Central Files only
CURTIS, H M Pennsylvania Power & Light Co 00/05/29 15pp

0004000543 Forward comments on draft suppl to draft EIS re operation of facilities, specifically Draft Hill Creek Reservoir
DAVIS, R R Environmental Protection Agency 00/05/20 App

0004130030 Responds to NRC requests for comments re draft suppl to draft EIS Review indicates use of Chautauque project currently under cont would provide better water storage than building new reservoir
LINDSAY, M Federal Energy Regulatory Commission 00/04/10 App

0004170003 Forward comments on draft suppl to OCS, add comments on DEB & utill seek release draft suppl to 0004 re Pass Hill Reservoir is inadequate & incomplete New release belators containing that need for plant use inadequately assessed
HAYN, D, SAGE, T Susquehanna Alliance 00/04/10 App

F Security, Medical, emergency & fire protection plans

0005000317 Forward clarification of NRC requirements for emergency response facilities defined in 700513 ltr Add specific criteria for facilities under development
EISENHUT, S O Division of Operating Reactors 00/04/25 App

0004000519 Notification of 000410 meeting w/utills in Bethesda, MD to discuss NRC emergency preparedness requirements technical support criteria & emergency response plan criteria
BUT, R M Licensing Branch 1 00/05/30 3pp

G Adjudication correspondence

0006000407 Motion to reclassify Contentions 2-16 & 17 in public health & safety Category Response re NRC remaining interregatories re witnesses & evidential documents Certificate of Doc & supporting documentation encl
HILL, S H M V J Citizens Against Nuclear Dangers 00/04/29 12pp

0006000404 Motion requesting that applicants be required to amend DEB in form of supplemental publication that discusses consequences of various accidents Certificate of Doc encl
Related correspondence
HILL, S H M V J Citizens Against Nuclear Dangers 00/04/30 7pp

0006000254 Addl response to applicants' & NRC interregatories re compliance w/ALB 000501 memorandum & order Includes discussion re 000222 release during fuel cycle per NEPA requirements w/Certificate of Doc Related correspondence
JOHNSON, J H Environmental Coalition on Nuclear Power 00/05/01 3pp

0006000307 Supplemental answers to all First round of interregatories Alleges radiological health effects of isotopes were underestimated due to reliance on southeast sector rather than northwest sector
GELTZ, G R Susquehanna Environmental Alliance 00/05/01 App

0006000320 Forward response to First round discovery requests re supplement to applicant answers re Environ Coalition on Nuclear Power Certificate of Doc encl
000700-3 A Pennsylvania Power & Light Co 00/05/01 3pp

0006000320 Response in opposition to Citizens Against Nuclear Dangers 000429 & 30 motions & replies to interregatories Contentions remain litigious under NEPA Policy re accident analysis not set changed Certificate of Doc encl
000700-3 A Pennsylvania Power & Light Co 00/05/01 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

0006000320 Response to ALB-392 No substantial changes have been made by rulings cited in ALB-392 Intervenor is unable to proceed to interregatories due to continuous procedural harassment by NRC Certificate of Doc encl
KEPPNER, C Environmental Coalition on Nuclear Power 00/05/30 App

D Inspection reports, IE Bulletin & correspondence

0006020223 Forwards IE Insp Rpt 30-087/60-00 on 800306-07 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/11 2pp

--0006020229 IE Insp Rpt 30-087/60-00 on 800306-07 No noncompliance noted Major areas inspected pressure insp activities & recirculation age mod
TRIPP, L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCSSEANTY, R A Region 1, Philadelphia, Office of the Director 80/03/20 2pp

0006020233 Forwards IE Insp Rpt 30-087/60-00 on 800416 mgt meeting
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/09 1p

--0006020247 IE Insp Rpt 30-087/60-00 on 800416 mgt meeting Areas discussed quality-related activities during contact & preparational meeting
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCSSEANTY, R A Region 1, Philadelphia, Office of the Director 80/03/09 2pp

0006020255 Act receipt of 800417 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 30-087/79-00
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/29 1p

--0006020259 Responds to NRC 000304 ltr re violations noted in IE Insp Rpt 30-087/79-00 Corrective actions reviewed past practices & Inspector assessment of adequacy & directed QA organization to improve procedures
MAGUIRE, R Pennsylvania Power & Light Co. 80/04/17 2pp

--0006020279 Forwards IE Insp Rpt 30-087/79-00 on 790726-26, 0802-09 & 1029-09, 1102 & 06-09 & notice of violation
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/04 2pp

--0006020281 Notice of violation from Insp on 790726-26, 0802-09 & 1029-09, 1102 & 06-09
Region 1, Philadelphia, Office of the Director 80/03/03 1p

--0006020284 IE Insp Rpt 30-087/79-00 on 790726-26, 0802-09 & 1029-09, 1102 & 06-09 Noncompliance noted failure to provide independence to persons performing QA function
CARLSON, R T Region 1, Philadelphia, Office of the Director
CARTER, B Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/03 14pp

D Reportable occurrences, LERs & related correspondence

0006020285 Act receipt of 800430 ltr re PSCC cable connector deficiency Awaiting Jul 1980 final rpt.
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/14 1p

--0006020286 Advises that final deficiency rpt re damaged PSCC cable connectors will be delayed until 8/1980 as still evaluating cause & corrective actions Final rpt anticipated in Oct 1980
CURTIS, N H Pennsylvania Power & Light Co 80/04/20 2pp

0006020288 Act receipt of 800418 final deficiency rpt re Cukier Hammer B-33 substation weather Rpt will be reviewed & reviewed
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/19 1p

0006020297 Act receipt of 800520 Interim deficiency rpt re use of Isometrics to locate supports
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/05 1p

0006020314 Act receipt of 800520 Interim deficiency rpt re HMTI shell-stage transition anchors
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/05 1p

0006020361 Act receipt of 800519 Interim deficiency rpt re American Warming & Ventilation, Inc damage
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/05 1p

0006020362 Update to 800201 deficiency rpt re unauthorized welding of attachment to reactor pressure vessel Caused by human error & unclear work drawings Craftsmen & foremen instructed that welding & burning on pressure vessel is prohibited
CURTIS, N H Pennsylvania Power & Light Co 80/06/13 2pp

0006020371 Forwards final rpt of deficiency on Lintierke motor operated valve stem nut stalling
CURTIS, N H Pennsylvania Power & Light Co 80/06/10 2pp

--0006020379 Final rpt for Lintierke motor operated valve stem lock nut showing all suspect valves inspected & showed 13ra sent to all suppliers informing of potential problem
PESCH, E D - HOLLMAN, H - BURBANK, H Sachtel Power Corp (subs of Sachtel Corp) 80/06/15 2pp

0006020385 Forwards final deficiency rpt re failure to state stem lock nuts when installing Lintierke motor operators on valves
Inspect valves were identified & measures taken to inspect & state valves
CURTIS, N H Pennsylvania Power & Light Co 80/06/15 7pp

0006020391 Interim deficiency rpt re small diameter pipe bent in field, exceeding allowable quality tolerance values Caused by bending method Criteria will be established for personnel, setting limits for quality & conditions for acceptance
CURTIS, N H Pennsylvania Power & Light Co 80/06/20 2pp

0006020392 Notification of Potential Gas/leakage ER 100408 re States Co. sliding links Failure occurs in form of crack between threaded screw hole & side of Unstayed Link HMI active of date of final rpt
CURTIS, N H Pennsylvania Power & Light Co 80/06/23 2pp

DOCKET 30-398 KANSASWATMAN STRAIN ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

0006020394 Act receipt of 800405 ltr describing results of utility investigation of specific employee concerns
CURTIS, N H Region 1, Philadelphia, Office of the Director 80/05/06 1p

--0006020398 Inform NRC that investigation of 120 items mentioned in Unit 2 790428 ltr have been completed Findings & actions taken re items investigated are available at all times until general act
CURTIS, N H Pennsylvania Power & Light Co 80/04/09 1p

--0006020404 Discusses utility efforts to encourage employee & const worker feedback re concerns about quality of design/mkt or workmanship at plant Personnel were sent questionnaire which received 120 specific items requiring investigation
CURTIS, N H Pennsylvania Power & Light Co 79/06/25 2pp

0006020397 Advises that utility has consistently maintained positive attitude re archaeological work in const area Unit 2 has allowed surveying in 1967 & funded 1978 archaeological work Glibert Associates now contracted to further survey area
DITLIT, J F Pennsylvania: State of 80/05/19 1p

0006020439 Forwards request for add ltr re repelling platform crane rails per review of facility application for DL
1028061035 & J Licensing Branch 1 80/05/20 2pp

0006020402 Summary of 800008 site visit to review reactor age & Instrumentation List of attended
STRAN, R Licensing Branch 1 80/05/20 2pp

0006020419 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria noted
EISENHUT, D S Division of Licensing 80/05/20 13pp

DOCKETED ITEMS

191

0006000207 Discusses summary of Case Load Forecast Panel 000600-01 wife visit to facilities re unit scheduling methods and present problems. The aspects not included in schedule 000600 reviews and documentation require 4 sets
CURTIS, H. W. Pennsylvania Power & Light Co. 00/05/20 App

0006000018 Requests encl add info re instrumentation & control sys to complete review of application for SL
0006000018 & J. Licensing Branch 1 00/05/27 App

0006000001 Summary of 000410 meeting with/with 11 encls group re suppression plant response to safety-related situations. Being considered that limit on temp and pressure requests that applicants submit detailed info for evaluation
SLT M. Containment Systems Branch 00/05/20 App

0006000013 Forwards "For Common" edition of NUREG-0010 Describes technical issues studies & analyses performed by SE
Comments should be forwarded to NRC by 000507 N/A encl
EISENHART, D. G. Division of Licensing 00/05/06 App

0006000022 Forwards "Design Assessment Rep./Revision 2" Proprietary version withheld (ref 000600 7901)
CURTIS, H. W. Pennsylvania Power & Light Co. 00/05/09 App.

0006000027 "Design Assessment Rep./Revision 2" proprietary version
a Pennsylvania Power & Light Co. 00/05/31 205pp

0006000019 Forwards request for add info re instrumentation & control sys
0006000019 & J. Licensing Branch 1 00/04/12 App

D. NRC Draft/Final Environmental Statements; supply & correspondence

0006000000 Notify that Bureau of Radiological Health/DOH has reviewed draft EIS
0006000000-DOH No applicable comments
NEAVER, C. NRC/DOH of. US Public Health Service. 00/05/20 App

0006000002 Response to NRC 730119 re request for comments on draft EIS
EIS Project does not appear to represent hazard to public health & safety
0006000002 & L. Health, Education & Welfare. Dept. of 73/03/09 App

0006000001 Forwards comments re draft EIS for facility statements that PA State Commission is given opportunity to comment on project
REITER, A. O. Pennsylvania, State of 00/05/20 App

0006000009 Submits comments re EIS draft supply review Clean Water Act conditions & not practices re proposed dam and Damask
will address flood hazard of spillway overtopping
WILSON, R. M. E. Army/Dept of 00/05/27 App

0006000007 Comments on draft supply to EIS re facility operation
Provided that still implements not plans in consultation
w/PA Fish & Game Commission no objections offered to construction
0006000007 & J. Interior, Dept. of 00/05/29 App.

0006000009 Forwards comments on draft supply to EIS re 000600-054 Encl
drawings in Central File only
CURTIS, H. W. Pennsylvania Power & Light Co. 00/05/29 App

0006000016 Forwards comments on draft supply to draft EIS re operation of facilities specifically Pond Hill Creek Reservoir
0006000016 & S. Environmental Protection Agency 00/05/30 App

0006000008 Responds to NRC requests for comments re draft supply to draft EIS
Review indicates use of Cosmoque project currently under construction would provide better water storage than existing one reservoir
LINDSEY, M. H. Federal Energy Regulatory Commission 00/06/10 App

0006000009 Forwards comments on draft supply to EIS re 000600-054 Encl
to still release draft supply to EIS re Pond Hill Reservoir
is inadequate & incomplete. Now release letters
conclusion that need for plant was inadequately assessed.
NANON, S. ADEP. B. Buckman Alliance 00/06/10 App

F. Security, medical, emergency & fire protection plans

0006000017 Forwards clarification of NRC requirements for emergency response facilities defined in 700013 for Add specific criteria for facilities under development
EISENHART, D. G. Division of Operating Reactors 00/04/25 App

0006000018 Notification of 000600 meeting w/with in Bethesda, MD to discuss NRC emergency preparedness requirements/technical support re criteria & emergency response plan criteria
0006000018 & J. Licensing Branch 1 00/05/30 App

G. Adjudicatory correspondence

0006000017 Motion to Relieve Contention 2, 3 & 17 re public health & safety category Responses re NRC remaining interrogatories re witnesses & evidence re documents Certificate of Doc & supporting documentation encl
HILLMAN, T. J. Citizens Against Nuclear Danger 00/04/29 App

0006000018 Motion requesting that applicants be required to amend EIS in form of supplemental publication that discusses consequences of various accidents Certificate of Doc encl
Related correspondence
HILLMAN, T. J. Citizens Against Nuclear Danger 00/04/30 App

0006000024 Add responses to applicants' & NRC interrogatories to compliance w/SL 000327 memorandum & order includes
discussions re 000327 responses during final customer NRC requirements w/Certificate of Doc Related correspondence
0006000024 & J. Environmental Coalition on Nuclear Power 00/05/01 App

0006000007 Supplemental answers to unit final round of interrogatories
Alleged radiological health effects of isotopes were underestimated due to reliance on southeast sector rather than northeast sector
0006000007 & R. Sequema Environmental Advocates 00/05/01 App

0006000020 Forwards response to final round discovery requests as supplement to applicant answers to Environ Coalition on Nuclear Power Certificate of Doc encl
0006000020 & L. Pennsylvania Power & Light Co. 00/05/01 App

0006000023 Response re Application to Citizens Against Nuclear Danger 000429 & 30 motions & replies to interrogatories/Contentions remain litigable under NRC Policy re accident scenario not yet changed Certificate of Doc encl
HILLMAN, T. J. Pennsylvania Power & Light Co. HILLMAN, T. J. Allegheny Electric Cooperative, Inc. HILLMAN, T. J. Shaw Pittman, Porter & Trevethick 00/05/14 App

0006000027 Supply to responses re applicants' interrogatories/Interrogatories
0006000027 & J. Application to Citizens Against Nuclear Danger 4 should be included as integral part of responses re Interrogatories w/Certificate of Doc Related correspondence
0006000027 & J. Environmental Coalition on Nuclear Power 00/05/29 App

0006000020 Response to ALAB-993 No substantial changes have been made by findings cited in ALAB-993 Interrogatories to be unable to respond to interrogatories due to continuous procedural harassment by NRC Certificate of Doc encl
0006000020 & J. Environmental Coalition on Nuclear Power 00/05/30 App

0006000026 Responses to make limited appearance statement at licensing hearing
HILLMAN, T. J. Application to Citizens Against Nuclear Danger 00/05/30 App

0006000031 Response to ALAB 000327 memorandum & order ALAB-993 re Environ Coalition on Nuclear Power allegations of extreme harassment in discovery
Interrogatory has not provided valid basis for blanket protective orders Certificate of Doc encl
CURTIS, H. W. Hearing Branch 3 00/06/12 App

0006000048 Response to ALAB 000327 memorandum & order ALAB-993 re
renewing Environ Coalition on Nuclear Power to inform ALAB of extent of relief sought Interrogatory 000327 request may be dismissed as moot
Certificate of Doc encl
TRAVES, D. D. Pennsylvania Power & Light Co. TRAVES, D. D. Allegheny Electric Cooperative, Inc. TRAVES, D. D. Shaw Pittman, Porter & Trevethick 00/06/13 App

0006000028 Memorandum & order grouping Citizens Against Nuclear Danger Contentions 2, 3 & 17 w/Interrogatory concerning Interrogatory requests for supplies to EIS for clarification & for extension
0006000028 & J. Atomic Safety and Licensing Board Panel 00/05/29 App

H. Reportable occurrences, LBRs & related correspondence

0006000019 Ack receipt of 000600 Final deficiency report to Outlier Number 0-30 prohibition notices that will be provided & evaluated
0006000019 & J. Philadelphia, Reactor Construction & Engineering Support Branch 00/05/19 App

DOCKETED ITEMS

8004200232 Ack receipt of 8004203 Interim deficiency rept re cable
pulling activities
CARLSBERG T Region 1, Philadelphia, Emergent Construction &
Engineering Support Branch 08/05/20 1p

0506200000 Ack receipt of 050400 interim deficiency rept. re separation criteria for electrical equipment Rept will be reviewed & evaluated
CARLSON, R T Region 8, Philadelphia, Swenar Construction & Engineering Support Branch 05/05/01 1p

950409038 Interview deficiency re: re pipe supports to contained
liner plate installation of supports was having civil design
group review structural adequacy resulted in overstressing
liner plate

8084625099 Ack receipt of 800520 interim deficiency report re use of
Isomeries to locate supports
CARLSON, H T Region 1, Philadelphia. Reiter Construction &
Engineering Support Branch 80/06/06 UP

0006250414 Ask receipt of 800320 interim deficiency report re HMT
shell-type expansion anchors
CARLETON, E Region 2, Philadelphia, Reactor Construction &
Engineering Support Branch 80/0A/Cb IP

804200044 Ask receipt of #80389 interim deficiency report re American
Manning & Ventilation, Inc. dampers
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch. #8/24/95. 12

0006200171 Forwards final rept of deficiency on LinCherque water operated valve stem not stating

--REDACTED Final repch for LimitGorge water operated valve when lock out
stalling. All suspect valves inspected & stated GTS sent to
all suppliers informing of potential problem
POWER & C. MOLLINS & S. N. SUMMERS Sektco Power Corp. Incub
of Rept. 10-1-80

800200336 Forward Final deficiency rept vs failure to state stem loc
aids when installing Lemniscas mbar operators on valves
Suspect valves were identified & measures taken to snap
or stake valves.
CURTIS N W Pennsylvania Power & Light Co 80/04/16 Jim

DD04270321 Interior deficiency rept re small diameter pipe bent in field,exceeding allowable ovality tolerance values Caused by bending method Criteria will be established for personnel setting limits for ovality & conditions for acceptance CUSTIS,M W Pennsylvania Power & Light Co 60264/250 204

8006270342 Notifies of Potential Deficiencies ER 100650 & ER 100500 re
Status Co sliding links failure occurs on form of crack
between threaded struts & side of Unshaped 15th Hill
advice of date of final report
CURTIS, M. Presumably Power & Light Co. 80/06/23 250

SECRET 50-369 BT LUCHE PLANT, UNIT 2

A. Application/construction stage documents & correspondence

0006640202 Ratification of contract extension-Med 1 to "Engineering Assistance re Antitrust Hearings for St. Louis 2 Nuclear Generating Station - Contractor JR Lusk & Associates
CLJ00LA, A P Administrative Contracts Branch NRC-20-00-00-000
00/03/20 1p

```
--006160034 No4 1. extending period of performance to "Engineering
Assistance re Antitrust Hearings for 30 Lucie 2 Nuclear
Generating Station "
EDWARD RYAN, D W Technical Assistance Contracts Branch
NR-00-77-185 00/03/06 to
```

Re Application to amend CPFR-144, transferring partial
title & site to City of Orlando, FL & Orlando
a. Info for additional review also sent
F&B Power & Light Co. 05/06/12 Is

--0036479273 Application to amend CPPI-144, transferring partial co-th
of facility & site to City of Orlando, FL & Orlando Utility
Commission (supportive financial nots, contracts & amend fee
sct)
ADAMW, E & Florida Power & Light Co ADAMS, II, B. Allgood M
Orlando, FL 8006/13 0826

• Security, medical, emergency & fire protection alarm

sg06190301 Forwards security plan-Revision 2
Plan withheld (ref 10CFR 7701
10010.2 E Florida Power & Light Co 03/06/10 1

0004250030 Forwards safeguards contingency plan. Revision 1.04 page 11
to NRC 000410 request for add info Revision 1/10/04
104 10CP12 7900
000310, S. E. Florida Power & Light Co. 000410/104 to

8. *Phylogenetic relationships*—A phylogenetic tree was constructed using the maximum parsimony method with 1000 random addition replicates and 1000 pseudoreplicates. The tree was rooted with *Phytophthora* as the outgroup. Bootstrap values were calculated using 1000 pseudoreplicates.

0006170267 Forwards application to amend EPN-644, transferring partial ownership of facility & site to City of Orlando, FL, & Gracen
UNCL Commission Info for anti-trust review also encl
UNCL R.E. Orlando, Revue & Lobb Co. 0006170267

==0006170273 Application to amend CPYS-144,transferring partial control
 of facility & site to City of Orlando,FL & Orlando Utility
 Commission supportive financial matl,contracts & amend fee
 recd
 ADORAT, E A Florida Power & Light Co ADORAT, E A HULEN, J M
 Orlando,FL 80/06/13 21745

000420037M Forward: Parts A & B of info requested in Reg Guide 9-2 J-6
consists of BEG prospectus, annual report, rate schedules,
interchange agreements, spinning & installed reserve info &
main schedule info available in Central Files
UNION E Florida Power & Light Co 80/266/IN 1a

4. Insurance & indemnity information

0000000000 Forwards Enclosures US to NGLIA Policy NP-227
FIELDER, J. Marsh & McLennan, Inc., N & M Nuclear Consultants, Inc.

803468113 Forwards Entersment 28 Le HNELJ Facility NY-88
F1ELDER, J. Hersh & McLenman, Inc. - H A H Nuclear Consultants, Inc
Div 80/06/09 Zpp

FD-302a (Rev. 11-27-2010)

000617D-0912 Forwards executed settlement agreement between City of
Orlando, FL, Orlando Utility Commission & will providing for
transfer of 000612 ownership share of facilities to Utility
Commission Application for NRC approval will be submitted
FOURMIGHT, J A Lounsbain, Neuman-Hess, Asplund & Tall 00/06/12
12

-----G805170479 Settlement agreement between City of Orlando, FL, Brian
Utilities Commission & e411 providing for transfer of 6 GPRS12
ownership share to Utilities Commission Release & Certificate
of Doc exec
* Orlando Utilities Commission ADVMS: H G Orlando, FL *
Florida Power & Light Co 05/06/05 2:30p

6006170267 Forwards application to amend CRR-144, transferring partial ownership of Facility 4 site to City of Orlando, FL, & Orlando Utilities Commission info for any/other review also mail UMID, R E Florida Power & Light Co. 03/06/13 to

ADDPAT, S A Florida Power & Light Co ADAMS, H S, MILLER, O N
Orlando, FL 80/86/13 387ee

0006240137 Notice by Orlando Utility Commission to withdraw intervention
 & request to institute proceedings re Commission 780727
 order City of Orlando-petitioner & utility 000600 settlement
 resolved issues Maffiorini & Certificate of Use
 WIDE-H C Orlando, FL 00/06/02 ddp

8006240466 Not: Files that antitrust info submitted 800613 re City of
Orlando, FL to Orlando Utils Commission is acceptable for
marketing & distribution
N80606000.P Utility Finance Branch 80/06/20 1a

DOCKETED ITEMS

193

--8004040472 Ack receipt of ambient info received 80040319 re City of Orlando, FL & Orlando Utility Commission Request that appropriate notice be published as soon as possible NRC/60/00/00 Utility Finance Branch 80/06/30 1p

8004030020 Forwarded info re all 8004009 application seeking amendment of CP to include City of Orlando, FL & Orlando Utility Commission as co-sponsors of Unit Data sent to Orlando SOI opportunity to request advice per 1984 Atomic Act info re: GANPH, R. K. Office of the Executive Legal Director 80/06/06 1p

G Inspection reports, IE Bulletins & correspondence

8004030423 Forwarded IE Insp Rept 80-389/80-03 on 8004002-04 No noncompliance noted NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp

--8004030405 IE Insp Rept 80-389/80-03 on 8004002-04 No noncompliance noted Major areas inspected correct progress, inspection findings/deficiencies identified items & IE Bulletin 79-02, 79-25 & 79-26
NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/24 2pp

8004030709 Forwarded IE Insp Rept 80-389/80-04 on 8004002-11 No noncompliance noted
NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp

--8004030704 IE Insp Rept 80-389/80-04 on 8004002-11 No noncompliance noted Major areas inspected welding activities, radiographic inspection, portable shop & followup of noncompliance
NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp

8004040000 Forwarded IE Bulletin 80-11, "Passing Wall Design" No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" re: 1
NRC/60/00/00 Region 2, Atlanta, Office of the Director 03/05/00 2pp

8004040074 Forwarded IE Bulletin 80-32, "Decay Heat Removal System" re: 1
NRC/60/00/00 Region 2, Atlanta, Office of the Director 03/05/00 2pp

8005000107 Forwarded IE Circular 80-31, "Emergency Diesel Generator Load Control Failures" No written response required
NRC/60/00/00 Region 2, Atlanta, Office of the Director 03/05/13 2pp

8004040013 Ack receipt of 800108.0321 & 800110s Informing NRC of steps taken to correct violations noted in IE Insp Repts 80-389/79-25, 80-389/79-26, 80-389/79-27, 80-389/79-28
NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 1p

--8004040021 Response to NRC 79/219 re violations noted in IE Insp Repts 80-389/79-25, 80-389/79-26, 80-389/79-27, 80-389/79-28
Corrective actions QA procedures will be revised until compliance achieved re 800201
NRC/60/00/00 Florida Power & Light Co 80/05/01 1p

--8004040033 Response to NRC 79/219 re 800202 re violations noted in IE Insp Repts 80-389/79-25, 80-389/79-26, 80-389/79-27, 80-389/79-28
Corrective actions QA procedures will be revised re implementation of 10CFR21
NRC/60/00/00 Florida Power & Light Co 80/03/02 3pp

G Reportable occurrences, LERs & related correspondence

8004030073 Forwarded PM-11-80-104 re 8004011 loss of component cooling water to reactor coolant pumps NRC will supplement IE. 10CFR21 but VVO technology re loss of cooling water to cartridge seal assembly
PATON, D. H. Hearing Branch 4 80/06/13 1p

--8004030077 PM-11-80-104 on 8004011 experienced loss of component cooling water to reactor coolant pumps caused by control solenoid failure on isolation valve. Cooling water returned. Investigative underway Press release will be issued
NRC/60/00/00 Region 2, Atlanta, Office of the Director 80/06/11 1p

SECRET SO-INFO NRC HAS NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8005020310 Advisory DMR & PM applicants of NRC decision to notify inspection plan provided in Section 4 of NRC-2077 re adequacy of applicable safety structures. General operating reactor review procedure & acceptance criteria re: 1
EISENHART, S. G. Division of Licensing 80/05/20 10pp

8005030031 Forwarded revised responses to Questions Q01, Q27, Q40 & Q31 124 of NRC 700001 ltr re seismic qualification of Class IE electrical equipment Repts re cable samples & 166K-203-172K qualification re: 1
MILLER, L. H. Tennessee Valley Authority 80/06/20 10pp

--8005030247 "Weight Pneumatic Test Procedure" re: 1
LEHMAN, S. Comp. Inc. & Ballo Systems Div 75/05/10 2pp

--8005030400 "Radiation Testing of Cell Number 695-Final Rept" re: 1
WILLIS, D. E. TR Corp 79/06/20 7pp

--8005030402 "Seismic Vibration Test of EIO Series Transmitters" re: 1
SEARS, J. A., HOSKINS, K., ARNOLD, R. Action Environ. Testing Corp 76/03/02 20pp

--8005030411 "Test Procedure for Seismic Vibration Qualification Test of EIO Series PGA/BBB Transmitters" re: 1
SEARS, J. A., HOSKINS, K., ARNOLD, R. Action Environ. Testing Corp 73/09/30 10pp

--8005030422 "Seismic & Differential Pressure Transmitters Type EIO Series" re: 1
SEARS, J. A., HOSKINS, K., ARNOLD, R. Action Environ. Testing Corp 73/09/30 10pp

--8005030424 "Qualification Test of Electrical Cables Under Simulated LOCA/BBB Re Sequential Exposure to Environments of Radiation Thermal Aging, Steam & Chemical Spray" re: 1
TAMM, D. E. Inc. Index of Hazardous Exposures, Inc 78/05/30 42pp

F Security, medical, emergency & fire protection plans

8005100017 Forwarded clarification of NRC requirements for emergency response facilities defined in 10CFR21 ltr Add specific criteria for facilities under development
EISENHART, S. G. Division of Operating Reactors 80/04/28 41pp

8006040094 Forwarded add info to training & qualification plan info withheld per 10CFR21 201
MILLER, L. H. Tennessee Valley Authority 80/06/02 2pp

G Inspection reports, IE Bulletins & correspondence

8006030092 Forwarded IE Insp Rept 80-390/80-05 on 800301-0320 No noncompliance noted
LEHMAN, S. G. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/21 2pp

--8006030093 IE Insp Rept 80-390/80-07 on 800301-0320 No noncompliance noted Major areas inspected correct verification, QA transfers & inspection familiarization
DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/21 2pp

8006030200 Forwarded IE Insp Repts 80-390/80-11 & 80-391/80-08 on 8004011 No noncompliance noted
NRC/60/00/00 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp

--8006030204 IE Insp Repts 80-390/80-11 & 80-391/80-08 on 8004011 No noncompliance noted Major areas inspected correct verification, QA transfers & inspection familiarization
DANCE, H. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/29 2pp

8006030307 Forwarded IE Bulletin 80-11, "Passing Wall Design" No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" re: 1
NRC/60/00/00 Region 2, Atlanta, Office of the Director 03/05/00 2pp

DOCKETED ITEMS

195

000420204 Submits addl info re 000213 Final deficiency rept re welds
sponsored by GE All noncompliance repts received & 20
inspections found no failure to comply w/operational
requirements. Ins. instances occurred after QA training given
MILLER, L. H. Tennessee Valley Authority 00/05/00 1p

V. Operator Examination

000420201 Addl exam of 000514 1st requesting review of addl training
for future applicants for licenses. CONCUR approved as
licensee not senior operators at Sequoyia for participation
in licensed personnel at Hatch 2st
000420201 A. Licensing Branch 2 00/05/00 3pp

DOCKET 00-091 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

000420202 Forwards application for license to receive, possess & store
assembled fuel assemblies & up to 100 loose fuel rods at Facility
MILLER, L. H. Tennessee Valley Authority 00/05/03 3pp

000420203 Application for license to receive, possess & store assembled
fuel assemblies & up to 100 loose fuel rods at Facility
M. Tennessee Valley Authority 00/05/03 2pp

0004202010 Advises 2st & 3rd applications of NRC decision to modify
implementation plan presented in Section 4 of JUNE03077 re
adequacy of applicable support structures General operating
reactor review procedure & acceptance criteria and
EISENHUT, J. S. Division of Licensing 00/05/00 73pp

0004202037 Forwards revised responses to Questions Q3, Q27, Q40 &
Q33 125 of NRC 700001 1st re automatic qualification of Class
II electrical equipment Repts re cable samples & IEEE-323
qualification and
MILLER, L. H. Tennessee Valley Authority 00/05/03 10pp

00042020377 "Seismic Pneumatic Test Procedure"
LEWIS, D. Comp. Inc. - Seismic Systems Div 70/04/00 2pp

0004202040 "Radiation Testing of Cell Number 1003 Final Rept"
MILLER, L. H. INT Corp 77/05/03 7pp

0004202049 "Seismic Vibration Test of EIO Series Transmitters"
BEARS, J. A., ROSSLAND, R., RUMBLE, F. Acton Environ Testing Corp
74/03/88 35pp

00042020414 "Test Procedure for Seismic Vibration/Qualification Test of
EIO Series RDA/SS Transmitters"
BEARS, J. A., ROSSLAND, R. S. Acton Environ Testing Corp 73/09/88
35pp

00042020422 "Seismic & Differential Pressure Transmitters Type EIO Series"
ROWE, R. W., GABRIEL, H., TOLP, R. L. Acton Environ Testing Corp
73/10/81 10pp

00042020429 "Qualification Test of Electrical Cables Under Simulated
LOCA/GSE by Sequential Exposure to Environments of Radiation,
Thermal Aging/Steam & Chemical Spray"
E. Insulin, Inc. (subs of Macfield Enterprises, Inc.)
70/05/80 42pp

F. Security, medical, emergency & fire protection plans

0005103017 Forwards clarification of NRC requirements for emergency
response facilities defined in 70001 1st Addl specific
criteria for facilities under development
EISENHUT, J. S. Division of Operating Reactors 00/04/00 41pp

0004202006 Forwards fuel storage physical security plan withheld
(ref 10098 700)
MILLER, L. H. Tennessee Valley Authority 00/05/00 2pp

0004202094 Forwards addl info re training & qualification plan info
withheld (ref 10098 700)
MILLER, L. H. Tennessee Valley Authority 00/05/02 2pp

G. Inspection reports, IE Bulletin & correspondence

000420200 Forwards IE Insp Repts 00-090/00-11 & 00-091/00-08 on
000409-11 re noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/00 2pp

000420200 IE Insp Repts 00-090/00-11 & 00-091/00-08 on 000409-11 re
noncompliance noted Major areas inspected pipe supports
insufficient extension bolts per IE Bulletin 79-20,
MORTT, A. B. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 000409-11 Region 2, Atlanta, Office of the
Director 00/04/00 3pp

0004202009 Forwards IE Bulletin 00-11, "Theory Mail Design" No action
on written response required IE Info Notice 79-20,
"Downloading of Structural Elements Due to Pipe Support
Loaders" and
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/00
2pp

0004202027 Forwards IE Bulletin 00-10, "Decay Heat Removal Sys
Operability" No written response required IE Info Notice
00-20, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" and
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/00
2pp

0004202044 Forwards IE Insp Repts 00-090/00-10 & 00-091/00-09 on
000409-11 re noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/00 2pp

0004202027 IE Insp Repts 00-090/00-10 & 00-091/00-09 on 000409-11 re
noncompliance noted Major areas inspected preservice insp,
welding records & worker controls
MORTT, A. B. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 000409-11 & COLEY, J. L. Region 2, Atlanta, Office
of the Director 00/05/00 7pp

0004202012 Forwards IE Insp Repts 00-090/00-12 & 00-091/00-09 on
000409-11 re noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/00 2pp

0004202018 IE Insp Repts 00-090/00-12 & 00-091/00-09 on 000409-11 re
noncompliance noted Major areas inspected 001750 SS items,
IE Bulletin & circulars, QA audits & general coast
activities
MORTT, A. B. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 000409-11 Region 2, Atlanta, Office
of the Director 00/05/00 4pp

0004202030 Ack receipt of 000601 1st Informing NRC of steps taken to
correct violations noted on IE Insp Repts 00-090/00-08 &
00-091/00-08
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/00 2pp

0004202030 Responds to NRC 000324 1st re violations noted in IE Insp
Repts 00-090/00-08 & 00-091/00-08 Corrective action
engineering unit supervisors directed to develop insp
programs for all safety-related features re fill weld
MILLER, L. H. Tennessee Valley Authority 00/05/00 3pp

0004202024 Forwards requests for relief from AMR Section 31 preservice
& inservice insp requirements for facility, TVA will revise
preservice & inservice insp program to reflect exceptions.
Requests comments by 000202
MILLER, L. H. Tennessee Valley Authority 00/05/00 14pp

0004202024 Forwards response to IE Bulletin 00-20 re vacuum conditions
resulting in damage to holdup tanks Pressure protection for
refueling water storage tank at Sequoyia & Hatch Bar is
provided by redundant heaters & tank insulation
MILLER, L. H. Tennessee Valley Authority 00/05/00 8pp

D. Reportable occurrences, LERs & related correspondence

0004202022 Forwards Final deficiency rept re temp effect on main
steam safety valve setpoint
MILLER, L. H. Tennessee Valley Authority 00/05/02 1p

0004202028 Final deficiency rept re temp effect on main steam safety
valve setpoint Ambient temp affects steam generator heat
Valve main temp adjusted by exhaust fan thermostat added
to valve room to limit temp range to 60-120 F
M. Tennessee Valley Authority 00/05/02 1p

0004202028 Forwards final interim deficiency rept re safety injection
sys Train B Pilot deficiency Rept re to be filed by 000404
MILLER, L. H. Tennessee Valley Authority 00/05/00 1p

0004202025 Final interim deficiency rept re 2nd pump motor vsc factor
AMR pump motors exceeded allowable vsc factor of 5.10 during
low flow operational mode. Flow restrictions added in each
AMR pump hot leg & cold leg injection header
M. Tennessee Valley Authority 00/05/00 1p

6026063484 Forwards. Final deficiency rept re shock arrester struts
assembly interference
4814-01-44 Reference: Natick Laboratory, 60-00100, 60-00101, 60-00102, 60-00103, 60-00104, 60-00105, 60-00106, 60-00107, 60-00108, 60-00109, 60-00110, 60-00111, 60-00112, 60-00113, 60-00114, 60-00115, 60-00116, 60-00117, 60-00118, 60-00119, 60-00120, 60-00121, 60-00122, 60-00123, 60-00124, 60-00125, 60-00126, 60-00127, 60-00128, 60-00129, 60-00130, 60-00131, 60-00132, 60-00133, 60-00134, 60-00135, 60-00136, 60-00137, 60-00138, 60-00139, 60-00140, 60-00141, 60-00142, 60-00143, 60-00144, 60-00145, 60-00146, 60-00147, 60-00148, 60-00149, 60-00150, 60-00151, 60-00152, 60-00153, 60-00154, 60-00155, 60-00156, 60-00157, 60-00158, 60-00159, 60-00160, 60-00161, 60-00162, 60-00163, 60-00164, 60-00165, 60-00166, 60-00167, 60-00168, 60-00169, 60-00170, 60-00171, 60-00172, 60-00173, 60-00174, 60-00175, 60-00176, 60-00177, 60-00178, 60-00179, 60-00180, 60-00181, 60-00182, 60-00183, 60-00184, 60-00185, 60-00186, 60-00187, 60-00188, 60-00189, 60-00190, 60-00191, 60-00192, 60-00193, 60-00194, 60-00195, 60-00196, 60-00197, 60-00198, 60-00199, 60-00200, 60-00201, 60-00202, 60-00203, 60-00204, 60-00205, 60-00206, 60-00207, 60-00208, 60-00209, 60-00210, 60-00211, 60-00212, 60-00213, 60-00214, 60-00215, 60-00216, 60-00217, 60-00218, 60-00219, 60-00220, 60-00221, 60-00222, 60-00223, 60-00224, 60-00225, 60-00226, 60-00227, 60-00228, 60-00229, 60-00230, 60-00231, 60-00232, 60-00233, 60-00234, 60-00235, 60-00236, 60-00237, 60-00238, 60-00239, 60-00240, 60-00241, 60-00242, 60-00243, 60-00244, 60-00245, 60-00246, 60-00247, 60-00248, 60-00249, 60-00250, 60-00251, 60-00252, 60-00253, 60-00254, 60-00255, 60-00256, 60-00257, 60-00258, 60-00259, 60-00260, 60-00261, 60-00262, 60-00263, 60-00264, 60-00265, 60-00266, 60-00267, 60-00268, 60-00269, 60-00270, 60-00271, 60-00272, 60-00273, 60-00274, 60-00275, 60-00276, 60-00277, 60-00278, 60-00279, 60-00280, 60-00281, 60-00282, 60-00283, 60-00284, 60-00285, 60-00286, 60-00287, 60-00288, 60-00289, 60-00290, 60-00291, 60-00292, 60-00293, 60-00294, 60-00295, 60-00296, 60-00297, 60-00298, 60-00299, 60-00300, 60-00301, 60-00302, 60-00303, 60-00304, 60-00305, 60-00306, 60-00307, 60-00308, 60-00309, 60-00310, 60-00311, 60-00312, 60-00313, 60-00314, 60-00315, 60-00316, 60-00317, 60-00318, 60-00319, 60-00320, 60-00321, 60-00322, 60-00323, 60-00324, 60-00325, 60-00326, 60-00327, 60-00328, 60-00329, 60-00330, 60-00331, 60-00332, 60-00333, 60-00334, 60-00335, 60-00336, 60-00337, 60-00338, 60-00339, 60-00340, 60-00341, 60-00342, 60-00343, 60-00344, 60-00345, 60-00346, 60-00347, 60-00348, 60-00349, 60-00350, 60-00351, 60-00352, 60-00353, 60-00354, 60-00355, 60-00356, 60-00357, 60-00358, 60-00359, 60-00360, 60-00361, 60-00362, 60-00363, 60-00364, 60-00365, 60-00366, 60-00367, 60-00368, 60-00369, 60-00370, 60-00371, 60-00372, 60-00373, 60-00374, 60-00375, 60-00376, 60-00377, 60-00378, 60-00379, 60-00380, 60-00381, 60-00382, 60-00383, 60-00384, 60-00385, 60-00386, 60-00387, 60-00388, 60-00389, 60-00390, 60-00391, 60-00392, 60-00393, 60-00394, 60-00395, 60-00396, 60-00397, 60-00398, 60-00399, 60-00400, 60-00401, 60-00402, 60-00403, 60-00404, 60-00405, 60-00406, 60-00407, 60-00408, 60-00409, 60-00410, 60-00411, 60-00412, 60-00413, 60-00414, 60-00415, 60-00416, 60-00417, 60-00418, 60-00419, 60-00420, 60-00421, 60-00422, 60-00423, 60-00424, 60-00425, 60-00426, 60-00427, 60-00428, 60-00429, 60-00430, 60-00431, 60-00432, 60-00433, 60-00434, 60-00435, 60-00436, 60-00437, 60-00438, 60-00439, 60-00440, 60-00441, 60-00442, 60-00443, 60-00444, 60-00445, 60-00446, 60-00447, 60-00448, 60-00449, 60-00450, 60-00451, 60-00452, 60-00453, 60-00454, 60-00455, 60-00456, 60-00457, 60-00458, 60-00459, 60-00460, 60-00461, 60-00462, 60-00463, 60-00464, 60-00465, 60-00466, 60-00467, 60-00468, 60-00469, 60-00470, 60-00471, 60-00472, 60-00473, 60-00474, 60-00475, 60-00476, 60-00477, 60-00478, 60-00479, 60-00480, 60-00481, 60-00482, 60-00483, 60-00484, 60-00485, 60-00486, 60-00487, 60-00488, 60-00489, 60-00490, 60-00491, 60-00492, 60-00493, 60-00494, 60-00495, 60-00496, 60-00497, 60-00498, 60-00499, 60-00500, 60-00501, 60-00502, 60-00503, 60-00504

```
--0006060409 First deficiency rep'd re check arrester strut assembly
Interference Assembly does not provide sufficient clearance
for arrester to function freely when installed at off-grid
angle greater than 80 degrees Assemblies will be replaced
* Tennessee Valley Authority 80405VCO in
```

000610026 Forwards Final deficiency report re Muskin fire dumpsite
HILLS, L. H. Tennessee Valley Authority 08/06/00 sp

--0000110043 First deficiency report re Rustlin fire dampers Rustlin has developed alternate fire providing positive shop for spring & snap-in work ensuring complete closure made will be completed by 0000110043 drawings and Tennessee Valley Authority 00/04/03 Jon

000470820 Third Informal deficiency report re control and drug events
yielding less conservative SNRs. Review of corrective
actions recommended by Westinghouse underway. Next report to be
submitted by 000900
MILLER, M Tennessee Valley Authority 00/04/04 10

0000170439 Forward revision to 000007 final deficiency rept re keep
effect of main steam valve setpoint
HDLB.E.H. Tennessee Valley Authority, Memphis, TN

--B006170672 Revision to B00527 final deficiency rept re temp effect of
main steam valve seatplug heating,ventilation & air
conditioning sys for valve room being modified to provide
maintainer temp range of 80-120 F
* Tennessee Valley Authority, B00527, to

SC06240493 P1P6 Interim deficiency repg re refueling water storage tank overflow line not fabricated to ASME code Pittsburgh-Dow Poines Steel Co will presently discussing repairs Next rept will be submitted by SC06240493

0036246307 Second Interon deficiency might re UNI hydraulic- isolation valve accumulator weighting sgs Review of mod proposed by Hawthorne is not complete Addl info will be supplied by Hawthorne

EO08240390 Forwards second interim deficiency report breakdown in
Bravo QA program
HOLLIS, M Tennessee Valley Authority 89/05/12 1a

4--B006040397 Second interim deficiency report re Spentolone in Grava M program caused by lack of documentation APPS code was installed Grava M still are reviewing radiographic film of all shop & field units for Class 1 & 2 piping
W Tennessee Valley Authority B0060419 14

00062588YD Third turbine deficiency kept re steam generator water
level ref column error 0411 16 investigating feasibility of
initially installing temp compensation & set stabilizing
insulation for Sequoyah 2 & Watts Bar
MILLS L M Tennessee Valley Authority 80/04/20 Doc

0006293024 Submits addl info for 200210 final deficiency rpt re wsl
agreed by OC All nonperformance rpt, reviewed & 20
instances found of failure to comply w/procedural
requirements Two instances occurred after 04 training given
HILL/L.H. Tennessee Valley Authority 00/06/02 ls

U. Gerdorf/OT-Exam/2016/1

000204151 Ask receipt of B00416 re requesting review of addl training
for future applicants for license. Concern w/ proposal to
license nine senior operators at Georgetown for participation
as licensed personnel at Watts Bar
B00416CER.A Licensing Branch 2 C/D D/R/CO Doc

DOCKET No. 492 CHIN-ISHAM POWER REACTOR, UNIT 1

P. Operating license stage documents & correspondence

0004120910 Application for Amend 4 to License 88-88-extended
expiration date to 03/30/01. Marked up license amend encl
0018096.8 0 General Electric Co 88/09/10 000

SECRET 50-375 VIRGIL C SAYER NUCLEAR STATION UNIT 1

9906030095 Forwards Natic Engineering Branch input re water chemistry
program W/o eval
WRIGHT, J F Assistant Director for Engineering 88/04/07 1a

NOA423010 Advises SIM & PAH applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria rev 1

0098030350 Submits description of Activities in response to HRC 005500
Request for detailed field audit of installed electrical
equipment
OSUUC, F.H. Goodmann California Edison Co. 06/09/92, San

0006006477 Request acceptance of outlined audit & insp programs as
verification of electrical equipment & sys conformance
with IEEE separation criteria per IEEE 000000 request

000409051: Ratification of 80062 meeting w/ Leslie in Bethesda, MD to discuss structural engineering review
HOUGHTON, T C Licensing Branch 3 03/08/20 Jon

800410391 Forwards request for addl info re level measurement errors
due to swirling temp effects on level instrument ref legs &
steam generator heads & control rod guide pin placement
COWAN5000, a J. Lawrence, Brook O. yed 060910Z Jul-

8006170368 Forwards Drawing B-200-004, Sheet 247, Revision 2 of roach
big purple exhaust butterfly sealless valve Drawing
available in Central Files only

800d170d41 Forward Drawing 8-511-028, Revision 1 for miscellaneous steel
for fuel transfer canal shielding Drawing available in
Central Files only

EC0240424 Forwards request for addl info on radiological assessment in order to continue review of CL application
ECHEMCEP.A Licentia Bruno R RD/04/11 msa

0006250007 Disturbs reorganization of Ofc of Nuclear Reactor
Regulation & advises that get licensing matters w/respect to
facility have been assigned to T Houghlin Reorganization
charls encl
TEDECO, E.L. Assistant Director for Licensing 88/06/20 1202

#03827000V Request add info to determine potential underlaid cracking
in reactor vessel nozzle Info must be submitted within 2
wks

DISPATCHED 4 Licenses French 9 00:14:16 PM

© 2005 Blackwell Publishing Ltd *Journal of Internal Medicine* 258: 499–506

8006950023 Significant deficiency re: re emission of whole life of tapes used for 400-unit terminations from site procedures. Shelf lives obtained from manufacturers & included in site storage procedures.

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

8005120317 Forwards clarification of NBC requirements for emergency response facilities defined in 790512 14r Addl specific criteria for facilities under development

0000000340 Forward radiation emergency plan
00048.8 H Bush Carolina Electric & Gas Co 00/06/04 10

--800A040294 Radiation emergency plan
* South Carolina Electric & Gas Co 80/06/04 200

H. Utility Plant Safety Analysis Report (PSAR) & amendments

8040230105 Forwards Aesed 19 to PSAR
CASSIDY E H Southern California Edison Co 80VD6/10 20

DOCKETED ITEMS

--003420190 Amdt 19 to FAR
Southern California Edison Co 05/06/35 3,000pp

8 Inspection reports, IE Bulletins & correspondence

0004140016 Forwards IE Insp Rpt 50-395/80-10 on 000414-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 05/05/82 2pp

--0004160219 IE Insp Rpt 50-395/80-10 on 000416-17 No noncompliance noted Major areas inspected open items & level of noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 05/05/82 2pp

0004040003 Forwards IE Bulletin 80-11, "Emergency Heat Design" - No action or written response required IE Info Notice 79-20, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/05/80 2pp

0004040007 Forwards IE Bulletin 80-11, "Emergency Heat Design" - No action or written response required IE Info Notice 79-20, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/05/80 1p

0004050025 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability" - No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/08/80 2pp

0004050037 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability" - No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/08/80 2pp

0004060045 Forwards IE Insp Rpt 50-395/80-09 on 000421-03 No noncompliance noted
O'REILLY, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 05/05/82 2pp

--0004240032 IE Insp Rpt 50-395/80-09 on 000421-03 No noncompliance noted Major areas inspected preoperational surveillance programs, instrumentation of CP requirements & detection protection
JENNINGS, E R Region 3, Atlanta, Fuel Facility & Materials Safety Branch 05/05/82 4pp

0004200007 Forwards IE Circular 80-11, "Emergency Diesel Generator Lake Oil Cooler Failures" - No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/05/82 2pp

0004200009 Forwards IE Circular 80-11, "Emergency Diesel Generator Lake Oil Cooler Failures" - No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/05/82 2pp

0004280105 Forwards IE Insp Rpt 50-395/80-13 on 000301-0430 No noncompliance noted
LEIGH, E C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 05/05/82 2pp

--0004290106 IE Insp Rpt 50-395/80-13 on 000301-0430 No noncompliance noted Major areas inspected preoperational test procedures review, QA, administrative controls & maintenance & preoperational test results
MULLIGAN, J J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 05/05/82 11pp

0004190054 Notifies that no proprietary info is contained in NRC Audit Rpt 50-395/80-10
JENNINGS, E R South Carolina Electric & Gas Co 05/09/80 1p

0004240276 Response to IE Bulletin 79-02A re defects in ANNE B-312 Type 304 stainless steel pipe facility design does not permit use of pipe described in Bulletin
CRENSHAW, E H South Carolina Electric & Gas Co 05/04/80 1p

0004200030 Ack receipt re IE Insp Rpt 50-395/80-12 on 000420-25 No proprietary info
JENNINGS, E R South Carolina Electric & Gas Co 05/06/82 1p

--0004300032 Forwards IE Insp Rpt 50-395/80-10 on 000422-25 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 05/05/82 2pp

--0004300035 IE Insp Rpt 50-395/80-10 on 000422-25 No noncompliance noted Major areas inspected open items & level of noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 05/05/82 2pp

8 Reportable occurrences, LRAs & related correspondence

0004230426 Efficiency rpt re AEPF Code Class 1 piping ordered w/o stipulating proper testing. Caused by misinterpretation of PAM requirements. Purchase order changed to require annealing
JENNINGS, E R South Carolina Electric & Gas Co 05/05/80 2pp

0004230509 Forwards significant deficiency rpt re shelf life of bags used for AEPF void terminations
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 1p

0004230488 Final deficiency rpt re shelf life of bags used for AEPF void terminations not being addressed in site procedures. Termination area being revised. Proper lives now being obtained & are included in site storage procedures. Details encl
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 2pp

0004240041 Final deficiency rpt re broken insulators on 7HV speed & transfer switches. RFE will provide non-removable shafts to operating mechanism & welded cracks. To reduce reflection. Operating angle of cracks will also be changed
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/80 2pp

0004240004 Final deficiency rpt re incorrect current sensor in AEPF vault load cut circuit breaker. Sensor replaced. AEPF-vault breakers inspected visually. This sensor replaced. Manufacturer notified
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 2pp

0004250002 Forwards final deficiency rpt re inadequate electrical separation
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 1p

--0004250037 Final deficiency rpt re inadequate electrical separation. Repair panel circuit (cl) was routed from safety-related distribution panel to non-safety-related panel upon installation. Device design revised. Proper requirements reviewed
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 2pp

0004210034 Significant deficiency rpt on 000420-01 discovered phillips unit could not be fully loaded before unit would trip out on low evaporator pressure. Low cut unmet. Flow control deleted
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 2pp

0004200032 Part B1 rpt re failed engine thrust bearing. Detail generator with same inspected in accordance with test procedures & revised drawings. Generators are free of reported potential defect
MULLIGAN, J J East Industries, Inc., Fairbanks Morse Engine Div 05/04/80 2pp

0004190045 Efficiency rpt re substantial safety hazard in Westinghouse centrifugal charging pump operation. Insulin needs suggested
CRENSHAW, E H South Carolina Electric & Gas Co 05/05/82 2pp

--0004190404 Efficiency 000308 tolon w/R Blackboard re substantial safety hazard notification per 10CFR21. Discovered Westinghouse charging pump operation & interim modifications for 3-imp & 4-imp. operating & nonoperating plants
WESTINGHOUSE, E H Westinghouse Electric Corp 05/05/80 2pp

DOCKET 50-397 UPPER NUCLEAR PROJECT, UNIT 2
A Application/construction stage documents & correspondence

0004200105 Notices NRC & PAM applicants of NRC decision to modify implementation plan presented in Section 4 of 000420-03 re adequacy of applicable support structures. General operating reactor review proceedings & advance criteria encl
EHRHARDT, B V Division of Licensing 05/05/80 12pp

DOCKETED ITEMS

MO00100416 Modification of MO0029 meeting w/Agri, CE & BW in Bethesda.
MO to discuss revised Chapter 7 of FSAE
LYNDAL H B Licensing Branch 1 80/68/26 2pg

930623000 Summary of BODBIO meeting w/Herb II owners group re suppression pool temp response to safety/relief actions. Study concluded that limits on temp put needed. Requests that applicants submit detailed info for evaluation.
D.J.T.H. Containment Systems Branch 80/05/20 App

==806424041B "Erwinas Programs Base Map - Hanford Area "
 * Washington Public Power Supply System 79/01/13 1

N. Utility Final Safety Analysis Report (FSAR) & amendments

0000010105 Forwards Amed Y to FEAR
MEMBERSEN, D L Washington Public Power Supply System 09/05/27
2pg

--9006100129 Amend 9 to PS&E
 A Washington Public Power Supply System 80/004.rpt 375pg

806473599 Forwards 8004739 transmittal ltr & Certificate of Gov for
Amend 9 to PSAR Amend was sent to Benton County-OR Board of
Commissioner's Energy Facility Site Evaluation Council & EPA
RENESEER, S L. Washington Public Power Supply System 80/06/09
3pg

8004110278 Notifies that lab will be conducting addl moisture testing
on low hydrogen electrodes using technique required in AWS
A5.1, Section 20. Electrode coating moisture testing results
will be applied only to Units 1 & 4.
RENDERER: D L Washington Public Power Supply System 80/06/06
1c

6064308910 Forwards "For Comment" edition of NUREG-0649, "SWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking".
 Page provides NRC resolution of Generic Technical Activity
 A-10 MFC and
 ESD-99/T.O. 5 Division of Licensee 80/06/06 See

8006503395 Forwards responses to Round 3-Set B questions from Instrumentation & Controls Sys Branch Questions will be incorporated into FMEA in next amendment

8006503395 D. L. Washington Public Power Supply System 8006503395
12/20/95

800A180426: Notification of 800A13 meeting w/OMR Licensing Resol
Group to Bethesda, MD to discuss progress
U118041-2 W. Licensing Branch 1 08-034-003 1/08

ECDC2002: Summary of ECDC14 meeting w/utills in Bethesda, MD: organization & objectives of SRR licensing resolution group
Agenda & viewpoint email
10/18/02: J. M. Desjardins, Research Scientist, ECDC/CAT, also

806030097 Forwards regional evaluation of licensee performance & supporting data re activities authorized by CPRE-TO Areas of concern & required corrective actions delineated in SBC
8060417 ltr
CYCLERIAN H, Region 5, San Francisco, Office of the Director
WASHDC, DC

--0006005991 Discusses regional evaluation of project activities for Apr 1979-Apr 1980 Strong measures required to provide adequate assurance that completed safety-related work was properly accomplished Evaluation form for period ends
POB09, R T Region 5, San Francisco; Reactor Construction & Engineering Support Branch, B1000CT M, KIR000-B F, Region 5, San Francisco; Office of the Director, B10000-000, Apr 1980

8064300081 Forwards addl info required for NRC to complete review of partial penetration weld substitution for sacrificial shield weld includes documents re shielding correction for shop pipe at elevation 540 inches to 2 ft & detailed drawings
ROEDERER, D L Washington Public Power Supply System 80/04/20
cibac

F. Security, medical, emergency & fire protection plans

6008420317 Foreword classification of HPC requirements for emergency response facilities defined in 790913 [tr Add specific criteria for facilities under development
E18080UT.D.D. Division of Quantities Research 00-004-000 110-

800240404 Forwards drawings re location for near-site emergency kit.
Requests immediate review & response so that site-specific
design work can proceed & site preparation begin.
"Preconceptual Site Plan" available in Central Files only.
826829288 D. L. Washington Public Power Supply System 80/0a/ria
444

-B0000240488 Blind Base for WFFS-2 for Apr 1974 to May 1975 at
 33 Ft Level -
 @ Washington Public Power Supply System, 75-033001, 10

* Washington Public Power Supply System 79/01/12 19

Q Reportable occurrences, LERs & related correspondence

0036000036 PHO-V-00-007 on 000810:Mount St Helen erupted Unit 2 has
approx 10-inch of ash on ground: some ash dust inside plant
distraction sys operability confirmed Monitoring to detect
abrasive media in app components underway
01015P: W Region 9, San Francisco, Office of the Director
00/05/19 Zpp

0006300219 EN-80-021 ex. 003657, notice of violation & notice of
proposed imposition of civil penalties will be issued re
will Action based on alleged items of noncompliance re
deficiencies in QA program during period of 1976-78
16050904 J. THOMPSON-R-H Office of Inspection & Enforcement,
Office of the Director 80/06/13 3p

DOCKET 50-400 BRAWN HANCOCK NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

800403010 Advises DMR & NRC applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EINBERG, D. C. Division of Licensing 05/05/80 12pp

800405026 Responds to 800318 ltr re NRC position on utility approach of applying AIF position paper for procurement of off-balance-of-load (NRC does not concur w/utility approach Procurement of spare or replacement parts may be OK controls
HARRIS, W. P. Reactor Assistance Branch 05/05/80 2pp

800405048 Forwards revised peripheral/plexikon biological monitoring program to provide predevelopment phytoplankton data for comparison w/post-development data
HARRIS, W. P. Carolina Power & Light Co. 05/06/80 1p

800405047 Revised biological monitoring program
Carolina Power & Light Co. 05/06/80 3pp

I Financial information

800410011 Responds to 800308 request for comment on utility D-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC
CHRISTENBURY, E. Hearings Division 05/05/80 1p

B Inspection reports, IE Bulletins & correspondence

800404048 Forwards IE Bulletin 80-11, "Reactor Main Design - No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405031 Forwards IE Bulletin 80-12, "Decay Heat Removal Rmk Generalizability" No written response required IE Info Notice 80-28, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405012 Forwards IE Circular 80-11, "Emergency Diesel Generator Lub Oil Cooler Failures" No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405012 Ack receipt of 800302 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07
HARRIS, W. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 05/05/80 1p

800405020 Responds to NRC 800415 ltr re violations noted in IE Insp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07
Corrective actions persons regulating/inspectable items will receive notice five days prior to expiration date
HARRIS, W. P. Carolina Power & Light Co. 05/05/80 2pp

800405044 Responds to IE Bulletin 79-28, "Possible Malfunction of NRC's Model IALC Limit Switches at Elk River Plant" No questionable NRC's DMR's limit switches need to comply with
HARRIS, W. P. Carolina Power & Light Co. 05/05/80 1p

800405025 Responds to IE Bulletin 80-09, "Vacuum Conditions Resulting in Damage to Chemical Vapour Control Bag Inlet Tank" Forwards list of tanks & measures taken to prevent tanks against vacuum conditions
HARRIS, W. P. Carolina Power & Light Co. 05/05/80 2pp

B Repeatable occurrences, LERs & related correspondence

800410024 Notifies that evaluation of potential repeatable deficiencies re welding defects in Bergen Palisades Co supplied tanks per in-core instrumentation will be completed by 050616
CHANDLER, H. J. Carolina Power & Light Co. 05/05/80 1p

800410024 Notifies that evaluation of potential repeatable deficiencies re welding defects in AFCD supplied tanks will be completed by 050616
CHANDLER, H. J. Carolina Power & Light Co. 05/05/80 1p

800405006 Interim deficiencies re re procurement, fabrication & inspection of engineered parts for concrete headbox & support of safety-related loads Investigation revealed 40W plates requiring corrective action
CHANDLER, H. J. Carolina Power & Light Co. 05/05/80 2pp

800405070 Forwards final deficiencies re re condition of rebar in reactor auxiliary bldg
CHANDLER, H. J. Carolina Power & Light Co. 05/05/80 1p

800405070 Final deficiencies re re condition of reinforcing steel in reactor auxiliary bldg 2nd exterior wheel well caused by human error Welds drilled & bars grouted into previously placed concrete Spinal welds conducted to validate repairs
Carolina Power & Light Co. 05/06/80 4pp

800405030 Confirms 800404 action which clarified that deficiencies identified during NRC audit need not be evaluated for repeatability per 1007000 21a & 1007000 Evaluation would involve duplicity of action
CHANDLER, H. J. Carolina Power & Light Co. 05/05/80 1p

DOCKET 50-401 BRAWN HANCOCK NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

800403010 Advises DMR & NRC applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EINBERG, D. C. Division of Licensing 05/05/80 12pp

800405026 Responds to 800318 ltr re NRC position on utility approach of applying AIF position paper for procurement of off-balance-of-load (NRC does not concur w/utility approach Procurement of spare or replacement parts may be OK controls
HARRIS, W. P. Reactor Assistance Branch 05/05/80 2pp

800405048 Forwards revised peripheral/plexikon biological monitoring program to provide predevelopment phytoplankton data for comparison w/post-development data
HARRIS, W. P. Carolina Power & Light Co. 05/06/80 1p

800405047 Revised biological monitoring program
Carolina Power & Light Co. 05/06/80 3pp

I Financial information

800410011 Responds to 800308 request for comment on utility D-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC
CHRISTENBURY, E. Hearings Division 05/05/80 1p

B Inspection reports, IE Bulletins & correspondence

800404048 Forwards IE Bulletin 80-11, "Reactor Main Design - No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405031 Forwards IE Bulletin 80-12, "Decay Heat Removal Rmk Generalizability" No written response required IE Info Notice 80-28, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405012 Forwards IE Circular 80-11, "Emergency Diesel Generator Lub Oil Cooler Failures" No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

800405012 Ack receipt of 800302 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07
Corrective actions persons regulating/inspectable items will receive notice five days prior to expiration date
HARRIS, W. P. Carolina Power & Light Co. 05/05/80 2pp

000610044 Responds to IE Bulletin 79-06: "Possible Malfunction of NRCO Model EX100 Limit Switches at Elevated Temp." No questionable NRCO EX100 limit switches sent to test site
HARRIS, H. A. Carolina Power & Light Co. 05/05/80 1p

000610054 Responds to IE Bulletin 80-06: "Vacuum Conditions Resulting in Damage to Chemical Vent Control Bays Holdup Tank." Forwarded list of tanks & measures taken to protect tanks against vacuum conditions
HARRIS, H. A. Carolina Power & Light Co. 05/06/80 9pp

B. Reportable occurrences, LERs & related correspondence

000610024 Notifies that evaluation of potential reportable deficiency re welding defects in Bergen Patterson Co supplied headers for in-core instrumentation will be completed by 05/05/80
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 1p

000610094 Notifies that evaluation of potential reportable deficiency re welding defects in AFCS supplied headers will be completed by 05/05/80
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 1p

000610036 Interim deficiency report re procurement, fabrication & inspection of concrete embedment & support of safety-related loads investigation revealed 469 plates requiring corrective action
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 2pp

000610076 Forwarded final deficiency report re omission of rebar in reactor auxiliary bldg
CHAMBERS, H. J. Carolina Power & Light Co. 05/06/80 1p

--000610076 Final deficiency report re omission of reinforcing steel in reactor auxiliary bldg 3 south, exterior, shear wall. Covered by human error holes drilled & bars grouted into previously placed concrete. Special tests conducted to validate repairs
+ Carolina Power & Light Co. 05/06/80 App

000610086 Confirms 000610036 which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10CFR20.30(a) & 10CFR20.30(b) Evaluation would involve duplicating of action
CHAMBERS, H. J. Carolina Power & Light Co. 05/06/80 1p

DOCKET 30-893 HARRIS HARRIS NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

000610010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating review procedure & acceptance criteria and
HARRIS, H. A. Division of Licensing 05/05/80 13pp

000610018 Responds to 000610010 re NRC position on utility approach of applying ATF position paper for procurement of off-the-shelf items NRC does not concur with utility approach Procurement of spare or replacement parts only to be OK controls
HARRIS, H. A. Quality Assurance Branch 05/05/80 3pp

000610048 Forwarded revised periphery/plant biological monitoring program to provide preimposed phytoplankton data for comparison w/post-impoundment data
HARRIS, H. A. Carolina Power & Light Co. 05/06/80 1p

--000610048 Revised biological monitoring program
+ Carolina Power & Light Co. 05/06/80 3pp

I. Financial information

000610001 Responds to 000610001 request for comment on utility 8-P registration statement Review identified no insurable elements re NRC regulatory requirements or financial info filed w/NRC
CHAMBERS, H. J. Hearings Division 05/05/80 1p

D. Inspection reports, IE Bulletin & correspondence

000610048 Forwarded IE Bulletin 80-11: "Welding Wall Design." No action required re IE Bulletin 79-06: "Overloading of Structural Elements Due to Pipe Support Load" not
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 05/05/80 3pp

000610024 Forwarded IE Bulletin 80-12: "Bargy Heat Removal System Capability." No written response required re IE Bulletin 80-25: "Loss of Bargy Heat Removal Capability at Davis-Besse Unit 1 while in Refueling Mode" not
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 05/05/80 2pp

000610018 Forwarded IE Bulletin 80-11: "Emergency Diesel Generator Lub Oil Cooler Failures." No written response required
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 05/05/80 3pp

000610018 Ack receipt of 000610018 re violations noted in IE Insp Repts 30-400/80-07 & 30-400/80-07 & 30-400/80-07 & 30-400/80-07
Corrective actions persons responsible for violations items will receive notice five days prior to expiration date
HARRIS, H. A. Carolina Power & Light Co. 05/05/80 3pp

--000610026 Responds to NRC 000415 for re violations noted in IE Insp Repts 30-400/80-07 & 30-400/80-07 & 30-400/80-07 & 30-400/80-07
Corrective actions persons responsible for violations items will receive notice five days prior to expiration date
HARRIS, H. A. Carolina Power & Light Co. 05/05/80 3pp

000610044 Responds to IE Bulletin 79-06: "Possible Malfunction of NRCO Model EX100 Limit Switches at Elevated Temp." No questionable NRCO EX100 limit switches sent to test site
HARRIS, H. A. Carolina Power & Light Co. 05/05/80 1p

000610076 Responds to IE Bulletin 80-06: "Vacuum Conditions Resulting in Damage to Chemical Vent Control Bays Holdup Tank." Forwarded list of tanks & measures taken to protect tanks against vacuum conditions
HARRIS, H. A. Carolina Power & Light Co. 05/06/80 9pp

B. Reportable occurrences, LERs & related correspondence

000610024 Notifies that evaluation of potential reportable deficiency re welding defects in Bergen Patterson Co supplied headers for in-core instrumentation will be completed by 05/05/80
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 1p

000610094 Notifies that evaluation of potential reportable deficiency re welding defects in AFCS supplied headers will be completed by 05/05/80
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 1p

000610036 Interim deficiency report re procurement, fabrication & inspection of concrete embedment & support of safety-related loads investigation revealed 469 plates requiring corrective action
CHAMBERS, H. J. Carolina Power & Light Co. 05/05/80 2pp

000610076 Forwarded final deficiency report re omission of rebar in reactor auxiliary bldg
CHAMBERS, H. J. Carolina Power & Light Co. 05/06/80 1p

--000610076 Final deficiency report re omission of reinforcing steel in reactor auxiliary bldg 3 south, exterior, shear wall. Covered by human error holes drilled & bars grouted into previously placed concrete. Special tests conducted to validate repairs
+ Carolina Power & Light Co. 05/06/80 App

000610086 Confirms 000610036 which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10CFR20.30(a) & 10CFR20.30(b) Evaluation would involve duplicating of action
CHAMBERS, H. J. Carolina Power & Light Co. 05/06/80 1p

DOCKET 30-893 HARRIS HARRIS NUCLEAR POWER PLANT, UNIT 4

A. Application/construction stage documents & correspondence

000610010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating review procedure & acceptance criteria and
HARRIS, H. A. Division of Licensing 05/05/80 13pp

000610018 Responds to 000610010 re NRC position on utility approach of applying ATF position paper for procurement of off-the-shelf items NRC does not concur with utility approach Procurement of spare or replacement parts only to be OK controls
HARRIS, H. A. Quality Assurance Branch 05/05/80 3pp

000610048 Forwarded revised periphery/plant biological monitoring program to provide preimposed phytoplankton data for comparison w/post-impoundment data
HARRIS, H. A. Carolina Power & Light Co. 05/06/80 1p

DOCKETED ITEMS

201

000610017 Revised biological monitoring program
4 Carolina Power & Light Co 00/05/10 3pp

1 Financial information

000612011 Response to 000590 request for comment on still 9-7
registration statement Review identified no inaccurate
statements re NRC regulatory requirements or financial info
filed w/NEC
CHSREBURY, E Hearings Division 00/05/09 1p

0 Inspection reports, IE Bulletin & correspondence
000604040 Forwards IE Bulletin 00-11, "Heavy Metal Design " No action
or written response required IE Info Notice 79-20,
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/03/06
2pp

000605021 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys
Operability " No written response required IE Info Notice
00-20, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/09
2pp

000605120 Forwards IE Circular 00-11, "Emergency Diesel Generator Load
Oil Cooler Failures " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/10
2pp

0006050102 Ack receipt of 000502 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rpts 30-400/00-07,
30-400/00-07, 30-400/00-07 & 30-400/00-07
NRC/NEC, E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/01 1p

000605020 Response to NRC 000410 ltr re violations noted in IE Insp
Rpts 30-400/00-07, 30-400/00-07, 30-400/00-07 & 30-400/00-07
Corrective actions program reinspectionable items
will receive notice five days prior to expiration date
NEC/NEC, H Carolina Power & Light Co 00/05/02 2pp

000605044 Response to IE Bulletin 79-20, "Possible Malfunction of
NACED Reset RAISD Limit Switches at Elevated Temp " No
questionable NACED EXLSD limit switches used to coast the
NACED/IE, H Carolina Power & Light Co 00/05/03 1p

000604020 Response to IE Bulletin 00-03, "Vacuum Conditions Resulting
in Damage to Chemical 90 Control Sys Backup Tank " Forwards
list of tanks & measured tanks to protect tanks against
vacuum conditions
NRC/SPFIE, H Carolina Power & Light Co 00/04/09 3pp

2 Reportable occurrences, LERs & related correspondence

0006110204 Notifies that evaluation of potential reportable deficiency
re welding defects in Bergen Patterson Co supplied hangers
for in-core instrumentation will be completed by 000611
CHANDLER, H Carolina Power & Light Co 00/05/02 1p

0006110204 Notifies that evaluation of potential reportable deficiency
re welding defects in APCC supplied added will be completed
by 000611
CHANDLER, H Carolina Power & Light Co 00/05/02 1p

0006090306 Interim deficiency re: re procurement, fabrication & inst of
engineered plates for concrete embedment & support of
safety-related loads investigation revealed 688 plates
requiring corrective action
CHANDLER, H Carolina Power & Light Co 00/03/00 2pp

000610070 Forwards final deficiency re: re omission of rebar in
reactor auxiliary 3140
CHANDLER, H Carolina Power & Light Co 00/05/09 1p

0006100705 Final deficiency re: re omission of reinforcing steel in
reactor auxiliary 3140 rebar, exterior, shear wall, caused by
human error. Rebar drilled & bars grouted into previously
placed concrete. Special tests conducted to validate rebar
Carolina Power & Light Co 00/06/04 App

0006040203 Confirms 000406 letter which clarified that deficiencies
identified during NRC audit need not be evaluated for
reportability per 10CFR30.39(a) & 10CFR32. Evaluation would
involve duplication of action
CHANDLER, H Carolina Power & Light Co 00/06/12 1p

DOCKET 30-400 NORTH ANNA POWER STATION, UNIT 3
A Application/construction stage documents & correspondence

000603010 Advances SAR & SAR applicants of NRC decision to modify
implementation plan presented in Section 4 of NRCSD-0377 re
adequacy of applicable support structures General operating
reactor review procedures & acceptance criteria encl
EISENHART, D Division of Licensing 00/05/02 12pp

3 Inspection reports, IE Bulletin & correspondence

000605040 Forwards IE Bulletin 00-11, "Heavy Metal Design " No action
or written response required IE Info Notice 79-20,
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/03/06
2pp

0006050105 Forwards IE Insp Rpts 30-400/00-17, 30-400/00-02 &
30-400/00-02 re 000409 & 10 No noncompliance noted
NRC/NEC, E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/09 2pp

00060400114 IE Insp Rpts 30-400/00-17, 30-400/00-02 & 30-400/00-02
re 000409 & 10 No noncompliance noted. Major areas inspected
IE Bulletin 79-17 & 00-00 activities re cracks in berated
water cap & containment liner penetration inside
O'REILLY, J P Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00060505, H Region 2, Atlanta, Office of the
Director 00/05/07 App

0006050201 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys
Operability " No written response required IE Info Notice
00-20, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/09
2pp

0006050307 Forwards IE Circular 00-11, "Emergency Diesel Generator Load
Oil Cooler Failures " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/10
2pp

0006050207 Advances re suspension of IE Bulletin 00-00 review due to
ongoing feasibility study Review will resume if study
indicates continuing of feasibility re nuclear waste
NRC/NEC, E Virginia Electric & Power Co 00/05/08 1p

DOCKET 30-400 NORTH ANNA POWER STATION, UNIT 4
A Application/construction stage documents & correspondence

000603010 Advances SAR & SAR applicants of NRC decision to modify
implementation plan presented in Section 4 of NRCSD-0377 re
adequacy of applicable support structures General operating
reactor review procedures & acceptance criteria encl
EISENHART, D Division of Licensing 00/05/02 12pp

3 Inspection reports, IE Bulletin & correspondence

000605040 Forwards IE Bulletin 00-11, "Heavy Metal Design " No action
or written response required IE Info Notice 79-20,
"Overloading of Structural Elements Due to Pipe Support
Loads" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/03/06
2pp

0006050105 Forwards IE Insp Rpts 30-400/00-17, 30-400/00-02 &
30-400/00-02 re 000409 & 10 No noncompliance noted
NRC/NEC, E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/09 2pp

00060400114 IE Insp Rpts 30-400/00-17, 30-400/00-02 & 30-400/00-02
re 000409 & 10 No noncompliance noted. Major areas inspected
IE Bulletin 79-17 & 00-00 activities re cracks in berated
water cap & containment liner penetration inside
O'REILLY, J P Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00060505, H Region 2, Atlanta, Office of the
Director 00/05/07 App

0006050201 Forwards IE Bulletin 00-12, "Decay Heat Removal Sys
Operability " No written response required IE Info Notice
00-20, "Loss of Decay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" encl
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/09
2pp

- 0004260137 Forwards 1E Circular 80-11 "Emergency Diesel Generation Unit
Oil Cooler Pumps" by Region 2, Atlanta, Office of the Director 80/05/13
app
- 0004260277 Advice of suspension of 1E Bulletin 80-08 invites due to
safety facilities study review until review of study
includes continuing effectiveness of nuclear units
BROWN, S C Virginia Electric & Power Co 80/05/28 1p
- DOCKET 50-409 LA CHESBIE SPILLING WATER REACTION
O. NRC Staff/Field Environmental Statement, supply & correspondence

- 0004110244 California 800829 conversation re request for extension until
000417 for comments on 800829-0191, Final EIS for facility
Extension period due to possible frequency of discussions
on benefit/cost ratio & radiological impacts
HOSAGE, J M Environmental Protection Agency 80/04/04 1p
- 0004140094 Comments on PER 14 Pollution Discharge Elimination by
permit for discharging wastewater to Delta 4 exhibit has not
been issued American Hydrocarbons rather than morphology should
be used as better predictor additive for oil refinement
GRUENKAMP, H Wisconsin, State of 80/04/06 app
- 0004170437 Notifies that Dept of Army permit not required for Final
EIS No comments re EIS
PARKINS, M D Army, Dept of 80/06/10 1p
- 0004260244 Forwards corrected Pages 3-11, 5-12, 5-17 & 5-21 to PER 8008-
0591 re occupational radiation exposure
CRITCHFIELD, S Operating Reactors Branch 80/04/11 app
- 8004300373 Revised Pages 5-11, 5-12, 5-17 & 5-21 to PER den Facility
Office of Nuclear Reactor Regulation, Director 80/04/11 app
- 0004300190 Notifies follows to 800406 for re add comments on PER for
Facility Response that permit used to requesting
comments or questions be modified to specifically identify
area addressed
GRUENKAMP, H Wisconsin, State of 80/04/19 app
- F. Security, medical, emergency & fire protection plans

- 0004260238 Notifies that new telephone sys called Health Physics
Network (HPN) has been installed at site Sys intended for
use during emergencies to link all power plants & NRC
Emergency Notification Sys hotline will also be used
BEPFORD, J D Region 2, Chicago, Office of the Director. 80/04/18
app
- 0004260487 Forwards proposed rule entitled, "Fire Protection Program
for Nuclear Power Plants Operating Prior to 790101" Rule
add new Section 80-40 & App B to 50CFR80 & is expected
to be published in FR by end of May
KILBING, S D Division of Licensing 80/05/19 app
- 0004110543 Forwards revised Pages 1-14 & New Page 14a for proposed
rule 100FR80 "Fire Protection Program for Nuclear Power
Plants Operating Prior to 790101." Unannounced by NRC 800519
for Page 14a not encl
EISENHUT, D D Division of Licensing 80/05/22 73pp
- 0004110543 Forwards revised modified assumed security plan Plan
unclassified (ref 100FR80 7901)
LINDBERG, P Maryland Power Cooperative 80/04/04 app
9. Regulatory correspondence

- 0004170125 Response to NRC interregulatory Company to draft EIS-LACBMR
Final & main units will risk factor than non-nuclear power
Dismantling has negative effect on cost benefit
Certificate of Use and Related correspondence
HOSAGE, A N - HYDRA-90 B Coeur d'Alene Energy Coalition 80/04/24
app
- 0004040024 Advice of request for hearing on 800829 order to show
cause NRC evaluating license responses to order & has
requested add info
BROWN, S C Office of Nuclear Reactor Regulation, Director
80/05/13 1p
- 8004300373 Forwards corrected Pages 3 & 4 to 800829 answer to
order to show cause
HOSAGE, A N Morgan, Lewis & Bockius 80/04/03 1p
- 8004400021 Corrected Pages 3 & 4 to 800829 answer to order to show
cause
LINDBERG, P Maryland Power Cooperative 80/05/25 app
- 8004100333 Advice that requests for hearing on order to show cause
& related documents should be referred to Commission for
advice of NRC
BROWN, S C Office of the Executive Legal Director 80/05/12
app
- 0004110208 Notice of withdrawal from proceeding Certificate of Use
encl
GAGN, S H Queen, R H 80/05/19 app
- 0004260243 Order for amendment of 800419 prehearing conference at
Site of H-L-Crossed, NRC re 100FR80 TSC nature & ADR 800933
amendment 6 order No limited appearances allowed
BROWN, S C Atomic Safety and Licensing Board Panel 80/05/23
1p
- 0004110318 Advice that NRC plans to delete name from list for
request of correspondence from NRC to license re 1975 pool
operation proceeding
CRITCHFIELD, S Operating Reactors Branch 80/05/23 1p
- 0004060010 Notice for summary disposition of intervenor Coeur d'Alene
Energy Coalition Contentions 18, 20, 21, 19 & 22 re activities
initiated due to absence of genuine issue of material fact
supporting contentions
BROWN, S C Hearing Branch 80/04/04 app
- 8004060010 Affidavit re intervenor Coeur d'Alene Energy Coalition
Contentions 20 & 21 Testing methodology in facility
radiological activity monitoring program meets best
requirements w/prof qualifications & supporting documents
BROWN, S C Radiological Assessment Branch 80/05/20 31pp
- 8004060010 Affidavit re intervenor Coeur d'Alene Energy Coalition
Contentions 20 Facts do not support contention that LACBMR
offices activities are critical to health & safety Prof
qualifications encl
HOSAGE, A N Radiological Assessment Branch 80/05/15 app
- 8004060023 Affidavit re intervenor Coeur d'Alene Energy Coalition
Contentions 19 Radiological & toxic impacts would be additive
rather than synergistic & would not be limited to health &
safety Prof qualifications encl
BROWN, S C Radiological Assessment Branch 80/05/15 app
- 8004060023 Affidavit re intervenor Coeur d'Alene Energy Coalition
Contentions 19 None of Contentions 19 cost factors would
offset benefits of continued operation Prof qualifications
encl
BROWN, S A Utility Finance Branch 80/05/21 app
- 8004060023 Affidavit re intervenor Coeur d'Alene Energy Coalition
Contentions 22 Measures outlined in contention would not
eliminate need for LACBMR Prof qualifications & Certificate
of Use encl
FELD, S D Utility Finance Branch 80/05/14 app
- 0004110209 Forwards 800409 PM notice re nuclear plant accident
considerations under NRC's of 1969 Parties are invited to
comment at 800419 prehearing conference on effect of new
policy statement on CL proceeding
BROWN, S C Atomic Safety and Licensing Board Panel 80/06/10
app
- 8004110209 PM notice re nuclear plant accident considerations under
NRC's of 1969 Revises NRC policy for considering Class V
activities from action point of view Supplementary info
encl
GAGN, S J Office of the Secretary of the Commission 80/06/09,
12pp
- 0004110140 Memorandum inviting parties to comment at 800409 prehearing
conference re Commission 800409 PM publication approval of
policy statement on Class V accident probabilities &
consequences
BROWN, S C Atomic Safety and Licensing Board Panel NRC
80/06/10 app
- 8004110142 "Nuclear Power Plant Accident Considerations Under NEPA
of 1969," 100FR80 & B statement of interim policy, withdrawn
proposed annex to App D of 100FR80 & supports following
CHILD, M J Office of the Secretary of the Commission 80/06/09
17pp

DOCKETED ITEMS

203

0006170513 Forwards RP Control 000616 affidavit & 1978 NUREC-0006 in response to questions of ASLS 000521 memorandum & order W/A NUREC
W0061604 C P Hearing Branch 3 00/06/16 1p

--0006170417 Affidavit in response to questions of ASLS 000521 memorandum & order re LINCOLN PWR Supporting documentation & proof qualifications encl
CEC/ELER.H P Environmental Engineering Branch 00/06/16 31pgs

J Insurance & indemnity information

0006170408 Forwards Endorsement 25 to AMI Policy 16-217 per Agreement 8-12
BEVINS.H P Duquoyland Power Cooperative 00/06/11 2pg

P Operating license stage documents & correspondence

0006170410 Forwards addl TRS-2 related requirements to operating Reactors Licensee requirements for TRS Action Plan include ASRS, training, licensing exams & licensee dissemination of operating experience Response requested within 30 days
EISENHART.D G Division of Licensing 00/08/07 10pgs

0006170407 Forwards NUREC-0456 Vols 1 & 11 W/A encl
CRUTCHFIELD.B Operating Reactors Branch 3 00/05/16 2pgs

0006170506 Forwards request for addl info per App J review of containment leakage testing
CRUTCHFIELD.B Operating Reactors Branch 3 00/05/19 5pg

0006170512 Requests comments on NUREC-0077, "Potential for Low Fracture Toughness & Laminar Tearing on PWR Steam Generator & Reactor Containment Pump Supports" - Proposed review procedures & implementation schedule encl
EISENHART.D G Division of Licensing 00/05/19 72pg

0006170516 Forwards completed questionnaires for epidemiologic studies on health effects of low level ionizing radiation exposure per DL 2100000000 request
LINCOLN.P Duquoyland Power Cooperative 00/06/02 10pgs

0006170524 Advances that reorganization of DOE of Nuclear Reactor Regulation became effective on 000428 Project manager J Shaw will coordinate licensing activities for facility
Reorganization is described in encl
CRUTCHFIELD.B Operating Reactors Branch 3 00/06/02 20pgs

0006170504 Ltr to all BWR licensees forwarding "Per Comment" edition of NUREC-0619, "BWR Feedwater Nozzle & Control Rod Drive Rotors Low Nozzle Cracking" - Comments will be evaluated by NRC prior to final implementation W/A encl
EISENHART.D G Division of Licensing 00/06/08 22pgs

0006170523 Forwards addl info re TRS Lessons Learned, Areas requiring post-accident entry were identified as control room, main steam, accident sampling station, health physics lab & technical support ctr; to be permanently located in Unit 3 Bldg
LINCOLN.P Duquoyland Power Cooperative 00/06/12 3pg

0006170520 Submits info in response to NRC 791023 ltr requesting verification of containment purging & venting during normal operation Design adequacy of containment valves confirmed in May 1979 w/ state model value qualification test program
LINCOLN.P Duquoyland Power Cooperative 00/06/12 20pgs

B Inspection reports, IE Bulletins & correspondence

0006170508 Forwards IE Insp Rpt 50-459/80-83 on 000428-29 M noncompliance noted
FOTONELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/05/14 2pgs

--0006170505 IE Insp Rpt 50-409/80-83 on 000428-29 M noncompliance noted Major areas inspected spent rack SA & SC programs
DANIELSON.O H Region 3, Chicago, Reactor Construction & Engineering Support Branch WMS.H G Region 3, Chicago, Office of the Director 00/05/13 4pgs

0006170515 Responds to IE Bulletin 79-56, "Baron Loss from BWR Control Blades" Each control blade was fully withdrawn Procedure demonstrated that reactor was subcritical w/o any control blade withdrawn 1 other 28 blades fully inserted
LINCOLN.P Duquoyland Power Cooperative 00/05/18 2pg

0006170513 Advances that insp of containment bldg reveals that 432 safety-related & maintenance-related electrical equipment does have positive anchorage Response action to IE info NUREC-00-21 & drawings encl
LINCOLN.P Duquoyland Power Cooperative 00/05/30 10pgs

0006170523 Forwards IE Insp Rpt 50-459/80-83 on 000428-29 & 0558-08 & notice of violation
HEIDEMANN.F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/05 2pgs

--0006170523 Notice of violation from insp on 000428-29 & 0505-09 & Region 3, Chicago, Office of the Director 00/05/30 1p

--0006170508 IE Insp Rpt 50-409/80-83 on 000428-29 & 0558-09 Noncompliance noted Failure to make prompt telephone notification of significant events to NRC operations ctr.
DANIELSON.O H, DRAHER.H M, FOTONELLI.H L Region 3, Chicago, Office of the Director 00/05/30 10pgs

R Periodic operating reports & related correspondence

0006170523 Forwards monthly operating rpt for May 1980
LINCOLN.P Duquoyland Power Cooperative 00/06/03 1p

--0006170523 Monthly operating rpt for May 1980
DANIELSON.O H Duquoyland Power Cooperative 00/06/03 7pgs

S Reportable occurrences, LERs & related correspondence

0006170524 Discusses findings governing up secondary relay valve sticking which causes initial pressure regulator to respond improperly immediate red alarm reporting is not necessary.
Comments Text Pages are enclosed
HEIDEMANN.F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/06/16 1p

T Hearing transcripts on non-entitled matters

0006170520 Transcript of 000619 prehearing conference in La Grasse, NC.
Re LINCOLN.P
* Atomic Safety and Licensing Board Panel 00/06/19 141pg

0006170523 Forwards transcript of 000619 prehearing conference W/A encl
WMS.H G P Hearing Branch 3 00/06/25 1p

DOCKET 50-410 NINE HOLE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

0006170510 Advances OMR & PWR applications of NRC decision to modify Implementation plan presented in Section 4 of NUREC-0077 re adequacy of applicable support structure demand operating reactor review procedure & acceptance criteria encl
EISENHART.D G Division of Licensing 00/05/20 10pgs

0006170524 Responds to 000615 & 0509 requests for review of plant geotechnical investigations Unit should evaluate safety implications of crack in reactor bldg roof wall
WMS.H G A. Asst. Dir. of, Corps of Engineers 00/06/30 2pgs

0006170520 Summary of 000410 meeting w/Mark II covers group re suppression pool pump response to safety-related actions
Decided concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation
WMS.H G Containment Division Branch 00/05/30 4pgs

0006170510 Notification of 000610 meeting w/Unit in Bethesda, MD to discuss pending defects in biological shield
WMS.H G Licensing Branch 1 00/06/32 2pgs

0006170512 Forwards "Per Comment" edition of NUREC-0619, "BWR Feedwater Nozzle & Control Rod Drive Rotors Low Nozzle Cracking" - Sept provides NRC resolution of Generic Technical Activity A-10 W/A encl
EISENHART.D G Division of Licensing 00/06/04 2pgs

0006170520 Submits anomalous geologic conditions per 000150 comment.
Shall, however, show fault previously encountered in Unit 3 which intersected in East Lake tower tunnel fault & showed display faults noted laterally
WMS.H G K. Niagara Mohawk Power Corp 00/06/09 1p

0004130223 Forwarded final response to geologic info Requests 0361 & 2, 10, 14 & 24 per 790204 Request
RDEGE & K. Niagara Mohawk Power Corp. 00/04/10 31pp

0004200090 Forwarded "Ductal Breaker Splice Sign" per 000303 addl info request re utility reinforcing steel bar splicing method
RDEGE & K. Niagara Mohawk Power Corp. 00/04/17 2pp

0004200084 Response to 000421 request for authorization to use 790432 NRC Code Case N-696 "Ball Certification Section III-Div 1, Classes 1, 2, 3, 4 & 5" Code case is acceptable sub to condition stated in 790432 addl info request
00/04/20 10 p

F Security, medical, emergency & fire protection plans

0004170029 Requests participation in NRC study of people-related problems in nuclear safeguards involve collection of data on licensee security forces & practices including visit to facility to interview security mgt personnel
UPPL/ITO T & K Operating Reactors Branch 3 00/04/02 2pp

G Inspection reports, IE Bulletins & correspondence

0004200042 Response to IE Bulletin 00-02, "Inspections of Fuel Handler Supplied Equipment - Feedwater spargers & thermal sleeves only by CR-Holtec"
RDEGE & K. Niagara Mohawk Power Corp. 00/04/23 1p

H Reportable occurrences, LERs & related correspondence

0004200028 Final Part 20 report re mixed heat of steel supplied by US West from which 4-inch elbows & 2-inch tees were used to SCAMPB requalification examinations conducted & closed at all listed facilities
GEAV, J. L. Chemtrec Corp., Tulsa Teros Div. 00/04/06 2pp

0004200046 Supplement 000416 interim deficiency report re historical shield wall Foundation & presentation for 000420 SCAMPB meeting & discussion re frame mechanics evaluation Sample fracture mechanic calculations encl
RDEGE & K. Niagara Mohawk Power Corp. 00/04/10 48pp

DOCKET 30-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/consentation stage documents & correspondence

0004200110 Advises BAE & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 000420-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EISBENUT, D O Division of Licensing 00/05/20 10pp

0004200124 Discussed reorganization of Div of Nuclear Reactor Regulation & advises that responsible officials re 000420 have been assigned to 4 Subdiv Reorganization charts encl
TOSBCE, E L Assistant Director for Licensing 00/04/13 11pp

D Inspection reports, IE Bulletins & correspondence

0004200018 Ack receipt of 000420 1st re number of inspections being performed inspections are intended to occur infrequently & will involve minimal duplication of inspection info
EISBENUT, V Office of Inspection & Enforcement, Office of the Director 00/03/05 2pp

0004200021 Response to NRC 791204 1st re performance & appraisal Section 6002 type of checks & balance via QA audit is desirable, though possibly too demanding on tag personnel
SCAMPB, B S Duquesne Light Co 00/02/09 2pp

0004200104 Ack receipt of 000416 1st re informing NRC of steps taken to correct substantiated allegations noted in IE Inspect 79-412/00-02
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/03/14 1p

re IE Inspect 30-412/00-02 on 000420-11
Philadelphia, Reactor Construction & Engineering Support Branch 00/03/13 2pp

0004200020 IE Inspect 30-412/00-02 on 000420-11 No noncompliance noted No allegations were substantiated internal audits not conducted in required time period 5 training program inadequate
WILL, E L Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 000420, J P Region 1, Philadelphia, Office of the Director 00/02/21 2pp

0004200029 IE Inspect 30-412/00-02 on 000420-20 No noncompliance noted
CARLSON, R T Region 3, Philadelphia, Reactor Construction & Engineering Support Branch 00/03/14 2pp

0004200029 IE Inspect 30-412/00-02 on 000420-20 No noncompliance noted Major problem suspected GC program for concrete placement & maintain, achievement monitoring program & previous test findings
SCAMPB, B S Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 000420, J P Region 1, Philadelphia, Office of the Director 00/03/09 2pp

0004200048 Forwarded IE Circular 00-13, "Orbit Spray Damage in Westinghouse Fuel Assembly - No written response required 0012-0 H Region 1, Philadelphia, Office of the Director 00/03/20 1p

0004200042 Response to IE Bulletin 00-05, "Vacuum Condition Resulting in Damage to Chemical Vent Control Gas (CVSG) Hotdog Tanks" Design features ensure that low pressure process or backup tanks are adequately designed against vacuum conditions
HOLLENB, E J Duquesne Light Co 00/04/06 2pp

D Reportable occurrences, LERs & related correspondence

0004200028 Ack receipt of 000420 final deficiency report re cable snag galvanizing deficiency
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 00/04/03 1p

0004190315 Forwarded final Significant Deficiency 79-05 re weld discontinuities in reactor vessel structural support
WOLLENB, E J Duquesne Light Co 00/04/16 1p

0004190321 Final Significant Deficiency 79-05 re weld discontinuities found during insp of reactor vessel structural support Cause consisted weld discontinuities in skirt-to-base flange weld to be weld-repaired & magnetic particles inspected by 001330
Duquesne Light Co 00/04/16 2pp

DOCKET 30-413 CATAMBA NUCLEAR STATION, UNIT 1

A Application/consentation stage documents & correspondence

0004200110 Advises BAE & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 000420-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EISBENUT, D O Division of Licensing 00/05/20 10pp

0004200094 Summary of 000420-04 meeting w/utl & H2 Municipal Power Agency Number 2 & also visit to assess cost schedule list of attendees, agenda, presentation summary, handouts & task program summary encl
HOB, D S Licensing Branch 3 00/04/26 22pp

D Inspection reports, IE Bulletins & correspondence

0004200027 Forwarded IE Bulletin 00-11, "Hanging Wall Design - No action on written response required IE Info Note 79-08, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, P Region 2, Atlanta, Office of the Director 00/03/08 2pp

0004200079 Forwarded IE Bulletin 00-12, "Duct Heat Removal Gap Operability - No written response required IE Info Note 79-08, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, P Region 2, Atlanta, Office of the Director 00/03/09 2pp

0004200110 Forwarded IE Circular 00-11, "Emergency Diesel Generator Lube Oil Cooler Problems - No written response required
O'REILLY, P Region 2, Atlanta, Office of the Director 00/03/13 2pp

DOCKETED ITEMS

206

8604130350 Ack receipt of 860320 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-413/80-04 & 80-414/80-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 1p

--8604130403 Responds to NRC 860424 ltr re violations noted in IE Insp Repts 80-413/80-04 & 80-414/80-04 Corrective actions noted control sheet re-organized & legible heat code re-established
PARKER, W O Duke Power Co 80/05/20 2pp

--8604130506 Forwards IE Insp Repts 80-413/80-04 & 80-414/80-04 on 860401-04 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/24 2pp

--8604130600 Notice of violation from Insp on 860401-04
Region 2, Atlanta, Office of the Director 80/04/23 1p

--8604130845 IE Insp Repts 80-413/80-04 & 80-414/80-04 on 860401-04 Noncompliance noted failure to provide identifiable heat number on weld record
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 860408-06 W F Region 2, Atlanta, Office of the Director 80/04/22 2pp

8604270082 Responds to IE Bulletin 80-05, "Human Conditions Resulting in Damage to Chemical Vent Control Sys Holding Tanks - Links to pressure & hot/sep tanks which are normally valued to contain primary cool water
PARKER, W O Duke Power Co 80/04/09 2pp

8604270219 Ack receipt of IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 Re regulations info
PARKER, W O Duke Power Co 80/04/24 1p

--8604270222 Forwards IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 2pp

--8604270228 Notice of violation from Insp on 860401-03
Region 2, Atlanta, Office of the Director 80/05/14 1p

--8604270201 IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 Noncompliance noted failure to follow drawing requirements
MURPHY, C E Region 2, Atlanta, Office of the Director 860408-06 W F Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/14 2pp

Reportable occurrences, LERs & related correspondence

8604280037 Forwards Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel equipment
PARKER, W O Duke Power Co 80/04/01 1p

--8604280345 Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel equipment batch output off by Lakeland Bridge & Steel Co & initially radiographed by Lakeland Testing Lab Repairs by 860503
Duke Power Co 80/05/01 2p

8604280504 PWR-11-80-005 NE issue notice printed allegations by const worker involving unsafe safety hazards worker contacted OSHA on 860508 following NRC referral OSHA contacted again on 860508 withstanding previous rept
MURPHY, C E Region 2, Atlanta, Office of the Director 80/05/15 1p

--8604280503 Forwards Significant Deficiencies 413-414/80-04 re improper radiography on steam generator enclosures
PARKER, W O Duke Power Co 80/06/02 1p

--8604280547 Significant Deficiency 413-414/80-04 re improper radiography on steam generator enclosures off by Lakeland Bridge & Steel Co Cause avoided Under radiographed in accordance w/ARPE. Close surveillance instituted to prevent recurrence
Duke Power Co 80/04/02 1p

8604280411 Informa that all Unit 1 safety-related motor control wire work has been inspected for proper power wires
Noncompliance noted failure to follow drawing requirements
MURPHY, C E Region 2, Atlanta, Office of the Director 860408-06 W F Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/14 2pp

8604280411 Informa that all Unit 1 safety-related motor control wire work has been inspected for proper power wires

A. Application/construction stage documents & correspondence

8604280410 Advises NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 860403-037 re adequacy of applicable support structures. General operating reactor review procedure & airplane criteria met
EITERHOUT, B O Division of Licensing 80/04/05 13pp

8604280394 Summary of 860423-04 meeting w/Unit 1 & NRC. Multiple Power Agency Number 1 site visit to assess cond schedule list of attendees, agenda, presentation summary, handouts & heat system summary and
MURPHY, C E Licensing Branch 2 80/04/06 2pp

B. Inspection reports, IE violations & correspondence

8604280427 Forwards IE Bulletin 80-11, "Emergency Hall Design" No action or written responses required IE Info Notice 70-02
"Overloading of Structural Elements Due to Pipe Support Loads" and
MURPHY, C E Region 2, Atlanta, Office of the Director 80/05/08 2pp

8604280427 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability" No written response required IE Info Notice 80-05, "Take of Decay Heat Removal Capability at Service-Basis Unit 1 While in Refueling Mode" and
MURPHY, C E Region 2, Atlanta, Office of the Director 80/05/09 2pp

8604280410 Forwards IE Circular 80-11, "Emergency Diesel Generator Load Oil System Failures" No written response required
MURPHY, C E Region 2, Atlanta, Office of the Director 80/05/15 2pp

8604280400 Ack receipt of 860400 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-413/80-04 & 80-414/80-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 1p

--8604280392 Responds to NRC 860424 ltr re violations noted in IE Insp Repts 80-413/80-04 & 80-414/80-04 Corrective actions noted control sheet re-organized & legible heat code re-established
PARKER, W O Duke Power Co 80/05/20 2pp

--8604280386 Forwards IE Insp Repts 80-413/80-04 & 80-414/80-04 on 860401-04 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/24 2pp

--8604280400 Notice of violation from Insp on 860401-04
Region 2, Atlanta, Office of the Director 80/04/20 1p

--8604280365 IE Insp Repts 80-413/80-04 & 80-414/80-04 on 860401-04 Noncompliance noted failure to provide identifiable heat number on weld record
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 860408-06 W F Region 2, Atlanta, Office of the Director 80/04/23 2pp

8604280382 Responds to IE Bulletin 80-05, "Human Conditions Resulting in Damage to Chemical Vent Control Sys Holding Tanks - Links to pressure & hot/sep tanks which are normally valued to contain primary cool water
PARKER, W O Duke Power Co 80/04/09 2pp

8604280321 Ack receipt of IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 Re regulations info
PARKER, W O Duke Power Co 80/04/09 1p

--8604280502 Forwards IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 2pp

--8604280528 Notice of violation from Insp on 860401-03
Region 2, Atlanta, Office of the Director 80/05/14 1p

--8604280501 IE Insp Repts 80-413/80-07 & 80-414/80-07 on 860401-03 Noncompliance noted failure to follow drawing requirements
MURPHY, C E Region 2, Atlanta, Office of the Director 860408-06 W F Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/14 2pp

B. Reproductive experiences, LBRs & related correspondence

800603037 Forwards Significant Deficiency Reps 413/90-04 & 414/90-04 re improper radiography of containment vessel equipment
PARSER, W O Date Power Co 80/04/01 1p

800603034 Significant Deficiency Reps 413/90-04 & 414/90-04 re improper radiography of containment vessel equipment
Hatch rep by Lakeside Bridge & Steel Co & initially rechecked by NRC's Testing Lab Reports by 800901
Date Power Co 80/04/01 2p

800603034 PMS-12-80-085 NC news media printed allegations by email involving email safety hazards. Markor contacted OSM on 800506 following NRC referral. OSM contacted again on 800908 withdrawing previous report
MAYHEW, J K Region 8, Atlanta, Office of the Director 80/08/13 1p

800603040 Forwards Significant Deficiency 413/414/90-04 re improper radiography of steam generator enclosures
PARSER, W O Date Power Co 80/04/02 1p

800603057 Significant Deficiency 413/414/90-04 re improper radiography of steam generator enclosures rep by Lakeside Bridge & Steel Co. OSM conducted initial radiography in accordance w/ NRC. Glass surveillance instituted to prevent recurrence
Date Power Co 80/04/02 1p

800603041 Inform that all Unit 1 safety-related meter system air equipment has been inspected for proper power wire connections. Necessary work was completed. Snap of Unit 2 is scheduled for completion by 801201
PARSER, W O Date Power Co 80/04/08 1p

DOCKET 80-416 GRAND GULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

800612060 Expresses appreciation re visit to facilities during previous w/ Mark II containment upgrade to be considerable improvement over Mark I & Mark II
HEMBEL, J H Mississippi Power & Light Co 80/04/30 1p

800603010 Reviews RWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of MSBR-0077 re adequacy of applicable support structures General operating reaction review procedure & acceptance criteria encl
KESINGER, D O Division of Licensing 80/05/20 10pp

800603053 Forwards request for add info as result of review of PWR & electrical control in Sections 7 & 8 of 7 Requests that PWR be amended to reflect responses
KESINGER, A Licensing Branch 2 80/05/28 7pp

800611015 Forwards drawings to support Unit 1, low-voltage piping analysis of Number 1s safety relief valve discharge line. In response to NRC 800214 ltr
SMILEY, F Mississippi Power & Light Co 80/06/02 2pp

800611019 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611020 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611020 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

"Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611021 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611021 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611022 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611027 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800611028 "Pipe Supports Containment, Main Safety Relief Valve Line - 1A - Sheet 1 of 3"
Date Power Co 80/04/21 1p

800619040 Summary of 800317-01 meeting w/ B&W & B&W Power Corp in San Bernardino, CA re structural engineering audit of facilities. List of attendees, request for add info & related documentation encl
KESINGER, D O Division of Licensing 80/06/04 8pp

800619040 Forwards preliminary version of technical info requested by NRC to support review of nuclear plant structural design. Preliminary efficient and info withheld (ref 800907 PWR)
MAYHEW, J K Mississippi Power & Light Co 80/06/06 4pp

800603070 Forwards "For Comment" edition of MSBR-0077 Comments should be forwarded by 800707 W/ encl
KESINGER, D O Division of Licensing 80/06/09 2pp

800603042 Forwards connection to 800514 ltr which misrepresented fuel load date for Unit 1. Correct date is 800501
SMILEY, F Mississippi Power & Light Co 80/06/11 1p

800603048 Corrected version of 800514 ltr re rescheduled fuel load date for Unit 1. Correct date is 800501. Requests most up-to-date & complete schedule for NRC safety review
SMILEY, F Mississippi Power & Light Co 80/06/11 1p

800603070 Notification of 800406 meeting w/ B&W in Bethesda, MD to discuss applicant approach to task action plan
HEMBEL, J H Licensing Branch 2 80/06/17 2pp

800603049 Requests 800708-10 meeting w/ NRC & consultants in San Bernardino, MD to discuss open items of RWR & PWR. Resolves 3 A-2 10, exclusive Forwards prepared agenda
SMILEY, F Mississippi Power & Light Co 80/06/20 2pp

800603047 Forwards Savannah River Lab preliminary draft review paper per 800603 balloon info should assist in review W/ encl
SMILEY, F Power Systems Branch 80/06/20 1p

C. Utility Environmental Report (ER), amendments & correspondence

800603023 Forwards Amend 4 to Final enviro report for facility drawings available in Central Files only
SMILEY, F Mississippi Power & Light Co 80/05/27 2pp

800603023 Amend 4 to Final enviro report for facility drawings available in Central Files only
SMILEY, F Mississippi Power & Light Co 80/05/27 13pp

800603028 Forwards affidavit of svc on distribution of Amend 4 to Final enviro report in accordance w/ NRC 1 to MSBR 300427 ltr
SMILEY, F Mississippi Power & Light Co 80/06/09 2pp

F. Security, medical, emergency & fire protection plans

800613017 Forwards clarification of NRC requirements for emergency response facilities defined in 700925 ltr. NRC specific criteria for facilities under development
KESINGER, D O Division of Licensing 80/04/28 41pp

800603075 Forwards Amend 40 to application for CLs for Licenses CRR-110 & CRR-115, consisting of revisions to P&ID, App 9B
SMILEY, F Mississippi Power & Light Co 80/06/17 1p

800603038 Amend 40 to application for CLs for Licenses CRR-110 & CRR-115, consisting of revisions to P&ID, App 9B, Certificate of Dvc encl
SMILEY, F Mississippi Power & Light Co 80/06/27 2pp

DOCKETED ITEMS

207

0004000084 Amend 40 to FBR, providing revisions to fire protection plan & emergency plan
Mississippi Power & Light Co 00/04/27 85pp

H General correspondence

0004000103 Express concern that no methodology exists for citizen input to development of nuclear site safety
STAPLEY, N.L. Mississippi Power & Light Co 00/04/02 2pp

0004000081 Outlines recent organizational changes Title of director of power protection changed to assistant vice president-nuclear production Production engineering section renamed nuclear plant engineering section Notification per an annual
HARRIS, T.E. Mississippi Power & Light Co 00/04/17 3pp

I Utility Final Safety Analysis Report (FSAR) & amendments

0004000093 Forwarded Amend 39 to FSAR & application for SLA
STAPLEY, N.L. Mississippi Power & Light Co 00/03/30 1p

0004000095 Application for Amend 39 to FSAR & application for SLA, consisting of Amend 39 to FSAR Certificate of SLA and
STAPLEY, N.L. Mississippi Power & Light Co 00/05/28 2pp

0004000097 Amend 39 to FSAR
Mississippi Power & Light Co 00/03/30 200pp

0004000120 Forwarded Affidavit of use and distribution of Amend 39 to application for SLA re FSAR per 780427 ltr
DALE, L.F. Mississippi Power & Light Co 00/04/09 2pp

0004000075 Forwarded Amend 40 to application for SLA for Licensee CFFB-10 & CFFB-11V, consisting of revision to FSAR App 10 Certificate of SLA and
STAPLEY, N.L. Mississippi Power & Light Co 00/04/27 1p

0004000082 Amend 40 to application for SLA for Licensee CFFB-10 & CFFB-11V, consisting of revision to FSAR App 10 Certificate of SLA and
STAPLEY, N.L. Mississippi Power & Light Co 00/04/27 2pp

0004000284 Amend 40 to FBR, providing revisions to fire protection plan & emergency plan
Mississippi Power & Light Co 00/04/27 85pp

H Antitrust correspondence

0004000442 Forwarded notice of receipt of add antitrust info re proposed add ownership by South MS Electric Power Association Legal notice for publication in various newspapers also sent
BCHMEIER, A. Licensing Branch 2 00/05/16 3pp

0004000447 Notice of receipt of add antitrust info ltr for submission of views on antitrust matters
BCHMEIER, A. Licensing Branch 2 00/05/16 4pp

0004000505 Comments as proposed amend to CP allowing South MS Power & Light Co to become co-owner No antitrust hearing necessary re proposed amend to CP
FARWELL, D.R. Justice, Dept of 00/05/20 1p

0004000030 Forwarded notice of violation of antitrust license conditions including refusing to offer City of Clarksville, MS & Municipal Energy Agency of MS opportunity to participate in facilities
BENTON, H.B. Office of Nuclear Reactor Regulation, Director 00/05/09 3pp

0004000403 Notice of violation of antitrust license conditions including refusing to offer City of Clarksville, MS & Municipal Energy Agency of MS opportunity to participate in facilities
BENTON, H.B. Office of Nuclear Reactor Regulation, Director 00/05/09 10pp

0004000032 Attorney General 000503 ltr furnishing add antitrust info ltr will be sent to City of Clarksville, MS to interview & requests for hearings may be filed by interested parties within 30 days after FR publication
BENTON, H.B. Utility Finance Branch 00/05/30 1p

0004000403 Advises that review of info submitted for antitrust review provides no basis to conclude that South MS Electric Power Association participation would create situation inconsistent w/antitrust laws
FARWELL, D.R. Justice, Dept of 00/05/20 1p

0004000088 Forwarded 000503 ltr containing Atty General advice that no antitrust hearing is necessary for proposed amend to CP
BENTON, H.B. Utility Finance Branch 00/06/03 2pp

0004000348 Response to 000503 notice of violation of CP antitrust conditions re: SLA 3 & 5 & 6. Notice allegation & suggests settlement to avoid delay in licensing No. 0004000088 ltr to Clarksville City sent
STAPLEY, N.L. Mississippi Power & Light Co 00/06/18 16pp

J Inspection reports, IE Bulletin & correspondence

0004000045 Forwarded IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000204-27 & notice of violation
FARWELL, J.P. Region 2, Atlanta, Office of the Director 00/04/14 3pp

0004000048 Notice of violation from Insp on 000304-07
Region 2, Atlanta, Office of the Director 00/04/14 1p

0004000081 IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000204-07. Noncompliance noted failure to evaluate & report some deficiencies in accordance w/10CFR20.201(a) Paragraph 2
STAPLEY, N.L. Region 2, Atlanta, Office of the Director, Construction & Engineering Support Branch 00/04/14 7pp

0004000427 Forwarded IE Bulletin 00-11, "Heavy Wall Design" No action or written response required IE info notice 30-20
"Overloading of Structural Elements Due to Pipe Support Loads" sent
FARWELL, J.P. Region 2, Atlanta, Office of the Director 00/05/09 2pp

0004000396 Forwarded IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000204-07. No noncompliance noted
FARWELL, J.P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/08 2pp

0004000070 IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000415-10 IE No noncompliance noted Major areas inspected: RCSP welding, pressure & service loss & heat treating
BENTON, H.B. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/08 4pp

0004000444 Forwarded IE Bulletin 00-12, "Decay Heat Removal System Capability" No written response required IE info notice 00-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" sent
FARWELL, J.P. Region 2, Atlanta, Office of the Director 00/05/09 2pp

0004000475 Forwarded IE Circular 00-11, "Emergency Diesel Generator Lubrication Failures" No written response required
FARWELL, J.P. Region 2, Atlanta, Office of the Director 00/05/13 2pp

0004000426 Act receipt of 000505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-414/00-02 & 00-417/00-02
FARWELL, J.P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/02 1p

0004000420 Inform NRC of possible definite mail shipment to power plant Notification was received per airtel vendor 0004000426 ltr
FARWELL, H.N. Library Equipment & Supply Co 00/04/04 4pp

0004000426 Act receipt of IE Insp Repts 00-414/00-02 & 00-417/00-02. No irregularities noted
FARWELL, J.P. Mississippi Power & Light Co 00/04/05 1p

0004000420 Forwarded IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000204-07. No noncompliance noted
FARWELL, J.P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/16 2pp

0004000427 IE Insp Repts 00-414/00-02 & 00-417/00-02 on 000415-10 IE No noncompliance noted Major areas inspected: instrumentation, work unit activities & SC records
BENTON, H.B. Region 2, Atlanta, Office of the Director, Construction & Engineering Support Branch 00/05/15 2pp

0004000407 Forwarded revised responses to notice of violation from Insp on 000303-05 providing more detailed & updated status of notice concerns
FARWELL, J.P. Mississippi Power & Light Co 00/06/17 7pp

R. Periodic operating reports & related correspondence

0006000075 Forwarded "Summary of Review Protection Program Respecting Control of Grand Gulf Nuclear Station Units 1, 2 & 3 For Bix Health Exemption 000430 -
HCS&NWH, J P Mississippi Power & Light Co 00/05/07 4pp

S. Reportable occurrences, LERs & related correspondence

0006000046 Potentially Reportable Deficiency 00/12 re design diagram used in siting & selection of hydroturbine electromechanical actuators. Revision 000328 re to correctly identify ITT General Controls as vendor. Final report will be completed by 000918.
DALE L F Mississippi Power & Light Co 00/04/25 2pp

0006000047 Part 21 re design diagrams used in siting & selection of ITT General Control hydroturbine electromechanical actuators. Diagrams may be incorrectly interpreted resulting in incorrect siting & selection of actuators.
DALE L F Mississippi Power & Light Co 00/04/25 3pp

0006000016 Reactor deficiency re to segregate bulk torque valves noted on IFCB pump. Vendor initiated changes to torque valves. Adequacy of original torqueing requirements under review. Final report expected by 000525.
DALE L F Mississippi Power & Light Co 00/05/09 2pp

0006000037 Third interim deficiency re to defective torque inverters. Complete corrective action plan forwarded. Proposed 00/06/06 re installation of protective filtering devices on inverter input. Under evaluation. Final report to be submitted by 000918.
DALE L F Mississippi Power & Light Co 00/05/10 2pp

0006000049 Interim deficiency re to carbon filters. Type WFF-2, supplied to Plant Co. Vendor reported that test equipment used for qualifying filters was unreliable. Filters returned for verification of quality & reliability.
HCS&NWH, J P Mississippi Power & Light Co 00/05/20 2pp

0006000050 Forwarded final deficiency re to PMS-00/26 re Containment gas analysis gas & 000403 3hr re NRC.
HCS&NWH, J P Mississippi Power & Light Co 00/05/20 3pp

0006000044 Notify NRC of defective Containment gas analysis gas during testing. Pump & deadband for approx 20% & pressure at pump outlet exceeded 10 psig. Pump discharge system line to be fixed.
HCS&NWH, J P Mississippi Power & Light Co 00/04/03 4pp

0006000070 Final deficiency re to PMS-00/26 re Containment gas analysis gas. Vendor proposed installation of bypass line on pump discharge to prevent overpressurization. Installation will be complete by 000825.
DALE L F Mississippi Power & Light Co 00/05/20 1p

0006000030 Interim deficiency re to NRC's Forwarded associated w/ Computer Sciences Corp callus valve. Evaluation of representative sample of callus equipment revealed no significant deficiencies. Final report provided by 000709.
HCS&NWH, J P Mississippi Power & Light Co 00/05/20 2pp

0006000024 Final Part 21 re to mixed head of steel supplied by UN Steel from which 4-inch elbows & 2-inch tees were cut to ASME requirements. Inspections conducted & closed at 46 listed facilities.
BRW, J L Children Corp - Tulsa Turns Div 00/06/06 2pp

0006000053 Forwarded interim deficiency re to damaged instrumentation cables under reactor pressure vessel. Final report will be sent by 000611.
HCS&NWH, J P Mississippi Power & Light Co 00/04/06 1p

0006000048 Interim deficiency re to damaged instrumentation cable under reactor pressure vessel. Approx 120 cables damaged during installation of control rod drive hydraulic gas & neutron monitoring gas. Closed by restricted working area.
DALE L F Mississippi Power & Light Co 00/04/06 1p

A final deficiency re to loose gas in Battis robot installed on Henry. Battis robot's valves
100P002 331a1 For Units 1 & 2 & 100P021 For
1 For Unit Co 00/06/11 3pp

re loose gas in Battis robot are
to verify valves. Operators will be
orientation not possible. New
re installed
t Co 00/06/11 3pp

0006000077 Deficiency re to PMS-00/26 re to GE Type 00-12 switches. Switches returned to safe position of operator was to stop on signal from reactor protection gas. Re-evaluation will be conducted & final report filed by 000918.
HCS&NWH, J P Mississippi Power & Light Co 00/04/12 2pp

0006000087 Forwarded third interim deficiency re to failure to provide qualified instrumentation on safety-related gas. Final report will be submitted by 000918.
HCS&NWH, J P Mississippi Power & Light Co 00/04/12 2pp

0006000021 Third interim deficiency re to failure to provide qualified instrumentation in safety-related gas. Corrective actions in previous action plan will be completed by 000711.
HCS&NWH, J P Mississippi Power & Light Co 00/04/12 4pp

0006000084 Notify re to final report & determination of potentially reportable deficiencies concerning failure of GE handswitch. CSN40-000202 will be provided by 000918.
HCS&NWH, J P Mississippi Power & Light Co 00/04/10 2pp

0006000024 Deficiency re to failure of radiographs to meet ASME Code requirements. Sample review of radiographs has been performed. Vendor plans to make tracking WABSE code body & discuss w/NRC. Final report will be provided by 000920.
HCS&NWH, J P Mississippi Power & Light Co 00/04/20 2pp

0006000047 00-457 00-458 GULF NUCLEAR STATION, UNIT 2
Application/contract/inspection stage documents & correspondence

0006000021 Expresses appreciation re visit to facilities during previous w/ Mark III containment appears to be considerable improvement over Unit 1 & 2 Mark III.
HCS&NWH, J P Mississippi Power & Light Co 00/04/20 1p

0006000010 Advice BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria and
CSN40001, J P Division of Licensing 00/05/20 1pp

0006000033 Forwarded request for addl info re result of review of PWR & nuclear comments on Sections 2 & 3 & 7. Requests that PWR be amended to reflect responses.
CSN40001, J P Licensing Branch 2 00/05/20 2pp

0006000072 Forwarded drawings to support BWR condenser piping analysis of Number 10 safety relief valve discharge line in response to NRC 000214 ltr.
DALE L F Mississippi Power & Light Co 00/06/02 2pp

0006000023 Summary of 000017-21 meeting w/ Battis Power Corp in Gethersburg, MD re structural engineering audit of facility. List of attendees, request for addl info & related documentation and
HCS&NWH, J P Operating Reactors Branch 2 00/04/04 4pp

0006000030 Forwarded preliminary version of technical info requested by NRC to support review of nuclear plant structural design. Preliminary effort will end. Info will be provided by 000918.
HCS&NWH, J P Battis Power Corp (subs of Battis Corp) 00/04/04 4pp

0006000070 Forwarded "Far Comment" edition of NUREG-0049 Comments should be forwarded by 000707 M/A and
EISB00001, J P Division of Licensing 00/04/09 2pp

0006000042 Forwarded correction to 000014 ltr which misrepresented fuel load data for Unit 1. Correct data is 000014.
DALE L F Mississippi Power & Light Co 00/06/11 1p

0006000040 Corrected version of 000014 ltr re rescheduled fuel load data for Unit 1. Correct data is 000014. Requests meet re data & complete schedule for NRC safety review.
DALE L F Mississippi Power & Light Co 00/04/11 1p

0006000029 Notification of 000024 meeting w/ Battis in Bethesda, MD to discuss applicant approach to leak action.
HCS&NWH, J P Licensing Branch 2 00/06/17 3pp

0006000049 Requests 000700-10 meeting w/NRC & consultants in Gethersburg, MD to discuss open items of EEN re PWR.
Battis Power Corp (subs of Battis Corp) 00/04/04 4pp

DALE L F Mississippi Power & Light Co 00/04/04 2pp

DOCKETED ITEMS

209

0004030627 Forwards Savannah River Lab preliminary draft review report for 0004030627 info should assist in review w/enc 1
KSMAP, P. Power Systems Branch 00/04/20 1p

C Utility Environmental Report (IER), amendments and correspondence

0004030622 Forwards Amend 4 to final envelope report for Facility Drawings available in Central File only
STAMPLEY, N. L. Mississippi Power & Light Co 00/05/92 3pp

--0004030629 Amend 4 to final envelope report for Facility
+ Mississippi Power & Light Co + Middle South Utilities, Inc. +
Middle South Services, Inc. 00/05/92 13pp

0004030635 Forwards Affidavit of use on distribution of Amend 4 to
final envelope report on expenditure w/enc 1 to MRC 780427 1hr
DALL, L. P. Mississippi Power & Light Co 00/04/92 3pp

F Security, medical, emergency & fire protection plans

0004030637 Forwards clarification of IERC requirements for emergency
response facilities defined in 790913 1hr Addl specific
criteria for facilities under development
CISBEN, S. D. Division of Operating Reactors 00/04/92 4pp

0004030635 Forwards Amend 40 to application for CLs for License CPM-
108 & CPM-110, consisting of revisions to PSMs App 90
STAMPLEY, N. L. Mississippi Power & Light Co 00/04/92 1p

--0004030636 Amend 40 to application for CLs for License CPM-110 &
CPM-110, consisting of revisions to PSMs App 90
+ Genc encl
STAMPLEY, N. L. Mississippi Power & Light Co 00/04/92 2pp

--0004030638 Amend 40 to FBR, providing revisions to fire protection plan
& emergency plan
+ Mississippi Power & Light Co 00/04/92 82pp

H General correspondence

0004030630 Expresses concern that no methodology exists for citizen
input to development of evaluation plan
MELLEN, J. Affiliates Unknown 00/04/92 2pp

0004030632 Outlines recent organizational changes Title of director of
Power production changed to assistant vice president/nuclear
production Production engineering section renamed nuclear
plant engineering section Notification per GR manual
REANES, T. E. Mississippi Power & Light Co 00/04/92 3pp

H Utility Final Safety Analysis Report (FSAR) & amendments

0004030603 Forwards Amend 29 to FSAR & application for CLs
STAMPLEY, N. L. Mississippi Power & Light Co 00/05/92 1p

--0004030605 Application for Amend 29 to application for CLs, consisting
of Amend 29 to FSAR Certificate of Use encl
STAMPLEY, N. L. Mississippi Power & Light Co 00/05/92 2pp

--0004030607 Amend 29 to FSAR
+ Mississippi Power & Light Co 00/05/92 200pp

0004030618 Forwards affidavit of use on distribution of Amend 29 to
application for CLs for FSAR per 780427 1hr
DALL, L. P. Mississippi Power & Light Co 00/04/92 3pp

H Antitrust correspondence

0004030643 Forwards notice of receipt of addl antitrust info re
proposed addl amendment to South MS Electric Power
Association Legal notice for publication in various
newspapers also encl
SCHMIDNER, A. Licensing Branch 2 00/05/92 2pp

--0004030647 Notice of receipt of addl antitrust info time for submission
of views on antitrust matters
SCHMIDNER, A. Licensing Branch 2 00/05/92 4pp

0004030650 Comments on proposed addl to EP allowing South MS Power &
Light Co to license competing MS antitrust hearing necessary
re proposed amend to CP
FARRINGTON, J. Justice, Dept of 00/05/92 1p

0004040035 Forwards notice of violation of antitrust license conditions
including referring to offer City of Clarkdale, MS &
Municipal Energy Agency of MS opportunity to participate in
facilities
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
00/05/92 3pp

--0004040043 Refusal of violation of antitrust license conditions
including refusing to offer City of Clarkdale, MS &
Municipal Energy Agency of MS opportunity to participate in
facilities
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
00/05/92 12pp

0004040045 Mississippi Ably General 000503 1hr Furnishing addl antitrust
info 1hr will be sent to Ofc of PR Relations to interview &
requestor or hearings may be held by interested parties
within 30 days after PR publication
GALT, J. W. Utility Finance Branch 00/05/92 1p

--0004040046 Advises that review of info submitted for antitrust review
provided no basis to conclude that South MS Electric Power
Association participation would create situation
inconspicuous antitrust laws
FARRINGTON, J. Justice, Dept of 00/05/92 1p

0004030608 Forwards 0004030632 1hr containing Ably General advice that
no antitrust hearing is necessary for proposed amend to CP
GALT, J. W. Utility Finance Branch 00/04/92 2pp

0004030635 Responds to 000503 notice of violation of CP antitrust
Conditions 4(a), 4(b) & 4(c) allegations & suggests
settlement to avoid delay in licensing MS. Sleeping 000403
1hr to Clarkdale City encl
STAMPLEY, N. L. Mississippi Power & Light Co 00/04/92 4pp

I Inspection reports, IE Bulletin & correspondence

0004030648 Forwards IE Insp Rpts 30-416/90-02 & 30-417/90-02 on
000304-07 & notice of violation
D'NEILLY, J. P. Region 2, Atlanta, Office of the Director 00/04/92 1p

--0004030648 Notice of violation from Insp on 000304-07
+ Region 2, Atlanta, Office of the Director 00/04/92 1p

--0004030650 IE Insp Rpts 30-416/90-02 & 30-417/90-02 on 000304-07
noncompliance noted failure to evaluate & report cond
deficiencies in accordance w/000303 55(a), Paragraph 3
000303, J. P. Region 2, Atlanta, Office of the Director
D'NEILLY, J. P. Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 00/04/92 7pp

0004040038 Forwards IE Bulletin 79-20, "Emergency Heat Removal
or Written Response Required" IE Info Notice 79-20,
"Overloading of Structural Elements Due to Pipe Support
Load" encl
D'NEILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/92 2pp

0004030638 Forwards IE Insp Rpts 30-416/90-09 & 30-417/90-07 on
000412-10 noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/92 4pp

--0004030639 IE Insp Rpts 30-416/90-09 & 30-417/90-07 on 000412-10
noncompliance noted major areas inspected RPS welding,
pressure & inservice insp & housekeeping
HERD, A. H. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/92 4pp

0004040038 Forwards IE Bulletin 80-10, "Emergency Heat Removal Rye
Operability" - No written response required IE Info Notice
80-20, "Loss of Steam Heat Removal Capability at Davis-Besse
Unit 1" 1hr in Refueling Room" encl
D'NEILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/92 2pp

0004030605 Forwards IE Circular 80-11, "Emergency Diesel Generator Load
Oil Level Failures" - No written response required
D'NEILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/92 2pp

0004030648 Forwards addl receipt of 000503 info informing MRC of items taken
to correct violations noted 30 IE Insp Rpts 30-416/90-02 &
30-417/90-09
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/92 1p

0006403007 Forwards IE Circular 80-13, "Old Ring Damage in Westinghouse Fuel Assemblies - No written response required
 80/09/28 1p
 Region 1, Philadelphia, Office of the Director

8 Reportable occurrences, LERs & related correspondence

0006404489 Act receipt of 800415 interim deficiency report re guide tube support pins. Checking report will be reviewed & evaluated
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/08 1p

--8006405476 Interim deficiency report re checking of control rod guide tube support pins. Checking restricted to pins solution
 annotated below 1,600 P. Check of tube support pins have potential for release of loose parts into upper core region
 CORRELL, M. G. Northeast Nuclear Energy Co. Issu. of Northeast Utilities 80/04/15 1p

0006406049 Act receipt of 800508 final deficiency report re component cooling water heat exchanger supports
 CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/08 1p

DOCKET 80-428 ALVIN W. VESTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

0006400106 Advances NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
 KISSENER, D. G. Division of Licensing 80/05/00 13pp

0006400279 Responds to NRC 800421 ltr requesting info re use of concrete masonry walls in Category 1 structures. No need to answer
 Questions 2-6
 KISSENER, D. G. Georgia Power Co. 80/06/12 1p

I Financial information

0006407030 Forwards Annual Financial Repts 1979
 WIGDER, W. A. Georgia Power Co. 80/06/11 1p

--8006407034 Annual Financial Rept 1979
 " The Southern Co. 80/03/10 43pp

--8006407038 Annual Financial Rept 1979
 " Georgia Power Co. 80/02/20 38pp

G Inspection reports, IE Bulletins & correspondence

0006403881 Forwards IE Insp Repts 80-424/80-06 & 80-425/80-06 on 800321-0402 re noncompliance noted
 STORR, J. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/21 2pp

--8006403585 IE Insp Repts 80-424/80-06 & 80-425/80-06 on 800321-0402 re noncompliance noted. Major areas inspected: environment, protection, erosion & runoff control & creek efforts
 monitoring
 JOHNSON, D. B. Region 2, Atlanta, Fuel Facility & Materials Safety Branch
 CUMMINGS, A. L. Region 2, Atlanta, Office of the Director 80/04/18 5pp

0006403942 Forwards IE Insp Repts 80-424/80-06 & 80-425/80-06 on 800415-17 re noncompliance noted
 HARRIS, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp

--8006405004 IE Insp Repts 80-424/80-06 & 80-425/80-06 on 800415-17 re noncompliance noted. Major areas inspected: control deficiencies
 re IE bulletins & circulars
 HUGHES, J. W. Region 2, Atlanta, Reactor Construction & Engineering Support Branch
 HART, M. D. Region 2, Atlanta, Office of the Director 80/05/01 4pp

0006406048 Forwards IE Bulletin 80-15, "Heavy Wall Design - No action re written response required IE Info Notice 79-28.
 "Overloading of Structural Elements Due to Pipe Support Loads" and
 D'NEILL, J. F. Region 2, Atlanta, Office of the Director 80/05/08 2pp

0006406026 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability - No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" and
 D'NEILL, J. F. Region 2, Atlanta, Office of the Director 80/05/09 2pp

0006406019 Forwards IE Circular 80-11, "Emergency Steam Generator Tube Oil Cooler Failures - No written response required
 D'NEILL, J. F. Region 2, Atlanta, Office of the Director 80/05/12 2pp

0006407038 Act receipt of IE Insp Repts 80-424/80-06 & 80-425/80-06 re proprietary info
 DUTTIN, D. Georgia Power Co. 80/06/05 1p

0006404027 Anticipates response to IE Bulletin 80-03 re vacuum condition resulting in damage to bulkup tanks until be submitted by 800721 Unit did not receive bulletin until 800606
 DUTTIN, D. Georgia Power Co. 80/06/09 1p

8 Reportable occurrences, LERs & related correspondence

0006406164 Act receipt of 800502 ltr providing interim followup to 800128 report re possible deficient pipe support design. Actions will be reviewed at next step
 DUTTIN, D. V. Region 2, Atlanta, Office of the Director 80/05/12 1p

--8006406170 Interim followup to 800128 report re possible pipe support design deficiency. Pipe support review will take longer than three months. Completion expected by June 1983. Current status of corrective actions includes review of 3,740 supports
 LEX, B. L. Bechtel Power Corp. Issu. of Bechtel Corp. 1 80/05/02 3pp

--8006406204 Confirms 800129 action re possible pipe support design deficiency. Written report will be filed by 800321 covering nature of deficiency, investigative & evaluation actions taken. Investigation should take 90 days
 LEX, B. L. Bechtel Power Corp. Issu. of Bechtel Corp. 1 80/01/29 2pp

0006407037 Advances that potential discrepancies in 79126 final significant deficiency report re embossed plate assembly have been evaluated. Corrective action noted is adequate & has been effected
 DUTTIN, D. Georgia Power Co. 80/06/20 2pp

DOCKET 80-428 ALVIN W. VESTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

0006400106 Advances NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
 KISSENER, D. G. Division of Licensing 80/05/00 13pp

0006400279 Responds to NRC 800421 ltr requesting info re use of concrete masonry walls in Category 1 structures. No need to answer
 Questions 2-6
 KISSENER, D. G. Georgia Power Co. 80/06/12 1p

I Financial information

0006407030 Forwards Annual Financial Repts 1979
 WIGDER, W. A. Georgia Power Co. 80/06/11 1p

--8006407034 Annual Financial Rept 1979
 " The Southern Co. 80/03/10 43pp

--8006407038 Annual Financial Rept 1979
 " Georgia Power Co. 80/02/20 38pp

G Inspection reports, IE Bulletins & correspondence

0006403881 Forwards IE Insp Repts 80-424/80-06 & 80-425/80-06 on 800321-0402 re noncompliance noted
 STORR, J. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/21 2pp

DOCKETED ITEMS

--000400285 IE Insp Repts 50-424/80-06 & 50-425/80-06 on 000331-0400 Re noncompliance noted Major areas inspected include protection, erosion & runoff control & coast effects monitoring
JAMES L. S. R. Region 2, Atlanta, Plant Facility & Materials Safety Branch
COMMISSIONER A. L. Region 2, Atlanta, Office of the Director 80/04/10 3pp

000400002 Forwards IE Insp Repts 50-424/80-06 & 50-425/80-06 on 000415-17 No noncompliance noted
RHHY, D. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/01 2pp

--000400004 IE Insp Repts 50-424/80-06 & 50-425/80-06 on 000415-17 No noncompliance noted Major areas inspected consist deficiency reports & IE Bulletin & circulars
RHHY, D. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch
RHHY, D. E. Region 2, Atlanta, Office of the Director 80/04/01 4pp

000400490 Forwards IE Bulletin 80-11, "Heavy Metal Design " No action or written response required IE Info Notice 79-38, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/08 3pp

000400426 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/09 2pp

000400019 Forwards IE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures " No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/12 2pp

000417013 Ack receipt of IE Insp Repts 50-424/80-06 & 50-425/80-06 Re noncompliance noted
DUFFON, D. Georgia Power Co 80/06/05 1p

000417027 Anticipates responses to IE Bulletin 80-05 re vacuum condition resulting in damage to piping tests will be submitted by 800501 until all test reactive bulletin until 800406
DUFFON, D. Georgia Power Co 80/06/09 1p

B Reportable circumstances, LERs & related correspondence

000400014 Ack receipt of 800502 1st providing Interim followup to 800413 re possible deficient pipe support design
SEYFRIED, H. V. Region 4, Dallas, Office of the Director 80/03/12 1p

--000400170 Status followup to 800413 re possible pipe support design deficiency Pipe support review will take longer than three months Completion expected by June 1980 Current status of corrective actions includes Review of 7-800 reports
LEE, B. L. Bechtel Power Corp (subs of Bechtel Corp) 80/05/02 2pp

--000400204 Confirms 800413 followup re possible pipe support design deficiency written repts will be filed by 060501. Copies of deficiency, investigative & evaluation actions taken Investigation should take 90 days
LEE, B. L. Bechtel Power Corp (subs of Bechtel Corp) 80/04/29 2pp

000407033 Advise that potential discrepancies in 791121 final significant deficiency repts re end-of-plate assembly have been evaluated Corrective action noted is adequate & has been effected
DUFFON, D. Georgia Power Co 80/05/02 3pp

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

000400028 Informes that revised physical security plan has been completed except for internal review plan should be submitted in approx 1 wk
PROFF, A. E. California, Univ. of Santa Barbara 80/05/27 1p

000420018 Forwards revised physical security plan for L-77 educational reactor reactor plan 2/80 (ref 00028 2/80)
PROFF, A. E. California, Univ. of Santa Barbara 80/04/10 1p

DOCKET 50-437 FLOATING NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

A Application/Construction stage documents & correspondence

000420010 Advices SAR & FWR applications of FNC decision to notify implementation plan presented in Section 3 of 80080-237 re adequacy of applicable support structures General meeting review procedure & acceptance criteria encl
EISENBERG, M. S. Division of Licensing 80/05/20 13pp

000400047 Summary of 000420 meeting w/applicant in Bethesda re re-term and license requirements from TII-2 accidents
EISENBERG, M. S. Licensing Branch 1 80/05/20 16pp

000420016 Forwards reorganization chart for Ops of Nuclear Reactor Regulation Facility licensing matters will be handled by R. B. Smith Transition being made admin of disruption to ongoing activities
EISENBERG, M. S. Assistant Director for Licensing 80/04/12 3pp

D Adjudicatory correspondence

000400048 Advices that status repts re progress of vendor application review will be submitted to 000501 Per 000500 1b-10C will respond to past-TII Action Plan items as of 1980 upon receipt Applicant responses will be evaluated for SAR input
O'REILLY, J. P. Hearing Branch 3 80/05/20 1p

D Advisory Committee on Reactor Safeguards reports & correspondence

000400076 Forwards RE Pleasent 000416 1st re suggestions & recommendations for floating nuclear plant core loads
Pleasent, R. S. 000502 as Compliance Division & urgent preparation for signature of executive director
PLEASANT, R. S. ACRS - Advisory Committee on Reactor Safeguards 80/04/17 1p

--000400079 Advices that review of vendor proposed core loads design for floating plant was completed during 800410-12 meeting Design acceptable but planned tests & analytical programs meet firm pleasent operation timelines prior to start
PLEASANT, R. S. ACRS - Advisory Committee on Reactor Safeguards 80/04/16 3pp

000410044 Responds to 000416 recommendation that consultant be engaged re design of high temp melting furnace & handling of high temp molten salts Contract w/Applied Science Associates, Inc. implemented on 000417
RHEB, D. F. Division of Systems Integration 80/04/08 2pp

--000410046 Suggests effort to mode to establish acceptable frequency for accident in which molten core reaches ocean & criteria for limiting accidental liquid releases Consultant should be engaged in design of high temp melting furnace
PLEASANT, R. S. ACRS - Advisory Committee on Reactor Safeguards 80/04/16 3pp

000410046 Confirms 000417 implementation of technical assistance contract w/Applied Science Associates, Inc. to perform core melt water interaction evaluations Annual progress repts will be forwarded
RHEB, D. F. Division of Systems Integration 80/04/04 1p

D Inspection reports, IE Bulletins & correspondence

000400076 Forwards IE Bulletin 80-11, "Heavy Metal Design " No action or written response required IE Info Notice 79-38, "Overloading of Structural Elements Due to Pipe Support Loads" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/08 1p

000400035 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/09 1p

000400077 Forwards IE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures " No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/13 1p

DOCKETED ITEMS

213

DOCKET 30-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

0004235110 Advises NRC & NRC applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0877 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl. ETR0807.0 & Division of Licensing 00/05/00 13pp

0004265220 Responds to NRC 000424 ltr re DRYED tendon installations & related O&O activities until has approved training procedures Following training of OZ inspectors SMVVO will resume installation Comments re procedures requested HILL,L.H. Tennessee Valley Authority 00/03/00 2pp

0004265204 Forwarded response to ED Parr 002325 supplemental request for addl info re changes & studies proposed in Encl F of 7/15/99 response to initial request Continued cost justified HILL,L.H. Tennessee Valley Authority 00/03/00 26pp

0004103015 Forwarded study plan for monitoring water quality & aquatic biological conditions in Sumnerville reservoir per Part 217 of NPDES Permit A0026439 EL-SHAMY,T. Tennessee Valley Authority 00/06/00 5pp

0004102502 Responds to NRC 000424 ltr requesting info re DRYED tendon installation operations & related O&O activities. DRYED training satisfactorily completed & resumption of tendon cutter reworking activities & storage planned HILL,L.H. Tennessee Valley Authority 00/04/00 1p

0004265049 Forwarded request for addl info re instrument & control sys for continuing review of Application for VOW060033.0 Licensing Branch 1 00/06/01 31PP

0004265210 Forwarded reorganization chart for Div of Nuclear Reactor Regulation Facility licensing matters will be handled by R Economic Transition being made watch of disruption to ongoing activities TRESCORD,C. Assistant Director For Licensing 00/04/02 2pp

0004265042 Responds to NRC 000424 ltr re DRYED tendon installation operations & related O&O activities until has approved w/ corrections as noted encl addl training procedures. HILL,L.H. Tennessee Valley Authority 00/04/00 3pp

F. Security, medical, emergency & fire protection plans

0001103017 Forwarded clarification of NRC requirements for emergency response facilities defined in 790113 10 Addl specific criteria for facilities under development 00/04/02 41pp ETR0807.0 & Division of Operating Reactors

0006040294 Forwarded addl info to training & qualification plan. Info withheld Encl 100782 7093 HILL,L.H. Tennessee Valley Authority 00/06/02 3pp

G. Inspection reports, IE Bulletins & correspondence

0004060599 Forwarded IE Bulletin 00-15, "Memory Wall Design - No action on written response required IE Info Notice 79-20 "Overloading of Structural Elements Due to Pipe Support Loaders" encl. D'TRELLY,J.P. Region 2, Atlanta, Office of the Director 00/05/06 3pp

0004045267 Forwarded IE Bulletin 00-12, "Decay Heat Removal Sys Operability - No written response required IE Info Notice 79-05, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl. D'TRELLY,J.P. Region 2, Atlanta, Office of the Director 00/05/09 3pp

0004103026 Forwarded IE Circular 00-11, "Emergency Diesel Generator Lube Oil Center Failures - No written response required. D'TRELLY,J.P. Region 2, Atlanta, Office of the Director 00/05/13 3pp

0004103033 Ack receipt of 000615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-438/00-04 & 30-439/00-04. HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/02 3pp

0004120037 Responds to NRC 000420 ltr re violations noted in IE Insp Repts 30-438/00-04 & 30-439/00-04 Corrective actions frequency of documented surveillance to ensure needed openings on piping equipment increased to once per week HILL,L.H. Tennessee Valley Authority 00/05/02 3pp

0004120043 Forwarded IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000318-21 & notice of violation HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/20 2pp

0004120043 Notice of violation from Insp on 000318-21 & Region 2, Atlanta, Office of the Director 00/04/20 1p

0004120044 IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000318-21 Noncompliance noted failure to follow procedure for capping & welding during piping sys fabrication & to provide appropriate criteria in 10pp procedures. HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/21 & HARRIS,C.E. Region 2, Atlanta, Office of the Director 00/04/21 3pp

0004265091 Ack receipt of 000602 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-438/00-04 & 30-439/00-04. HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/09 2pp

0004265227 Responds to NRC 000605 ltr re violations noted in IE Insp Repts 30-438/00-04 & 30-439/00-04 Corrective actions noted release written to react Council 143-M018-0 to eliminate chance of alternate Cabinet installation HILL,L.H. Tennessee Valley Authority 00/06/02 2pp

0004265201 Forwarded IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000415-18 & notice of violation HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/02 3pp

0004265202 Notice of violation from Insp on 000415-18 & Region 2, Atlanta, Office of the Director 00/05/02 1p

0004265203 IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000415-18 Noncompliance noted failure to follow procedures on installation & loss of safety-related cables. HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/02 & HARRIS,C.E. Region 2, Atlanta, Office of the Director 00/05/02 4pp

0004265050 Forwarded response to IE Bulletin 00-05 re vacuum conditions resulting in damage to Sodium Lube Pressure Protection For refueling water storage tank at Sequoyah & Watts Bar is provided by redundant breakers & tank insulation HILL,L.H. Tennessee Valley Authority 00/06/09 3pp

0004270017 Ack receipt of 000719 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 30-438/00-04 & 30-439/00-04. HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/10 3pp

0004270197 Responds to NRC 000424 ltr re violation noted in IE Insp Repts 30-438/00-04 & 30-439/00-04 Corrective actions clear watch on water storage tank will be undertaken Inspectors' training program will be established HILL,L.H. Tennessee Valley Authority 00/06/19 2pp

0004270207 Forwarded IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000420-04 & notice of violation HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/24 3pp

0004270211 Notice of violation from Insp on 000420-04 & Region 2, Atlanta, Office of the Director 00/06/20 1pp

0004270214 IE Insp Repts 30-438/00-04 & 30-439/00-04 on 000420-04 Noncompliance noted failure to maintain proper storage of preheating sys components & failure to maintain accurate quality records. HARRIS,C.E. Region 2, Atlanta, Office of the Director 00/06/24 & HARRIS,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/23 7pp

H. Reportable occurrences, UERs & related correspondence

0004103043 Forwarded first interim deficiency report re welding of structural steel annulus flange framing HILL,L.H. Tennessee Valley Authority 00/05/15 1p

DOCKETED ITEMS

000610085 First interim deficiency report re welding of structural steel erection floor framing. Records completed. Improperly will be investigated & affected welds will be reinspected. Inspection will be restricted on completion of RC requests.
Tennessee Valley Authority 00/05/93 1p

000600080 Forwards First Interim deficiency report re control DA audit deficiency
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000600037 First interim deficiency report re control DA audit deficiency DA audit revealed that three welders & all welder foremen were not included in DA training/re-training outlined in 000000 1p re NRC Personnel are being re-trained.
Tennessee Valley Authority 00/05/93 1p

000600034 Forwards RC 30-430/80-DA-01
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000600033 First interim deficiency report re control DA audit deficiency welds were found to be inspected & accepted by QC caused by deep overwelds. Inspectors & electrical craft foreman retrained.
Tennessee Valley Authority 00/05/93 2pp

000600041 Forwards final deficiency report re Ruston fire dampers
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000600047a Final deficiency report re Ruston fire dampers. Closure spring detaches from mounting bracket on Ruston vertical forcing closure. EBB fire dampers. Alternative fit of small metal clamp developed & strap-to strip installed to avoid blade.
Tennessee Valley Authority 00/05/93 1p

000610074 Forwards fourth interim deficiency report re defective seat ring seal welds on Borg-Warner valves
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000610079 Fourth interim deficiency report re defective seat ring seal welds on Borg-Warner valves. All inspection completed on representative sample of 10 valves. Four valves failed liquid penetrant inspection.
Tennessee Valley Authority 00/05/93 1p

000610028 Forwards second interim deficiency report re lack of internal purge on Survalite in chemical addition & barren recovery. See Next page will be submitted by 000723
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000610030 Second interim deficiency report re lack of internal purge on Survalite in chemical addition & barren recovery. See. Helds made by welders FARM, FARM, FARM & FARM investigated. Unacceptable welds will be removed & training implemented.
Tennessee Valley Authority 00/05/93 2pp

000610130 Discusses deficiency report re welding in waste disposal system. Forwards steel tank data requested in 000511. Action in response to RC comments re revised Plate 100 and 400.
HILLIS, L. H. Tennessee Valley Authority 00/05/94 1p

000620048 Forwards addl lab data in response to NRC 000511. Action request re deficiencies in welding for waste disposal system.
HILLIS, L. H. Tennessee Valley Authority 00/06/94 1p

000620045 Forwards First interim deficiency report re defective Fillet welds. Next will be submitted by 000715
HILLIS, L. H. Tennessee Valley Authority 00/05/93 1p

000617049 First interim deficiency report re deficient Fillet welds. Action & Fillet welds will be reinspected. QA procedures have been revised & retrained to reflect ASME code requirements.
Tennessee Valley Authority 00/06/93 1p

000620004 Final Part 21 report re mixed head of steel supplied by US Steel. From which 4-inch elbows & branch tees were affixed to 400HP requirement. Investigations conducted & closed at 400HP facilities.
SEAV, J. L. Chemtron Corp., Lake Tennesse, TN 00/06/93 3pp

000620027 Forwards second revised final deficiency report re blown fuses in low voltage switchgear.
HILLIS, L. H. Tennessee Valley Authority 00/06/93 1p

000620020 Second revised final deficiency report re blown fuses in low voltage switchgear. To avoid possibility of fuses opening on inrush current. 3-phase fuses will be replaced w/4-wire fuses.
Tennessee Valley Authority 00/06/93 1p

DOCKET NO. 30-430 BELL-SPRING NUCLEAR PLANT, UNIT 2
A. Application/construction stage documents & correspondence

000620010 Advises NRC & PAH applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria and EDOB/MSU-2 3 Division of Licensing 00/05/93 2pp

000611037 Forwards study plan for monitoring water quality & aquatic biological conditions in Germantown reservoir. Part III 17 of NUREG Part II 0006425
E-0006/01 2 Tennessee Valley Authority 00/06/93 12pp

000610040 Forwards request for addl info re instrument & control sys for continuing review of application for DA.
NURREG-000-3 3 Licensing Branch 1 00/05/93 11pp

000600030 Forwards reorganization chart for OIC of Nuclear Reactor Regulation Facility licensing matters will be handled by R. Borman. Transition being made within of disruption to ongoing activities.
TODERICH, L. Assistant Director for Licensing 00/06/93 2pp

000600046 Forwards response to CD Part 000023 supplemental request for addl info re changes & studies prepared in Part 2 of 791203 response to initial request 000023.
HILLIS, L. H. Tennessee Valley Authority 00/05/93 00pp

F. Security, medical, emergency & fire protection plans

000610037 Forwards clarification of NRC requirements for emergency response facilities defined in 790913. 1st addl specific criteria for facilities under development.
EIDENBUD, J. 3 Division of Operating Reactors 00/06/93 41pp

000600024 Forwards addl info re training & qualification plan. Info withheld (ref 100782 703)
HILLIS, L. H. Tennessee Valley Authority 00/05/93 2pp

G. Inspection reports, IE Bulletins & correspondence

000610019 Forwards IE Bulletin 00-11, "Memory Hall Beagle." No action or written response required. IE Info Notice 70-20. "Overloading of Structural Elements Due to Pipe Support Loads" encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/93 2pp

000600027 Forwards IE Bulletin 00-12, "Deacy Heat Removal Sys Operability." No written response required. IE Info Notice 80-50. "Loss of Deacy Heat Removal Capability at Davis-Beesse Unit 1 While in Refueling Mode" encl.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/93 2pp

000610004 Forwards IE Circular 90-11, "Emergency Diesel Generator Load." No written response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/93 2pp

000612003 Ack receipt of 000910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-430/80-04 & 30-430/80-04.
HARRIS, C. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/93 2pp

000612007 Response to NRC 000423 ltr re violations noted in IE Insp Repts 30-430/80-04 & 30-430/80-04. Corrective actions. Frequency of documented surveillance to ensure welded openings on piping equipment increased to once per week.
HILLIS, L. H. Tennessee Valley Authority 00/05/93 3pp

000612007 Forwards IE Insp Repts 30-430/80-04 & 30-430/80-04 on 000310-21 & notice of violation.
HARRIS, C. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/93 2pp

000612003 Notice of violation from Insp as 000310-21
Region 2, Atlanta, Office of the Director 00/04/93 1p

DOCKETED ITEMS

- 0004120041 IE Insp Repts 50-430/00-04 & 50-439/00-04 on 000410-21 Noncompliance noted failure to follow procedure for capping & sealing during piping gas fabrication & to provide appropriate criteria in insp procedures
USMST, A. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch COLBY, J. L. ALINGSON, M. P. Region 2, Atlanta, Office of the Director 00/04/21 App
- 0004120021 Act receipt of 000402 IE informing NRC of steps taken to correct violations noted in IE Insp Repts 50-430/00-04 & 50-439/00-04
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/09 App
- 0004120037 Response to NRC 000505 IE re violations noted in IE Insp Repts 50-430/00-04 & 50-439/00-04 Corrective actions were released written to reports Council 100-0014-B to eliminate chance of inaccurate cables reinstalled
HILLIS, L. H. Tennessee Valley Authority 00/04/02 App
- 0004120021 Forwarded IE Insp Repts 50-430/00-04 & 50-439/00-04 on 000410-18 & notice of violation
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/05 App
- 0004120032 Notice of violation from Insp on 000410-18
* Region 2, Atlanta, Office of the Director 00/02/03 App
- 0004120034 IE Insp Repts 50-430/00-04 & 50-439/00-04 on 000410-18 Noncompliance noted failure to follow procedure on installation & insp of substructure cables
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J. R. ALINGSON, M. P. Region 2, Atlanta, Office of the Director 00/04/05 App
- 0004120040 Forwarded response to IE Violation 00-01 re valve conditions resulting in damage to help tanks France protection for refueling water storage tank at Sequoyah & Main Bar is provided by redundant barriers & tank insulation
HILLIS, L. H. Tennessee Valley Authority 00/04/05 App
- 0004120019 Act receipt of 000019 IE informing NRC of steps taken to correct violations noted in IE Insp Repts 50-430/00-04 & 50-439/00-05
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/10 App
- 0004120197 Response to NRC 000404 IE re violation noted in IE Insp Repts 50-430/00-04 & 50-439/00-05 Corrective actions noted in IE Insp Repts 50-430/00-04 & 50-439/00-05
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/24 App
- 0004120027 Forwarded IE Insp Repts 50-430/00-04 & 50-439/00-05 on 000402-04 & notice of violation
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/24 App
- 0004120011 Notice of violation from Insp on 000402-04
* Region 2, Atlanta, Office of the Director 00/04/23 App
- 0004120014 IE Insp Repts 50-430/00-05 & 50-439/00-05 on 000402-04 Noncompliance noted failure to maintain proper storage of pressurizing gas components & failure to maintain accurate quality records
USMST, C. E. Region 2, Atlanta, Office of the Director USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/23 App
- B Reportable occurrences, LRS & related correspondence**
- 0004120020 Forwarded First interim deficiency report re voiding of structural steel annular floor framing
HILLIS, L. H. Tennessee Valley Authority 00/05/10 App
- 0004120005 First interim deficiency report re voiding of structural steel annular floor framing Records completed improperly until re-inspected & affected voids will be re-inspected
Inspectors will be re-inspected on completion of QC records
* Tennessee Valley Authority 00/05/10 App
- 0004120003 Forwarded First interim deficiency report re chert Gk audit deficiency
HILLIS, L. H. Tennessee Valley Authority 00/05/10 App
- 0004120007 First interim deficiency report re chert Gk audit deficiency QC audit revealed that three welders & all welder personnel were not included in QC training/re-training confined in 000504 IE re NRC Personnel are being re-trained
* Tennessee Valley Authority 00/05/10 App
- 0004120017 Forwarded final deficiency report re Rustin fire dampers
HILLIS, L. H. Tennessee Valley Authority 00/05/02 App
- 0004120016 Final deficiency report re Rustin fire dampers Closure of rustin mounting bracket on Rustin vertical spring closure, 180 fire dampers Alternative fix of small metal clamp developed & snap-in strip installed to hold plate
* Tennessee Valley Authority 00/05/02 App
- 0004120014 Forwarded Fourth interim deficiency report re defective seal weld on Berg-Harper valves
HILLIS, L. H. Tennessee Valley Authority 00/04/03 App
- 0004120019 Fourth interim deficiency report re defective seal ring on weld on Berg-Harper valves 0011 issue completed on representative sample of 93 valves Four valves failed liquid gastight test
* Tennessee Valley Authority 00/04/03 App
- 0004120028 Forwarded second interim deficiency report re lack of internal purge on two voids in chemical addition & burner recovery
void test will be submitted by 000502
HILLIS, L. H. Tennessee Valley Authority 00/04/03 App
- 0004120030 Second interim deficiency report re lack of internal purge on two voids in chemical addition & burner recovery
void test will be submitted by 000502
HILLIS, L. H. Tennessee Valley Authority 00/04/03 App
- 0004120018 Discussed deficiency report re voiding in waste disposal area
Forwarded audit lab data requested in 000501 action in response to IE comments on revised final report void and
HILLIS, L. H. Tennessee Valley Authority 00/04/04 App
- 0004120040 Forwarded audit lab data in response to NRC 000501 action
re voiding in IE comments on revised final report void and
HILLIS, L. H. Tennessee Valley Authority 00/04/04 App
- 0004120040 Forwarded final interim deficient report re defective fillet welds 0019 report will be submitted by 000501
HILLIS, L. H. Tennessee Valley Authority 00/04/04 App
- 0004120019 First interim deficiency report re deficient fillet welds, Beaker & flame fillet welds will be reinspected QA procedures have been revised & revised to reflect ASME code requirements
* Tennessee Valley Authority 00/04/06 App
- 0004120004 Final Part 21 report re mixed heat of steel supplied by US
Mixed from 4-inch above & 2-inch below were mfg to ASME requirements, investigations conducted & closed at 45 listed facilities
USMST, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/06 App
- 0004120027 Forwarded second revised final deficiency report re steam duct in low voltage substation
HILLIS, L. H. Tennessee Valley Authority 00/04/20 App
- 0004120020 Second revised final deficiency report re blown fuse in low voltage substation To avoid possibility of fuse opening on inrush current, 2-amp fuse will be replaced w/4-amp fuse
* Tennessee Valley Authority 00/04/20 App
- C Utility Environmental Report (ERI), audits & correspondence**
- 0004120040 PERRY NUCLEAR POWER PLANT, UNIT 3
Cleveland Electric Illuminating Co
A Application/construction stage documents & correspondence
- 0004120010 Advise EIR & PAR applicants of NRC decision to modify
contamination plan presented in Division 4 of 000405-0077 re adequacy of applicable support structure General operating reactor review procedure & acceptance criteria and
EIR/0007, D. Division of Licensing 00/05/00 App
- 0004120075 Notification of 000410 meeting w/ utility in Bethesda, MD to discuss facility DL application & schedule
HARRIS, J. R. Licensing Branch 21 00/04/13 App
- C Utility Environmental Report (ERI), audits & correspondence**
- 0004120028 Forwarded annular report, Vols 1 & 2
Cleveland Electric Illuminating Co 00/04/28 App
- 0004120020 Electric report, Vol 1
* Cleveland Electric Illuminating Co 00/04/20 App

DOCKETED ITEMS

--0004270205 Envision reph:Vol 2
+ Cleveland Electric Illuminating Co 00/06/20 350pp

I Financial Information

0004270205 Forwards amend to application for GL including of 1979 annual repts for Duquesne Light, Toledo Edison, Cleveland Electric Illuminating Co, and Power Co & Co Electric Co
00/05/20 0 0 Cleveland Electric Illuminating Co 00/06/20 1p

--0004270206 Amend to application for GL including annual repts for 5 utility and miscellaneous financial info
+ Cleveland Electric Illuminating Co 00/06/20 400pp

H Antitrust correspondence

0004260204 Requests that deadline for requests for hearings be extended to 000700 re availability of information and Extension will allow NRC & intervenor to work out language discord between PERC opinion 04 & NRC 000513 order
00/05/05 0 Cleveland, OH SOLBERG, R Goldberg-Fieldman & Latham P C 00/06/22 2pp

0004270205 Motion for and of NRC 000513 order to require filing of transmission schedule per PERC 000505 order Requests hearing on 000513 order if NRC denies said Certificate of Due well
USAM, J R Justice Dept of 00/06/09 12pp

G Inspection reports, 3E Bulletin & correspondence

0004260378 Responds to 3E Bulletin 00-09 re hydrogenator actuator deficiencies Vendor supplying valve actuators indicated that only Power Regulatory Co supplied TTT General Model NW-90 hydrogenator actuators Model NW-90 not supplied
00/05/20 0 Cleveland Electric Illuminating Co 00/06/18 1p

E Reportable occurrences, LEM & related correspondence

0004020279 Part 21 re possible noncompliance of motor control ctra to container space unit will be requested to remove units & Motion for ultra and will be authorized by various necessary blocks
00/05/05 0 Gutter-Hanner, Inc 00/05/19 3pp

0004260205 Act receipt of 000502 interim deficiency reph re pump failures on Comby post-LOGA hydrogen analyzers Review of action will be completed during future into
FIORELLI, B Region 2 Chicago, Reactor Construction & Engineering Support Branch 00/06/10 1p

DOCKET 90-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

0004230210 Advises NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NRC03-0077 re adequacy of applicable support structures general operating reactor review procedure & acceptance criteria and
CIBROW, J D Division of Licensing 00/05/20 13pp

0004250216 Notification of 000619 meeting until in Bethesda, MD to discuss facility GL application & schedule
00/06/10 0 Licensing Branch 2 00/06/13 0pp

C Utility Environmental Report (UR), amendments & correspondence

0004270205 Forwards envision reph:Vol 1 & 2
00/05/20 0 Cleveland Electric Illuminating Co 00/06/20 1p

--0004270206 Envision reph:Vol 1
+ Cleveland Electric Illuminating Co 00/06/20 250pp

--0004270205 Envision reph:Vol 2
+ Cleveland Electric Illuminating Co 00/06/20 320pp

I Financial Information

0004270205 Forwards amend to application for GL consisting of 1979 annual repts for Duquesne Light, Toledo Edison, Cleveland Electric Illuminating Co, and Power Co & Co Electric Co
00/05/20 0 Cleveland Electric Illuminating Co 00/06/20 1p

--0004270206 Amend to application for GL including annual repts for 5 utility and miscellaneous financial info
+ Cleveland Electric Illuminating Co 00/06/20 400pp

H Antitrust correspondence

0004260204 Requests that deadline for requests for hearings be extended to 000700 re availability of information and Extension will allow NRC & intervenor to work out language discord between PERC opinion 04 & NRC 000513 order
00/05/05 0 Cleveland, OH SOLBERG, R Goldberg-Fieldman & Latham P C 00/06/22 2pp

0004270205 Motion for and of NRC 000513 order to require filing of transmission schedule per PERC 000505 order Requests hearing on 000513 order if NRC denies said Certificate of Due well
USAM, J R Justice Dept of 00/06/09 12pp

G Inspection reports, 3E Bulletin & correspondence

0004260378 Responds to 3E Bulletin 00-09 re hydrogenator actuator deficiencies Vendor supplying valve actuators indicated that only Power Regulatory Co supplied TTT General Model NW-90 hydrogenator actuators Model NW-90 not supplied
00/05/20 0 Cleveland Electric Illuminating Co 00/06/18 1p

E Reportable occurrences, LEM & related correspondence

0004260205 Act receipt of 000502 interim deficiency reph re pump failures on Comby post-LOGA hydrogen analyzers Review of action will be completed during future into
FIORELLI, B Region 2 Chicago, Reactor Construction & Engineering Support Branch 00/06/10 1p

DOCKET 90-442 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

0004270210 Advises NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NRC03-0077 re adequacy of applicable support structures general operating reactor review procedure & acceptance criteria and
CIBROW, J D Division of Licensing 00/05/20 13pp

0004260205 Responds to 791013 1p requesting use of certain AGNE code cases in case of components for Facility Code Cases M-237, N-218 & N-236 are acceptable use of code cases should be documented in FRM
YOUNG, G B J Licensing Branch 1 00/05/20 2pp

G Application correspondence

0004260102 Forwards written remarks to be made part of 000322 briefing before Commission re review of ASL&B seismic devices
ALAB-028 & ALAB-041 Requests copy of device
NEHOLD, E H Affiliation Unknown 00/05/17 1p

--0004260101 Urges that Commission grant New England coalition on Nuclear Pollution petition to review ASL&B decisions on seismic design Requests review of current comments & NRC quarterly bulletin supporting activities
NEHOLD, E H Affiliation Unknown 00/05/17 2pp

0004260479 Informs NRC that financial difficulties prohibit attendance at 000322 briefing re intervenor New England Coalition on Nuclear Pollution petition for review of ASL&B-028 & ALAB-041 Forwards written remarks for inclusion in record
NEHOLD, E H Affiliation Unknown 00/05/17 4pp

0004260479 Advises that Chimney will make major portion of New England Coalition on Nuclear Power presentation at Thursday briefing Operating equipment for viewgraphs necessary
NEHOLD, E H Region, HANCOCK & HANCO NEHOLD, E H New England Coalition on Nuclear Pollution 00/05/20 1p

0004260328 Prepares on behalf of New England Coalition on Nuclear Pollution that three listed documents be included in record of pending proceeding re seismic risk Forwards MA Inst of Technology re "Investigation of Max Possible Earthquakes"
NEHOLD, E H Region, HANCOCK & HANCO 00/06/11 4pp

--0004260328 "Investigation of Max Possible Earthquakes," annual reph
CHANNING, M A Massachusetts Institute of Technology
NRC-04-77-019 70/05/13 70pp

DOCKETED ITEMS

217

6140100 Order granting extension until 000425 For Commission to
review Director's 000211 decision denying petition for
emergency planning & Class 9 accidents, under 10CFR2.205
HLM, & 2 Office of the Secretary of the Commission 00/06/11
a

6180404 Order granting extension until 000627 for Commission to
1944 whether to review ALAB-432 & ALAB-541

4230261 Response in opposition to New England Coalition on Nuclear
 4230262 petition H0363; action to reopen record & introduce new
 4230263 evidence (Chernobyl theory ignores geology) for NRC purposes
 4230264 RNS dismissal of petition for review M/Certificate of Ene
 4230265 10/04/17 0. RTHWHR/J A Scope 5 Gray 8/05/17 7pp

659049; Response to New England Coalition on Nuclear
Collection EDOAS its requesting reopening of record to enter
Nine articles & EDOAS holding transcript Admittance
could violate rules of evidence Certificate of Use and
EIS, E. J. Heavens Branch 2 06/06/24 3pp

General correspondence

004170183 Submits extract of Kensington, NH 800313 town meeting minutes
Re evacuation of 10-50 mile radius around nuclear
facilities. License should not be granted until safe
evacuation plan demonstrated
CARTMAN, C. R. GRANVILLE, New Hampshire, phone of 8070428 in

MOBILITY Responds to encl B00441N ltr to President Carter expressing
 opposition to coast of facilities NRC authority does not
 extend to planning for adequate electrical generating
 capacity or for siting/adding in state & local decisions
 2/10/79, 2 p. 1 (encl B00441N) 1 p. 2 (encl B00441N) 1 p. 3

N300240 Responds to 791041 ltr to President Carter requesting halt
convet until safe & timely evacuation plan is achieved NRC
emergency planning review will include re-evaluation of
existing licenses & local & state govt emergency plans
BENTON, H R Office of Nuclear Reactor Regulation, Director
D/DG/13 ggc

060000251 Forwards 06 Dunfeg,EO Pavear,EF Parr & P Keenan 791011 11z
to President Carter requesting halt of coast until safe &
timely evacuation plan is achieved. Headcast area cannot be
evacuated in event of serious accident.
SEAL.#11. President of US & Executive Offices 79/10/17 2pg

Anti-trust correspondence

6240207 Advises that FEC of H&M add antitrust info will not be
provided as stated in H&M Shaper 800515 ltr to Atty General
COMMUNIT. Antitrust Division 80024104 2c

Investigation reports, EE Bulletin & correspondence

5060251 Forwards combined IE Insp Repts 90-443/90-01 & 90-444/90-01
a arrests of coast workers on charges of conspiracy to
isolate state drug laws No concern necessary re quality of
coast work & drug inquiry
RTER, E H Region I, Philadelphia, Office of the Director
2/20/11 in

52000000 Ferrous DE Circular 80-13. "Grid Strap Damage in
extinguisher Fuel Assemblies." No written response required
TIGER, H. W. Region I, Philadelphia. Office of the Director
3/25/78 In

N98027A Responds to IE Bulletin 88-05, "Vacuum Condition Resulting
 in Damage to Chemical Vapour Control Sys Holdup Tanks." All
 units except resin sludge & primary drain tanks either will
 not experience or can withstand full vacuum conditions
 instantaneously. Public Service Co. of New Hampshire 88/05/05 A

Non-portable occurrences, LERs & related correspondence

5/22/00: Part 21 rept no discrepancy in seismic design in containment
 vessel area cause unstated details contained in unit
 212225 deficiency rept

0005180072 Park 21 rept re util use of levellid seismic Amplifier
measuror spectra GasPira 8N Leonard 808020 talces w/WP
Reimarth of revision to final rept date Short-term audit &
redesign of containment annular steel complete
SARSTEN, D E United Engineers & Constructors, Inc (kabe of
Southern Co) 80/05/02 4ea

5 Hearing transcripts on consent/assent matters

8002620075 Transcript of 800329 afternoon public meeting in Washington, DC re atomic issue Pg 1-32 Supporting documentation encl
 AHEARNE, J F. GILLINBERG, J. BRADFORD, P A Completion 80/05/29
 1110

SECRET 50-444 BROADBENT NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8004233110 Advises DNR & PWR applicants of NRC decision to modify implementation plan presented to Section 4 of MREX-0577 re adequacy of applicable support structures General operating reactor review procedure & Acceptance criteria encl
EIS004477, D O Division of Licensing 06/05/20 1300

EC06180648 Responds to 7991018 Rfr.requesting use of certain ASM
cases in const of components for Facility Code Cases M-237,
M-215 & M-258 are acceptable Use of code cases should be
documented in FEAR
YOUNGBLOOD, D J Licensing Branch 1 EO/05/90 Zpp

© Adjudicators correspondence

EO60408B2 Forwards written remarks to be made part of 800020 briefing before Commission re review of ASAB scientific decision
ALAB-422 to ALAB-061 Requests copy of decision
HEINROLD, E M Affiliation Unknown EO/DOJ/17 is

--B000408791 Urges that Commission grant New England coalition on Nuclear Pollution petition to review AILAB decisions on seismic design Requests review of current comments & NRC quarterly bulletins supporting activities

EO0308247 Inform: HRC What Financial Difficulties prohibit attendance
at 000023 briefing re Interview New England Coalition on
Nuclear Pollution petition for review of ALAB-422 b
ALAB-266 Petitioners written PARAGRAPHS for inclusion in RECORD
0010404.E.H.M. Affiliation Unknown. 00/05/17 des

0006110044 Advises that Chinnery will make major portion of New England Coalition on Nuclear Power presentation at Thursday briefing Operating equipment for videography necessary
WEISS, E E Shelden, Harmon & Weiss WEISS, E E New England Coalition on Nuclear Pollution 00/05/80 1a.

EO0160007 Proposed on behalf of New England Coalition on Nuclear
Pollution, that three listed documents be included in record
of pending proceeding re atomic risks. Forwarded NM Inst of
Technology re: "Investigation of New Possible Earthquakes"
NEISS-E E. Shotton, Harwood & Weiss. 00/05/11 bps

--DOOSEBERRY "Investigation of Max Possible Earthquakes" annual rept
CHENBERY, M A Massachusetts Institute of Technology
MRC-04-22-019 78/08/10 WDC

8006150160 Under-granting extension until 805625 for Commission to review Director's 805211 decision denying petition re emergency planning & Class T accidents-under 100PFR 205 CHLR, S J Office of the Secretary of the Commission 80/06/11 1a

8006180406 Order granting extension until 800627 for Commission to
start whether to review ALAB-822 & ALAB-861
COLUMBIA, S.C. Office of the Secretary of the Commission. 8000611

0004200061 Response in opposition to New England Coalition on Nuclear
Proliferation 000411 notice to reopen record & introduce new
evidence Chingery theory ignores geology for NME purposes
Under dismissal of petition for review W/Certificate of Rev
0000041 T.O. - RITCHEY, J.A. Rosen & Gray 000404/17 7m

BOG600491 Response to application to New England Cellulose re New
Petition BOG60111 by requesting reopening of record to enter
Chimney articles & BOG6027 briefing transcript Admittance
would violate rules of evidence Certificate of Div and
MSB, E. J. Hastings Branch D. BOG6026. See.

Reportable occurrences: LERs & related correspondence

DOCKETED ITEMS

219

0034240005 Statement of position on ALAB-1990 application to
admissibility of intervenor contentions. Opinion places
intervenor under no obligation to establish validity of
contentions. Certificate of Dvc encl
DAY, D H Association of Community Organizations For Reform
New-Texas DAY, D H West Texas Legal Services 00/05/12 App

0034240007 Statement of position re 04/30 contention. Urges keeping
contention broad at this stage in interest of justice & in
compliance with ALAB-1990 Certificate of Dvc encl
DAY, D H Association of Community Organizations For Reform
New-Texas DAY, D H West Texas Legal Services 00/05/12 App

0034240009 Forward Commission 000016 memorandum & order ruling on
certified question of litigability of combustible gas
control issue
RDTHSCHILB, H U Hearing Branch 1 00/05/03 1p

0034240010 Forward final version of DUBED-0040, "NRC Action Plan
Developed as Result of TMI-2 Accident," Vols 1 & 2 W/enc
RDTHSCHILB, H U Hearing Branch 1 00/05/03 1p

0034240044 Order accepting Citizenn For Fair Util Regulation
Contentions 1,24,25,34 & 36 & Association of Community
Organizations For Reform New Contentions 1,3 - 11,14,25,26,
28,34,35 & 36
0034240045 E Atlantic Safety and Licensing Board Panel 00/06/16
18pp

Re Antitrust correspondence

0034102043 Discovery reph for Mar 1989 No discovery requests initiated
or received. Certificate of Dvc & change of address notice
encl
JOHN, D F Southwest Texas Electric Cooperative JOHN, D F
McDonnell-Will & Emery 00/04/16 5pp

0034240020 Corrects misstatement of fact in Public Utility Board of City
of Brownsville, 73 Member 1960 discovery reph. Failure to
participate in J. Brownman deposition was due to counsel
independent decision not to attend. Certificate of Dvc encl
STAHM, D H Jahan, Lincoln & Beale 00/05/01 App

0034102054 Motion for 003009 prehearing conference to apprise ARB of
status of settlement discussions. Prepaid order &
Certificate of Dvc encl
CYRNET, D B - DPHRIVIC, D A, LUGER, N Justice, Dept of 00/05/05
5pp

0034240024 Forward status reph. Delivery arrangements made for 003512
003512, J B Debevoise & Liberman 00/05/09 1p

--0034240044 Status reph re settlement negotiations' progress
Discussions are continuing. Urges ARB to hold prehearing
conference by 003014 & request deferral of ruling on
extension Certificate of Dvc & supporting documents encl
SAMPWEL, H D Texas Utilities Co SAMPWEL, H D Sherman, Paraghis
& Samuels 00/05/09 20pp

0034240033 Forward Houston Lighting & Power status of settlement reph.
per ARB 000410 order Affidavit not appropriate
003512, D O Louisiana-Houston, Ret. Arivaz & Toll 00/05/09 2pp

--0034240034 Status of settlement reph per ARB 000410 order deferring
trial. Briefs, final prehearing conference & evidentiary
hearing. Urges add 30-day extension for continuance of
negotiations due to complexity. Certificate of Dvc encl
WANNETT, E W Houston Lighting & Power Co 00/05/09 7pp

0034240042 Status reph re settlement discussions' progress. Urges ARB to
commence pretrial conference to accommodate outstanding
discovery. Final trial preparation & resolution of remaining
procedural matters. Certificate of Dvc encl
CYRNET, D B - PARMENTER, P DPHRIVIC, D A Justice, Dept of
00/05/09 9pp

0034102030 Forward reph on status of settlement
003512, D O Louisiana-Houston, Ret. Arivaz & Toll 00/05/09 2pp

0034102107 Repl on settlement negotiations. Suggests that conference be
held on alternate odd time needed by applicant. Trial should
be preceded by pretrial conference to accommodate discovery
& other matters. Certificate of Dvc
CYRNET, D B - PARMENTER, P DPHRIVIC, D A Justice, Dept of
00/05/09 9pp

0034232157 Settlement status reph by Public Utility Board of Brownsville.
Trial Prepaid early trial schedule & 30-day extension to
ensure possibility of settlement. Certificate of Dvc encl
SPIGIEL, D Brownsville, TX SPIGIEL, D Spiegel & McDaniel
00/05/09 App

0034240020 Status reph on settlement negotiations per ARB 000410
order. Requests 30-day extension in procedural dates to allow
consummation of discussions. Certificate of Dvc encl
STAHM, D H Jahan, Lincoln & Beale 00/05/09 10pp

0034240193 Reinit status reph on settlement negotiations per ARB
000410 order. Joint ownership agreement will be completed by
0010: Supporting documents & Certificate of Dvc encl
BURCHFIELD, M H - STITH, F R Texas-Louisiana Electric Cooperative, Inc.
BURCHFIELD, M H Northcutt, F H 00/05/09 27pp

0034240044 Discovery reph for Apr 1989 Util counsel participated in
depositions of NC Lerner & S Taylor, expert economic
witnesses for NRC & DOT, respectively
ANAHN, C B Texas Utilities Co ANAHN, C B Debevoise & Liberman
00/05/13 2pp

00342400175 Discovery reph for Apr 1989 Participated in NC Lerner & S
Taylor. Depositions Reviewed NRC updated response to Houston
Lighting & Power second set of interrogatories. Expected NRC
documents designated by expert witness
ANAHN, C B Texas Utilities Generating Co ANAHN, C B Debevoise &
Liberman 00/05/15 2pp

00342400142 Discovery reph for Apr 1989 Participated in QTC Taylor
deposition. Responded to Houston Lighting & Power motion to
compel production of documents. Understood settlement
discussions & brief Preparation. Certificate of Dvc encl,
CYRNET, D B Justice, Dept of 00/05/13 3pp

0034240043 Motion to establish trial & procedural dates. Prepaid 003009
Per settlement reph, 003010 Per prehearing, 003013 Per
witness links & briefs, 003027 for responding parties &
003030 for final prehearing conference. Certificate of Dvc
CYRNET, D B - PARMENTER, P DPHRIVIC, D A Justice, Dept of
00/05/11 App

0034102043 Discovery reph for Apr 1989 Attended continuation of NC
Lerner. Deposition. Responded to Houston Lighting & Power
Final set of interrogatories. Joint parties' motion for 30-day
extension. Certificate of Dvc encl
SAMPWEL, H D Central & South West Corp 00/05/12 4pp

0034102024 Forward documents corrected Page 2 to 003030 motion to establish
trial & other procedural dates. Certificate of Dvc encl
CYRNET, D B Justice, Dept of 00/05/23 1p

--0034102077 Corrected Page 3 to 003030 motion to establish trial &
other procedural dates. Certificate of Dvc encl
CYRNET, D B - PARMENTER, P DPHRIVIC, D A Justice, Dept of
00/05/21 4pp

0034102025 Reply in opposition to DOJ 003021 motion to establish trial &
other procedural dates. Request premature, ARB should
address previous discussion that parties address schedule
to 003010 prehearing conference. Certificate of Dvc encl
003512, J B Debevoise & Liberman 00/05/20 2pp

0034032272 Notice of appearance in proceeding Certificate of Dvc encl,
LEWIS, D H Hearing Branch 2 00/06/03 4pp

0034102142 Motion to establish trial & procedural dates. Appearing in proceeding on
behalf of NRC in response of O Deigned & Deigned & McDaniel
representing Public Utility Board of City of Brownsville, TX
No conflict of interest exists
CHAMBERLAIN, P D Antitrust Division 00/06/06 1p

0034102034 Repl on settlement negotiations per ARB 000410 order.
Requests 30-day extension for prehearing conference to resolve &
narrow issues. Prehearing conference should be held at end of
extension. Certificate of Dvc encl
SAMPWEL, H D - WANNETT, E W Texas Utilities Generating Co
SAMPWEL, H D Sherman, Paraghis & Samuels 00/06/09 3pp

0034102030 Second settlement status reph per ARB 000410 order. Urges
add 60 to 90-day extension to permit continued efforts.
Complex areas re scheduling & access to dc interconnections
remain under continuing study. Certificate of Dvc encl
CHAMBERLAIN, P D Antitrust Division 00/06/09 7pp

DO0410297 Reclamation status report per ASLD 000003 order Urges establishment of trial date to complete outstanding ASLD discovery, to resolve ASLD discovery & to expedite final trial preparation Certificate of Doc and

CYPHENT, S B Justice Dept of MO/06/07 app

0004098040 Ack receipt of IE Insp Repts 50-445/80-07 & IE Investigation
Repts 50-445/80-02 & 50-446/80-02 No Proprietary Info
GARY, R J Texas Utilities Generating Co 80/04/87 1p

GETTLE, H C Region 4, Dallas, Reardon Construction & Engineering
Support Branch 03/04/18 Rep

--0006120027 Notice of violation from may dating Mar 1980
* Region 4, Dallas, Reactor Construction & Engineering Support
Branch 80/04/19 10

--M00412001 HE Insp Repts 50-445/50-08 & 50-446/50-08 during Mar 1960
Noncompliance noted failure to follow procedures for repair
of damaged table & failure to report significant test
deficiency
TAYLOR, R G , CROSSMAN, W A, Region 4, Dallas, Office of the
Attorney M0041216 10a

8004192218 Forwards Hgt Hoisting Repts 90-445/85-12 & 90-445/86-12 on
800406 No noncompliance noted
SEIBLE, H C Region 4; Dallas, Regular Construction & Engineering

--0001100000 Mgt Meeting Repts 00-440/90-12 & 00-444/90-12 on 000000 No noncompliance noted Areas discussed at meeting reparability & documentation of significant control deficiencies & other events of NRC interest not within reporting requirements CROSBMAN-W & TAYLOR-R G, REIDLE-W C Region 4, Dallas, Office of the Director 00/03/99 dca

60061936a3 Advises that IC Insp Repts 92-445/80-09 & 92-446/80-09
contain no proprietary info
GARY, R J Texas Utilities Generating Co 60/05/08 ip

BO0400286. Forwards IE Bulletin 00-10. "Decay Heat Removal Sys
Capability." No written response required IE Info Notice
00-00. "Loss of Decay Heat Removal Capability at Davis-Besse

SECRET, R V Region 4 Dallas Office of the Director 00/00/00
lp

EO0410018 Advises NRC that IE Insp Repts SO-445/80-08 & SO-446/80-09
do not contain any proprietary info
DARY, R J Texas Utilities Generating Co SO/05/10 ip

0006090580 Ack receipt of 000505 ltr informing MPO of steps taken to
address violation noted in EC Insp Rpts 80-445/80-11 &
80-446/80-11
GEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Boswell Branch 80/85/14 is

20. Antineoplastic Nursing: Sparsigels

0056200013 Forwards IE Circular 00-18, "Valve-Shaft-To-Actuator Key Key
Fail Out of Place When Mounted Below Horizontal Axis " No
written response required
SEVPRET, A V Region 4, Dallas, Office of the Director 00/03/94
is

6866050110 Ack receipt of 003505 ltr informing NRC of steps taken to correct violation noted in IC Insp Regs 90-443/EO-QT 4
90-443/EO-QT

4 Inspection reports, DE Bulletin & correspondence

--000000103 Response to TRC 000487 ltr re violation noted in IE Insp
Nepht 30-643/00-09 & 30-646/00-09 Corrective actions
conducted review of flow measuring instrumentation, meter
demand & recording procedure
Q857.R v Texas Utilities Generation Co. 00/00/00 Jax

--0004050115 Pasadena IE Insp Repts 50-445/00-09 & 50-446/00-09 on
#000312-14 & notice of violation
38504-G-2 Region 4, Dallas Fuel Facility & Materials Safety
Branch 80/04/07 Zpp

--0006050117 Notice of violation from Insp on 000312-14
* Regles 4. Sajas. Office of the Director 00/00/00 to

0004050202 IF Insp Repts 50-445/00-07 & 50-446/00-09 on 000401-14
noncompliance noted pursuant to withdrawal rules above
1 unit
BUTLER, D B Region 4, Dallas, Fuel Facility & Materials Safety
Branch 00/05/01 Region 4, Dallas, Office of the Director
00/05/31 7pp

0004050740 Advice that IE Insp Repts 50-446/00-17 & 50-446/00-12
contain no prosecutable info
GARY, R J Texas Utilities Generating Co 00/05/01 1p

0004050207 Forward IF Insp Repts 50-445/00-13 & 50-446/00-13 on
000401-20 & notice of violation
BUTLER, D B Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/05/31 7pp

0004050209 Notice of violation from Insp on 000401-20
re Region 4, Dallas, Office of the Director 00/05/02 4pp

0004050201 IE Insp Repts 50-447/00-13 & 50-446/00-13 on 000401-03
noncompliance noted Failure to follow welding & Insp
procedures
BUTLER, D B Region 4, Dallas, Reactor Construction & Engineering
Support Branch 000500-01, A. OILHEIT, L Region 4, Dallas,
Office of the Director 00/05/02 7pp

0004050240 Ack receipt of 000510 Insp Informing MEO of steps taken to
correct violation noted in IE Insp Repts 50-445/00-00 &
50-446/00-00
BUTLER, D B Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/05/02 1p

0004050245 Response to MEO 000401-14 re violation noted in IE Insp
Repts 50-445/00-00 & 50-446/00-00 Corrective actions cable
sent pulled back during investigation of damage to cable
jarret A will be replaced
GARY, R J Texas Utilities Generating Co 00/05/04 2pp

0004050310 Response to IE Bulletin 00-05 re vacuum condition resulting
in damage to chemical wet holding tanks Licensee review is
not yet complete Thus far, all affected tanks are in ABBN
state of supply, except 000310 holding tanks
GARY, R J Texas Utilities Generating Co 00/05/02 1p

D Reportable occurrences, LRA & related correspondence

0004050570 Efficiency report re apparent discrepancy in installation &
Insp requirements for Class D sub-nuclear safety-related
piping support format report should be submitted by 000710
GARY, R J Texas Utilities Generating Co 00/04/01 1p

0004050576 Efficiency report re welded control cable connections, updating
000301 report must be completed by 000701
GARY, R J Texas Utilities Generating Co 00/05/02 1p

0004050624 Supplemental deficiency report re 1901-03 2000 PSI installation
piping mis wall engineering review & disposition of mis
wall violations at units & base noted defects in continuing
activities exhibiting next progress sent by 001210
GARY, R J Texas Utilities Generating Co 00/05/19 1p

T Hearing transcripts on non-intervent matters

0004100209 Submits proposed corrections to transcript of 000430 & 0001
proceeding conference held in Port Worth, TX Certificate of
Dnc met
REYNOLDS, N B Texas Utilities Generating Co REYNOLDS, N B
Delaney & Liberman 00/06/15 27pp

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC B76 UNIT 2

A Application/construction stage documents & correspondence

0004050110 Advise BMR & PWR applicants of NRC decision to modify
implementation plan presented in Section 4 of 000501-0077 re
accuracy of applicable support structure General operating
reactor review procedure & acceptance criteria incl
EISENHART, D D Division of Licensing 00/05/02 13pp

0004050207 Summary of 000310 meeting w/utl in Bethesda, MD re
instrumentation & control sys
BUTLER, D B Licensing Branch 2 00/05/02 6pp

0004050404 Summary of 000420 meeting w/utl in Bethesda, MD re
reliability evaluation of auxiliary feedwater sys
BUTLER, D B Licensing Branch 2 00/05/03 4pp

0004100240 Forward qualification test schedule & status per Class IE
equipment to be supplied by vendor Submittal in response to
action item per 000507 meeting re qualification programs &
revised, required to submit timely issuance of QI
ANDERSON, T H Westinghouse Electric Corp 00/06/03 2pp

0004050510 Notice that utl has provided detailed design info re
plant analysis of main steam line inside containment Action
is taken in conformance w/NRC PM Operating Procedure 209.
Revision 1, "Submittal of Supplementary Detailed Data"
BUTLER, D B Licensing Branch 2 00/04/06 1p

0004050520 Lists ltr incorporating detailed electrical
instrumentation & control drawings re facility design Action
is taken in conformance w/NRC PM Operating Procedure 209.
Revision 1, "Submittal of Supplementary Detailed Data"
BUTLER, D B Licensing Branch 2 00/04/06 1p

0004050422 Notification of 000418 & IV meetings w/utl & ABE in
Bethesda & Silver Spring, MD, respectively, re review
electrical instrumentation & control drawings for conformance
w/separation redundancy & signal failure criteria
BUTLER, D B Licensing Branch 2 00/04/12 2pp

0004100405 Forward electrical instrumentation & control drawings List
of drawings & revision status incl Drawings available in
control files only
GARY, R J Texas Utilities Generating Co 00/06/13 2pp

F Security, medical, emergency & fire protection plans

0004100307 Forward classification of NRC requirements for emergency
response facilities defined in 790912 3dr Add specific
criteria for facilities under development
FISCHER, D D Division of Operating Branch 00/04/02 40pp

0004050205 Summary of 000510 meeting w/utl in Bethesda, MD re fire
protection criteria
BUTLER, D B Licensing Branch 2 00/06/07 3pp

G Administrative correspondence

0004050205 Motion to compel applicants to supply 000410 position on
submissions per ABE 000410 order re prehearing conference
schedule Urges postponement of 000420 prehearing conference
pending receipt & review of position by Certificate of Dnc
BUTLER, D B Citizens Association for Sound Energy 00/04/01 4pp

0004050207 Corrects typographical omissions & errors made in Intervenor
000410 position on containment, table of contents incl
BUTLER, D B Citizens Association for Sound Energy 00/04/01 4pp

0004050201 Corrects typographical errors made in Intervenor 000410
motion for extension of time & 000410 motion to compel
Containment Certificate of Dnc incl
BUTLER, D B Citizens Association for Sound Energy 00/04/01 2pp

0004050204 Notice in support of Intervenor Contention 19 re 00/03
Present working covers areas of concern re design, testing,
operational & administrative controls Proposed other version
if present wording is not accepted Certificate of Dnc incl
BUTLER, D B Citizens Association for Sound Energy 00/05/12 10pp

0004050307 Post-hearing conference memo/minutes exhibiting statement of
position re impact of ALAB-590 wording of Citizens'
Association for Sound Energy commitments & Intervenor's
proposed 00/03 contention Certificate of Dnc incl
REYNOLDS, N B & REYNOLDS, N B Texas Utilities Generating Co
REYNOLDS, N B Delaney & Liberman 00/05/12 13pp

0004050301 Position on Contention 4 A, Intervenor supports present
wording of contention & modification of Contention 4 B
Interim 4 B special operating requirements in prehearing
Certificate of Dnc incl
FISCHER, D A Citizens for Fair Utility Regulation 00/05/12 4pp

0004050205 Statement of position re ALAB-590 application to
admissibility of Intervenor's tentative Opinion places
Intervenor under an obligation to explain validity of
contention Certificate of Dnc incl
GARY, D M Association of Community Organizations for Reform
Now-Texas GARY, D M West Texas Legal Services 00/05/12 1pp

0004050307 Statement of position re 00/03 contention Urges keeping
contention broad as this stage in interest of justice & in
compliance w/ALAB-590 Certificate of Dnc incl
GARY, D M Association of Community Organizations for Reform
Now-Texas GARY, D M West Texas Legal Services 00/05/12 3pp

8004020075 Forwards Commission 800516 memorandum and order ruling on certifying question of liability/apportionment of contributory gas control issues
ROTHGCHILB, H U Hearing Branch 3 00/05/08 1p

8004020076 Forwards Final version of ASLES-0460, "NRC Action Plan Developed as Result of TMI-2 Accidents," Vols 1 & 2 W/ve encl
ROTHGCHILB, H U Hearing Branch 3 00/05/08 1p

8004020078 Order accepting Citizens for Fair Use Regulation Contention 1, 2a, 2b, 2c & 2d & Association of Community Organizations for Reform Now Contentions 1, 2 - 11, 14, 15, 20, 22, 24, 25 & 26
ROTHGCHILB, H U Atomic Safety and Licensing Board Panel 00/05/16 14pp

N Antitrust Correspondence

8004020079 Discovery reft for Mar 1980 No discovery requests initiated or received Certificate of Doc & change of address notice encl
JOHN, D F Houston Texas Electric Cooperative JOHN, D F Houston, TX & Encl 00/05/16 5pp

8004020080 Corrects misstatement of fact in Public Utility Board of City of Brownsville, TX, Mar-Apr 1980 discovery reft Failure to participate in J. Douglas deposition was due to counsel independent decision not to attend Certificate of Doc encl
STAMP, D H Inham, Lincoln & Beale 00/05/01 App

8004020081 Motion for 800509 prehearing conference to apprise ASLB of status of settlement discussions Proposed order & Certificate of Doc encl
CYPHERT, S B & DORFMAN, D A & LIGUE, H Justice, Dept of 00/05/08 5pp

8004020082 Forwards status reft Delivery arrangements made for 800512 KNOTTS, J B Debevoise & Liberman 00/05/09 1p

--8004020083 Status reft re settlement negotiations' progress Discussions are continuing Urges ASLB to hold prehearing conference by 800514 & requests deferral of ruling on outstanding Certificate of Doc & supporting documents encl
BARNETT, E W Texas Utilities Co GUNDEL, S D Warshaw, Forsythe & Ganapala 00/05/09 21pp

8004020084 Forwards Houston Lighting & Power status of settlement reft. per ASLB 800510 order. Affiliates not appropriate & Tel
GUNDEL, S D Lounsbury, Newman, Reis, Aschard & Tel 00/05/09 2pp

--8004020085 Status of settlement reft per ASLB 800510 order deferring trial briefs, final prehearing conference & evidentiary hearing Urges add 30-day extension for continuance of negotiations due to complexity Certificate of Doc encl
BARNETT, E W Houston Lighting & Power Co 00/05/09 7pp

8004020086 Status reft re settlement discussions' progress Urges ASLB to convene pretrial conference to accommodate outstanding discovery, final trial preparation & resolution of remaining procedural matters Certificate of Doc encl
CYPHERT, S B & PARKHENTER, F & DORFMAN, D A Justice, Dept of 00/05/09 1pp

8004020087 Forwards reft on status of settlement
GUNDEL, S D Lounsbury, Newman, Reis, Aschard & Tel 00/05/09 2pp

8004020088 Reft on settlement negotiations Suggests that conference be held to determine add time needed by applicant Trial should be provided by pretrial conference to accommodate discovery & other matters Certificate of Doc encl
CYPHERT, S B & PARKHENTER, F & DORFMAN, D A Justice, Dept of 00/05/09 5pp

8004020089 Settlement status reft by Public Utility Board of Brownsville, TX, Proposed early trial schedule & 30-day extension to explore possibility of settlement Certificate of Doc encl
GUNDEL, S D Brownsville, TX EPFIEDL, G Spiegel & McDermid 00/05/09 App

ment negotiations per ASLB 800410
n procedural duty to allow
"Issue of Doc encl
services, Inc. (TALC, D H Inham.

Witness negotiations per ASLB
ment will be completed by
Certificate of Doc encl
Lounsbury Electric Cooperative, Inc.
00/05/09 2pp

8004020090 Discovery reft for Apr 1980 Unit removal participated in deposition of NE Letter, D O Taylor, expert economic witnesses, per ASLB & DOJ, respectively Certificate of Doc encl
GUNDEL, S D Texas Utilities Co ANHEARN, C D Debevoise & Liberman 00/05/10 5pp

8004020091 Discovery reft for Apr 1980 Participated in NE Letter & Taylor deposition Received NRC updated response to Houston Lighting & Power second set of interrogatories Inspected NRC documents designated by expert witnesses
GUNDEL, S D Texas Utilities Generating Co ANHEARN, C D Debevoise & Liberman 00/05/10 5pp

8004020092 Discovery reft for Apr 1980 Participated in DTG Taylor deposition Responded to Houston Lighting & Power motion to compel production of documents Underwent settlement discussions & trial preparation Certificate of Doc encl
CYPHERT, S B Justice, Dept of 00/05/19 5pp

8004020093 Motion to establish trial & procedural dates Proposed 800509 for settlement refts, 800510 for prehearing, 800513 for witness trials & briefs, 800514 for responding parties & 800701 for final prehearing conference Certificate of Doc encl
CYPHERT, S B & PARKHENTER, F & DORFMAN, D A Justice, Dept of 00/05/21 4pp

8004020094 Discovery reft for Apr 1980 Attended certification of NE Letter deposition Responded to Houston Lighting & Power First set of interrogatories Joint parties' motion for 30-day extension Certificate of Doc encl
GUNDEL, S B Central & South West Corp 00/05/22 4pp

8004020095 Forwards corrected Page 3 to DOJ 800521 motion to establish trial & other procedural dates
CYPHERT, S B Justice, Dept of 00/05/23 1p

--8004020096 Connected Page 3 to DOJ 800521 motion to establish trial & other procedural dates Certificate of Doc encl
CYPHERT, S B & PARKHENTER, F & DORFMAN, D A Justice, Dept of 00/05/23 4pp

8004020097 Reply in opposition to DOJ 800521 motion to establish trial & other procedural dates Request premature ASLB should adhere to previous discussion that parties address schedule of counsel prehearing conference Certificate of Doc encl
KNOTTS, J B Texas Utilities Generating Co KNOTTS, J B Debevoise & Liberman 00/05/28 5pp

8004020098 Notice of appearance in proceeding Certificate of Doc encl.
LEWIS, S H Hearing Branch 2 00/05/28 5pp

8004020099 Motionfile parties that Sh Lewis, appearing in proceeding on behalf of NRC, is nephew of O Spiegel of Spiegel & McDermid, representing Public Utility Board of City of Brownsville, TX. No conflict of interest exists
CHARNICK, F D Antitrust Division 00/05/06 1p

8004020100 Reft on settlement negotiations per ASLB 800513 order. Requests 30-day extension for procedural dates to resolve & narrow issues Prehearing conference should be held at end of outstanding Certificate of Doc encl
GUNDEL, S D & KNOTTS, J B Texas Utilities Generating Co BARNETT, E W Warshaw, Forsythe & Ganapala 00/05/09 5pp

8004020101 Second settlement status reft per ASLB 800513 order Urges add 30-day extension to permit continued efforts. Completes answer re discovery & access to do interconnections remain under continuing study Certificate of Doc encl
CHARNICK, F D Antitrust Division 00/05/09 7pp

8004020102 Settlement status reft per ASLB 800513 order Urges establishment of trial date to complete outstanding ASLB discovery to resolve ASLB discovery & to expedite final trial preparation Certificate of Doc encl
CYPHERT, S B Justice, Dept of 00/05/09 App

8004020103 Reft on settlement negotiations per ASLB 800513 order. Urges add extension to entertain further substantial progress. Expects to execute agreement w/Central & South West Corp & TX Utility Generating Co Certificate of Doc encl
BARNETT, E W Houston Lighting & Power Co S. Baker & Asst. S Lounsbury, Newman, Reis, Aschard & Tel 00/05/09 7pp

8004020104 Reft on settlement negotiations by Public Utility Board of City of Brownsville, TX, per ASLB 800513 order. Requested draft of transmission agreement & return to Central & South West Corp. No response received Certificate of Doc encl
EPFIEDL, G Texas, Office of SPIEGEL, G Spiegel & McDermid 00/05/09 App

0006120245 Ais receipt of 000914 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 30-445/00-2a & 30-445/00-06
000914 M C Region A, Dallas, Reactor Construction & Engineering Support Branch 00/03/02 1p

-0006120245 Response to NRC 000408 ltr re violation noted in 1E Insp Repts 30-445/00-06 & 30-445/00-06 Corrective Action cable was pulled last during investigation of damage to cable jacket & will be replaced
000914 J Texas Utilities Generating Co 00/03/16 3pp

0006230119 Response to 1E Bulletin 00-02 re vacuum condition resulting in damage to chemical venting tanks. Licensee claims it has not yet complete Time Available affected items are in NRC scope of supply except reactor fuel oil pumps tanks
000914 J Texas Utilities Generating Co 00/03/27 1pp

9 Reportable occurrences, LERs & related correspondence

0006060070 Deficiency reft re apparent discrepancy in installation & insp requirements for Class 5 nonnuclear safety-related piping supports. Formal rpt should be submitted by 000715
000914 J Texas Utilities Generating Co 00/06/02 1p

0006230116 Deficiency reft re welded control head connections, updating 000321 reft rpt will be completed by 000701
000914 J Texas Utilities Generating Co 00/03/02 1p

0006240242 Supplemental deficiency reft re 1988-03 2200 HMI installation piping min wall Engineering review & inspection of min wall violations at welds & have metal defects in continuing. Anticipated submitting next progress rpt by 001210
000914 J Texas Utilities Generating Co 00/06/10 1p

7 Hearing transcripts on non-emergency matters

0006100270 Submits proposed corrections to transcripts of 000420 & 0001 granting conference held in Park North-TX. Certificate of Rev encl
000914 M C Texas Utilities Generating Co 00/06/01 2pp

DOCKET 30-648 DOUGLAS POINT NUCLEAR STATION, UNIT 1

G Adjudicatory correspondence

0006060070 Notice of withdrawal of application for early site review. Load growth forecasts indicate little possibility of connecting demand within vicinity of findings. Requests under terminating proceeding Certificate of Rev encl
000914 M C Potomac Electric Power Co 00/03/16 3pp

0006240201 Forwards PDC of NS Order 44326, closing Case 4603, PEPDC application for certificate of public convenience & necessity for construction of two nuclear power plants, due to unit 000623 withdrawal of application
000914 M C Maryland, State of 00/06/17 2pp

DOCKET 30-444 DOUGLAS POINT NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

0006060070 Notice of withdrawal of application for early site review. Load growth forecasts indicate little possibility of connecting demand within vicinity of findings. Requests under terminating proceeding Certificate of Rev encl
000914 M C Potomac Electric Power Co 00/03/16 3pp

0006240201 Forwards PDC of NS Order 44326, closing Case 4603, PEPDC application for certificate of public convenience & necessity for construction of two nuclear power plants, due to unit 000623 withdrawal of application
000914 M C Maryland, State of 00/06/17 2pp

DOCKET 30-452 GREENWICH ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

0006230110 Advances BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria encl
000914 M C Division of Licensing 00/06/20 13pp

G Adjudicatory correspondence

0006240311 Order granting extension until 000715 for applicant to respond to Citizens for Energy & Employees 000608 notice to compel withdrawal of application for licenses
000914 M C Atomic Safety and Licensing Board Panel 00/06/18 1p

0006240447 Forwards procedural rules in response to intervenor 000602 motion M/A encl
000914 J Hearing Branch 3 NRC 00/06/23 1p

0006240408 Response to Concerned Citizens for Employment & Energy 000602 motion to compel withdrawal of applications for CPs. Urges referral to ASL having jurisdiction over issue. Notice of appearance & Certificate of Rev encl
000914 J Hearing Branch 3 00/06/23 3pp

DOCKET 30-450 GREENWICH ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

0006230110 Advances BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria encl
000914 M C Division of Licensing 00/06/20 13pp

G Adjudicatory correspondence

0006240311 Order granting extension until 000715 for applicant to respond to Citizens for Energy & Employees 000608 notice to compel withdrawal of application for licenses
000914 M C Atomic Safety and Licensing Board Panel 00/06/18 1p

0006240447 Forwards procedural rules in response to intervenor 000602 motion M/A encl
000914 J Hearing Branch 3 NRC 00/06/23 1p

0006240408 Response to Concerned Citizens for Employment & Energy 000602 motion to compel withdrawal of applications for CPs. Urges referral to ASL having jurisdiction over issue. Notice of appearance & Certificate of Rev encl
000914 J Hearing Branch 3 00/06/23 3pp

DOCKET 30-458 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

0006230110 Advances BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria encl
000914 M C Division of Licensing 00/06/20 13pp

0006100040 Forwards Drawing 000499 inadvertently omitted from Sta 7 of 000534 ltr
000914 M C Commonwealth Edison Co 00/06/03 1p

0006250145 Reviews reorganization of Div of Nuclear Reactor Regulation & advises that most responsibilities re facility have been assigned to C. Ross. Reorganization chart encl
000914 M C Assistant Director for Licensing 00/06/12 13pp

0006230167 Requests add info re auxiliary bldg design & containment bldg loads to assist NRC in preparation of independent structural analysis
000914 M C J. Licensing Branch 1 00/06/16 3pp

0006060040 Submits update of scheduled commercial nuc dates for facilities reflecting Status 5 scheduled CL test load dates. Reviews importance of continued licensing process for Byron & Braidwood
000914 M C Commonwealth Edison Co 00/06/20 2pp

0006270006 Forwards revised Revision II & II consisting of Page 1-7 of CE-1-A, "Exam II QA Program for Nuclear Generating Reactors." Revised Revision II includes basis in which equivalent education requirements will be established
000914 M C Commonwealth Edison Co 00/06/23 1p

F Security, medical, emergency & fire protection plans

000130317 Forwards clarification of NRC requirements for emergency response facilities defined in 700623 ltr add specific criteria for facilities under development
000914 M C Division of Operating Reactors 00/06/23 13pp

DOCKETED ITEMS

221

0004160077 Forwards request for addl info re 000304 safeguards concerning plant constituting eighth set of Round 3 sections C-11 withheld from (00092 700)
YOUNGLOREN, J. Licensing Branch 1 00/06/02 2pp

0004160078 Forwards Revision 1 to draft emergency plan Emergency plan station withheld also addl
FISHER, D. L. Commonwealth Edison Co 00/06/04 2pp

--0004160078 Revision 2 to draft emergency plan
* Commonwealth Edison Co 00/07/01 12pp

0004240490 Requests to NRC 000429-00, 00-0501-00 & 00-0502-00 for requesting addl info re good licensing & qualification plans Requests that request submittal date be extended to 000504
FISHER, D. L. Commonwealth Edison Co 00/06/10 1p

G Adjudicatory Correspondence

0004260020 Supplemental statement of contentions alleging lack of technical qualifications to operate station Does impacts of projected routine releases of radioactive effluents should be reevaluated Certificate of Dismissal
* Safety Area Alliance for Responsible Energy * Safe Energy for Newsmen 00/05/07 24pp

0004260035 Answer to Safety Area Alliance for Responsible Energy & Environmental Protection Re: Divulge on supplemental contentions Recommends Contentions 7 & 8, re-writing of Contentions 1, 2 & 3 & 4 of Contentions 2a, 3 & 4 & 5 of Certificate of Dismissal
Hearing Branch 2 00/03/29 10pp

H General correspondence

0004260039 Requests that EN Cross of Margent & Lundy be added to distribution list
HARRISON, W. F. Commonwealth Edison Co 00/05/02 1p

I Inspection reports, EE Bulletins & correspondence

0004360025 Forwards IE Insp Repts 00-375/00-10, 00-374/00-11, 00-454/00-04, 00-453/00-04, 00-454/00-02 & 00-457/00-02 from meeting on 000320 Noncompliance noted
NRCPLD, B. J. Region 2, Chicago, Office of the Director 00/04/24 3pp

--0004360020 IE Insp Repts 00-375/00-10, 00-374/00-11, 00-454/00-04, 00-453/00-04, 00-454/00-02 & 00-457/00-02 from meeting on 000320 Noncompliance noted
FISHER, D. L. Region 2, Chicago, Office of the Director 00/04/14 4pp

0004170028 Forwards IE Insp Repts 00-454/00-05 & 00-455/00-00 on 000320-02 re notice of violation
NRCPLD, B. J. Region 2, Chicago, Office of the Director 00/04/20 3pp

--0004170028 Notice of violation from Insp on 000320-02
* Region 2, Chicago, Office of the Director 00/04/18 3pp

--0004170028 IE Insp Repts 00-454/00-05 & 00-455/00-00 on 000320-02 Noncompliance noted Inadequate design drawing review & installation procedures
YOUNGLOREN, J. Region 2, Chicago, Office of the Director 00/04/18 4pp

0004200013 Forwards IE Insp Rept 00-454/00-07 on 000408-10 re Noncompliance noted
FISHER, D. L. Region 2, Chicago, Reactor Construction & Engineering Support Branch 00/04/26 2pp

--0004200013 IE Insp Rept 00-454/00-07 on 000408-10 re Noncompliance noted Rept areas inspected RCN & safety-related piping with activities waiting & procedures
SWOCC, B. H. Region 2, Chicago, Reactor Construction & Engineering Support Branch 00/04/21 4pp

0004240490 Confirms 000319 discussion re 000320 meeting in Glen Ellyn. Re discusses findings of utility investigation into wall failure of containment post-tensioning eye anchor heads & remedial action to be taken
FISHER, D. L. Region 2, Chicago, Office of the Director 00/05/02 1p

0004170040 Reviews responses to IE Bulletin 77-20, "Flexible Mainfunction of NRCN Model 80100 Link Switches at Elevated Temperatures" Cover switch replacement will be completed when cables to switches are terminated
NRCPLD, B. J. Commonwealth Edison Co 00/05/08 2pp

0004260035 Confirms 000412 meeting in Glen Ellyn will discuss findings of utility investigation into wall failure of containment post-tensioning eye anchor heads & remedial action
FISHER, D. L. Region 2, Chicago, Office of the Director 00/06/04 1p

0004260039 Ack receipt of 000507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-454/00-05 & 00-455/00-00
FISHER, D. L. Region 2, Chicago, Reactor Construction & Engineering Support Branch 00/06/10 1p

--0004260039 Responses to NRC 000429 ltr re violations noted in IE Insp Repts 00-454/00-05 & 00-455/00-00 Corrective actions safety-related tubing & submer supply forwarded revised installation instructions
FISHER, D. L. Commonwealth Edison Co 00/05/07 80pp

0004260035 Ack receipt of 000501 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 00-454/00-05 & 00-455/00-00
FISHER, D. L. Region 2, Chicago, Reactor Construction & Engineering Support Branch 00/06/12 1p

--0004260032 Responses to NRC 000426 ltr re violations noted in IE Insp Repts 00-454/00-05 & 00-455/00-00 Corrective actions in depth analysis on concrete expansion anchor installations accomplished installation procedures reviewed & approved
NRCPLD, B. J. Commonwealth Edison Co 00/05/21 2pp

B Reportable occurrences, LERs & related correspondence

0004260044 Ack receipt of 000913 information deficiency report re post-tensioning anchorhead failure Requested extension until 000429 for completion of final report is acceptable
FISHER, D. L. Region 2, Chicago, Reactor Construction & Engineering Support Branch 00/05/20 1p

DOCKET 00-455 EVEN STATION, UNIT 2

A Application/construction stage documents & correspondence

0004260010 Advises NRC & PWR applicants of NRC decision to modify implementation plan presented to Section 4 of 00000-0377 re adequacy of applicable support structures General operating re-evaluation procedure & acceptance criteria and
KIMMERT, D. G. Division of Licensing 00/05/26 10pp

0004100040 Forwards Drawing 000449 inadvertently omitted from Item 7 of 000004 ltr
HARRISON, W. F. Commonwealth Edison Co 00/06/03 1p

0004280045 Discusses reorganization of Div of Nuclear Reactor Regulation & advises that responsibility re facility have been assigned to C. H. HARRISON, W. F. Assistant Director for Licensing 00/04/18 11pp

0004200017 Requests addl info re auxiliary bldg design & containment bldg loads to assist NRC in preparation of independent structural analysis
YOUNGLOREN, J. Licensing Branch 1 00/04/16 3pp

0004200043 Submits update of scheduled commercial use dates for facilities, refueling bldgs & scheduled EL fuel load dates Storage Insurance of combined licensing process for Durrin & Bradwood
NRCPLD, B. J. Commonwealth Edison Co 00/06/06 3pp

0004270004 Forwards revised Revisions 1 & 2 consisting of Pages 1-7 of CE-4-A, "Common CE 4-A Program for Nuclear Generating Stations" Revised Revision 1 includes basis on which nuclear safety requirements will be established
NRCPLD, B. J. Commonwealth Edison Co 00/04/22 1p

F Security, medical, emergency & fire protection plans

0004200017 Forwards clarification of NRC requirements for emergency response facilities defined in 000013 ltr Add specific criteria for facilities under development
KIMMERT, D. G. Division of Operating Reactors 00/04/23 61pp

DOCKETED ITEMS

00001A0209 Forwards request for addl info re 000004 safeports
contingency plan constituting eighth set of Round 1
questions (incl withheld pref 10CP22 790)
000A00L000.5 J Lansing Branch 1 03/06/02 Rep

0006180292 Forwards Revision I to draft emergency plan Emergency plan
station address also encl
0006180292 D L Commonwealth Release Co 00/06/84 Ppp

--G00418004? Revision 1 to draft emergency plan
 1/1/2000 10:00 AM 00000000 00000000 00000000

B303240479 Response to NRC B004025-20-0001.07 & 23 letter requesting add info re guard training & qualification plans Requests that response submittal date be extended to 02/09/04
HCOPLER, D L. Commonwealth Edison Co 85/03/18 1a

© Adjudicator's correspondence

HO06040222 Supplemented statement of contentions alleging lack of technical qualifications to operate station Bore impacts of projected routine releases of radioactive gases should be re-evaluated Certificate of Noe ent 1
 • Safe Energy Alliance for Responsible Energy • Safe Energy for New Mexico 02/05/09 340a

0004920105 Annual to Dakota Area Alliance for Responsible Energy & Minnesota Alliance for Environment symposiumed conventions
Recommendations 7 & 8. Hearing of Customers 1:2 &
& 3. Hearing of Customers 2:3 & 4. Hearing of Customers of Soc
NARMA. Hearing Branch 2. 00/00/00 1600

H. General correspondence

900A000084 Requests that ER Cross of Sargent & Lundy be added to distribution list
HARRISON, M P. Cavanaugh18 Edison Co. 01/05/92 1c

0 Inspection reports, IE Subjective & correspondence

0004540325 Forwards EE Insp Rpts 50-373/93-10, 50-374/90-11,
50-454/90-06, 50-449/90-06, 50-454/90-03 & 50-457/90-02 from
meeting on 000026 Re: reconnaissance noted
X3PPLK.v.d Region 3, Chicago- Office of the Director 00/04/24
Jax

--0001040223 DE [encl Repts 30-073/80-18, 30-074/80-11, 30-454/80-06, 30-455/80-56, 30-456/80-02 & 30-457/80-02 from meeting on 300328 Areas inspected status of three statuses under const FIORELLI, G Region 3, Chicago. Reactor Construction & Engineering Support Branch 30/05/80 Jue

000417020B Forwards IE Insp Regis 50-434/50-25 & 50-435/50-25 on
000025-26 & notice of violations
KUFPLER, J O Register 2; Chicago, Office of the Director 86/04/25
Dix

--0006070210 Notice of violation from insp on 000005-26
 * Region 2, Chicago, Office of the Director 00/04/10 Jee

-B00470329 DE Insp Repts SO-404/80-05 & SO-444/80-05 an SOCCMS-04
 Noncompliance noted inadequate design drawing review &
 installation procedures
 YON, I T, SANILS04.D H Region 3, Chicago, Office of the
 Director 03/04/18 App

000690499 Confirms 000009 discussion re 000000 meeting in Glen Ellyn, IL to discuss findings of soil investigation into soil
 failure of containment post-bombing eye anchor heads &
 remedial action to be taken
 KFFLEIN, J D Region 3, Chicago, Office of the Director 00/00/00
 1a

0004373140 Review responses to IE Bulletin 79-28, "Possible Malfunction of SAKCO Model SA180 Limit Switches at Elevated Temperatures"
Cover gasket replacement will be completed when cables to switches are terminated
FEDPLAB 2 L. Commonwealth Edison Co. 03/05/90 Due

0004240038 Confirms 000613 meeting in Glen Elgin, IL to discuss findings of this investigation into wall failure of containment post-breaching the anchor heads & remedial action.
REPPLES, J Q Region 3, Chicago. Office of the Director 00/06/04,
JA

0006200012 Ack receipt of 000597 ltr informing ABC of steps taken to correct violations noted in IE Insp Rpts 00-454/00-05 b
00-455/00-00
FIORELLI, G Region 3, Chicago, Swacker Construction & Engineering
Support Branch 00/06/10 1p

--0064200018 Responds to NRC 300425 re re violations noted in IE Insp
Letter 30-434/EO-05 & 30-435/EO-05 Corrective actions safety-
related hammer & snubber supplier forwarded revised
installation instructions
RDS/PLN, D L Commonwealth Edison Co 30/03/27 10pp

0006260303 Ack receipt of 000001 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 20-454/79-IB & 20-455/79-IB
FIDELL L O Region 5 Chicago, Reactor Construction & Engineering Support Branch 03/26/12 lp

--806260312 Responds to NRC 800126 ltr re violations noted in IE Insp
Rpts 80-434/79-18 & 80-485/79-18 Corrective actions
in depth analysis on concrete expansion anchor installations
accomplished. Installation procedures revised & approved
FEDPLD, E. L. Cunningham & Sons Co 80/05/21 Zuo

3 Reportable occurrences, LRA & related correspondence

900A020564 Ack receipt of 900315 interim deficiency rep't re post-tensioning anchorhead failure Requested extension until 090600 per submittal of final rpt is acceptable FIORELLI, S Region S, Chicago, Reactor Construction & Engineering Support Branch 90003/32 1p

DOCKET NO-454, BRANWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8006230110 Advises GWR & PWR applicants of HRC decision to modify
implementation plan presented in Section 3 of NUREG-0577 re
adequacy of applicable support structures General operating
reactor review procedure & licensing criteria encl
EIS0200UT.D 0 Division of Licensing 08/05/90 1336

893610040 Forwards Drawing 560F499 inadvertently omitted from Item 7
of 800506 ltr
NAUOKHOM M P Commonwealth Edison Co 80/06/03 10

0006250145 Discusses reorganization of Div of Nuclear Reactor
Regulation & advises that npt responsibilities as facility
have been assigned to 2 Room Reorganization charts encl
TEOE00000 L Assistant Director for Licensing 00/06/12 lgg

0046280167 Requests addl info re auxiliary bldg design & containment
bldg loads to assist NRC in preparation of independent
structural analysis
YOUNGLOOS, S J Licensing Branch 1 80/04/14 3ss

HD064300452 Submit update of scheduled commercial svc dates for facilities, reflecting delays & scheduled GL fuel load dates. Stressing importance of continued licensing process for Byron & Bradwood.

900A292356 Forwards revised Revisions II & III consisting of Page 1-7 of
CE-1-a. "Comm Ed QA Program for Nuclear Generating
Stations - Revised Revision II Includes basis on which
equivalent education requirements will be established
PEOPLE, D. L. Commonwealth Edition Co. 00/06/23 1a

F. Security, media, emergency & fire protection plans

000150617 Forward clarification of NRC requirements for emergency response facilities defined in 70CFR2.14r Add specific criteria for facilities under development
EISENHUT, R G Division of Operating Reactors 88/04/25 4pp

05/04/2017 Forwards seventh set of round one questions re 790818
training & requalification plan per review of application
for St. Vincent Island (ref 10CFR79.79)
YOUNGLOOD, J. Licensing Branch 1 03/04/20 2pp

006170888 Forwards eighth set of Round one questions re 000028
safeguards contingency plan Questions withheld inst
10CFR2.740
YOU006170888 E. J. Licessini Branch 1 80/06/02 Dan

00680093 Forward Revision 1 to draft emergency plan Emergency plan
Station entries also whel
FSPLED-D.L. Commonwealth Edison Co 06/06/04 Spa

DOCKETED ITEMS

--0004100347 Revision 1 to draft emergency plan
+ Commonwealth Edison Co 00/07/31 13ppp

0004204090 Responds to NRC 000425.30.030.09 & 30 item requesting add
low re guard training & qualification plans Requests that
response submittal date be extended to 000424
PEOPLE'S D. L. Commonwealth Edison Co 00/06/18 1p

H General correspondence

0004202029 Requests that ER Cross of Sargent & Lundy be added to
distribution list
MUGHTON, G F Commonwealth Edison Co 00/05/22 1p

G Inspection reports, IE Bulletins & correspondence

0004040328 Forwards IE Insp Repts 00-373/80-10, 00-374/80-11,
00-454/80-06, 00-443/80-06, 00-456/80-02 & 00-457/80-02 from
meeting on 000328 No noncompliance noted
PEOPLE'S D. Region 3, Chicago, Office of the Director 00/04/24
2pp

--0004040339 IE Insp Repts 00-373/80-10, 00-374/80-11, 00-454/80-06,
00-456/80-06, 00-443/80-06, 00-456/80-02 & 00-457/80-02
000328 Areas inspected status of three stations under const
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/04/14 4pp

0004170771 Forwards IE Insp Repts 00-454/80-02 & 00-457/80-02 on
000416-17 No noncompliance noted
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/05/06 2pp

--0004170774 IE Insp Repts 00-454/80-02 & 00-457/80-02 on 000416-17 No
noncompliance noted Major areas inspected review of records,
cable tray hanger space & action on previous inspection findings
MUGHTON, G F Region 3, Chicago, Office of the Director 00/04/24
Region 3, Chicago, Reactor Construction & Engineering Support
Branch 00/05/06 4pp

0004090044 Ack receipt of 000508 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 00-454/79-15 &
00-457/79-15
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/05/21 1p

--0004090047 Responds to NRC 000510 ltr re violations noted in IE Insp
Repts 00-454/79-15 & 00-457/79-15 Corrective actions under
long-term storage recommendations will be reviewed & filed
for future ref
PEOPLE'S D. L. Commonwealth Edison Co 00/05/08 2pp

0004170160 Revises response to IE Bulletin 79-28, "Possible Half-Function
of NRCO Model CASRO Limit Switches at Elevated Temperatures"
Cover gasket replacement will be completed when cables to
switches are terminated.
PEOPLE'S D. L. Commonwealth Edison Co 00/05/20 4pp

DOCKET 30-457 BRAW/0026 STATION UNIT 2

A Application/Construction stage documents & correspondence

0004200110 Advises RMT & PMR applicants of NRC decision to modify
implementation plan presented in Section 4 of 00005-0077 re
adequacy of applicable support structures General operating
reactor review procedure & acceptance criteria encl.
RIMBROOK, D. D. Division of Licensing 00/03/00 12pp

0004100490 Forwards Drawing 38P/499 inadvertently omitted from Item 7
of 000406 ltr
MUGHTON, G F Commonwealth Edison Co 00/06/02 1p

0004200145 Discusses reorganization of Div of Nuclear Reactor
Regulation & advises that new non-compliance re facilities
have been assigned to C Ross Reorganization charts encl.
MUGHTON, G F Assistant Director for Licensing 00/06/12 11pp

0004200167 Requests add ltr re auxiliary bldg design & containment
bldg leads to assist E&O in preparation of independent
structural analysis.
YOUNGBERG, D. J. Licensing Branch 1 00/06/18 3pp

0004200450 Submits update of scheduled commercial use dates for
facilities, reflecting delays & scheduled CL fuel load
dates Shows importance of continued licensing process for
Sarg & Lundy
PEOPLE'S D. L. Commonwealth Edison Co 00/06/20 4pp

0004202036 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of
C-1-A, "Control E&O Program for Nuclear Generating
Units" Revised Revision 11 includes table on which
equivalent education requirements will be established
PEOPLE'S D. L. Commonwealth Edison Co 00/06/23 1p

F Security, medical, emergency & fire protection plans

0003132017 Forwards Clarification of NRC requirements for emergency
response facilities defined in 790913 ltr Add specific
criteria for facilities under development
RIMBROOK, D. D. Division of Operating Reactors 00/04/25 4pp

0004040019 Forwards seventh set of round one questions re 790818
training & requalification plan per review of application
for CL Encl withheld ltr 100P/2 7901
YOUNGBERG, D. J. Licensing Branch 1 00/05/20 3pp

0004170788 Forwards eighth set of Round one questions re 000324
safety contingency plan Questions withheld ltr
100P/2 7901
YOUNGBERG, D. J. Licensing Branch 1 00/06/02 2pp

0004040029 Forwards Revision 1 to draft emergency plan Emergency plan
status under review also with qualification plan Requests that
PEOPLE'S D. L. Commonwealth Edison Co 00/06/06 4pp

--0004100347 Revision 1 to draft emergency plan
+ Commonwealth Edison Co 00/07/31 13ppp

0004204090 Responds to NRC 000425.30.030.09 & 30 item requesting add
low re guard training & qualification plans Requests that
response submittal date be extended to 000424
PEOPLE'S D. L. Commonwealth Edison Co 00/06/18 1p

H General correspondence

0004202029 Requests that ER Cross of Sargent & Lundy be added to
distribution list
MUGHTON, G F Commonwealth Edison Co 00/05/22 1p

G Inspection reports, IE Bulletins & correspondence

0004040328 Forwards IE Insp Repts 00-373/80-10, 00-374/80-11,
00-454/80-06, 00-443/80-06, 00-456/80-02 & 00-457/80-02 from
meeting on 000328 No noncompliance noted
PEOPLE'S D. Region 3, Chicago, Office of the Director 00/04/24
2pp

--0004040339 IE Insp Repts 00-373/80-10, 00-374/80-11, 00-454/80-06,
00-456/80-06, 00-443/80-06, 00-456/80-02 & 00-457/80-02
000328 Areas inspected status of three stations under const
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/04/14 4pp

0004170771 Forwards IE Insp Repts 00-454/80-02 & 00-457/80-02 on
000416-17 No noncompliance noted
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/05/06 2pp

--0004170774 IE Insp Repts 00-454/80-02 & 00-457/80-02 on 000416-17 No
noncompliance noted Major areas inspected review of records,
cable tray hanger space & action on previous inspection findings
MUGHTON, G F Region 3, Chicago, Office of the Director 00/04/24
Region 3, Chicago, Reactor Construction & Engineering Support
Branch 00/05/06 4pp

0004090044 Ack receipt of 000508 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 00-454/79-15 &
00-457/79-15
PIORILLI, D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/05/21 1p

--0004090047 Responds to NRC 000510 ltr re violations noted in IE Insp
Repts 00-454/79-15 & 00-457/79-15 Corrective actions under
long-term storage recommendations will be reviewed & filed
for future ref
PEOPLE'S D. L. Commonwealth Edison Co 00/05/08 2pp

0004170160 Revises response to IE Bulletin 79-28, "Possible Half-Function
of NRCO Model CASRO Limit Switches at Elevated Temperatures"
Cover gasket replacement will be completed when cables to
switches are terminated.
PEOPLE'S D. L. Commonwealth Edison Co 00/05/20 4pp

DOCKETED ITEMS

DOCKET 80-199 RIVER BEAD STATION, UNIT 2

A Application/construction stage documents & correspondence

0004200100 Advances BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 800300-0400 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EISENHUT, D O Division of Licensing 80/05/02 13pp

0004000201 Act receipt of 800300-100 re frequency of testing for job permit still pending after consideration of final 6-month
ACTS CDFP further re test reqs. NRC has no further questions
MEISLE, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/02 1p

0004000300 Forwards Pittsburgh Testing Lab 800400 & 800400 repts for line & source aggregates respectively in response to NRC 7/12/83 requests repts give summary results of ASSTC CDFP nuclear test using high & low axial job permit
MEISLE, M C Gulf States Utilities Co 80/05/06 2pp

0004170071 Forwards "Proposed Widening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2," preliminary case repts Requested expedited comments since utility has been requested to suspend latest activities
BEDMAN, M H Sitting Analysis Branch 80/04/02 2pp

0004170075 "Proposed Widening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2," preliminary case repts Mail Register property descriptions & proposed memorandum of agreement encl
Division of Engineering 80/04/02 42pp

0004200401 Forwards "For Comment" edition of NUREG-0419 Requests review & comment W/c encl
EISENHUT, D O Division of Licensing 80/04/08 3pp

II Architect correspondence

0004000500 Discusses NRC antitrust review in response to 800400-100 re possible Cajon Electric Reactor Acquisition, Inc antitrust violations contract to facility Comments will be considered when still applies FAR 24
LITWACK, S H Utility Finance Branch 80/05/08 2pp

0004000600 Forwards Atty General 800300-100 forwarding addl antitrust info ltr will be sent to Dc of FR Petitions to intervene & requests for hearings may be filed by interested parties within 30 days after FR publication
SALTZMAN, J Utility Finance Branch 80/05/10 1p

0004000700 Advances that review of info submitted for antitrust review provides no basis to conclude that Cajon Electric Power Cooperative, Inc participation would create situation inconsistent w/antitrust law
LITWACK, S H Justice Dept of 80/05/03 1p

0004000801 Forwards Atty General 800300-100 providing addl antitrust advice re CP application to antitrust hearing necessary for proposed amend to CP
SALTZMAN, J Antitrust & Indemnity Group 80/05/01 2pp

0004000901 Advances that review of info submitted for antitrust review provides no basis to conclude that Cajon Electric Power Cooperative, Inc & San Felipe CDFP, Inc to become unit consumers provides no basis for antitrust hearing
LITWACK, S H Justice Dept of 80/05/03 1p

G Inspection reports, IE Bulletin & correspondence

0004000900 Forwards IE Bulletin 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply" No written response required
REYFITT, R V Region 4, Dallas, Office of the Director 80/04/01 1p

0004000900 Forwards IE Inspect 80-450/80-04 on 800300-0400 No noncompliance noted
REYFITT, R V Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/14 2pp

0004000900 IE Inspect 80-450/80-04 on 800300-0400 No noncompliance noted BWR areas located storage of reheat/preheated equipment, concrete placement & reinforcing steel installation
CROWMAN, A A, BEADIN, A, OBERDORF, C Region 4, Dallas, Office of the Director 80/04/13 2pp

0004000900 Forwards IE Bulletin 80-10, "Decay Heat Removal Sys Operability" No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
REYFITT, R V Region 4, Dallas, Office of the Director 80/05/09 1p

0004000900 Forwards IE Circular 80-10, "Active-Bright-To-Interlock Key May Fall Out of Place When Mounted Below Horizontal Axis" No written response required
REYFITT, R V Region 4, Dallas, Office of the Director 80/05/14 1p

0004000901 Act receipt of 800300 & 0420-100 informing NRC of steps taken to correct violations noted in IE Inspect Rept 30-450/79-06
REYFITT, R V Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/02 1p

0004000901 Response to NRC 800400-100 re violations noted in IE Inspect Rept 30-450/79-06 Corrective actions excepted, just cited
Far potentially reactive aggregate w/low alkaline cement has been deleted
NEUBERG, J O Gulf States Utilities Co 80/04/02 2pp

0004000901 Response to IE Bulletin 80-06, "Inadequate QA for Nuclear Supplied Equipment" No notice on work have been provided by Nevada Engineering Co re supplies reactor pressure vessels & interlocks under contract w/utl
SIMPSON, E L Gulf States Utilities Co 80/05/02 1p

B Reportable occurrences, LERs & related correspondence

0004000900 Advances that potential deficiency re concrete "cold joint" does not appear to represent a significant deficiency
Available under 10CFR50.52(a) Results of final analysis will be forwarded within 30 days
NEUBERG, J O Gulf States Utilities Co 80/04/02 1p

0004000900 Deficiencies repts re diesel generator bldg concrete mkt cold joint Equipment failure did not represent breakdown in QA program Deficiency analysis indicated unexplained cement joint did not impair structural integrity or performance of mkt
SIMPSON, E L Gulf States Utilities Co 80/05/02 1p

DOCKET 80-199 RIVER BEAD STATION, UNIT 2

A Application/construction stage documents & correspondence

0004200100 Advances BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 800300-0400 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EISENHUT, D O Division of Licensing 80/05/02 13pp

0004170071 Forwards "Proposed Widening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2," preliminary case repts Requested expedited comments since utility has been requested to suspend latest activities
BEDMAN, M H Sitting Analysis Branch 80/04/02 2pp

0004170075 "Proposed Widening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2," preliminary case repts Mail Register property descriptions & proposed memorandum of agreement encl
Division of Engineering 80/04/02 42pp

0004200401 Forwards "For Comment" edition of NUREG-0419 Requests review & comment W/c encl
EISENHUT, D O Division of Licensing 80/04/08 3pp

G Inspection reports, IE Bulletin & correspondence

0004000900 Forwards IE Bulletin 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply" No written response required
REYFITT, R V Region 4, Dallas, Office of the Director 80/04/01 1p

0004000900 Forwards IE Bulletin 80-10, "Decay Heat Removal Sys Operability" No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl
REYFITT, R V Region 4, Dallas, Office of the Director 80/05/09 1p

DOCKETED ITEMS

229

0004000045 Forwards IE Circular 00-02, "Valve-Shift-to-Actuator May May
Fall Out of Place When Mounted Below Horizontal Axis " No
written response required.
00/05/14 1p

0004000103 Responds to IE Bulletin 00-02, "Leakage to Air Handler
Supplying Equipment " No action as unit have been provided by
Havlic Engineering Co. Co supplies correct pressure vessels
& generally under contract w/015
00APFC/R.L. Gulf States Utilities Co 00/05/23 1p

0004000142 00-462 WPMS NACPLAN PROTECT UNIT 1
A Application/construction stage documents & correspondence

0004000210 Advices BMR & PWR applicants of NRC decision to modify
implementation plan presented in Section 4 of NRC00-037 re
adequacy of applicable support structures. General operating
reactor review procedure & acceptance criteria and
00/05/20 13pp

0004000440 Suggests that classification be added to Page 54 of NRC00-
0440, Vol. 1, to reflect content in which test estimates for
ATWS tests are made. Utility believes indirect costs were under-
estimated. Disputes value impact analysis.
00/05/28 2pp

0004000556 Forwards reference to NRC 000320 request for add info re
safety significance.
00/04/08 2pp

0006110270 Notifies that lab will be conducting add moisture testing
on low voltage electrodes using methods required in NRC
AD 3-Section 25. Electrode coating moisture testing results
will be applied only to Units 1 & 2.
00/04/04 1p

F Security, medical, emergency & fire protection plans

0006270024 Forwards Amend 2 to "Fire Protection Evaluation"
00/04/11 2pp

0006270024 Amend 2 to "Fire Protection Evaluation"
Washington Public Power Supply System 00/05/31 4pp

0006290004 Forwards drawings re location for seismic emergency exit
Requirements immediate review & response on that site-specific
design work has been completed & site preparation begin
"Conceptual Site Plan" available in Central Files only
00/06/05 5pp

0006290040 "Used Road for WPPSS-D For Apr 1976 to Mar 1978 at
00 PL Level"
Washington Public Power Supply System 79/05/31 1p

0006290043 "Combined Plant Area & Emergency Coordination Facility
Site Location, 1-93D Nuke Reactor Exclusion Areas & Property
Lines"
Washington Public Power Supply System 79/01/12 1p

0006290049 "Environ Programs Data Map - Hanford Area"
Washington Public Power Supply System 79/01/12 1p

3 Inspection reports, IE Bulletin & correspondence

0006300134 Forwards IE Insp Repts 00-460/00-03 & 00-513/00-03 on
000331-0400 No noncompliance noted
00/04/08 2pp

0006300141 IE Insp Repts 00-460/00-03 & 00-513/00-03 on 000331-0400 No
noncompliance noted. Major areas inspected. PWR used for
inspections, pipe supports & restraint aids & administrative
controls for nonconformance conditions.
00/04/08 2pp

0006300200 Notification of 000628-04 meeting until in October. It is
planned for October. Canceled. For more info visit
00/05/07 4pp

0006300300 Act receipt of 000315 for informing NRC of steps taken to
correct deviations noted in IE Insp Repts 00-460/00-03 &
00-513/00-04
00/04/08 2pp

0006300400 Responds to NRC 000415 for deviations noted in IE Insp
Repts 00-460/00-03 & 00-513/00-04. Corrective actions
supplied. Evaluations of findings. (Lab use of electrode is
acceptable based on ASME III guidelines)
00/05/19 2pp

0006300500 Forwards IE Insp Repts 00-460/00-04 & 00-513/00-04 on
000331-01 & notice of deviation
00/04/13 2pp

0006300510 Notice of deviation from insp on 000331-01
Region 3, San Francisco. Office of the Director 00/04/13 1p

0006300610 IE Insp Repts 00-460/00-04 & 00-513/00-04 on 000331-01
Noncompliance noted. Welding electrodes qualified under NRC
00-01-1 rather than 00-01-3 were used for welding
plant-instrument generator. RDPG units.
00/04/13 7pp

0006300610 Act receipt of 000367 for informing NRC of steps taken to
correct violations noted in IE Insp Repts 00-460/00-03 &
00-513/00-04
00/05/20 3p

0006300614 Responses to NRC 000367 for violations noted in IE Insp
Repts 00-460/00-03 & 00-513/00-04. Corrective actions
supplied. Evaluations of findings. (Lab use of electrode is
acceptable based on ASME III guidelines)
00/05/07 4pp

0006300641 Forwards IE Insp Repts 00-460/00-03 & 00-513/00-03 on
000331-01 & notice of violation
00/04/07 2pp

0006300644 Notice of violation from insp on 000331-01
Region 3, San Francisco. Office of the Director 00/04/02 2pp

0006300647 IE Insp Repts 00-460/00-03 & 00-513/00-03 on 000331-01
Noncompliance noted. Failure to control sagging supports
at structural steel & underside welds on pipe supports
00/04/02 9pp

B Reportable occurrences, LFNs & related correspondence

0006300650 Part 23 report re use of earlier revision of simplified
response spectra in design of low safety-related tanks.
Details in NRC 790021-29 DA program 00/04/02 2pp

0006300655 Notice of deviation from insp on 790021-29
Region 4, Dallas. Office of the Director 79/06/10 1p

0006300656 PWR-00-037 on 000315/00-03. Notes on Unit 2 has
00/05/19 2pp

0006300661 CLINTON POWER STATION UNIT 1

A Application/construction stage documents & correspondence

0006300710 Advices BMR & PWR applicants of NRC decision to modify
implementation plan presented in Section 4 of NRC00-037 re
adequacy of applicable support structures. General operating
reactor review procedure & acceptance criteria and
00/05/20 13pp

DOCKETED ITEMS

8006200014 Forwards "For Comment" edition of NUREC-0419 Comments should be forwarded by 800707 WFO encl
EISENHARTZ-D Division of Licensing 80/04/09 App

F Security, medical, emergency & fire protection plans

8006200038 Requests extension of time for submittal of security guard training & qualification program until Dec 1980 Previously issued security plan mail has been accepted for docketing
MALLER-G E Illinois Power Co 80/04/19 1p

D Inspection reports, DE Substantive & correspondence

8006200010 Forwards IE Insp Rept 80-461/80-04 on 800328-06 & notice of violation
FIORELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/28 2pp

8006200121 Notice of violation from Insp on 800555-08
+ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/28 1p

8006200124 IE Insp Rept 80-461/80-04 on 800529-24 Noncompliance noted requirements not correctly translated into drawings & specs
MALLER-G, HARRIS, R. HARRIS-C Region 3, Chicago, Office of the Director 80/04/28 1pp

8006200045 Forwards IE Insp Rept 80-461/80-07 on 800422-04 & notice of violation
FIORELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/09 App

8006200148 Notice of violation from Insp on 800482-04
+ Region 3, Chicago, Office of the Director 80/05/09 App

8006200151 IE Insp Rept 80-461/80-07 on 800450-24 Noncompliance noted failure to properly store welding materials to verify conformance during Insp & failure to conform w/procedures
DANIELSON-H H Region 3, Chicago, Reactor Construction & Engineering Support Branch L&E & H Region 3, Chicago, Office of the Director 80/05/09 App

8006200047 Forwards IE Insp Rept 80-461/80-06 on 800414-30 & notice of violation
FIORELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/14 2pp

8006200084 Notice of violation from Insp on 800414-30
+ Region 3, Chicago, Office of the Director 80/05/13 App

8006200082 IE Insp Rept 80-461/80-08 on 800414-30 Noncompliance noted inadequate control of welding processes & inadequate control of outgassing metal
ADAMS-S, LIVINGSTON-H H Region 3, Chicago, Office of the Director 80/05/13 App

8006200072 Act receipt of 800582 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-461/80-04
FIORELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/11 1p

8006200075 Response to NRC 800420 ltr re violations noted in IE Insp Rept 80-461/80-04 Corrective actions Barrett & Lund design drawing will be resubmitted to identify 480-volt outgassing holes to be welded to embedded angle iron
OWENSTON-W C Illinois Power Co 80/06/22 2pp

8006200043 Act receipt of 800506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-461/80-06
FIORELLI-G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/17 1p

8006200046 Response to NRC 800514 ltr re violations noted in IE Insp Rept 80-461/80-08 Corrective actions resubmitted all scrap metal from designated pinchpoint area & verified appropriate boundary markers
HARRIS-M C Illinois Power Co 80/06/06 1p

8006200044 Forwards "For Comment" edition of NUREC-0419 Comments should be forwarded by 800707 WFO
EISENHARTZ-D Division of Licensing 80/06/09 2pp

F Security, medical, emergency & fire protection plans

8006200038 Requests extension of time for submittal of security guard training & qualification program until Dec 1980 Previously issued security plan mail has been accepted for docketing
MALLER-G E Illinois Power Co 80/06/19 1p

DOCKET 80-461 ALLENS CREEK NUCLEAR STATION, UNIT 1

A Application/Construction stage documents & correspondence

8006200110 Advises BWR & BWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREC-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
EISENHARTZ-D Division of Licensing 80/05/26 13pp

8006200123 Forwards "For Comment" edition of NUREC-0419 Describes technical issues, studies & analyses performed by DC Comments should be forwarded to NRC by 800707 WFO encl
EISENHARTZ-D Division of Licensing 80/06/06 2pp

8006200121 Discusses reorganization of O&E of Nuclear Reactor Regulation & advises that responsibility for facilities have been assigned to C. Hugh Hargreaves charts encl
EISENHARTZ-D Assistant Director for Licensing 80/06/12 11pp

G Adjudicatory correspondence

8006190033 Response to telegram ltr requesting clarification of applicant responses to 12th set of Interregulator Explanations
use of abbreviations & proposed changes to correspondence
BIDLER-C T Baker & Bette 80/05/30 2pp

8006190033 Response to Houston Lighting & Power notice to compel production of documents from 12 FIRD & C Hazardous Material re most due to Johnson 800518 ltr informing of intention to produce documents in bus use Related correspondence
BIDLER-C T Texas Public Interest Research Group 80/05/06 1p

8006200072 Interregulator & requests for production of documents re remediated Contention 2 concerning effect of transmission lines on human health HARRIS 800502 ltr to unit & Certificate of Rev encl
HARRIS-C L HARRIS-D HARRIS-W E Affiliation Unknown 80/05/03 1pp

8006190033 Response to JP Roberts 16th request for production of documents NEDD-10000-1, NEDD-10000-2, NEDD-10000-3, NEDD-10000-4, NEDD-10000-5, NEDD-10000-6, NEDD-10000-7, NEDD-10000-8, NEDD-10000-9, NEDD-10000-10, NEDD-10000-11, NEDD-10000-12, NEDD-10000-13, NEDD-10000-14, NEDD-10000-15, NEDD-10000-16, NEDD-10000-17, NEDD-10000-18, NEDD-10000-19, NEDD-10000-20, NEDD-10000-21, NEDD-10000-22, NEDD-10000-23, NEDD-10000-24, NEDD-10000-25, NEDD-10000-26, NEDD-10000-27, NEDD-10000-28, NEDD-10000-29, NEDD-10000-30, NEDD-10000-31, NEDD-10000-32, NEDD-10000-33, NEDD-10000-34, NEDD-10000-35, NEDD-10000-36, NEDD-10000-37, NEDD-10000-38, NEDD-10000-39, NEDD-10000-40, NEDD-10000-41, NEDD-10000-42, NEDD-10000-43, NEDD-10000-44, NEDD-10000-45, NEDD-10000-46, NEDD-10000-47, NEDD-10000-48, NEDD-10000-49, NEDD-10000-50, NEDD-10000-51, NEDD-10000-52, NEDD-10000-53, NEDD-10000-54, NEDD-10000-55, NEDD-10000-56, NEDD-10000-57, NEDD-10000-58, NEDD-10000-59, NEDD-10000-60, NEDD-10000-61, NEDD-10000-62, NEDD-10000-63, NEDD-10000-64, NEDD-10000-65, NEDD-10000-66, NEDD-10000-67, NEDD-10000-68, NEDD-10000-69, NEDD-10000-70, NEDD-10000-71, NEDD-10000-72, NEDD-10000-73, NEDD-10000-74, NEDD-10000-75, NEDD-10000-76, NEDD-10000-77, NEDD-10000-78, NEDD-10000-79, NEDD-10000-80, NEDD-10000-81, NEDD-10000-82, NEDD-10000-83, NEDD-10000-84, NEDD-10000-85, NEDD-10000-86, NEDD-10000-87, NEDD-10000-88, NEDD-10000-89, NEDD-10000-90, NEDD-10000-91, NEDD-10000-92, NEDD-10000-93, NEDD-10000-94, NEDD-10000-95, NEDD-10000-96, NEDD-10000-97, NEDD-10000-98, NEDD-10000-99, NEDD-10000-100, NEDD-10000-101, NEDD-10000-102, NEDD-10000-103, NEDD-10000-104, NEDD-10000-105, NEDD-10000-106, NEDD-10000-107, NEDD-10000-108, NEDD-10000-109, NEDD-10000-110, NEDD-10000-111, NEDD-10000-112, NEDD-10000-113, NEDD-10000-114, NEDD-10000-115, NEDD-10000-116, NEDD-10000-117, NEDD-10000-118, NEDD-10000-119, NEDD-10000-120, NEDD-10000-121, NEDD-10000-122, NEDD-10000-123, NEDD-10000-124, NEDD-10000-125, NEDD-10000-126, NEDD-10000-127, NEDD-10000-128, NEDD-10000-129, NEDD-10000-130, NEDD-10000-131, NEDD-10000-132, NEDD-10000-133, NEDD-10000-134, NEDD-10000-135, NEDD-10000-136, NEDD-10000-137, NEDD-10000-138, NEDD-10000-139, NEDD-10000-140, NEDD-10000-141, NEDD-10000-142, NEDD-10000-143, NEDD-10000-144, NEDD-10000-145, NEDD-10000-146, NEDD-10000-147, NEDD-10000-148, NEDD-10000-149, NEDD-10000-150, NEDD-10000-151, NEDD-10000-152, NEDD-10000-153, NEDD-10000-154, NEDD-10000-155, NEDD-10000-156, NEDD-10000-157, NEDD-10000-158, NEDD-10000-159, NEDD-10000-160, NEDD-10000-161, NEDD-10000-162, NEDD-10000-163, NEDD-10000-164, NEDD-10000-165, NEDD-10000-166, NEDD-10000-167, NEDD-10000-168, NEDD-10000-169, NEDD-10000-170, NEDD-10000-171, NEDD-10000-172, NEDD-10000-173, NEDD-10000-174, NEDD-10000-175, NEDD-10000-176, NEDD-10000-177, NEDD-10000-178, NEDD-10000-179, NEDD-10000-180, NEDD-10000-181, NEDD-10000-182, NEDD-10000-183, NEDD-10000-184, NEDD-10000-185, NEDD-10000-186, NEDD-10000-187, NEDD-10000-188, NEDD-10000-189, NEDD-10000-190, NEDD-10000-191, NEDD-10000-192, NEDD-10000-193, NEDD-10000-194, NEDD-10000-195, NEDD-10000-196, NEDD-10000-197, NEDD-10000-198, NEDD-10000-199, NEDD-10000-200, NEDD-10000-201, NEDD-10000-202, NEDD-10000-203, NEDD-10000-204, NEDD-10000-205, NEDD-10000-206, NEDD-10000-207, NEDD-10000-208, NEDD-10000-209, NEDD-10000-210, NEDD-10000-211, NEDD-10000-212, NEDD-10000-213, NEDD-10000-214, NEDD-10000-215, NEDD-10000-216, NEDD-10000-217, NEDD-10000-218, NEDD-10000-219, NEDD-10000-220, NEDD-10000-221, NEDD-10000-222, NEDD-10000-223, NEDD-10000-224, NEDD-10000-225, NEDD-10000-226, NEDD-10000-227, NEDD-10000-228, NEDD-10000-229, NEDD-10000-230, NEDD-10000-231, NEDD-10000-232, NEDD-10000-233, NEDD-10000-234, NEDD-10000-235, NEDD-10000-236, NEDD-10000-237, NEDD-10000-238, NEDD-10000-239, NEDD-10000-240, NEDD-10000-241, NEDD-10000-242, NEDD-10000-243, NEDD-10000-244, NEDD-10000-245, NEDD-10000-246, NEDD-10000-247, NEDD-10000-248, NEDD-10000-249, NEDD-10000-250, NEDD-10000-251, NEDD-10000-252, NEDD-10000-253, NEDD-10000-254, NEDD-10000-255, NEDD-10000-256, NEDD-10000-257, NEDD-10000-258, NEDD-10000-259, NEDD-10000-260, NEDD-10000-261, NEDD-10000-262, NEDD-10000-263, NEDD-10000-264, NEDD-10000-265, NEDD-10000-266, NEDD-10000-267, NEDD-10000-268, NEDD-10000-269, NEDD-10000-270, NEDD-10000-271, NEDD-10000-272, NEDD-10000-273, NEDD-10000-274, NEDD-10000-275, NEDD-10000-276, NEDD-10000-277, NEDD-10000-278, NEDD-10000-279, NEDD-10000-280, NEDD-10000-281, NEDD-10000-282, NEDD-10000-283, NEDD-10000-284, NEDD-10000-285, NEDD-10000-286, NEDD-10000-287, NEDD-10000-288, NEDD-10000-289, NEDD-10000-290, NEDD-10000-291, NEDD-10000-292, NEDD-10000-293, NEDD-10000-294, NEDD-10000-295, NEDD-10000-296, NEDD-10000-297, NEDD-10000-298, NEDD-10000-299, NEDD-10000-300, NEDD-10000-301, NEDD-10000-302, NEDD-10000-303, NEDD-10000-304, NEDD-10000-305, NEDD-10000-306, NEDD-10000-307, NEDD-10000-308, NEDD-10000-309, NEDD-10000-310, NEDD-10000-311, NEDD-10000-312, NEDD-10000-313, NEDD-10000-314, NEDD-10000-315, NEDD-10000-316, NEDD-10000-317, NEDD-10000-318, NEDD-10000-319, NEDD-10000-320, NEDD-10000-321, NEDD-10000-322, NEDD-10000-323, NEDD-10000-324, NEDD-10000-325, NEDD-10000-326, NEDD-10000-327, NEDD-10000-328, NEDD-10000-329, NEDD-10000-330, NEDD-10000-331, NEDD-10000-332, NEDD-10000-333, NEDD-10000-334, NEDD-10000-335, NEDD-10000-336, NEDD-10000-337, NEDD-10000-338, NEDD-10000-339, NEDD-10000-340, NEDD-10000-341, NEDD-10000-342, NEDD-10000-343, NEDD-10000-344, NEDD-10000-345, NEDD-10000-346, NEDD-10000-347, NEDD-10000-348, NEDD-10000-349, NEDD-10000-350, NEDD-10000-351, NEDD-10000-352, NEDD-10000-353, NEDD-10000-354, NEDD-10000-355, NEDD-10000-356, NEDD-10000-357, NEDD-10000-358, NEDD-10000-359, NEDD-10000-360, NEDD-10000-361, NEDD-10000-362, NEDD-10000-363, NEDD-10000-364, NEDD-10000-365, NEDD-10000-366, NEDD-10000-367, NEDD-10000-368, NEDD-10000-369, NEDD-10000-370, NEDD-10000-371, NEDD-10000-372, NEDD-10000-373, NEDD-10000-374, NEDD-10000-375, NEDD-10000-376, NEDD-10000-377, NEDD-10000-378, NEDD-10000-379, NEDD-10000-380, NEDD-10000-381, NEDD-10000-382, NEDD-10000-383, NEDD-10000-384, NEDD-10000-385, NEDD-10000-386, NEDD-10000-387, NEDD-10000-388, NEDD-10000-389, NEDD-10000-390, NEDD-10000-391, NEDD-10000-392, NEDD-10000-393, NEDD-10000-394, NEDD-10000-395, NEDD-10000-396, NEDD-10000-397, NEDD-10000-398, NEDD-10000-399, NEDD-10000-400, NEDD-10000-401, NEDD-10000-402, NEDD-10000-403, NEDD-10000-404, NEDD-10000-405, NEDD-10000-406, NEDD-10000-407, NEDD-10000-408, NEDD-10000-409, NEDD-10000-410, NEDD-10000-411, NEDD-10000-412, NEDD-10000-413, NEDD-10000-414, NEDD-10000-415, NEDD-10000-416, NEDD-10000-417, NEDD-10000-418, NEDD-10000-419, NEDD-10000-420, NEDD-10000-421, NEDD-10000-422, NEDD-10000-423, NEDD-10000-424, NEDD-10000-425, NEDD-10000-426, NEDD-10000-427, NEDD-10000-428, NEDD-10000-429, NEDD-10000-430, NEDD-10000-431, NEDD-10000-432, NEDD-10000-433, NEDD-10000-434, NEDD-10000-435, NEDD-10000-436, NEDD-10000-437, NEDD-10000-438, NEDD-10000-439, NEDD-10000-440, NEDD-10000-441, NEDD-10000-442, NEDD-10000-443, NEDD-10000-444, NEDD-10000-445, NEDD-10000-446, NEDD-10000-447, NEDD-10000-448, NEDD-10000-449, NEDD-10000-450, NEDD-10000-451, NEDD-10000-452, NEDD-10000-453, NEDD-10000-454, NEDD-10000-455, NEDD-10000-456, NEDD-10000-457, NEDD-10000-458, NEDD-10000-459, NEDD-10000-460, NEDD-10000-461, NEDD-10000-462, NEDD-10000-463, NEDD-10000-464, NEDD-10000-465, NEDD-10000-466, NEDD-10000-467, NEDD-10000-468, NEDD-10000-469, NEDD-10000-470, NEDD-10000-471, NEDD-10000-472, NEDD-10000-473, NEDD-10000-474, NEDD-10000-475, NEDD-10000-476, NEDD-10000-477, NEDD-10000-478, NEDD-10000-479, NEDD-10000-480, NEDD-10000-481, NEDD-10000-482, NEDD-10000-483, NEDD-10000-484, NEDD-10000-485, NEDD-10000-486, NEDD-10000-487, NEDD-10000-488, NEDD-10000-489, NEDD-10000-490, NEDD-10000-491, NEDD-10000-492, NEDD-10000-493, NEDD-10000-494, NEDD-10000-495, NEDD-10000-496, NEDD-10000-497, NEDD-10000-498, NEDD-10000-499, NEDD-10000-500, NEDD-10000-501, NEDD-10000-502, NEDD-10000-503, NEDD-10000-504, NEDD-10000-505, NEDD-10000-506, NEDD-10000-507, NEDD-10000-508, NEDD-10000-509, NEDD-10000-510, NEDD-10000-511, NEDD-10000-512, NEDD-10000-513, NEDD-10000-514, NEDD-10000-515, NEDD-10000-516, NEDD-10000-517, NEDD-10000-518, NEDD-10000-519, NEDD-10000-520, NEDD-10000-521, NEDD-10000-522, NEDD-10000-523, NEDD-10000-524, NEDD-10000-525, NEDD-10000-526, NEDD-10000-527, NEDD-10000-528, NEDD-10000-529, NEDD-10000-530, NEDD-10000-531, NEDD-10000-532, NEDD-10000-533, NEDD-10000-534, NEDD-10000-535, NEDD-10000-536, NEDD-10000-537, NEDD-10000-538, NEDD-10000-539, NEDD-10000-540, NEDD-10000-541, NEDD-10000-542, NEDD-10000-543, NEDD-10000-544, NEDD-10000-545, NEDD-10000-546, NEDD-10000-547, NEDD-10000-548, NEDD-10000-549, NEDD-10000-550, NEDD-10000-551, NEDD-10000-552, NEDD-10000-553, NEDD-10000-554, NEDD-10000-555, NEDD-10000-556, NEDD-10000-557, NEDD-10000-558, NEDD-10000-559, NEDD-10000-560, NEDD-10000-561, NEDD-10000-562, NEDD-10000-563, NEDD-10000-564, NEDD-10000-565, NEDD-10000-566, NEDD-10000-567, NEDD-10000-568, NEDD-10000-569, NEDD-10000-570, NEDD-10000-571, NEDD-10000-572, NEDD-10000-573, NEDD-10000-574, NEDD-10000-575, NEDD-10000-576, NEDD-10000-577, NEDD-10000-578, NEDD-10000-579, NEDD-10000-580, NEDD-10000-581, NEDD-10000-582, NEDD-10000-583, NEDD-10000-584, NEDD-10000-585, NEDD-10000-586, NEDD-10000-587, NEDD-10000-588, NEDD-10000-589, NEDD-10000-590, NEDD-10000-591, NEDD-10000-592, NEDD-10000-593, NEDD-10000-594, NEDD-10000-595, NEDD-10000-596, NEDD-10000-597, NEDD-10000-598, NEDD-10000-599, NEDD-10000-600, NEDD-10000-601, NEDD-10000-602, NEDD-10000-603, NEDD-10000-604, NEDD-10000-605, NEDD-10000-606, NEDD-10000-607, NEDD-10000-608, NEDD-10000-609, NEDD-10000-610, NEDD-10000-611, NEDD-10000-612, NEDD-10000-613, NEDD-10000-614, NEDD-10000-615, NEDD-10000-616, NEDD-10000-617, NEDD-10000-618, NEDD-10000-619, NEDD-10000-620, NEDD-10000-621, NEDD-10000-622, NEDD-10000-623, NEDD-10000-624, NEDD-10000-625, NEDD-10000-626, NEDD-10000-627, NEDD-10000-628, NEDD-10000-629, NEDD-10000-630, NEDD-10000-631, NEDD-10000-632, NEDD-10000-633, NEDD-10000-634, NEDD-10000-635, NEDD-10000-636, NEDD-10000-637, NEDD-10000-638, NEDD-10000-639, NEDD-10000-640, NEDD-10000-641, NEDD-10000-642, NEDD-10000-643, NEDD-10000-644, NEDD-10000-645, NEDD-10000-646, NEDD-10000-647, NEDD-10000-648, NEDD-10000-649, NEDD-10000-650, NEDD-10000-651, NEDD-10000-652, NEDD-10000-653, NEDD-10000-654, NEDD-10000-655, NEDD-10000-656, NEDD-10000-657, NEDD-10000-658, NEDD-10000-659, NEDD-10000-660, NEDD-10000-661, NEDD-10000-662, NEDD-10000-663, NEDD-10000-664, NEDD-10000-665, NEDD-10000-666, NEDD-10000-667, NEDD-10000-668, NEDD-10000-669, NEDD-10000-670, NEDD-10000-671, NEDD-10000-672, NEDD-10000-673, NED

DOCKETED ITEMS

237

0036890215 First set of interrogatories & requests for production of documents directed to Intervenor G. Baker Requests identification of expert witnesses & matters related to testimony Certificate of the and Related correspondence BIDDLE, J G Hensley Lighting & Power Co BIDDLE, J G Baker & Mott. 06/05/17 See

==B0061A017B Notice requesting R or H Franson to appear for B0061B
deposition on behalf of still at athena sfc.ms connections
admitted by AMSP B0061C order instructions & Certificate of
Ex. encl
BIDDLE, C T Houston Lighting & Power Co BIDDLE, C T Baker &
Sons, Houston, Tex.

0004120061 First set of interrogatories & requests for production of documents directed to intervenor SA Doggett. Requests identification of witnesses & facts related to planned expert testimony. Certificate of Doc until 0004120061 T. MEMPHIS JR Houston Lighting & Power Co 0004120061 T Baker & Betts 00/05/17 Doc

0006190101 FOIA request for ID documents specifically identified by
accession number, docket numbers & brief description to aid
in facility processing
BQHRTY, J F BQHRTY, J F 03/05/20 4pp

0006070605 Order granting applicant 0004279 motion to compel production of documents from interviewers C Hinderstein & TX FIRM re documents not produced on 0005010 [interviewers shall comply w/order by 0006079]
WLFJE, G. J. Atomic Safety and Licensing Board Panel 05/05/00 25

—000070076 Express concerns re exemption of plants from reviews in
consideration on catastrophic events
WEINRED-R/NOT Affiliation Unknown 00/00/00 Ray

---000690583 Urges issuance of supplemental SID re Client T accident
potential Certificate of Muc anal
SCHWITZ, A R Term: Skote of 00/03/22 4pp

6034320642 First set of interrogatories & requests for production of documents directed to Intervenor 3 Monarch Requests
Identification of witnesses & notice related to planned expert testimony Certificate of Service
BIDDLE, C T, NERHAM, J H Houston Lighting & Power Co BIDDLE, C T
Baker & Pettit 06/03/17 5:00

0004170204 Order granting applicant 0004209 motion to compel production of documents from intervenors G Hinderstein & TX FINE re three groups of documents not produced on 000510 Intervenor's shall comply under by 0006009

803a26097 First set of interrogatories & requests for production of documents directed to intervenor PW Potteboff. Requests identification of witnesses & native related to planned expert testimony. Certificate of Doc sent

RIDDLE C T, MEMPHIS J R Houston Lighting & Power Co RIDDLE C T Baker & Smith 8/6/08/17 Sup

000640000 Response to Houston Lighting & Power first set of
interrogatories & requests for production of documents.
Interview witness & testimony-related documents are
unknown certificate of live until Related correspondence
***** B-4 *****
***** B-4 *****

documents from TX PIRD & G Hindemstein Financial terms
between intervenors & witnesses are proprietary in nature.
TX PIRD does not possess city water supply studies
SCOTT-J Texas Public Interest Research Group 08/05/03 3pp

000120417 Urges that applicant 000429 motion be granted to compel production of documents from Ts PIRG & C Hinderstaedt, re three groups of documents not produced on 000012 Certificate of Exc and Related correspondence

NR01MM, J R Lauenstein, Neuman, Reia, Arnold & Tall 00/05/20 40

0036045115 Second partial response to JF Oshery twelfth set of interrogatories includes NUREG CR-3440 recommendations, DE field inspections of QA program implementation, and diesel generator events AR264611 and Certificate of Review and Approval, AEP-100, Revision 1, March 9, 1994.

0034180194 Notice of 000413 deposition at author aft.directed to Mr.
Baker is testify on behalf of utility contentions admitted
per ARLE 000310 under Instructions & Certificate of Ave
encl
COPELAND, J O Houston Lighting & Power Co COPELAND, J O Baker
Baker 00/05/20 app

MOBILE10175 Motion to quash applicant 000429 motion to compel produc
of documents from C Hinderstein & TS PIRN No written
contract or agreement w/Baron exists Other info requested

000519050 Statement of position re linkage of financial qualification
to safety ASSE 000310 under did not prevent intervenors from
examining linkage between financial qualifications & safety.
Certificate of Gov encl Related correspondence
SARIS, D. Affiliation Unknown 00036700_4aa

---000690557 Response to applicant first set of interrogatories & request for production of documents. Witnesses as yet unknown. Certificate of Doc and Related correspondence.

--00010000 Notice of 000412 deposition at author's direction to D
Duggert to testify on behalf of utility conventions admitted
per ASLR 000010 order instructions & Certificate of Doc
and
COPELAND, J D Houston Lighting & Power Co. COPELAND, J D Saka
Saka, PO-10000, doc.

--2006170864 Second set of interrogatories & request for production of documents Requests identity of witnesses Certificate of Ovc

8036020466 Order granting in part & denying in part applicant's 032501
motion to confine agreements on consolidation & to
consolidate certain contentious Lead party must be appointed
in 10 days to present evidence cross-examine & plead
SUN SEC E. Shanks, Robert and J. Greenlee, David, David 80488623

000419069 First set of interrogatories re consolidated bankruptcies
Support 4 & Proposed 1 Requests info re witnesses, financial
statements of const delays & estimate of date of commercial
operation Certificate of Rev encl Related correspondence

BOA060663 Advises that authors do not share IH Lase concerns that ALAB-990 eliminates bases requirement for contentions. AGLD is not free to determine whether petitioner has correctly relied on bases cited.

PARIS, G H.; ECHENBERG, G.; WHALF, J. Atomic Safety and Licensing

8004140028 Forwards 800606 Interrogatories & requests for production documents - JUDGE0014.C Texas Public Interest Research Group, 8004140026, to

---800616029 Interregatories & requests for production of documents.
Includes questions re computation of stress capabilities of
resistor coolant boundaries & length of time required for

000460166 Notice requesting D Herbeck to appear for \$50420 deposit
on behalf of utilitat author of.cve certifications admitted by
ASLR 000300 order instructions & Certificate of sue sue!
Related correspondence
000460166 Houston Lighting & Power Co. 010460166 Baker &
Botts 06/05/97 due

0006100427 Recommends that AGLAS composition be changed to remove imbalance between lawyer & technical members & that unnecessary legislative burdens, procedures & requirements be eliminated.

DOCKETED ITEMS

H. General correspondence

0004040568 Request mod of first page of Distribution list Distribution list 0001
NICKERLAW F Boston Edison Co 00/04/07 3pp

I. Advisory Committee on Reactor Safeguards reports & correspondence

0004000530 Forward ACRG ltr re near-term CP applications
SCHUBNER A Licensing Branch 3 00/03/00 4pp

--0004000536 Discusses ACRG 000501-03 meeting re review of near-term CPs
larger than NRC resources be made available for resolution
of action plan items & policy questions
FLEISCHER H ACRG - Advisory Committee on Reactor Safeguards
00/03/06 3pp

G. Inspection reports, IE Bulletins & correspondence

0004100532 Request provision of personnel for field survey re plant
troubleshooting. Ltr to 0003010 until allow ins of use
of structure. Site visit necessary to recommend final
approval of design & placement
FLEISCHER H E Hydrological & Geotechnical Engineering Branch 00/05/20
2pp

DOCKET 00H-90-000 WOLF CREEK GENERATING STATION

A. Application/construction stage documents & correspondence

0004000510 Advise NRC & PWR applicants of NRC desires to modify
implementation plan presented in Section 4 of 00050-0007 re
adequacy of applicable support structures. General operating
reactor review procedure & acceptance criteria sent
FLEISCHER H E Division of Licensing 00/05/25 13pp

0004000516 Reports that ASME Code Case N-73-9 re add note for
competent supports fabricated by welding is continuously
approved for general use
FLEISCHER H E Licensing Branch 3 00/06/10 1p

F. Security, medical, emergency & fire protection plans

0004100535 Discusses review of 00010007 ltr responding to questions
re 94 programs for fire protection. Requests that 0001 & CP
holders be informed that responses are acceptable
HARRIS W F Quality Assurance Branch 00/04/05 1p

0004000534 Confirm intention to submit security training &
qualification plan by 000101
HARRIS W F Kansas Gas & Electric Co 00/06/10 3pp

G. Adjudicatory correspondence

0004000529 Notice of withdrawal from proceedings effective 000402
Certificate of Rev and
LEWIS S H Hearing Branch 2 00/04/05 3pp

H. Antitrust correspondence

0004000540 Ask receipt of 000306 ltr submitting antitrust info per Reg
Guide 9.3
HARRIS W F Utility Finance Branch 00/05/01 1p

F. Operating license stage documents & correspondence

0004000544 Forward Conak Technology Labs "MR Marsh Basemat Concrete
Testing Program," supporting void content that basemat
concrete is uniform & of high quality material in use
throughout exceeding 3,000 psi
HARRIS W F Kansas Gas & Electric Co 7/9/00/06 3pp

--0004000547 "MR Marsh Basemat Concrete Testing Program"
SHIMMEL J J CAMPBELL B H Construction Technology Laboratories
City of Portland Cement Assoc 3 7/9/00/06 43pp

G. Inspection reports, IE Bulletins & correspondence

0004000547 Forward IE Circular 00-05, "Emergency Diesel Generator
Lubricating Oil Addition & Onsite Supply." No written
response required
HARRIS W F Region 4, Dallas, Office of the Director 00/04/01
1p

0004000550 Forward IE Insp Rept 00-482/00-08 on 000317-28 & notice
of violation
HARRIS W F Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/11 3pp

--0004000552 Notice of violation from Insp on 000317-28
Region 4, Dallas, Office of the Director 00/04/08 3pp

--0004000558 IE Insp Rept 00-482/00-09 on 000317-30 Noncompliance noted
Failure to provide prompt & adequate corrective action
HARRIS W F Region 4, Dallas, Office of the Director 00/04/09 4pp

0004000559 Forward IE Insp Rept 00-482/00-07 on 000301-0463 No
compliance noted
HARRIS W F Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/14 3pp

--0004000561 IE Insp Rept 00-482/00-07 on 000301-0463 No noncompliance
noted. Region 4, Dallas, Office of the Director 00/04/14 3pp

0004100566 Advise that IE Insp Rept 00-482/00-06 does not contain
proprietary info. Forwarding ltr 5 may be placed in PER
HARRIS W F Kansas Gas & Electric Co 00/04/24 1p

0004000560 Forward IE Bulletin 00-12, "Boysen Heat Removal Sys
Operability." No written response required IE ltr Rept
00-12, "Loss of Boysen Heat Removal Capability at Davis-Besse
Unit 5." Unit 5 Submittal Rept sent
HARRIS W F Region 4, Dallas, Office of the Director 00/05/09
1p

0004000564 Forward IE Circular 00-12, "Valve-Block-To-Actuator Key Map
Full Set of Plans when Modified Detail Horizontal Axis." No
written response required
HARRIS W F Region 4, Dallas, Office of the Director 00/05/14
1p

0004000565 Ask receipt of 000309 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 00-482/00-05
HARRIS W F Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/05/22 1p

--0004000568 Responds to NRC 000411 ltr re violations noted in IE Insp
Rept 00-482/00-09 Corrective actions. Storage bins have been
inspected. Insulation sealed & drainage around bins improved
HARRIS W F Kansas Gas & Electric Co 00/05/07 3pp

0004100571 Forward IE Investigation Rept 00-482/00-10 on 000409-00 No
noncompliance noted
HARRIS W F Region 4, Dallas, Office of the Director 00/05/29
1p

--0004100578 IE Investigation Rept 00-482/00-10 on 000409-00 No
noncompliance noted. Major areas inspected. Allegations that
supervisors & labor personnel involved in narcotics use at
site
HARRIS W F HARRIS W F HARRIS W F HARRIS W F HARRIS W F
00/05/29 4pp

0004100582 Responds to IE Bulletin 00-09 re vacuum condition resulting
in damage to chemical vent control gas buildup tanks. Tanks
damage due to vacuum condition. Insulation around tanks improved.
Provisions for suitable vent connections
HARRIS W F Standardized Nuclear Unit Power Plant System
00/05/06 3pp

B. Reportable occurrences, LERs & related correspondence

0004000583 Potential deficiency rept re Rockwell cable jacket
installation defects. Jacket defects do not affect nuclear
qualification or ability of cable to perform intended
function. Defects do not constitute reportable deficiency
HARRIS W F Kansas Gas & Electric Co 00/05/08 1p

0004000585 Deficiency rept re cracks in refueling pool flange adjacent
to reactor center. Act failure to submit timely Rept to NRC
Cracks are being evaluated by Doctel. Problem does not
appear to constitute reportable deficiency
HARRIS W F Kansas Gas & Electric Co 00/05/14 1pp

0004200591 Forward Doctel 000590 suppl to final deficiency rept re
Austin ltr re vertical air dampers. Had proposed to 000319
final rept is unacceptable. Since Austin & Austin could
become ltr re Austin. Has developed successful design. Had
PETERSON A Standardized Nuclear Unit Power Plant System
00/05/16 3pp

DOCKETED ITEMS

000800041 Part 21 rept re pipe support wavy struts w/loader bushings
During recent overhauling could be overhauled struts
have been removed to correct deficiencies
NCE/SJS, D L Bethel Cox 00/05/10 Jap

■ General correspondence

0006020451 Responds to 000324 request for info re applicat
Facility of NRC revisions in plant design & safety stds
Resulting from TMI-2 accident Revisions published in eng
NAREDS OSTG & SSES W/o encls
VOLUME 000, P. 1 Licensing Branch C, 000007Z Dec

0004120011: Internal defueling rack in centrifugal charging pump operation following secondary side line rupture discussed in 000508 helicon Evaluation of transient described in Westinghouse 003508 ltr will be provided pending completion PETROCK, M.A. Standardized Nuclear Unit Power Plant System 00/04/76 dss

890610240 Submits info re recent functional changes in whl
organizational structure
BRVAM, J R. Union Electric Co. 89/06/06 in

⑤ Inspection reports, 18 Bulletins & correspondence

0304200200 Follows up E00000 notification of potential deficiency re
liner indications in pipe span in essential avg water
discharge line Evaluation determining matter not reportable
HOUSTON, D L. Kiewit Gas & Electric Co. E0/04/00A In

ST00090606 Formerly IZ Insp Repts 30-482/89-01 ex 000107-07 No
noncompliance noted
FIORELLI, R Region 3; Chicago, Reacher Construction & Engineering
Slovak, Robert 800.224.1777 Dec

MO04244004 Follow up 000509 notification of potential deficiency re
enter coding of wires in safety-related switchgear supplied
by GE Evaluation determined matter not reportable
ROEBTER, G L. Kansas Gas & Electric Co 00/06/04 is

--0004005011 IE Insp Rept 80-583/00-01 on 000107-09 Re noncompliance
w/ed Major areas inspected QA program relating to control
of design & procurement, audit program & document control
MMP, R C, WESCOTT, H M, HANSEN, W Region 3, Chicago, Office of
the Director 80/04/17 Doc.

9004280403 Act receipt of \$60000 final deficiency waph re Bunker Raco
Corp electrical gear/shield assemblies
CARLSON H Y Region 3, Philadelphia, Reactor Construction &
Engineering Division Branch 80060000 IP

8906170196 Forwarded 12 Sep Sept 90-482/00-07 on 800311-14 & notice
of violation
FIRMAL.L.S Region 3, Chicago, Weaver Construction & Engineering
Support Branch 20/04/90 Dan

found penetration wire terminations with insulation extending into terminal lug barrel & incorrectly sized lugs on wire inside. Hold on add fabrication at Nuclear Kanto established.

SSNDW-6 J Standardized Nuclear Unit Power Plant System 05/06/12

3pp

—B06470197 Notice of violation from line on B06011-14

* Region 3: Chicago, Office of the Director 80504/25

2006170412 Supplement 800506 Interim deficiencies re:pt re quality &
integrity of penetration wire terminations And terminations
found w/insulation standing into or through terminal lug
barrel Assessment of Busbar Name DA & rpt underway
RETURNED Standardized Nuclear Unit Power Plant System 80/06/12
Doc

--B004170W01 IE Insp Rept 50-462/80-07 on B00311-14 Noncompliance w/ failure to establish procedure to control welding
B00307T:H H : RMOP:R C Region 3, Chicago Office of the Director
80/04/25 App

BUCKET 8TH-50-400 CALLOWAY PLANT, 100Y.

Application/construction stage documents & correspondence

NO041ED410 Forwards IE Insp Rpt 50-462/80-11 on 000029-27 Ha
noncompliance noted
FIDELLIG Region D, Chicago, Reactor Construction & Engineering
Support Branch 00/04/29 2xx

0004170230 Summaries questions transmitted to Echelon as result of
800400 meeting re civil and natl rept
ECHINEL, G P Union Electric Co, St. Louis, Mo.

000180414 IE Insp Rept 80-403/80-11 on 80025-27 No noncompliances
 noted Major areas inspected safety-related structural
 concrete & masonry work
 LANDSHUTZ & Region 3, Chicago, Office of the Director
 HAYES, R & Region 3, Chicago, Reactor Construction & Engineering
 Report Branch 80/04/20 dss

DOE/NE-0011000 Advice and PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure and acceptance criteria and EIS/NEUT.00 Division of Licensing 00/05/20 1000.

106170187 Forwards connected copy of HRC 800426 ltr-transmitting IT
link Sept 93-402/90-07
FIDRELLI, B Region 3, Chicago, Reactor Construction & Engineering
Support Branch, MO/nuem, 1-

0062000014	Region 4 Chicago Office of the Director	06/06/02	fy
0062000014 Forwards reorganization chart for Ofc of Nuclear Reactor Regulation Facility licensing matters will be handled by R Start Transition being made within of disruption to ongoing activities			
TEDECO, R L	Assistant Director for Licensing	06/06/02	See

-0056170195 Corrected copy of 800426 ltr forwarding IE Insp Rpt
80-403780-87 & notice of violation W/o seals
F100MLL:0 Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80-058700 2-88

0625019A, Reports that HERE Code Case H-71-9 re Add welds for
compartments supports fabricated by welding is conditionally
approved for general use
HOUNGHELOO, B J Licensing Branch 1 0625019A 1

60490067 Forward: IE Insp Rept 90-482/90-09 re 600423-24 & notice of violation
FIDHLL1.0 Region 3, Chicago, Reactor Construction & Engineering
Support Branch 00/CR/14 Doc

Securing, medical, emergency & fire protection plans

* Region 3, Chicago, Office of the Director 80/03/12 1p

holders be informed that responses are acceptable
HAAS/W P Quality Assurance Branch 88066/05 10

8004266073 IE Insp Rept 95-483/80-89 on 800423-24 Noncompliance with
failure to implement design instructions shown in design
drawings. A loadable Insp program to provide timely
verification of work per design requirements
DANIELSON, G H Region 3, Chicago, Reactor Construction &
Engineering Support Branch VIN. 1 T Region 3, Chicago, Office
the Director 03/05/12 Abs

35420312 Response to PE Bulletin 80-05 re vacuum condition resulting in damage to chemical val control sys holder tanks Tank damage due to vacuum conditions precluded by design provisions at suitable vent connections

040700363 Acl receipt of 000820M ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-083/00-07
#100001,0 Region 3, Chicago. Weather Construction & Engineering
Support Branch. 000820M 30-

DOCKETED ITEMS

235

--000423560 Response to NRC 800436 ltr re violations noted in IE insp
Reps 30-00042357 Corrective actions arranging meeting
w/Bechtel & P-W Industries to resolve questions re welding
procedures used for cable tie fasteners
BRYAN J K Union Electric Co 80/05/28 2pp

5 Reportable occurrences, LERs & related correspondence

800423018 Forwarder Bechtel 800508 report to final deficiency report re
Bunker Hfg Co structural fire damage prior to proposed in 800515
final report is unacceptable since NRC has a serious concern
because Bunker Hfg has developed successful design and
PETROLIO, H A. Standardized Nuclear Unit Power Plant System
80/05/16 0pp

800423001 Ack receipt of 800512 interim deficiency report re improper
grading of heavy structural members prior to welding
NRC will review final report upon receipt
PETERLIN, G. Region 1, Philadelphia. Reactor Construction & Engineering
Support Branch 80/05/22 1p

800423034 Ack receipt of 800516 final deficiency report re Bunker Hfg Co
fire damage
CARLSON, R T. Region 1, Philadelphia. Reactor Construction &
Engineering Support Branch 80/05/22 1p

800412031 Interim deficiency report re centrifugal charging pump
operation following secondary side line rupture discussed in
800508 letter Evaluation of Damages described in
Washington 800508 ltr will be provided pending completion
PETROLIO, H A. Standardized Nuclear Unit Power Plant System
80/05/26 2pp

800423040 Ack receipt of 800506 final deficiency report re Bunker Hfg
Co electrical penetration assemblies
CARLSON, R T. Region 1, Philadelphia. Reactor Construction &
Engineering Support Branch 80/05/26 1p

800417092 Supplemental deficiency report advising NRC that add insp
found penetrations wire terminations in insulation extending
into terminal lug barrel & incorrectly sized lugs on wire
module hold in add'l fabrication at Bunker Hfg established
800423016 J. Standardized Nuclear Unit Power Plant System 80/06/12
2pp

800417012 Supplemental 800508 interim deficiency report re quality &
integrity of penetrations wire terminations. Add'l terminated
found insulation extending into or through terminal lug
barrel. Assessment of Bunker Hfg on & not underway
800423016 J. Standardized Nuclear Unit Power Plant System 80/06/12
2pp

800423041 Interim deficiency report re surface mounted plates
disposition of surface mounted plates under final
report will be issued on 800508
BRYAN J K Union Electric Co 80/06/16 1p

U Congressional/Executive Correspondence

800412080 Expresses concern over delays in NRC review of pending
OL applications for facilities. Failure to carry out reviews
in timely manner is unacceptable. Schedule for reviews should
be developed & implemented
FAGLETH, T F. - SANFORD J C. - BOLD, R. Senator, Governmental Affairs,
80/05/16 4pp

DOCKET WITH-30-403 STERLING POWER PROJECT NUCLEAR UNIT 1

A Application/construction stage documents & correspondence

800423010 Advises BWR & PWR applicants of NRC decision to modify
implementation plan presented in Section A of NUREG-0577 re
adequacy of applicable support structures. General operating
reactor review procedure & acceptance criteria met
KREMER, H D. G. Division of Licensing 80/05/20 13pp

800418037 Comments on 800506 presentation to NRC Commissioners re
status of NRC & description of deficiencies as lack of
agreement by licensee NRC has not provided guidelines
inadequate regulatory priorities have arisen
MUTTLER, D. Rochester Gas & Electric Corp 80/06/12 2pp

5 Adjudicatory correspondence

800412047 Requests confirmation of NRC decision re licensing of
proposed facility ltr prompted by 800501 ltr to editor in
Times-Union newspaper in which JE Houston claimed project
was cancelled
BROOKMAN, D A. Atomic Safety and Licensing Appeal Panel 80/05/26
2p

800423045 Request for extension until 800618 for petition, except NRC, to
submit post-hearing memoranda re radon issue. Second lengthy
& intervenors have other commitments made prior to Feb 1980
Certificate of Rev. met
HARRIS, C. Citizens for Safe Environment 80/05/20 4pp

800423046 Correction to licensee's 800428 brief on disposition of
alleged violations & Certificate of Rev. met
MELBERG, J F. Philadelphia Electric Co 80/05/20 5pp

800423047 Response to intervenors. Veri Committee for Safe Environment &
Citizens for Safe Environment request for extension until
800618 to file proposed findings of fact in generic radon
proceeding. Many delays in proceeding are caused by various
CONRAD, T E. Philadelphia Electric Co 80/05/23 11pp

800423050 Order granting extension until 800618 for Veri Committee for
Safe Environment & Citizens for Safe Environment to file proposed
findings of fact & conclusions of law. NRC findings due on
800703 & intervenors' & applicant's responses on 800718
BROOKMAN, D A. Atomic Safety and Licensing Appeal Panel 80/05/26
2pp

800423053 Order, CL-10-83 affirming NRC decision ALM-502. Separate
views of Commissioners Kennedy & Heffner, separate views of
Commissioner Gilman & dissenting views of Chairman
CHILKOT, J. Office of the Secretary of the Commission 80/05/29
12pp

800411012 Advises that no clear basis exists for termination of
proceeding due to unconfirmed reports of contamination of
project. Applicant must plainly set forth intentions
MELBERG, J F. Hearing Branch 3 80/06/06 3pp

800423077 Memorandum & order vacating for mootness AOL 1977 initial
decision which authorized issuance of CP Regulation
terminated. Director of Nuclear Reactor Regulation instructed
to revoke authorization CP
BROOKMAN, D A. Atomic Safety and Licensing Appeal Panel 80/06/17
2pp

800423078 Memorandum & order advising that BWRing issue is no longer
pertinent to consolidated proceedings where radon issue is
being determined. Ecology Action case for last intervention
must be filed by 800702
BROOKMAN, D A. Atomic Safety and Licensing Appeal Panel 80/06/22
2pp

0 Inspection reports, IC Bulletin & correspondence

800423003 Forwarder IE Circular 80-10, "Grid Strap Damage in
Washington. Panel 1: Philadelphia. No written response required.
80/05/28 1p

800423012 Response to JE Bulletin 80-08 re vacuum condition resulting
in damage to chemical vent control lvs. Heating tanks. Test
damage due to vacuum conditions prohibited by design
provisions on suitable vent connections
PETROLIO, H A. Standardized Nuclear Unit Power Plant System
80/06/06 2pp

5 Reportable occurrences, LERs & related correspondence

800412031 Interim deficiency report re centrifugal charging pump
operation following secondary side line rupture discussed in
800508 letter Evaluation of Damages described in
Washington 800508 ltr will be provided pending completion
PETROLIO, H A. Standardized Nuclear Unit Power Plant System
80/06/06 2pp

DOCKET WITH-30-406 CALLOUGH PLANT, UNIT 2

A Application/construction stage documents & correspondence

800423026 Requests Commission notification of any acceleration in
facility cost schedule
CHILKOT, J. Office of the Secretary of the Commission 80/06/17
1p

DOCKETED ITEMS

237

0004180241 Motion for extension until 000825 or after to file exceptions to ARLB 000022 partial initial decision. Assisted resolution of petition to reopen record based on D Springer affidavit may make appeal unnecessary. NC Certificate of Div PFFPFR000000-W Paffenbarger & Cooley, P.A. 00/06/11 2pp

0004190440 Order declaring ARLB has jurisdiction to consider D Springer 000418 petition to intervene. Will not rule on merits until ARLB decides jurisdiction question. NRC must respond to petition & 000418 affidavit regardless of outcome. 000402-C J Atomic Safety and Licensing Board Panel 00/06/17 4pp

0004200442 Response in opposition to interveners' 000418 motion for add time to file exceptions to ARLB 000022 partial initial decision re alternate site issue. Motion is based on Springer affidavit which was opposed by NRC. NC Certificate of Div HCCAPWV-J M Duke Power Co HCCAPWV-J M Dobrowolski & Liberman 00/06/18 4pp

0004200448 Response in opposition to interveners' 000418 motion for extension until 000825 to file exceptions to ARLB 000022 partial initial decision on site alternative. Certificate of Div encl 000418-C J Atomic Safety and Licensing Board Panel 00/06/18 8pp

0004200445 Memorandum & order. ARLB-577 extending time to file exceptions to ARLB 000022 partial initial decision. LBLB takes action on interveners' petition to intervene & interveners' 000426 motion & until ARLB further order 000426-C J Atomic Safety and Licensing Board Panel 00/06/20 10pp

0004200201 Response in opposition to interveners' 000426 motion to reconsider or reopen record. Applicant has already opposed D Springer petition & affidavit on which interveners' motion was based as untimely & unsupported. Certificate of Div encl HCCAPWV-J M PORTER-H L Duke Power Co 00/06/23 3pp

0004200446 Response in opposition to interveners' 000426 motion to reconsider ARLB 000022 partial initial decision re site alternative. Motion untimely & reconsideration was not met. Certificate of Div encl 000418-C J Atomic Safety and Licensing Board Panel 00/06/26 10pp

0 Advisory Committee on Reactor Safeguards reports & correspondence

0004200020 Petitions RE Pleasur 000026 ltr to JC Aharne re near-term CP applications 0004200020-C J Licensing Branch 3 00/05/28 2pp

0004200006 Discusses ASRB review of near-term CPs. Util identified site policy issues. Interim position must be developed to resolve issues. PLPBBT-M R ASRB - Advisory Committee on Reactor Safeguards 00/06/06 3pp

0 Inspection reports, IE Bulletin & correspondence

0004200442 Petitions RE Bulletin 00-11, "Emergency Exit Design - No action or written response required RE Info Notice 7Y-02, "Overloading of Structural Elements Due to Pipe Support Loads" encl 000418-C J Region 2, Atlanta, Office of the Director 00/05/08 2pp

0004200339 Petitions RE Bulletin 00-12, "Emergency Heat Removal Sys Capability - No written response required RE Info Notice 7Y-02, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 (Units in Refueling Mode)" encl 000418-C J Region 2, Atlanta, Office of the Director 00/05/09 2pp

0004200123 Petitions RE Circular 00-11, "Emergency Diesel Generator Load D1 Cooler Failures - No written response required 000418-C J Region 2, Atlanta, Office of the Director 00/05/13 2pp

0004200229 Petitions response to IE Bulletin 00-09 re vacuum conditions resulting in damage to boiler tanks. Lists vacuum conditions in low pressure & boiler tanks by tank name, qty, quantity/ unit, design pressure & protective measures. DALL-C G Duke Power Co 00/06/09 2pp

0004210000 50-40V PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

0004230110 Affidavits BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of TWRB-0077 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria encl 0004230110-C J Division of Licensing 00/05/20 8pp

0004230149 Discusses representation of Div of Nuclear Reactor Regulation & advice that not responsibilities re facility have been assigned to C Non-Regulation claims encl 0004230149-C J Assistant Director for Licensing 00/06/12 11pp

0 Application correspondence

0004230144 Response in support of D Springer petition to intervene. Add info may be helpful in reaching proper decision. Certificate of Div & supporting documentation encl PFFPFR000000-W Paffenbarger & Cooley, P.A. 00/05/09 4pp

0004230204 Response in opposition to D Springer 000418 petition to intervene. Intervenor advanced grounds that have been previously rejected in 1976-77 petition. Petition untimely & unsupported by facts. Certificate of Div encl HCCAPWV-J M Duke Power Co HCCAPWV-J M Dobrowolski & Liberman 00/05/09 4pp

0004230227 Act receipt of NRC 000025 response to 000418 petition & ARLB 000007 memorandum & order. Urges that request for 60-day extension be considered. Certificate of Div encl 0004230227-C J Affiliation Unknown 00/05/12 1p

0004230189 Affidavit in support of D Springer 000418 petition alleging that neither NRC or ARLB has fully considered potential for once-through cooling & lower cooling. Supporting documentation & Certificate of Div encl 0004230189-C J Affiliation Unknown 00/05/21 13pp

0004230034 Petitions Pages 4-3 & 4 which were inadvertently omitted from Exhibit A of High Rock Lake Association 000026 affidavit 0004230034-C J High Rock Lake Association 00/05/03 1p

0004230071 Pages 4-3 & 4 of Exhibit A of High Rock Lake Association 000026 affidavit 0004230071-C J High Rock Lake Association 00/05/16 4pp

0004230310 Order granting extension until 000818 for Commission to review ARLB-001 CHILB-C J Office of the Secretary of the Commission 00/05/29 1p

0004230372 Order advising petition to file exceptions to ARLB 000022 partial initial decision. LBLB-00-07 re alternate site issue. Certificate of Div encl 0004230372-C J Atomic Safety and Licensing Board Panel 00/05/30 2pp

0004210348 Motion to reconsider ARLB 000022 decision or to reopen record due to reasons stated in D Springer affidavit. Certificate of Div encl PFFPFR000000-W Paffenbarger & Cooley, P.A. 00/06/06 2pp

0004210377 Response in opposition to D Springer 000418 affidavit re 000418 petition requesting 60-day extension to file documents supporting intervention. Affidavit to 000418 petition. Certificate of Div encl HCCAPWV-J M Duke Power Co HCCAPWV-J M Dobrowolski & Liberman 00/06/09 4pp

0004210201 Motion for extension until 000825 or after to file exceptions to ARLB 000022 partial initial decision. Assisted resolution of petition to reopen record based on D Springer affidavit may make appeal unnecessary. NC Certificate of Div PFFPFR000000-W Paffenbarger & Cooley, P.A. 00/06/11 2pp

0004210242 Order declaring ARLB has jurisdiction to consider D Springer 000418 petition to intervene. Will not rule on merits until ARLB decides jurisdiction question. NRC must respond to petition & 000418 affidavit regardless of outcome. 0004210242-C J Atomic Safety and Licensing Board Panel 00/06/17 4pp

0004240143 Response in opposition to interveners' 000411 motion for additional time to file exceptions to ARLJ 000322 partial initial decision re alternative site issue Motion is based on Springer affidavit which was opposed by utility W/Certificate of Doc. HCDARRY, J. H. Duke Power Co. HCDARRY, J. H. Debovisse & Liberman 00/04/10 App

0004230240 Response in opposition to interveners' 000411 motion for extension until 000325 to file exceptions to ARLJ 790202 partial initial decision on site alternatives Certificate of Doc. encl. DARTL, C. A. Hearing Branch 3 00/06/19 App

0004240415 Memorandum & order, ALAB-977, extending time to file exceptions to ARLJ 000322 partial initial decision: LEP-00-09, until ARLJ takes action re D Springer petition & interveners' 000406 motion & until ARLJ further order BIRNBERG, C. J. Atomic Safety and Licensing Appeal Panel 00/04/20 10pp

0004250021 Response in opposition to interveners' 000406 motion to reconsider or request record Applicant has already opposed D Springer petition & affidavit on which interveners' motion was based on utility & unsupported Certificate of Doc. encl. HCDARRY, J. H. & HORTER, W. L. Duke Power Co. 00/04/20 App

0004260046 Response in opposition to interveners' 000406 motion to reconsider ARLJ 000322 partial initial decision re site alternatives Motion unlikely & reconsideration sites not met Certificate of Doc. encl. DARTL, C. A. Hearing Branch 3 00/04/20 10pp

D Advisory Committee on Reactor Safeguards reports & correspondence

0004090002 Forwarded HS Planet 000506 ltr to JF Ahrens re near-term CP applications YOUNGBERG, S. J. Licensing Branch 1 00/03/28 App

-0004090003 Discusses ACRB review of near-term CPs. Utility identified six paper issues. Extension position must be formulated to resolve issues. PLESSET, H. B. ACRB - Advisory Committee on Reactor Safeguards 00/05/04 App

3 Inspection reports, SE Solicitation & correspondence

0004040043 Forwarded IE Bulletin 00-11, "Heating Vial Design - No action or written response required IE Info Bulletin 79-08, "Overloading of Structural Elements Due to Pipe Support Loads" encl. D'NEILL, J. P. Region 2, Atlanta, Office of the Director 00/05/08 2pp

0004040225 Forwarded IE Bulletin 00-12, "Energy Heat Removal Sys. Operability" - No written response required IE Info Bulletin 00-25, "Loss of Energy Heat Removal Capability at Sevier-Besse Unit 1 While in Refueling Mode" encl. D'NEILL, J. P. Region 2, Atlanta, Office of the Director 00/05/09 App

0004050122 Forwarded IE Circular 00-11, "Emergency Diesel Generator Lubrication System" - No written response required D'NEILL, J. P. Region 2, Atlanta, Office of the Director 00/05/10 2pp

0004050228 Forwarded response to IE Bulletin 00-09 re vacuum conditions resulting in damage to holdup tanks. Lists vacuum conditions in the pressure & holdup tanks by tank name, quantity, unit, design pressure & protective measures. DALL, C. Duke Power Co. 00/04/09 App

DOCKETED 00-09-440 PENNSYLVANIA NUCLEAR STATION, UNIT 3

A Application for construction stage documents & correspondence

0004230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of 04062-0577 re application of applicable support structures General operating reactor review procedures & acceptance criteria encl. BIRNBERG, C. J. Division of Licensing 00/05/20 10pp

0004250146 Discusses reorganization of Div. of Nuclear Reactor Regulation & advises that not yet reorganized re facilities have been assigned to C. Ross Reorganization chart encl. DEBBES, R. L. Assistant Director for Licensing 00/04/12 11pp

D Adjudicatory correspondence

0004070014 Response in support of D Springer petition to intervene. Addl info may be helpful in reaching proper decision Certificate of Doc. & supporting documentation encl. PEPFERKORN, H. P. Hearing Branch 3 00/03/09 App

0004120042 Response in opposition to D Springer 000410 petition to intervene. Information advanced grounds that have been previously rejected in 00/04-77 petition. Petition unlikely & unsupported by facts Certificate of Doc. encl. HCDARRY, J. H. Duke Power Co. HCDARRY, J. H. Debovisse & Liberman 00/04/09 App

0004170027 Ack receipt of NRC 000306 response to 000410 petition & ARLJ 000507 assurance & order Urges that request for 60-day extension be considered. Criticizes NRC bureaucratic attitude. DARTL, C. A. Affiliation Unknown 00/03/12 1p

0004190109 Affidavit in support of D Springer 000410 petition alleging that neither NRC or ARLJ has fully considered potential for once-through cooling & tower cooling Supporting documentation & Certificate of Doc. encl. BIRNBERG, C. J. Affiliation Unknown 00/03/21 15pp

0004220044 Forwarded Pages 4, 5 & 6 which were inadvertently omitted from Exhibit A of High Rock Lake Association 000501 affidavit. BIRNBERG, C. J. High Rock Lake Association 00/03/23 1p

0004230010 Order granting extension until 000512 for Commission to review ALAB-091. SHELLEY, J. Office of the Secretary of the Commission 00/05/29 1p

0004060572 Order advising parties to file exceptions to ARLJ 000322 partial initial decision: LEP-00-09, re alternative site issue: interveners' 000406 Certificate of Doc. encl. BIRNBERG, C. J. Atomic Safety and Licensing Appeal Panel 00/05/03 5pp

0004100442 Motion to reconsider ARLJ 000322 decision on re response record due to reasons stated in D Springer affidavit Certificate of Doc. encl. PEPFERKORN, H. P. Hearing Branch 3 00/04/04 App

0004110247 Response in opposition to D Springer 000410 affidavit re 000410 petition requesting 60-day extension to file documents Supporting allegations Address to BIRNBERG position Certificate of Doc. encl. HCDARRY, J. H. Duke Power Co. HCDARRY, J. H. Debovisse & Liberman 00/04/09 App

0004110041 Motion for extension until 000325 or after to file exceptions to ARLJ 000322 partial initial decision. Aswette resolution of petition to respond record based on D Springer affidavit may make appeal unnecessary W/Certificate of Doc. PEPFERKORN, H. P. Hearing Branch 3 00/04/11 App

0004100442 Order declaring ARLJ has jurisdiction to consider D Springer 000410 petition to intervene. Will not rule on merits until ARLJ decides jurisdiction questions NRC must respond to petition & 000410 affidavit regardless of outcome. BIRNBERG, C. J. Atomic Safety and Licensing Appeal Panel 00/04/17 4pp

0004240143 Response in opposition to interveners' 000411 motion for addl time to file exceptions to ARLJ 000322 partial initial decision re alternative site issue Motion is based on Springer affidavit which was opposed by utility W/Certificate of Doc. HCDARRY, J. H. Duke Power Co. HCDARRY, J. H. Debovisse & Liberman 00/04/10 App

0004230240 Response in opposition to interveners' 000411 motion for extension until 000325 to file exceptions to ARLJ 790202 partial initial decision on site alternatives Certificate of Doc. encl. DARTL, C. A. Hearing Branch 3 00/06/19 App

0004240415 Memorandum & order, ALAB-977, extending time to file exceptions to ARLJ 000322 partial initial decision: LEP-00-09, until ARLJ takes action re D Springer petition & interveners' 000406 motion & until ARLJ further order BIRNBERG, C. J. Atomic Safety and Licensing Appeal Panel 00/04/20 10pp

- 000425023 Response in opposition to intervenors' 000606 motion to reconsider or require record Applicant has already opposed
 O Springer, Debbie S. Affidavit in which intervenors' motion was based, as untimely & unsupported Certificate of Due and
 HCSAHH, J. H., PORTER, H. L. Date Power Co 00/04/23 App
- 000425044 Response in opposition to intervenors' 000606 motion to reconsider ARS 000602 partial initial decision re site alternatives Motion unlikely to be reconsideration does not meet Certificate of Due and
 SMTH, C. A. Hearing Branch 3 00/04/26 App
- D Advisory Committee on Reactor Safeguards reports & correspondence**
- 000425050 Forwards HR Pleasas 000504 1tr to JF Abshire re near-term CP Applications
 Y00009,000,3 J Licensing Branch 3 00/05/28 App
- 000425056 Discusses ACSS review of near-term CPs 0014 identified as policy issues interim position must be formulated to resolve issues
 BLDSST, H. E. ACSS - Advisory Committee on Reactor Safeguards 00/05/06 App
- G Inspection reports, IE Bulletins & correspondence**
- 000425060 Forwards IE Bulletin 00-11, "Masonry Wall Design - No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/08 App
- 000425066 Forwards IE Bulletin 00-10, "Decay Heat Removal Sys Operability - No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" and
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/09 App
- 000425068 Forwards response to IE Bulletin 00-03 re vacuum conditions resulting in damage to holdup tanks. Lists vacuum conditions in low pressure & holdup tanks by tank name, size, quantity, unit, design pressure & protective measures
 DALL, L. C. Date Power Co 00/06/09 App
- H Reportable occurrences, LRA's & related correspondence**
- 000425069 Final Part B report re mixed heat of steel applied by US Steel from which 4-inch elbows & 2-inch tees were wgt to
 O20496 requirement investigations conducted & closed at 46 stated facilities
 BEAR, L. Chevrolet Corp., Tube Turns Div 00/06/06 App
- DOCKET BTH-50-492 CHEROKEE NUCLEAR STATION, UNIT 2**
- A Application/construction stage documents & correspondence**
- 000425070 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0877 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
 EIDENMUT, D. G. Division of Licensing 00/06/20 App
- 000425076 Forwards reorganization chart for DPs of Nuclear Reactor Regulation Facility licensing matters will be handled by C. Ross Transition being made within of disruption to ongoing activities
 TEBERCO, H. L. Assistant Director for Licensing 00/06/12, App
- G Inspection reports, IE Bulletins & correspondence**
- 000425080 Forwards IE Bulletin 00-11, "Masonry Wall Design - No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/08 App
- 000425090 Ack receipt of IE Insp Repts 00-491/00-05, 00-492/00-05 & 00-493/00-05 No proprietary info
 DALL, L. C. Date Power Co 00/06/08 App
- 000425094 Forwards IE Insp Repts 00-491/00-05, 00-492/00-05 & 00-493/00-05 re violation of 000418-17 & notice of violation
 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/09 App
- 000425097 Notice of violation from Insp on 000418-17
 Region 2, Atlanta, Office of the Director 00/06/09 App
- 000425098 IE Insp Repts 00-491/00-05, 00-492/00-05 & 00-493/00-05 re monitoring of Unit 1 & auxiliary bldg not documented & performed as required
 CONDON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/06/09 App
- 000425099 Forwards IE Bulletin 00-10, "Decay Heat Removal Sys Operability - No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" and
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/09 App
- 000425099 Notice of violation from Insp on 000418-17
 Region 2, Atlanta, Office of the Director 00/06/09 App

DOCKETED ITEMS

0006000103 Forwarded RE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures." No written response required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 2pp

0006000009 Forwarded response to IE Bulletin 80-05 re vacuum conditions resulting in damage to hot-leg tanks. Lists vacuum conditions in test pressure & holding tanks by tank name, qty, quantity, unit, design pressure & protective measures.
DALL, C Duke Power Co 80/05/09 2pp

B Reportable occurrences, LERs & related correspondence

0006000004 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch plates & 2-inch tees were mfg to 200MW requirement. Investigation conducted & closed at 46 listed facilities.
SEAR, J.L. Shenkman Corp., Tube Turns Div 80/05/06 3pp

DOCKET 80W-50-493 CHEMURGE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

0006000010 Advices NRC & PWR applicants of NRC decision to notify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met.
EISENHUT, D.D. Division of Licensing 80/05/20 13pp

0006000006 Forwarded reorganization chart for Dir. of Nuclear Reactor Regulation Facility. Following matters will be handled by Regional Transmission Board made aware of situation to suggest activities.
EISENHUT, D.D. Assistant Director for Licensing 80/05/12 2pp

C Inspection reports, IE Bulletin & correspondence

0006000003 Forwarded IE Bulletin 80-11, "Heavy metal design." No action or written response required. IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" sent.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 2pp

0006000142 Airt receipt of IE Sup Repts 80-01/08-05, 80-02/80-05 & 80-03/80-05 No proprietary info.
DALL, C Duke Power Co 80/05/08 1p

--0006000104 Forwarded IE Sup Repts 80-01/08-05, 80-02/80-05 & 80-03/80-05 as 800415-17 & notice of violation.
HARRIS, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 2pp

--0006000147 Notice of violation from Insp on 800415-17
Region 2, Atlanta, Office of the Director 80/05/29 1p

--0006000136 IE Sup Repts 80-01/08-05, 80-02/80-05 & 80-03/80-05 on 800415-17 Noncompliance noted survey, loop closure date & equipment monitoring on Unit 1 & auxiliary bldg not documented & performed as required.
CARLSON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 800415-17 Region 2, Atlanta, Office of the Director 80/05/29 4pp

0006000289 Forwarded IE Bulletin 80-12, "Decay Heat Removal Box Operability." No written response required. IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" sent.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 2pp

0006000323 Forwarded IE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures." No written response required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 2pp

0006000288 Forwarded response to IE Bulletin 80-05 re vacuum conditions resulting in damage to hot-leg tanks. Lists vacuum conditions in test pressure & hot-leg tanks by tank name, qty, quantity, unit, design pressure & protective measures.
DALL, C Duke Power Co 80/05/09 2pp

B Reportable occurrences, LERs & related correspondence

0006000004 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch plates & 2-inch tees were mfg to 200MW requirement. Investigation conducted & closed at 46 listed facilities.
SEAR, J.L. Shenkman Corp., Tube Turns Div 80/05/06 3pp

DOCKET 80W-50-493 CHEMURGE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

0006000010 Advices NRC & PWR applicants of NRC decision to notify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met.
EISENHUT, D.D. Division of Licensing 80/05/20 13pp

DOCKET 80W-50-493 CHEMURGE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

0006000010 Advices NRC & PWR applicants of NRC decision to notify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met.
EISENHUT, D.D. Division of Licensing 80/05/20 13pp

DOCKET 80W-50-493 CHEMURGE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

0006000010 Advices NRC & PWR applicants of NRC decision to notify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met.
EISENHUT, D.D. Division of Licensing 80/05/20 13pp

0006000003 Advices that CAV 79-37 will be withheld from public distribution per 10CFR 290. Document is part of package sent by US to WHOED representing detailed technical aspect of test design.
SCHNEIDER, A. Operating Reactors Branch 2 80/05/20 2pp

0006000106 Notification of 800420 meeting w/utl in Bethesda, MD re soil/structure interaction study Meeting originally scheduled for 800426.
BELL, D. Licensing Branch 2 80/05/02 1p

0006000106 Notification of 800420 meeting w/utl in Bethesda, MD to discuss soil/structure interaction study.
BELL, D. Licensing Branch 2 80/05/02 3pp

F. Security, medical, emergency & fire protection plans

000130017 Forwarded clarification of NRC requirements for emergency response facilities defined in 70CFR 19.404 specific criteria for facilities under development.
EISENHUT, D.D. Division of Operating Reactors 80/05/25 41pp

0006000368 Response to NRC 790121 ltr re upgraded emergency plans Unit will defer substantial or upgraded plan until later date consistent w/approach licensing schedule & development of NRC guidance.
REQUIRE, W.F. Houston Lighting & Power Co 80/05/20 2pp

G. Adjudicatory correspondence

0006000070 Confirms & notifies parties of agreement for IE Repts 800415-21 deposition w/utl to AGS granting of action for discovery extension. Place will be determined at later time.
CARLSON, T.E. Baker & Botsky 80/05/28 3pp

0006000070 Confirms & notifies parties of L. Smith 800418 deposition deposition w/utl to AGS granting of action for discovery extension. Place will be determined at later time.
CARLSON, T.E. Baker & Botsky 80/05/28 3pp

0006000470 Motion to compel Citibank for Equitable Util to provide further answers to first set of interrogatories. Intervenor 800420 answers incomplete & sometimes irrelevant & corresponding Certificate of Due Diligence.
CARLSON, T.E. Baker & Botsky 80/05/28 11pp

DOCKETED ITEMS

241

0006200129 Act 04/05/06 telcon re agreement for P Buchner 000617 deposition in San Antonio, TX. Deposition will be taken on 04/05/06 at 10:00 AM in San Antonio, TX. 04/05/06 3pp

000610267 Confirmed final arrangements for P Buchner, L. Henslin & S. Bueger deposition P Buchner, S. Bueger depositions scheduled 000617 / 1B, respectively, in San Antonio, TX. S. Bueger deposition scheduled 000617 in San Antonio, TX. 04/05/06 3pp

000610085 Nubia's supportive evidence for 000627 request that NRC remove public hearing on 000620 show cause order re violations noted in NRC investigation (information) was able to be able to prevent evidence re violations noted in NRC investigation. Citizens Concerned About Nuclear Power, Inc. 04/05/06 13pp

0006200129 advises that NRC has received Houston Lighting & Power 000620 letter in response to IE 000620 letter in order to show cause notice of violation & notice of proposed imposition of civil penalties. 04/05/06 3pp

000610140 Discusses possible solutions to matter raised by P Buchner at 000627 meeting concerning application for CE. Requests that P Buchner submit list of specific documents for examination or duplication. 04/05/06 3pp

000610094 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utility request for hearing re IE 000620 order to show cause. Petitioners failed to establish right to hearing. Certificate of Dec. and CULP, H. H. 04/05/06 13pp

000610094 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utility request for hearing re IE 000620 order to show cause. Petitioners failed to establish right to hearing. Certificate of Dec. and CULP, H. H. 04/05/06 13pp

000610094 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utility request for hearing re IE 000620 order to show cause. Petitioners failed to establish right to hearing. Certificate of Dec. and CULP, H. H. 04/05/06 13pp

000610094 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utility request for hearing re IE 000620 order to show cause. Petitioners failed to establish right to hearing. Certificate of Dec. and CULP, H. H. 04/05/06 13pp

000610094 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utility request for hearing re IE 000620 order to show cause. Petitioners failed to establish right to hearing. Certificate of Dec. and CULP, H. H. 04/05/06 13pp

H General correspondence

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

N Utility Final Safety Analysis Report (FSAR) & amendments

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

H Antitrust correspondence

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

000610020H Deposed licensing of power plant informs NRC that legal action will be taken to prevent licensing. 04/05/06 13pp

DOCKETED ITEMS

HOOGMOED Discusses review of ROOSEY document re question of
disconnecting facilities in event of interconnection in
Interstate Commerce Commission should not agree prematurely to
license conditions re federal jurisdiction exemption
SP1886.L.O Spiegel & McDaniel 10/25/20 2pp

8006979484 Submits settlement negotiations status rephr per ASBL 800512
order TX LA & TX Power & Light Co resolved differences
in TX of intent Petition to Intervene still be amended to
reflect new position Certificate of Ovc and
BARNETTE, M H - 80075-F in Northeast City 80/04/09 Rep

0004200147 Negt on settlement negotiations status South TX Electric
Cooperative & Medina Electric Cooperative should be brought
to settlement process due to readiness to address concerns
re protection of certain interests (Certificate of Noj was)
JCHS D F. HUNTER, H Medina Electric Cooperative, Inc JCHS D F
McDonald, Will & Emery 05/05/09 ***

8006110346 Forwards settlement agreement, executed 800609
8006110347, J A Lammstein, Newman, Reiss, Axelrad & Tall 05/06/80
to

-000610282 Settlement agreement for all outstanding controversies re
 question whether Electric Reliability Council of TX should
 be interconnected w/Southwest Power Pool Certificate of Int
 and
 JORDAN, D B Houston Lighting & Power Co FARRINGTON, J B Dallas
 Power & Light Co MARQUARDT, W Texas Electric Service Co

000609090 Order advising that further settlement negotiations status
repts are to be filed by 000711, that another prehearing
conference be held on 000714 & that discovery question be
deferred until further developments Urges fair agreement
NHTSP/C J Atomic Safety and Licensing Appeal Panel 00/06/16
Dm.

M. Antitank Bearing Transcalt®

8006170743 Transcript of 200610 prehearing conference in Bethesda, MD
 Pg. 002-070 Hearing session
 * Atomic Safety and Licensing Board Panel 05/06/10 09pg

006420054 Proposed corrections to 000610 prehearing conference
transcript Certificate of Notari
COURT, R. B. - Justice, Court of Appeals, New York
000610

3. Inspection reports, IE Bulletin & correspondence

3064300000 Forwarded SE Circular 30-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required

9006108194 Forwards notice of violation from insp on 900081-21 SE insp
Nepis 88-498/80-03 & 80-497/80-05 will be issued in near
future

0006108800 Notice of violation from innp on 000001-01 Noncompliance failure to provide timely reply to item of noncompliance & failure to provide timely notification of cost deficiencies
* Region 4, Dallas, Office of the Director 00/04/04 Zpp

9304133061 Forwards IE Insp Repts SO-498/80-05 & SO-499/80-05 on
800301-01
BRIDGES, H.C. Region 4, Bellas, Reactor Construction & Engineer-
Support Branch SO/04/25 2pp

--BODS\20074 SE Insp Repts 50-499/50-55 & 50-499/50-55 as BOD301-33
Noncompliance noted failure to provide timely reply to item
of noncompliance & failure to provide timely notification of
coral deficiencies
CRENSHAW, W.A. , PHELPHIPS, H B Region 4, Dallas, Office of the
Director 50/04/24 Dss

IS06C0086 Dismisses special investigation of coast activities conducted 79B110-009287 Areas inspected include allegations of harassment, intimidation & lack of support of GC inspectors by SC mgt & assessment of QA/QC program.

WELLD,V Office of Inspection & Enforcement, Office of the Director, BSA/CDC, dx

004690228 Forwards IE Insp Rpts 80-498/80-07 & 80-499/80-07 as
800488-01 & notice of violation
SEISL&W C Region 4, Dallas, Reactor Construction & Engineer
Support Branch. 80/04/20 Zpp

* Region 4, Dallas, Office of the Director 06/04/24 10

DOCKETED ITEMS

243

- 000405023 IE Insp Repts 50-498-07 & 50-499-03 sent on 000405-10
Noncompliance noted failure to follow procedure for storage of seal
MUSCARE, W. S. Region 4, Dallas, Office of the Director 00/04/24 App
- 000405028 Forward IE Bulletin 00-12, "Deag Heat Removal Sys Operability" No written response required IE Info Notice 00-20, "Lock of Deag Heat Removal Capability at Servo-Reset Unit & While in Refueling Mode" encl
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 00/05/09 1p
- 0004050017 Act receipt of 000507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498-07-05 & 50-499-03-05
BETTEL, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/05/14 1p
- 0004050021 Responds to NRC 000404 ltr re violations noted in IE Insp Repts 50-498-05-05 & 50-499-03-05 Corrective actions applicable personnel have been reminded to provide timely replies & notification to NRC
TURNER, E. A. Houston Lighting & Power Co 00/05/07 App
- 0004050042 Forward IE Circular 00-12, "Valve-Graft-To-Activation May May Out of Place When Mounted Below Horizontal Axis" No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 00/05/14 1p
- 0004050018 Forward payment of civil penalties in amount of \$100,000 in response to NRC 000430 notice item of noncompliance are essentially substantiated Certificates of NoC encl
OPREA, S. M. Houston Lighting & Power Co 00/05/23 3pp
- 0004050023 Responds to 000430 show cause order Matters re Section 111 answered in reply to notice of violation NRC is committed to discuss more involved in program to make 00/02 Functions highly visible & independent Certificate of NoC encl
OPREA, S. M. Houston Lighting & Power Co 00/05/23 App
- 0004050072 Responds to NRC 000430 ltr re violations noted in IE Insp Repts 50-498-07-05 & 50-499-03-05 Corrective actions Brown & Root conducted not assessment of causes or perception of harassment Until increased involvement in 00/02 program
OPREA, S. M. Houston Lighting & Power Co 00/05/23 7pp
- 0004050048 Forward IE Circular 00-12, "Cold Strip Damage in Washhouse Fuel Assemblies" No written response required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 00/05/20 1p
- 0004050057 Responds to IE Bulletin 00-09, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holiday Tanks" The tanks will be augmented w/overcome relief valves prior to plant operation Sys summary table encl
TURNER, E. A. Houston Lighting & Power Co 00/05/02 App
- 0004050017 Summary of 000503 meeting w/uttl in Bethesda, MD re still responses to enforcement actions
MORRIS, H. B. Division of Reactor Construction Inspection 00/05/03 2pp
- 0004050043 Act receipt of 000503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498-07-05 & 50-499-03-05
BETTEL, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 00/05/07 1p
- 0004050044 Responds to NRC 000430 ltr re violations noted in IE Insp Repts 50-498-07-05 & 50-499-03-05 Corrective actions site mechanical OK instructed to perform surveillance of installed penetrations/closures on weekly basis
TURNER, E. A. Houston Lighting & Power Co 00/05/23 App
- 0 Reportable occurrences, LRSs & related correspondence
- 0004050071 Advise that potential deficiency re excessive hydrostatic pressure under extended cooling pond does not meet criteria of 10CFR180.4e
TURNER, E. A. Houston Lighting & Power Co 00/04/25 App
- 0004050048 Notifies NRC that 000411 final Part 21 report re unscheduled motor operator for turbine driven auxiliary feedwater pump was also intended to satisfy 10CFR20.33(c) reporting requirements
TURNER, E. A. Houston Lighting & Power Co 00/05/07 App
- 0004100014 Forward Final deficiency report re safety injection sys containment emergency stop piping design
TURNER, E. A. Houston Lighting & Power Co 00/05/20 3pp
- 0004100022 Final deficiency report re safety injection sys containment emergency stop piping design During routine review discovered unit between pump liner & process pipe insufficient Design corrected & procedures revised.
Houston Lighting & Power Co 00/05/20 3pp
- 0004100037 Interim deficiency report re nonconforming backfill wall areas around Unit 2 2nd floor Backfilling into structural backfill showed Unit 2 area in conformance Four areas within Unit 2 found potentially below NRC criteria During diagram work
TURNER, E. A. Houston Lighting & Power Co 00/05/20 2pp
- 0004100042 Second interim deficiency report re essential cooling water sys birth used radiograph rejectable indications Deficiency will be addressed in this response to show source under heat
Houston Lighting & Power Co 00/05/13 App
- 0004100043 Interim deficiency report re seismic qualification of essential cooling water intake structures pending frame & diesel generator fuel oil storage tank Preliminary findings show designs sufficiently conservative Made not expected
OPREA, S. M. Houston Lighting & Power Co 00/05/26 2pp
- V. Operator Examinations
- 0004100095 Notification of 000717 meeting w/uttl in Bethesda, MD to discuss current requirements for operator qualification & licensing
BELL, D. E. Licensing Branch 2 00/05/02 1p
- 0004100099 Notification of 000429 meeting w/uttl in Bethesda, MD to discuss current requirements for operator qualification & licensing
BELL, D. E. Licensing Branch 2 00/05/02 3pp
- DOCKET 00N-50-499 SOUTH TEXAS PROTECT, UNIT 2
A Application/construction stage documents & correspondence
- 0004200110 Advise NRC & NRC applicants of NRC decision to modify implementation plan presented in Section 4 of 000600-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
ETIMMUT, D. G. Division of Licensing 00/05/02 10pp
- 0004200259 Advise that CMV 79-37 will be withheld from public disclosure per 10CFR2.790 Document is part of package sent by uttl on 7/11/02 representing detailed technical audit of fuel design
EICHMEIER, A. Operating Reactors Branch 2 00/05/22, 3pp
- 0004201258 Notification of 000718 meeting w/uttl in Bethesda, MD re self-inspection interaction study Meeting originally scheduled for 00/04/20
BELL, D. E. Licensing Branch 2 00/05/02 1p
- 0004201608 Notification of 000426 meeting w/uttl in Bethesda, MD to discuss self-inspection interaction study
BELL, D. E. Licensing Branch 2 00/05/02 2pp
- F. Reactivity, medical, emergency & fire protection plans
- 0004203021 Forward clarification of NRC requirements for Emergency response facilities defined in 700913 ltr Adcl specific guidance for facilities under development
EISENHUT, S. G. Division of Operating Reactors 00/04/25 41pp
- 0004203368 Responds to NRC 7/11/02 ltr re updated emergency plans Utll will defer submit of updated plan until later date consistent w/project licensing schedule & development of NRC guidance
HOSBIE, W. F. Houston Lighting & Power Co 00/05/20 2pp
- 0 Adjustability correspondence
- 0004203070 Confirm & notify of agreement for DE Design 000419-21 deposit, early to Adcl granting of motion for discovery Enforcement Plan will be determined at later date
GILKIN, F. E. Baker & Bots 00/04/28 1p

DOCKETED ITEMS

506a22027a Confirms & notifies parties of L. Simlin 500618 Deposition
Hearings/Judging necessitated by involvement in other hearing
Suggests 500617 Re: Southern deposition Related
correspondence
COMM-F R Baker & Bette 09/03/05 3pm

14. Antiterrorism responsibilities

0000100243 Discovery sept for Mar 1980 No discovery requests initiated
on received Certificate of Reg Change of Address notice
encl
00001011 Southwest Texas Electric Cooperative 00/04/10 See

0006200129 Ack 000806- telcom re agreement for F Southern 000417
deposition in San Antonio. TE Birtin deposition will be taken
on 000418 & Swartz on 000419-21
CCMAIL P E Sawyer & Wells BD/CO/CO Sjs

0006060400 Corrects misstatement of fact in Public Utility Board of City of Brownsville, TX Mar-Apr 1990 discovery report. Failure to participate in J. Dreggones deposition was due to external independent decision not to attend. Certificate of Evt encl.

0006100047 Confirms final arrangements for P Buchorn-L. Binkes &
D Bumpus departures P Buchorn & L Binkes departures
scheduled 000617 & 18 respectively in New Antonio, TX &
D Bumpus departure scheduled 000619 in Bay City, TX

000220056 Helian for BO0509 prehearing conference to apprise AWLB of
status of settlement discussions Proposed order &
Certificate of Conc. and
CYNARD, L. D. ; MARMONTE, F. ; WALLACE, R. L. Justice Dept # BO/05/03
300

EO36170505 Submits supportive evidence for 000327 request that NRC convene public hearing on EO4430 show cause order re violations noted in NRC investigation interviews should be able to present evidence re violations Han and BWR334-L. Citizens Concerned About Nuclear Power, Inc. B11K16.

MS00102292 Discovery rept for April 1980 No discovery requests received
on Initiated Certificate of Rev encl
MS00-J C San Antonio, TX MS00-J C Matthews, Nowlin, MacFarlane
& Bennett R005/00 4pp

0006000109 Advises that NBC has received Houston Lighting & Power
0006000200 ltr in response to LE 000530 ltr re order to show
0006000300 cause, notice of violations & notice of proposed imposition
0006000400 of civil penalties
0006000500 HJR/HSD: H J Hearing Branch 1 00/05/00 1p

EO0600026 Advises that Public Utility Board of City of Brownsville, TX does not agree w/DM3141 version of facts re Druggan's deposition labeling matter as misunderstanding considered as polite misstatement
FOI#ER.M R. Murgal & McDaniel 02/05/07 1p

000610040 Discusses possible solutions to matter raised by P Buch at 0005029 meeting concerning application for GL. Suggests that P Buchman submit list of specific documents for examination or duplication.

8006660000 Forward status reft Delivery arrangements made for 800512
800776 J S Debevoise & Liberman 80/02/09 1p

000480000. Response in opposition to Citizens Concerned About Nuclear Power & Citizens For Equitable Utility request for hearing re IE 0004300 order to show cause. Petitioners failed to establish right to hearing. Certificate of Decision CULP-R 18, CDM&P Western Lighting & Power Co. CULP-R 18

```
--B006050358 Status re settlement negotiations' progress
Discussions are continuing Urges AMLC to hold prehearing
conference by B00314 & requests deferral of ruling on
extension Certificate of Doc & supporting documents encl
BAPOLC.M.D Texas Utilities Co B0705709 D000
```

0004260194 Motion to deny Citizens Concerned About Nuclear Power & Citizens for Equitable Utility 000327 request for hearing re RE 000430 order to show cause why safety-related civil activities should not be stopped Certificate of Dnc and LIEBERMAN, J. BURKH & Releasing & Enforcement Division

0006660003 Forwards Houston Lighting & Power status of settlement reph-
per AGLA 80010 order Affidavit not appropriate
GREEN S 2 Lowenstein-Neuman, Roca, Arnold & Toll 00/00/00 2pp

--9004260498 Requests bearing on behalf of Matagorda County, TX citizens NRC 8004260498 report sent to Houston Lighting & Power H
Growth 8004260498 article in Houston Post & Citizens of
Matagorda County petition and
NRCN: Affiliation: Unknown 80/05/18 See

--HODAGOSCU Status of settlement rpt per ALE HODAGD order deferring
trial briefs, final prehearing conference & evidentiary
hearing Urges addl 30-day extension for continuance of
negotiations due to complexity Certificate of Wx and
SAPHEIT, E.M. Mountain, Lighthouse & Power Co. 8/20/05/05. The

---0002628200 Submits Dezer County,TX,21st Senatorial district cover
788414100 requesting hearing to provide public w/4021 info
re order to show cause based on util violations

NO66040492 Status rept re settlement discussions' progress Ungea ABL
to convene trial conference to accommodate outstanding
discovery, final trial preparation & resolution of remaining
procedural matters Certificate of
Dvc sec1
CYNHRT, R. R. LUGM, N. MALLACE, R Justice, Sent at 06/05/09 06

--800A060206 Requests hearing on behalf of Houshon Gulf Coast Bldg
Council in Hattager County, TX
VAN BCM, D Affiliation Unknown 00/00/00 by

0004110233 Forwards rpt on status of settlement
098324.3-0 Lowenstein, Neuman, Rels. Anshel & Tejl 80/05/09 3pg

H General correspondence

MOA190129 Rept on settlement negotiations suggests that conference be held to determine add'l time needed by applicant. Trial should be preceded by pretrial conference to accommodate discovery & other matters. W/Certificate of Soc CYNBER, B B, LUCHE, K, MALLACE, R Justice, Dept of MO/OS/54 YW

K. Utility Final Safety Analysis Report (FSAR) & amendments

DOUGLAS B037D Forward Amend II re FBAR, consisting primarily of response
to RAO DOG318 request for add'l GA info.
COSTA-O M. Morrison Lighting & Sound Co. #0001196 Doc

0004230157 Settlement status rept by Public Utility Board of Brownsville
TX Proposed early trial schedule & 30-day extension to
explore possibility of settlement Certificate of Gov encl.
BPIEGL-0 Brownsville, TX 06/05/99 gsp

---8004100370 Amend II to FOIA, consisting primarily of responses to
800310 request for addl OA info.

0000240285 Status re:pt on settlement negotiations per ABL 606410
order Requests 30-day extension in procedural dates to allow
continuation of discussions Certificate of Use etc)
ETAM...D H Central & South West Services, Inc 00/05/09 12pm

EC04250193 Submitte status report on settlement negotiations per ARLB
EC0410 order Joint ownership agreement will be completed by
BO1101. Supporting documentation & Certificate of Gov. enrl.
BURNETTE, H H Texas-Louisiana Electric Cooperative, Inc RITTS, F H

000604054: Discovery rpt for Apr 1980 Util counsel participated in depositions of NC Lander & G Taylor, expert economic witnesses for HNS & DGT, respectively

DOCKETED ITEMS

SE06090225 Forwards IE Insp Repts SO-470/00-07 & SO-479/00-07 on
800408-jt & notice of violation
SEATTLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 00/04/00 Doe

--8006090029 Notice of violation from insp on 800408-11
* Region 4, Dallas, Office of the Director 80/04/24 1p

--0000000234 IE Insp Repts 50-498/89-07 & 50-499/89-07 re EDOA08-11
Noncompliance with failure to follow procedure for storage
of mail
HARRACH, W O. CROSBY, W A Region 4, Dallas, Office of the
Director 80/04/28 4pp

800464650W Forwarded RE Bulletin 05-12, "Barely Heat Removal Sys
Operability." No written response required RE Info Notice
05-20, "Loss of Barely Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" and
SNFPRIT.M W Region 4, Dallas. Office of the Director 05/05/09
la.

8004560017 Ack receipt of 800507 ltr informing SAC of steps taken to correct violations noted in IE Insp Repts 50-492/88-05 & 50-499/88-05
DEBUE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 88/05/14 ip

--006699021 Responds to NRC 600404 1hr re violations noted in IE Insp
Rpts 50-450/80-05 & 50-499/80-05 Corrective actions
applicable personnel have been reminded to provide timely
replies & notification to NRC
TURNER, E A Houston Lighting & Power Co 80/08/87 Jpp

800438882 Forwards IE Circular 80-12: "Valve-Shaft-to-Airlock Key May Fall Out of Place When Mounted Below Horizontal Axis." No written response required
 BYRON, K V Region 4: Dallas, Office of the Director 80/05/14
 1p.

82060388@ Forwards payment of civil penalties in amount of \$800,000 in response to RRC 800430 notice items of noncompliance are essentially unsubstantiated. Certificate of Due and

8306030022: Response to 800430 show cease order Nations re Section 111
 answered in reply re notice of violation Sgt is committed
 to become more involved in program & make DA/OC functions
 highly visible & independent Certificate of Wcc sent
 DPMSEA G M Houston Lighting & Power Co 88/03/22 App

8034500172 Response to NRC 805430 ltr re violations noted in IE Insp
Repts 80-498/77-14 & 80-495/77-19 Corrective actions Brown &
Root conducted w/pt assessment of causes of perception of
harassment Util increased involvement in QA/QC program
OPR&A, p. 2 Houston Lighting & Power Co 80/03/23. 75pp

0006200046 Forwarded DE Circular 90-13, "Grid Strap Damage in Westinghouse Fuel Assemblies." No written response required
ECWPR:W.V. Region 4, Dallas, Office of the Director, 80/03/28
lc

8006300878 Response to IE Bulletin 80-03: "Vacuum Condition Resulting
in Damage to Chemical Vol Control Sys (ICVCI) Holdup Tanks"
Two tanks will be augmented w/vacuum relief valves prior to
plant operation. Sys summary table encl.
TURNER, E A Heston Lighting & Power Co 80/06/02 Zep

8006160175 Summary of 800950 meeting w/utill in Bethesda, MD re utill
response to enforcement actions
THORNBURG, H S Division of Reactor Construction Inspection
03/14/80 JWS

8006288626 Ack receipt of 800523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/80-07 & 50-499/80-07
RNDRL:W C Region 4, Dallas, Reactor Construction & Engineering
70/06/09 1a

0004050439 Notifies NRC that 000401 Final Part 25 req'd re unqualified
motor operator for turbine driven auxiliary feedwater pump
was also intended to satisfy 10CFR50.53(c) reporting
requirements
TURNER, E. A. Houston Lighting & Power Co 00/05/07 3pp

806410014 Forward Fusel deficiency rept re safety injection system containment emergency dump piping design
TURNER, R. A. Houston: Lightning & Brown Co. 80/038/30. See

---0000000000 Final deficiency report re safety injection sys containment emergency pump piping design. During routine review, discovered weld between pump liner & process pipe insufficient. Design corrected & procedures revised. W. Houston Liskings & Power Co. 00/00/00 Spc

0006110337 Interion deficiency report was nonconforming backfill with areas around Unit 2 power block bearings into structural backfill showed Unit 1 area in reinforced four areas within Unit 2. Found potentially below GC criteria. Bearing diagram and TURNER, C.A. Heston Lighting & Power Co. 80/05/20 See

000A240292 Second interim deficiency report re essential cooling water
age girth weld radiograph rejectable indications. Deficiency
will be addressed in utility response to show cause order. Next
report will be submitted 000P12
DPREA-G W Houston Lighting & Power Co 00/06/12 Gop

000600438 Insulin deficiency kept re seismic qualification of
essential cooling water intake structure gantry crane &
diesel generator fuel oil storage tank Preliminary findings
show design sufficiently conservative kept not expected
OFFER.G W Huxley Lighting & Power Co 02/06/25 Bop

V Operator Examinations

806480095 Notification of 008717 meeting w/utill in Bethesda, MD to discuss current requirements for operator qualification & licensing Meeting originally scheduled for 008628
RELEAS E Lorraine Branch 2 0086402 in

800480009 Notification of 800480 meeting w/Phil in Bethesda, MD to discuss current requirements for operator qualification & licensing
 800480010 Licensing Branch 2 800480009 Sup.

SOCKET 50-000 DAVIS-BENNE NUCLEAR POWER STATION, UNIT 2

A Application/reconstruction of documents & correspondence

800A230110 Advises BAE & MWR applicants of NYC decision to modify implementation plan presented in Section 4 of MUREP-0577 re adequacy of applicable support structures General operating master review procedure & acceptance criteria email
R10044/J.D.D. Division of Licensing 00/08/20 13pp

© Adjudicators correspondence

0000200071 Pages 4-5 b 6 For Exhibit A of High Back Lake A
000021 aff'davis
RPM0020.D. High Back Lake Association. 2011/11/16. 40

DOCKET NO-804 DAVID-BESSE NUCLEAR POWER STATION, UNIT 2

A. Application/contract/offer stage documents & correspondence

0006200000 Advises DNR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EIS/DSEIS/D.O. Division of Licensing R0003/20 1700.

DOCKET STM-50-502 HAVEN NUCLEAR PLANT, UNIT 1

A Application/Construction stage documents & correspondence

W004230100 Advises DMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
K19804U.2 2 Division of Licensing 05/05/90 13pp

DOCKETED ITEMS

2

DOCKET SW-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

0004025010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of WASH-80-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART, G Division of Licensing 00/05/80 13pp

0004100270 Notifies that job will be conducting add moisture testing on low hydrogen electrodes using technique required in AWS AB 5 Section 23 Electrode coating moisture testing results will be applied only to Units 1 & 4
RENEBERGER, D L Washington Public Power Supply System 00/04/80 1p

0004025040 Discusses reorganization of Of of Nuclear Reactor Regulation & advises that reg responsibilities re Facility have been assigned to a Bureau Reorganization chart and
TERRECO, R L Assistant Director for Licensing 00/06/82 1pp

F Security, medical, emergency & fire protection plans

0004035045 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
TERRECO, R L Assistant Director for Licensing 00/04/80 2pp

G Reportable occurrences, LERs & related correspondence

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

DOCKET SW-50-509 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

0004025010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of WASH-80-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART, G Division of Licensing 00/05/80 13pp

0004100270 Notifies that job will be conducting add moisture testing on low hydrogen electrodes using technique required in AWS AB 5 Section 23 Electrode coating moisture testing results will be applied only to Units 1 & 4
RENEBERGER, D L Washington Public Power Supply System 00/04/80 1p

0004025040 Discusses reorganization of Of of Nuclear Reactor Regulation & advises that reg responsibilities re Facility have been assigned to a Bureau Reorganization chart and
TERRECO, R L Assistant Director for Licensing 00/06/82 1pp

F Security, medical, emergency & fire protection plans

0004035045 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
TERRECO, R L Assistant Director for Licensing 00/04/80 2pp

G Reportable occurrences, LERs & related correspondence

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

DOCKET SW-510 WPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

0004025010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of WASH-80-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART, G Division of Licensing 00/05/80 13pp

0004035045 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
TERRECO, R L Assistant Director for Licensing 00/04/80 2pp

0004100270 Notifies that job will be conducting add moisture testing on low hydrogen electrodes using technique required in AWS AB 5 Section 23 Electrode coating moisture testing results will be applied only to Units 1 & 4
RENEBERGER, D L Washington Public Power Supply System 00/04/80 1p

0004025040 Discusses reorganization of Of of Nuclear Reactor Regulation & advises that reg responsibilities re Facility have been assigned to a Bureau Reorganization chart and
TERRECO, R L Assistant Director for Licensing 00/06/82 1pp

F Security, medical, emergency & fire protection plans

0004035045 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
TERRECO, R L Assistant Director for Licensing 00/04/80 2pp

0004035045 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
TERRECO, R L Assistant Director for Licensing 00/04/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

0004050230 PW-4-W-00-037 on 000516, Mount St Helens erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive ash in sys components underway
DIRRIP, F W Region 5, San Francisco, Office of the Director 00/03/80 2pp

DOCKETED ITEMS

060906 Ais receipt of 060907 re informing NRC of steps taken to track violations noted in IE Insp Repts 90-446/80-31 & 90-513/80-01
 060906 G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 06/05/90 1p

060909416 Response to NRC 800549 1tr re violations noted in IE Insp Repts 90-446/80-01 & 90-513/80-01 corrective actions
 060909416 G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 06/05/90 1p

060909416 G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 06/05/90 1p

060909416 Forward IE Insp Repts 90-446/80-01 & 90-513/80-01 on 060909416 G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 06/04/90 2pp

060909444 Notice of violation from Insp on 060909416 G S Region 5, San Francisco, Office of the Director 06/04/90 2pp

060909447 IE Insp Repts 90-446/80-01 & 90-513/80-01 on 060909416 Monitoring noted failure to control temporary attachments to structural steel & violations noted in other reports
 060909447 G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 06/04/90 2pp

LET 90-004 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

Application/construction stage documents & correspondence

060910010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURE-0577 re sequence of applicable support structures General operating reactor review procedure & acceptance criteria and
 060910010 G S Division of Licensing 06/05/90 13pp

Administrative correspondence

060910010 Response to ARLS 800507 & 0403 orders & to PWR Suppl 1 Urges re response to alternative analysis prior to further hearings Recommends that Subpart II of EPA be treated as objection in proceeding
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Request for deferred until 060910 to respond to interveners review on Board 800507 contributions Proposed contributions on NRC alternative site reanalysis need to be discussed
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Order for 060923 prehearing conference to consider appropriate issues for entry into vulnerability hearing Board submission until 060910 for NRC to respond to Foreman as noted & LE Harbor 060907 filing
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

Advisory Committee on Reactor Safeguards reports & correspondence

060910010 Forward ACRS 800506 1tr to JF Ahearn re near-term CP applications need for info
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Discusses ACRS 800506 1tr to JF Ahearn re near-term CP applications need for info
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

LET 90-004 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

Application/construction stage documents & correspondence

060910010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURE-0577 re sequence of applicable support structures General operating reactor review procedure & acceptance criteria and
 060910010 G S Division of Licensing 06/05/90 13pp

Administrative correspondence

060910010 Response to ARLS 800507 & 0403 orders & to PWR Suppl 1 Urges re response to alternative analysis prior to further hearings Recommends that Subpart II of EPA be treated as objection in proceeding
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Request for deferred until 060910 to respond to interveners review on Board 800507 contributions Proposed contributions on NRC alternative site reanalysis need to be discussed
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Order for 060923 prehearing conference to consider appropriate issues for entry into vulnerability hearing Board submission until 060910 for NRC to respond to Foreman as noted & LE Harbor 060907 filing
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

Advisory Committee on Reactor Safeguards reports & correspondence

060910010 Forward ACRS 800506 1tr to JF Ahearn re near-term CP applications need for info
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

060910010 Discusses ACRS 800506 1tr to JF Ahearn re near-term CP applications need for info
 060910010 G S Region 5, San Francisco, Office of the Director 06/05/90 2pp

DOCKET 90-010 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

Application/construction stage documents & correspondence

060910010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURE-0577 re sequence of applicable support structures General operating reactor review procedure & acceptance criteria and
 060910010 G S Division of Licensing 06/05/90 13pp

060910010 Advises that NRC overcharged until for review & processing
 060910010 G S Division of Licensing 06/05/90 2pp

H General correspondence

060910010 Requests verification of address Related correspondence
 060910010 G S Division of Licensing 06/05/90 2pp

0 Inspection reports, IE Bulletins & correspondence

060910010 Forward IE Circular 80-13, "Grid Strip Damage in Westinghouse Fuel Assemblies" to Utilities Response required
 060910010 G S Region 1, Philadelphia, Office of the Director 06/05/90 2pp

060910010 Response to IE Bulletin 79-02A, "Longitudinal Weld Defects in ACRS 304 Type 304 Stainless Steel" All Westinghouse supplied pipe for use on NRC in either of forged stainless or centrifugal cast duct
 060910010 G S Region 1, Philadelphia, Office of the Director 06/05/90 2pp

DOCKET 90-010 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

Application/construction stage documents & correspondence

060910010 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURE-0577 re sequence of applicable support structures General operating reactor review procedure & acceptance criteria and
 060910010 G S Division of Licensing 06/05/90 13pp

060910010 Advises that NRC overcharged until for review & processing
 060910010 G S Division of Licensing 06/05/90 2pp

H General correspondence

060910010 Requests verification of address Related correspondence
 060910010 G S Division of Licensing 06/05/90 2pp

0 Inspection reports, IE Bulletins & correspondence

060910010 Forward IE Circular 80-13, "Grid Strip Damage in Westinghouse Fuel Assemblies" to Utilities Response required
 060910010 G S Region 1, Philadelphia, Office of the Director 06/05/90 2pp

DOCKETED ITEMS

249

0004240603 Response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME Sec-III Type 304 Stainless Steel." All Westinghouse-supplied type 304 SS WBSB is either of forged seamless or centrifugal cast content.
PLANS&ENR E Long Island Lighting Co 00/03/29 1p

DOCKET RTV-50-508 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

0004230113 Advises BME & PNE applicants of NRC decision to modify implementation plan presented in Section 4 of M0400-08/7 re adequacy of applicable support structures General operating reactor service procedure 5 completed 07/05/01
CIBEMMT, R D Division of Licensing 00/03/20 13p

Q Adjudicatory correspondence

0004040050 Advises that Mr. Guttenham will no longer appear in proceedings on behalf of unit.
GAW28, H B Tennessee Valley Authority 00/03/19 3pp

Q Inspection reports, IE Bulletin & correspondence

0004230400 Forwarded IE Insp Repts 50-510/00-05, 50-519/00-05, 50-520/00-05 & 50-521/00-05 on 000308-0029 Re welds/insulation noted.
M0400, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/02 2pp

0004020011 IE Insp Repts 50-510/00-05, 50-519/00-05, 50-520/00-05 & 50-521/00-05 on 000308-0029 Re noted thermal stress inspected structural concrete, steel structures & reactor vessel installation.
G000000, J D Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/02 2pp

0004040109 Forwarded IE Bulletin 80-11, "Harding Wall Design." No action or written response required IE Info Notice 79-00.
"Overloading of Structural Elements Due to Pipe Support Loads" only.
O'DELL, V J Region 2, Atlanta, Office of the Director 00/05/08 1p

0004040267 Forwarded IE Bulletin 80-13, "Dorag Heat Removal Sys Operability." No written response required IE Info Notice 80-02.
"Loss of Dorag Heat Removal Capacity at Davis-Besse Unit 1 While in Hardening Mode" only.
O'DELL, V J Region 2, Atlanta, Office of the Director 00/05/09 3pp

0004120038 Forwarded IE Circular 80-11, "Emergency Diesel Generator Load Oil Cooler Failures." No written response required.
O'DELL, V J Region 2, Atlanta, Office of the Director 00/05/12 3pp

0004090406 Response to 000201 IE unit transmitted IE Bulletin 80-02.
Investigations revealed that feedwater spargers on thermal elements mfg. by Nucor Fabricated by Nucor Engineering Co have not been purchased from have not been installed in plants.
HILL, L M Tennessee Valley Authority 00/03/25 1p

0004100043 Ark Receipt of 000507 IE info/insp NRC # of steps taken to correct violations noted in IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04.
M0400, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/03/31 2pp

0004180004 Forwarded supplemental response to IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04 Supplemental report re by 000509.
HILL, L M Tennessee Valley Authority 00/05/07 3pp

0004180005 Ark Receipt of 000409 IE info/insp NRC # of steps taken to correct violations noted in IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04 Supplemental report re by 000509.
M0400, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/30 2pp

0004180006 Response to NRC 000507 IE re violations noted in IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04.
Corrective actions called stamped under stress stamps in piping walls adjacent to welds.
HILL, L M Tennessee Valley Authority 00/04/09 2pp

0004180007 Forwarded IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04 re 000201-02 & notice of violation.
BRUNW, J F Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/07/17 3pp

0004180008 Notice of violation from Insp on 000201-02.
Region 2, Atlanta, Office of the Director 00/05/11 3p

0004180009 IE Insp Repts 50-510/00-04, 50-519/00-04, 50-520/00-04 & 50-521/00-04 on 000201-02 Noncompliance noted failures to follow procedures in weld joint identification.
M0400, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/11 7pp

Q Reportable occurrences, LERs & related correspondence

0004060030 Forwarded CTF-Nuclear 000503 Part 21 re potential failure on Hudson Reagen device used in CTF-Nuclear electrical control circuit for detecting high temps in airstream in various air filtration sys.
K0000, H Tennessee Valley Authority 00/05/08 4pp

0004060110 Pwd-11-00-09S on 000505 while in process of pouring Steel A-1 vent well/covers. Small failure & dropped steel slab with concrete lumps. Three employees were severely injured.
Licenses plans to issue press release.
W0000, J M, C000000, H Region 2, Atlanta, Office of the Director 00/05/02 1p

0004060230 Forwarded second interim deficiency report re weld deficiencies on nuclear pressure vessel shell. Unit Final report should be submitted by 000705.
HILL, L M Tennessee Valley Authority 00/05/29 1p

0004060301 Second interim deficiency report re weld deficiencies on nuclear pressure vessel shell. Unit Final report should be submitted by 000705.
HILL, L M Tennessee Valley Authority 00/05/29 1p

0004060401 Forwarded final deficiency report re unacceptable handling of welded stud anchors on embedded plates.
HILL, L M Tennessee Valley Authority 00/06/02 1p

0004060403 Final deficiency report re unacceptable handling of welded stud anchors on embedded plates. Testing program was initiated.
Handling of studs has no significant effect on stud capacity.
Data guidelines for max handling of stud anchors.
Tennessee Valley Authority 00/06/02 2pp

0004100048 Forwarded final interim deficiency report re standing gas treatment sys charcoal adsorber.
HILL, L M Tennessee Valley Authority 00/06/04 1p

0004100058 First interim deficiency report re standing gas treatment sys charcoal adsorber. Chemical retention screws separating from frames due to improper or broken split wedge.
CTF-Nuclear, investigating problem. Final report by 000503.
Tennessee Valley Authority 00/06/04 1p

0004100059 Forwarded interim deficiency report re steam tunnel embedded stiffener plate weld.
HILL, L M Tennessee Valley Authority 00/06/04 1p

0004120012 Interim deficiency report re failure by Atlas dachino & Iron Works to implement AS procedure for final removal of welds.
Superior plate used. Stiffener plate M04-10 welded per AS requirements & aid for Atlas AS program contract.
Tennessee Valley Authority 00/06/04 1p

0004120018 Final Part 21 report re mixed bed of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AS2049S requirement. Investigation conducted & closed at AS listed facilities.
SEAY, J L, Chemron Corp., Tube Furnace Div 00/06/04 3pp

0004120042 Forwarded final deficiency report re defective McGraw-Hill steam detection controllers in standing gas treatment sys.
HILL, L M Tennessee Valley Authority 00/06/13 1p

0004120045 Final deficiency report re defective temp detection controller in standing gas treatment sys. Electronic temp detection controller failed in wet. Cause of acid flux under sealing remains. Controllers to be replaced w/scrapped controllers.
Tennessee Valley Authority 00/06/13 2pp

0004090205 Forwards final deficiency report re incorrect root face on shroud catalyst sleeves
HILLIS, L. M. Tennessee Valley Authority 00/06/19 1p

--0004090206 Final deficiency report re incorrect root face on shroud catalyst sleeves Atlas Machine & Iron Works fabricated some representative structures using same welding process as shroud structures and tests performed satisfactorily
Tennessee Valley Authority 00/05/19 2pp

0004090206 Second interim deficiency report re defects in Rosemount trip/callout unit & GE investigations re quality of Rosemount 1155 pressure transmitters shipped containing final report will be submitted by 000517
HILLIS, L. M. Tennessee Valley Authority 00/06/20 1p

DOCKET 000-51V HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

0004090206 Advise SWR & PWR applicants of NRC decision to modify implementation plan presented in Section 6 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met
NRC/DOE, D. O. Division of Licensing 00/05/20 12pp

D Addendum correspondence

0004090206 Advise that AN Cushman will be longer appear in proceedings on behalf of CVI
NRC/DOE, D. O. Tennessee Valley Authority 00/05/19 2pp

I Inspection reports, IE Bulletins & correspondence

0004090206 Forwards IE Insp Report 00-518/00-05, 00-519/00-05, 00-520/00-05 & 00-521/00-05 re noncompliance noted
HARTV, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/22 2pp

--0004090206 IE Insp Report 00-518/00-05, 00-519/00-05, 00-520/00-05 & 00-521/00-05 re noncompliance noted Major areas inspected structural concrete/steel structures & reactor vessel installation
CARROLL, J. F. Region 2, Atlanta, Reactor Construction & Engineering Support Branch SHAW, H. D. Region 2, Atlanta, Office of the Director 00/04/22 2pp

0004090206 Forwards IE Bulletin 00-1, "Heavy Wall Design" No action or written response required IE Info Notice 79-20, "Overloading of Structural Elements Due to Pipe Support Loads" and
O'REILLY, J. F. Region 2, Atlanta, Office of the Director 00/05/09 2pp

0004090206 Forwards IE Bulletin 00-10, "Bray Heat Removal Sys Operability" No written response required IE Info Notice 79-20, "Loss of Bray Heat Removal Capability at Davis-Besse Unit 1 (Unit in Refueling Mode)" and
O'REILLY, J. F. Region 2, Atlanta, Office of the Director, 00/05/09 2pp

0004090206 Forwards IE Circular 00-1, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required
O'REILLY, J. F. Region 2, Atlanta, Office of the Director 00/05/13 2pp

0004090206 Responds to 000321 1st which transmitted IE Bulletin 00-02 Investigations revealed that feedwater spargers or shroud sleeves may have fabricated by Marvin Engineering Co. have not been purchased &/or have not been installed in plants
HILLIS, L. M. Tennessee Valley Authority 00/05/21 1p

0004090206 Ack receipt of 000507 1st Informing NRC of steps taken to correct violations noted in IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04
HARTV, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/21 2pp

--0004090206 Forwards Supplemental response to IE Insp Report 00-518/00-04 Investigating all applicable welds 00-17 & 00-34 being revised Clarification of requirements will prevent noncompliance through misinterpretation
HILLIS, L. M. Tennessee Valley Authority 00/05/07 2pp

--0004090206 Ack receipt of 000409 1st Informing NRC of steps taken to correct violations noted in IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04 Supplemental report due by 000509
HARTV, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/08 2pp

--0004090206 Responds to NRC 000217 1st re violations noted in IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04 Corrective actions taken to correct shroud stress changes in piping metal adjacent to welds
HILLIS, L. M. Tennessee Valley Authority 00/04/09 2pp

--0004090207 Forwards IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04 on 000219-22 & notice of violation
HARTV, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/17 2pp

--0004090208 Notice of violation from insp on 000219-22
Region 2, Atlanta, Office of the Director 00/05/11 1p

--0004090208 IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04 re 000219-22 Noncompliance noted failed failure procedure in weld joint identification
HARTV, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch SHAW, H. D. Region 2, Atlanta, Office of the Director 00/05/11 7pp

I Reportable occurrences, letters & related correspondence

0004090209 Forwards CVI-Nuclear 000903 Part 21 report re potential failure of McDowd Edison device used in CVI-Nuclear electronic control circuit for detecting high temps in steamline in various air filtration systems
HARTV, C. E. Tennessee Valley Authority 00/05/08 4pp

0004090209 Forwards final deficiency report re unacceptable bending of welded air shroud and concrete structures noted in IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04
HILLIS, L. M. Tennessee Valley Authority 00/06/02 1p

--0004090209 Final deficiency report re unacceptable bending of welded air shroud and concrete structures noted in IE Insp Report 00-518/00-04, 00-519/00-04, 00-520/00-04 & 00-521/00-04 Bending of shroud has no significant effect on stud capacity
Letter guidelines for max bending of stud anchors
Tennessee Valley Authority 00/06/02 2pp

0004090209 Forwards final interim deficiency report re standing gas treatment sys chemical adder
HILLIS, L. M. Tennessee Valley Authority 00/06/04 1p

--0004090209 Final interim deficiency report re standing gas treatment sys chemical adders Chemical retention screens separating from frames due to improper or broken spot welds Vendor, CVI-Nuclear, investigating problem Final report by 000600
Tennessee Valley Authority 00/06/04 1p

0004090209 Forwards interim deficiency report re steam tunnel embedment stiffener plate weld
HILLIS, L. M. Tennessee Valley Authority 00/06/04 1p

--0004090209 Interim deficiency report re failures by Atlas Machine & Iron Works to implement QA procedures for steam tunnel embedment stiffener plate weld Stiffener plate NCR-13 welded per QA requirements & aid for Atlas QA program constructed
Tennessee Valley Authority 00/06/04 1p

0004090209 Final Part 21 report re mixed heat of steel supplied by US Steel from which 4-inch shroud & 2-inch base were weld to ASME requirement Investigations conducted & closed at 46 failed facilities
BRAY, J. L. Chemtreat Corp., Tulsa Turns Div 00/04/06 2pp

0004090209 Forwards final deficiency report re defective McDowd-Edison temp detection controllers in standing gas treatment sys
HILLIS, L. M. Tennessee Valley Authority 00/06/13 1p

--0004090209 Final deficiency report re defective temp detection control in standing gas treatment sys Electronic temp detection controllers failed in test Caused by acid flux solder sealing controls Controllers to be replaced with certified controllers
Tennessee Valley Authority 00/06/13 2pp

0004090209 Forwards final deficiency report re incorrect root face on shroud catalyst sleeves
HILLIS, L. M. Tennessee Valley Authority 00/06/19 1p

DOCKETED ITEMS

281

```
--B0062502B: Found deficiency re: incorrect root base on skewed
cadwall sleeves Atlas Machine & Iron Works fabricated some
representative structures using same welding process as
sleeves Destructive pull tests performed satisfactorily
* Tennessee Valley Authority 80/04/19 Zpp
```

8004290256 Second interim deficiency rept re defects in Rose
caliber units Unit 8 GE investigations re quantity of Model
1102 pressure transmitters shipped continuing Final rept
will be submitted by 800917
MILLS, J. H Tennessee Valley Authority 80/04/20 is

SECRET STN-50-506 HARTSVILLE NUCLEAR PLANT, UNIT 3

A. Application/construction stage documents & correspondence

REG-2003-0300: Advisers IIR & PIR applicants of NRC decision to implement a plan presented in Section 4 of NUREG-6577
adequacy of applicable support structures General operating
reactor review procedure & acceptance criteria until
EISENHUT, D G Division of Licensing 80/05/00 13ss

© Adjudicators correspondence

0000000356. Advises that Al Getteman will no longer appear in proceedings on behalf of util
BAGGER, H M Tennessee Valley Authority 00/00/19. See

6 Inspection reports, IE Bulletin & correspondence

8004039498 Forwarded IE Insp Repts 80-818/80-08, 80-819/80-08, 80-820/
80-08 & 80-326/80-08 on 805128-8229 No noncompliance noted
HARRIS, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/84/22 Doc

```
--B004030811 [E Insp Regis 20-318/90-03, 20-319/90-03, 20-820/90-03 &
20-821/90-05 on 000520=0229 No noncompliance noted. Major
areas inspected structural concrete, steel structures &
reactor vessel installation
CANSURELL, P 6 Region 2, Atlanta, Reactor Construction &
Engineering Support Branch SWAN, W B Region 2, Atlanta, Office
of the Director 20/04/92 App
```

EO04040139 Forwarded IE Bulletin 88-11, "Masonry Wall Design - No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and G'RESLEY, J P Region 2, Atlanta, Office of the Director 88/05/08 Dm

EO0404067 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability." No written response required IE Info Mobile 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" and O'NEILLY, J P Region 2, Atlanta, Office of the Director 80/05/09 Don

8004120004 Forwarded DE Circular 80-11, "Emergency Diesel Generator Lubrication Oil Cooler Failures." No written response required.
O'NEIL, J. P., Region 2, Atlanta, Office of the Director 80/05/13
Jus

0004092454 Responds to 000123 ltr which transmitted SE Bulletin 00-02
Investigations revealed that Feedwater spargers or thermal
element mfg &/or fabricated by Marvin Engineering Co have
not been purchased &/or have not been installed in plants
HILL, L. M. Tennessee Valley Authority 02/05/02. is

0004180041 Act receipt of 800907 is informing NRC of steps taken to correct violations noted in IX Insp Repts 80-018/80-04, 80-519/80-04, 80-520/80-04 and 80-521/80-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/09/24 JWS

--9006190064 Forwards supplemental response to IE Insp Rept
30-CIR/90-04. Investigating all applicable weeds RCP-17 &
RCP-04 being revised. Clarification of requirements will
prevent concurrence through misinterpretation.
NLLS, L. M. Tennessee Valley Authority 00/03/07 Doc

--0006180000 Act receipt of 800409 ltr informing NRE of steps taken to
 correct violations noted in SE Insp Regs 80-028/80-04;
 80-019/80-04, 80-020/80-04 & 80-021/80-04 Supplemental rept
 due by 080509
 S&BPHY:C E Region 2, Atlanta; Reactor Construction & Engineering
 Branch, Branch 80/04/20, 2ea

```
--800480072 Response to NAC 800317 Str re violations noted in DE Invp
Rpts 80-010/80-04, 80-019/80-04, 80-020/80-04 & 80-021/80-04
Corrective actions joint stamped w/low stress stamps in
piping metl adjacent to welds
PILGR, M. Tegemeier-Mailou Authority 85064/06 pas
```

--8004190077 Forwards 18 insp Repts 30-518/89-94, 50-519/90-94,
30-520/90-04 & 30-521/90-04 as 800217-32 & notice of
violation
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering
Bryant, James 80-02143

==B004180000 Notice of violation from Insp on 080219-22
 * Region 2, Atlanta, Office of the Director 06/02/11 in

--8006180091 IE Insp Repts 30-518/80-84, 30-519/80-84, 30-520/80-84 & 30-521/80-84 on 800319-22 Noncompliance noted failure to follow procedure in weld joint identification
HERFOT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch BLAND, J J, NLEINSTRONG, W Region 2, Atlanta, Office of the Director 80/03/11 7pg

B Reportable occurrences, LORs & related correspondence

60-0606230 Forwards CTE-Nuclear 808882 Park 21 rept re potential failure of McDraw Edison device used in CTE-Nuclear electronic control circuit for detecting high temps in steam from uranium air filter/briden sys
KENDRICK, M Tennessee Valley Authority. 30/05/08 4pg

BO06060401 Forwards final deficiency rpt re unacceptable bending of
welded stud anchors on embedded plates
HILL&L H Tennessee Valley Authority BO/06/02 1p

--0006860410 Final deficiency report re unacceptable bending of welded stud anchors on embedded plates Testing program was initiated
Bending of studs has no significant effect on stud capacity.
Life guidelines for max bending of stud anchors
* Tennessee Valley Authority 00/06/02 Jap

000610040 Forwards first interim deficiency report re steady gas treatment w/o charcoal adsorber
MCC-BUS, M Tennessee Valley Authority 00/06/94 5p.

--0004100000 First interim deficiency report re standby gas treatment system thermal adsorbent Charcoal Retention exceeds capacities expiring from frame due to improper or broken spot welds. Vendor, OTS/Nuclear, investigating problem. Final report by 000820
* Tennessee Valley Authority 02/06/04 ts.

000420309 Forward interior deficiency rept re steam tunnel embedment
stiffener plate weld
HSL&I, Inc. Tennessee Valley Authority 95/04/04. 1p.

 00042000Z Enterin deficiency report re failure by Atlas Machine & Iron
 Works to implement GA procedures for steam tunnel embedment
 stiffener plate weld Stiffener plate NER-10 welded per GA
 requirements & aid for Atlas GA program contracted
 5. Expenses Atlas Authority. 00042004. 10.

8026200004 Final Part 21 rept on mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AS24478 requirement. Investigations conducted & closed at 46 listed facilities

W036200432: Forwards final deficiency report re defective McGraw-Hill
lamp detection controllers in standby gas treatment systems
Hill, E. M. Tennessee Valley Authority. W036200432 1p.

--0006200484 Final deficiency report defective temp detection controller
in standby gas treatment sys Electronic temp detection
controller failed in svc Caused by acid fume solder sealing
temperature controllers to be replaced w/unaffected controllers
* Tennessee Valley Authority 06/06/12 298

00042800286 Second interim deficiency report re defects in Rosemount trip
cable units Util & OE investigations re quantity of Model
1150 pressure transmitters shipped continuing final report
to be submitted by 000917
001461.0 Tennessee Valley Authority 00704/00 1p.

DOCKET 274-50-321 SHAWVILLE NUCLEAR PLANT, UNIT 4

A Application/Construction stage documents & correspondence

0056230100 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0877 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria met.
EIS/DO/001.0 0 Division of Licensing 00/09/20 17pp

G Adjudication correspondence

0056230200 Advises that Mr. Gutierrez will no longer appear in proceedings on behalf of still.
MS/SEC.H 0 Tennessee Valley Authority 00/09/19 7pp

Q Inspection reports, IE Bulletins & correspondence

0056230400 Forwards IE Insp Repts 50-510/00-05, 50-519/03-05, 50-520/00-05 & 50-521/00-05 on 00/01/02-02/02 re noncompliance notices.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/23 2pp

0056230500 IE Insp Repts 50-510/00-05, 50-519/03-05, 50-520/00-05 & 50-521/00-05 on 00/01/02-02/02 re noncompliance notices.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/22 4pp

0056230600 IE Insp Repts 50-510/00-05, 50-519/03-05, 50-520/00-05 & 50-521/00-05 on 00/01/02-02/02 re noncompliance notices.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/22 4pp

0056230700 Forwards IE Bulletin 00-13, "Safety Heat Removal By Coreability." No written response required IE Insp Notice 00-25, "Loss of Safety Heat Removal Coreability at Davis-Besse Unit 1 while in Refueling Mode" and
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/05/00 0pp

0056230800 Forwards IE Circular 00-11, "Emergency Diesel Generator Load Control Function." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/06/12 0pp

0056230900 Responds to 005021 ltr which transmitted IE Bulletin 00-02. Investigation revealed that redundant spargers or thermal sleeves are not fabricated by Marvin Engineering to have not been purchased for have not been installed in place.
MILLER, L H Tennessee Valley Authority 00/05/20 1p

0056231000 Ack receipt of 005007 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-510/00-04, 50-519/03-04, 50-520/00-04 & 50-521/00-04.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/21 2pp

0056231100 Forwards supplemental response to IE Insp Repts 50-510/00-04, 50-519/03-04, 50-520/00-04 & 50-521/00-04.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/21 2pp

0056231200 Ack receipt of 005049 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-510/00-04, 50-519/03-04, 50-520/00-04 & 50-521/00-04.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/20 2pp

0056231300 IE Insp Repts 50-510/00-04, 50-519/03-04, 50-520/00-04 & 50-521/00-04 on 00/01/02-02/02 re noncompliance notices. Failure to follow procedure in weld joint identification.
MS/SEC.H 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/21 7pp

Q Reportable occurrences, LERs & related correspondence

0056230200 Forwards CTF-Nuclear 00/03/03 Part 21 re potential failure of McGraw-Hill device used in CTF-Nuclear electronic control circuit. JOP defectives found in airframe in various air filtration systems.
REYNOLDS Tennessee Valley Authority 00/04/00 4pp

0056230300 Forwards final deficiency rept re unacceptable bending of welded stud anchors on embedded plates.
MILLER, L H Tennessee Valley Authority 00/06/02 1p

0056230400 Final deficiency rept re unacceptable bending of welded stud anchors on embedded plates. Testing program was initiated. Bending of studs has no significant effect on stud capacity.
Latta guidelines for max bending of stud anchors.
Tennessee Valley Authority 00/06/02 7pp

0056230500 Forwards final interim deficiency rept re standby gas treatment gas charcoal adsorber.
MILLER, L H Tennessee Valley Authority 00/06/04 1p

0056230600 Final interim deficiency rept re standby gas treatment gas charcoal adsorbers. Chemical retention tanks separating from frame due to improper or broken spot welds. Vendor, CTF-Nuclear, investigating problem. Final rept by 00/02/04.
Tennessee Valley Authority 00/06/04 1p

0056230700 Forwards interim deficiency rept re steam tunnel embedded stiffener plate weld.
MILLER, L H Tennessee Valley Authority 00/06/04 1p

0056230800 Interim deficiency rept re failure by Allen Machine & Iron Works to implement acceptance for steam tunnel embedded stiffener plate weld. Stiffener plate NCB-10 welded per GA requirements to aid for Allen 30 program conducted.
Tennessee Valley Authority 00/06/04 1p

0056230900 Final Part 21 re missed heat of steel supplied by US Steel when 2-inch elbows & 2-inch tees were used to ASME required investigations conducted & closed at de listed facilities.
SEAR, J L Chatterbox Corp., Tube Tensile Div 00/06/06 3pp

0056231000 Forwards final deficiency rept re defective temp detection controller in standby gas treatment gas Electronic temp detection controller failed in use caused by acid flux residue. Sealing materials Controllers to be replaced or certified controllers.
Tennessee Valley Authority 00/06/13 4pp

0056231100 Final deficiency rept re defective temp detection controller in standby gas treatment gas Electronic temp detection controller failed in use caused by acid flux residue. Sealing materials Controllers to be replaced or certified controllers.
Tennessee Valley Authority 00/06/13 4pp

0056231200 Second interim deficiency rept re defects in Rosemount trip/cut-off valve. LTR re investigation re quantity of hoses (132 pressure transmitters shipped containing final rept will be submitted by 00/07/07).
MILLER, L H Tennessee Valley Authority 00/06/20 1p

DOCKET 274-50-322 SHAWVILLE NUCLEAR POWER PROJECT, UNIT 1

A Application/Construction stage documents & correspondence

0056230100 Requests info re composition of open cooling gas. Advises that Elgert Tribe concern about toxicity at diffusers have been satisfied.
BUECHER H Emergreen Legal Services 00/01/20 1p

0056230200 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0877 re adequacy of applicable support structures. General operating reactor review procedure & acceptance criteria met.
EIS/DO/001.0 0 Division of Licensing 00/09/20 13pp

0. Adjudicatory correspondence

0004040099 Motion to dismiss application w/precedice Applicants took no steps to pursue application despite opportunity given at 000402 conference to address pending priority & administrative issues Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/05/98 3pp

0004040020 Forwards meeting status report for May 1988 consisting of utility reply in opposition to intervenor Skaghtians Concerned About Nuclear Power Motion to Dismiss Court Application & JE Hecce affidavit Wra encl THIRSELM F T Perkins Case Olsen Olsen & Williams 00/05/93 3pp

0004040020 Reply in opposition to Skaghtians Concerned About Nuclear Power 000009 motion to dismiss application w/precedice due to lack of diligent pursuit Applicants are engaged in extensive program to locate suitable site THIRSELM F T Perkins Case Olsen Olsen & Williams 00/05/93 3pp

0004040020 Affidavit in support of applicants' reply objecting to Skaghtians Concerned About Nuclear Power 000009 motion to dismiss application Explains applicants' efforts to locate suitable site Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/05/93 3pp

0004040033 Submits second status report re Skagit application & continuing review efforts by NRC & USDO No progress made re responsive review Anticipates Change in proposed site is being considered by applicants Updated info will be provided BLACK P L Hearing Branch 00/05/93 3pp

0004040047 Reply withdrawing 000009 motion to dismiss application Applicant response to motion & Hecce affidavit provided detailed info re applicant 000044 reply Progress report must be filed by 000401 by applicant Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/06/94 3pp

0004040041 Accepts 000430 as date for submittal of NRC & applicants' reply continuing Aft-May response to Paragraph 14 C of ABL 000304 order BLACK P L Atomic Safety and Licensing Board Panel 00/06/93 1p

0. Advisory Committee on Reactor Safeguards reports & correspondence

0004040093 Forwards 000356 ltr from ASRS to Commissioner Ahearn re near-term CP applications for info & use SCHWENKER A Licensing Branch 2 00/05/90 3pp

DOCKET ITEM 50-503 SHADY NUCLEAR POWER PROJECT, UNIT 2

A. Application/contracting stage documents & correspondence

0004040091 Requests info re completion of open cooling sys Advises that Skagit Tribes concern about toxicity at different have intensified BERNER D R H Evergreen Legal Services 00/06/93 1p

0004040010 Advises BNL & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHART D D Division of Licensing 00/06/90 13pp

0. Adjudicatory correspondence

0004040099 Motion to dismiss application w/precedice Applicants took no steps to pursue application despite opportunity given at 000402 conference to address pending priority & administrative issues Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/05/98 3pp

0004040020 Forwards meeting status report for May 1988 consisting of utility reply in opposition to intervenor Skaghtians Concerned About Nuclear Power Motion to Dismiss Court Application & JE Hecce affidavit Wra encl THIRSELM F T Perkins Case Olsen Olsen & Williams 00/05/93 3pp

0004040020 Reply in opposition to Skaghtians Concerned About Nuclear Power 000009 motion to dismiss application w/precedice due to lack of diligent pursuit Applicants are engaged in extensive program to locate suitable site THIRSELM F T Perkins Case Olsen Olsen & Williams 00/05/93 3pp

0004040020 Affidavit in support of applicants' reply objecting to Skaghtians Concerned About Nuclear Power 000009 motion to dismiss application Explains applicants' efforts to locate suitable site Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/05/93 3pp

0004040033 Submits second status report re Skagit application & continuing review efforts by NRC & USDO No progress made re responsive review Anticipates Change in proposed site is being considered by applicants Updated info will be provided BLACK P L Hearing Branch 00/05/93 3pp

0004040047 Reply withdrawing 000009 motion to dismiss application Applicant response to motion & Hecce affidavit provided detailed info re applicant 000044 reply Progress report must be filed by 000401 by applicant Certificate of Gov and LECB R H Skaghtians Concerned About Nuclear Power LECB R H Lusk R H 00/06/94 3pp

0004040041 Accepts 000430 as date for submittal of NRC & applicants' reply continuing Aft-May response to Paragraph 14 C of ABL 000304 order BLACK P L Atomic Safety and Licensing Board Panel 00/06/93 1p

C. Utility Environmental Report (ER), amendments & correspondence

0004040020 Forwards 000356 ltr from ASRS to Commissioner Ahearn re near-term CP applications for info & use SCHWENKER A Licensing Branch 2 00/05/90 3pp

DOCKET ITEM 50-503 SHADY NUCLEAR STATION, UNIT 1

A. Application/contracting stage documents & correspondence

0004040010 Advises BNL & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHART D D Division of Licensing 00/06/90 13pp

0004040020 Advises that NRC & industry should develop improved procedures for expediting license applications Suggests meeting applicant & vendors for expeditious review of key design decisions EISENHART D D Division of Licensing 00/06/90 1p

0004040020 Notification of 000379-10 meeting until in Bethesda, MD to participate in review of all power ops BERNER D R H Licensing Branch 2 00/06/90 1p

0004040010 Memorandum that status application be accepted for sketching Application is about 90% complete & some sections of FEAR & environ report are complete TEDESCO L Assistant Director for Licensing 00/06/90 1p

0004040010 Forwards application for OL

WV BRUNT E E Arizona Public Service Co 00/06/89 3p

0004040010 Application for OL

Arizona Public Service Co 00/06/89 35pp

0004040010 Forwards "100-2 Lessons Learned Implementation Report" WVA BRUNT E E Arizona Public Service Co 00/06/89 13pp

C. Utility Environmental Report (ER), amendments & correspondence

0004040010 Forwards environ report, Vols 1-4 WVA BRUNT E E Arizona Public Service Co 00/06/89 1p

0004040010 Environ report, Vol 1 of 4

Arizona Public Service Co 00/06/89 35pp

0004040010 Environ report, Vol 2 of 4

Arizona Public Service Co 00/06/89 89pp

0004040010 Environ report, Vol 3 of 4

Arizona Public Service Co 00/06/89 89pp

DOCKETED ITEMS

--000230705 Extends reg. Vol 4 of 4
* Arizona Public Service Co 00/06/19 500pp

P Security, medical, emergency & fire protection plans

000230691 Forwards emergency plan
VAM BRUNT, E E Arizona Public Service Co 00/06/19 1p

--000230696 Emergency plan
* Arizona Public Service Co 00/06/19 140pp

G Administrative correspondence

0002306158 Forwards Director's decision per 2 204 & PR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental environmental statements on Class 9 accidents at Palo Verde Nuclear Station & Palo Verde
BENTON, H R Office of Nuclear Reactor Regulation, Director 00/06/19 2pp

--0002306185 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at Palo Verde. No special circumstances exist which would warrant requesting proceedings Request denied
BENTON, H R Office of Nuclear Reactor Regulation, Director 00/06/19 2pp

--0002306161 Director's decision per 2 204 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents No special circumstances exist which would warrant requesting proceedings
BENTON, H R Office of Nuclear Reactor Regulation, Director 00/06/19 17pp

--0002306162 Notice of issuance of Director's decision per 2 204 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents
BENTON, H R Office of Nuclear Reactor Regulation, Director 00/06/19 3pp

K Utilities Final Safety Analysis Report (FSAR) & amendments

0002306073 Chapter 1 of Palo Verde FSAR, "Introduction & General Description of Plant" Includes Revision 1
* Arizona Public Service Co 00/05/31 100pp

0002306077 Chapter 2 of Palo Verde FSAR, "Site Characteristics"
* Arizona Public Service Co 00/06/19 300pp

0002306083 Chapter 3 of Palo Verde FSAR, "Design of Structures, Components, Equipment & Systems"
* Arizona Public Service Co 00/06/19 400pp

0002306088 Chapter 4 of Palo Verde FSAR, "Reactor"
* Arizona Public Service Co 00/06/19 200pp

0002306094 Forwards FSAR, Vols 1-10
VAM BRUNT, E E Arizona Public Service Co 00/06/19 1p

--0002306098 FSAR, Vols 1-10 Includes Revision 1
* Arizona Public Service Co 00/03/31 210pp

0002306095 Chapter 5 of Palo Verde FSAR, "BOS & Connected Systems"
* Arizona Public Service Co 00/06/19 400pp

0002306201 Chapter 6 of Palo Verde FSAR, "Engineered Safety Features"
* Arizona Public Service Co 00/06/19 300pp

0002306203 Chapter 7 of Palo Verde FSAR, "Instrumentation & Controls"
* Arizona Public Service Co 00/06/19 540pp

0002306210 Chapter 8 of Palo Verde FSAR, "Electric Power"
* Arizona Public Service Co 00/06/19 130pp

Utility Sys
100pp

Steam & Power Conversion
130pp

Isolating Sys
120pp

000230701a Chapter 12 of Palo Verde FSAR, "Radiation Protection"
* Arizona Public Service Co 00/06/19 100pp

0002307017 Chapter 13 of Palo Verde FSAR, "Conduct of Operations"
* Arizona Public Service Co 00/06/19 40pp

0002307018 Chapter 14 of Palo Verde FSAR, "Initial Test Program"
* Arizona Public Service Co 00/06/19 20pp

0002307020 Chapter 15 of Palo Verde FSAR, "Accident Analysis"
* Arizona Public Service Co 00/06/19 40pp

0002307021 Chapter 16 of Palo Verde FSAR, "Tech Specs"
* Arizona Public Service Co 00/06/19 120pp

0002307022 Chapter 17 of Palo Verde FSAR, "QA"
* Arizona Public Service Co 00/06/19 30pp

B Inspection reports, IN Bulletin & correspondence

00023070187 Forwards IE Insp Repts 00-520/00-04, 00-520/00-04 & 00-520/00-04 re NRC001-00 re non-compliance noted Major areas requested containment bldg contractor/palisade crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement
BENTON, H R Region 5, San Francisco, Reactor Construction & Engineering Support Branch 00/05/02 2pp

--00023070192 IE Insp Repts 00-520/00-04, 00-520/00-04 & 00-520/00-04 re NRC001-00 re non-compliance noted Major areas requested containment bldg contractor/palisade crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement
BENTON, H R Region 5, San Francisco, Reactor Construction & Engineering Support Branch 00/05/01 4pp

B Reportable occurrences, LBRs & related correspondence

00023070201 Advises that commitment made in 000024 preliminary deficiency report will be met before 40 days due to implementation difficult info provided by 000024
VAM BRUNT, E E Arizona Public Service Co 00/05/20 2pp

0002307024 Final Part 25 report re rated heat of steel supplied by UM Steel from which 4-inch steam & 2-inch condensate were withdrawn
BENTON, H R Region 5, San Francisco, Reactor Construction & Engineering Support Branch 00/05/06 3pp

T Hearing transcripts on non-antitrust matters

0002307028 Forwards 000508 app review transcript re Class IE power app Review held before Power Sys Review Board in Phoenix, AZ
VAM BRUNT, E E Arizona Public Service Co 00/06/04 200pp

DOCKET 00-520-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

0002307010 Advises NRC & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedures & acceptance criteria NRC
BENTON, H R Division of Licensing 00/05/20 13pp

0002307022 Advises that NRC & industry should develop improved procedures for expediting license applications Supports meeting w/applicants & vendors for expeditious review of app design decisions
BENTON, H R Division of Licensing 00/06/10 1p

--0002307026 Notification of 000509-10 meeting w/app in Bethesda, MD to participate in review of app power sys
BENTON, H R Licensing Branch 2 00/06/10 1p

00023070185 Recommends that station application be accepted for deciding application is about 90% complete & some sections of FSAR & environ report are complete
TERESKO, R L Assistant Director for Licensing 00/06/16 1p

0002307017a Forwards application for CL
VAM BRUNT, E E Arizona Public Service Co 00/06/19 1p

--0002307020 Application for CL
* Arizona Public Service Co 00/06/19 240pp

DOCKETED ITEMS

260

0004230470 Forwards "NII-D Lessons Learned Implementation Rept."
VAM BRUNT, E.C. Arizona Public Service Co. 00/04/19 100pp

C. Utility Environmental Report (ERI), amendments & correspondence

0004230486 Forwards environ rept, Vols 1-4
VAM BRUNT, E.C. Arizona Public Service Co. 00/04/19 1p

--0004230492 Environ rept, Vol 1 of 4
* Arizona Public Service Co. 00/04/19 300pp

--0004230497 Environ rept, Vol 2 of 4
* Arizona Public Service Co. 00/04/19 300pp

--0004230702 Environ rept, Vol 3 of 4
* Arizona Public Service Co. 00/04/19 300pp

--0004230705 Environ rept, Vol 4 of 4
* Arizona Public Service Co. 00/04/19 300pp

F. Security, medical, emergency & fire protection plans

0004230491 Forwards emergency plan
VAM BRUNT, E.C. Arizona Public Service Co. 00/04/19 1p

--0004230496 Emergency plan
* Arizona Public Service Co. 00/04/19 140pp

G. Adjudicatory correspondence

0004230498 Forwards Director's decision per 2 206 & FR notice in
response to Friends of the Earth 791024 petition to require
preparation of supplemental environ statements on Class 9
accidents at Diablo Canyon, Rancho Seco & Palo Verde
NHTS, H.R. Office of Nuclear Reactor Regulation, Director
00/04/19 2pp

--0004230499 Responds to 791024 petition requesting preparation of
supplemental EIS re impact of Class 9 accidents at
facilities No special circumstances exist which would
warrant expediting proceedings Request denied
NHTS, H.R. Office of Nuclear Reactor Regulation, Director
00/04/19 2pp

--0004230501 Director's decision per 2 206 denying Friends of the Earth
791024 petition to require preparation of supplemental EIS
on Class 9 accidents No special circumstances exist which
would warrant expediting proceedings
NHTS, H.R. Office of Nuclear Reactor Regulation, Director
00/04/19 17pp

--0004230503 Notice of issuance of Director's decision per 2 206 denying
Friends of the Earth 791024 petition to require preparation
of supplemental EIS re Class 9 accidents
NHTS, H.R. Office of Nuclear Reactor Regulation, Director
00/04/19 2pp

K. Utility Final Safety Analysis Report (FSAR) & amendments

0004230670 Chapter 1 of Palo Verde FSAR, "Introduction & General
Description of Plant." Includes Revision 1
* Arizona Public Service Co. 00/03/20 100pp

0004230677 Chapter 2 of Palo Verde FSAR, "Site Characteristics"
* Arizona Public Service Co. 00/04/19 300pp

0004230683 Chapter 3 of Palo Verde FSAR, "Design of Structures,
Components, Equipment & Sys."
* Arizona Public Service Co. 00/04/19 400pp

0004230689 Chapter 4 of Palo Verde FSAR, "Reactor"
* Arizona Public Service Co. 00/04/19 20pp

0004230694 Forwards FSAR, Vols 1-10
VAM BRUNT, E.C. Arizona Public Service Co. 00/04/19 1p

--0004230699 FSAR, Vols 1-10 Includes Revision 1
* Arizona Public Service Co. 00/03/20 200pp

0004230695 Chapter 5 of Palo Verde FSAR, "ROD & Connected Sys."
* Arizona Public Service Co. 00/04/19 40pp

0004230704 Chapter 6 of Palo Verde FSAR, "Engineered Safety Features"
* Arizona Public Service Co. 00/04/19 200pp

0004230705 Chapter 7 of Palo Verde FSAR, "Instrumentation & Controls"
* Arizona Public Service Co. 00/04/19 140pp

0004230710 Chapter 8 of Palo Verde FSAR, "Electric Power"
* Arizona Public Service Co. 00/04/19 100pp

0004230711 Chapter 9 of Palo Verde FSAR, "Auxiliary Sys."
* Arizona Public Service Co. 00/04/19 400pp

0004230712 Chapter 10 of Palo Verde FSAR, "Clean & Power Conversion
Sys."
* Arizona Public Service Co. 00/04/19 180pp

0004230714 Chapter 11 of Palo Verde FSAR, "Radiation Hgt."
* Arizona Public Service Co. 00/04/19 120pp

0004230716 Chapter 12 of Palo Verde FSAR, "Radiation Protection"
* Arizona Public Service Co. 00/04/19 100pp

0004230717 Chapter 13 of Palo Verde FSAR, "Contact of Operations"
* Arizona Public Service Co. 00/04/19 40pp

0004230718 Chapter 14 of Palo Verde FSAR, "Initial Test Program"
* Arizona Public Service Co. 00/04/19 20pp

0004230720 Chapter 15 of Palo Verde FSAR, "Accident Analysis"
* Arizona Public Service Co. 00/04/19 80pp

0004230721 Chapter 16 of Palo Verde FSAR, "Tech Specs"
* Arizona Public Service Co. 00/04/19 120pp

0004230722 Chapter 17 of Palo Verde FSAR, "QA"
* Arizona Public Service Co. 00/04/19 10pp

O. Inspection reports, IE Bulletin & correspondence

00042309107 Forwards IE Insp Repts 00-028/RO-04, 00-029/RO-04 &
00-030/RO-04 on 000021-02 No non-compliance noted
00/02/02 0.0 Region 3, San Francisco, Reactor Construction &
Engineering Support Branch. 00/03/02 2pp

--00042309102 IE Insp Repts 00-028/RO-04, 00-029/RO-04 & 00-030/RO-04 on
000021-02 No non-compliance noted Major areas inspected
contained no b/c concrete, roller crane support girder,
reactor vessel supports & auxiliary bldg wall reinforcement
000021-02 Region 3, San Francisco, Reactor Construction &
Engineering Support Branch. 00/03/02 4pp

G. Reportable occurrences, LERs & related correspondence

0004230931 Advises that comment made in 000024 preliminary
decisionary report will not be met info from certification
testing will not be available within 60 days due to
implementation difficulties Info finalized by 000423
VAM BRUNT, E.C. Arizona Public Service Co. 00/05/02 2pp

0004230938 Final Park 21 rept re mixed heat of steel supplied by US
Steel from which 4-inch without & 2-inch heat were mfg by
AZSAP/JPL requirement investigations conducted & closed at
4B listed facilities
GEAR, J.L. Elmstrom Corp. Tube Turns Div. 00/06/04 2pp

T. Hearing transcripts on non-arbitrated matters

0004110099 Forwards 000528 sys review transcript re Class 10 power sys
Review held before Power Sys Review Board in Phoenix, AZ
Pg 1-170
VAM BRUNT, E.C. Arizona Public Service Co. 00/05/04 200pp

DOCKET WITH-30-330 PALO VERDE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

0004230910 Advises DWR & PWR applicants of NRC decision to modify
implementation plan presented in Section 4 of 000021-007 re
adequacy of applicable support structures General operating
reactor review procedure & acceptance criteria and
EIS/ENR/02 0.0 Division of Licensing 00/03/02 17pp

8004200222 Advice that NRC & industry should develop improved procedures for expediting license application. Suggests meeting with applicant & vendors re expediting review of app design decisions
ESTHER HUT, S. Division of Licensing 80/06/10 1p

--8004200223 Notification of 800797-10 seeking advice in Bethesda, MD to participate in review of AC power sys
HERRIGMAN, J. Licensing Branch 2 80/06/10 1p

8004200189 Recommends that station application be accepted for processing. Application is about 70% complete & some sections of PSAR & environ. rept are complete
TEDESCO, R. L. Assistant Director for Licensing 80/06/10 1p

8004200276 Forwards application for CL
VAN BRUNT, E. E. Arizona Public Service Co 80/06/19 1p

--8004200280 Application for CL
Arizona Public Service Co 80/06/19 250pp

8004200473 Forwards "TRN-2 Lessons Learned Implementation Rept"
VAN BRUNT, E. E. Arizona Public Service Co 80/06/19 150pp

C. Utility Environmental Report (LER), amendments & correspondence

8004200474 Forwards environ. rept. Vols 1-4
VAN BRUNT, E. E. Arizona Public Service Co 80/06/19 1p

--8004200492 Environ. rept. Vol 1 of 4
Arizona Public Service Co 80/06/19 300pp

--8004200497 Environ. rept. Vol 2 of 4
Arizona Public Service Co 80/06/19 300pp

--8004200702 Environ. rept. Vol 3 of 4
Arizona Public Service Co 80/06/19 300pp

--8004200705 Environ. rept. Vol 4 of 4
Arizona Public Service Co 80/06/19 300pp

F. Security, medical, emergency & fire protection plans

8004200495 Forwards emergency plan
VAN BRUNT, E. E. Arizona Public Service Co 80/06/19 1p

--8004200496 Emergency plan
Arizona Public Service Co 80/06/19 140pp

G. Adjudicatory correspondence

8004200190 Forwards Director's decision per 2 206 & PR seeking in response to Friends of the Earth 791024 petition to require preparation of supplemental EIS on Class 9 accidents at Palo Verde
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/06/19 3pp

--8004200197 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at facilities. No special circumstances exist which would warrant reopening proceedings. Request denied
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/06/19 2pp

--8004200198 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS on Class 9 accidents. No special circumstances exist which would warrant reopening proceedings
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/06/19 17pp

--8004200199 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS on Class 9 accidents
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/06/19 3pp

H. Utility Final Safety Analysis Report (FSAR) & amendments

8004200473 Chapter 3 of Palo Verde FSAR, "Introduction & General Description of Plant." Includes Revision 3
Arizona Public Service Co 80/05/23 120pp

8004200477 Chapter 3 of Palo Verde FSAR, "Site Characteristics"
Arizona Public Service Co 80/06/19 500pp

8004200478 Chapter 3 of Palo Verde FSAR, "Design of Structure, Components, Equipment & Sys."
Arizona Public Service Co 80/06/19 400pp

8004200479 Chapter 4 of Palo Verde FSAR, "Reactor"
Arizona Public Service Co 80/06/19 30pp

8004200479 Forwards FSAR Vols 1-10
VAN BRUNT, E. E. Arizona Public Service Co 80/06/19 1p

--8004200479 FSAR Vols 1-10 includes Revision 3
Arizona Public Service Co 80/05/23 210pp

8004200479 Chapter 3 of Palo Verde FSAR, "Reactor Connected Sys."
Arizona Public Service Co 80/06/19 40pp

8004200701 Chapter 5 of Palo Verde FSAR, "Engineered Safety Features"
Arizona Public Service Co 80/06/19 300pp

8004200702 Chapter 7 of Palo Verde FSAR, "Instrumentation & Controls"
Arizona Public Service Co 80/06/19 140pp

8004200703 Chapter 8 of Palo Verde FSAR, "Electric Power"
Arizona Public Service Co 80/06/19 150pp

8004200701 Chapter 9 of Palo Verde FSAR, "Auxiliary Sys."
Arizona Public Service Co 80/06/19 40pp

8004200703 Chapter 10 of Palo Verde FSAR, "Steam & Power Conversion Sys."
Arizona Public Service Co 80/06/19 180pp

8004200704 Chapter 11 of Palo Verde FSAR, "Radiation Nt"
Arizona Public Service Co 80/06/19 120pp

8004200704 Chapter 12 of Palo Verde FSAR, "Radiation Protection"
Arizona Public Service Co 80/06/19 100pp

8004200707 Chapter 13 of Palo Verde FSAR, "Conduct of Operations"
Arizona Public Service Co 80/06/19 40pp

8004200708 Chapter 14 of Palo Verde FSAR, "Initial Test Program"
Arizona Public Service Co 80/06/19 30pp

8004200702 Chapter 15 of Palo Verde FSAR, "Accident Analysis"
Arizona Public Service Co 80/06/19 40pp

8004200701 Chapter 16 of Palo Verde FSAR, "Tech Specs"
Arizona Public Service Co 80/06/19 130pp

8004200702 Chapter 17 of Palo Verde FSAR, "QA"
Arizona Public Service Co 80/06/19 20pp

I. Inspection reports, IE Bulletin & correspondence

8004200187 Forwards IE Insps Repts 30-508/80-04, 30-509/80-04 & 30-530/80-04 on 800201-20 Re noncompliance noted. Major areas inspected: containment bldg, concrete-pillar crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement
8004200187 Region 5, San Francisco, Reactor Construction & Engineering Support Branch, VORDEER/100000, Region 5, San Francisco, Office of the Director 80/05/02 2pp

--8004200192 IE Insps Repts 30-509/80-04, 30-509/80-04 & 30-530/80-04 on 800201-20 Re noncompliance noted. Major areas inspected: containment bldg, concrete-pillar crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement
8004200192 Region 5, San Francisco, Reactor Construction & Engineering Support Branch, VORDEER/100000, Region 5, San Francisco, Office of the Director 80/05/01 3pp

J. Reportable occurrences, LERs & related correspondence

8004200251 Advises that compliance data in 800258 preliminary deficiency rept will not be available within 60 days due to testing will not be available within 60 days due to testing. Will not be available within 60 days due to testing. Will not be available within 60 days due to testing
VAN BRUNT, E. E. Arizona Public Service Co 80/05/23 2pp

0001208604 Final Part 23 must be used back of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WP8 requirement investigations conducted & closed at 46 listed facilities
SEAR, J L. Clemons Corp., Tube Turns Div 80/06/86 3pg

GEAR: J L. Chetron Corp., Tube Turns Div 50/04/86 300

T. Hearing transcripts as nonofficially stated matters

000410200 Forward's 000500 sgs review transcript re Class EE power sgs
Review held before Power Sgs Review Board in Phoenix, AZ
Pg 1-179
MMT 00007, R E Arizona Public Service Co 00/04/84 008ss

DECKET 36-537 CLINCH RIVER WHEELER RESERVOIR

6. Utility Preliminary Safety Analysis Report, under

DD06103301 Confirms distribution of Amend 06 to PSNR Certificate of
Sve until
COPPLAND, E L. Chungy, Sept 04, Clinch River Breeder Reactor Plant
RD/DA023 Jan

6664270305 Forwards Amend 56 to PSAR
COPLAND, R L Energy Dept of, Clinch River Breeder Reactor Plant
80/06/27 400

--8006270223 Amend SO to PWR
* Energy Dept. of. Clinch River Breeder Reactor Plant 03/06/27
500us

BUCKET 50-508 MEMPHIS STATE UNIV RESEARCH REACTOR

© 2011 John Wiley & Sons, Ltd.

BOGA(YC001) Response in opposition to Zimmer Area Citizens BO0355
proposed tenthekens Interveners failed to demonstrate good
cause under policy stated in Commission decision overruling
ALAB-500 Certificate of NUC and
COMMITTEE B Cincinnati Gas & Electric Co. HETTERMAN, M. J. Connors,
Norman & Co. BOGA(YC001, 1000

SECRET BTH-80-546 PABBLE HILL NUCLEAR STATION. UNIT 1

B. Application reconstruction stage documents & correspondence

8064220110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
K1563047.D 0 Division of Licensing 00/05/20 13pp

0006660592 Forwards evaluation of 000400 consolidated description of revised GR program & 000004 supplemental rept Revised GR program is acceptable
Y04060003, B J Licensing Branch 1 00/00/03 400

--BCC6040996 Safety evaluation supporting revised QA program
* Licensing Branch 1 00/05/20 Sep

00060700071 Forwards response to questions & comments presented at
0006025 public meeting & 0004037 ltr Sdc of Nuclear Reactor
regulation 000411 meeting discussed changes to SW program
Changes have been documented & are part of doctored file
07ELLO-V Office of Inspection & Enforcement, Office of the
Director 00/03/02 70a

```
--B066090073 GA program for Facility
      * Samsont & Lunde, Inc  08/05/2003    07:00
```

2006190285 Ack receipt of E00509 ltr informing NRC of proposed method
for evaluating concrete surfaces which are inaccessible due
to backfilling
FIORIELLO, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/05/28 js

8066200610 Informes that proposed alternatives for design of quality records storage facility are acceptable. Acceptable alternatives should be incorporated into QA program.

THEODORE L. AUSTIN, Director for Licensing 02/04/93 App

© Admunications Corporation

000A10424 Response to Save the Valley-Save Harbin Hill BOCAHD action
to strike & objections to bill 1103 of Senate Civil Action
70-1367 on appeal Urges assigning costs to State of NY &
intervenor McCorrill of Sec Related correspondence
VOIST.H.H Public Service Co of Indiana, Sec VOIST.H.H LaSalle,
Lamb, Leiby & Harbin 05/05/79 3pp

8004000443 Forwarded graduated restriction of 70013 order
STELLIO-V Office of Inspection & Enforcement, Office of the Director
04/08/15 is

--BEC6DSD40F Deactivated reception of 790319 order-confirming that process prescribed in app affords reasonable assurance that safety-related activities will be conducted per requirements

BTLELO.V Office of Inspection & Enforcement, Office of the Director 80/03/13 Ann

iv. General correspondence

0000210113 Requests as Follows to 000033 Str. that safety-related work
 not be allowed until FBI investigation results are known
 FOM: L H Senate 00/04/17 Dgg

0000210100 Ltr from six citizens & associations requesting that CP not be issued until FBI investigation results are known & acted upon Urges that all work be stopped until facility is inspected by State the Valley engineers
DILLON - 004830,000 J L, 00PLN,0 Affiliation Unknown 00/00/00
dca

8006090138 Advances of certain changes in PRC of IN senior mgt. Mr. Barton
elected chairman but will also serve as chief executive officer
officer DV Hammer elected president but will serve as
chief operating officer Related correspondence
VOIR: H. H. Lohmeyer, Lamb, Lohmeyer & Nease 80/03/02 See

000010114 Mailgrams from 23 citizens requesting that CP should not be issued until FBI investigation results are known & acted upon. Urges that all contact be stopped until facility is inspected by Dave the Valley engineers.
DORCH, F. WINDLER, T. F., BERNETT, H. Affiliation Unknown 08/05/95
23a.

ECOLOGISTS Oppose Facility based on inadequate demand for increased electrical generating capacity & public safety considerations. Utility motivated by tax-related incentives. Preliminary has incentive vest and
HALL, F. Dave the Valley - Dave Markle Hill 805/650-4444

00041204AG Response to 000404 Ltr re status of FBI investigation in re alleged misconduct at facilities. Premature release of findings could jeopardize future action of DOJ Ltr & plan will be attached to transcript of 000325 meeting

BTLELLV Office of Inspection & Enforcement, Office of the Director
00/00/23 In

8064120184 Ack receipt of 803326 by enclosing H Hudgin statement & MA
Caseano prof vita Buils will be placed in 800329 meeting
record & MA Caseano vita will be considered in selection
process for independent engineer
STELLO V Office of Inspection & Enforcement, Office of the
Director 05/05/2010 In

--B006120187 Fernando R. Hidalgo statement presented at NYC 800325 m
w/afil in Mexican IN & MA Cessars prof vite
BATTISTO, F. M. BATTISTO, F. M. 00-107426, 2nd

0006170005 Ack receipt of 0000326 ltr forwarding comments re 000233
meeting on resumption of coast Community will be carefully
considered
STELL-V Office of Inspection & Enforcement, Office of the
Director 00/05/23 to

--0000170042 Forward statement which was not completely presented at 000025 meeting re resumption of trust Giuseppe Andolen written statement also sent WFO Giuseppe Andolen statement HANCO, F Save the Valley - New Marble Hill 00/03/06 1200

00062040 Response to 000411 ltr re DE McElrath comments & questions
about meeting in Madison, WI concerning Facility Forward NRC
response
00062040 J. Office of the Executive Director Per Operations
00062040 J

DOCKETED ITEMS

- 0004120146 Act receipt of 800902 ltr providing list of comments & questions for record of 800325 meeting re Facility Comments & questions will be included in meeting record & considered in license deliberations
BIELOU, W. Office of Inspection & Enforcement, Office of the Director 80/05/23 1p
- 0004120150 Requests review of OH McWhirter ltr re 800325 meeting in Madison, IN re facility
FORBES, M. Senate, Commerce, Business & Transportation 80/04/15 1p
- 0004173255 Notifies of donation of new div & author relocation to plant site
HILLIARD, S. Public Service Co. of Indiana, Inc. 80/04/09 1p
- 0 Inspection reports, 86 Bulletin and correspondence
- 0004090038 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800402-04 & 80-11 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/29 2pp
- 0004090055 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800402-04 & 80-11 No noncompliance noted Major areas inspected safety-related
HAWKINS, F. C. Region 3, Chicago, Office of the Director
HAWKINS, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 2pp
- 0004120020 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800321-0493 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Office of the Director 80/04/26 2pp
- 0004090024 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800321-0493 No noncompliance noted Major areas inspected safety-related
HAWKINS, F. C. Region 3, Chicago, Office of the Director
HAWKINS, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 2pp
- 0004090059 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800227-29, 0206 & 18-21 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- 0004120052 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800227-29, 0206 & 18-21 No noncompliance noted Major areas inspected observation of work & review of quality records & procedures
HAWKINS, F. C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 2pp
HAWKINS, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/17 2pp
- 0004090049 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800321 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Office of the Director 80/04/26 2pp
- 0004090070 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800321 No noncompliance noted Major areas inspected, meeting to discuss proposed neutron program & presentation of receipt issue activities
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/23 2pp
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- 0004170319 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800418-10 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/29 2pp
- 0004190323 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800418-10 No noncompliance noted Major areas inspected, license actions re temp of installed electrical structural steel & safety-related piping as part of cost verification program
HAWKINS, F. C. Region 3, Chicago, Office of the Director 80/04/23 2pp
- 0004090016 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800418-10 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- 0004090070 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800418-10 No noncompliance noted Major areas inspected cost activities & storage & preservation of steel & equipment
HAWKINS, F. C. Region 3, Chicago, Office of the Director 80/04/23 2pp
- 8004260175 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800329-02 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- 0004090018 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800327-08 No noncompliance noted Major areas inspected license action relative to physical tags & verification of in-place safety Category 1 piping & hangers
COCHRAN, E. C. Region 3, Chicago, Office of the Director
DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/19 2pp
- 8004190076 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190700 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190702 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190704 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190705 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190713 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl 10/0 encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0004190717 Notifies New York State Board of 800606 meeting in Madison, IN to discuss NRC regulatory & resident ins programs for nuclear power plants tentative agenda encl
HUFFLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 1p
- 0006200162 Responds to IE Bulletin 80-08 re vacuum condition resulting in damage to chemical vol holdup tanks Evaluation of protection measures against vacuum damage is ongoing
Requests extension until 800709
HILLIARD, S. Public Service Co. of Indiana, Inc. 80/06/06 1p
- 0006190606 Forwarded IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800429-01, 0409-0505, 04-09 & 18-10 No noncompliance noted
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- 0004190300 IE Insp Repts 80-546/80-10 & 80-547/80-11 on 800429-01, 0409-0505, 04-09 & 18-10 No noncompliance noted Major areas inspected procedures, deviations, quality records observation of work & previous ins findings
HAWKINS, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/06 2pp
HAWKINS, F. C. Region 3, Chicago, Office of the Director 80/06/06 2pp
- 8006200052 Act receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-546/80-10 & 80-547/80-11
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8006200055 Responds to NRC 000528 ltr re violations noted in IE Insp Repts 80-546/80-10 & 80-547/80-11 Corrective actions: until is presently arranging for proper personnel assignment to ensure deficiency report responsibilities
HILLIARD, S. Public Service Co. of Indiana, Inc. 80/06/20 2pp
5. Reportable occurrences, 86B & related correspondence
- 8006200049 Interim Part 23 test re operation of centrifugal charging pump at min flow rate when RCR reached pressurizer safety valve setpoint pressure during secondaries up high energy line rupture testing/flow will analyze problem
DANIELSON, D. H. Public Service Co. of Indiana, Inc. 80/06/20 2pp

DOCKETED ITEMS

21

7 Hearing transcripts on non-NRC trust matters

0005010137 Forwards transcript of 000325 hearing in Madison, IN concerning two witnesses & some uncertainties due to absence of prof. court reporter
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/05 1p

--0005010177 Transcript of 000325 hearing in Madison, IN
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/05 200p

--0005010187 Ack receipt of NRC notice of 000401 meeting in Bethesda, MD re revised QA program. Expresses concerns re safety-related questions not answered at Madison, IN meeting
EYED,J A Bensafra Audubon Society 00/04/07 2pp

--0005010202 Submits questions & comments presented at 000325 public meeting in Madison, IN
EYED,J A Bensafra Audubon Society 00/04/03 2pp

--0005010208 Forwards H. Hudgins statement presented at 000325 meeting in Madison, IN w/proof qualifications
BATTILO,T H Battilio, T H 00/03/26 2pp

--0005010217 Comments handling of 000325 meeting in Madison, IN re H. Hudgins re safety matters and
BATTILO,T H Battilio, T H 00/03/26 2pp

DOCKET 07N-00-047 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

0006200110 Advises DMR & P&H applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0057 re adequacy of applicable support. Also transmits General operating reactor review procedure & acceptance criteria and
ETEMER,F D Division of Licensing 00/05/00 10pp

0006000092 Forwards evaluation of 000420 consolidated description of revised QA program & 000506 supplemental report. Revised QA program is acceptable
YBARRAS,JOE D J Licensing Branch 1 00/05/03 4pp

--0006000096 Safety evaluation supporting revised QA program & Licensing Branch 1 00/05/03 2pp

0006000097 Forwards response to questions & comments presented at 000325 public meeting & 000401 re QA of Nuclear Reactor Regulation. 000401 meeting discussed changes to QA program. Changes have been discussed & are part of revised file
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/03 7pp

--0006000097 QA program for facility
W. Barent & Lundy, Inc 00/05/03 37pp

0006100004 Ack receipt of 000509 letter informing NRC of proposed method for evaluating concrete surfaces which are inaccessible due to scaffolding
FISHER,L J Hagler, S. Chicago, Reactor Construction & Engineering Support Branch 00/06/03 1p

0006200013 Informs that proposed alternatives for design of quality records storage facility are acceptable. Acceptable alternatives should include surfaces which are inaccessible due to scaffolding
TERRECO,R L Assistant Director for Licensing 00/04/00 4pp

8 Regulatory correspondence

0006100024 Response to Save the Valley-Marble Hill 000403 action to advise NRC of objections to unit 2 of costs re civil action. 70-1200 re model Urges assigning costs to State of KY & intervenor. McCarty/Certificate of Rev Related correspondence
WIGST,H H Public Service Co. of Indiana, Inc WIGST,H H LeBaron, Lundy, Leiby & Decker 00/04/20 3pp

0006000043 Forwards production notification of 790815 order
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/15 1p

--0006000049 Graduated revocation of 790815 order, confirming when process prescribed in app affords reasonable assurance that safety-related activities will be conducted per requirements
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/13 4pp

H General correspondence

0005010113 Requests, as follows, re 000313 ltr that safety-related work not be allowed until FBI investigation results are known
FORD,J W Senate 00/04/17 2pp

0005010130 Ltr from six citizens & associations requesting that CP not be issued until FBI investigation results are known & acted upon. Urges that all costs be stopped until facility is inspected by Save the Valley engineers
OILL,M J ORELAND,WM J L HEPNER,H Affiliation Unknown 00/04/30 4pp

0006000124 Advises of certain changes in PEO of IN senior opt. H. Barker elected chairman but will also serve as chief executive officer. Dr. Barker elected president but will serve as chief operating officer. Related correspondence
WIGST,H H LeBaron, Lundy, Leiby & Decker 00/05/02 2pp

0005010114 Requests from six citizens requesting that CP should not be issued until FBI investigation results are known & acted upon. Urges that all costs be stopped until facility is inspected by Save the Valley engineers
OILL,M J ORELAND,WM J L HEPNER,H Affiliation Unknown 00/05/05 2pp

0006000085 Opposes facility based on inadequate demand for increased electrical generating capacity & public safety considerations. Will motivated by associated incentives. Preliminary cost incentive report and
BATTILO,T H Battilio, T H 00/05/05 4pp

0006100442 Response to 000404 ltr re status of FBI investigation into alleged misconduct at Facility. Preliminary release of findings could jeopardize future action of DOE. Ltr plan will be attached to transcript of 000325 meeting
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/02 1p

0006100014 Ack receipt of 000325 ltr enclosing H. Hudgins statement & MA Casanova report. Will be placed in 000325 meeting record & MA Casanova will be considered in selection process for independent program
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/03 1p

--0006100018 Forwards H. Hudgins statement presented at MA 000325 meeting until re Madison, IN re MA Casanova report
BATTILO,T H Battilio, T H 00/05/06 7pp

0006100023 Ack receipt of 000325 ltr forwarding comments re 000325 meeting re resumption of work. Comments will be carefully considered
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/03 1p

--0006100042 Forwards statement which was not completely presented at 000325 meeting re resumption of work. Bensafra Audubon Society statement also sent to Bensafra Audubon Society
BATTILO,T H Battilio, T H 00/05/05 10pp

0006100043 Response to 000411 ltr re DH McCarty comments & questions about meeting in Madison, IN concerning Facility. Forwards NRC response
BTELL,V Office of the Executive Director for Operations 00/05/00 1p

--0006100044 Ack receipt of 000502 ltr providing list of comments & questions for record of 000325 meeting re Facility. Comments & questions will be included in meeting record & considered in license deliberations
BTELL,V Office of Inspection & Enforcement, Office of the Director 00/05/03 1p

--0006100100 Requests review of DH McCarty ltr re 000325 meeting in Madison, IN re Facility
BTELL,V Senate, Commerce, Science & Transportation 00/04/01 1p

0006100031 Notice of formation of new div & author relocation to plant site
BTELL,V Public Service Co. of Indiana, Inc 00/04/89 1p

9 Inspection reports, CE Bulletin & correspondence

0006000052 Forwards IE Insp Repts 00-546-00-11 & 00-547-00-11 on 000402-04 & 00-11. Non-compliance noted
FISHER,L J Hagler, S. Chicago, Reactor Construction & Engineering Support Branch 00/04/25 2pp

DOCKETED ITEMS

--E006090056 IE Insp Repts: 50-346/00-11 & 50-347/00-11 on 500402-04 &
00-11 No noncompliance noted Major Areas Inspected Status
Review of IOPR21 Item & assist verification Procedures RPP-2
5, RPP-5
HARRIS, F.C. Region 2, Chicago, Office of the Director
NAYCS, D.R. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/05/21 2pp

00A020020 Forwards RE Insp Repts 30-346/00-14 & 50-547/00-14 on
000000-0400 No response/sends noted
FIONELL, Q Rept 3, Chicago, Office of the Director 00/04/26
Doc

--E05A000124 DE Insp Repts 10-046/BQ-14 & 10-047/BQ-14 on 000301-0403 Re noncompliance noted Major areas inspected safety-related piping, laydown areas & storage warehouses GABRIELSON, D H Region 2, Chicago, Heaster Construction & Engineering Support Branch CHS0883 J C Region 3, Chicago, Office of the Director 80/04/20 3cc

006025009 Forwards IE loss Regis SO-344/EO-38 & SO-347/EO-38 as
800227-29, 5006 & 10-23 No noncompliance noted
FIDELL-9 Region 3, Chicago, Reactor Construction & Engineer
Support Branch 00/04/26 260

--80662200A3 IE Insp Repts 80-546/80-06 & 80-547/80-02 on 8006227-2F.0366
 & 80-21 No noncompliance noted Major areas inspected
 observation of work & review of quality records &
 procedures
 HWYB-D W Region 3, Chicago, Reactor Construction & Engineering
 Support Branch (HWKJNDP C, HWKJNDP R Region 3, Chicago,
 Office of the Director 80/04/17 Top

0000000009 Forwards EE Insp Septs 00-046/00-12 & 00-047/00-12 re
000001 No noncompliance noted
KOPFLER, J G Region 2, Chicago, Office of the Director 00/04/26
Dag

--B005020373 LE Insp Regs 30-346/80-12 & 30-347/80-12 on 000230 No
 Aircompliance noted Major areas impacted waiting to discuss
 proposed restart program & resumption of receipt insp
 activities
 FID88011.0 Region 3 Chicago Swanton Construction & Engineering
 Support Branch DCH4E181A2-E 8, HANDED W Region 3 Chicago
 Office of the Director 00/04/93 2pc

2024192219 February 18 Insp Repts 50-544/EO-15 & 50-547/EO-15 on
500415-10 No noncompliance noted
FIDELL, J Region D, Chicago Reactor Construction & Engineering
Support Branch 02/04/24 2pg

--0906190329 IE Insp Repts 50-546/90-15 & 50-547/90-13 on 808416-10 Re
noncompliance noted Major areas inspected 808008 accident
re insp of installed Category I structural steel & safety-
related piping as part of const verification program
NGAWLM, J E, CORDEIRO, Z C, WILLIAMS, C C Region 3 Chicago
Office of the Director 80/D4/201 App

0006280166 Forwards IE Insp Repts 90-046/00-20 & 90-047/00-20 re
000401-09 No noncompliance noted
FIDRML1.2 Reg'n 3, Chicago, Reactor Construction & Engineering
Supply Branch 00/05/01 Doc

--S060295170 IE Insp Reps 30-344/30-20 & 30-347/30-20 on S804q1-35 Me
 noncompliance noted Major areas inspected cased activities
 & storage & preservation of mail & equipment
 WILLIAMS, C. C. HARRISON, J. J. Region 3, Chicago, Office of the
 Director S804q1-35

0006300179 Forwarded IE Insp Regis 80-344/80-18 & 80-347/80-18 on
090507-00 No compliance noted
FEDERAL, Q, Regis 3, Chicago, Reactor Construction & Engineering
Support Branch 80/05/24 Doc

000600000000 1K Insp Repts 50-546/EO-5B & 50-547/EO-1B on 000000-00 Re
 noncompliance noted Major areas inspected license action
 relative to physical Insp I verification of in-place safety
 Category I piping & hangers.
 CDB/DRO, I C. Region 3, Chicago, Office of the Director.
 SAMUELSON, D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch 02/05/19 Jon

00619DWA Notifier Board of Clark County Commissioners:Jeffersonville
IN at 0900h meeting in Madison IN to discuss NRC regulatory
& resident insop programs for nuclear power plants Tentative
agenda encl: M/W encl.
WAPLEN, J D Region 3, Chicago, Office of the Director 00/00/00

--000110700 Activities Board of Clark County Commissioners-Jeffersonville.
BR of 0006000 mapping in Madison. IN RE discuss MEC regulatory
 & resident into program for nuclear power plants tentative
 agenda only. MFO est
NMP/ER/J & Region 3. Chicago: Office of the Director 01/05/29
14

--BODDME/06000 Notifying Board of Clark County Commissioners, Jeffersonville, IN of BODDME meeting in Madison, IN to discuss NRC regulatory
A resident inn program for nuclear power plants tentative agenda encl WVS encl
APPLER, J. G. Section 3, Chicago, Office of the Governor. 05/05/99

==886610756: Notifies Hanover Town Board/Hanover, IN of BSC606 meeting;
Notifies IN to discuss NRC regulatory & resident insp
programs for nuclear power plants Tentative agenda and H/s
encl
REFFER: J O Region 3, Chicago, Office of the Director 05/05/99
tp

--BOGALHOFFS Notification of BOGALHOFFS meeting in Madison, IN to discuss NE
regulatory & resident info programs for nuclear power
plants. Tentative agenda and info and
HOPPLER, J D Region 3, Chicago, Office of the Director 03/05/29
1p

--8006192759 Notifies New WA State Bank of 800606 meeting in Madison, IN
to discuss ABC regulatory & resident insap program for
multipler power plants. Tentative agenda encl
JEFFLER, J O Region 2, Chicago, Office of the Director 80/05/29
Jec

8006230162 Responds to SE Radiation 60-65 vs vacuum condition resulting in damage to chemical vat holdup tanks Evaluation of protective measures against vacuum damage is ongoing
Requires extension until 800709
SHFELD-5 H Public Service Co. of Indiana, Inc 80/04-04 1a

MOA192296 Fernando SE Insp Repts SO-546/80-16 & SO-547/80-16 on
089922-25-0429-0522, 06-09 & 14-16 No noncompliances noted
FISSELL, J Region D, Chicago, Reactor Construction & Engineering
Support Branch SO/GS/OA 2/c

#0385240200 1E Insp Repts. 30-34A/EO-34 & 30-347/EO-16 on 800422-25. 0429-
 0523, 06-09 & 14-16 No noncompliance noted Major areas
 inspected procedure revisions, quality records, observation of
 work & previous Insp findings.
 HWY63, D M Region 3, Chicago, Reister Construction & Engineering
 Support Branch HAWKINS, P C. HAWKINS, J R Region 3, Chicago.
 Office of the Director 86/05/02 ggg

5004260352 Ack receipt of 500528 ltr informing NRC of steps taken to correct violations noted in LE Insp Rpts 50-544/10-22 & 50-547/80-03
FISHER, L. B Region 3, Chicago, Reactor Construction & Engineering Support Branch 00/06/11 10

-00000000354 Response to NRC 000021 for re violations noted in SE Insp
 Septs 30-044/00-03 & 00-047/00-03 Corrective actions will
 be presently arranging for proper personnel assignment to
 ensure dedication & responsibility
 SHARON M M Public Service Co of Indiana, Inc 00/05/00 Doc

5 Reportable occurrences, L&Es & related correspondence

90062093054 Interim Part 22 kept in operation of centrifugal charging
pump at min #200 rate when BCB reaches pressurizer safety
valve setpoint pressure during secondary was high energy
line rupture Westinghouse will analyze problem
SHLEDS, D W Public Service Co of Indiana, Inc 00/00/02 Dec

T. Keeping transcripts on non-antitrust matters

0002250137 Forward transcript of 800325 leaving in Madison, IN
containing few omissions & some inaccuracies due to absence
of prof court reporter
STELLA V Office of Inspection & Enforcement, Office of the
Attorney General 80/03/05 3p

--000220177 Transcript of HQ328 hearing in Madison, IN
 DTBLLD-V Office of Inspection & Enforcement, Office of the
 Director 80/03/25 230pp

-0003210187 Ack receipt of WFO notice of 000451 meeting in Bethesda-HQ
 re revised OH program Expenses concerns re safety-related
 questions not answered at Madison, IN meeting
 EYED, J A. Bessafree Audubon Society 00/04/07 Gpp

DOCKETED ITEMS

--6605210202 Substantive questions & comments presented at 090525 public meeting in Madison, IN
FRED J. A. Bessafres, Andrew Elliott, 03/04/20, Tue

--8003210008 Forwards M. Higgins statement presented at 800325 meeting in
Madison, IN w/prof qualifications
BATTILO, T M Battilo, T M 80/03/26 7pp

```
--8008216217 Compliments handling of 000328 meeting in Madison, IN F Heack
comments re safety matters encl
WALKE,F   Save the Valley - Save Harole Hill   00/03/26   App
```

DOCKET 56-549 PORT CALHOUN STATION, UNIT 2

9 Adjudicator correspondence

0006040486 Urges to hold Publisher licensing proceeding in Abeyance due
to pending Westinghouse breach of contract action against
until Present is constitutes semiannual status rept Related
correspondence
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 00/05/00 is

H General Correspondence

800411008a Requests that MA Tabor be substituted for MH Panolis
on our task in future; all info should be sent to MA Tabor
Tabor, H. A. Leibauf, Lomb, Leiby & MacDon 80/05/28 to

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

A Application/construction stage documents & correspondence

6004230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor Review procedure & acceptance criteria encl
E188360JF.D Q Division of Licensing 8/3/78 20 13pp

Ⓢ Adjudicatory correspondence

0006d10020 Notice of withdrawal from proceeding effective 0006d02
 certificate of Rev. and
 LAMAR R R Hearing Branch 2 00/06/03 400

DOCKET #TN-90-553 PHIPPS SEND NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

506220110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl
E18384UT.D O Division of Licensing NRC/OS/20 12pp

02068660270 Forwards detailed description of transverse flow
essential eye water spray pond one per 802502 5 09 telc
Fault is not judged capable per App A to 10CFR100
HILL-L M Tennessee Valley Authority 85/06/003 App

800624620 Perwards "For Comment" edition of NUREG-0619 Requests review
& comment W/o encl
815646UT.3 0 Divisions of Licensing 90/06/10 3pp

© Adjudicator correspondence

9006060356-Advices that AH Guterman will no longer appear in
proceedings on behalf of WHI
BANDER, R. W. Tennessee Valley Authority 80005/19 300

© Inspection reports, IE Bulletin & correspondence

0004050415 Forwarded IE Insp Repts 50-503/80-24 & 50-554/87-08 on
800321-0403 Re noncompliance 84442
NMPHY-C E Region 2, Atlanta, Reactor Construction & Enginee
Support Branch 80/04/83 Doc

--8066050420 IE Insp Repts 80-853/00-04 & 80-854/00-08 re 800331-0403 Noncompliance noted Major areas inspected concrete placement, QA manual review & Inspector Followup Items CONTROL, F G Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIH/F.R.H. Region 2, Atlanta, Office of the Director, 80/04/22 Yea

0006060159 Forwarded to Bulletin 88-11, "Nesemy Hall Design" No action
or written response required IE Info Notice 79-28.
*Downloaded at Structural Elements See to Five Support

U.S.S.I., J. P. Region 2, Atlanta, Office of the Director 00V 00V 000

004640M7 Forwarded IE Bulletin 00-12, "Secay Heat Removal Sys
Operability: No unitless response required IE Info Notice
00-20, "Loss of Secay Heat Removal Capability at Davis-Besse
Unit 1 While in Refueling Mode" and
00RGLUJ.P Region 2, Atlanta; Office of the Director 00/05/09
Jas

000610004 Forward: 1E Circular 001L "Emergency Diesel Generator Load
Gill Cooler Failures." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 05/05/13
Jea

0036035602 Air report of B00508 for informing NRC of steps taken to correct violation noted in IE Insp Repts 90-053/79-17 & 90-154/79-15
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 See

==8006830A04 Responds to NRC 800429 ltr re violation noted in EE ltr
Repts 50-553/79-17 & 50-554/79-18 Corrosion activity
discovered weld metal in excess of limit will be removed
NRC/LA H Tennessee Valley Authority 80/08/98 4cc

-B00603064 Act receipt of B003311r informing IBC of steps taken to
 correct violation noted in IE Insp Rpts 90-352/79-17 &
 90-054/79-14
 NUBPHC & Region 2, Atlanta, Reader Construction & Engineering
 Support Branch 80/04/29 Doo

--B000030308 Responds to ABC 800025 r/r re violation noted in 2E Insp
Repts 80-553/77-17 & 80-334/77-18 (corrective actions taken
while metal deposits will be removed Add details re case
w/ave with provided in Houseperformance Rpt PSH-067
MILAN, L M Tennessee Valley Authority Rpt 80/00/21 1p

Investigations revealed that feedwater spargers or thermal sleeves ofg &/or fabricated by Harvis Engineering Co have not been purchased &/or have not been installed in plants. MILLS, J. N Tennessee Valley Authority 02/05/01 by

0004100547 Outlines 000556 trap or geologic faulting in Unit 5 spray
pond UH3 may preclude offfall concrete operations on Dose 20
& Fault 19 Addl faulting must be reported
HURHW, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 20/05/97 See

0006190466 Response to WFO 000521 ltr re violation noted in
Repts 90-003/90-07 & 90-054/90-06 Corrective actions
procedure for controlling submerged are welding flux has
been made available to craft personnel
HILL, L. R Tennessee Valley Authority 00/06/92 3pg

0026250202 Forwards final response to notice of violation
RE Insp Repts 10-253/00-CR & 10-254/00-07 Concrete column
breaks for samples representing safety-related structure
statements made 8/20/97-CF have been reviewed
MILLER, L. M. Tennessee Valley Authority 03/04/99 2pg

© Recordable occurrences, LORs & related correspondence

EO6060Q230 Forwards CTI-Nuclear 800503 Part 21 rept re a
Failure of McGraw Edison device used in CTI-Nuclear
electronic control circuit for detecting high temps in
airstream in various air filtration sys
KENYON, H Tennessee Valley Authority 03/03/08 4pg

80060403401 Forwards final deficiency rept re unacceptable handling of
united stud anchors on embedded plates
MILLIG, L. Tennessee Valley Authority 80/06/00 10

```
--0000060453 Final Deficiency report unacceptable bending of welded stud  
anchors on embedded plates Testing program was initiated.  
Bending of studs has no significant effect on stud capacity  
Liste guidelines for bending of stud anchors  
* Tennessee Valley Authority 00/06/02, 3pp
```

8006110040 Forwards first interim deficiency rept re standby gas
treatment sys charcoal adsorber
MILLER, M Tennessee Valley Authority 80/05/04 1p

DOCKETED ITEMS

--0006100098 First interim deficiency report re standby gas treatment was chemical adsorbent. Chemical retention solvent separating from France due to improper re broken plate welds Vendor.
CTI-Nuclear, investigation problem Final report by 0006020
* Tennessee Valley Authority 00/04/04 1p

0006112009 Forwards interim deficiency report re steam tunnel embedment stiffener plate welds
HILLB.L.H. Tennessee Valley Authority 00/04/04 1p

--0006120013 Interim deficiency report re failure by Atlas Machine & Iron Works to implement AS procedures for steam tunnel embedment stiffener plate weld Stiffener plate NHI-10 welded per AS requirements & said for Atlas AS program contracted
* Tennessee Valley Authority 00/04/04 1p

0006120024 Final Part 21 report re allowed heat of steel supplied by US Steel from which 4-inch above & 2-inch base were off 22
A234AFB requirement investigation conducted & closed at AS listed facilities
HEARN,J.C. Chatham Corp. - Tube Times Div 00/04/06 3pp

0006130012 Forwards Final deficiency report re defective McGraw-Eddison temp detection controllers in standby gas treatment unit
HILLB.L.H. Tennessee Valley Authority 00/04/13 1p

--0006130048 Final deficiency report re defective temp detection controller in standby gas treatment unit. Electronic temp detection controller failed in test. Caused by wire flow solder sealing controls. Controllers to be replaced with certified controllers
* Tennessee Valley Authority 00/04/13 2pp

0006130057 Forwards First interim deficiency report re Springer Insp records
HILLB.L.H. Tennessee Valley Authority 00/04/19 1p

--0006130061 First interim deficiency report re Springer Insp records Civil SC Insp program being reviewed to determine changes necessary for compliance with applicable requirements.
* Tennessee Valley Authority 00/04/19 1p

0006130078 Forwards Final deficiency report re incorrect rust face on steam reduced sleeves
HILLB.L.H. Tennessee Valley Authority 00/04/19 1p

--0006130081 Final deficiency report re incorrect rust face on steam reduced sleeves. Atlas Machine & Iron Works fabricated some representative structures using same welding process as sleeves. Destruction pull tests performed satisfactorily
* Tennessee Valley Authority 00/04/19 2pp

0006130096 Second interim deficiency report re defects in Rosemount trip/calibrator units 1A & 2E investigations re quality of Model 1135 pressure transmitters shipped containing Final report will be submitted by 000617
HILLB.L.H. Tennessee Valley Authority 00/04/20 1p

DOCKET RTR-00-094 PHPPB BEND NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

0006130110 Advise EIR & FHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0877 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria met
EIDENHART,D.G. Division of Licensing 00/05/20 12pp

0006130370 Forwards detailed description of transverse fault beneath essential live water pipe for 000600 & 000601
Fault is not judged capable per App A to 10CFR101
HILLB.L.H. Tennessee Valley Authority 00/04/03 4pp

0006130400 Forwards "For Comment" edition of 000600-0419 Requests review & comment NRC met
EIDENHART,D.G. Division of Licensing 00/04/10 3pp

3 Adjudicatory correspondence

0006130258 Advise that AS Outcomes will no longer appear in proceedings on behalf of unit
DANZEL,H.D. Tennessee Valley Authority 00/05/19 3pp

4 Inspection reports, IE Bulletins & correspondence

0006130415 Forwards IE Insp Repts 00-093/02-04 & 00-094/02-03 on 000613-0403 AS noncompliance noted
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/03 2pp

--0006130420 IE Insp Repts 00-093/02-04 & 00-094/02-05 on 000613-0403 AS noncompliance noted Major areas inspected concrete placements, AS manual review & inspector followup items
CONTELL,J.P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/03 7pp

0006130439 Forwards IE Bulletin 00-11, "Warning: Halt Design" No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements due to Pipe Support Loads" email
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 00/05/00 2pp

0006130457 Forwards IE Bulletin 00-12, "Decay Heat Removal Dye Operability" No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" email
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 00/05/00 2pp

0006130504 Forwards IE Circular 00-11, "Emergency Diesel Generator Load 241 Circuit Reduced" No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" email
O'REILLY,J.P. Region 2, Atlanta, Office of the Director 00/05/13 2pp

0006130602 Ack receipt of 000606 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 00-050/79-17 & 00-054/79-16
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/21 2pp

--0006130604 Responds to NRC 000610 ltr re violation noted in IE Insp Repts 00-050/79-17 & 00-054/79-16 Corrective actions identified will be met in excess of limits will be removed
HILLB.L.H. Tennessee Valley Authority 00/05/08 4pp

--0006130606 Ack receipt of 000603 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 00-050/79-17 & 00-054/79-16
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/04/29 2pp

--0006130608 Responds to NRC 000625 ltr re violation noted in IE Insp Repts 00-050/79-17 & 00-054/79-16 Corrective actions excess will be met in excess of limits will be removed All details re met under which provided in Noncompliance Report 00-057
HILLB.L.H. Tennessee Valley Authority 00/05/21 1p

0006130616 Responds to 000121 ltr which transmitted IE Bulletin 00-02 Investigations revealed that feedwater spargers or thermal sleeves nfg &/or fabricated by Harvie Engineering Co have not been purchased &/or have not been installed in plants
HILLB.L.H. Tennessee Valley Authority 00/05/25 1p

0006130617 Outlines 000616 Insp of seismic faulting in Unit 1 spray pond Unit 1 was probed w/13 concrete operations on June 20 & Fault 19 A23 faulting must be repaired
MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/05/20 2pp

0006140446 Responds to NRC 000621 ltr re violation noted in IE Insp Repts 00-093/02-07 & 00-094/02-08 Corrective actions planned for unsatisfactory welds re welding flux has been made available to work personnel
HILLB.L.H. Tennessee Valley Authority 00/04/02 3pp

0006150258 Forwards final response to notice of violation described in IE Insp Repts 00-093/02-08 & 00-094/02-07 Corrective actions taken for samples representing safety-related structures placements made 000607-09 have been reviewed
HILLB.L.H. Tennessee Valley Authority 00/04/19 3pp

B Regulatory correspondence, LERs & related correspondence

0006160293 Forwards CTI-Nuclear 000503 Part 21 report re potential failure of McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in stream in various air filtration unit
HEARN,J.C. Chatham Corp. 00/05/08 4pp

DOCKETED ITEMS

263

8004040480 Forwards final deficiency rep't re unacceptable bending of welded stud anchors on embedded plates
NILLB.L.H Tennessee Valley Authority 00/06/02 1p

--8004040480 Final deficiency rep't re unacceptable bending of welded stud anchors on embedded plates Testing program was initiated
Bending of studs has no significant effect on stud capacity
Liste guidelines for max bending of stud anchors
w Tennessee Valley Authority 00/06/02 2pp

8006100408 Forwards first interim deficiency rep't re standby gas treatment sys charcoal adsorber
NILLB.L.H Tennessee Valley Authority 00/06/04 1p

--8006100408 First interim deficiency rep't re standby gas treatment sys charcoal adsorber
Charcoal replacement screens separating from frames due to improper or broken sept welds Vendor, CFI-mechanical investigating problem Final rep't by 800600
w Tennessee Valley Authority 00/06/04 1p

8006100328 Forwards interim deficiency rep't re steam tunnel embedment stiffener plate weld
NILLB.L.H Tennessee Valley Authority 00/06/04 1p

--8006100328 Interim deficiency rep't re failure by Atlas Machine & Iron Works to implement QA procedures for steam tunnel embedment stiffener plate weld
Stiffener plate NCR-10 welded per QA requirements & acid for Atlas QC program contracted
w Tennessee Valley Authority 00/06/04 1p

8004000024 Final Part 2b rep't re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch lines were wgt by
ASME requirements Investigations conducted & closed at 40 limited facilities
SEAW-J.L Chascon Corp., Tube Term Biv 00/06/04 3pp

8004000032 Forwards final deficiency rep't re defective McGraw-Edison temp detection controllers in standby gas treatment sys
NILLB.L.H Tennessee Valley Authority 00/06/03 1p

--8004000032 Final deficiency rep't re defective temp detection controller in standby gas treatment sys
Temp detection controller failed in svc Caused by acid Also solder sealing controls Controllers to be replaced w/certified controllers
w Tennessee Valley Authority 00/06/03 2pp

8004000037 Forwards first interim deficiency rep't re improper insp records
NILLB.L.H Tennessee Valley Authority 00/06/01 1p

--8004000037 First interim deficiency rep't re improper insp records Civil
QC insp program being reviewed to determine changes necessary for compliance w/certified requirements
w Tennessee Valley Authority 00/06/01 1p

8004000081 Final deficiency rep't re incorrect post face on shielded metal arc Atlas Machine & Iron Works fabricated cone representative structures using same welding process as sleeve Restructuring task performed satisfactorily
w Tennessee Valley Authority 00/06/01 2pp

8004000028 Second interim deficiency rep't re defects in Rosemount trip/stop pressure Transmitters shipped continuing Final rep't will be submitted by 800917
NILLB.L.H Tennessee Valley Authority 00/06/02 1p

SECRET DTN-90-095 BLACK FOX STATISTICAL UNIT 1

A Application/construction stage documents & correspondence

8004000110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART,D.G Division of Licensing 00/05/02 13pp

8004000040 Advises that list of walls to be used in case of fire stops & characteristics re flammability & fire reactivity will be provided 1 or subsequent receipt of CP
RUEHCH,D.M Public Service Co. of Oklahoma 00/06/00 2pp

F Security, medical, emergency & fire protection plans

8004000068 Advises that list of walls to be used in case of fire stops & characteristics re flammability & fire reactivity will be provided 1 or subsequent receipt of CP
RUEHCH,D.M Public Service Co. of Oklahoma 00/06/00 2pp

O Advisory Committee on Reactor Safeguards reports & correspondence

8004000072 Forwards ACRS 800504a 1st to JF Ahern re near-term CP application
SCHNEIDER,A Licensing Branch 2 00/05/00 2pp

SECRET DTN-90-097 BLACK FOX STATISTICAL UNIT 2

A Application/construction stage documents & correspondence

8004000110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART,D.G Division of Licensing 00/05/02 13pp

8004000068 Advises that list of walls to be used in case of fire stops & characteristics re flammability & fire reactivity will be provided 1 or subsequent receipt of CP
RUEHCH,D.M Public Service Co. of Oklahoma 00/06/00 2pp

O Advisory Committee on Reactor Safeguards reports & correspondence

8004000072 Forwards ACRS 800504a 1st to JF Ahern re near-term CP application
SCHNEIDER,A Licensing Branch 2 00/05/00 2pp

SECRET DTN-90-041 01-041-005

A Application/construction stage documents & correspondence

8004000070 Forwards addl info re extended operation of LWR core in Skipper Power Station per 800508 request Release of radioactivity continues to be below applicable state as documented in annual routine tests
RICKKIRK,H.D Energy Dept of 00/05/02 13pp

--8004000014 Forwards comments on extension of LWR operations Proposed modification might affect conclusions re areas of proposed augmented inservice insp program reactor vessel irradiation & control rod drive mechanisms
DENTON,H.R Office of Nuclear Reactor Regulation Director 00/04/00 4pp

--8004000118 Forwards ACRS conclusions re extended operation of LWR core W/c and
FRALY,S.F ACRS - Advisory Committee on Reactor Safeguards 00/05/04 1p

SECRET DTN-90-066 YELLOW GREEN NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8004000020 Summary of 800507 meeting re partial refusal of CP Fee Refund
will be made using NRC's average of 6 mo-days
HOLLANDAY,C.J License Fee Management Branch 00/05/01 1p

8004000110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and
EISENHART,D.G Division of Licensing 00/05/02 13pp

8004040081 Notifies unit that NRC will refund portion of sum paid in CP fees Fees paid exceeded cost of processing & issuing
NILLB,L.H License Fee Management Branch 00/05/02 1p

8004040077 Informs that effective 800405 DFC of Nuclear Reactor Regulation was reorganized Hgt of all licensing matters
w respect to facility have been assigned to R Head
Bergstrom,Chert and
TOSCHER,R.L Assistant Director for Licensing 00/06/02 10pp

E NRC Safety Evaluation Report (SER), supp's & correspondence

8004000078 Safety Evaluation re Const of Yellow Creek Nuclear Plant: Units 1 & 2, 1 Suppl 1
w Office of Nuclear Reactor Regulation, Director 00/00-0047 80
78/06/77 3pp Available at DTIC 94 00

DOCKETED ITEMS

D. Adjudicatory correspondence

0036040254 Advises that AH Outturn will no longer appear in proceedings as behalf of civil
0036028 H E Tennessee Valley Authority 00/05/19 3p

Q. Inspection reports, IE Bulletins & correspondence

0004050095 Forwards IE Insp Repts 50-366/80-05 & 50-367/80-06 on
000319-21 No noncompliance noted
0036040 H E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/04/11 3p

--0004050123 IE Insp Repts 50-366/80-04 & 50-367/80-06 on 000319-21 No
noncompliance noted Major areas inspected uncorrected followup
Items: 1. 12CH850 SS-11 slum observations of safety-related work
activities & unaddressed items
0036040 H E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 1036045 H Region 2, Atlanta, Office
of the Director 00/04/11 3p

0036040159 Forwards IE Bulletin 00-15, "Passing Wall Design" No action
on written responses required IE Info Notice 70-25
"Understanding of Structural Elements Due to Pipe Support
Loads" con't
0036040 H E Region 2, Atlanta, Office of the Director 00/05/09
3p

0036040267 Forwards IE Bulletin 00-15, "Decay Heat Removal Dry
Sump" No written responses required IE Info Notice
70-25, "Decay Heat Removal Capability at Davis-Besse
Unit 1 Under an Refueling Mode" con't
0036040 H E Region 2, Atlanta, Office of the Director 00/05/09
3p

0004050034 Forwards IE Circular 00-15, "Emergency Diesel Generator Load
Oil Cooler Failures" No written responses required
0036040 H E Region 2, Atlanta, Office of the Director 00/05/10
3p

0036040032 Ack receipt of 0036028 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-366/80-03 &
50-367/80-02
0036040 H E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/19 2p

--0036040249 Responds to NRC 0036028 ltr re violations noted in IE Insp
Repts 50-366/80-03 & 50-367/80-02 Corrective actions 0036028
& 04201 submits revised Generalization of radiographs
showed only seven welds will require radiographing
0036040 H E Tennessee Valley Authority 00/04/30 3p

--0036040254 Responds to NRC 0036028 ltr re violations noted in IE Insp
Repts 50-366/80-03 & 50-367/80-02 Advises that revised
response to 0036028 ltr will be submitted by 0036028
0036040 H E Tennessee Valley Authority 00/04/21 1p

0036170740 Ack receipt of 0036017 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-366/80-07 &
50-367/80-07
0036040 H E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/05/02 2p

--0036170754 Responds to NRC 0036017 ltr re violations noted in IE Insp
Repts 50-366/80-07 & 50-367/80-07 Corrective actions purge
oil blower filters & welded valve claimed
0036040 H E Tennessee Valley Authority 00/05/19 3p

--0036170751 Forwards IE Insp Repts 50-366/80-07 & 50-367/80-07 on
0036017-24 & notices of violation
0036040 H E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 00/04/24 2p

--0036170760 Notice of violation from Insp on 0036017-24
* Region 2, Atlanta, Office of the Director 00/04/23 1p

--0036170760 IE Insp Repts 50-366/80-07 & 50-367/80-07 on 0036017-24
Noncompliance noted records on Four A1-A11 test record
water contents incompatible with recorded slump test data
Records for Four A1-A11 unreadable
0036040 H E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 0036017 H Region 2, Atlanta, Office of the Director
00/04/23 0p

0036040360 Forwards response to IE Bulletin 00-05 re vacuum conditions
resulting in damage to holding tanks Presta protection for
refueling water storage tank at Sequoyah & Unit 1 are
provided by redundant heaters & bank insulation
0036040 H E Tennessee Valley Authority 00/05/09 0p

0004070540 Responds to IE Insp Repts 50-366/80-03 & 50-367/80-03
re failure to establish adequate measures to control
radiography Radiography of welds scheduled for completion
in 000760
0036040 H E Tennessee Valley Authority 00/05/10 1p

W. Reportable occurrences, LERs & related correspondence

0004080052 Forwards First interim deficiency report re placement &
condition of concrete pour 40-01
0036040 H E Tennessee Valley Authority 00/05/27 1p

--0004080054 First interim deficiency report re placement & condition
of concrete pour 40-01 Concrete placement is being evaluated
for acceptability w/FC-2 requirements Noncompliance item
determined not acceptable
* Tennessee Valley Authority 00/05/27 1p

0036180210 Forwards First interim deficiency report re Cast On Audit
VC-740-05 test report will be submitted by 000710
0036040 H E Tennessee Valley Authority 00/05/27 1p

--0036180208 First interim deficiency report re Cast On Audit VC-740-05
On 000025 test report placed & completed per conch spec No
on performed inspections conducted in requirements of
General Cast Spec 0-2
* Tennessee Valley Authority 00/05/27 1p

0004080394 Final Part 21 report re mixed heat of steel supplied by MB
Mixed steel which 4-inch elbows & 2-inch tees were mfg to
ASTM requirements Investigations conducted & closed at
40-1040 Facilities
0036040 H E Construction Corp., Tube Towns Div 00/05/04 3p

0004080075 Forwards final deficiency report re defective concrete pour
in auxiliary Sdg
0036040 H E Tennessee Valley Authority 00/06/13 1p

--0004080336 Final deficiency report re failure of concrete pour A3-73 to
achieve initial set in normal time Apparently caused by
abnormal amount of air volume Defective concrete replaced
Outside drawings 0036017-28 series will be revised
* Tennessee Valley Authority 00/06/13 3p

DOCKET ETH-NO-167 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A. Application/Construction stage documents & correspondence

0036090260 Summary of 0036057 meeting re partial refund of CP Fee Refund
will be made using ASLR average of 6 non-firm
0036040 H E License Fee Management Branch 00/05/19 1p

0036035110 Advises I&R & PWR applicants of NRC decision to modify
implementation plan presented in Section 4 of NUREG-0577 re
adequacy of applicable support structures General operating
reactor review procedure & acceptance criteria met
0036040 H E Division of Licensing 00/05/20 13p

0036035110 Notices that NRC will refund portion of sum paid in
CP Fee Pass paid exceeded cost of processing & issuing
0036040 H E License Fee Management Branch 00/05/23 1p

0036040077 Informs that effective 0036028, D.C. of Nuclear Reactor
Regulation was reorganized Mgt of all licensing matters
w/ respect to facilities have been assigned to H Head
Regulation chart NRC
0036040 H E Assistant Director for Licensing 00/05/10 10p

E. NRC Safety Evaluation Report (SER), supp & correspondence

0036036895 "Safety Evaluation re Genet of Yellow Creek Nuclear Plant
Units 1 & 2" Suppl 1
* Office of Nuclear Reactor Regulation, Director 0036036895 H
76/06/27 2p Available at DTIC 40 00

D. Adjudicatory correspondence

0036040254 Advises that AH Outturn will no longer appear in
proceedings as behalf of civil
0036028 H E Tennessee Valley Authority 00/05/19 3p

DOCKETED ITEMS

265

6 Inspection reports, IE Bulletins & correspondence

8004050019 Forwards IE Insp Repts 80-566/03-04 & 80-567/00-04 on 800319-21 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/15 2pp

--8004050019 IE Insp Repts 80-566/03-04 & 80-567/00-04 on 800319-21 No noncompliance noted Major areas inspected inspection followup items, IECRHS 2014, item observation of safety-related work activities & maintenance items
CANTRELL, J P Region 2, Atlanta, Reactor Construction & Engineering Support Branch THORNS, R Region 2, Atlanta, Office of the Director 80/04/15 2pp

8004050019 Forwards IE Bulletin 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No action or written response required IE Info Notice 79-56
Overloading of Structural Elements Due to Pipe Support Loads" ems
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp

8004040027 Forwards IE Bulletin 80-12, "Darcy Heat Removal Wgs Operability" No written response required IE Info Notice 80-20, "Loss of Darcy Heat Removal Capability at Swirl-Drum Unit 3 While in Refueling Mode" ems
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09 2pp

8004120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 2pp

8004040022 Ack receipt of 800328 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/03-03 & 80-567/00-03
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/19 2pp

--8004040024 Responds to NRC 800320 ltr re violations noted in IE Insp Repts 80-566/03-03 & 80-567/00-03 Corrective actions 800404
& 8004040024 Responds to re-evaluation of radiographs showed only seven welds will require reregraphing
HILLIS, L N Tennessee Valley Authority 80/04/20 4pp

--8004040034 Responds to NRC 800328 ltr re violations noted in IE Insp Repts 80-566/03-03 & 80-567/00-03 Advice that revised response to 800409 ltr will be submitted by 800408
HILLIS, L N Tennessee Valley Authority 80/04/21 1p

8004170740 Ack receipt of 800519 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/00-07 & 80-567/00-07
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/22 2pp

--8004170740 Responds to NRC 800426 ltr re violations noted in IE Insp Repts 80-566/00-07 & 80-567/00-07 Corrective actions pump air blower filters & isolated valve cleaned
HILLIS, L N Tennessee Valley Authority 80/05/19 3pp

--8004170750 Forwards IE Insp Repts 80-566/06-07 & 80-567/00-07 on 800405-04 Notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/24 2pp

--8004170757 Notice of violation from Insp on 800401-04
= Region 2, Atlanta, Office of the Director 80/04/22 1p

--8004170748 IE Insp Repts 80-566/00-07 & 80-567/00-07 on 800401-04 Noncompliance noted records on Four All-1 show recorded water contents unacceptable unwrapped vimp test data Records for Four A-WP unreadable
CANTRELL, J P Region 2, Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J R Region 2, Atlanta, Office of the Director 80/04/23 2pp

8004060030 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequoyia & Watts Bar is provided by redundant heaters & tank insulation
HILLIS, L N Tennessee Valley Authority 80/04/09 4pp

8004170540 Responds to IE Insp Repts 80-566/03-03 & 80-567/00-03 re failure to establish edgewise measure to control radiography Radiography of welds scheduled for completion by 800701
HILLIS, L N Tennessee Valley Authority 80/06/19 1p

8 Reportable occurrences, LERs & related correspondence

8004050019 Forwards First interim deficiency report re placement & connection of concrete pour 80-01
HILLIS, L N Tennessee Valley Authority 80/05/27 1p

--8004050019 First interim deficiency report re placement & connection of concrete pour 80-01 Concrete placement is being evaluated per acceptance criteria w/25% requirements however increase determined not acceptable
= Tennessee Valley Authority 80/05/27 1p

8004110274 Forwards First interim deficiency report re Const QA Audit VC-88-05 Mail input will be submitted by 800710
HILLIS, L N Tennessee Valley Authority 80/07/27 1p

--8004110274 First interim deficiency report re Const QA Audit VC-88-05 Mail input will be submitted by 800710
= QA performed inspections instructed in requirements of General Const Dept 0-2
= Tennessee Valley Authority 80/08/27 1p

8004200024 Final Part 21 report re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AS20MPD requirement Investigations conducted & closed at 40 limited facilities
SEAY, J L Chemtron Corp., Tube Turns Div 80/06/06 3pp

DOCKET 87N-80-573 RE-RD, UNIT 2

8 Reportable occurrences, LERs & related correspondence

8004050024 PWD-40-037 on 800519 Mount St Helen erupted Unit 2 has approx 120-inch of ash on ground at 800519
Filtration ops operability confirmed Monitoring to detect additional ash in gas samples underway
800405-01 Region 3, San Francisco, Office of the Director 80/05/19 2pp

DOCKET 87N-80-574 TENDON NUCLEAR POWER PROJECT

8 Reportable occurrences, LERs & related correspondence

8004170752 Confirms T. Rothchild 800418 letter w/IE Cowan Requests
Ltr of previous vessel steam generator control rod & coolant pump alignment re NHTS/CSO 800418 apparatus to action for stay pending appeal Certificate of Rev ems
800418-01 Office of the General Counsel 80/04/22 4pp

8004200024 Brief on appeal before US Court of Appeals, DC Circuit, from Commission 800350A orders Case must be remanded to examine US common defense & security under Atomic Energy Act/Muclear Non-Proliferation Act & RSCA Certificate of Rev ems
800705-01 Center for Law & Social Policy CURTIS-C E National Resources Defense Council CURTIS-C E Philippines Movement for Environmental Protection 80/06/10 9pp

DOCKET 87N-80-591 E99AB, EDA90C 800510C

6 Inspection reports, IE Bulletins & correspondence

8004120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 2pp

DOCKET 87N-80-592 PALD VERSE NUCLEAR STATION, UNIT 2

8 Reportable occurrences, LERs & related correspondence

8004200024 Final Part 21 report re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AS20MPD requirement Investigations conducted & closed at 40 limited facilities
SEAY, J L Chemtron Corp., Tube Turns Div 80/06/06 3pp

DOCKET 87N-80-593 PALD VERSE NUCLEAR STATION, UNIT 5

8 Reportable occurrences, LERs & related correspondence

8004200024 Final Part 21 report re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AS20MPD requirement Investigations conducted & closed at 40 limited facilities
SEAY, J L Chemtron Corp., Tube Turns Div 80/06/06 3pp

DOCKETED ITEMS

267

- 0004172029 IE Insp Rept 70-0029/79-10 on 791007 & 11-14 Noncompliance noted arithmetic calculations of filter efficiency of air cleaning system found to be in error in more than 50% of tests reviewed
GOLDMAN, M. J. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 00/04/21 10p
- 0004172029 Responds to NRC 000421 ltr re deviation noted in IE Insp Rept 70-0029/79-10 corrective actions written procedures for completing DCP tests have been revised to clarify & simplify arithmetic manipulations
HILL, E. H. Savannah International Corp 00/05/13 1p
- 0004172020 Ack receipt of 000513 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 70-0029/79-10
GOLDMAN, M. J. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 00/05/21 1p
- DOCKET 70-0027 WABCOON & HILCO CO.
- 0004200120 Submits add'l info to 000130 ltr Evaluation of core storage facility has been reviewed & approved Nuclear Safety calculation performed using WEND & Morgan Hansen-Mech core section library of effects of Section III
GOLDMAN, M. J. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/03/27 1p
- 0004200120 Application for amend to provide for proposed revisions to plant liquid effluent lines Change reviewed & approved & involving piping revisions & liquid effluent U content measurement per & revised license pages encl.
GOLDMAN, M. J. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/03/25 10p
- 0005200132 Forwards certificate of assurance of vendor ability to cover costs of decommissioning all nuclear facilities
JORDAN, L. V. Babcock & Wilcox Co 00/05/26 3pp
- 0004200272 Forwards certificate to company lenders that all restrictive covenants contained in note agreements have been met as assurance of ability to cover decommissioning costs
JORDAN, L. V. Babcock & Wilcox Co 00/05/26 3pp
- 0005200202 Application for Amend to License SRM-42 requesting exception to 10CFR70.51 to delay completion of calculation of associated limit of 100% of RUP & fissile isotope per U contained in fuel in process 000401-04 M/A encl amend fee
GOLDMAN, M. J. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/05/21 1p
- 0004180616 Advises that JP Clark has been appointed vice president replacing JP Ewing who transferred to corporate office in New Orleans, LA
GOLDMAN, M. J. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/04/28 1p
- 0004040429 Submits review of 760405 license amend application, 760703 revision & 000130 & 0387 supply Adequate safety is provided in event of addition to north end of day 44 & storage of complete power assemblies in addition
GOLDMAN, M. J. METLACH, N. Uranium Fuel Licensing Branch 00/04/29 3pp
- 0004180501 Requests 30-day time limit exception for shipment NAB-PCR-47 to complete all measurements of well test U analysis of unfiltered samples will be performed when equipment available Forwards administrative amend fee M/A encl
GOLDMAN, M. J. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/05/08 1p
- 0004050299 Forwards IE Insp Rept 70-0027/80-06 on 000484-49 Cover sheet only encl Rebuttal withheld (ref 10CFR2 790)
NEALE, M. E. Region 3, Chicago, Safeguards Branch 00/06/09 1p
- 0004050410 IE Insp Rept 70-0027/80-06 on 000484-29 Re noncompliance noted Details withheld (ref 10CFR2 790)
HIND, J. A. Region 3, Chicago, Safeguards Branch FINLEY, A. O. PATTERSON, J. P. Region 3, Chicago, Office of the Director 00/05/29 1p
- 0004050501 Notifies vendor that License SRM-42 is amended to authorize use of flowmeters & proportional arithmetic samplers to measure U content of liquid effluents as they are discharged from retention tanks to liquid waste treatment facility
PAGE, E. Q. Uranium Fuel Licensing Branch 00/05/20 1p
- 0004050507 Safety evaluation of 000518 license amend application requesting authorization to use flowmeters & proportional arithmetic samplers to measure U content of liquid effluents, Controls & procedures are adequate to protect public safety.
METLACH, N. ENCL. M. T. Uranium Fuel Licensing Branch 00/05/20 2pp
- 0004050599 Advises that review of Amendment expenditures required for review of amend #9 to License 000442 was less than submitted
GOLDMAN, M. J. Region 3, San Francisco, Fuel Facility & Materials Safety Branch 00/05/27 1p
- 0004050604 Ack receipt of 000330 ltr assuring that SRM has sufficient capital to cover decommissioning costs
PAGE, E. Q. Uranium Recovery Licensing Branch 00/06/02 1p
- 0004050620 Submits contract costs incurred & worksheets appended in revising 000518 application for amend & 000330 revision to License SRM-42
METLACH, N. Uranium Recovery Licensing Branch 00/06/04 1p
- 0005200519 Ack receipt of 000521 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/79-58
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/06/12 1p
- 0004050524 Responds to NRC 000536 ltr re violations noted in IE Insp Rept 70-0027/79-10 Corrective actions withheld (ref 10CFR2 790)
O'REILLY, J. P. Babcock & Wilcox Co., Naval Nuclear Fuel Div 00/05/21 1p
- 0004050532 Forwards IE Insp Rept 70-0027/79-18 on 791013-000104 & notices of violation Encls withheld (ref 10CFR2 790)
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/05/26 1p
- DOCKET 70-0020 TEXAS INSTRUMENTS, INC.
- 0004050549 Forwards Figures 2-1 & 2-2 of plan for protection of nuclear facilities & materials inadvertently omitted from 000518 ltr. Figures depict actual physical structure & security organization.
ELTIS, R. Texas Instruments, Inc 00/04/08 3pp
- 0004050627 Forwards nonproprietary version of IE Insp Rept 70-0023/80-04 Re noncompliance noted Details withheld (ref 10CFR2 790)
HARTMAN, G. Region 1, Philadelphia, Safeguards Branch 00/04/28 2pp
- 0004050627 Nonproprietary version of IE Insp Rept 70-0023/80-04 on 000310-01 Re noncompliance noted Major areas inspected security plan & organizational physical barriers, access controls, inventory & locks Details withheld (ref 10CFR2 790)
LAUREN, H. J. Region 1, Philadelphia, Office of the Director 00/04/23 1p
- 0004050627 Forwards IE Insp Rept 70-0023/80-03 on 000403-10, Re noncompliance noted Cover sheet only encl Rebuttal withheld (ref 10CFR2 790)
HARTMAN, G. Region 1, Philadelphia, Safeguards Branch 00/04/29 2pp
- 0004050536 Nonproprietary version of IE Insp Rept 70-0023/80-05 on 000310-02 Re noncompliance noted Major areas inspected physical inventory reconciliation, records & photographic & recording Details withheld (ref 10CFR2 790)
LAUREN, H. J. Region 1, Philadelphia, Office of the Director 00/04/23 1p
- 0004050627 Ack receipt of 000417 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0023/80-03
SHITH, G. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/30 1p
- 0004050627 Responds to NRC 000402 ltr re violations noted in IE Insp Rept 70-0023/80-03 Corrective actions personnel instructed to complete all record items for each occasion of respirator use
SCHWENK, F. E. Texas Instruments, Inc 00/04/17 1p
- 0004050627 Forwards IE Insp Rept 70-0023/80-03 on 000312-14 & notice of violation
HARTMAN, G. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 00/04/03 2pp

- 800425004 Notice of violation from Insp. at 800312-14
+ Region 1, Philadelphia, Office of the Director 80/04/02 1p
- 800405008 IE Insp Rept 75-0032/80-03 on 800312-14 Noncompliance noted failure to maintain records on respirator assignments & leak tests
NUPP, P Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
CLINTON, P Region 1, Philadelphia, Office of the Director 80/04/02 3pp
- 800430021 Forwarded updated sections of NFPA project emergency plan w/o encl
SCHWENK, R Texas Instruments, Inc 80/05/21 3pp
- DOCKET 70-0026 COMBUSTION ENGINEERING, INC
- 800423006 Advances of completion of hydrologic & hydraulic analysis for Joachim Creek in Jefferson County, MD. Hydrology & Frequency & Flood Elevation determined to be about 425 3-Ft. not study will be available shortly after 800318
CORBIN, M D. Army, Dept of Corps of Engineers 80/03/11 1p
- 800419047 Forwarded Penn. OSH Annual Rept 1979 w/o encl
LIGHTENHIZER, R Combustion Engineering, Inc 80/04/11 1p
- 800420012 Forwarded final draft of Clark Dist. Engineers "Special Study for Joachim Creek, Jefferson County, MD."
CLINTON, M D. Army, Dept of Corps of Engineers 80/04/18 1p
- 800420017 Final draft of "Special Study for Joachim Creek, Jefferson County, MD."
+ Clark Dist. Engineers 80/03/31 1app
- 800440082 Requests submission of major safeguards amended fee re 800313
Unrealistic of physical protection of the Plan classified as requiring major amend to License SMR-02
MIDG, D License Fee Management Branch 80/04/20 1p
- DOCKET 70-0049 HANSHUCHETTE INST OF TECHNOLOGY
- 800420020 Forwarded table listing all licenses authorizing SMR form, location, type of mail, authorized amounts & 800321 inventory
Table withheld (ref 10CFR 7901)
CLARK, L. Massachusetts Institute of Technology 80/04/20 1p
- DOCKET 70-0049 HANSHUCHETTE INST OF TECHNOLOGY
- 800420020 Forwarded table listing all licenses authorizing SMR form, location, type of mail, authorized amounts & 800321 inventory
Table withheld (ref 10CFR 7901)
CLARK, L. Massachusetts Institute of Technology 80/04/20 1p
- DOCKET 70-0124 TELEPHONE INSTRUMENTS
- 800420014 Forwarded administrative fee for amend to License SMR-107 for exemption to crystalline alarm requirement
BLANCH, B Telephone Instruments 80/05/20 1p
- DOCKET 70-0125 BARBER & WILCOX CO
- 800418044 Forwarded revisions to Spec 1-4 & Table 5 of Spec 1-5 of License SMR-145 re operations organization changes
AUSTIN, M A Barber & Wilcox Co 80/03/20 13pp
- 800418039 Forwarded approved organizational change evaluation w/complete description Change will maintain & strengthen technical control support of product lines
AUSTIN, M A Barber & Wilcox Co 80/03/20 1app
- 800418033 Forwarded administrative amend fee re SMR 800380 ltr to RB Page concerning technical control dept reorganization
AUSTIN, M A Barber & Wilcox Co 80/03/20 1p
- 800420010 Notification of current project being undertaken at Nuclear Metals & Hfg Div Project involves dismantling of blue bldg & pond used for in-transit placement of trailers, uranium salt, will be required to ensure timely & efficient operation
AUSTIN, M A Barber & Wilcox Co, Nuclear Material Div 80/03/26 3pp
- 800420007 Forwarded certificate to company lenders that all restrictive covenants contained in 1938 agreements have been met as assurance of ability to cover decontamination costs
JORDAN, L V Barber & Wilcox Co 80/03/28 2pp
- 800420002 Requested amend of Tech Spec 1 B 3 (A) per encl revised page re WILCOX 800320 telcon w/DO Defilipis Amend will make contamination survey frequency consistent w/other applicable survey frequencies
AUSTIN, M A Barber & Wilcox Co 80/03/31 2pp
- 800420034 Notification of personnel change within SMR Effective 800406, CJ Garach will replace JO Garach as General Manager of Nuclear Metals & Hfg Div
AUSTIN, M A Barber & Wilcox Co, Nuclear Material Div 80/04/06 1p
- 800440024 Submita costs for review of 79081A & 27 applications to amend License SMR-145
NIXON, W A Uranium Fuel Licensing Branch 80/04/03 1p
- 800440045 Forwarded IE Insp Repts 70-0125/80-07 & 70-0344/80-04 on 800304-29 re noncompliance noted
MARTIN, W D Region 1, Philadelphia, Safeguards Branch 80/04/08 2pp
- 800440029 IE Insp Repts 70-0125/80-07 & 70-0344/80-04 on 800304-29 re noncompliance noted Rept areas inspected met control, physical security & health & industrial safety Portals withheld (ref 10CFR 7901)
CLINTON, M Region 1, Philadelphia, Safeguards Branch
MIDG, M L Region 1, Philadelphia, Office of the Director 80/04/07 3pp
- 800420090 Forwarded application for amend of License SMR-145, revising Spec 3 D 5 to assure that employees on extended absences receive required monthly workplace meeting info
AUSTIN, M A Barber & Wilcox Co, Nuclear Material Div 80/04/14 1p
- 800420093 Application for amend of License SMR-145, revising Spec 1 D 5 to assure that employees on extended absences receive required monthly workplace meeting info
+ Barber & Wilcox Co, Nuclear Material Div 80/04/14 2pp
- 800417028 Inform that RV Carlson will replace EH Benson as manager of PA operations
AUSTIN, M A Barber & Wilcox Co, Nuclear Material Div 80/05/01 1p
- 800440015 Forwarded corrected Page 3 Per IE Insp Repts 70-0125/79-09 & 70-0344/79-12 Unrevised form 70-044/79-04-03, materially closed out, will be addressed in IE Insp Repts 70-0125/80-10 & 70-0044/80-12 Encl withheld (ref 10CFR 7901)
MIDG, M L Region 1, Philadelphia, Safeguards Branch 80/05/08 1p
- 800417012 Act result of 800328 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0125/80-04
CLINTON, M Region 1, Philadelphia, Office of the Director 80/05/22 1p
- 800417017 Response to NRC 800305 ltr re violations noted in IE Insp Rept 70-0125/80-04 Corrective actions all personally issued, none are being inspected annually by lead P/S test chamber operator
MARTIN, M A Barber & Wilcox Co, Nuclear Material Div 80/05/28 2pp
- 800417020 Forwarded IE Insp Rept 70-0125/80-04 on 800123-25 & notice of violation
MIDG, M L Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/03 2pp
- 800420014 Notice of violation from Insp. at 800123-25
+ Region 1, Philadelphia, Office of the Director 80/05/25 2pp
- 800420010 IE Insp Rept 70-0125/80-04 on 800123-25 Noncompliance noted four personnel safety measures issued w/o being inspected or documented
CLINTON, P Region 1, Philadelphia, Office of the Director
CLINTON, M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/20 7pp
- 800420006 Advances that no add'l fee is required for review & approval of minor safety w/revise amend
HILLER, W D License Fee Management Branch 80/04/05 1p

DOCKETED ITEMS

269

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC

0004200598 Application for amend of license RM-124 revising exception items of the Condition 2 of the Amended HRP-1 to include strag generated from cleanup & equipment made 7/12/13-800321 & from cleanup of U baffle/uride line.800321-5009 Fee sec] HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/14 App

0004190203 Forwards Revision 12 to fundamental nuclear matl control plan.see 1990 Changes are upgrading mode which do not decrease effectiveness of control plan Encl withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/14 App

0004060236 Advises that 60-day extension requested on 000420 to complete procedure for evaluation of shipper/receiver differences is not granted. It is sufficient time for compliance. This extension is acceptable. HENLEY,K D Region 2, Atlanta, Safeguards Branch 05/05/08 App

0004120082 Request amend of license RM-124 Proprietary info withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/05/04 App

0004170250 Application for amend of license RM-124 as described in Encl. Fee and Encl. describing amend request withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/05/05 App

0004120093 Ack receipt of IE Insp Rept 70-0143/05-10 456 000426 No proprietary info HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/05/12 App

0004200259 Forwards IE Insp Rept 70-0143/05-10 on 000251-0410 No noncompliance noted Details withheld (ref 10CFR2 7501) HENLEY,K D Region 2, Atlanta, Safeguards Branch 05/05/12 App

0004060236 IE Insp Rept 70-0143/05-10 on 000251-0410 No noncompliance noted Major areas inspected under concerns: radiation protection, burial shipments & U bldg in sited areas. Safeguards & security measures withheld (ref 10CFR2 7501) LECT, T ; T005, D A Region 2, Atlanta, Office of the Director OILLEGISL, P P Region 2, Atlanta, Safeguards Branch 05/04/24 App

0004060236 Advises that License RM-124 is amended, modifying Conditions 1a, 17, 20 & 22 adding Conditions 6b-1c, to assure that concentrations of radioactivity both inside & outside plant are as low as reasonably achievable. P052, H D Uranium Fuel Licensing Branch 05/05/15 App

0004160234 Forwards App 9 to 000595 Fundamental nuclear matl control plan Changes are upgrading mode which do not decrease effectiveness of plan Encl withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/05/15 App

0004160236 Forwards Supplemental IE Insp Rept 70-0143/05-10 on 000317-0424 No noncompliance noted HENLEY,K D Region 2, Atlanta, Safeguards Branch 05/05/27 App

0004060236 Supplemental IE Insp Rept 70-0143/05-10 on 000317-0424 No noncompliance noted Major areas inspected program for nuclear matl control & specific license conditions details withheld (ref 10CFR2 7501) CLAY, E L ; OILLEGISL, P P Region 2, Atlanta, Safeguards Branch 05/05/23 App

0004170031 Revises License Condition 2 i of Amended HRP-1 to license RM-124, effective immediately based on NRC review, revised Section 1 a & new App 9 to fundamental nuclear matl control plan are both acceptable. PARTLCK, J D Material Control Licensing Branch 05/05/28 App

0004120295 Forwards Revision 1a to fundamental nuclear matl control plan 454 May 1980 Changes consist of upgrading mode Revision withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/02 App

0004200303 Forwards revisions to fundamental nuclear matl control plan Revisions withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/02 App

0004200304 Forwards response to NRC 000318 ltr re violations noted in IE Insp Rept 70-0143/05-12 Encl withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/03 App

0004200302 Forwards IE Insp Rept 70-0143/05-10 on 000318-1a No noncompliance noted HENLEY,K D Region 2, Atlanta, Safeguards Branch 05/04/04 App

0004200303 IE Insp Rept 70-0143/05-10 on 000318-1a No noncompliance noted Major areas inspected containment control program Details withheld (ref 10CFR2 7501) OILLEGISL, P P Region 2, Atlanta, Safeguards Branch BATES, J W Region 2, Atlanta, Office of the Director 05/04/03 App

0004200303 Forwards request for add info in order to complete review of 000318 fundamental nuclear matl control plan, Section A 0 Encl withheld (ref 10CFR2 7501) PARTLCK, J D Material Control Licensing Branch 05/04/10 App

0004190287 Forwards response to NRC 000304 ltr stating evaluation & significant differences identified in IE Insp Rept 70-0143/05-09 Response withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/11 App

0004190288 Forwards biweekly status rpt for completing installation on add liquid storage capacity for waste water treatment facility Ltr withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co) 05/04/11 App

0004190480 Application for amend to license RM-124 Administrative amend Fee and Encl withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/04/12 App

0004190779 Forwards proprietary version of June 1980 App C to fundamental nuclear matl control plan App consists of upgrading mode info withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/04/12 App

0004200383 Responds to appeal re denial of FDSR request for documents re licensing of NRC driven nuclear fuel facility Denial appeal re App 3 Documents 2, 4 & 7 (ref FDSR Exemption 3) Grants appeal for App 3 Documents 1, 3, 5 & 6 CHEN, R J Office of the Secretary of the Commission, 05/04/16 App

0004200408 Nonproprietary memo recommending that facility license be modified to preclude possession of significant quantities of high enriched U Levels considerations in reviewing paper info withheld (ref FDSR Exemption 3) THORPSON, H L Commission 7/9/12/15 App

0004200412 Nonproprietary memo recommending that facility be allowed to operate under NRC licensing control w/10 limit of 1% throughout NRC work increase physical security as proposed in IECT-79-650 info withheld (ref FDSR Exemption 3) HENLEY,K D Commission 05/01/09 App

0004200424 Nonproprietary memo agreeing w/050109 memo Commission position on facility sub 1 to listed requirements Commission decision should be rendered immediately. HENLEY,K D Commission 05/01/11 App

0004200423 Considers w/summary points in 000109 memo recommending Commission position on facility sub 1 to listed requirements Commission decision should be rendered immediately. HENLEY,K D Commission 05/01/11 App

0004060201 Forwards matl balances for inventory period 7/12/04-8/05/07 For U enriched U Encl withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/04/17 App

0004200403 Ack receipt of IE Insp Rept 70-0143/05-10 No proprietary info PARTLCK, J D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/04/17 App

0004200423 Forwards Revision 1a to fundamental nuclear matl control plan Revision withheld (ref 10CFR2 7501) HENLEY,K D Nuclear Fuel Services, Inc (subs of Setty Oil Co.) 05/04/16 App

DOCKETED ITEMS

DOCKET 70-0194 HARRACHRETH INST EP TECHNOLOGY

0004030290 Forward table listing all licenses authorizing ENR form, location, type of authorized amounts & 000301 inventory table withheld (ref 10CFR 790)
 OLARIC, Massachusetts Institute of Technology 05/06/83 1p

DOCKET 70-0267 NUCLEAR SCIENCE & TECHNOLOGY FACILITY AT SUNY

0004030270 Requests NRC action on 760716 application for revision of license SMN-270 & SMN-703
 HERRICK, G New York, State Univ of, Buffalo 05/05/82 1p

--0004030679 Requests current status of 760816 application for revision of license SMN-270 & SMN-703
 HERRICK, G New York, State Univ of, Buffalo 08/07/82 1p

DOCKET 70-0344 PARKS TOWNSHIP SITE, BARCOCK & WILCOX CO

0004030199 Forward revisions to Demonstration 11-D of License SMN-414, changing page numbers Pages were inadvertently misnumbered when originally submitted for review & approval
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div. 05/03/80 1p

0004030156 Forward change in organization & evaluation Change will strengthen technical control support of product lines.
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div. 05/03/80 1p

0004030088 Confirms 000310 & 24 letters & Formletters BSW understanding of Condition 12 of License SMN-414 re intended phaseout of Pu facility operations Data reduction equipment may be waived following review of first qtr data
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div 05/03/80 1p

0004030089 Notifies of intention to phase down Pu facility activities at site An a retrofit physical security upgrades required by applicable regulations will not be implemented
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div 05/03/80 1p

0004030072 Forward certificate to company lenders that all restrictive covenants contained in note agreements have been met as assurance of ability to cover subordination costs
 JOHNSON, L V Barcock & Wilcox Co 05/03/80 2pp

0004030054 Notifies of personnel change within BSW Effective 000401, C.J. Barack will resign as Director as General Manager of Nuclear Metals & Hfg Div
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div 05/04/80 1p

0004030445 Forward 1E Insp Repts 70-0135/80-07 & 70-0344/80-04 re 000324-29 No noncompliance noted
 MARTIN, M A Region I, Philadelphia, Safeguards Branch 05/04/80 2pp

--0004030270 1E Insp Repts 70-0135/80-07 & 70-0344/80-04 re 000324-29 No noncompliance noted Major areas inspected mail controls, physical security & health & industrial safety Permits withheld (ref 10CFR 790)
 JOHNSON, L V Region I, Philadelphia, Safeguards Branch 05/04/80 1p
 MARTIN, M A Region I, Philadelphia, Office of the Director 05/04/80 1p

0004030421 Forward add info re mini-plan for storage/tagging area at site. In response to NRC 0003410 request Encl withheld (ref 10CFR 790)
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div. 05/04/80 1p

0004030111 Application for amend to License SMN-414 per W Buchhardt 000416 letter w/PJ DePillips Amend assumes required training to all employees & does not decrease effectiveness of training program
 MARTIN, M A Barcock & Wilcox Co 05/04/80 1p

0004030199 Informs that RV Carlson will replace EH Eason as manager of PA operations
 MARTIN, M A Barcock & Wilcox Co Nuclear Material Div 05/05/80 1p

0004030199 Forward corrected Page 2 for 1E Insp Repts 70-0135/79-09 & 70-0344/79-10 Unresolved Item 70-044/79-04-03 mistakenly listed sub-111 addressed in 1E Insp Repts 70-0135/80-12 & 70-0344/80-12 Encl withheld (ref 10CFR 790)
 MARTIN, M A Region I, Philadelphia, Safeguards Branch 05/05/80 1p

0004030023 Forward revision to Fundamental nuclear mail control plan Revision withheld (ref 10CFR 790)
 MARTIN, M A Barcock & Wilcox Co 05/05/80 1p

0004030140 Advice of refusal following submittal of Fee for CL Amends & C
 MILLER, W D License Fee Management Branch 05/06/80 1p

0004030233 Advice of revision to Safeguards Amend APP-1 to License SMN-414, effective immediately Adds new License Condition 2 & 3 Waste storage plan submitted by licensee acceptable
 PARTLOU, J D Material Control Licensing Branch 05/04/80 1p

DOCKET 70-0371 UNITED NUCLEAR CORP

0004030158 Forward revised emergency plan & comments
 KIRK, W F United Nuclear Corp., Naval Products Div 05/02/80 11pp

--0004030158 Revised emergency plan
 United Nuclear Corp., Naval Products Div 05/01/80 8pp

0004030204 Forward 1E Insp Repts 70-0371/80-03 re 000314-29 No noncompliance noted
 MARTIN, M A Region I, Philadelphia, Safeguards Branch 05/04/80 1p

--0004030202 1E Insp Repts 70-0371/80-03 re 000314-29 No noncompliance noted Major areas inspected physical inventory procedures Details withheld (ref 10CFR 790)
 JOHNSON, L V Region I, Philadelphia, Safeguards Branch 05/04/80 1p
 ZIEGLER, H Region I, Philadelphia, Office of the Director 05/04/80 1p

0004030111 Forward 1E Insp Repts 70-0371/80-04 re 000408-03 No noncompliance noted
 MARTIN, M A Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/04/80 2pp

--0004030111 1E Insp Repts 70-0371/80-04 re 000408-03 No noncompliance noted Major areas inspected License program for packaging low level waste for transport & burial
 JOHNSON, L V Region I, Philadelphia, Office of the Director 05/04/80 1p
 ZIEGLER, H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/04/80 1p

0004030229 Expresses concern re potential adverse impact on facility safeguards program of licensee decision to terminate recovery of high enriched U Excessive scrap not conducive to effective safeguards may accumulate
 PARTLOU, J D Material Control Licensing Branch 05/04/80 1p

DOCKET 70-0398 COMMERCE, DEPT OF

0004030425 Ack receipt of 000422 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 70-0398/80-02
 MARTIN, M A Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/05/80 1p

--0004030429 Response to NRC 000327 ltr re violations noted in 1E Insp Repts 70-0398/80-02 Corrective actions large quantity radioactive waste shipments have been terminated Effective 000328
 BELL, P E Commerce, Dept of, National Bureau of Standards 05/04/80 2pp

--0004030424 Forward 1E Insp Repts 70-0398/80-02 re 000327-29 & notice of violation
 MARTIN, M A Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/05/80 2pp

--0004030424 Notice of violation from Insp re 000327-29
 Region I, Philadelphia, Office of the Director 05/03/80 1p

--0004030424 1E Insp Repts 70-0398/80-02 re 000327-29 Noncompliance noted. GA program for shipping packages not submitted to NRC & approx 27 shipments of fissile radioactive waste made
 79010-1210
 MARTIN, M A Region I, Philadelphia, Office of the Director 05/05/80 1p
 ZIEGLER, H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 05/05/80 1p

DOCKETED ITEMS

273

--0006200172 "Demonstration & Conditions for License SMH-778," Amend G, Revision 4, Pages A-41 & A-42 re fuel rod demonstration-shipment & disposal
+ Babcock & Wilcox Co SMH-381 86 80/03/31 App

0006200173 Forwards certificate to company leaders that all restrictive covenants contained in sale agreements have been waived, assurance of ability to cover decommissioning costs
CLERKEN, V Babcock & Wilcox Co 80/03/28 App

0006180142 Forwards revised replacement pages for SMH-381, "Demonstration & Conditions for License SMH-778," dtd 03/03/81 & 701231 re renewal application
CLERKEN, V Babcock & Wilcox Co 80/04/08 Ip

--0006180145 Revised replacement Pages 3-32, 3-32a, A-19 & A-20 for "Demonstration & Conditions for License SMH-778," 700501
+ Babcock & Wilcox Co SMH-381 80/04/30 App

--0006180146 Revised replacement Pages 3-37, 3-38, 3-37a, A-20, 3-19 & 3-20 for "Demonstration & Conditions for License SMH-778," 701231 renewal application
+ Babcock & Wilcox Co SMH-381 80/04/30 App

0006180378 Forwards revised pages for assuring personnel qualification training & equipment plan Pages withheld (ref 10CFR2 760)
CLERKEN, V Babcock & Wilcox Co 80/04/30 Ip

0006090041 Safety evaluation re ESN 000310 amend application & 000325 & 0408 supply requesting consent & use of temporary addition to Bldg J for storage of solid transuranic waste Recommends issuance of amend
HILLER, W D Uranium Fuel Licensing Branch 80/05/07 App

0006130246 Forwards License SMH-778 Apr 1989 reqt for normal operating license, mail unaccounted for & backup of ESN
CLERKEN, V Babcock & Wilcox Co 80/05/07 App

0006040088 Forwards replacement pages for renewal application to License SMH-778
CLERKEN, V Babcock & Wilcox Co 80/05/09 Ip

--0006040092 Replacement pages for renewal application to License SMH-778
+ Babcock & Wilcox Co 80/05/20 App

0006090149 Forwards replacement pages for Section 1 & two add pages for Section 2 of SN plan per NRC 000314 request
CLERKEN, V Babcock & Wilcox Co 80/05/18 App

0006280186 Forwards Revision 11 to application for renewal of License SMH-778
CLERKEN, V Babcock & Wilcox Co 80/05/20 Ip

--0006280180 Revision 11 to application for renewal of License SMH-778, + Babcock & Wilcox Co 80/05/20 12pp

0006200600 Advises that review of manpower expenditures required for Phase 11 to License SMH-778 was less than submitted SFC of Control has been notified to send refund
HILLER, W D License Fee Management Branch 80/05/27 Ip

0006270057 Forwards SMH-381, "Demonstration & Conditions for License SMH-778" (Renewal Application), Revision 12
CLERKEN, V Babcock & Wilcox Co 80/05/30 Ip

--0006270071 "Demonstration & Conditions for License SMH-778" (Renewal Application), Revision 12
+ Babcock & Wilcox Co SMH-381 812 80/05/31 App

0006260244 Advises licensee of partial refund of fee accompanying 000328 application for amend to License SMH-778 Manpower expenditures required to review application were less than anticipated
HILLER, W D License Fee Management Branch 80/05/06 Ip

0006160122 Forwards reqt for normal operating license, mail unaccounted for & backup of ESN
CLERKEN, V Babcock & Wilcox Co 80/06/09 App

0006270012 Grants 000613 request for extension until 06/07 to complete final corrective action re two previously reported items of non-compliance
HEWNA, W B Region 2, Atlanta, Safeguards Branch 80/06/17 Ip

SECRET 70-0925 CORNWALL FACILITY, WERN-HOUSE CORP

0006200046 Notification that new telephone sys called Health Physics Network (HPN) has been installed at site Rys intended for use during emergency to link all power plants & NRC Emergency Notification Rys facilities will also be used
HAPPEL, J D Region 3, Chicago, Office of the Director 80/06/18 App

DOCKET 70-0730 MASSACHUSETTS INST OF TECHNOLOGY

0006300240 Forwards table listing all licenses authorizing ESN forms, location type of mail, authorized amounts & 000001 inventory table withheld (ref 10CFR2 760)
CLERKEN, V Massachusetts Institute of Technology 80/06/23 Ip

DOCKET 70-0924 PACIFIC NORTHWEST LAB

0006235509 Forwards responses to NRC questions re application for renewal of License SMH-762 decommissioning plan for Savannah facility & Revision 7 to renewal application
CLERKEN, V Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/27 Ip

--0006235522 Provides assurance that lab will maintain sufficient financial resources to decommission & demolish lab-owned facilities at such time as may be appropriate
CLERKEN, V Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/28 Ip

--0006235525 "Decommissioning of ESN-Quoted Facilities at Richland, WA" Response to NRC comments & questions re license renewal application and
+ Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/27 18pp

--0006235526 Revision 7 to application for renewal of License SMH-762 + Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/19 40pp

SECRET 70-1007 GENERAL ELECTRIC CO

0006130034 Application to amend Certificate of Compliance 9019 for BU-7 package to increase net bulk density of W-oxide powder from 3.0 to 3.5 g/cc Amend fee and
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 80/09/19 App

--0006130038 Forwards Certificate of Compliance 9019 & 9019a authorizing delivery of radioactive mail to carrier for transport in Models BU-6 & BU-7 under License SMH-54
KAPLAN, A L General Electric Co 74/08/26 Ip

--0006130032 Certificate of Compliance 9019a authorizing delivery of radioactive mail to carrier for transport in Models BU-6 & BU-7 under License SMH-54
KAPLAN, A L General Electric Co 74/08/26 App

--0006130033 Application to amend License SMH-54 to authorize delivery of BU-6 carrier for transport in Models BU-6 & BU-7
KAPLAN, A L General Electric Co 74/08/24 App

--0006130038 "SE Model BU-7 U Shipping Container Critically Safe" Analysis
KAPLAN, A L General Electric Co NEDD-11277 74/02/28 App

SECRET 70-1003 CONSUMPTION SHOWING ESN, INC

0006170723 Forwards revised Page 6 of fundamental nuclear mail central plan per 10CFR270 32 & NRC 790726 Ip
EATY, F S C-E Power Systems 80/07/19 App

0006060101 Forwards definition of book record or book balance to be added to Chapter 3 & 4 of fundamental nuclear mail central plan per 000325 request
LIGHTNER, R E C-E Power Systems 80/06/02 App

0006160147 Forwards Form 12-N Annual Ref 199 W-2 and 1
LIGHTNER, R E Conduction Engineering, Inc 80/06/11 Ip

- 8006040142 Requests submittal of major safeguards amendment fee re 800516 transmittal of physical protection plan Plan classified as requiring amendment to License 88W-1087
VERBES, S. License Fee Management Branch 80/05/21 1p
- 8006030526 Adds License Condition 3 B of Amend 88W-4 to License 88W-1087, permitting physical inventories of low-enriched U
PARTLOW, J. Physical Security Licensing Branch 80/04/09 1p
- DOCKET 70-1112 GENERAL ELECTRIC CO

- 8006030544 Forwards info re 88W 31 caditor in response to NJ Nucleon
KAPLAN, A. General Electric Co., Nuclear Energy Products Div 80/03/20 4pp
- 8006030648 Forwards revisions to fundamental nuclear melt control plan.
Plan withheld (ref 10CFR2 790)
KAPLAN, A. General Electric Co., Nuclear Energy Products Div 80/03/21 1p
- 8006030652 Forwards statistical summary of personnel monitoring during 88W
KAPLAN, A. General Electric Co., Nuclear Energy Products Div. 80/03/20 2pp.
- 8006040223 Forwards latest revisions to fundamental nuclear melt control plan Encl withheld (ref 10CFR2 790)
KAPLAN, A. General Electric Co., Nuclear Energy Products Div. 80/04/10 1p
- 8006040306 Forwards revisions to fundamental nuclear melt control plan Revisions withheld (ref 10CFR2 790)
KAPLAN, A. General Electric Co., Nuclear Energy Products Div. 80/04/24 1p
- 8006030607 790-11-80-083 critically warning on experienced false alarm & fuel mfg bldg was evacuated. Licenses determined no abnormal radiation levels existed. No-on-site team verified that radiation levels were normal
OLBRIEN, F. P., KENNA, W. D. Region 2, Atlanta, Office of the Director 80/05/13 1p
- 8006040306 Forwards changes to fundamental nuclear melt control plan Changes withheld (ref 10CFR2 790)
KAPLAN, A. General Electric Co., Nuclear Energy Products Div 80/05/14 1p
- 8006040409 Asa receipt of 18r reporting results of IE Insp Rept 70-1112/80-06 on 800421-23 Requests rept be withheld (ref 10CFR2 790)
KAPLAN, A. General Electric Co., Nuclear Energy Products Div 80/05/20 1p
- 8006040424 Requests submittal of major safeguards amendment fee re 800516 transmittal of physical protection plan Plan classified as requiring major amendment to License 88W-1087
VERBES, S. License Fee Management Branch 80/05/21 1p
- 8006050418 PWD-15-80-092 on 800520, release from pipe flange to work area of Jaws 1 then 1 kg U hexafluoride occurred. Two workers evacuated from area. No detectable personnel exposures resulted
CORDELL, D. P., KENNA, W. D. Region 2, Atlanta, Office of the Director 80/05/22 1p
- 8006050423 Forwards add info for 800409 response to IE Insp Rept 70-1112/80-02 Info includes melt control & accounting procedures
KAPLAN, A. General Electric Co., Nuclear Energy Products Div. 80/05/13 7pp
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 8006050574 Forwards manual, "Physical Security Plan for Protection of BWR of Moderate Strategic Significance at Chevalier BWR," for NRC approval. Fee and Plan withheld (ref 10CFR2 790).
DIPATIA, R. P. Westinghouse Electric Corp 80/05/11 1p
- 8006080514 Forwards IE Insp Rept 70-1142/80-04 on 800212-25. No noncompliance noted
MARTIN, W. D. Region 1, Philadelphia, Safeguards Branch 80/04/29, 2pp
- 8006090512 IE Insp Rept 70-1143/80-04 on 800212-21. No noncompliance noted. Major areas inspected: prearrangement planning/shipping containers, melt & in-transit procedures. Details withheld (ref 10CFR2 790)
DEVILIN, J. W., LADNER, R., RACONIS, W. Region 1, Philadelphia, Safeguards Branch 80/04/07 1p
- 8006090513 Forwards IE Insp Rept 70-1143/80-08 on 800334-27. No noncompliance noted
MARTIN, W. D. Region 1, Philadelphia, Safeguards Branch 80/04/16 2pp
- 8006090517 IE Insp Rept 70-1143/80-08 on 800526-27. No noncompliance noted. Major areas inspected: measurements & statistical controls & inventory difference & associated limits of error. Details withheld (ref 10CFR2 790)
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch 80/04/16 1p
JOYNER, J. H. Region 1, Philadelphia, Office of the Director 80/04/16 1p
- 8006200120 Forwards Revision 4 to fundamental nuclear melt control plan for Pu Fuels development. Encl withheld (ref 10CFR2 790)
DIPATIA, R. P. Westinghouse Electric Corp 80/04/18 1p
- 8006200392 Forwards Revision 1 to manual, "Physical Security Plan for Protection of BWR of Moderate Strategic Significance at Chevalier BWR," for NRC approval. Revision incorporates administrative recommendations. Encl withheld (ref 10CFR2 790)
DIPATIA, R. P. Westinghouse Electric Corp 80/05/02 1p
- 8006040100 Advises that negative air atmosphere is appropriate in ASD gloveboxes & PFD during present decontamination activities for final decontamination of Pu Fuel Facility during operation. Work atmosphere was required
BOULE, C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/08 1p
- 8006040177 Requests exemption from certain of 10CFR2 requirements for isolation of radioactively contaminated waste from aggregate BWR quantity held in an containment awaiting burial at authorized site. Fee and Plan withheld (ref 10CFR2 790)
DIPATIA, R. P. Westinghouse Electric Corp 80/05/12 1p
- 8006200304 Forwards application for Revision 4 to License 88W-1120 reducing quantities of radioactive waste authorized for possession at facility. Fee and Plan withheld (ref 10CFR2 790)
DIPATIA, R. P. Westinghouse Electric Corp 80/05/12 2pp
- 8006200308 Application for Revision 4 to License 88W-1120, reducing quantities of radioactive waste authorized for possession at facility.
DIPATIA, R. P. Westinghouse Electric Corp 80/05/12 2pp
- 8006200180 Forwards IE Insp Rept 70-1142/80-06 on 800212-25 & 27-29. No noncompliance noted
MARTIN, W. D. Region 1, Philadelphia, Safeguards Branch 80/05/12 2pp
- 8006200131 IE Insp Rept 70-1143/80-06 on 800212-23 & 27-29. No noncompliance noted. Major areas inspected: melt control & accounting, physical security & health & industrial safety. Penalties withheld (ref 10CFR2 790)
WILKINSON, M. L. Region 1, Philadelphia, Office of the Director 80/05/08 4pp
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch 80/05/08 4pp
- 8006200229 Advises that License 88W-1120 is amended. Amend reduces possession limits identified in Attachment 1 of 800512 application.
BOULE, C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/16 2pp
- 8006200507 Revises License Condition 2 I of License 88W-1120, permitting revised pages in "Fundamental Nuclear Melt Control Plan for Pu Fuels Development Lab."
PARTLOW, J. Material Control Licensing Branch 80/05/22 1pp.
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

- 8006200574 Forwards manual, "Physical Security Plan for Protection of BWR of Moderate Strategic Significance at Chevalier BWR," for NRC approval. Fee and Plan withheld (ref 10CFR2 790).
DIPATIA, R. P. Westinghouse Electric Corp 80/05/11 1p
- 8006200581 Forwards IE Insp Rept 70-1142/80-04 on 800212-21. No noncompliance noted
MARTIN, W. D. Region 1, Philadelphia, Safeguards Branch 80/04/29, 2pp
- 8006200629 Forwards revised manual, "Fundamental Nuclear Melt Control Plan - Columbia Plant." Requests approval. Manual withheld (ref 10CFR2 790)
DIPATIA, R. P. Westinghouse Electric Corp., PWR Systems Div 80/05/01 1p

0004280050 Application for amend to License EMH-1107, deleting requirement for gross beta analysis of ambient air particulates
BIPALIA, R P Hestingshouse Electric Corp 05/09/14 3pp

0004280017 Forwards site physical security plan for approval Fee and
Plan withheld (ref 10CFR2 7901)
BIPALIA, R P Hestingshouse Electric Corp, PWR Systems Div 05/09/15 1p

0004280047 PW-11-00-04 as 000519, bomb threat was received by
receptionist at facility. Licensee conducted searches, bomb
was found. Facility was not evacuated.
GILBERT, J P, CORREIA, J P Region 2, Atlanta, Office of the
Director 05/09/20 1p

0004180001 Ack receipt of 000429 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 70-1151/02-04
STOKES, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 05/05/29 1p

--0004180002 Responds to NRC 000408 ltr re violations noted in IE Insp
Rept 70-1151/02-04 Corrective actions instituted formal
program to assure annual fish collection. Samples will be
obtained by 000501
STOKES, J P Hestingshouse Electric Corp 05/04/29 2pp

--0004180003 Forwards IE Insp Rept 70-1151/00-04 as 000225-00 & notice
of violation
STOKES, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 05/04/28 2pp

--0004180004 Notice of violation from Insp on 000225-00
Region 2, Atlanta, Office of the Director 05/04/07 1p

--0004180009 IE Insp Rept 70-1151/00-04 as 000225-00 Noncompliance noted
Failure to obtain required fish samples
STOKES, J P Region 2, Atlanta, Fuel Facility & Materials Safety
Branch 05/04/07 1p

0004000004 Ack receipt of 000513 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-1151/00-04
STOKES, J P Region 2, Atlanta, Safeguards Branch 05/05/09 1p

--0004280007 Responds to NRC 000423 ltr re violations noted in IE Insp
Rept 70-1151/02-04 Corrective actions withheld (ref 10CFR2 7901)
STOKES, J P, STOKES, H Hestingshouse Electric Corp 05/09/13 1p

--0004280010 Forwards IE Insp Rept 70-1151/00-10 as 000225-00 & notice
of violation Notice of violation withheld (ref 10CFR2 7901)
STOKES, J P Region 2, Atlanta, Safeguards Branch 05/04/21 2pp

--0004280015 IE Insp Rept 70-1151/00-10 as 000225-00 Noncompliance noted
Failure to calibrate emission spectrometer w/techs. Unable to
maintain sig. of test & failure to record results of control
data according limit details withheld (ref 10CFR2 7901)
GILBERT, J P Region 2, Atlanta, Safeguards Branch 05/04/21 1p

SECRET 70-1103 CHERRAWH FACILITY, ABBEY-HOGE CORP

0004020045 Notifies that new telephone ex called Health Physics
Network (PHN) has been installed at site. Bps intended for
use during emergencies to link all power plants & NRC.
Emergency Notification Bps hotline will also be used.
KEMPNER, J D Region 2, Chicago, Office of the Director 05/04/08 2pp

0004280033 Forwards proposed changes to standby physical security plan
Proposed changes strengthen access control & thus do not
require prior license approval
STOKES, J P Hestingshouse Corp 05/05/09 5pp

0004170035 Determined that reporting requirements of License Condition
& 1 are no longer necessary. Amend HPP-3 to License EMH-1174
in revised, effective immediately to delete license
condition
PARTELOW, J D Material Control & Accountability Development Branch 05/04/02 1p

0004280007 Discusses review of mat control & accounting requirements
re License EMH-1174 Amend HPP-3 Condition & 1 is deleted
Monthly loss rep not required
PARTELOW, J D Material Control Licensing Branch 05/04/02 1p

SECRET 70-1201 UP & CONVERSION FACILITY, BABCOCK & WILCOX CO

0004280072 Forwards Certificate to company lenders that all restrictive
covenants contained in note agreements have been met.
Assurance of ability to cover decommitting costs
JORDAN, L V Babcock & Wilcox Co 05/03/28 2pp

0004170028 Forwards administrative amend license Fee re revised HPP-2
Condition & 5 for License EMH-1168 exempting plant from
requirements to issue HSC-741 documents for shipment of empty
containers in U power plant. License withheld (ref 10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/04/10 1p

--0004170029 Requests amend to License EMH-1168 exempting plant from
requirements to issue HSC-741 documents for shipment of empty
containers to U power plant.
JEDF, D W Babcock & Wilcox Co 05/04/01 1p

0004280082 Application to amend License EMH-1168 re use of emission
spectrometry technique for isotopic measurements. Encls
withheld (ref 10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/04/17 1p

0004280082 Application to amend License EMH-1168 re measurement of
radiated fuel assemblies & control charts for leakage
analysis. Encls withheld (ref 10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/04/17 1p

0004280019 Forwards Revision 0 to Fundamental nuclear matl control plan
& administrative Licensing Fee Encls withheld
(ref 10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/05/01 1p

0004280010 Forwards Fee & revised app. pages re 000109 Amend
Application 79-3 for License EMH-1168
JEDF, D W Babcock & Wilcox Co 05/05/05 2pp

--0004040018 Revision to 000109 Amend Application 79-3 for License
EMH-1168 Areas addressed include levels of air effluent
releases & liquid effluent releases & contamination survey
frequency
JEDF, D W Babcock & Wilcox Co 05/05/05 2pp

0004280033 Forwards physical security plan for review & approval.
Includes request for exemption of liquid effluent retention &
disposal w/ addition of certain license conditions &
exclusion of manual sections. Plan withheld (ref 10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/05/16 1p

0004280013 Requests investigation into trend of abnormal oscillatory
pattern in recent inventory difference review. Should include
reasons for trends, corrective actions & projected schedule
for completion. Results requested by 000501
PARTELOW, J D Material Control Licensing Branch 05/05/02 1p

0004280022 Ack receipt of 000514 ltr which transmitted physical
protection plan for BPP of low strategic significance. Plan
classified by safeguards licensing staff as requiring major
amend to License EMH-1168. Safeguards amend Fee required
NETH, B License Fee Management Branch 05/05/21 1p

0004280004 Application for amend to License EMH-1168. Revisions include
action levels for air & liquid effluent releases, isolation
criteria & contamination survey frequency
JEDF, D W Babcock & Wilcox Co 05/05/22 23pp

0004280044 Forwards application to amend License EMH-1168 re regulatory
requirement for action monitoring & maintaining control. Encls.
Administrative amend Fee and Application withheld (ref
10CFR2 7901)
JEDF, D W Babcock & Wilcox Co 05/05/22 1p

SECRET 70-1250 EDLOW INTERNATIONAL CO

0004280019 Requests 30-day extension for submittal of security plan in
order to prepare Form competition with regulations
WILSON, D Edlow International Co 05/03/16 1p

SECRET 70-1259 REED GILLES FABRICATION PLANT, EXXON NUCLEAR CO., INC.

0004280046 Lists four items not covered by current Fundamental matl
control plan. Revision will be submitted if necessary.
SCHNEIDER, R A Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 05/05/25 2pp

- 8006260081 Forwards upgrading & clarifying revisions to 790430 application for renewal of License 89H-1267
EDWARDS, P. Erwin Nuclear Co., Inc (subs of Exxon Corp.) 05/04/30 1p
- 8006260090 Revised pages to 790430 application for renewal of License 89H-1267
" Erwin Nuclear Co., Inc (subs of Exxon Corp.) 05/04/30 2pp
- 8006260545 Advances that no add safety & environ fee is required for Amend 22 to License 89H-1267 based on 800415 response
applicants required to review 79119 amend application entered on fee limit
HOLMES, J. D. License Fee Management Branch 05/05/01 1p
- 8006260546 Advances that License Condition 2 B has been added to Amend HPP-2 to License 89H-1267 for sampling & measurement of U hexafluoride from foreign source
PARTLOW, J. D. Licensing Management Branch 05/05/03 1p
- 8006260546 Requests payment of administrative amend fee re 800556 request for temporary exemption from dose requirements
HOLMES, J. D. License Fee Management Branch 05/05/07 1p
- 8006260546 Revised License Condition 2 B of Amend HPP-2 to License 89H-1267 & deletes License Condition 3 D License Condition 5 D will be reworded 5 D
PARTLOW, J. D. Division of Licensing 05/05/30 1p
- 8006120434 Advances that major safeguards amend fee is required for review of physical protection plan submitted as 800556
HOLMES, J. D. Licensing Management Branch 05/05/02 1p
- 8006110013 Advances that minor safeguards amend fee required for review of 800508 proposed procedures to perform receipt measurements of nine cylinders of U hexafluoride
HOLMES, J. D. Licensing Management Branch 05/05/02 1p
- 800627 76-1336 HERRICK OPERATIONS, GENERAL ELECTRIC CO

- 8006260040 Forwards "EIA re Renewal of Hattis License 89H-1265 for Receipt, Storage & Transfer of Spent Fuel at Morris Operation, GE Co."
" Office of Nuclear Material Safety & Safeguards 05/04/30 2pp
- 8006260049 "EIA re Renewal of Hattis License 89H-1265 for Receipt, Storage & Transfer of Spent Fuel at Morris Operation, GE Co."
" Office of Nuclear Material Safety & Safeguards 05/04/30 03pp
- 8006260202 Informa that GE general revenues & retained earnings as shown by 1994 annual reports sufficiently large that resources deemed necessary to demonstrate Morris Facility will be available Board Resolution 54-0, dtd 7/9/92 encl.
HOLMES, J. D. General Electric Co 05/04/10 2pp
- 8006120386 Forwards table showing increased inventory of fuel
SABERS, S. H. General Electric Co., Nuclear Energy Products Div 05/05/01 2pp
- 8006170083 Forwards JE Issp Rpts 70-1300/80-02 as 800321 & 26-27 No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 05/05/02 2pp
- 8006170084 JE Issp Rpts 70-1300/80-02 as 800321 & 26-27 No noncompliance noted Major areas inspected Organization, Fuel Storage & Handling, Facility changes & modifications, surveillance testing & internal exposure control
PETER, C. Region 3, Chicago, Office of the Director, F334R, H. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 05/04/20 2pp
- 8006162332 Oppose reissuance of Facility due to radioactive emissions from plant; close proximity & undue risks to public health & safety
WALSH, J. Affiliation Unknown. 05/06/05 2pp
- 8006170083 Forwards OA Input to SER re vendor application to renew License 89H-1265
OBERG, L. L. Advanced Fuel & Spent Fuel Licensing Branch 05/05/14 0pp
- 8006110293 Forwards GE 800556 ltr to NRC re License 89H-1265 Related correspondence
SABERS, S. H. Reger, Brown & Platt 05/05/02 1p
- 8006110293 Hattis that physical security plan for License 89H-1265 changed Requests sent to ltr be withheld filed 100592 7701
SABERS, S. H. General Electric Co. 05/05/04 2pp
- 8006120123 Notification of 800550 meeting w/ORE in Silver Spring, MD re 800123 license amend request & vendor plans for possible expansion of pool pump room
CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch 05/05/30 0pp
- 8006090304 Order ruling on EL Raman, R. Brown, & E. Guigay conditions wording of contention as accepted by AEL3
encl
OBERG, L. L. Atomic Safety and Licensing Board Panel 05/05/04 03pp
- 8006090307 Order denying E. Hatch 800403 petition to Intervene as matter of right & discontinue Contention is not litigable Petitioner failed to establish good cause for late intervention
OBERG, L. L. Atomic Safety and Licensing Board Panel 05/05/04 0pp
- 8006090308 Order establishing discovery schedule Requests must be served by 800508 objections by 800711 & answers to requests w/objections by 800730 AEL3 will establish dates for summary disposition during or after discovery
OBERG, L. L. Atomic Safety and Licensing Board Panel 05/06/04 2pp
- 8006090344 Forwards Jan 1980 EIA re renewal of Hattis License 89H-1265 for receipt, storage & transfer of spent fuel
EDWARDS, P. H. Hearing Branch 1 05/05/05 1p
- 8006090344 EIA re renewal of Hattis License 89H-1265 for receipt, storage & transfer of spent fuel
" Office of Nuclear Material Safety & Safeguards 05/05/05 10pp
- 8006180333 Motion for extension until 800730 or 30 days after receipt of NRC safety evaluation to complete final round of discovery Requests due in 10-day extension for objections & answers after final filing of requests w/Certificate of Doc
SABERS, S. H. Illinois, State of 05/06/12 7pp
- 8006180107 Motion for reconsideration of AEL3 800604 order ruling on contention Urges denial of Contention 10/11/04
certification of whether parties are consolidated re combined combined Certificate of Doc encl
EDWARDS, P. H. Hearing Branch 1 05/06/15 12pp
- 8006260416 Memorandum in opposition to State of IL motion for adjl time for preparation of discovery requests Urges denial of IL to devote efforts to preparation of requests by 800626 schedule should not be abandoned Certificate of Doc encl
EDWARDS, P. H. 7/20/92, H. A. General Electric Co. EDWARDS, P. H. Reger, Brown & Platt 05/06/16 2pp
- 8006260425 Notice of Filing of motion for reconsideration & memorandum in support
EDWARDS, P. H. Illinois, State of 05/06/20 1p
- 8006260397 Motion to reconsider AEL3 800604 ruling on parties' contentions & to admit State of IL Contentions 10/11/04
EDWARDS, P. H. GEORGE, W. J. Illinois, State of 05/06/30 1p
- 8006260292 Memorandum in support of motion for reconsideration of AEL3 800604 ruling on parties' contentions Urges admission of State of IL Contentions 10/11/04 & 11/11/04 to conform w/NRC interim policy on EIS Submittals of Doc encl
EDWARDS, P. H. GEORGE, W. J. Illinois, State of 05/06/30 8pp
- 8006260254 Order extending discovery requests until 800735 objection to requests until 800804 answers to discovery until 800804 & parties opinions re further discovery until filing of SER
OBERG, L. L. Atomic Safety and Licensing Board Panel 05/06/22 2pp
- 8006260203 Response supporting in part, State of IL 800612 motion for adjl time Urges revision of AEL3 800604 order re discovery schedule to adopt NRC dates which will relieve burden & will take into account AEL3 & NRC change w/Certificate of Doc
EDWARDS, P. H. Hearing Branch 1 05/06/06 1pp
- 8006260425 "EIA re Renewal of License 89H-1265 for Receipt, Storage & Transfer of Spent Fuel"
" Office of Nuclear Material Safety & Safeguards. HERRICK-0079 05/04/30 104pp

DOCKET 76-0548 WESTINGHOUSE ELECTRIC CO

0004120452 Requests amend to export license, extending expiration date to 01/02/31
 NRC/STOJ, C O Westinghouse Electric Corp 00/05/02 1p

0004093852 Amend 4 to import license for Westinghouse, extending expiration date from 01/02/31 to 01/02/31
 PETERSON, R S Assistant Director For Export/Import & International Safeguards 00/05/02 1p

DOCKET 76-0669 COMMONWEALTH Edison CO

0004093852 Application for amend to License 00W-1002 & 00W-1003 extending expiration dates to 01/02/30 & 02/03/31, respectively
 PETERSON, R S Commonwealth Edison Co 00/04/03 2pp

0004049274 Application for amend to License 00W-1002 & 00W-1003, extending expiration dates to 01/02/30 & 02/03/31, respectively
 PETERSON, R S Commonwealth Edison Co 00/04/03 2pp

DOCKET 76-0687 MCDONNELL DOWNEY MCDONNELL IN

0004293665 Discusses IE imp of Licenses 10-10408-01, 10-10409-02 & 10W-1744 & forwards notice of violation
 SAVINIA, B Region 3, Chicago, Fuel Facility & Materials Safety Branch 00/04/02 2pp

0004293665 Notice of violation from imp on 000414 Noncompliance noted failure to conduct quarterly meetings of medical inhouse
 Noncompliance violation records showed that 00W-57 fuel source was not assayed before daily use
 Region 3, Chicago, Office of the Director 00/05/02 2pp

DOCKET 76-0693 McDOWNEY SPENT FUEL, P.O. BOX 10000 CO

0004293665 Forwards resolution opposing movement of spent nuclear fuel or waste over road through Lincoln County NC Road
 reaffirmed on 000408 that spent nuclear fuel or waste should be transported on interstate highways
 HUBBARD, R M Affiliation Unknown 00/04/17 3pp

0004040254 Forwards Lincoln County NC Board of County Commissioners 7/1/01 & 000408 resolutions affirming position that spent nuclear fuel should be transported from Oncon to McDowney on interstate highways
 HUBBARD, R M North Carolina, State of 00/04/17 3pp

0004040254 Advises that still will submit revision to spent fuel transportation plan incorporating regulatory requirements set as in 000408 plan & noted in 01/04/00 000408 Affair
 light changes to be made
 PARKER, D O Duke Power Co 00/04/08 2pp

0004293665 Advises that still is to submit proposed findings of fact by 000417, non-NRC parties by 000428 & NRC by 000407
 McDOWNEY, J H Doherty & Liberman 00/04/05 1p

0004100210 Responds to appeal re partial denial of FOIA request for route info re spent fuel shipments from Clark River to NC Appeal is denied with no further (re) FOIA Exemption 4 & (re) FOIA 7(c)
 BIRCH, W J Office of the Executive Director For Operations 00/05/02 2pp

0004040254 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision
 McDOWNEY, J H Doherty & Liberman 00/05/02 1p

0004040254 Submittal of proposed findings of fact & conclusions of law in form of initial decision
 McDOWNEY, J H Duke Power Co 00/05/02 1p

0004040254 Proposed initial decision containing findings of fact & conclusions of law, approving amend to authorize storage of Oncon spent fuel at McDowney involves radiological monitoring program shall be maintained w/ Certificate of Approval
 McDOWNEY, J H Duke Power Co 00/05/02 1pp

0004100246 Proposed findings of fact & conclusions of law toward Initial Decision Alleges that NRC has not been covered w/ federal law & that ASR can rule matter per President Carter 000412 address to Congress Affirmation of act will
 RICHIE, L Carolina Environmental Study Group 00/05/02 50pp

0004101014 Notice for extension until 000417 to file proposed findings of fact & conclusions of law due to other assignments & complex nature of case Certificate of Approval
 PETERSON, R S Hearing Branch 4 00/05/03 4pp

0004101024 Order granting extension until 000417 for NRC to file proposed findings of fact & conclusions of law
 RICHIE, L E Atomic Safety & Licensing Board Panel 00/05/03 1p

0004101024 Responds in opposition to NRC 000408 proposed findings of fact & conclusions of law in form of initial decision requesting denial of License Amend Maintaining that containment have been resolved Certificate of Approval
 McDOWNEY, J H Duke Power Co McDOWNEY, J H Doherty & Liberman 00/05/03 17pp

0004101037 Responds in opposition to Carolina Environ Study Group 000408 proposed findings of fact & conclusions of law toward Initial Decision No good reason presented for not approving application re spent fuel shipment w/ Certificate of Approval
 McDOWNEY, J H Duke Power Co 00/05/03 21pp

0004101038 Forwards 000408 FOI notice requesting NRC amend to physical protection regulation of irradiated reactor fuel during transit Fulfills NRC commitment made at 000408-09 hearings
 HUBBARD, R M Hearing Branch 4 00/05/03 13pp

0004101039 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oncon spent fuel transportation to & storage at McDowney
 PETERSON, R S Hearing Branch 4 00/05/03 1p

0004101046 Proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oncon spent fuel transportation to & storage at McDowney
 Proposed transcript corrections & Certificate of Approval
 PETERSON, R S Hearing Branch 4 00/05/03 150pp

DOCKET 76-0693 NISBOLD-NISBOLD AMERICAN CORP

0004293665 Application by Nisbald-Nisbald American Corp to amend license to export 100 lbs of spent fuel shipping container to 30 300 100 U-235
 contained in 10 100 10 10
 NISBOLD, R Nisbald-Nisbald American Corp 00/05/07 1p

DOCKET 76-0693 NISBOLD-NISBOLD GAS & ELECTRIC CO

0004293665 Application for amend to License 00W-1002 extending expiration date to earlier of 01/02/30 or compliance to US
 PLYMOUTH, D Connecticut Gas & Electric Co 00/04/03 2pp

DOCKET 76-0695 COMMONWEALTH Edison CO

0004093852 Application for amend to Licenses 00W-1002 & 00W-1003 extending expiration dates to 01/02/30 & 02/03/31, respectively
 PETERSON, R L Commonwealth Edison Co 00/04/03 2pp

0004049274 Application for Amend to Licenses 00W-1002 & 00W-1003, extending expiration dates to 01/02/30 & 02/03/31, respectively
 PETERSON, R L Commonwealth Edison Co 00/04/03 2pp

DOCKET 76-0709 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

0004050287 Requests placement on list to receive DOE for NRC license for proposed Westinghouse nuclear fuel fabrication plant
 near Princeton, NJ
 WESTINGHOUSE, J National Wildlife Federation 00/03/02 1p

0004050291 Notifies that add distribution of environ report by federal, state & local officials has been completed per instructions provided in NRC 000207 1st Amendment will be placed on envin report distribution list for future amendments
 PLYMOUTH, D Westinghouse Electric Corp 00/05/02 1p

0004100254 Forwards NRC notice of hearing & NRC rules & regulations, 100202 documents concerning proposed facility NRC acts
 NISBOLD, R A Uranium Fuel Licensing Branch 00/05/02 1p

0004050292 Opposes proposed Westinghouse fuel pellet plant Companies should build plants in sparsely populated areas such as NW & UT Small group of people should not sub entire area to potential catastrophe
 WILSON, E Affiliation Unknown 00/05/02 2pp

0004240587 Requests that 56 listed questions be addressed in NRC EIS for Facility, including effect on economic, social & ecological activities of central AL. ALFRED, W. H. Affiliation Unknown 00/04/02 App

0004240154 Comments on EIS. Suggests inclusion of add effects re characterization of AL River, radioactive releases into underground areas, use of Pu & waste from transportation. Certificate of Gov. ARMOON, R. Affiliation Unknown HPHILLIPS, J. Affiliation Unknown 00/04/03 App

0004240133 Motion for two-month extension to make comments on scope of EIS. Statements during 000327 meeting confused parties re deadlines. Certificate of Gov. ARMOON, R. Affiliation Unknown HPHILLIPS, J. Affiliation Unknown 00/04/03 App

0004240174 Protests chemical & radioactive pollutants & wastes discharged into air & AL River from Hestingshouse Power Co. NRC decision to award EIS contract to ORNL will not result impartial study. BE L, JAMES, D. V. Affiliation Unknown 00/04/03 App

0004240075 Protests NRC decision to contract performance of AL Nuclear Fuel Fabrication Plant EIS w/ORNL & manner in which 000327 meeting was posted. Site of advertisement & solicitation of expertise made legal notice unreadable. DELISSANDER, V. Affiliation Unknown 00/04/03 App

0004230142 Forwards questions & statement handout distributed by Hestingshouse Electric Corp. Group & used by news speaking at 000328 scoping meeting in Prattville, AL. Newspaper article re meeting also incl. Transcript expected. HESTINGSHOUSE, R. Hestingshouse Electric Corp. - PWR Systems Div. 00/04/07 12pp

0004230744 Advances of extension until 000414 to file request for hearing re issuance of NRC license to facility. Extension is necessary for public review of revised EIS notice and. PAGES, R. O. Uranium Fuel Licensing Branch 00/04/08 App

0004230743 Notice of extension of opportunity to file request for hearing re issuance of NRC license for facility. PAGES, R. O. Uranium Fuel Licensing Branch 00/04/08 App

0004230570 Requests info re whether any plants or animals listed as endangered species may be present in vicinity of proposed plant. Plant will convert commercial U base fuels into U dioxide for fabrication into ceramic fuel pellets. SHUM, G. Y. Uranium Fuel Licensing Branch 00/04/09 App

0004230487 Comments on environ. rept. for nuclear fuel fabrication plant in Autauga County, AL. Environ. statement should identify aquifer tapped by Prattville wells & should assess impacts of water demand on Prattville sys. & on aquifer. HENDRICKS, M. Stationary Dept. of Geologic Survey 00/04/14 1p

0004230330 Expresses concern re environ. impact of proposed nuclear re. nrg. plant near Prattville, AL. River is major part of watershed in area. STEINHAUER, J. Affiliation Unknown 00/04/16 1p

0004230324 Requests that second public scoping hearing re environ. rept. for proposed fuel fabrication facility be held in near future. Hearing should be held due to unavailability of rept. prior to first hearing in Prattville, AL. MILLER, D. L. Affiliation Unknown 00/04/21 App

0004230283 Ack receipt of NRC 000489 request for info re endangered & threatened species in site area. Request has been forwarded to Jackson area odc for review. BLACK, A. S. Interior Dept. of Fish & Wildlife Service 00/04/23 App

0004230357 Forwards NRC environ. review schedule for proposed fuel fabrication plant in response to request NRC anticipates licensing EIS by 000518 & EIS by 000504. CRAM, M. T. Uranium Fuel Licensing Branch 00/04/23 App

0004230304 Forwards comments & questions re environ. rept. for proposed fuel fabrication plant. Requests response by 000510. HESTINGSHOUSE, R. Uranium Fuel Licensing Branch 00/04/00 12pp

DOCKET 70-0910 TENNESSEE VALLEY AUTHORITY

0004230553 Application for amend to License 0001024, reflecting personnel & fix changes within unit & making Unit 1 & 2 applications identical. MILLER, M. Tennessee Valley Authority 00/03/12 App

DOCKET 70-0903 ALABAMA POWER CO.

0004230142 Forwards signed copy of Amend & its Indemnity Agreement to GIL. CLAYTON, P. L. Alabama Power Co. 00/03/27 App

DOCKET 70-0926 TENNESSEE VALLEY AUTHORITY

0004230542 Forwards application for license to receive, possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility. MILLER, M. Tennessee Valley Authority 00/03/12 App

0004230543 Application for license to receive, possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility. MILLER, M. Tennessee Valley Authority 00/03/12 App

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0015 CHICAGO BRIDGE & IRON CO.

0004230529 Requests certificate of approval from 700415 submittal of GA program for radioactive mail shipping packages. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/03/27 1p

0004230520 Responds to 000328 ltr re GA program by forwarding NRC 700429 ltr & approval of GA program ltr w/mt. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/03/27 1p

DOCKET 71-0102 SOURCE PROD. & EQUIP. CO. - INC.

0004230556 Discusses status of Source Production & Equipment Co. 700423 application for GA program for Type B packages. Requests explanation of what is unacceptable in application & which points of regulation apply to program. PARKER, R. A. Parker, R. A. 00/03/30 App

DOCKET 71-0103 MINNESOTA UNIV. OF

0004230174 Forwards request for addl info re research reactor facility GA program submitted w/700627 ltr. Includes questions re GA responsibilities of such organization, elements in app. & requirements for position of reactor manager. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/04/04 App

DOCKET 71-0139 BARBOCK & WILCOX CO.

0004230254 Forwards Revision # to PA operations GA policy & procedures manual re NRC 000314 request for addl info. Table referencing each comment in applicable paragraph in manual w/mt. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/03/16 App

0004230356 PA operations GA policy & procedures manual, Revision #. CARLSON, R. V. Babcock & Wilcox Co. 00/04/30 07pp

0004230174 Forwards GA program approval for radioactive mail package. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/03/27 1p

0004230177 GA program approval for radioactive mail package. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/03/27 1p

DOCKET 71-0164 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

0004230255 Forwards request for addl info re 700403 GA program in order to satisfy 10CFR71. App E requirements. Response due within 60 days. HESTINGSHOUSE, R. Chicago Bridge & Iron Co. 00/04/12 App

DOCKETED ITEMS

DOCKET 71-0148 NAVY, DEPT OF

8026300620 Forcer's revised QA program for industrial radiography in response to NRC 790813 ltr
ORR/OS & L. Navy, Dept. of, Naval Nuclear Power Unit 80/02/28 1a

--0004300622 Forward revised QA program for industrial radiography Code
 requirements & sample program forwarded in NRC 790012 ltr
 were used to revise program
 GLENN, T O Newcast of 80/02/87 is

--8004200426 Revised QA program for industrial radiography
GLENN, T D. Navy. Sept 82. 60/02/82. 4pp

DOCREF 71-6123 BATTLE-PACIFIC NORTHWEST 8.A00

0004200208 Forward revised GA program description incorporating addl
info requested in 000007 ltr
FUGURY, J J Battelle Memorial Institute, Pacific Northwest
Laboratory 90/03/16 14

--8005260292 QA program for shipping packages of radioactive matts.
Revision 2
* Battelle Memorial Institute, Pacific Northwest Laboratory
09/25/76 lpo

DOCKET 71-0125 FBF, INC.

8006200095 Forwarded GA program approval for radioactive mail package
MAC02641 J-C E. Transportation Branch 05/04/20 2p

--B005200100 GA program approval for radioactive waste package 0055.
Revision 0
NACONSLN.C E Transportation Branch 0004/00 to

SECRET 75-0000 BARBOCK & WELCH CO

0000000159 Forwards replacement page for Section 1 & two addl pages for
Section 2 D of GA plan per HIC 000014 request
CLINTON A F Bakewell & Wilson Co 00/09/15 4pg

901610226 Forwarded EA program approval for radioactive waste package
KAC05AMMLO C E Transportation Branch 00/05/27 3p

--260at30034 DA program approval for radioactive mahl package 0320
Revision 0
HAC00NAL0000 Transportation Branch 00/05/97 14

BOONBY 71-0384 NEW ENGLAND NUCLEAR CORP

0035520485 Forward request for addl info re NRC review of B0415 GA
program lines identifying reporting responsibilities should
be shown in Figure 3-1. Statement should be provided to
understruction & training program
NAC03ALD.C E Transportation Branch #03/25/21 Gae

8004200297 Forwards revised QA program for Facility Requests that
review of program be given priority status
007071A/E New England Nuclear Corp 80/04/08 1a

--0004230266 Revised QA program for fueling
SUNMHA.E New England Nuclear Corp. TRG-1 00/04/19 2100

—0004000579 GA program for receipt use & transfer of radioactive material
shipping packages by USS CHAMPAG
A. Nove, Dept of 80/04/03 600

806090002 Forward SA program approval for radioactive matl package

--0000090024 GA program approval for radioactive materi package 0000
Revision 0
NACED0000000000 Transportation Branch 00/05/27 10

pubkey: 71-0399-680951A, 1917 OF

0004095404 Forwarded mail on GA program for shipping container for 3 of
Am-241 sealed source to be used for analysis of mineral
samples Requests notification of addl required info
NUGENT A Georgia Univ of. 00/08/12 21pp

0006250197 Forwards request for add info to complete review of QA
program
MACBOM.B.C E Transportation Branch 06/06/06 Zoo

DOCUMENT 71-0392 COMMERCE, DEPT OF, NATIONAL BUREAU OF STANDARDS

WD06170094: Forwarded proposed ON program for procurement, maint, repair, & use of transportation packages for radioactive waste
FEDVY: L. E. Conner, Dept. of National Bureau of Standards
on/05/06 1a

--8006175106 Proposed GA program for procurement, maint, repair & use of transportation packages for radioactive waste
* Commerce, Dept of, National Bureau of Standards 06/03/78 7p

80643006; Forward: SA program approved for radioactive mat; package
HAC92AM.D.C.F. Transmutation Branch 80/04/12 is

--E03430061R 08 program approval for radioactive matl package 0390.
Revision 0
HACEDMARD C E Transportation Branch 08/06/12 ip

BOCKET 71-0091 NAVY. DEPT OF

506430854 Forwards BA program description
PROVNS, K. L. Navg. Dept of. Naval Nuclear Power Unit ED/OA/ID 5a

--880620000 Forwards QA program
JTHCDB, R M Navy, Dept of, Naval Facilities Engineering Command
09/05/21 1p

--8006366608 GA program for Licenses 39-08478-03 & 39-08479-04
IIMDOR R E Navy-Dept of, Bureau of Medicine & Surgery 00/05/90
Gpp

8066250121 Notice of expiration of Certificate of Compliance 4090 For Models Sentinel-20A, LCO-25A; Sentinel-250, LCO-250; Sentinel-250, LCO-250; Sentinel-250A, -250A, -250A & -250A to continue using package, should request Renewal

SECRET 21-4999A RTDCL BA-2. EARTH NUCLEAR CB - DNE

0006040000 Ack receipt of 000400 ltr requesting amend to Certificate of Compliance 4996 to permit shipment of test trains to Ontario,Canada
WK156.D License Fee Management Branch 00/05/01 ip

--GD06060005 Requests asked to Certificate of Compliance 4904 to permit shipment of nuclear fuel test trains to site in Deep River, Ontario, Canada. Forwards drawings & data demonstrating safety of Class 1 shipments
Battelle Memorial Institute, Pacific Northwest Laboratory
BD/04/02 18pp

—0000000000 "Test Train Arrangement" Sheet 1 of 17
 * Battelle Memorial Institute, Pacific Northwest Laboratory
 Energy Dept of 80/00/28 1p

DOCKETED ITEMS

281

- 0036060010 "Test Train Arrangement " Sheet 2 of 17
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 00/03/98 1p
- 0036060014 "Thermal Hydraulic 5 Melts Test Bundle Assemblies, Side A " Sheet 1 of 1
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 79/12/10 1p
- 0036060020 "Thermal Hydraulic 4 Melts Test Bundle Assemblies, Side 1 " Sheet 1 of 1
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 80/01/17 1p
- 0036060022 "Shipping Container For Test Assemblies " Sheet 1 of 2
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 00/04/07 1p
- 0036060024 "Shipping Container For Test Assemblies " Sheet 2 of 2
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 00/04/07 1p
- 0036060028 "Shipping Container For Test Bundle " Sheet 1 of 1
 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy Dept. of 80/04/07 1p
- DOCKET 71-5026 MODEL BC-40-220, ATOM, INC
- 0036060034 Requests registration as user of Model BC-40-220
 HANBY, R Georgia Power Co 80/04/30 1p
- 0036060034 Requests registration as user of Models G14, BC-160, PG-1, BC-40-220, LL-50-100 & LL-200
 HANBY, R Georgia Power Co 80/04/30 1p
- 0036060017 Advises still of registration as user of Models E-2, OE-1600, C-04, BS-09, 1-100, LL-50-100 & LL-200
 HANCOCK, D C Transportation Branch 80/06/03 3pp
- DOCKET 71-5071 MODEL UR3P-0-1, HWY, DEPT DF
- 0036060010 Notifies of expiration of Certificate of Compliance 5071 for Model UR3P-0-1 To continue using package should request renewal of existing certificate of compliance
 HANCOCK, D C Transportation Branch 80/06/11 1p
- DOCKET 71-5034 MODEL NPI-47-9442 NEUTRON PRODUCTS, INC
- 0036060010 Requests amend to Certificate of Compliance 5344 allowing shipment of large quantities of Co-60 Pw and N/A mail
 SHEDDEN, C Neutron Products, Inc 80/05/12 1p
- 0036060010 Forwards Revision 3 to Certificate of Compliance 5344 for Model NPI-47-9442
 HANCOCK, D C Transportation Branch 80/05/20 2pp
- 0036060041 Certificate of Compliance 5044, Revision 3, for Model NPI-47-9442
 HANCOCK, D C Transportation Branch 80/05/20 3pp
- DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP.
- 0036060001 Requests that Certificate of Compliance 3450 be revised to include RCC-4-type shipping package List of requested changes in certificate & rpt on fresh fuel shipping container test and
 DIPATIA, A P Westinghouse Electric Corp 80/06/02 8pp
- 0036060005 "Rpt on Test of Fresh Fuel Shipping Container P/W 3450001-1, 30 P1 Prep Tests & Pw Brea " *
 * Container Research Corp 78/01/13 7pp
- 0036060006 "Fuel Assembly Shipping Container Internals Support Frame & Details " *
 * Westinghouse Electric Corp , Nuclear Energy Systems 80/02/10 1p
- 0036060007 "XL Fuel Assembly Shipping Container/Internals " Sheet 2 of 2
 * Westinghouse Electric Corp , Nuclear Energy Systems 80/04/01 1p
- 0036060004 "XL Fuel Assembly Shipping Container Cover & Base Weldment Details " Sheet 1 of 1
 * Westinghouse Electric Corp , Nuclear Energy Systems 80/04/01 1p
- 0036060018 "XL Fuel Assembly Shipping Container/Internals " Sheet 1 of 2
 * Westinghouse Electric Corp 80/04/01 1p
- 0036060040 Notifies of intention to use Model 800-L2 & D TUNDY, C P Portland General Electric Co 80/05/23 3pp
- DOCKET 71-5607 MODEL GE T-2, GENERAL ELECTRIC CO
- 0036060028 Forwards Certificate of Compliance 5607 for shipping package Model GE T-2 DOE evaluation of SAR & upgrade "T-2 Shipping Package SAR " *
 ROSEN, D H Energy Dept of 80/06/07 1p
- 0036060048 Certificate of Compliance 5607 for shipping package Model GE T-2 DOE evaluation of T-2 shipping container and
 HATTELLE, R C Energy Dept of 80/06/07 3pp
- 0036060046 Upgraded "T-2 Shipping Package SAR " Shipping container drawings and
 PETER, B F & Le Pont de Nemours & Co - Inc 80/04/30 49pp
- DOCKET 71-5076 MODEL 3813A1, PECCAN CORPORATION
- 0036060059 Forwards last rate card to upgrade metric licenses
 PEGGON, C A Picher Corp 80/06/20 3pp
- DOCKET 71-5803 MODEL BMAP 21, HWY, DEPT OF
- 0036060010 Notifies of expiration of Certificate of Compliance 5800 for Model BMAP-21 To continue using package, should request renewal of existing certificate of compliance
 HANCOCK, D C Transportation Branch 80/06/11 1p
- DOCKET 71-5842 MODEL BENTNELL-100P, TELEDYNE ENERGY SYSTEMS
- 0036060061 Notifies of expiration of Certificate of Compliance 5842 for Model Bentnell-100P To continue using package, should request renewal of existing certificate of compliance.
 HANCOCK, D C Transportation Branch 80/06/11 1p
- 0036060030 Forwards fee for renewal of three certificates of Compliance Requests renewal of current revision of Certificate of Compliance 5842 for T-yr period ending 08/07/83
 ROSEN, D H Teledyne Energy Systems 80/06/13 1p
- DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO
- 0036060032 Advises that vendor is reanalyzing shielded shipping container to confirm that calculational methods will accurately predict container response to accidents Personnel shortage impeding progress
 GUNDEL, R G General Electric Co 80/05/20 3pp
- DOCKET 71-5929 MODEL GE-1300, GENERAL ELECTRIC CO
- 0036060042 Forwards comparative data to welded Maxellair C-076 & Type 314, stainless steel Data is submitted as supplemental info for req of Certificate of Compliance 5929, Priority review requested
 TRAVIS, H H Energy Dept of 80/06/14 2pp
- 0036060010 Forwards Revision 4 to Certificate of Compliance 5929 for Model GE-1300
 HANCOCK, D C Transportation Branch 80/05/22 3pp
- 0036060011 Certificate of Compliance 5929, Revision 4, for Model GE-1300
 HANCOCK, D C Transportation Branch 80/05/22 3pp
- 0036060032 Forwards Revision 3 to Certificate of Compliance 5929 for Model GE-1300
 HANCOCK, D C Transportation Branch 80/06/06 2pp

DOCKETED ITEMS

8004200037 Certificate of Compliance 5704, Revision 3, For Model GE-1500
HACDONALD, C E Transportation Branch 80/04/06 App

DOCKET 71-3940 MODEL EC-14-10, BATTELLE COLUMBIA LABORATORIES

8004200128 Notification of expiration of Certificate of Compliance 5940 For Model EC-14-10 To continue using package, should request renewal of existing certificate of compliance
HACDONALD, C E Transportation Branch 80/05/13 1p

DOCKET 71-3942 MODEL GE-700, GENERAL ELECTRIC CO

8004200436 Requests renewal of Certificate of Compliance 5942 For Model 700 shipping container. Furnish drawings & package description. Consolidated application for certification & renewal fee and drawings available in Control Files only
HACDONALD, C E General Electric Co 80/05/13 5pp

8005210460 "Shipping Cask Basket"
General Electric Co 70/02/26 1p

8005210461 "Transfer Buggy Details"
General Electric Co 49/05/21 1p

8005210465 "Cask Extension"
General Electric Co 71/07/09 1p

8005210469 "700 Fuel Shipping Cask"
General Electric Co 72/03/09 1p

8005210472 "700 Shipping Cask"
General Electric Co 72/03/06 1p

8005210475 "Protective Jacket 700 Series Cask"
General Electric Co 72/03/06 1p

8005210479 "Fuel Shipping Cask Extension 700 Series"
General Electric Co 44/01/30 1p

8005210480 "Base 700 Series Cask"
General Electric Co 72/03/06 1p

8006200044 Notification of registration as user of Model GE-700 in response to request
HACDONALD, C E Transportation Branch 80/04/06 1p

DOCKET 71-5957 MODEL ENH-1, ENDSRV, DEPT OP

8004096032 Requests that address be removed from list of shipping package addresses. Research reactor has been shut down since Jan 1970. No use for Model ENH-1 package. Personnel, WISD, A - Ames Laboratory, Energy & Mineral Resources Res. Institute 80/05/12 1p

DOCKET 71-5973 MODEL 5975, SCHLUMBERGER WELL SERVICES

8004200367 Notification of expiration of Certificate of Compliance 5975 For Model 5975 To continue using package, should request renewal of existing certificate of compliance
HACDONALD, C E Transportation Branch 80/05/09 1p

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

8004270057 Informs that before applying for competent authority certificate, amend to Certificate of Compliance 5980 mechanism. Design contents & operating conditions of package must be same in competent authority certificate.
HACDONALD, C E Transportation Branch 80/05/12 1p

DOCKET 71-6018 MODEL B3-1, NUCLEAR ENGINEERING CO

8004170077 Notification of registration as user of Model Super Tiger, Paduch Tiger, A479, Poly Tiger, B-3, B-2 & A372 in response to request
HACDONALD, C E Transportation Branch 80/05/13 2pp

DOCKET 71-6044 MODEL A144, NUCLEAR ENGINEERING CO

8004200444 Requests registration as user of Model CNR 15-1400
HARRY, R Georgia Power Co 80/04/30 1p

8004200584 Requests registration as user of Models A144, GE-1400, pg-1, EC-4B-200, LL-30-100 & LL-2B-4
HARRY, R Georgia Power Co 80/04/30 1p

8004170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, A479, Poly Tiger, B-3, B-2 & A372 in response to request
HACDONALD, C E Transportation Branch 80/05/13 2pp

8004200354 Requests registration as user of Model A144/B
HARRY, R Toledo Edison Co 80/05/19 1p

8004120195 Requests registration as user of Model CNR 15-1400 shipping cask
SEBBS, H H Nuclear Products, Inc 80/05/19 1p

8004200167 Advises util of registration as user of Models B-2, GE-1400, CNR-4-B, CNR-14-190, LL-30-100 & LL-2B-4
HACDONALD, C E Transportation Branch 80/06/03 2pp

8004200007 Notification of registration as user of Models CNR-14-190-B & B-2
HACDONALD, C E Transportation Branch 80/04/16 1p

DOCKET 71-6026 MODEL B, BANCOR & HILCOSS CO

8004200116 Notification of registration as user of Model B
HACDONALD, C E Transportation Branch 80/06/04 1p

DOCKET 71-6072 MODEL POLY PANTHER, TELEPHONE ENERGY SYSTEMS

8004170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, A479, Poly Tiger, B-3, B-2 & A372 in response to request
HACDONALD, C E Transportation Branch 80/05/13 2pp

DOCKET 71-6075 MODEL LL-2B-4, CHEM-NUCLEAR SYSTEMS, INC

8004200018 Requests registration as user of Model LL-2B-4
HARRY, R Georgia Power Co 80/04/30 1p

8004200541 Requests registration as user of Models A144, GE-1400, PG-1, EC-4B-200, LL-30-100 & LL-2B-4
HARRY, R Georgia Power Co 80/04/30 1p

8004040076 Requests termination of Certificate of Compliance 5275 Cask involved in refurbish package exceed what could be realized to become
CORBETT, J B Chem-Nuclear Systems, Inc 80/05/09 1p

8004200467 Advises util of registration as user of Models B-2, GE-1400, CNR-4-B, CNR-14-190, LL-30-100 & LL-2B-4
HACDONALD, C E Transportation Branch 80/06/03 2pp

DOCKET 71-6075 MODEL PG-1, CHEM-NUCLEAR SYSTEMS, INC

8004200341 Requests registration as user of Models A144, GE-1400, PG-1, EC-4B-200, LL-30-100 & LL-2B-4
HARRY, R Georgia Power Co 80/04/30 1p

8004190144 Requests that period of 180 days be allowed to respond to MSZ 800404 for re-embarked package.
CORBETT, J B Chem-Nuclear Systems, Inc 80/05/26 1p

8004200167 Advises util of registration as user of Models B-2, GE-1400, CNR-4-B, CNR-14-190, LL-30-100 & LL-2B-4
HACDONALD, C E Transportation Branch 80/06/03 2pp

8004200125 Notification of registration as user of Model CNR 4-B
HACDONALD, C E Transportation Branch 80/06/06 1p

DOCKETED ITEMS

283

DOCKET 71-4387 MODEL 60, BAYTELLE MEMORIAL INSTITUTE

8004270064 Forwards "HCL Model 60 Unirradiated Fissionable Salt Shipping Container CAN for Packaging (500P) - Regt contains info for consolidated application for removal of certificate of compliance Removal for emil
FUGUE, J. J. Battelle Memorial Institute, Pacific Northwest Laboratory 80/04/02 2pp

DOCKET 71-4400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

8004020418 Responds to NRC 800329 ltr re Certificate of Compliance A400-Revision 8 Forwards post from contractor, Westinghouse Hanford Co Contains noted in Regt is only needed Super-Tiger delivered to carrier since 700208
F110017000, T. Energy Dept of 80/05/07 13pp

8004040108 Forwards add info & drawings per NRC 800329 request re packaging covered by Certificate of Compliance A400
JEFFERSON, R. Sandia Laboratories 80/05/08 4pp

--8004040172 "Super Tiger Assembly " Sheet 3 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040173 "Super Tiger Assembly Details " Sheet 2 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040179 "Lid Assembly & Details " Sheet 3 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040181 "Lid Assembly & Details " Sheet 4 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040183 "Exterior Shell Assembly " Sheet 5 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040186 "Exterior Shell Details " Sheet 6 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040187 "Interior Shell Assembly " Sheet 7 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040190 "Aluminum Cover " Sheet 8 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

--8004040191 "Super Tiger Details " Sheet 9 of 9
* Nuccon Engineering Co., Inc. (subs of Teledyne, Inc.) 7/6/72/14 1p

8004040208 Responds to NRC 800329 ltr re Model A400 shipping package Lab has never owned package Three shipments made in package since 700208
H104168, T. J. Battelle Memorial Institute, Columbus Laboratories 80/05/13 1p

8004170077 Notification of registration as user of Models Super Tiger, Patch Tiger, 6075-Poly Tiger, 3-D-B-2 & 6272 in response to request
HACDOWALD, C E Transportation Branch 80/05/13 2pp

8004120199 Responds to 800329 ltr transmitting Certificate of Compliance A400-Revision 8 Advises that Nuclear Engineering Co owns two SUPER TIGER shipping packages & remains registered users
DALES, T W Nuclear Engineering Co., Inc. (subs of Teledyne, Inc.) 80/05/14 1p

8004190009 Forwards Regt results on container Lab owns one Super Tiger, Serial Number NO A200 Lab has not used any other Model A400 packaging since 700208
CHINN, B. Lawrence Livermore Laboratory 80/05/19 3pp

8004200136 Forwards 80 Spec 80-01 AW for approval Spec used to inspect shipping container Model A400
F400000, A H 3M Co., Minnesota Mining & Mfg Co 80/06/03 3pp

DOCKET 71-4332 MODEL, PAQUAN TIGER, ENERGY DEPT OF

8004170077 Notification of registration as user of Models Super Tiger, Patch Tiger, 6075-Poly Tiger, 3-D-B-2 & 6272 in response to request
HACDOWALD, C E Transportation Branch 80/05/13 2pp

DOCKET 71-4001 MODEL, 51000-1 & SA, EXXON NUCLEAR CO, INC

8004030421 Forwards Revision 1 to consolidated license renewal application for Models 51000-1 & SA in response to NRC 800404 & 12 requests
HAWKINS, E. Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80/05/13 2pp

--8004030423 Revised pages for Revision 1 to consolidated license application for Models 51000-1 & SA
* Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80-05/03 74pp

--8004030427 "U Guide Pool Red Inner Shipping Container " 80/05/03
* Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80-05/03 80/05/03 1p

--8004030428 "Mod Packaging Method for Use w/Shipping Container Model 51000-1 " 80/05/03
* Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80-05/03 80/05/03 1p

DOCKET 71-4401 MODEL, LL-50-100, CHEN-NUCLEAR SYSTEMS, INC.

8004030463 Requests registration as user of Model LL-50-100
HARRY, M. Georgia Power Co 80/04/30 1p

8004050541 Requests registration as user of Models 6144, 62-1000-PS-1, 62-40-100, LL-50-100 & LL-50-4
HARRY, M. Georgia Power Co 80/04/30 1p

8004170212 Notification of registration as user of Model LL-50-100.
HACDOWALD, C E Transportation Branch 80/05/03 1p

8004200167 Advises until of registration as user of Models 8-2, 8E-1600, 800-4-40, 800-5-4-100, LL-50-100 & LL-50-4
HACDOWALD, C E Transportation Branch 80/06/03 2pp

DOCKET 71-4439 MODEL, RH-5A, ARMY, DEPT OF

8004050529 Responds to NRC 800404 ltr re Model RH-5A packaging. Consultant will answer NRC questions by 800501 & will arrange meeting as soon as authorization to proceed is obtained from Sandia Lab
KRAMER, H L. Edgemoor & Associates 80/05/02 1p

DOCKET 71-4479 MODEL, 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

8004170077 Notification of registration as user of Models Super Tiger, Patch Tiger, 6075-Poly Tiger, 3-D-B-2 & 6272 in response to request
HACDOWALD, C E Transportation Branch 80/05/13 2pp

DOCKET 71-4477 MODEL, 8000 PKG, GENERAL ELECTRIC CO

8004030483 Requests registration as user of Model 8000
FITZGERALD, T. Energy Dept of 80/04/09 1p

DOCKET 71-4476 MODEL, NFB-4, NUCLEAR FUEL REFINING CO, INC

8004050517 Application for amend to Certificate of Compliance 649B, Revision 9, for Model NFB-4, revising removable impact limiter & protection for valves & altering configuration of bottom end of Cook WCC-1 drawings & safety analysis NCI
HEDERWALL, M. L., CHWEDON, C R Nuclear Assurance Corp 80/05/28 3pp

--8004050518 "Shipping Cast - Spent Fuel, NFB-4 & HAC-1 " Sheet 1 of 3
WILKESMAN, L W Nuclear Assurance Corp 80/05/28 1p

DOCKETED ITEMS

- 8004160172 Shipping Cask - Spent Fuel-NFS-4 & NAC-1 " Sheet 2 of 5
WISDOMMAN, L. Nuclear Assurance Corp. 00/09/00 1p
- 8004160174 Shipping Cask - Spent Fuel-NFS-4 & NAC-1 " Sheet 3 of 5
WISDOMMAN, L. Nuclear Assurance Corp. 00/09/00 1p
- 8004160175 Shipping Cask - Spent Fuel-NFS-4 & NAC-1 " Sheet 4 of 5
WISDOMMAN, L. Nuclear Assurance Corp. 00/09/00 1p
- 8004160184 Shipping Cask - Spent Fuel-NFS-4 & NAC-1 " Sheet 5 of 5
WISDOMMAN, L. Nuclear Assurance Corp. 00/09/00 1p
- 8004160187 Safety Analysis of Modified NAC-1 Spent Fuel Shipping Cask -
Nuclear Assurance Corp. NAC-1-005 00/05/16 200pp
- DOCKET 71-6717 MODEL 6717 B

- 8004030009 Requests approval to use Model 6717-B if approval not
already granted Model 6717-B is used for air shipments
throughout US & transportation of exposure device in
darkroom truck vehicles NSF compliance certificate WCCB
CUTHEBERTSON, T. Peabody Testing/Engineering Co. 00/03/00
4pp
- 8004030001 Requests payment of fee to BGSBCB request for amend to
Certificate of Compliance 6717
HEISE, D. License Fee Management Branch 00/03/02 1p
- 8004160002 Requests registration as user of Gamma Industries Model
6717-B & Technical Operations Model 715
GIBBS, D. C. Nuclear Energy Service, Inc. 00/04/04 1p
- 8004030009 Notification of registration as user of Model 6717-B in
response to BGSBCB Request
MACDONALD, C. E. Transportation Branch 00/03/06 1p
- DOCKET 71-6744 MODEL 6744 TIGER, NUCLEAR ENGINEERING CO.

- 8004160077 Notification of registration as user of Model Tiger Tiger,
Tiger Tiger-6679, Tiger Tiger-6679-B & 6679 in response to
request
MACDONALD, C. E. Transportation Branch 00/05/03 3pp
- DOCKET 71-6771 MODEL 6671-S, NUCLEAR ENGINEERING CO.

- 8004030063 Notice of expiration of Certificate of Compliance 6771 for
Model 6671
MACDONALD, C. E. Transportation Branch 00/04/06 1p
- DOCKET 71-6786 MODEL 6786-00, NUCLEAR, DUFF CO.

- 8004030003 Notice of expiration of Certificate of Compliance 6786 for
Model 6786-00 & 6786-00 To continue using package, renewal
should be requested
MACDONALD, C. E. Transportation Branch 00/06/11 1p
- DOCKET 71-7001 MODEL 7001-00, GENERAL ELECTRIC CO.

- 8004160047 Requests amend to Certificate of Compliance 7001, Revision 9,
for IP-200 Spent Fuel Shipping Cask Forwards Revision 9A
for insertion into HESD-10004-2, "Consolidated SAR for
IP-200 Shipping Cask." Vols 1 & 2 Per mail
BARBON, R. H. General Electric Co. 00/08/12 2pp
- 8004030074 Forwards Revision 9A for "Consolidated SAR for IP-200
Shipping Cask." Vol 2 Revision incorporates high pressure
fuel rod accident analysis for dry cask shipping mode
General Electric Co. HESD-10004-2 US 00/04/00 7pp
- 8004030078 Forwards Revision 9A for "Consolidated SAR for IP-200
Shipping Cask." Vol 2 Revision incorporates high pressure
fuel rod accident analysis for dry cask shipping mode
General Electric Co. HESD-10004-2 US 00/04/05 20pp
- 8004040020 Ask receipt of 800422 1st Informing NRC of steps taken to
correct deviations noted in SA Program Insp Repts
99000302/00-01 & 71-0001/00-01
PETAPQVBL, U. Region 4, Dallas, Vendor Inspection Branch 00/08/13
1p
- 8004040032 Requests to NRC 800324 1st re deviations noted in SA Program
Insp Repts 99000302/00-01 & 71-0001/00-01 Corrective
actions fabrication records for PVV valves requested from
supplier
HODDINSETH, J. E. General Electric Co. 00/04/02 8pp
- 8004040035 Forwards SA Program Insp Repts 99000302/00-01 & 71-0001/00-01
to 71-0001/00-01 as 800425-29 & notice of deviation
PETAPQVBL, U. Region 4, Dallas, Vendor Inspection Branch 00/03/04
2pp
- 8004040037 Notice of deviation from Insp SA 800425-29
Region 4, Dallas, Vendor Inspection Branch 00/03/00 2pp
- 8004040038 SA Program Insp Repts 99000302/00-01 & 71-0001/00-01 re
800425-29 Hexametric noted six categories of negative net
as file, Cask 300 not hydrostatically tested to 600 psig
WRIEYELL, D. E. Region 4, Dallas, Vendor Inspection Branch
HODDINSETH, J. E. CD060001, J. E. Region 4, Dallas, Office of the
Director 00/03/00 8pp
- 800421 71-9007 MODEL 500, AECOM/NE NATIONAL LABORATORY

- 8004070013 Forwards drawings in support of application for renewal of
Certificate of Compliance 7007 for Model 500 Irridium
exposure device Drawings available in Central Files only
BARTON, M. F. Automation Industries, Inc. 00/03/05 1p
- 8004070015 "Head Assembly Irridium Model 500 " Sheet 1 of 1
Automation Industries, Inc. 70/12/21 1p
- 8004070020 "Shield & Sleeve Assembly Model 500 " Sheet 1 of 1
Automation Industries, Inc. 70/12/21 1p
- 8004070021 "Top Tube Model 500 " Sheet 1 of 1
Automation Industries, Inc. 70/12/21 1p
- 8004070032 "Shield Cask Model 500 " Sheet 1 of 1
Automation Industries, Inc. 70/12/21 1p
- 8004040048 Forwards Revision 2 to Certificate of Compliance 9007 for
Model 500
MACDONALD, C. E. Transportation Branch 00/05/03 2pp
- 8004040049 Certificate of Compliance 9007, Revision 2, for Model 500
MACDONALD, C. E. Transportation Branch 00/05/03 2pp
- 8004250102 Notification of registration as user of Model 500
MACDONALD, C. E. Transportation Branch 00/04/06 1p
- DOCKET 71-9009 MODEL 10-1, GENERAL ELECTRIC CO.

- 8004160068 Requests amend to Certificate of Compliance 7007, Revision 7,
revising dimensions of alternate inner container constructed
of 300 series stainless steel pipe permit tubing or pipe
welded diameter tolerance of 0.031 inches
AUSTIN, R. A. Docket & Section 6 - Nuclear Material Div. 00/09/14
1p
- 8004160069 Forwards check in payment for 800416 amend request to
Certificate of Compliance 7009, Revision 2
AUSTIN, R. A. Docket & Section 6 - Nuclear Material Div. 00/05/14
1p
- DOCKET 71-9010 MODEL 10-1/2, NUCLEAR INDUSTRIES, INC.

- 8004250223 Requests that Certificate of Compliance 9010 be revised to
provide option for method of lapping off neutron shield
expansion vent Certificate available in Central Files only
Per mail
WILLIAMS, C. E. N. Industries, Inc. Nuclear Div. 00/02/21 2pp
- 8004250262 "NLS 1/2 Cask & Trailer General Arrangement " Sheet 1 of 2
N. Industries, Inc. 00/02/13 1p
- 8004250270 "NLS 1/2 Cask & Trailer General Arrangement " Sheet 2 of 2
N. Industries, Inc. 00/02/13 1p
- 8004250277 "NLS 1/2 Spent Fuel Cask Details, Configuration B " Sheet 1 of 4
N. Industries, Inc. 00/02/13 1p

DOCKETED ITEMS

285

DOCKET 71-9011 MODEL E-MH-00-00001. TRANSPORTATION. DEPT OF

0004010188 Forwards test rate levels to upgrade mail licenses
FEMDOL/C A. Plicker Corp 00/04/08 3pp

DOCKET 71-9018 MODEL TH-B. TRANSMACLEAR, INC

0005000033 Requests renewal of Certificate of Compliance 9018 For
Model TH-B packaging & 9016 for Model TH-B packaging
Forwards "TH-B & TH-B SAR" Vol 1 & 2 to Radiation S
COLDFARM, K Transnuclear, Inc 00/04/09 3pp

--0005000037 "TH-B & TH-B SAR" * Six oversize drawings encl
* Transnuclear, Inc 00/04/08 200pp

DOCKET 71-9018 MODEL TH-B, TRANSMACLEAR, INC

0005000033 Requests renewal of Certificate of Compliance 9018 For
Model TH-B packaging & 9016 for Model TH-B packaging
Forwards "TH-B & TH-B SAR" Vol 1 & 2 to Radiation S
COLDFARM, K Transnuclear, Inc 00/04/09 3pp

--0005000037 "TH-B & TH-B SAR" * Six oversize drawings encl
* Transnuclear, Inc 00/04/08 200pp

DOCKET 71-9018 MODEL BU-A. GENERAL ELECTRIC CO

0004100204 Application to amend Certificate of Compliance 9019 For BU-7
package to increase max bulk density of U oxide powder from
2.3 to 4.2 g/cc Amend fee encl
HAPLAN, A L General Electric Co, Nuclear Energy Products Div
00/05/10 3pp

--0004100208 Forwards Certificate of Compliance 9018 & 9019, authorizing
delivery of radioactive mail to carrier for transport in Models BU-A &
BU-7 under License 00W-54
HACEDONAL, C E Transportation Branch 74/08/04 3p

--0004100202 Certificate of Compliance 9019, authorizing delivery of
radioactive mail to carrier for transport in Models BU-A &
BU-7 under License 00W-54
HACEDONAL, C E Transportation Branch 74/08/04 4pp

--0004100210 Application to amend License 00W-54, to authorize delivery
of 00W to carrier for transport in Models BU-A & BU-7
TOSCHKE, A N General Electric Co 74/05/24 10pp

--0004100215 "GE Model BU-7 U Shipping Container Criticality Safety
Analysis"
ARTESM, R, WILSON, S B General Electric Co 0000-11277
74/02/08 3pp

DOCKET 71-9019 MODEL BU-7. GENERAL ELECTRIC CO

0004100204 Application to amend Certificate of Compliance 9019 For BU-7
package to increase max bulk density of U oxide powder from
2.3 to 4.2 g/cc Amend fee encl
HAPLAN, A L General Electric Co, Nuclear Energy Products Div
00/05/10 3pp

--0004100208 Forwards Certificate of Compliance 9018 & 9019, authorizing
delivery of radioactive mail to carrier for transport in Models BU-A &
BU-7 under License 00W-54
HACEDONAL, C E Transportation Branch 74/08/04 3p

--0004100210 Certificate of Compliance 9019, authorizing delivery of
radioactive mail to carrier for transport in Models BU-A &
BU-7 under License 00W-54
HACEDONAL, C E Transportation Branch 74/08/04 4pp

--0004100215 Application to amend License 00W-54, to authorize delivery
of 00W to carrier for transport in Models BU-A & BU-7
TOSCHKE, A N General Electric Co 74/05/24 10pp

--0004100215 "GE Model BU-7 U Shipping Container Criticality Safety
Analysis"
ARTESM, R, WILSON, S B General Electric Co. 0000-11277
74/02/08 3pp

DOCKET 71-9023 MODEL AL-1-10/24. HL INDUSTRIES, INC

0004100295 Recommends issuance of IAEA Certificate of Competent
Authority for HL Industries Model AL-1-10/24 as Type B(II)
package in response to license 000027 request
HACEDONAL, C E Transportation Branch 00/04/03 1p

DOCKET 71-9028 MODEL 650. TECHNICAL OPERATIONS, INC

0002700411 Notification of registration as user of Model 650
HACEDONAL, C E Transportation Branch 00/05/09 1p

DOCKET 71-9029 MODEL 715. TECHNICAL OPERATIONS, INC

0004100341 Requests continued registration as user of Model 715 mail
shipping package
CONWAY, W F Capital X-Ray Service 00/05/12 1p

0004100342 Requests renewal of Certificate of Compliance 9029 For
Technical Operations Model 715 shipping package
DALLINGER, J F General Dynamics Corp Electric Boat Div 00/05/13
1p

0004100440 Advises that Model 715, authorized by Certificate of
Compliance 9029, meets IAEA requirements for Type B(II)
package
HACEDONAL, C E Transportation Branch 00/05/07 1p

0004020111 Requests registration as user of Tech/Ops Model 715.
HARR, C N High Steel Structures, Inc 00/05/09 1p

0004100300 Notifies of registration as user of Model 715
HACEDONAL, C E Transportation Branch 00/06/02 1p

0004100302 Requests registration as user of Genco Industries Model
0215-0 Technical Operations Model 715
DANIEL, C C Nuclear Energy Services, Inc 00/06/04 1p

0004030108 Notification of registration as user of Model 715 in
response to request
HACEDONAL, C E Transportation Branch 00/06/10 1p

DOCKET 71-9044 MODEL GE-1600. GENERAL ELECTRIC CO.

0003200044 Requests renewal of Certificate of Compliance 9044 For Model
1600 shipping cask Oversee revised cask drawings to support
of application & payment fee encl I/A renewal fee
CUMMINGS, D E General Electric Co 00/04/09 10pp

--0003200075 "Hysac & Pump"
* General Electric Co 77/08/03 1p

--0003200075 "Hysac Control Drawing Model 1600 Seal," Sheet 1
* General Electric Co 80/04/17 1p

--0003200083 "Lifting Device Cover & Lock Assembly,"
* General Electric Co 85/03/31 1p

--0003200087 "Reinforced Car"
* General Electric Co 78/10/10 1p

--0003200091 Model 1600 Jacket Tie-Down Yoke," Sheet 1,
* General Electric Co 79/10/10 1p

--0003200095 "Model 1600 Transport Container Assembly"
* General Electric Co 79/10/11 1p

--0003200100 "Base, Model 1600 Cask"
* General Electric Co 79/10/10 1p

--0003200105 "Shielding Liner 24-Inch Diameter Lead Model 1600"
* General Electric Co 79/10/10 1p

--0003200111 "Facets, Model 1600,"
* General Electric Co 79/10/10 1p

--0003200115 "Neutron Shielding Liner"
* General Electric Co 79/03/10 1p

DOCKETED ITEMS

--800590120 "Model 1400 Shipping Cask"
* General Electric Co 79/10/10 1p

--800590120 "Model 1400 Cask/Independent Suspension Bars"
* General Electric Co 79/10/10 1p

800400549 Requests registration as user of Model GE-1400
HARRY.H Georgia Power Co 80/04/30 1p

800400541 Requests registration as user of Models 8144, GE-1400, PG-1,
GE-48-200, LL-30-100 & LL-20-4
HARRY.H Georgia Power Co 80/04/30 1p

800400544 Forwarded 10P & analysis that should have been included w/
800400549 request for Certificate of Compliance 9044
CUMMINGS.H.G.E General Electric Co 80/05/07 1p

--800410040 Application to amend License BR-765 to increase allowable
loading of flexible mat to 3200 g
CUMMINGS.H.G.E General Electric Co, Nuclear Energy Products Div.
79/07/03 10pp.

800400517 advises unit of registration as user of Models B-2, GE-1400,
DND-4-65, DND-14-100, LL-30-100 & LL-20-4
KACDONALD.G.E Transportation Branch 80/05/03 2pp

DOCKET 71-9040 MODEL GE-1000, GENERAL ELECTRIC CO

800400303 Requests renewal of Certificate of Compliance 9040 for GE
Model 1000 shipping container. Revised consolidated
application & revised drawings w/nc1
CUMMINGS.H.G.E General Electric Co 80/04/20 13pp

--800400303 "Jacket, 1,000 Series Cask"
* General Electric Co 80/03/26 1p

--800400304 "Cask, 1,000 Series"
* General Electric Co 80/03/26 1p

--800400304 "Rear, 1,000 Series Cask"
* General Electric Co 80/03/26 1p

--800400304 "Shipping Assembly, 1,000 Series Cask"
* General Electric Co 80/03/26 1p

DOCKET 71-9046 MODEL GE-1100, GENERAL ELECTRIC CO

800507030 Requests renewal of Certificate of Compliance 7046 for Model
1100 shipping container. Revised consolidated application
supporting request & revised drawings w/nc1
CUMMINGS.H.G.E General Electric Co 80/04/22 13pp.

--800507030 "Jacket, 1100 Series Cask"
* General Electric Co 80/03/26 1p.

--800507030 "Shipping Cask Assembly"
* General Electric Co 80/03/26 1p.

--800507030 "Cask, 1100 Series Cask"
* General Electric Co 80/03/26 1p.

--800507030 "Rear, 107 Series Cask"
* General Electric Co 80/03/26 1p

DOCKET 71-9050 MODEL GE-900, GENERAL ELECTRIC CO

800400019 Requests renewal of Certificate of Compliance 9050 for GE
Model 900 shipping container. Forwarded revised consolidated
application, revised drawings & revised file
CUMMINGS.H.G.E General Electric Co 80/04/18 13pp

--800400022 "Jacket Assembly, 900 Series Cask"
* General Electric Co 80/03/20 1p

--800400022 "Rear - 400, 900 & 1,400 Series Cask"
* General Electric Co 80/03/20 1p

--800400031 "Shipping Assembly, 900 Series Cask"
* General Electric Co 80/03/20 1p

DOCKET 71-9051 MODEL GE-1400, GENERAL ELECTRIC CO

800400047 "Rear - 400, 900, 1,400 Series Cask"
* General Electric Co 80/03/20 1p

--800400070 "Jacket Assembly - 1400 Series Cask"
* General Electric Co 80/03/20 1p

--800400070 "Shipping Assembly - 1400 Series Cask"
* General Electric Co 80/03/20 1p

--800400070 "Shipping Cask Assembly, 1,000 C1 Co-M - 1400 Series Cask"
* Bull Co 80/01/07 1p

DOCKET 71-9070 MODEL N-26, ENERGY DEPT OF

8004000179 advises that vendor will ship 3 nCi Co-57 sealed sources
under general license
VERMILION.P.D Naves Corp Analytical Instrument Div 80/04/29 1p

800400010 Notifies of registration as user of Model N-26
KACDONALD.G.E Transportation Branch 80/04/03 1p

DOCKET 71-9071 MODEL AP-101, CH2M-NUCLEAR WTB, INC

800400004 Forwarded "Amend to ASNPED, Inc. SAR, Cask AP-101, Section 4
Criticality & Section 7 Operating Procedures" w/nc1
complete petition to amend Certificate of Compliance 9071
to include spent fuel assemblies as contents
KEMPIN.W.B Amec/Inc 80/03/16 2pp

--800400004 "Amend to ASNPED, Inc. SAR, Cask AP-101, Section 4
Criticality & Section 7 Operating Procedures"
* Amec/Inc 80/05/15 10pp

DOCKET 71-9073 MODEL GH-140, NUCLEAR PACKAGING, INC

8004000149 Advances of address change effective 7/9/82
KOBORN.D Nuclear Packaging, Inc 80/05/12 1p

DOCKET 71-9074 MODEL HN-100 SERIES 2, HITTMAN NUCLEAR & DEVELOPMENT

800507024 Requests that Certificate of Compliance 7074 for Model HN-
100 be amended to cover use of nonstructural appurtenances.
Forwarded Drawing 0001-4-9119, Revision E, Sheets 1 to 7
Amend file forwarded in 7/82/10 1st Drawings in Central Files
HILL.D.R.C M. Hittman Nuclear & Development Corp (subs. Hittman
Corp.) 80/03/17 2pp

--800507024 "Assembly Transportation Shield Model HN-100 Series-2"
Sheet 1 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Cask Body HN-100-2 Transportation
Shield" Sheet 2 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Cask Body HN-100-2 Transportation
Shield" Sheet 3 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Primary Lid HN-100-2 Transportation
Shield" Sheet 4 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Primary Lid HN-100-2 Transportation
Shield" Sheet 5 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Primary Lid HN-100-2 Transportation
Shield" Sheet 6 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

--800507024 "Shield & Details Secondary Lid HN-100-2 Transportation
Shield" Sheet 7 of 7
* Hittman Nuclear & Development Corp (subs. Hittman Corp.)
80/03/17 1p

DOCKETED ITEMS

267

- 8005700319 "Optional Cash Appurtenances HN-100 Series-2 " Sheet 7 of 7
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/17 1p
- 8005690403 Requests amend to Certificate of Compliance 7074,reviving drawings to show critical features of cash which are part of safety analysis (needed for eval)
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/09 2pp
- 8005690407 "Assembly Transportation Shield HN-100 Series-2 " Sheet 1 of 1
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/14 1p
- 8005690409 "Unidirectional Cash Body Transportation Shield HN-100 Series 2 " Sheet 1 of 1
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/13 1p
- 8005690441 "Cyclon Cash Appurtenances Transportation Shield HN-100 Series-2 " Sheet 1 of 1
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/13 1p
- 80056906276 Forwards Revision 3 to Certificate of Compliance 9079 for Model HN-100 Series 2 Shipping Package
MAGDONALD, C E Transportation Branch 8/03/05/23 2pp
- 80056906282 Certificate of Compliance 7079,Revision 3,for Model HN-100 Series 2 shipping package
MAGDONALD, C E Transportation Branch 8/03/05/23 2pp
- DOCKET 71-7074 MODEL CM81-1400-H, CHEN-NUCLEAR SYSTEMS, INC

8005690478 Requests registration as user of Model CM81-1400
MURRAY, T B Toledo Edison Co 8/03/05/06 1p
- 80056907024 Notifies of registration as user of Model CM81-1400
MAGDONALD, C E Transportation Branch 8/03/05/03 1p
- DOCKET 71-7078 MODEL HN-100 SER1013, HITTMAN NUCLEAR & DEVELOPMENT
- 80057012081 Requests that Certificate of Compliance 7078 for Model HN-100 Series 1 be amended to cover use of nonstructural appurtenances Forwards Drawing C001-5-9102,Sheet 1 & list of requested changes in Certificate of Compliance 7078
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/17 2pp
- 8005701302 "Optional Cash Appurtenances HN-100, Series 1." Sheet 1 of 1
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/17 1p
- DOCKET 71-7074 MODEL HN-100 S, HITTMAN NUCLEAR & DEVELOPMENT CORP

- 8005702540 Requests that Certificate of Compliance 9079 for Model HN-100 Series 2 be amended to cover use of nonstructural appurtenances Forwards Drawing C001-5-9102,Sheet 1 & list of requested changes in Certificate of Compliance 9079
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/17 2pp
- 800570264 "Optional Cash Appurtenances HN-100S, " Sheet 1 of 1
* Hittman Nuclear & Development Corp (subs Hittman Corp) 8/03/05/18 1p
- DOCKET 71-7071 MODEL 3D A, GENERAL ELECTRIC CO

- 8005690192 Requests registration as user of Model 3D A
SHELLEY, W J Rare-Robee Corp 8/03/03/28 1p
- DOCKET 71-7079 MODEL HN-100, HITTMAN NUCLEAR & DEVELOPMENT CORP.

- 80056902035 Notifies of expiration of Certificate of Compliance 7079 for Models HN-3003,Revision 3 & Revision 4 to continue using package,should request renewal of existing certificate of compliance
MAGDONALD, C E Transportation Branch 8/03/05/06 1p
- DOCKET 71-7074 MODEL CM81-1400-H, CHEN-NUCLEAR SYSTEMS, INC

- 8005700516 Forwards consolidation of application & SAR for Model 14-195-H shipping Cash,overriding refs. In 750400 certificate of compliance,Revision 3 Includes Revision A-F to Drawing 14-195-H,Sheet for eval
CORRETT, J D Chen-Nuclear Systems, Inc 8/03/03/31 2pp
- 8005700522 Inform of refund resulting from overpayment of minor based fee for Certificate of Compliance 7074
MAGDONALD, C E License Fee Management Branch 8/03/04/17 1p
- 8005700525 "SAR for Model 14-195-H Shipping Cash
* Chen-Nuclear Systems, Inc 8/03/03/31 11pp
- 8005700528 "Transport Cash 14-195-H," Revision A-F
* Chen-Nuclear Systems, Inc 8/03/03/31 1p
- 8006030152 Forwards override Drawings 1-107-101 & 1-270-101,per 800509 telcon between D Degeerten & B Winda
* Chen-Nuclear Systems, Inc 8/03/05/09 1p
- 8006030161 "Transport Cash 14-195-H "
* Chen-Nuclear Systems, Inc 8/03/05/28 1p
- 8006030164 "Transport Cash 21-300 "
* Chen-Nuclear Systems, Inc 8/03/05/28 1p
- 8006030196 Requests registration as user of Model CM81-14-195-H
MURRAY, T B Toledo Edison Co 8/03/05/06 1p
- 8006030203 Forwards Revision 4 to Certificate of Compliance 9074 for Model CM81 14-195-H
MAGDONALD, C E Transportation Branch 8/03/05/20 2pp
- 8006030303 Certificate of Compliance 7074,Revision 4,for Model CM81 14-195-H
MAGDONALD, C E Transportation Branch 8/03/05/20 2pp
- 8006170615 Forwards Certificate of Compliance 7074,Revision 3,for Model CM81 14-195-H Supersede Revision 4,also 800500 Constitutes authority to use package for shipment of radioactive mail & for package to be shipped per code requirements
MAGDONALD, C E Transportation Branch 8/03/05/29 2pp
- 8006170617 Certificate of Compliance 7074,Revision 3,for Model CM81 14-195-H
MAGDONALD, C E Transportation Branch 8/03/05/29 2pp
- 8006170657 Notifies of registration as user of Model CM81-14-195-H
MAGDONALD, C E Transportation Branch 8/03/06/1A 1p
- DOCKET 71-7076 MODEL CM81-21-300, CHEN-NUCLEAR SYSTEMS, INC

- 8006170621 Forwards consolidated Application & SAR for manual of certificate of compliance for Model 21-300 Supersede all work in Certificate of Compliance 7076,Revision 2
CORRETT, J D Chen-Nuclear Systems, Inc 8/03/04/14 3pp
- 8006170623 Forwards override Drawings 1-107-101 & 1-270-101,per 800509 telcon between D Degeerten & B Winda
* Chen-Nuclear Systems, Inc 8/03/05/09 1p
- 8006170624 "Transport Cash 14-195-H "
* Chen-Nuclear Systems, Inc 8/03/05/28 1p
- 8006170626 "Transport Cash 21-300 "
* Chen-Nuclear Systems, Inc 8/03/05/28 1p
- 8006170628 Forwards Revision 3 to Certificate of Compliance 9076 for Model CM81 21-300
MAGDONALD, C E Transportation Branch 8/03/05/20 2pp
- 8006170629 Certificate of Compliance 7076,Revision 2,for Model CM81 21-300
MAGDONALD, C E Transportation Branch 8/03/05/20 2pp
- 8006170714 Authorizes extension of Certificate of Compliance 7076, Revision 2,until 800731 Extension will provide ordering transaction to implement packet and changes required by Revision 3 of certificate,also 800500
MAGDONALD, C E Transportation Branch 8/03/05/29 2pp

DOCKETED ITEMS

DOCKET 71-9103 MODEL, N.I.-4502

DO66105210 Responds to Appeal re partial denial of PCIA request for public info re spent fuel shipments from Chalk River to Ontario/Canada Appeal is denied info withheld (ref FDIA Exemption A & 10CFR2.401)
 DUNBAR, J. J. Office of the Executive Director for Operations
 80/05/09 2pp

--DO66105223 Certificate of Compliance 7103, Revision 1, for radioactive mail shipping package Model 71-1-4503
 MACDONALD, C. E. Transportation Branch 70/05/03 4pp

DOCKET 71-9113 MODEL, CMB-80A, CHEN-NUCLEAR, INC.

DO66040045 Notifies that facility will use Chen Nuclear, Inc. Model CMB 80-A-02 radioactive shipping tank for delivery of waste to carrier
 FAY, C. W. Wisconsin Electric Power Co. 80/05/14 1p

DO66170287 Notifies of registration as user of Model CMB-80A
 MACDONALD, C. E. Transportation Branch 80/04/03 1p

DOCKET 71-9113 MODEL, 7-10A, CHEN-NUCLEAR ENERGY, INC.

DO66040071 Requests registration as user of Model CMB-7-100 waste shipping package
 STANED, P. F. Ontario Public Power District 80/05/08 1p

DO66230318 Forwards revision bringing Certificate of Compliance 7113 in line w/Certificate 7000, issued for same package. Upgrades mail from A-02 to A-01A Grade 70, providing larger positive safety margin. Suggestive drawings and
 HANSEN, L. J. Nuclear Packaging, Inc. 80/05/09 2pps

--DO66230319 "Transportation Shield, Model 7-100, Type A," Sheet 1 of 2
 * Nuclear Packaging, Inc. 78/05/01 1p

--DO66230322 "Transportation Shield, Model 7-100, Type A," Sheet 2 of 2
 * Nuclear Packaging, Inc. 80/05/14 1p

DO66170285 Notifies of registration as user of Model 7-100,
 MACDONALD, C. E. Transportation Branch 80/04/03 1p

DOCKET 71-9132 MODEL, T-3, NUCLEAR PACKAGING, INC.

DO66040429 Forwards Revision 0 to Certificate of Compliance 7132 for Model T-3 and safety evaluation
 MACDONALD, C. E. Transportation Branch 80/05/21 1p

--DO66050423 Certificate of Compliance 7132, Revision 0, for Model T-3
 MACDONALD, C. E. Transportation Branch 80/05/21 4pp

--DO66050437 Safety evaluation approving Model T-3 cast
 MACDONALD, C. E. Transportation Branch, 80/05/21 1pp

DOCKET 71-9135 MODEL, CENTURY, OMAHA INDUSTRIES

DO66030047 Forwards request for mail info re 790504 application as amended DO6227 requesting approval to deliver Century model packaging to carrier for transport. Addl info should be submitted in form of revised pages to original SAR.
 MACDONALD, C. E. Transportation Branch 80/05/16 2pp

DOCKET 71-9135 MODEL, 7B-0-1450, NAVY, DEPT OF

DO66000465 Advises that request for info re container approval is being prepared & will be forwarded by DO6630
 MCNIGHT, T. R. Navy Dept of 80/05/28 1p

DOCKET 71-9141 MODEL, 900 TYPE B, TECHNICAL OPERATIONS, INC.

DO66090407 Forwards Revision 0 to Certificate of Compliance 7141 for Model 900 Type B & safety evaluation
 MACDONALD, C. E. Transportation Branch 80/05/30 1p

--DO66090410 Certificate of Compliance 7141, Revision 0, for Model 900 Type B
 * MACDONALD, C. E. Transportation Branch 80/05/30 2pp

--DO66090413 Safety evaluation approving Model 900 Type B packaging
 MACDONALD, C. E. Transportation Branch 80/05/30 2pp

DO66090483 Advises that Model 900, authorized by Certificate of Compliance 7141, meets requirements for Type B(U) packages
 MACDONALD, C. E. Transportation Branch 80/05/30 1p

DOCKET 71-9083 MODEL, ORNL - SHL - NSB UN FUEL CONTAINER, ENERGY.

DO66040088 Forwards as-built ORNL drawings for shipping container per NSC request
 TWAIB, W. H. Energy Dept of 80/05/03 1p

--DO66040089 "Unirradiated Fuel Element Shipping Container Details," as-built Sheet 2 of 2
 * Union Carbide Corp. 79/02/30 1p

--DO66040089 "Unirradiated Fuel Element Shipping Container Assembly," as-built Sheet 1 of 1
 * Union Carbide Corp. 80/02/06 1p

--DO66040102 "Unirradiated Fuel Element Shipping Container Details," as-built Sheet 2 of 2
 * Union Carbide Corp. 80/02/06 1p

--DO66040105 "Unirradiated Fuel Element Shipping Container Assembly," as-built Sheet 1 of 1
 * Union Carbide Corp. 80/02/06 1p

--DO66040107 "Unirradiated Fuel Element Shipping Container Details," as-built Sheet 2 of 2
 * Union Carbide Corp. 80/02/06 1p

--DO66040109 "Unirradiated Fuel Element Shipping Container Assembly," as-built Sheet 1 of 1
 * Union Carbide Corp. 80/02/06 1p

DO66040421 Forwards Revision 1 to Certificate of Compliance 7083 for Model ORNL-SHL-NSB unirradiated fuel shipping container shipping packages
 MACDONALD, C. E. Transportation Branch 80/05/22 4pp

--DO66040425 Certificate of Compliance 7083, Revision 1, for Models ORNL-SHL-NSB unirradiated fuel shipping container shipping packages
 MACDONALD, C. E. Transportation Branch 80/05/22 3pp

NONDOCKETED ITEMS

646FR COMMISSION MEETING RECORDS

800310017a Transcript of 800303 briefing on assessment of cleanup at THT
 Pg 1-45
 * Commission 80/02/05 45pp

--800310018 Forwards "Evaluation of Cleanup Activities at THT," rept of special task force formed on 800219 Latic actions to be taken in order to respond forward action to cleanup process
 DIRRER, W J Office of the Executive Director for Operations
 80/02/29. 8pp

8003270078 Forwards notice of 800309 & 27 meetings of Advisory Screening Committee For Lawyer Members Requests 800425 FR publication
 HOLLE, J C ACR - Advisory Committee on Reactor Refuguards
 80/04/23 1p

--8003270081 Notice of 800309 & 27 meetings of Advisory Screening Committee For Lawyer Members
 HOLLE, J C Office of the Secretary of the Commission 80/04/23 1p

8004040215 Transcript of 800415 public meeting in Bethesda, MD re withdrawal of HRC spent fuel route info from public disclosure Pg 1-34
 * Commission 80/05/15 35pp.

8004120467 Transcript of 800428 afternoon Affirmation Session 80-23 re SECT-A-80-74 in Washington, DC Pg 1-3
 * Commission 80/05/28. 3pp

8004120482 Transcript of 800515 briefing in Bethesda, MD re upgrade of operations for P-13 Morning session
 * Commission 80/05/15 73pp.

8004130487 Forwards notice of Commission meetings during wk of 800519 for publication in 800519 FR
 CHILK, S J Office of the Secretary of the Commission 80/05/15 1p

--8004130491 Notice of Commission meetings during wk of 800519 to discuss org-organization & internal personnel matters
 THEBER, R H Office of the Secretary of the Commission. 80/05/16 1p

8004130509 Transcript of 800406 public meeting in Washington, DC re discuss action plan policy statement Pg 1-25
 * Commission 80/06/06 25pp

8004130579 Forwards notice of Commission meetings during wk of 800603 for publication in 800606 FR.
 CHILK, S J Office of the Secretary of the Commission 80/05/01 1p.

--8004130583 Notice of Commission 800605, 06 & 07 meetings in Washington, DC re revised Philippine opinion, affirmation items & cost reimbursement at Manila 9011.
 THEBER, R H Office of the Secretary of the Commission. 80/04/29 1p.

8004230487 Forwards notice of availability of draft safety guide for public comment.
 CHILK, S J Office of the Secretary of the Commission 80/05/08 1p.

--8004130591 Notice of availability of draft safety guide for public comment.
 HUNTER, R S. Office of Standards Development, Director 80/04/29 2pp

8004130100 Forwards notice of Commission meetings during wk of 800505 for publication in 800506 FR.
 CHILK, S J Office of the Secretary of the Commission 80/05/06 1p

--8004130103 Notice of Commission 800512 meeting in Washington, DC re meeting w/Herzberg-Riesleum area citizen groups re THT-2 cleanup
 FMOSE, W Office of the Secretary of the Commission 80/05/05 1p.

8004140147 Informs that Commission approved proposed 1st re McDonough re retransfer of medium enriched U to South Africa sub j to listed and
 CHILK, S J Office of the Secretary of the Commission 80/04/03 1p

8004170500 Transcript of 800515 Affirmation Session 80-22 in Bethesda, MD Pg 1-4 afternoon session draft FR notice incl
 * Commission 80/05/15 14pp

8004170497 Transcript of 800514 discussion of SECT-80-230 in Washington, DC Pg 1-30 Morning session
 * Commission 80/05/16 31pp

8004180128 Transcript of 800503 Affirmation Session 80-26 in Washington, DC Pg 1-2
 * Commission 80/05/30 3pp

--8004180132 DEE-V-00-1002
 Recommends approval of wst revised draft under Sect PA
 Bradford verbatim statement to be appended to order.
 BIGHART, L Office of the General Counsel 80/05/29. 1pp.

--8004180138 Responds to 800324 ltr to J. Adams re problems of evacuating large populations in short period of time
 Program of upgrading emergency planning is being carried out by SSC teams who visit each site of operating nuclear plants.
 BOSTON, H M Office of Nuclear Reactor Regulation, Director
 80/04/29 2pp

--8004180149 Elaborates on concerns expressed in 800322 ltr re need for practical evacuation plans around nuclear power sites
 Problems of evacuating large populations in short time have been underestimated Requests open hearing on issues
 WOLF, R Affiliation Subarea 80/05/24 2pp

8004180546 Transcript of 770231 Commission briefing on South Africa in Washington, DC Pg 1-3 Afternoon session
 * Commission 77/03/31 10pp

8004180176 Transcript of 800512 Affirmation Session 80-21 in Washington, DC Pg 1-4 Afternoon session.
 * Commission 80/05/12 7pp

8004180482 Transcript of 800404 public meeting in Washington, DC to discuss action plan Pg 1-45.
 * Commission. 80/06/04 46pp

8004180483 Transcript of 800606 meeting re site characteristics in Washington, DC Pg 1-27
 * Commission. 80/06/06 28pp.

8004180488 Transcript of 800605 Affirmation Session 80-27 in Washington, DC Pg 1-3
 * Commission 80/06/05 4pp

8004180483 Transcript of 800528 open Affirmation Session 80-24 in Washington, DC re SECT-A-80-74 & SECT-80-232 Pg 1-3
 * Commission 80/05/23 4pp

NONDOCKETED ITEMS

--0004200949 SECY-00-002

Discusses role of NRC in waste confidence proceeding
Recommendations issued of proposed mechanisms to order draft
regulation & order rule
BICSMIT, L. Office of the General Counsel 00/04/24 4pp

0004200950 Transcript of 000412 public meeting in Washington, DC to
discuss progress, status & plans of Nuclear Safety Analysis
Civ. Pp. 1-104 Videographs and
* Commission 00/04/12 100pp

0004200978 Forwards IAEA draft safety guide notice of availability for
public comment for FR publication in earliest possible date
CHILK, S. J. Office of the Secretary of the Commission 00/04/04
1p

--0004200980 Notice of availability of IAEA draft safety guide for public
comment
BETH, R. D. Office of Standards Development, Director 00/04/02
1pp

0004200981 Forwards Sunshine FR notice of Commission meetings during wk of
000419, for 000419 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/03/19
1p

--0004200986 Sunshine FR notice of Commission meetings during wk of
000419
HARRIS, W. Office of the Secretary of the Commission 00/03/15
1p

0004200987 Forwards Sunshine FR notice of Commission meetings during wk of
000419, for 000419 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/02
1p

--0004200988 Sunshine FR notice of Commission meetings during wk of
000419 to discuss Indian Point revised order
HARRIS, W. Office of the Secretary of the Commission 00/03/15
1p

0004200989 Forwards Sunshine FR notice of Commission meetings during wk of
000419, for 000419 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/03/02
1p

--0004200990 Sunshine FR notice of Commission meetings during wk of
000419
HARRIS, W. Office of the Secretary of the Commission 00/03/15
1p

0004200991 Forwards FR notice of Commission meetings during wk of
000419, for 000419 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/04
1p

--0004200992 FR notice of Commission meetings during wk of 000409, for
publication in 000409
HARRIS, W. Office of the Secretary of the Commission 00/04/03
1p

0004200993 Forwards notice of Commission meetings during wk of 000419
for 000419 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/03/23
1p

--0004200994 Sunshine FR notice of Commission meetings during wk of
000419 & 000419 to discuss self-organization & internal
personnel matters & review ALAP-002
HARRIS, W. Office of the Secretary of the Commission 00/03/23
1p

0004200995 Transcript of 000412 discussion & vote on affirmation item
in Washington, DC Pp. 1-12, Draft orders & separate views of
Commissioners Draft rule
* Commission 00/04/12, 00pp

--0004200996 SECY-00-071A

Forwards draft revision to TMI action plan statement of
policy reflecting changes made as result of 000406
Commission meeting, made to language & minor editorial
changes
BICSMIT, L. Office of the General Counsel 00/04/11, 10pp

0004200997 Forwards notice of issuance of appointment of performance
review board for Senior Executive Div for earliest possible
FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/03/15
1p

--0004200998 Notice of issuance of appointment of performance review
board for Senior Executive Div for earliest possible
FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/03/09 2pp

0004200999 Forwards notice of Commission meetings during wk of 000409
for publication in 000409 FR
CHILK, S. J. Office of the Secretary of the Commission 00/03/02
1p

--0004200999 Notice of Commission 000409 meeting in Washington, DC re self-
organization internal personnel & action plan
HARRIS, W. Office of the Secretary of the Commission 00/03/01
1p

0004200999 Forwards notice of Commission 000409 meeting in Washington,
DC for publication in 000409 FR
CHILK, S. J. Office of the Secretary of the Commission 00/03/06
1p

--0004200999 Notice of Commission 000409 meeting in Washington, DC to
discuss Philippine export & SEP
HARRIS, W. Office of the Secretary of the Commission 00/03/01
1p

0004200999 Forwards Sunshine FR notice of Commission meeting during wk of
000409, for publication in 000409
CHILK, S. J. Office of the Secretary of the Commission 00/03/30
1p

--0004200999 Sunshine FR notice of Commission meeting during wk of
000409
HARRIS, W. Office of the Secretary of the Commission 00/03/29
1p

0004200999 Forwards notice of Commission meetings during wk of 000409
for publication in 000409 FR
CHILK, S. J. Office of the Secretary of the Commission 00/03/09
1p

--0004200999 Notice of Commission meetings during wk of 000409 to
discuss Philippine export
HARRIS, W. Office of the Secretary of the Commission 00/03/01
1p

0004200999 Forwards notice of Commission meetings during wk of 000412
for publication in 000412 FR
CHILK, S. J. Office of the Secretary of the Commission 00/03/09
1p

--0004200999 Notice of Commission 000412, 13 & 15 meetings in Washington,
DC re TMI-2 cleanup, transport, export licenses, operations, etc.
upgrade & protection of existing info
HARRIS, W. Office of the Secretary of the Commission 00/03/09
1p

0004200999 Forwards FR notice of 000409, 0406 & 09 closed meetings of
Advisory Steering Committee for Larger Variations on ALAP,
for publication on earliest possible date
CHILK, S. J. Office of the Secretary of the Commission 00/03/19
1p

--0004200999 FR notice of 000409, 0406 & 09 closed meetings of Advisory
Steering Committee for Larger Variations on ALAP,
for publication on earliest possible date
CHILK, S. J. Office of the Secretary of the Commission 00/03/19
2pp

0004200999 Transcript of Commission 000410 public meeting in
Washington, DC re final rulemaking on emergency preparedness
Pp. 1-10
* Commission 00/04/16 100pp

0004200999 Transcript of 770406 meeting in Washington, DC re development
of evaluation program Prepared from tape recording Pp. 1-52
* Commission 77/04/05, 00pp

0004200999 Transcript of 770321 briefing in Washington, DC re Edlow
into GO application he reports 0001 to India Pp. 1-62
* Commission 77/03/21, 40pp

NONDOCKETED ITEMS

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

000230084 Discusses review of draft WREG-0450 during 00010-12 meeting. Comprehensive discussion of issues important to safety and subsequent termination of licensing reactor safety improvements should be developed.
PLUMMER, N. S. ACRS - Advisory Committee on Reactor Safeguards
00/01/10 2pp

000230007 Forwards notice of ACRS Ad Hoc Subcommittee on Class 9 Accidents 00007 meeting Request 00048 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/21 1p

000230032 Notice of ACRS Ad Hoc Subcommittee on Class 9 Accidents 00007 meeting in Chicago, IL. Meeting originally scheduled to be held 00004 in Washington, DC
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/21 2pp

000230107 Forwards change notice for ACRS Subcommittee on Reactor Fuel 00049 meeting Request 00045 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/22 1p

000230118 Notice of ACRS Subcommittee on Reactor Fuel 00049 meeting change. Portions of meeting may be closed
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/22 1p

000230247 Forwards notice of ACRS 000510-20 & 20-29 meetings w/ German Reactor Safety Committee & French Group Permanent-Reactor-Reactor, respectively Request 00001 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/25 1p

000230293 Notice of ACRS 000519-20 & 20-29 meetings w/ German Reactor Safety Committee & French Group Permanent-Reactor-Reactor, respectively
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/25 2pp

000230274 Forwards notice of ACRS Subcommittee on Regulatory Activities 00040 meeting Request 00048 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/19 1p

000230289 Notice of ACRS Subcommittee on Regulatory Activities 00040 meeting
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/19 1pp

000230380 Forwards notice of ACRS Subcommittee on Metal Components 00044 meeting agenda & location change Request 00041 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/16 1p

000230209 Notice of change of location and date of ACRS Subcommittee on Reactor Components 00044 meeting. Meeting will now only 1 day, rather than 2 & will be held at House of Science & Energy, rather than ORNL.
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/16 1p

000230374 Forwards change notice of ACRS Subcommittee on Reliability Probabilistic Assessment 00040 meeting Request 00042 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/22 1p

000230399 Notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 00040 meeting change. Portions of meeting may be closed
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/22 1p

000230240 Forwards notice of ACRS Subcommittee on Site Evaluation & Reactor Radiological Effects joint 00002 & 22 meeting.
Request 00004 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/29 1p

000230306 Notice of ACRS Subcommittee on Site Evaluation & Reactor Radiological Effects joint 00002 & 22 meeting
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/29 1pp

000270043 Forwards notice of ACRS Subcommittee on Reactor Radiological Effects 00043 meeting to be published on 00003
CHILK, S. J. Office of the Secretary of the Commission 00/04/20 1p

000270053 Notice of ACRS Subcommittee on Reactor Radiological Effects 00043 meeting in Washington, DC to review nuclear power plant radiological protection programs
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/20 2pp

000270055 Forwards notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 00040 meeting to be published on 00013
CHILK, S. J. Office of the Secretary of the Commission 00/04/10 1p

000270067 Notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 00040 meeting to be published on 00013
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/09 2pp

000270029 Forwards notice of ACRS 000501-03 meeting Request 00040 FR publication
CHILK, S. J. Office of the Secretary of the Commission 00/04/24 1p

000270054 Notice of ACRS 000501-03 meeting to miscellaneous matters of ACRS activities
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/22 1pp

000270026 Forwards notice of ACRS Subcommittee on Concrete & Concrete Structures 00042-23 meeting to be published on 00047
CHILK, S. J. Office of the Secretary of the Commission 00/04/22 1p

000270019 Notice of ACRS Subcommittee on Concrete & Concrete Structures 00042-23 meeting to review of user needs in structural engineering
HOLTE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/21 2pp

000270049 Discusses ACRS 000501-03 meeting. ACRS strongly recommends assignment of specific identification numbers to proposed tag guides prior to submittal for ACRS review. Concurrently released on Revision 1: Reg Guide 1.144
PLUMMER, N. S. ACRS - Advisory Committee on Reactor Safeguards
00/05/06 2pp

000270044 Transcript of ACRS Joint Subcommittee on Site Evaluation & Reactor Radiological Effects 00052 meeting. Listing of viewpoints & description of atmospheric dispersion research program and C
ACRS - Advisory Committee on Reactor Safeguards 00/05/22 12pp

000270017 Transcript of ACRS Subcommittee on Regulatory Activities 00044 meeting in Washington, DC Pg 1-128
ACRS - Advisory Committee on Reactor Safeguards 00/05/04 12pp

000270010 Transcript of ACRS Subcommittee on Reactor Safety Research 00040 meeting in Washington, DC Pg 1-24
ACRS - Advisory Committee on Reactor Safeguards 00/05/02 25pp

000270032 Transcript of ACRS Subcommittee on Extreme External Phenomena 00044 meeting in Washington, DC Pg 1-28
ACRS - Advisory Committee on Reactor Safeguards 00/05/04 28pp

000270010 Transcript of ACRS Subcommittee on Extreme External Phenomena 00044 meeting in Washington, DC Pg 289-414
ACRS - Advisory Committee on Reactor Safeguards 00/05/04 29pp

000270029 Discusses comparative suitability of LWRs for electric power generation. Next generation of nuclear plants will need to be self-sufficient.
EPRI, E. P. ACRS - Advisory Committee on Reactor Safeguards 00/04/01 1pp

000270025 Discusses feasibility of designing containment that can withstand core melt. Blay could be designed based on present information about its response.
GATTONE, J. ACRS - Advisory Committee on Reactor Safeguards 00/04/25 1pp

- 0006160294 Summary of ACRS Subcommittee on Concrete Structures Subcommittee 000425
SUBCOM-1 Franklin Institute/Franklin Research Center 00/04/25 3pp.
- 0006160295 Comments on ACRS Subcommittee on Natural Circulation 000424
meeting Document on possible developing new technology
LIEBMAN, J. H. KATZ, Univ. of 00/04/25 4pp
- 0006160299 Comments on NUREC-0667 NUREC should be issued as guide only
a industry invited to originate own implementation details
in alternative NUREC should be made part of action plan
ZUMARS, J. Franklin Institute/Franklin Research Center 00/04/20
2pp
- 0006160302 Summary of ACRS Site Evaluation Subcommittee 000424 meeting
in Washington, DC re proposed emergency planning rule
* ACRS - Advisory Committee on Reactor Safeguards 00/05/16 10pp
- 0006160304 Summary of ACRS Subcommittee on Reactor Safety Research
000424 meeting in Washington, DC re PWR1 & PWR2 research
budgets
* ACRS - Advisory Committee on Reactor Safeguards 00/04/28 14pp
- 0006160307 Summary of ACRS Reactor Radiological Effects Subcommittee
000424 meeting in Washington, DC re radiological safety
evaluation program for operating plants
* ACRS - Advisory Committee on Reactor Safeguards 00/05/16 7pp
- 0006160308 Summary of ACRS BW Reactor Subcommittee 000428
meeting in Washington, DC re BW reactor sensitivity to
feedwater transients
* ACRS - Advisory Committee on Reactor Safeguards 00/04/17 12pp
- 0006160309 Summary of ACRS Subcommittee on Regulatory Activities 000429
meeting in Washington, DC re regulatory guides & rules
* ACRS - Advisory Committee on Reactor Safeguards 00/05/01 16pp
- 0006160309 Discussion draft final rules 10CFR50 & 70 on emergency
planning, NRC-NRRA approach should be developed & implemented
to encourage state & local agencies to incorporate federal
efforts into their emergency planning
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/11 2pp.
- 0006160306 Discussion proposed position on seismic screen NRC does not
have position for or against seismic screen. Recommends that
NRC initiate modest study of effects of seismic screen on
various accident or transient scenarios
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/11 1p.
- 0006160307 Discussion seismic qualification of PWR auxiliary feedwater
sys. Recommends that NRC apply dual purpose to complete
review of affected plants. ULHS should perform independent
review on same time scale.
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/10 1p.
- 0006160309 Response to 000401 request for add info re ACRS comments
on 000341 for concerning near-term ULHS from Draft 3
of NRC Action Plan Appendix of draft of referenced
proposal will be possible only after reference study.
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/10 2pp
- 0006160301 Comments on NUREC-0667 "Transient Response of BWR-Designed
Reactors." Expresses concern that recommendations in report
show continuation of NRC toward sound less flexibility in
evaluation of safety issues.
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/10 2pp
- 0006160311 Discussion Reacting of quantitative estimates into seismic
safety evaluation. ACRS wishes to develop rationale for
including estimates in decision-making process. Requests
update re NRC efforts to develop rationale
FLEISHER, M. D. ACRS - Advisory Committee on Reactor Safeguards
00/04/10 1p
- 0006160302 Comments on 000424 re hot fluids meeting on natural
circulation. Recommendation should be encouraged to solve heat
loss problem on Priority 1 basis. LOST instrumentation group
needs to be initiated & needs to be unambiguous
CATCOM-1 ACRS - Advisory Committee on Reactor Safeguards
00/09/03 1p
- 0006160309 Comments on ECRS & Natural Circulation Subcommittee
000325-26 meetings. Recommendation should be used soon for
series of scaling experiments to determine amount of
noncondensable gas necessary to degrade reflux boiling mode
CATCOM-1 ACRS - Advisory Committee on Reactor Safeguards
00/05/03 2pp
- 0006160310 Discussion 000411-12 WRA/less Germany suit research program
review & info exchange meeting & Denning recommendation for
support of Refluxed mode. Request include uncertainties in extent of
boundary conditions
CATCOM-1 ACRS - Advisory Committee on Reactor Safeguards
00/04/10 4pp
- 0006160303 Discussion ACRS Subcommittee on Concrete & Castable
Structures 000425-26 meeting Adequate recommendations for
integrating results of related research efforts by industry
sponsored groups & govt organizations not apparent
PICHLE, T. H. Stein Corbide Corp 00/04/16 2pp
- 0006160301 Transcript of 000428 ACRS meeting on 000405 in Washington, DC
Pg 3-254
* ACRS - Advisory Committee on Reactor Safeguards 00/06/09
27pp
- 0006160309 Transcript of 000428 ACRS open session on 000406 in
Washington, DC Pg 330-389
* ACRS - Advisory Committee on Reactor Safeguards 00/06/06 43pp
- 0006160307 Requests brief, written status report re overall effort by DPE
of Nuclear Reactor Regulation in area of pellet-clad
interaction. Should include discussion of whether fuel
failures would be increased by extending fuel burning limits
LIEBMAN, J. H. ACRS - Advisory Committee on Reactor Safeguards
00/07/27 1p.
- 0006160303 Summary of combined ACRS ECRS/Reactor Fuel Subcommittee
000414 meeting in Washington, DC re effects of externally
sourced thermocouples on LOST fuel rods
* ACRS - Advisory Committee on Reactor Safeguards 00/04/30 39pp
- 0006160303 Summary of ACRS Subcommittee on ATWS 000419 meeting in
Washington, DC re proposed regulation of ATWS
* ACRS - Advisory Committee on Reactor Safeguards 00/04/12 83pp
- 0006160304 Summary of ACRS Subcommittee on Metal Components 000424
meeting in Washington, DC re status of steam generator
problems
* ACRS - Advisory Committee on Reactor Safeguards 00/03/21 25pp
- 0006160309 Comments on 000424 natural circulation meeting re use of
LOFT/REINFORCE facilities in future research activities
How specific elements should be made up purpose of back
of instrumentation & programs used.
ACRHS, A. J. Affiliation Unknown 00/04/29 1p
- 0006160309 Notice of change of location of ACRS Ad Hoc Subcommittee on
THERMIT 2 Accident Action Plan 000401-02 meetings. Meetings
will be held in Room P-15B, Phillips Bldg, Bethesda, MD
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/03/19 1p.
- 0006160309 Notice of rescheduling of ACRS Subcommittee on Metal
Components meeting. Meeting will be held on 000424 at
American Museum of Natural History, 1200 York Ave, New York, NY
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/16 1p
- 0006160309 Notice of ACRS Procedures & Administration 000400 meeting
in Washington, DC.
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/14 1p
- 0006160309 Notice of ACRS Subcommittee on Metal Components 000424-25
meetings in Washington, DC to review heavy section steel
technology
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/16 2pp
- 0006160309 Notice of ACRS Ad Hoc Subcommittee on Natural Circulation
of Feed & Steam Heat Removal 000424 meeting in
Washington, DC.
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/16 2pp
- 0006160303 Notice of ACRS Subcommittee on ECRS 000405 in Washington, DC
HEYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards
00/04/16 2pp

NONDOCKETED ITEMS

293

- 8504190647 Summary of ACRS Waste Mgt Subcommittee 791221 meeting in Washington, DC to re-evaluate goals & priorities of NRC waste mgt & fuel cycle research program
ACRS - Advisory Committee on Reactor Safeguards 79/12/10 10pp
- 8504190648 Discusses Waste Mgt Subcommittee 791221 meeting. Forwards revised log to project classification matrices and 791222 memo
ACRS-Subcommittee P & Division of Safeguards 79/12/10 4pp
- 8504200339 Notice of ACRS Ad Hoc Subcommittee on ENI Unit 2 Accident Action Plan 800401-02 meeting in Washington, DC to continue consideration of Draft 2 of NURE-0640
NRC, J.C. Office of the Secretary of the Commission 80/03/10 2pp
- 8504200183 Summary of ACRS TH-R-2 Accident Bulletin & Orders Subcommittee 800304 meeting in Washington, DC
ACRS - Advisory Committee on Reactor Safeguards 80/04/22 13pp
- 8504200519 Notice of ACRS Subcommittee on ATIS 800326 meeting in Washington, DC
NRC, J.C. Office of the Secretary of the Commission 80/03/05 2pp
- 8504200503 Notice of proposed meetings of ACRS subcommittee-working group & full committee from 800205-0256
NRC, J.C. Office of the Secretary of the Commission 80/03/14 2pp
- 8504200418 Notice of ACRS Subcommittee on Site Evaluation 800432 meeting in Washington, DC to review DCPRS & NURE-0645
NRC, J.C. Office of the Secretary of the Commission 80/04/01 2pp
- 8504200323 Notice of ACRS Subcommittee on Reactor Safety Research 800409 meeting in Washington, DC to review DFC of Nuclear Regulatory Research response to ACRS recommendation to Congress re NURE-0647
NRC, J.C. Office of the Secretary of the Commission 80/03/20 2pp
- 8504200227 Notice of ACRS Subcommittee on B&M Water Reactors 800408 meeting in Washington, DC to complete review of NRC study to determine whether coast should be halted on certain B&M plants
NRC, J.C. Office of the Secretary of the Commission 80/03/18 2pp
- 8504200285 Notice of ACRS Subcommittee on Regulatory Activities 800409 meeting in Washington, DC
NRC, J.C. Office of the Secretary of the Commission 80/03/20 2pp
- 8504200288 Notice of ACRS Subcommittee on Power & Electrical Sys 800409 meeting in Washington, DC to discuss nuclear data 1pp
NRC, J.C. Office of the Secretary of the Commission 80/03/20 2pp
- 8504200568 Notice of ACRS Ad Hoc Subcommittee on TH-Unit 2 Accident Implications 800409 meeting in Washington, DC
NRC, J.C. Office of the Secretary of the Commission 80/03/20 2pp
- 8504200277 Notice of ACRS Subcommittee on Concrete & Concrete Structures 800325-26 meetings in Washington, DC to review work under in structural engineering
NRC, J.C. Office of the Secretary of the Commission 80/03/05 2pp
- 8504200584 Notice of change of date of ACRS Subcommittee on EOGS meeting. Meeting rescheduled to 800303
NRC, J.C. Office of the Secretary of the Commission 80/03/14 1p
- 8504200227 Notice of ACRS Subcommittee on Reactor Fuel 800424 meeting in Washington, DC to discuss NRC research program to reactor fuels for ACRS annual report to NRC & Congress
NRC, J.C. Office of the Secretary of the Commission 80/04/09 2pp
- 8504200224 Notice of rescheduling of date of ACRS Ad Hoc Subcommittee on Natural Circulation Heat Removal meeting to 800308. Title of subcommittee changed to ACRS Ad Hoc Subcommittee on Natural Circulation & Feed & Bleed Heat Removal
NRC, J.C. Office of the Secretary of the Commission 80/03/14 1p
- 8504200357 Notice of ACRS Subcommittee on Safeguards & Security 800424 meeting in Washington, DC to review pertinent portions of NRC research program re spent fuel storage pool consequences estimates from sabotage & plant security
NRC, J.C. Office of the Secretary of the Commission 80/04/08 2pp
- 8504200325 Notice of ACRS Subcommittee on EOGS 800424-25 meeting in Washington, DC to review research program re LDCAs & transients & LPT
NRC, J.C. Office of the Secretary of the Commission 80/04/04 2pp
- 8504200358 Notice of ACRS Subcommittee on Metal Components 800417-18 meeting in Washington, DC to review pertinent portions of NRC research program
NRC, J.C. Office of the Secretary of the Commission 80/05/22 2pp
- 8504200491 Notice of ACRS Subcommittee on Advanced Reactors 800418 meeting in Washington, DC to discuss NRC funding & program direction/terminations. Some closed sessions necessary
NRC, J.C. Office of the Secretary of the Commission 80/05/23 2pp
- 8504200499 Notice of ACRS Subcommittee on Regulatory Activities 800404 open meeting in Washington, DC to discuss proposed Reg Guide 1.23, Revision 1 & revisions to 10CFR50 & 55
NRC, J.C. Office of the Secretary of the Commission 80/05/16 2pp
- 8504200403 Notice of ACRS Subcommittee on Extreme External Phenomena 800404 meeting in Washington, DC to discuss criteria for seismic design of safe shutdown & best removal systems, screen & research budget. Some closed sessions may be needed
NRC, J.C. Office of the Secretary of the Commission 80/05/16 2pp
- 8504200308 Notice of ACRS Subcommittee on Reactor Safety Research 800403 meeting in Washington, DC to review pertinent portions of FY80 research budget. Some sessions may be closed to explore matters involving proprietary info.
NRC, J.C. Office of the Secretary of the Commission 80/05/16 2pp
- 8504200387 Notice of ACRS Subcommittee on Waste Mgt & Fuel Cycle 800426-27 meeting in Washington, DC to discuss pertinent portions of NRC research program
NRC, J.C. Office of the Secretary of the Commission 80/04/08 2pp
- 8504200591 Notice of preliminary schedule of proposed meetings of ACRS subcommittee & working group-taking into account add'l & postponed/cancelled meetings since 800425 publication
NRC, J.C. Office of the Secretary of the Commission 80/05/12 4pp
- 8504200417 Notice of ACRS Subcommittee on LWRs 800422 meeting in Washington, DC
NRC, J.C. Office of the Secretary of the Commission 80/04/08 2pp
- 8504200501 Summary of ACRS Ad Hoc TH-R-2 Accident Implications Subcommittee 800303 meeting in Washington, DC
ACRS - Advisory Committee on Reactor Safeguards 80/04/22 20pp
- 8504200391 Summary of 229th ACRS meeting on 800306-08 in Washington, DC. Items considered include NURE-0645 proposed plant for implementation of NRC bulletin & orders resulting from B&M-2 accident & floating nuclear plant core level design
NRC, J.C. Office of the Secretary of the Commission 80/03/24 2pp
- 8504200374 Discusses plan for extended operation of light water breeder reactor based on safety meeting on 800501-03 in Washington, DC. US, DOE & NRC-ACRS believes operation of reactor safe to 24,000 EFP is acceptable.
NRC, J.C. Office of the Secretary of the Commission 80/05/04 1p
- 8504200492 Notification of ACRS Subcommittee on B&M Water Reactors 800424 meeting in Washington, DC to review NURE-0645
NRC, J.C. Office of the Secretary of the Commission, INEL, DS, J.C. Office of the General Counsel 80/04/09 2pp
- 8504200425 Forwards PI notice ACRS Subcommittee on Advanced Reactors 800418 meeting for publication on 800303
NRC, J.C. Office of the Secretary of the Commission 80/05/22 1p

NONDOCKETED ITEMS

--000400084 PR notice of ACRS Subcommittee on Advanced Reactors B00415 meeting in Washington, DC
HUTLEY, J. C. Office of the Secretary of the Commission 00/04/20 2pp

B00407008 Notification of ACRS Subcommittee on Regulatory Activities B00430 meeting in Washington, DC to hear comments on Reg Guide 1.144 & 1.213
HUTLEY, J. C. Office of the Secretary of the Commission 00/04/14 2pp

B00407008 Executive schedule for ACRS Subcommittee on BWI Water Reactors B00408 meeting
ACRS - Advisory Committee on Reactor Safeguards 00/04/08 1p

B00407008 Schedule & outline for discussion at 241st ACRS meeting on B00021-03 in Washington, DC
ACRS - Advisory Committee on Reactor Safeguards 00/04/03 5pp

B00407007 Transcript of ACRS Subcommittee on Reactor Components B00418 meeting in Washington, DC, Pa 260-643, morning session Related mail & vignettes encl.
ACRS - Advisory Committee on Reactor Safeguards 00/04/18 27pp

B00407008 Transcript of ACRS Subcommittee on Advanced Reactors B00413 meeting in Washington, DC Pa 1-005 Related mail & vignettes encl.
ACRS - Advisory Committee on Reactor Safeguards 00/04/13 30pp

B004050010 Summits status of near-term CP applications discussed at 241st ACRS meeting on B00021-03 Support's recommendation by representative that interim approach to major policy issues should be developed
PLURIST, H. B. ACRS - Advisory Committee on Reactor Safeguards 00/03/06 2pp

B004050015 First draft of "Physics of Reactor Meltdown Accident" CONRAD, S. L. Pittsburgh, Univ. of. 00/03/24, 2pp

B004050012 Notification of ACRS Subcommittee on Reliability & Probabilistic Assessment B00430 meeting in Washington, DC to combine evaluation of need to develop quantitative safety goals for plants Segregation determination encl.
HUTLEY, J. C. Office of the Secretary of the Commission 00/04/09, 2pp

B004050018 Notification of ACRS Ad Hoc Subcommittee on Class Y Accidents B00609 meeting in Chicago, IL Segregation determination encl.
HUTLEY, J. C. Office of the Secretary of the Commission. SHIELDS, W. C. Office of the General Counsel 00/04/21 3pp

B004050024 Notification of ACRS B00819-20 & 2B-07 meetings w/German Reactor Safety Committee & French Group Permanent-Reactors in Strasbourg, Germany & Fontenay-aux-Roses, France to discuss reactor safety & practice, W/Segregation determination encl.
HUTLEY, J. C. Office of the Secretary of the Commission. SHIELDS, W. C. Office of the General Counsel 00/04/20, 2pp

B004050027 Notification of ACRS Subcommittee on Reactor Operations B00430 meeting in Washington, DC to review NRC research program Segregation determination encl.
HUTLEY, J. C. Office of the Secretary of the Commission. SHIELDS, W. C. Office of the General Counsel 00/04/20 3pp

B004050049 Notification of change of ACRS Subcommittee on Reliability & Probabilistic Assessment B00430 meeting, Portion of meeting re NRC budget may be closed to public w/ determination made per Federal Advisory Committee Act
SHIELDS, W. C. Office of the Secretary of the Commission. SHIELDS, W. C. Office of the General Counsel 00/04/22, 3pp

B004050045 Summary of 241st ACRS Meeting on B00410-12 in Washington, DC Items considered include review of NUREG-0408 discussion of ACRS representatives of nuclear power industry & discussion of impact on ACRS of 1990 Reorganization Plan 1
PLESSET, H. B. ACRS - Advisory Committee on Reactor Safeguards, 00/04/22 3pp

COMMISSION NRC CORRESPONDENCE

B01404246 Commissioner Kennedy's correspondence for May-Dec 1979
KENNEDY, H. T. Commission 7/7/10/18 110pp

B00410000 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 1p

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

--B00410010 Request comments on proposed rulemaking concerning disposal of radwaste produced by nuclear facilities Comments due by B00415 PR notice encl.
AHMANN, J. F. Commission 00/03/12 2pp

B00418211 Response to B00128 for re NRC emphasis on emergency planning for nuclear accidents NRC & PRA cooperate in developing emergency planning rules & related state guidance.
AHMANN, J. F. Commission 00/03/18 1p

B00320000 Discuss reasons why Commission does not support H.R. 5923 re requiring Secretary of Energy or Secretary of Defense to verify state legislation about proposed construction of state radwaste storage facility
AHMANN, J. F. Commission 00/04/20 2pp

NONDOCKETED ITEMS

236

- 000920012 Requests comments on encl H R 4903 re requiring Secretary of Energy or Director of Defense to notify State Legislature about proposed treaty of state radioactive storage facilities
DTAG00000 H D House of Rep. Internat & Foreign Commerce
7/11/23 6pp
- 00032004488 Responds to 0005007 ltr re reactor core failures which could result in accident sequences not previously anticipated Commission recognizes need for addl deliberate investigation of control sys failures & consequent effects
AHEARNIE J F Commission 00/05/14 2pp
- 0009200473 Discusses status of actions re high energy line break w/ consequential control sys failure Provides interim criteria to be considered in revised followup review Supporting tables encl
CHENR D P Division of Operating Reactors 7/13/23 17pp
- 00030000154 Comments on draft bill: "To Establish Nuclear Safety Oversight Committee" Recommends that accompanying ltr be sent to Congress clarifying that committee will not influence decisions or actions before Commission
AHEARNIE J F Commission 00/05/01 11pp
- 00030000004 Comments on Draft 3 of NUREG-0460, "NRC Action Plans Developed as Result of TSC-4 Accident" Insufficient attention given to both general & special policy questions which require consideration in connection w/inter-term OLA
PLANNING H R AGOR - Advisory Committee on Reactor Safeguards
00/04/17 2pp
- 00050000020 Responds to request for data comparing population densities near reactor sites abroad w/US figures Info in sketchy & imprecise Comparisons should serve immediate purposes US foreign countries involved have higher densities than US
NABERMAN M E J Office of Standards Development Director 00/04/28 10pp
- 00040000010 Act receipt of 000012 ltr re NRC policy on differing prof appointed Outline characteristics of proposed NRC policy (has match intent of recipient committee)
AHEARNIE J F Commission 00/04/29 1p
- 0004000112 Comments on NRC proposed policy on differing prof opinions Policy should be immediately implemented
VOON HIFUO P., RAVEN-HANSEN P., American Association for the Advancement of Science 00/03/28 6pp
- 00040000070 Meeting info rept for w/ ending 000514
ZIMM T A Office of the Executive Director for Operations
00/05/21 32pp
- 00040000020 Meeting info rept for w/ ending 000520
ZIMM T A Office of the Executive Director for Operations
00/05/29 33pp
- 00040000003 Comments on amendments to Reorganization Plan 1 of 1980 Congress should not disapprove amend plan OLC may agency authority to interpret & apply plan varies w/Commission Addl clarification needed to prevent conflict for NRC
AHEARNIE J F Commission 00/05/14 2pp
- 0004100071 Comments on amendments to Reorganization Plan 1 of 1980 Congress should not disapprove amend plan Addl clarification needed to prevent conflict for NRC Separate comments by Chairman
AHEARNIE J F Commission 00/05/14 6pp
- 00041001000 Comments on H R 4939 authorizing Dir of Science & Technology to serve as Federal focal point for encouraging technological risk comparisons Bill addresses desirable objective Proposed approach would be useful
AHEARNIE J F Commission 00/05/14 1p
- 0004100007 Requests comments on encl H R 4939 authorizing Dir of Science & Technology to serve as federal focal point for encouraging technological risk comparisons
RITTER D House of Rep. Science & Technology 00/03/26 10pp
- 00040000001 Declines invitation to speak at Fourth ANS Topical Meeting on Technology of Controlled Nuclear Fusion on 00/01/4
HENDRICK A H Commission 00/05/02 1p
- 0004100007 Extends invitation to speak at Fourth ANS Topical Meeting on Technology of Controlled Nuclear Fusion on 00/01/4
CHENR D P Division of Oper 00/04/20 1p
- 00040000013 Responds to 000405 ltr re project to compile fact sheets of Energy and Environment for State Project is excellent & would be useful Offers NRC assistance
HENDRICK A H Commission 00/05/02 1p
- 0004100019 Requests NRC assistance in compilation of fact-sheet sheet re low level waste
HARTY R Swedish Hosp Medical Center Seattle WA 00/04/03 1p
- 00041000000 Requests assistance in obtaining Congressional approval of PWR supplemental budget 000 0004057 seeking of NRC level & transportation funds would severely limit ability of NRC to carry out required functions
AHEARNIE J F Commission 00/05/13 1p
- 00041000044 Act receipt of Gollingsburg II workshop proceedings & copies of recent speeches Discussions at Gollingsburg are kept forward
HENDRICK A H Commission 00/05/02 1p
- 00041000044 Forwarded Gollingsburg II workshop proceedings & recent speeches Workshop brought together approx 40 representatives of nuclear enterprise & public regulatory bodies w/US encl
WEINBERG A H Oak Ridge Univ 00/04/25 2pp
- 00041000000 Declines invitation to attend 10th Annual Natl Conference on Radiation Control on 000518-20 in Louisville KY Prior commitments preclude attendance
HENDRICK A H Commission 00/04/00 1p
- 00041000003 Extends invitation to attend 10th Annual Natl Conference on Radiation Control on 000518-20 in Louisville KY
LACROIX D N Conference of Radiation Control Program Directors Inc 00/04/15 1p
- 00041000023 Responds to 000444 ltr RE Hingou, Director, Dir of Risk Development will be NRC representative to Radiation Policy Council w/ Dir, Director of Nuclear Natl Safety & Safeguards will be alternate
AHEARNIE J F Commission 00/05/12 1p
- 0004100012 Requests appointment of NRC representative to Radiation Policy Council Executive order establishing council encl
COYLE D N President of US & Executive Offices 00/04/04 13pp
- 0004100001 Requests appointment of NRC representative in anticipation of executive order establishing Radiation Policy Council
COYLE D N Environmental Protection Agency 7/11/23 1p
- 00041000000 Comments on H R 4970 re providing Federal assistance to states for development of waste burial grounds Section 43b should be amended to permit use of Federal facilities by states committed to establishment of disposal facility
AHEARNIE J F Commission 00/05/29 4pp
- 0004100019 Requests views on encl H R 4970 re providing Federal assistance to states for development of waste burial grounds
STANBARD H D House of Rep. Internat & Foreign Commerce
00/05/21 11pp
- 00041001047 Submits quarterly rept to Congress on number of full-time employees hired & promoted 7/10/01-12/01 No actions reported re promoting NRC equal employment opportunity w/US encl
AHEARNIE J F Commission 00/05/28 1p
- 0004100000 Submits quarterly rept to Congress on number of full-time employees hired & promoted 7/10/01-12/01 No actions reported re promoting NRC equal employment opportunity w/US encl
AHEARNIE J F Commission 00/05/28 1p
- 0004100000 Provides Subcommittee on Environ, Energy & Natural Resources w/quarterly rept to Congress on number of full-time employees hired & promoted 7/10/01-12/01 No actions reported re promoting NRC equal employment opportunity w/US encl
AHEARNIE J F Commission 00/05/28 1p
- 0004100000 Provides Subcommittee on Nuclear Regulation w/quarterly rept to Congress on number of full-time employees hired & promoted 7/10/01-12/01 No actions reported re promoting NRC equal employment opportunity w/US encl
AHEARNIE J F Commission 00/05/28 1p
- 0004100000 Provides Subcommittee on Energy & Environ w/quarterly rept to Congress on number of full-time employees hired & promoted 7/10/01-12/01 No actions reported re promoting NRC equal employment opportunity w/US encl
AHEARNIE J F Commission 00/05/28 1p

NONDOCKETED ITEMS

297

- 000400092V Mod 4, extending period of performance, to "Document Control By"
PATITA, R. J. Administrative Contracts Branch FELTON, R. W. 788A
Contract NRC-10-79-392 05/05/22 1p
- 000400094S Notification of contract execution, Mod 3 to "Electrostatic Copying By" Contractor Literature Research Co
GELBMAN, R. Administrative Contracts Branch NRC-10-79-394
05/05/20 1p
- 000400097T Mod 3, obligating add funds, to "Electrostatic Copying By"
PATITA, R. J. Administrative Contracts Branch NRC-10-79-394
05/05/20 1p
- 000400098I Notification of contract execution, Mod 4 to "Belmont Testing Map for Mining Nuclear Electric Power Generating Facilities in Eastern US" Contractor Research Associates, Inc
SMITH, P. A. Technical Assistance Contracts Branch NRC-03-78-134
05/05/21 1p
- 000400099S Mod 4, modifying Article 1 re description of work, to "Belmont Testing Map for Mining Nuclear Electric Power Generating Facilities in Eastern US"
Research Associates, Inc. Technical Assistance Contracts Branch NRC-03-78-134 05/05/23 1p
- 000400094S Notification of contract execution, Mod 2 to "Responding to Verification" Contractor Small Business Administration
Subcontractor Intl Business Dev. Inc
WIDOWSKI, E. Administrative Contracts Branch NRC-10-79-393
05/05/20 1p
- 000400094S Mod 2, increasing total amount obligated under contract, to "Responding to Verifying By"
PATITA, R. J. Administrative Contracts Branch NRC-10-79-393
05/05/20 1p
- 000400094S Notification of contract execution, "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries," awarded to Franklin Inst
NRC-04, A. R. Administrative Contracts Branch PIN 8-144B
NRC-03-80-038 05/05/20 1p
- 000400094S Contract "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries," awarded to Franklin Inst
NRC-04, A. R. Administrative Contracts Branch PIN 8-144B
NRC-03-80-038 05/05/20 1p
- 000400094S Request Commission views on results of studies & recommendations re health & safety considerations in NRC research planning & nuclear assistance programs. Request Commission approve scil analysis
WHA, J. R. Office of International Programs, Director 78/07/03 2p
- 000400094S "NRC Staff Analysis of Health & Safety Considerations in Reactor Experiments & Assistance Programs"
Commission 78/06/28 8pp.
- 000400098S Notification of contract execution, Mod 3 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Within NC" Contractor State of NC
BAIDREX, L. Research Contracts Branch PIN 8-3112 NRC-03-77-106
07/05/01 1p
- 000400094S Mod 3, obligating funds at contract execution, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Within NC & Related by Commission"
NRC-04, A. R. Research Contracts Branch PIN 8-3112
NRC-07-77-106 07/05/01 1p
- 000400099S Responds to POIA request for NRC-03-80-137 between NRC & Roman Design Group, underlying request for proposal & related correspondence. Records documents listed in 402, WFO
FELTON, R. W. Division of Rules and Records, NRC-03-80-137
05/06/10 2p
- 000400094S Notification of contract execution, Mod 4 to "Modeling Tornado Dynamics" Contractor Aeronautical Research Associates of Princeton
WOLFE, R. A. Research Contracts Branch PIN 8-3793 NRC-04-76-218
05/03/31 1p
- 000400094S Mod 4, adding cost overrun, to "Modeling Tornado Dynamics" Contractor Aeronautical Research Associates of Princeton
WOLFE, R. A. Research Contracts Branch PIN 8-3793 NRC-04-76-218
05/03/31 1p
- 000400095S Notification of contract execution "Site Characterization Test Program," awarded to Order Associates
Order Associates PATITA, R. J. Administrative Contracts Branch PIN 8-3930-3 NRC-03-80-036 05/06/09 34pp.
- 000400095S Notification of contract execution, Mod 4 to "Vol Reduction Techniques in Low Level Releases By" Contractor Telephon, Inc
SMITH, P. A. Administrative Contracts Branch PIN 8-6413-9
NRC-02-79-034 05/05/20 1p
- 000400094S Notification of contract execution, Mod 3 to "Dye Analysis of Shallow Land Harbors" Contractor Brice Applications, Inc
SMITH, P. A. Administrative Contracts Branch PIN 8-6423-9
NRC-02-79-032 05/05/08 1p
- 000400094S Notification of contract execution, Mod 3 to "EIS for Low Level Waste Regulation" Contractor Jones & Jones
SMITH, P. A. Administrative Contracts Branch NRC-02-79-028
05/05/23 1p
- 000400098S Mod 3, deleting P Labels & substituting O Labels, to "EIS for Low Level Waste Regulation"
J. Jones & Jones, Inc. Technical Assistance Contracts Branch NRC-02-79-028 05/05/23 1p
- 000400092S Notification of contract execution, Mod 3 to "Responding to Verification" Contractor Small Business Administration
Subcontractor Intl Business Dev. Inc
WIDOWSKI, E. Administrative Contracts Branch NRC-10-79-393
05/05/20 1p
- 000400092S Mod 3, increasing funds, to "Responding to Verification,"
Small Business Administration, PATITA, R. J. Technical Assistance Contracts Branch NRC-10-79-393 05/05/20 1p
- 000400092S RFP NRC-80-03-038, "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries," NRC award (FPM NRC-4091 re publication of technical documents by NRC contractors & App A contract provisions, etc)
STOWN, J. R. Franklin Institute/Franklin Research Center
NRC-00-80-038 79/11/14 132pp.
- 000400094S Notification of contract execution, Mod 1 to "Disasterion by Emergency Radio" Contractor Energy Dely, Inc.
FLANNERY, J. Administrative Contracts Branch NRC-10-80-066
05/05/30 1p
- 000400094S Mod 1, adding four subscriptions to "Disasterion by Emergency Radio"
ENERDEL, J. E. Energy Dely, Inc. PATITA, R. J. Administrative Contracts Branch NRC-10-80-066 05/05/30 2pp
- 000400094S Notification of contract execution "Cost of Underground Tests," awarded to American Mine Dev. Inc
GELBMAN, R. Administrative Contracts Branch PIN 8-6999-0
NRC-02-80-003 05/06/09 1p
- 000400094S Contract "Cost of Underground Tests," awarded to American Mine Dev. Inc
GELBMAN, R. Administrative Contracts Branch PIN 8-6999-0
NRC-02-80-003 05/06/09 40pp
- 000400098S Notification of contract execution, Mod 2 to "Extension of Highline II," Contractor Radiation Research Associates
PEARL, N. J. Purchasing Section, NRC-03-79-139 05/06/04 1p
- 000400098S Mod 2, extending period of performance, to "Extension of Highline II,"
RACHAPPER, N. H. Radiation Research Associates, PATITA, R. J. Administrative Contracts Branch, NRC-03-79-139 05/06/04 1p
- 000400094S Notification of contract execution, "Licensing Technical Assistance," awarded to Business Applications, Inc
DOCKERTY, P. J. Technical Assistance Contracts Branch NRC-03-80-025 05/05/23 1p

NONDOCKETED ITEMS

- 0004199004 Contract "Licensing Technical Assistance," awarded to Science Applications, Inc. P0004199004, D. J. Technical Assistance Contracts Branch NRC-02-00-038 00/03/23 4pp
- 0004199009 Authorization expenditure of funds obligated under contract & projects performance of work Task Order 1 Milestones Applications Inc. completed on 8/04/08
NRC-02-00-038 00/04/11 4pp
- 0004199004 Notification of contract execution, Mod 3 to "Study of Braket Hydrodynamics Important in LSCA Refined" Contractor: State Univ. of NY
HASEY, H. Research Contracts Branch FIN 8-0211. NRC-01-70-194 00/03/29 1p
- 0004199002 Mod 3, adding funds to "Study of Braket Hydrodynamics Important in LSCA Refined" P0004199002, D. J. Technical Assistance Contracts Branch NRC-02-00-038 00/05/29 4pp
- 0004199001 Notification of contract execution, Mod 3 to "Evaluation of Financial Assistance Alternatives for Economizing Nuclear Reactors & Impact on Rates" Contractor: New England Conference of Public Utility Commissioners
GUTHRIE, J. P. Research Contracts Branch FIN 8-10100 00/04/30 1p
- 0004199007 Mod 3, adding to cost extension to "Evaluation of Financial Assistance Alternatives for Economizing Nuclear Reactors & Impact on Rates" P0004199007, D. J. Technical Assistance Contracts Branch NRC-02-00-038 00/05/29 4pp
- 0004199002 Notification of contract execution, Mod 4 to "Study of Regional Technical & Scientific Per NRC" Contractor: State of NE
NRC-02-00-038 00/05/29 1p
- 0004199006 Mod 4, adding funds & scope for 31st of 3-yr contract, to "Study of Regional Technical & Scientific Per NRC" Contractor: State of NE
NRC-02-00-038 00/05/29 4pp
- 0004199002 Add 3, adding addresses to distribution list for monthly reports to "Oil Reduction Techniques in Low Level Radioactive Mgt."
a. Telecomm. Inc. 0004199002, D. J. Division of Contracts NRC-02-00-038 00/05/29 2pp
- 0004199002 Notification of contract execution "Conversion Programming, Implementation & Documentation of NRC Automated Personnel Sys." awarded to Rehab Group, Inc.
NRC-02-00-038 00/05/29 1p
- 0004199002 Notification of contract execution "Conversion Programming, Implementation & Documentation of NRC Automated Personnel Sys." awarded to Rehab Group, Inc.
NRC-02-00-038 00/05/29 1p
- 0004199003 "Automatic Data Processing Study - Automated Sys Documentation Handbook," App 0003
a. Office of Administration. 7/9/04 4pp
- 0004199003 Notification of contract execution, Mod 3 to "Determination of Tornado Wind Speed From Tornado Bore" Contractor: UNIV. of MD
HASEY, H. Research Contracts Branch FIN 8-0211. NRC-04-70-241. 00/04/02 1p
- 0004199008 Mod 3, adding 3-yr needs extension to "Determination of Tornado Wind Speed From Tornado Bore" Contractor: UNIV. of MD
HASEY, H. Research Contracts Branch FIN 8-0211. NRC-04-70-241. 00/04/02 1p
- 0004199006 Notification of contract execution "Purchase & Installation of 816 Teleprinters," awarded to Eitel Corp/Marner Associates, Inc.
NRC-02-00-038 00/04/04 1p
- 0004199009 Contract "Purchase & Installation of 816 Teleprinters," awarded to Eitel Corp/Marner Associates, Inc.
NRC-02-00-038 00/04/04 4pp
- 0004200104 Notification of contract execution, Mod 1 to "GEMS - ACRO & Hearing Apparatus" Contractor: GE Research
NRC-02-00-038 00/04/04 1p
- 0004200107 Mod 3, extending period of performance to "GEMS - ACRO & Hearing Apparatus" Contractor: GE Research
NRC-02-00-038 00/04/04 1p
- 0004200104 Notification of contract execution, Mod 4 to "Economic Consulting Study in Connection with Sanitation Nuclear Unit," Contractor: P. B. Berman
NRC-02-00-038 00/03/30 1p
- 0004200108 Mod 4, modifying period of performance & increasing ceiling amount, to "Economic Consulting Study in Connection with Sanitation Nuclear Unit," Contractor: P. B. Berman
NRC-02-00-038 00/03/30 1p
- 0004200104 Notification of contract execution, Mod 3 to "Conduct of Special Inquiry into Incident at TMI-2" Contractor: Regener, Stern & Hugs
NRC-02-00-038 00/04/04 1p
- 0004200104 Mod 3, adding funds & extending period of performance, to "Conduct of Special Inquiry into Incident at TMI-2" Contractor: Regener, Stern & Hugs
NRC-02-00-038 00/04/04 1p
- 0004200108 Notification of contract execution "Licensing Assistance/Scientific Impact Evaluation," awarded to Denver Research Inst
NRC-02-00-038 00/05/29 1p
- 0004200104 Contract "Licensing Assistance/Scientific Impact Evaluation," awarded to Denver Research Inst
NRC-02-00-038 00/05/29 4pp
- 0004200109 Notification of contract execution, Mod 2 to "Evaluation of Physical Security & Matt Control & Accounting Assessment Results" Contractor: Science Applications, Inc.
NRC-02-00-038 00/04/04 1p
- 0004200104 Mod 3, establishing delivery dates specified in contract & modifying period of performance, to "Evaluation of Physical Security & Matt Control & Accounting Assessment Results" Contractor: Science Applications, Inc.
NRC-02-00-038 00/04/04 1p
- 0004200104 Notification of contract execution, Mod 1 to "Technical Presentation & Consultation in Connection with Sanitation Nuclear Unit," Contractor: Stanford Research Inst.
NRC-02-00-038 00/03/30 1p
- 0004200108 Mod 4, decreasing funds, to "Technical Presentation & Consultation in Connection with Sanitation Nuclear Unit," Contractor: Stanford Research Inst.
NRC-02-00-038 00/03/30 1p
- 0004200120 Notification of contract execution, Mod 3 to "Survey of Current State Radiological Emergency Response Capabilities for Transportation Related Incidents" Contractor: IN Univ
NRC-01-70-013 00/04/04 1p
- 0004200124 Mod 3, changing time for submission of final report to read 30 months after effective date of contract to "Survey of Current State Radiological Emergency Response Capabilities for Transportation Related Incidents" Contractor: IN Univ
NRC-01-70-013 00/04/04 1p
- 0004200129 Notification of contract execution, Mod 3 to "Properties of Reactor Heat at Constant Turbine Rates" Contractor: Univ. of FL
NRC-02-00-038 00/04/04 1p

--0004230123 Mod 3, extending contract through 000430 at no add costs to "Properties of Reactor Halls at Constant True Strain Rates" =
HARRIS, A. P. Florida Univ. of Gainesville, HORTON, R. V.
Research Contracts Branch FIN E-3948 NRC-04-77-037 00/04/11 App

0004230150 Notification of contract execution, Mod 1 to "Thermal Conductivity of Disordered Minerals & of Rocks to High Level Waste Regenerators" = Contractor Cornell Univ.
HARRIS, A. P. Research Contracts Branch FIN E-4626 NRC-04-78-251 00/04/10 1p

--0004230164 Mod 1, adding direct extension for one add year to "Conductivity of Disordered Minerals & of Rocks to High Level Waste Regenerators" =
HARRIS, A. P. Cornell Univ. HORTON, R. V. Research Contracts Branch FIN E-4626 NRC-04-78-251 00/04/10 2pp

0004230170 Notification of contract execution, Mod 1 to "Biographic Reporting Data (LUT 1)" = Contractor East Versatile Reporters Inc.
HARRIS, A. P. Administrative Contracts Branch FIN E-1311 NRC-17-90-448 00/04/11 1p

--0004230170 Mod 1, terminating contract effective 000102 to, "Biographic Reporting Data (LUT 1)" =
HARRIS, A. P. East Versatile Reporters Inc. HARRIS, A. P. Administrative Contracts Branch FIN E-1311 NRC-17-90-448 00/04/11 1p

0004230194 Notification of contract execution, Mod 1 to "Core Halls Matrix Interaction Evaluations" = Contractor Applied Science Associates, Inc.
HARRIS, A. P. Technical Assistance Contracts Branch FIN E-4602 NRC-03-00-104 00/04/04 1p

--0004230200 Mod 1, changing Article V - overhead/general administrative rates to, "Core Halls Matrix Interaction Evaluations" =
BAMMBA, D. D. Applied Science Associates, Inc. SECURITY, D. J. Technical Assistance Contracts Branch FIN E-4602 NRC-03-00-104 00/04/04 1p

0004230201 Notification of contract execution "Development of Model State Emergency Response Program for Transportation Related Radiological Incidents" = Contractor EPA Municipal Services Research Lab
HARRIS, A. P. Research Contracts Branch FIN E-10750 NRC-01-05-020 00/04/02 1p

--0004230204 Contract "Development of Model State Emergency Response Program for Transportation Related Radiological Incidents," awarded to EPA Municipal Services Research Lab
HARRIS, A. P. Environmental Protection Agency HORTON, R. V. Research Contracts Branch FIN E-10750 NRC-01-05-020 00/04/02 App

0004230205 Forward State of GA second quarterly report re transportation surveillance program Requests comments.
HARRIS, A. P. Office of State Programs, Director NRC-04-78-042 00/04/02 App

--0004230205 Forward second quarterly progress report Jan-Mar 1990 re transportation surveillance
HARRIS, A. P. Georgia, State of NRC-04-78-382 00/04/13 3pp

0004230205 Notification of contract execution, Mod 2 to "Core Halls Cancellation" = Contractor Ender, Elmer, Hendricks & Wheeler, Inc.
HARRIS, A. P. Administrative Contracts Branch NRC-10-79-037 00/04/02 1p

--0004230205 Mod 2, changing phase of performance & amount of work obligation to "Career Counseling" =
HARRIS, A. P. Ender, Elmer, Hendricks & Wheeler, Inc. HARRIS, A. P. Administrative Contracts Branch NRC-10-79-037 00/04/02 1p

0004230205 Notification of contract execution, Mod 2 to "Meteorological Consulting Svc" = Contractor US Dept of Commerce Quiver Research Labs
HARRIS, A. P. Technical Assistance Contracts Branch FIN E-4602 NRC-03-77-132 00/01/21 1p

--0004230204 Mod 2, modifying scope of work & increasing financial obligation to "Meteorological Consulting Svc" =
HARRIS, A. P. Commerce, Dept of SECURITY, D. J. Technical Assistance Contracts Branch FIN E-4602 NRC-03/01/21 1p

0004230222 Notification of contract execution, Mod 4 to "Fixed Protection" = Contractor US Army Coastal Engineering Research
HARRIS, A. P. Technical Assistance Contracts Branch FIN E-5975 NRC-03-77-006 00/04/02 1p

--0004230228 Mod 4, replacing LO Haiman with Given as NRC assigned engineer to "Fixed Protection" =
HARRIS, A. P. Army, Dept of SECURITY, D. J. Technical Assistance Contracts Branch FIN E-5975 NRC-03-77-006 00/04/02 1p

0004230247 Notification of contract execution, Mod 2 to "Document Control Sys" =
LEED, C. B. Administrative Contracts Branch NRC-10-79-390 00/04/12 1p

--0004230249 Mod 2, ordering option of three, to "Document Control Sys" =
FLYNN, H. W. TERA Corp. HARRIS, A. P. Administrative Contracts Branch NRC-10-79-390 00/04/12 2pp

0004230261 Notification of contract execution "Evolution Monitoring Program W/State of MI" = Contractor State of MI
HARRIS, A. P. Research Contracts Branch FIN E-0114 NRC-05-00-070 00/01/01 1p

--0004230261 Contract "Evolution Monitoring Program W/State of MI," awarded to State of MI
HARRIS, A. P. Michigan, State of HORTON, R. V. Research Contracts Branch FIN E-0114 NRC-05-00-070 00/01/01 1pp

0004230269 Notification of contract execution, Mod 1 to "Economic Assistance re Antitrust Hearings for South TX Antitrust & Commerce Peak Antitrust Proceedings" =
HARRIS, A. P. Technical Assistance Contracts Branch FIN E-4602 NRC-03-00-129 00/04/07 1p

--0004230269 Mod 1, adding Task 4 & extending performance period to 007220 to "Economic Assistance re Antitrust Hearings for South TX Antitrust & Commerce Peak Antitrust Proceedings" =
HARRIS, A. P. Division of Contracts LEWIS, R. C. Transmatic, Inc. FIN E-4602 NRC-03-00-129 00/03/27 1p

0004230266 Notification of contract execution, Mod 4 to "Analysis of Hypothetical Accidents Resulting From Core Meltdown" =
HARRIS, A. P. Research Contracts Branch FIN A-0047 NRC-04-78-070 79/11/91 1p

--0004230266 Mod 4, to include add'l work including probabilistic uncertainty analysis to "Analysis of Hypothetical Accidents Resulting From Core Meltdown" =
HARRIS, A. P. Battelle Memorial Institute, Columbus Laboratories, LINT, P. V. Division of Contracts FIN A-0047 NRC-04-78-070 79/11/91 App

0004230286 Notification of contract execution, Mod 2 to "Tearing Stability Analysis for LWR Piping" = Contractor US Univ
HARRIS, A. P. Technical Assistance Contracts Branch FIN E-0271 NRC-03-79-124 00/04/29 1p

--0004230290 Mod 2, modifying description of work, gvt will & consideration to "Tearing Stability Analysis for LWR Piping" =
HARRIS, A. P. Washington Univ SECURITY, D. J. Technical Assistance Contracts Branch FIN E-0271 NRC-03-79-124 00/06/29 App

0004230286 Notification of contract execution, Mod 4 to "Mgmt of Data General Corp C/330 Computers & Associated Peripherals" =
HARRIS, A. P. Data Consultants, Inc. HARRIS, A. P. Administrative Contracts Branch NRC-10-77-190 00/04/02 1p

--0004230286 Mod 4, changing Items 1, 7 & 8, adding Item 40A, setting forth current sgs configurations, increasing total amount of contract & revising pricing schedule to "Mgmt of Data General Corp C/330 Computers & Associated Peripherals" =
HARRIS, A. P. Data Consultants, Inc. HARRIS, A. P. Administrative Contracts Branch NRC-10-77-190 00/04/02 9pp

0004230282 Notification of contract execution, Mod 1 to "Subscriptions to Huxley's MI" = Contractor Huxley-Mill, Inc.
FLYNN, H. W. Administrative Contracts Branch NRC-10-80-645 00/04/03 1p

--0004230282 Mod 1, adding four subscriptions to "Subscriptions to Huxley's MI" =
HARRIS, A. P. Huxley-Mill Publications Co. HARRIS, A. P. Administrative Contracts Branch NRC-10-80-645 00/04/03 2pp

NONDOCKETED ITEMS

0004200293 Notification of contract execution, Mod 3 to "Electrostatic Coating Unit" Contractor Patomac Research, Inc.
FELTON, J. Administrative Contracts Branch NRC-17-77-152 00/06/10 1p

0004200298 Mod 2, relocating Xerox machines to Room 155 in Meteoric Bldg.
to "Electrostatic Coating Unit"
BAIN, L.L. Patomac Research, Inc. MATTHEW, J. Administrative Contracts Branch NRC-17-77-152 00/06/10 1p

0004200330 Mod 1, correcting typographical errors to "Bye Analysis of Shell and Burial"
TRIVETT, T. Science Applications, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN 8-6328-P NRC-02-77-052 00/05/06 2pp

0004200310 Response to FOIA request for NRC-03-80-117 & winning technical proposal forwards requested documents
FELTON, J. Division of Rules and Records 00/06/10 1p

0004200304 Contract "Study of Requirements for Operator Licensing" awarded to Analysts & Technology, Inc.
WORTH, M.L. Analysts & Technology, Inc. DOUGHERTY, D. J. Division of Contracts 00/05/12 23pp

0004200302 Notification of contract execution "Alternative Processes for TMI-2 R-05 Removal." awarded to Science Applications, Inc.
HAGAN, T. F. Administrative Contracts Branch FIN 8-6388 NRC-19-80-472 00/05/20 1p

0004200301 Contract "Alternative Processes for TMI-2 R-05 Removal." awarded to Science Applications, Inc.
FINDLEY, D. E. Science Applications, Inc. MATTHEW, J. Administrative Contracts Branch FIN 8-6382 NRC-19-80-472 00/05/20 12pp

0004200338 Notification of contract execution, Mod 2 to "Engineering Assistance Related to Hearings for South TC Antitrust & Commerce Peak Antitrust Proceedings" Contractor RM Beck & Associates
OLMURA, A. P. Technical Assistance Contracts Branch FIN 8-6322 NRC-03-80-120 00/06/10 1p

0004200303 Mod 2, supplying scope of work & period of performance & increasing funds to "Engineering Assistance Related to Hearings for South TC Antitrust & Commerce Peak Antitrust Proceedings"
a Bechtel Corp. DOUGHERTY, D. J. Division of Contracts FIN 8-6322 NRC-03-80-120 00/06/10 2pp

0004200308 Notification of contract execution, Mod 2 to "Review of Environ. Impacts of High Level Radioactive Mgt." Contractor: Telescan, Inc.
WORTH, P. A. Technical Assistance Contracts Branch FIN 8-6135-P NRC-02-77-165 00/06/13 1p

0004200355 Mod 2, changing completion date of Subtask 2 to 03/07/01 to "Review of Environ. Impacts of High Level Radioactive Mgt." Contractor: Telescan, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN 8-6135-P NRC-02-77-165 00/06/13 1p

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

7903140178 R. G. has been appointed radiation safety officer for all activities relating to License 2P-132P-02 W/enc resume detailing R. G.'s qualifications.
KIM, S. M. Radiation Management Corp. 70773 29/08/23 4pp

790326178 Discussion SE Enap 30-13219/77-01 on 790315 of License 19-1700P-01 No noncompliance noted Major areas inspected radiation safety & compliance w/WRC rules & regulations
MOS, J. M. D. Region 1, Philadelphia, Office of the Director 79/03/25 2pp

0003061038 PWD-11-80-649 Safe Energy Alliance is planning forum on 000329 at part outside plant safe Energy has demonstrated peacefully before at plant
MATTHEW, J. Region 2, Atlanta, Office of the Director 00/03/20 1p

0004200311 Response to FOIA request for M. Industries amended applications, including route info Request pertains to records to be received at future date FOIA is not applicable
FELTON, J. Division of Rules and Records 00/05/27 1p

0004200113 FOIA request for M. Industries amended applications, including route info
RENN, K. P. Sierra Club 00/05/11 1p

0004200445 FOIA request for records concerning Hittman Nuclear & Development Corp. NRC Encl & Radiation Mgt Corp & issues of utility info rights to date
BUTTER, M. H. Radiological Controls 00/05/05 2pp

0004200105 Response to FOIA request for EEC-70-137 Document is available in NRC PDR
FELTON, J. Division of Rules and Records NRC 00/06/03 1p

0004200167 FOIA request for EEC-70-137
J. H. R. R. C. Texas Public Interest Research Group 00/05/07 1p

0004200149 Response to FOIA request for documents between R Martin & V Shell, summaries of conversations, logs for licensing or outgoing telcons & all R Martin travel claims since 000401
No documents available pertaining to request
FELTON, J. Division of Rules and Records 00/06/03 1p

0004200174 FOIA request for documents between R Martin & V Shell, summaries of conversations, logs for licensing or outgoing telcons & all R Martin travel claims since 000401
FELTON, J. Division of Rules and Records 00/05/03 2pp

0004200176 Partial response to FOIA request for documents re rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors forwards documents listed in App A W/enc
FELTON, J. Division of Rules and Records 00/06/10 2pp

0004200180 FOIA request for documents re rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors
MATTHEW, J. Affiliation Unknown 00/05/14 1p

0004200184 FOIA request for TVA 740126 environ info rept, TVA responses to NRC comments on Edgemont U Mill, Jul 1970 environ info rept & engineering analysis of mill facility decommissioning & complete tailings stabilization
REID, A. B. Black Hills Alliance 00/05/12 3pp

0004200401 Response to Westchester County Board of Legislators FOIA request for documents re N. Lighthouse grant proposal NRC has on record of receiving proposal from N. Lighthouse
FELTON, J. Division of Rules and Records 00/06/10 1p

0004200403 FOIA request for N. Lighthouse grant proposal & supporting documentation
AUSTIN, L. Westchester County, NY 00/05/16 1p

0004200409 Response to FOIA request for NRC-03-80-137 between NRC & Hansen Design Group, underlying request for proposal & related correspondence forwards documents listed in app W/enc
FELTON, J. Division of Rules and Records NRC-03-80-137 00/06/10 2pp

0004200412 FOIA request for NRC-03-80-137 between NRC & Hansen Design Group, underlying request for proposal & related correspondence
FELTON, J. Division of Rules and Records 00/05/21 1p

0004200516 Response to FOIA 000507 request for license applications & licenses issued to Pharmaco-Nuclear Forwards App A documents documents 20, 33 & 104 partially withheld base telephone numbers Encl FOIA Exemption 61 W/enc
FELTON, J. Division of Rules and Records 00/06/05 10pp

0004200518 FOIA request for license applications & licenses issued to Pharmaco-Nuclear
NICHOLS, D. E. Hialeah Pharmacy, Inc. DNR 800-7 00/05/07 1p

0004200521 Final response to FOIA request for various documents listed & specifically identified by accession & rept numbers, author, number of pages & brief description
FELTON, J. Division of Rules and Records 00/06/06 2pp

0004200144 Discussion Off of General Counsel legislative proposal for changing civil penalty authority, Problems remain re legislative for increasing civil penalty limits Provides arguments supporting increased limits
MURRAY, J. P. Rulemaking & Enforcement Division 79/12/21 2pp

0004200149 Comments on paper recommending change in NRC civil penalty authority Little weakness in arguments supporting various penalties advanced in paper Rebuttal comments justifying bases for civil penalty increase
MURRAY, J. P. Rulemaking & Enforcement Division 77/12/12 4pp

- 0004120148 Comments on final draft of Commission paper recommending higher civil penalty authority. Recommends that Executive Legal Director not occur w/upper unless arguments are well-documented.
HARRIS, J. P. Rulemaking & Enforcement Division 7/30/03 3pp
- 0004120151 Forwards final draft of Commission paper recommending substantial increase in NRC civil penalty authority. Requests review & comments. App. Murray draft mem. encl.
COMMISSION, B. Office of Inspection & Enforcement, Office of the Director 7/30/03 2pp
- 0004120152 Forwards suggestions re proposed Commission paper concerning NRC civil penalty authority.
HARRIS, J. P. Rulemaking & Enforcement Division 7/30/03 4pp
- 0004120154 Informs that NRC has draft proposal for civil penalties legislation, modified to remove 30-day limitation & w/ supporting arguments. Requests meeting to discuss procedure for developing penalties. List of civil penalty cases encl.
HARRIS, J. P. Commission 7/30/03 13pp
- 0004120209 Responds to FOIA request for eight categories of personnel info re Hispanic employment. Forwards documents listed in app. NRC has no accession or promotion info for Hispanic for 1977 Hispanic recruitment program is underway.
FELTON, J. H. Division of Rules and Records 9/5/03/30 43pp
- 0004120252 FOIA request for eight categories of personnel info re Hispanic employment.
HARRIS, J. P. National Image, Inc. 06/03/27 2pp
- 0004120262 FOIA request for documents re NRC imp. of Atomic Test & allegations of B. Schacter.
HARRIS, J. P. Affiliation Unknown NRC 05/03/08 4pp
- 0004120267 Requests brief, written status report re overall effort by OEC of Nuclear Reactor Regulation in area of pellet-lead. Information should include detection of whether Pellet-lead would be increased by extending fuel burnup limits.
LIDARSKI, H. W. ACRR - Advisory Committee on Reactor Safeguards 7/4/07/27 1p.
- 0004120291 Partial response to FOIA request for 22 categories of documents re Facility. Forwards App. A & B documents. Portion of App. A documents & names of individuals exposed to radiation withheld. Incl. FOIA Exemptions 4 & 5. W/ encl.
FELTON, J. H. Division of Rules and Records 8/03/03/11 8pp
- 0004120297 FOIA request for 22 categories of documents re Facility.
GIVEL, R. Affiliation Unknown 05/05/15 2pp
- 0004120311 Responds to FOIA request for list of Region 4 employees, including grades & dept. &/or office. Forwards requested list, w/ encl.
FELTON, J. H. Division of Rules and Records 03/06/02 1p.
- 0004120312 FOIA request for list of Region 4 employees, including grades & dept. &/or office.
DAVIS, E. P. General Services Life Insurance Co. 03/04/03 1p
- 0004120316 Responds to FOIA request for records re Hitman Nuclear & Development Corp. RAD Brev. Inc. & Radiation Mgt. Corp. & Radio article entitled "On of IC. Issue of Interest" from weekly info. re. Forwards documents listed in App. A.
FELTON, J. H. Division of Rules and Records 05/06/02 43pp
- 0004120318 Hatt/Agreement License 19-17039-01 for Hitman Nuclear & Development Corp. authorizing possession & receipt of packages containing solid waste. Agreement source & NRC. Request in Agreement Drafts Draft encl.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 7/3/07/03 4pp
- 0004120319 Forwards addendum to 771017 licensing info re Model B-6405. Addendum sources for use in waste disposal. Info should be incorporated into original submission for evaluation.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 7/30/03 4pp
- 0004120319 Submits correction to 770619 1tr re NRC specified under Requested Change Item 4 & 5.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 7/30/03 1p.
- 0004120329 Application for amend of 760504 application for Hatt/Agreement License, changing Items 4 & 5 & 7 re requests shipment packaging, receipt & possession related documentation. encl.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 8/29/03 77/03/19 13pp
- 0004120338 Requests extension until 770520 to forward application for Hatt/Agreement License in response to Commission request for add info.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 77/03/21 1p
- 0004120337 Notifies that unless add info re application for Hatt/Agreement License is received within 30 days, application will be voided.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 77/04/03 1p
- 0004120341 Responds to 760524 1tr re application for license to receive radioactive waste. Requests add info re receipt of waste & transportation waste, quantities of waste, amount of time spent in training & driver training program description.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 77/04/03 1p
- 0004120345 Notifies that unless add info re application for Hatt/Agreement License is received within 30 days, application will be voided.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 76/09/29 1p
- 0004120352 Forwards add info in response to NRC 760617 request for info concerning 760504 application for Hatt/Agreement License. Info should allow NRC to proceed w/issuance of license.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 76/09/24 1p
- 0004120352 Responds to 760514 application for Hatt/Agreement License. Requests add info re quantity of waste, receipt & specific training & instruction.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 76/09/24 1p
- 0004120359 Forwards application for Hatt/Agreement License. Fee encl.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 8/29/03 76/03/26 1p
- 0004120359 Application for Hatt/Agreement License, authorizing J. Derrin to use, possess & transport use of 5,000 Ci radioactive waste w/atomic numbers 1-90, 500 lb. req. source waste & 300 & 300. W/ encl.
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 8/29/03 76/03/14 4pp
- 0004120368 "Radioactive Program,"
HARRIS, J. P. Hitman Nuclear & Development Corp. (encl. Hitman Corp.) 8/29/03 76/03/14 27pp
- 0004120369 Amends Hatt/Agreement License 27-17010-01 for RAD Brev. Inc. per 761020 application. Amend 1 removes condition authorizing license to store packages containing waste. Hatt/Agreement License 27-17010-01.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 77/02/04 2pp
- 0004120369 Hatt/Agreement License 27-17010-01 for RAD Brev. Inc. authorizing receipt & possession of 10,000 Ci Hatt/Agreement License w/atomic numbers 1-90 & 10 Ci. encl.
HARRIS, J. P. Radiological Licensing Branch (Pfr 790501) 76/09/21 2pp
- 0004120367 Application for amend of Hatt/Agreement License 27-17010-01, relating Item 2 re storage in bldg. at Route 10 & Gethwood Drive, Big Beaver Township, Beaver Falls, PA. RAD Brev. Inc. is seeking for new bldg. to carry out licensed operations.
HARRIS, J. P. RAD Services, Inc. 05/04/03 76/02/03 2pp
- 0004120373 Responds to NRC 760617 request for add info re serial site. Forwards info for inclusion in waste disposal license application. Consists of corrected section, "Radiation Detection Instrumentation," & radiation training program.
HARRIS, J. P. RAD Services, Inc. 76/07/20 2pp
- 0004120381 Corrected section, "Radiation Detection Instrumentation," radiation safety training program & corrected instructions to personnel re packaged waste.
HARRIS, J. P. RAD Services, Inc. 76/07/20 2pp

- 0004180245 Response to 740426 application for radiological license
Request clarification of inclusion of A-241 in
activity limits to tailor test length of training program
SARSEN, H. Radiological Licensing Branch (Pw 770551) 74/04/17
2pp
- 0004180252 Forwards application for radiological license license fee
sent.
HARSEN, D. H. Rad Services, Inc. 71340 74/04/26 1p
- 0004180263 Application for radiological license authorizing
operation of 100 Ci byproduct plutonium, transport & disposal
of 10,000 Ci plutonium & possession of 10 Ci Am-241 in sealed
sources Supporting documentation sent
SARSEN, H. Rad Services, Inc. 71340 74/04/26 47pp
- 7702140222 Radiological License 37-13129-03 For Radiation Management
Corp authorizing use of H-404 foils in Parkin-Silva gas
chromatographs for sample analysis
SARSEN, H. Radiological Licensing Branch (Pw 770501) 77/01/22
2pp
- 0004180248 Forwards application for radiological license
KIN, B. H. Radiation Management Corp. 67002 78/12/26 1p
- 0004180272 Application for byproduct/radiological license, authorizing
possession & use of H-404 deposited on gold or platinum foil
contained in detector cell
KIN, B. H. Radiation Management Corp. 67863 78/12/27 3pp
- 0004180275 Amends Radiological License 37-13129-03 per 770526 1p
Amend 1 changes Condition 7 to authorize possession & use of
licensed radiol described in item 4, 7 & 8 in accordance
w/commitments.
GILMAN, P. Radiological Licensing Branch (Pw 770501) 80/02/19
1p
- 0004180279 Amends Radiological License 37-13129-03 per 770223 1p
Amend 1 changes Condition 7 to authorize possession & use of
licensed radiol described in item 4, 7 & 8 in accordance
w/commitments
* Radiological Licensing Branch (Pw 770501) 78/04/26 1p
- 0004180282 Radiological License 37-13129-03 For Radiation Mgt Corp
authorizing receipt, possession & transport of 2,000 Ci
byproduct metal w/atomic numbers 1-98 inclusive, 2,000 kg
source metal, 25 g U-235 & 150 g Pu.
SARSEN, H. Radiological Licensing Branch (Pw 770501) 78/11/13
2pp.
- 0004180284 Forwards payment of fee per 770526 request for amend to
Byproduct/Radiol License 37-13129-02
KIN, B. H. Radiation Management Corp. 79/11/14 1p
- 0004180285 Response to 770526 request for amend to Byproduct/Radiol
License 37-13129-02 Request amend fee. Application will be
processed upon receipt of fee.
SARSEN, H. License Fee Management Branch 79/11/05 1p
- 0004180297 Response to NRC request for amend fee per 770522 request re
Byproduct/Radiol License 37-13129-02 fee sent.
KIN, B. H. Radiation Management Corp. 79/03/12 1p
- 0004180294 Response to 770522 request for amend to Byproduct/Radiol
License 37-13129-02 Request amend fee. Application will be
processed upon receipt of fee.
SARSEN, H. License Fee Management Branch 79/03/06 1p
- 0004180300 Application for amend to Radiological License 37-13127-02,
changing BOP for commercial waste disposal by eliminating
the use of storage drums.
KIN, B. H. Radiation Management Corp. NRC 03825 79/10/26 1p.
- 0004180307 Forwards two amend applications & supplemental info
reflecting new addresses on Licenses 37-13129-01 &
37-13129-02
KIN, B. H. Radiation Management Corp. 00192 79/05/25 1p
- 0004180325 Informs that BOP for commercial waste disposal has been
amended to incorporate suggestions contained in NRC 780504
1p. Lists procedures revisions Forwards BOP
KIN, B. H. Radiation Management Corp. 78/07/02 28pp.
- 0004180326 Requests add info re 780504 application for license to
receive prepackaged waste. Lists comments re BOP for
commercial waste disposal
SARSEN, H. Radiological Licensing Branch (Pw 770501) 78/07/12
2pp
- 0004180342 Forwards application for license to collect prepackaged
licensed radiol waste. Application fee sent
KIN, B. H. Radiation Management Corp. 94440 78/05/04 1p
- 0004180348 Application for radiological license authorizing JB Davis
to use & supervise use of 2,000 Ci-wg byproduct metal
w/atomic numbers 1-98, 2,000 kg source metal & 200 g SRM
BOP sent
KIN, B. H. Radiation Management Corp. 94440 78/05/04 28pp
- 0004180352 Response to appeal re partial denial of PSDA request for route
info re spent fuel shipments from Chalk River to
Ontario. Canada Appeal is denied. Info withheld (re: PSDA
Exemption 4 & 10 CFR 7902)
DIDSON, W. J. Office of the Executive Director for Operations
00/05/07 2pp
- 0004180319 Response to City of Ontario Commission 000329 request for info
re CI content of spent fuel shipments from Chalk River
research Reactor & For NRC-0129 Shipments new range in CI
content from 1 & 1 million to 1 & 1 million Ci
BURNETT, R. F. Division of Safeguards 80/02/21 1p
- 0004180324 Forwards summary of 000416 meeting between NRC & NY State
Energy Div. re transportation of spent nuclear fuel. Requests
to be kept informed of NRC progress re proposed changes to
spent fuel transportation safeguard regulations
SPATH, J. P. New York, State of 00/04/20 6pp
- 0004180326 Appeals partial denial of PSDA request for route info re
shipment of spent fuel shipments from Chalk River. Ontario to
NC
SARSEN, H. License Fee Management Branch 80/04/26 2pp
- 0004180328 PSDA request for info re minimal recovery of reprocessing
operation conducted on premises of 9200 Laffey Avenue, St.
Louis, MO.
HILTY, J. W. Affiliation Unknown 80/02/25 3pp
- 0004180332 Response to PSDA request for info re minimal recovery of
reprocessing operation conducted on premises of 9200 Laffey
Avenue, St. Louis, MO. Items 7-10 & 13-16 are not GSE
responsibilities & have been referred to NRC
RAHEY, R. W. Energy Dept of 00/03/12 2pp
- 0004180340 PSDA request for info re Condition for Non-Nuclear World,
member organizations how well or how nuclear reactors held
during 000529-0430
WANN, G. S. Affiliation Unknown 80/03/31 1p
- 0004180372 Partial response to PSDA request for info re Condition for
Non-Nuclear World, member organizations how well or how
nuclear reactors held during 000529-0430 Forwards documents
in app NRC does not maintain files on organizations
PELTON, J. H. Division of Rules and Records. 80/04/13 2pp
- 0004180390 Discusses WTTB-TV news report re 000448 nuclear protest in
Washington, DC. Daily is not an act of anti-nuclear
demonstration. Next scheduled meeting will be at Pentagon
* Affiliation Unknown. NRC-00126 00/05/21 1p
- 0004180414 Response to PSDA request for winning technical proposal in
response to RFP-NRC-001-80-0005 "Study & Review of Issues
Concerning Equal Employment Opportunity at NRC" Forwards
comparative version of proposal. N/A sent.
PELTON, J. H. Division of Rules and Records. 00/04/11 1p
- 0004180415 Supplements 781130 response to PSDA request for info re
proposed nuclear fuel facilities in Pacific region. Forwards
Documents 1 & 2 in app a Document 3 partially withheld
& Document 4 withheld (re: PSDA Exemption 1)
PELTON, J. H. Division of Rules and Records. NRC/78C/79-49
00/06/13 2pp
- 0004180418 Requests statement of NRC licensing criteria applying
to storage of foreign spent fuel in US or possessions
Statement will be forwarded to NRC. Sent re: Unsubstantiated
study on US foreign policy re foreign spent fuel storage
BREA, T. R. Office of International Programs, Director 78/04/27
1p
- 0004180422 Response to 700723 1p re storage technologies & potential
Pacific basin sites for spent fuel storage. NRC will provide
technical expertise to respond to foreign requests for
assessments of site suitability & storage technology.
GOSWAMI, L. V. Office of the Executive Director for Operations
78/06/18 3pp

- 0056150129 Response to FOIA request for discussion of use of Pacific basin islands as interim spent fuel storage ctf Proposed independent spent fuel storage installation is expected to be of passive dry above-ground, sealed, steel & concrete tank design
SHELDON, J. H. Office of International Programs, Director 70/07/20 1p
- 0004190130 Responds to FOIA request for winning proposal in response to RF 80-100-00-02, "Energetic Thermal Interactions: Reactivity & HTR Accident & Transient Coolant Flow" Forwards document w/6 encl
FELTON, J. H. Division of Rules and Records 80/04/17 1p
- 0004190207 Responds to FOIA request for list of equipment environmentally qualified by environ testing labs no documents available RH Vol 100000 memo Forwarding memorandum & order re civilian qualification encl
FELTON, J. H. Division of Rules and Records 80/05/12 1p
- 0056150285 Forwards NRC 800528 memorandum & order re fire protection for electrical cables & environ qualification of electrical components
VOLLMER, E. H. Division of Engineering 80/05/30 1p
- 0004190288 FOIA request for list of equipment environmentally qualified by environ testing labs
RUMBLE, D. P. NRC, Inc 80/05/12 1p
- 0004090460 Responds to FOIA request for L. Pittin 1973-78 study of radiation levels in areas near active & inactive U mills & 1979 study under NRC contract re radiation levels in Shiprock, NM Deposit is required before request processed
FELTON, J. H. Division of Rules and Records 80/04/23 3pp
- 0004090564 FOIA request for L. Pittin 1973-78 study of radiation levels in areas near active & inactive U mills & 1979 study under NRC contract re radiation levels in Shiprock, NM area
HEILMAN, E. A. - People's Legal Services, Inc 80/05/03 1p
- 0004090547 Responds to FOIA request for seven categories of NRC distribution lists Forwards lists w/6 encls
FELTON, J. H. Division of Rules and Records 80/04/16 1p
- 0004090550 FOIA request for seven categories of NRC distribution lists
WILSON, J. T. Nucleonics Weekly, pub of AMR Hill, Inc 80/05/20 1p
- 0004090507 Responds to FOIA request for documents prepared for compliance w/NRC regulations re physical protection of irradiated reactor fuel in transit Documents listed in App A withheld (ref FOIA Exemption 4 & 1CFR262.740)
FELTON, J. H. Division of Rules and Records 80/04/16 3pp
- 0004090509 FOIA request for documents prepared for compliance w/NRC regulations re physical protection of irradiated reactor fuel in transit
MYERS, E. M. American Friends Service Committee 80/05/21 2pp
- 0004090520 Responds to FOIA request for five categories of documents pertaining to specific companies in NY & MD Forwards documents listed in App A Portions of Document 4 withheld (ref FOIA Exemption 4) (ref FOIA Exemption 4)
FELTON, J. H. Division of Rules and Records 80/04/17 3pp
- 0004090506 FOIA request for five categories of documents pertaining to specific companies in NY & MD
REID, A. B. Affiliation Unknown 80/05/12 2pp
- 0004090508 Responds to FOIA request sent to Dept of State for info re nuclear fuel facilities in Pacific region Documents responsive to request sent released to NRC on 800613 (FOIA-70-322, Document 2)
FELTON, J. H. Division of Rules and Records 80/05/17 1p
- 0004090504 Forwards NRC 781113 & 27 FOIA requests for info re proposed facilities in Pacific region Requests response Dept of State
CHAMBERLAIN, C. State, Dept of 80/05/10 3pp
- 0004090500 Responds to FOIA request for GECV-75-429 Forwards document w/6 encl
FELTON, J. H. Division of Rules and Records 80/04/16 1p
- 0004090504 FOIA request for GECV-75-429
FIDELL, L. E. R. Labouf, Lamb, Lelby & Harlow 80/05/13 1p
- 0004230001 FOIA request for Egeenex U mill declassification documents on activities after Dec 1978
REID, A. B. Affiliation Unknown 80/05/12 3pp
- 0004230005 Responds to FOIA request for documents re proposed nuclear reactors to be located near Oquema, Norena 3001-80-100 & License 30-0225 are available in RSR
FELTON, J. H. Division of Rules and Records 80/04/17 1p
- 0004230007 FOIA request for documents re proposed nuclear reactors to be located near Oquema, Norena
FIDELL, L. E. R. Center for Development Policy 80/05/21 1p
- 0004240442 Responds to FOIA request for documents re cost benefit analysis of 800607 order & list of incidents in first paragraph of Section 1 of order No cost benefit analysis was performed Forwards list of incidents & exposures
FELTON, J. H. Division of Rules and Records 80/04/19 4pp
- 0004240447 FOIA request for documents re cost benefit analysis of 800607 order & list of incidents in first paragraph of Section 1 of order
HUBBARD, L. B. American Association of Physicians in Medicine 80/05/10 1p
- 0004240600 Addl response to FOIA request for documents re proposed nuclear reactors located near Oquema, Norena Forwards OH McCarville 780528 memo NRC-79-143 is also sent to request & is available in RSR
FELTON, J. H. Division of Rules and Records 80/04/20 1p
- 0056150600 Discusses review of application for license to export reactor to Korea No physical security concerns apparent Requests that Executive Branch provide info re Korean exp of accounting & control & status of safeguards implementation
ROSENBAUM, S. M. Physical Security Licensing Branch 70/05/22 1p
- 0004270010 Responds to FOIA request for NRC-03-00-117 & winning technical proposal Forwards requested documents
FELTON, J. H. Division of Rules and Records 80/04/26 1p
- 0056150014 Analytical "Study of Requirements for Operator Licensing," awarded to Analysts & Technology, Inc
GORDON, L. Analysts & Technology, Inc 80/05/21 2pp
- 0056150017 Response to RFP 80-088-00-117, "Study of Requirements for Operator Licensing," Describes technical approach, technical difficulties & solutions, power plant & training systems (ref FOIA Exemption 4, 5, 6) encls
Analysts & Technology, Inc 80-088-00-117 80/05/12 7pp
- 0004270012 FOIA request for NRC-03-00-117 & winning technical proposal
WISSELLA, D. J. Advanced Technology, Inc 80/05/25 1p
- 0004270014 Responds to FOIA request for documents re Rockwell Intl Energy Sys Group use of radioactive materials Forwards documents in Apps A-G, incl partially withheld names & social security numbers (ref FOIA Exemption 4, 5, 6) encls
FELTON, J. H. Division of Rules and Records 80/04/20 3pp
- 0004270013 FOIA request for documents re Rockwell Intl Energy Sys Group handling & use of radioactive materials
GORDON, L. Affiliation Unknown 80/05/26 3pp
- 0004270016 Responds to FOIA request for documents re transportation of SRM Forwards JN Hendrix 700428 ltr to 2 brackets
FELTON, J. H. Division of Rules and Records 80/04/20 1p
- 0056150448 Forwards NRC 700428 ltr, in response to NRC request for assistance re FOIA request
ROSEN, E. B. President of US & Executive Offices 80/05/21 1p
- 0056150419 Discusses possible use of military airfield for high enriched U shipments Question has been referred to Executive Branch for consideration NRC responsibility in its regulate commercial export & import of privately owned SRM
HARRIS, R. J. Committee 70/04/28 2pp
- 0004270017 FOIA request for documents re transportation of SRM
HARRIS, R. J. Illinois State of 70/05/24 2pp
- 0004090502 Responds to FOIA request for documents listing nuclear plant locations, list of accidents at each facility & radiation leaks & results Forwards App A documents Remainder of request does not meet specificity requirement
FELTON, J. H. Division of Rules and Records 80/04/19 3pp

NONDOCKETED ITEMS

0906200024 FOIA request for documents listing nuclear plant locations,
list of accidents at each location-results of environ
impacts,radiation leaks & results & list of radwaste depots
RDMCY.J Affiliation Unknown RDCMR22 Sep

900430022: Forwards announcement re ACIS B0040W technical meeting in Washington, DC to continue review of HRC study on whether equipment changes should be made on BSM plants. Announcement will be sent to news media on B0022B. H/r: encl. NAME: [REDACTED] Office of Congressional Affairs B0/03/25 1p

—0004000229 Forwards announcement re NRC appointment of BJ Bader as program manager of Facility cleanup operations W/o encl
KAPPEER, C Office of Congressional Affairs 04/03/95 1p

--800AC00245 Forward announcement re NRE publication of notice of availability for public comment of draft environ assessment concerning dewatering/dredging of Peckliss reach-40-41d along atmosphere M/S east KAFFRER, C OFFICE OF Congressional Affairs 6/9/03/26 1c

--004300254 Forwards announcement re AGRE 00040F meeting in Washington, DC to discuss implications of Facility Incident in relation to applications for CRs Announcement will be mailed to news media re 000326 W/o encl
ANNEXED:G Office of Congressional Affairs 00/02/26 to

--BDC630020 Forwarded announcement re NRC response for public comment of
Addendum 2 to draft rep. "Environ Assessment for
Decommissioning TH-1 Reactor Bldg. Ashporens " W/s encl
HANNBERG,C Office of Congressional Affairs BDC64/02 ip

--8064300024 Forwards announcement re V Stello confirmation that DE has been actively pursuing inquiries into allegations made by H. Markham. Former facility control room operator W/A and NAWHEDRON.C. Office of Congressional Affairs 80/04/17 10

--3004300337 Forwards assessment w/attached NRC determination that facility incident did not constitute extraordinary nuclear occurrence as defined by Price-Anderson Act & Commission regulations w/s encl
KAMPEREN,C Office of Congressional Affairs MD/04/17 ip

—EOG260345 Forwards announcement re NRC approval of utility plans to make
 named entry into facility subsequently bid M/R encl
 KARNER,C Office of Congressional Affairs 50/04/22 1p

--8004200347 Forwards Announcement To NRRL 800013 prehearing conference
in Harrisburg, PA concerning proposed restart of facility
W/S and
8000008.0 Office of Congressional Affairs BORDENT, IN

--8006300445 Forwards announcement re extension until 800516 Per
comment on draft arrives. Assessment for decontamination of
reactor bldg atmosphere. U/S end!
KAMH0000ZC Office of Congressional Affairs 05/05/06 10

9004300305 Add response to PDR request for rule basing system
Impact Reg Analysis of possible risks in event of major
accidents at nuclear reactors Forwards documents listed in
App A
FEL:DM J M Division of Rules and Records 00/04/17 2ss

--600636538 Comments on BGCY-03-121, "Accident Considerations Under NEPA." Agree w/recommendations in Paper Commission should approve recommendation to initiate new approach w/ongoing NEPA reviews

IC946 Staff requirement memo re B009416 upon meeting in Washington.
A discuss SECY-80-121. "Accident Considerations Under
1. Commission requested that personnel consider methods
using plants in early coast shops
***** of the Secretary of the Commission 08/06/84

rest for records pertaining to firm
JCSHQ, HHC is unable to
and Records. 0000110 is

add on MEMO to Revisited 83

Order re SHAWNEE in Peabody, N.H.
as above; suppl. correspondence
to Dr. Shawnee

00062005M9 Response to appeal of partial denial of FOIA request for WL
Shedden's most recent approved spent fuel route plan Appeal
is denied in part partially withheld surface transportation
routes (ref FOIA Exemption 4 & 10CFR 270)
BUREAU of the Executive Director for Operations
MCNARM is

FOIA000576 Appeals partial denial of FOIA request for HL Industries
most recent approved spent fuel re-use plan
FOIA000576 Sierra Club 06/09/12 12

5004300582 Response to FOIA request for NUREG-0446 & NUREG-0449
 Forwards documents w/o encls
 FELTON, J H, Division of Rules and Records 05/04/20 1a

EO04000583 Responds to appeal re denial of FOIA request for documents re licensing of SWB Brown nuclear fuel facility Denies appeal re App B Documents 2-4 & 7 (ref PQSA Exemption 2) Grants appeal for App B Documents 1, 3, 5 & 6
CHILKIS J. Office of the Secretary of the Commission. 00/04/96
1a.

--B006300655 Nonproprietary memo recommending that facility license be modified to preclude possession of significant quantities of high enriched U L145s Considerations in reviewing paper info withheld (ref FOIA Exemption 3)
THOMPSON, H. L. Commission 35/12/13 Qas

```
--8066300612 Nonproprietary memo recommending that facility be allowed to
operate under NRC licensing control w/ID limit of 12
throughout NER must increase physical security as proposed
in EECY-79-620 Info withheld (ref FOIA Exemption D)
AMEHSE, J. Commission 80/01/00 Doc.
```

--0094309629 Nonproprietary memo agreeing w/000307 memo re Cons
 position on Facility Recommendations that IX throughput be
 considered ID limit goal.w/shutdown & inventory required at
 1 & 2 & 3; Info withheld (ref FOIA Exemption D)
 MKHREJ,J.H. Commission 80/05/11 In.

--0004300435 Covers w/summary points in EEO109 memo recommending
Commission position on fertility subj to listed requirements
Commission decision should be rendered immediately
H004629.8 T Commission 00/03/15 1p

BO06000586 FOIA request for NUREG-0546 & NUREG-0548
DANIEL A P Affiliation Unknown BO/06/02. 3p

EO 64000088 Add: Response to FOIA Request for all IRC records re
Coalition For Non-Nuclear World-member organizations &/or
nati & intl protests held during 000029-0450 Parawide
documents listed in App A Leaflet accounting protest and:
FELTOM:J H Division of Rules and Records 00/06/18 App

--B004300592 Announcement of a Coalition for Non-Nuclear World B00428
possible demonstration at DOE Forrestal Bldg in Washington-
DC & NYC W Street Bldg Demonstrators should be treated in
courteous manner
B00428.W.J. Debra of the Executive Director for Operations

--006430094 *Civil Disobedience Action Training Handbook, March from DOE
to Blockade Pentagon, 000428 *
* Coalition for a Non-Nuclear World 00/04/98 22us

HQ0430060: Response to FOIA request for mailing list: "MRC Distribution
 Category Code REL-State Legislation & Activities Rept "
 Forwarded mailing list M/A week
 REL/204. J N Division of Rules and Records 09/06/93 to

DO0600609 FOIA request for mailing list- "NRC Distribution Category
Code MC- State Legislation & Activities Rept "
FORSTER, J Affiliation Unknown 06/06/09 ip

NOA00000007 Responds to FOIA request for info re medical-psych projects NRE has no records pertaining to request
FELTON, J M Division of Rules and Records, 00/06/23 1p.

0006300609 FOIA request for info re medical-psychic projects.
SENSE:J H Affiliation Unknown NO/NO/IO ip

9006300665 Response to FOIA request for official communications from
JR HENRIDE to Congress during tenure as Chairman &
Commissioner of NRC All correspondence is available in FOM
FOLIO documents listed in App A
FOLIO: J.H. Division of Rules and Records 05/04/2015 Rios

NONDOCKETED ITEMS

PUBLIC DOCUMENT ROOM MISCELLANEOUS

00982 Advances of BODi3 on 20 meeting requested by J Nicholson of
United Healthcare Technology, Inc to discuss future
tion for railroads
BY, J.J Transportation & Product Standards Branch 03/02/97

120249 Discussion Interim procedures for research & study
radiation DFC of Nuclear Regulatory Research safety needs
studies are underway Needs, comments & communications
will be transmitted to Div of Safety Technology
FORMAL H: Office of Nuclear Reactor Regulation: Director
105/03 Day

1003022 Forwards two tables of water levels measured in Great Marsh
or Coules Bog during 180403-09 & 0414-0801
18041.0 1. Interior Peak of Geological Survey 1003022 466

020944 Informs that priorities for nuclear units scheduled for annual operation in 1992-93 period will be completed
Three WAs in response to 000507 ltr Data sufficient to
risk priority analysis will be supplied
INER, R E. Energy Dept of 01/03/93 to

000056 Comments on HR Denies 000028 its re qualification of reactor
operators requirement for engineering degree should be more
specific & spec of credit hr requirements should be more
responsive
LEER, B M Dept State Univ 00/03/91 2pg

000099 Ack Receipt of 000030 to R G/Yeung Forwards rough guide to
labile toxicity of various radiomolecules included in App B
000030. *Concentrations in Air & Water Above Natural
Background *

CH200444 Act receipt of HRC 800103 ltr & 800121 telcon w/JS Daegli
Expresses interest in short-lived, typically reactor-derived
isotopes for potential use as radiological weapons Request
originally sent to DOE
DPF04H.F.J. Defense Laboratories 80/03/30 tp

980299 Industry, education, govt radiation machine registration
 yigation
 RT, D, D Affiliation Unknown RD/Ed/03 2pg

110000 Forward specimen of all property insurance policy for smelter power reactors, including endorsements & clarification page Policy form used for all insured, however, dividend coverage may be subject to conditions.
 00000 C & American Nuclear Insurers 00/06/05 12pp

190084 Notification of B00029 meeting w/IFPD in Bethesda, MD to
 review exchange re. Human Factors program
 ELAND, R. Division of Human Factors Safety 89/05/23 2pg

120120 Responds to 800423 Re re FL Willman concerns about impact
land uses at nuclear plant sites in State of IL Amount of
land involved is small fraction of total farmland
available
800424 J. Office of the Executive Director for Operations
J05/021 200

04/20/22 Forwards PL Wilson ltr concerning impacts on land w
nuclear plant sites in State of IL
NASHBACK, E House of Rep 80/04/22 2pg

020157 Forwards comments on RM Clark paper. "Thermodynamics & Design of Heat Engines." Forwarded by BOD-129 1st Concerns. Is applicable to nuclear reactor regulation since based on validated models rather than actual properties of matter. DTIC 8 J Office of Nuclear Regulatory Research, Director 020157 4pp

06100100 Forward "Thermodynamics & Design of Heat Engines" Nuclear
Scheduling is not based on true, precise, next to perfect
science
CLARK, R W Affiliation Unknown EO/DA/DP is

55120061 "Thermodynamics & Design of Heat Engines"
 CLARK, B W Affiliation Unknown 80/04/29 24pp

120072 Requests info re Atomic Energy Act of 1954, including any
mandatory law & financial responsibility requirements of
linear facilities such as insurance requirements of accounts
insurance permissible
MC, H.D. Reuq. Martin & Fay Inc. 86/09/00 3p

000030100 Modification of 000610 meeting w/Nuclear Voice Control re demonstration of auto shutoff valve fail-out capability into valve check gauge, flow meter, dial, light & high/low temp indication
JOYCE, J Human Factors Engineering Branch 06/05/90 2pp

006103012 Forward extract of Team of Kensington. 003012 meeting re article 18 of 1980 Team Warrant. Evacuation for team feasible within time frame during which radioactive plume might cover town
R000VH, H R000VH, Steve & Hupe 00/05/12 12

0006176435 Notifies that Facility's Form modified to reflect change re definitions of insured shipment & insp suspension condition
Amendatory Endorsements NR-20 & NR-01 excl
QWATTECCCHJ, J American Nuclear Insurers 00/06/13 App

000606020 Returns license application for export of uranium to
Czechoslovakia w/o action because molb no longer requires
specific NRC export license FR notice of rulemaking amending
NRC (10CFR) 20 regulations and w/o action
HENRY, E O Office of International Programs, Director 80/06/05
1a

0046180000 Provides status of THE Bulletins & Orders Task Force work
Discusses WEF-V008-00CA analysis, auxiliary feedwater
upgrade & plant procedural audits
R088.0 TRU-2 Bulletins & Orders 78/11/03 App

0036200662 Adviser of inability to participate in Marketing Group 2 of
Coordinating Committee on Mill Tailings due to limited
travel funds Recommends rescheduling of mill tailings &
waste mgmt meetings to facilitate attendance
MARTIN, J B Uranium Recovery Licensing Branch 00/08/97 2pg

8006235046 Summary of 800029 meeting w/Inst for Nuclear Power
Operations re exchange of technical info
100-880-8 Division of Human Factors Safety 80/06/10 600

```
0005240460 Forwards "Test Rept A0521678/VR, Revision A, Booklet 174."
Catalog 50-1, get SRC 000524 15 requests Response to IE
Info Notice 50-15 will be forwarded upon Test rept & catalog
withheld (ref 106P52, 790)
0005240460 106P52, 790
0005240460 106P52, 790
```

000260009 Notification of 000617 meeting w/whil group in Bethesda, MD
to discuss IE Bulletin 00-01-messing well design
JORDAN, E.L. Division of Reactor Operations Inspections (IS-00-1
00/06/10 2pp

8006220031 Submit trip report of third meeting of Nuclear Waste Mtg
Process Review Forum on 800407-09 Supportive documentation
encl

000000046 Call special attention to certain procedures of revised manual chapter concerning radioactive contamination clearance. Emphasizes need to establish representative monitoring grid.

BSLBB M B Atomic Energy Commission 73/01/15 1960

NSC NSC/SAR REPLY ADV COMBINATION GENERAL

000000000 Notifies that current financial disclosure statements for senior AEC officials have been released to DOE per Ethics in Govt Act.
 * Office of the Secretary of the Commission 00/05/27 ip

0065300807 informs that confidential statement of employment & financial interests has been reviewed Exemption from provisions of IDOPD 710-31 must be granted in order to allow work on licensing matters involving Washington44
VOLUME 8 H Division of Engineering 00706211. Is

ABSTRACT

0005020426 Comments on NURE-0684 some criteria excessive. More important requirements should be tested on prototype basis before implementation on grand expensive scale. Also, NRC/PSRM should develop model emergency plan for states & towns.

0005020427 J. R. Marchant, Illinois, 0005020426, 7cc.

0006020537 NUREG/CR-0608
"On Corrosion Adequacy of 2 1/4 Cr-W Ni Steel for LWR
Steam Generation Sys By "
IIMA, G.S Battelle Memorial Institute, Pacific Northwest Laboratory
FIN 3-2181, PNL-2795. 00/05/91 70pg Available as NTIS

NONDOCKETED ITEMS

307

- 0006020543 NUREG/CR-1455
"Photostatic Studies of Sealing Crack Propagation and Crack Arrest in Polymers S-4260 Steel."
IMBIE, D. R.; SHERMAN, D. S.; GARNAND, R. J. Maryland Univ. of FM A-9026 05/03/83 27pp. Available at NTIS
- 0006020544 Comments on NUREG-0454 requirement for mechanical maint person on shift is of questionable value Requirement for bus or three main people on cell could be preferable
FARRER, M. E. Power Core 05/05/83 3pp
- 0006020550 Comments on NUREG-0034 document should be amended to follow warning sign he has second level received by individuals Examples of most info encl
KORNE, R. E. Affiliation Unknown 05/05/81 11pp
- 0006030084 Forwards comments on NUREG-0460, Vol 4, re ATMS for LWRs Committee on Reactor Licensing and Safety diagrams w/ proposed resolution based on design requirements
STONE, D. C. Atomic Industrial Forum 05/05/82 12pp
- 0006030094 Forwards will 000512 comments on NUREG-0454/FM-REF-1, "Criteria for Preparation and Evaluation of Radiological Emergency Response Plans and Procedures in Support of Nuclear Plants" submitted in response to 000512 PR notice
JAMES, R. M. American Electric Power Co., Inc. 05/05/82 13pp
- 0006030303 Comments on proposed NUREG-0454 submitted by County of Orange, CA, City of Anaheim City Requirements for fire terminology inconsistent w/ requirement for brevity
TURNER, E. B. Affiliation Unknown PC-01 05/05/89 3pp
- 0006030304 Comments on Draft 3 of NUREG-0460, "NRC Action Plans Developed as Result of TMI-2 Accident." Insufficient attention given to both general and special policy questions re: relative risk information in description w/ear-term OAS
FLISSET, R. B. ACSD - Advisory Committee on Reactor Safeguards 04/04/77 2pp
- 0006030504 Comments on NUREG-0460, Vol 4, ATMS resolution defined by Vol 3 is not factors for making of plants in operation & under const
GOSWAMY, R. Westinghouse Operating Plants Owners Group BLNRG 05-17 05/04/82 3pp
- 0006030512 Recommendations annually initiated 85 ppm standby liquid control sys as solution to ATMS issue basic approach should be to improve reliability of reactor term sys
JONES, M. H. Detroit Edison Co. 05/04/83 3pp
- 0006040001 NUREG/CR-1392
"Evaluating Strength and Ductility of Irradiated Zircaloy Test 5." Quarterly progress report Apr-June 1979
LOONEY, J. W.; HARRINGTON, J. E.; FORBES, J. E. Battelle Memorial Institute, Columbus Laboratories PIN A-8608 BNI-0649 05/05/81 45pp Available at GPO
- 0006040004 NUREG/CR-1392
"Final Report - Phase 2: Sys Interaction Methodology Applications Program."
DODD, J. W.; CHANDLER, R. R.; HATCH, E. M. Battelle Laboratories PIN A-1113 SAND 80-0384 03/04/80 21pp Available at GPO
- 0006040009 NUREG/CR-0049 UN
"Bifurcated Rate Control and Accounting Program." Vol 4, quarterly report Jul-May 1979
DAME, D. R. Lawrence Livermore Laboratory PIN A-0115 LORL-52735-73-4 05/05/83 24pp. Available at GPO
- 0006040101 NUREG-0460 Vol
"NRC Action Plan Developed as Result of TMI-2 Accident." Vol 1
* Commission 02/05/81 200pp Available at GPO
- 0006040282 Forwards comments on Vol 4 of draft NUREG-0460, "ATMS for LWRs." w/ encl
LOCHMUTZ, H. W. Electric Power Research Institute 05/05/89 1p
- 0006050427 Comments on proposed rule (SFRS) evaluation criteria do not adequately address issue of Class 9 event Requests available info that deals w/ specific problem of protecting infants
GARNETT, E. G. Affiliation Unknown 05/04/81 3pp
- 0006050507 Forwards partial BNL response to NUREG-0570, Section 2.1.9. The comments that BNL program for leadership have existing procedures for development of operator guidelines w/ encl
CAPRA, R. A. TMI-2 Bulletin & Orders 70/12/82 2pp
- 0006060292 Forwards Analysis Group recommendations in draft App V111 to NUREG-0411, "Research Evaluation of Feedwater Transients and Small Break LOCA in Nonboiling Designed Operating Plants."
ROSLITOV, I. R. TMI-2 Bulletin & Orders 70/12/82 10pp
- 0006060303 Requests info re encl draft request for add info required to complete evaluation of responses for power operated relief valve/safety valve activation & reactor trip frequency
CAPRA, R. A. TMI-2 Bulletin & Orders 70/09/82 3pp
- 0006060304 Discusses options for enforcing compliance w/ NUREG-0370 requirement re LGT. Example of LGT prediction of L2-D
KOLLS, D. Division of Project Management 70/11/85 3pp
- 0006090103 Comments on draft NUREG-0394 definition of "critical load" should be changed Differences between host drive motors should be explained
KATZ, R. E. Affiliation Unknown 05/04/85 3pp
- 0006090119 NUREG-75/087 CO 9 &
"Interim Revision 2 to Section 3.9.6." Interview Testing
* Office of Nuclear Reactor Regulation, Director 06/03/82 9 & 82 05/04/83 10pp
- 0006090244 NUREG/CR-1452
"Pusher Testing of Fuel-Clad Electronic Detectors."
FON, R. A.; HODGINS, C. D.; HODGINS, R. J. Battelle Memorial Institute, Pacific Northwest Laboratory PIN D-01270 PNL-0384 05/04/80 25pp
- 0006090302 NUREG/CR-1462
"Thickened Considerations Used in Development of PROFIT Fuel Pellet Model."
PARKER, R. J.; BATTIE, R. J. Battelle Memorial Institute, Pacific Northwest Laboratory PIN D-0271-0 PNL-0386 05/05/80 9pp Available at NTIS
- 0006090341 NUREG/CR-0441
"SOURCE Census Abuse Simulation Code."
OTHEL, R. L. Battelle Laboratories PIN A-1170 SAND 78-0334 70/05/81 30pp Available at NTIS
- 0006090352 NUREG-0460 B1
"Methodology for Combining Dynamic Responses."
HATCH, R. B. Division of Systems Integration 05/05/81 34pp Available at NTIS
- 0006100299 Provides review of NUREG/CR-1280, "Power Plant Staffing" & agrees w/ some recommendations Under NRC work w/ encl for Nuclear Power Corporation on new requirements
HODGA, J. M. Puget Sound Power & Light Co. PLM-008 05/04/83 2pp
- 0006100355 Requests extension to 000632 for response to NUREG/CR-1280, "Power Plant Staffing" published in 05/04/84 PR Delay caused by numerous local union replies received & anticipated
PILLARD, C. H. International Brotherhood of Electrical Workers 05/06/84 3p
- 0006100364 Address that Section 3.2 of NUREG/CR-1280 not completely true Personnel performing maint on US Navy facilities not always nuclear trained but are normally under or repair support personnel
KILLER, C. Affiliation Unknown 05/05/84 3pp
- 0006120155 Provides subcommittee on Energy & Power w/ NUREG-0449, "BNR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking." Per comments w/ encl PR notice encl
DENTON, D. R. Office of Nuclear Reactor Regulation, Director 05/05/82 1p
- 0006120165 Notice of issuance & availability of NUREG-0449, "BNR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking."
KERNST, D. G. Division of Licensing 05/04/82 3pp
- 0006120249 Forwards formal comments on proposed NUREG-0454/FM-REF-1, NRC & BNL have failed to recognize diversity of state & local goals Provision for assignments of responsibility should be identified as guidance not for concurrence
THORPE, L. M. South Carolina State 05/05/83 3pp
- 0006120264 Provides Subcommittee on Energy & Environ w/ NUREG-0449, "BNR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking." Per comments w/ encl PR notice encl
DENTON, D. R. Office of Nuclear Reactor Regulation, Director 05/05/82 1p

NONDOCKETED ITEMS

0006120170 Provided Subcommittee on Energy & Environ w/REG-00-0655. "SNF
Feedwater Nozzle & control Rod Drive Return-Line Nozzle
Cracking." for comment WFO and PR notice email
DENTON H N, Office of Nuclear Reactor Regulation, Strasser
06/05/02 3c

SEC0520571 Provides Subcommittee on Energy & Environ w/USDO-DOE, "BWR
Feedwater Nozzle & Control Rod Drive Mechanism-Like Nozzle
Cracking," for comment WFO and FR notice mail
SECTION 5. R. Office of Nuclear Reactor Regulation, Director
Groups/200 1.

0006120689 Comments on Vol 4 of NUREG-0460 Vol 3 requirements provide adequate resolution of ASB for most plants NRC concerns do not justify add requirements contained in Vol 4
BOWDER, F Standardized Nuclear Unit Power Plant System
BOWEN, J. See

NOA-2023-0000 Comments on NURE-2023-0000 should be issued as guidance only
 & industry invited to originate own implementation details
 In alternative, NURE should be made part of action plan
 DUDANS: I / Franklin Institute/Franklin Research Center 03/04/2023
 See

8004650355 informs that Commission paper is being prepared re proposed regulation of ATM generic issue contained in NUREG-0460
BOM, B. O. Michael Research Group, BOSTON, MA

9004120469 NUREG/CR-1135
"Econometric Study of Electricity Demand by Mfg Industries."
CHASS, H. B., CHASS, W. S. Oak Ridge National Laboratory, PIM B-0190-0
ORNL-NUREG/TR-8 80/05/31 63pp

8006120474 NUREG/CR-1422
"Analytic Rebalance Technique for Pressure Calculations in
Two-Phase Flow Systems"
MAG, C. C.; SMITH, V. L.; KRAVITZ, J. L. Argonne National Laboratory
ETN-A-2545 MS-CT-80-19 80/05/30 28pp

000410007 Forwards notice of BOGGS release of HUREG-0090, Vol 2, Number 4, consisting of 1918 AD rept to Congress
CHILE, B w Office of the Secretary of the Commission 05/08/09
1c

--000613004: Notice of release of ARJED-COTO Vol 2, Number 4, Consisting
1986 AG rpt to Congress
CHLN:B J Office of the Secretary of the Commission 00/05/EB
200.

EOG-130070 Forward notice of issuance & availability of HURD-0409, "SWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." For publication in earliest possible PR CHALK-B w/ Office of the Secretary of the Commission 08/08/10
1a

--800613007: Notice of issuance & availability of NUREG-0619, "SAR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking" - Comments should be forwarded by 800707
EJG:WWT,D & Division of Licensing, MS/CR-27, 2e.

0006150018 Submit comments on NUREG/CR-1288 re power plant staffing
Lack of knowledge of civilian power industry shown by
document. Major differences not shown in operation of
Navy plant compared to civilian nuclear plant
BIOGENSE, F. T. Kansas Gen. & Electric Co. 0006150000 doc

00566009% Response to 000400 request for add'l info re ACRS comments
in 000011 ltr concerning near-term CL items from Draft 3
of NRC Action Plan appraisal of merit of referenced
proposals will be possible only after deliberate study
PL03827-10 B ACRS - Advisory Committee on Reactor Safeguards
00/08/10 gpe

DOE/EA-000 Comments on NUREG-0657, "Transient Response of BSM-Designed Reactors " Expresses concern that recommendations in report show continuation of NRC trend toward less flexibility in resolution of safety issues.

PLESSET, M S ACRC - Advisory Committee on Reactor Safeguards

0066260141 HURON/CB-1387
*Independent Verification Testing/Analysis of Alternatives
For Conducting Independent Verification Testing of
Environmentally Qualified Safety-Related Equipment *
BNSG/L L Sandie Laboratories FIN 3-3977 BNSG7B-2444
06/05/01 4100 Available at NTIS

8906160140 NURDQ-0090 Y4 W05
"Program Summary Rept." Vol 4, Number 5
* Office of Management and Program Analysis 89-088423 100pp

03061601A9 Comments on AUREO-0454 suggests some specific requirements for protecting transient population be included in regional emergency preparedness program
BARKLEY, V D Transmittation, Dept of 03/03/09 4pp

9006570164 HUNG/CH-1120 VZ
"Reinhold Safety Nursing Research Program (Phase II):"
Progress Rept. 6
BASLEY, R. D. / SMITH, P. S. / CHOW, C. H. Lawrence Livermore Laboratory
EML-60104 04/06/75 1100s Available as NTIS

DOUGLE7627 Responds to NUREG-0460, "ASME Per LIRN - Several inadvertent startups of HPCI sys at Peach Bottom will show higher impact when factored into EPRF value-impact analysis"
KIMMEL, J W Philadelphia Electric Co 09/26/10 3ps

BOA200054 MURED-0574
Draft MURED-0676, "THI-Related Requirements for New OLs"
a Commission BO/06/18 2006

EO 0402229 Comments on proposed rule (ECFRS) properly organized and warning sys should address & include emergency broadcast sys HE Bureau of Civil Emergency Preparedness will develop plan compatible w/federal guidelines
HCDRAIL, M J Federal Emergency Management Agency BOD/DA/01 4p

9036200518 NUREG/CR-1339
"TRAFPLD Computer Code No Calculate Mass Flow Rates in
Thermal Hydraulic Test Facilities"
WHITEHEAD Oak Ridge National Laboratory PIN B-525
with ORNL-CR-78-502

0044900004 UNKED/ER-1017
"Vulnerability Analysis of Mixed-Grade Plants"
EASTER, K. W., WALTERMAN, H. A. Nonseris Co. RLP-2671 30/05/68
72c Available at NTIS

80342085H MURDO/CR-1005
Heavy Section Steel Technology Program, Quarterly Progress
Rep For Oct-Dec 1979 *
MITHRAN, G D , BRYAN, R H Oak Ridge National Laboratory FIN 8-0119
ORNL/MURDO/TH-3 80/03/731 105pp Available at NTIS

STUDY NO. 2003-01-001
*Models Selected for Calculation of Doses, Health Effects &
Economic Costs Due to Accidental Radioactive Releases
From Nuclear Power Plants*
STUDY NO. 2003-01-001
Laboratory: 2003-01-001 05/05/2003 1999 Available at NHTL

8004200035 NUMBER/CH-1397
"Risk Methodology For Geologic Disposal of Radwaste Small
Sample Sensitivity Analysis Techniques For Computer
Modeling/Application to Risk Assessment"
SHALE, L., CORNWELL, W. J., CAMPBELL, J. E. Sandia Laboratories P
A-1192 80/03/21 141cc Available as NTIS

HQ4200042 MURRO/CR-1430
 "Test PCN-5 Fuel Rod Nucleic Behavior"
 MURRO/CR-1430
 9999 Available at NTIS

0005230543 Comments on NURE-3622 & Addenda 1 & 2 reactor bld atmosphere & Hr-85 should be released to atmosphere as soon as possible
H05EPH66 M H Environmental Protection Agency 85/04/23 05

D04205846 NUREG/CR-1244
 "Development of Checklist for Evaluating Maint. Test &
 Repair Procedures Used in Nuclear Power Plants"
 SPUR, R. I., WEINSTEIN, M. Sandia Laboratories. PGN A-2292
 D04205847 50/55/51 2000 Available as NTIS

0000000000 "Capital Recovery of Nuclear Plant Decommissioning Costs"
 EWERTS B J Northern States Power Co 80/03/31 108pp

8004200334 Forwards updated status of activities for BSA plants re Bulletin evaluations, compliance w/long-term requirements of NSC 1979 orders & implementation of NUREG-0076 items
CAPSA, E. A. TRN-2 Bulletin & Orders 79/10/22 10pm

6004200543 NUREG/CR-1099
"Estimating Meter Equivalent Snow Depth From Related
Meteorological Variables."
STENHART, L. T.; LADIG, E. N.; STROMMEN, M. D. Commerce, Dept. of National
Geographic & Atmospheric Administration, PIN 2-1080 00/05/01
48pg Available at NTIS

NONDOCKETED ITEMS

- 0004200583 NUREC/CR-1429
"Strategic Review Table"
BARKER, H., BEICH, M., MODLER, S. Brookhaven National Laboratory FIN
A-3526 05/05/31 20pp Available at NTIS
- 0004200588 NUREC/CR-1274
"User's Manual for LARTOP 31 - Computer Program for
Calculating Radiation Exposure to Man from Routine Release
of Nuclear Reactor Liquid Effluents"
BIRNBAUM, S. B., MODLER, S. L. Oak Ridge National Laboratory FIN
A-1103 ORNL/NUREG/TR-82 05/05/31 32pp Available at NTIS
- 0004200593 NUREC/CR-1395
"Probability Estimates of Tsunami Extremes for Contiguous US"
BROOKHUIS, M. L., SUTPHAM, W. S. Cambridge Dept. of National Oceanographic
& Atmospheric Administration FIN A-1528 05/05/31 80pp
Available at NTIS
- 0004200597 NUREC/CR-0474
"Security Personnel Training & Qualification Criteria"
BROOKHUIS, M. L. Battelle Memorial Institute Safety & Safeguards NERS-5
Division of Safeguards 05/05/31 24pp Available at NTIS
- 0004200599 NUREC/CR-1297
"Best-Estimate LCCA Radiation Signature"
BROOKHUIS, M. L. Battelle Laboratories LURIE, M. A. IRT Corp FIN
A-1051-9 04/07/31 2143 05/05/31 170pp Available at NTIS
- 0004200605 NUREC/CR-1154 VI HQ2
"SWR Shutdown Emergency Core Cooling," Fourteenth quarterly
progress rept Apr-June 1979
GILBERT, D. L. General Electric Co NRC-04-76-215 GEMP-21504-14
7/9/06/31 20pp Available at NTIS
- 0004200611 NUREC/CR-1243
"Qualification Testing Evaluation Program LWR Safety
Research, Quarterly Rept Apr-June 1979"
BROOKHUIS, M. L., GILBERT, D. L. Battelle Laboratories FIN
A-1051-9 04/07/31 0275 05/05/31 42pp Available at NTIS
- 0004200619 NUREC/CR-0611
Errata sheet for Page 45 of NUREC/CR-0611, "Proceedings of
Workshop on Proposed Subelement on Emergency Planning for
Nuclear Power Plants."
A Division of Battelle, Health & Safeguards Standards 05/05/31
2pp
- 0004200621 NUREC/CR-0672 VI
"Summary of Technology, Safety & Costs of Decommissioning Ref
BWR Power Stations," Vol. 1: Main Rept
BARKER, H., HOLTER, G. H., REINBERG, W. E. Battelle Memorial Institute,
Pacific Northwest Laboratory 05/05/31 18pp
- 0004200626 NUREC/CR-0508
"Analysis of Fuel Allocation for NRC/PHN Halden Assemblies
198-421, 198-422, & 198-423," Interim Rept
GILBERT, D. L., MODLER, S. L., LARSEN, D. D. Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-2709 05/05/31 80pp Available
at NTIS
- 0004200641 NUREC/CR-1239
"Bibliography of Research on Research Sponsored by NRC Off. of
Nuclear Regulatory Research, Jan-June 1979"
STANBURN, J. B. Oak Ridge National Laboratory FIN B-0124
ORNL/NUREG/RSIC 05/05/31 121pp
- 0004200643 NUREC/CR-1412
"Bay for Continuous Measurement of Airborne Ra-222
Concentration & Mixing Level"
JOHNSON, M. H., TOLKIN, J. A., HIRSHMAN, J. E. Argonne National Laboratory
FIN A-2209 ORNL/EG-80 05/05/31 44pp Available at NTIS
- 0004200645 NUREC/CR-1285
"Accounting Data for BWR Control"
JOHNSON, P. A. Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-00549 PNL-3865 05/05/31 75pp Available at
NTIS
- 0004200648 NUREC/CR-1264
"Measurement of Aerosol Deposition Rates in Turbulent
Flow"
DICKERSON, J. A., LIKE, K. M., GILBERT, D. L. Battelle Memorial Institute,
Columbus Laboratories FIN A-0578 05/05/31 30pp Available at NTIS
- 0004200653 NUREC/CR-0047 VI
"Designated Mail Control & Accounting Program," quarterly
rept Oct-Dec 1978
DUNN, D. B., HARRISON, A. Lawrence Livermore Laboratory FIN A-0115
ORNL-02715-79-11 05/05/31 83pp Available at NTIS
- 0004200656 NUREC/CR-1114
"Physical Protection of Nuclear Facilities," quarterly
progress rept Apr-Jul-Sept 1979
CONRAD, S. Battelle Laboratories FIN A-1045 04/07/31 2060
7/9/12/31 28pp Available at NTIS
- 0004200658 NUREC/CR-1078
"Investigation of Distribution & Entrainment of Emergency
Control City Water Injected Into Open Phenon"
BARNHART, S., RICHARDS, H. J., MALL, D. G. D. Dartmouth College FIN
A-4076 05/05/31 47pp
- 0004200659 NUREC/CR-0435 VI HQ4
"Research Results Utilization," status summary rept, data as
of 7/9/81
Office of Nuclear Regulatory Research, Director 7/9/81/31 80pp
- 0004200662 NUREC/CR-1231
"Remote Sensing For Detection & Monitoring of Salt Stress on
Vegetation Evaluation & Guidelines," final rept Sept 1978 -
Mar 1979
GILBERT, D. L., FARMER, S. D., THOMPSON, H. D. INTESA Environmental
Consultants, Inc. FIN B-0205 05/05/31 150pp Available at NTIS
- 0004200663 NUREC/CR-0440
Draft "Draft Review of Radiological Assessment of Neph
Nuclear Power Plant, Analysis of Rept Prepared by Univ
of Heidelberg, West Germany"
BARNHART, S. F., CONRAD, P. J., CARDLE, P. P. Division of Systems
Integration 05/05/31 120pp
- 0004200665 NUREC/CR-1030
"Quarterly Technical Progress Rept on Water Reactor Safety
Program Sponsored by NRC Div. of Reactor Safety Research,
Jul-Sep 1979"
YANAGISAWA, J. I. Idaho National Engineering Laboratory FIN A-6038
05/05/31 79/10/31 44pp Available at NTIS
- 0004200667 NUREC/CR-1133
"Diffusion & Substitution of Radon from W Tailings"
SILVER, W. S., MCABERN, M. S. Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2267 PNL-3367 7/9/10/31 100pp
Available at NTIS
- 0004200668 NUREC/CR-1077
"Characterization Rept for Instrumented Nuclear Fuel
Assembly 198-813"
BRADLEY, E. E., CUSHINGHAM, H. E., DANIEL, J. L. Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-0043 PNL-3154
7/9/12/31 97pp Available at NTIS
- 0004200669 NUREC/CR-0202
"Ninth Annual Occupational Radiation Exposure Rept 1976"
Office of Management and Program Analysis 7/9/10/31 42pp
Available at NTIS
- 0004200671 NUREC/CR-1095
"NRC Safety Studies For Div. of Reactor Safety Research
Quarterly Progress Rept Apr-June 1979"
DANIEL, J. L., CLARK, J. C., CONRAD, P. J. C. Oak Ridge National
Laboratory FIN B-0102 ORNL/NUREG/TH-3 7/9/12/31 28pp
Available at NTIS
- 0004200675 NUREC/CR-1184 VI HQ2
"SWR Shutdown Emergency Core Cooling Fourteenth Quarterly
Progress Rept, Apr-June 1979"
GILBERT, D. L. General Electric Co NRC-04-76-215 GEMP-21504-14
7/9/06/31 22pp
- 0004200678 NUREC/CR-1217
"Central VA Regional Seismic Network Crystal Velocity
Structure in Central & Southwestern VA"
BOLLENDER, G. A., CHAPMAN, M. C., MOORE, T. P. Virginia Tech
NRC-04-77-124 05/05/31 321pp Available at NTIS
- 0004200679 NUREC/CR-1150
"Tensile Properties of Irradiated & Unirradiated Holders of
2022 Steel Pins & A500 Fasteners"
WILLIAMS, J. L. General Engineering Development Laboratory FIN
B-0110 NREL-TN-79-21 05/05/31 30pp Available at NTIS
- 0004200681 NUREC/CR-1261
"Data Summary of Life of Control Rods & Drive Mechanism
at JO Commercial Nuclear Power Plants," Jan 1972-Apr 1978
MARRIS, W. H., MILLER, C. F. EG&G Idaho, Inc. FIN A-6274 EG&G-5070
05/05/31 410pp Available at NTIS
- 0004200682 NUREC/CR-0254
"Methods for Assessability of Mixed Oxide"
Commission NRC-13 7/7/64/30 84pp Available at NTIS

- 8004270045 NUREG/CR-1111
"Development of Fabrication Procedures for H₂O₂ Fuel
Element Based on Use of Cold-Pressed Sinter Nitride
Powders"
HARRISON, R. W., JACOB, P. T., CLARK, D. L. Oak Ridge National
Laboratory ORNL/NUREG/TR-3 05/05/81 149pp Available at NTIS
- 8004270070 NUREG/CR-1264
"Microprocessor Based Underwater Data Acquisition Sys"
HOSLEY, S. L. Florida Univ. of, Gainesville UFV/OSL/TR/036
05/03/81 129pp
- 8004270097 NUREG-2297
"Review & Assessment of Research Relevant to Design Aspects
of Nuclear Fuel Element Piping Sys." Final rept.
"Division of Reactor Safety Research" HANEY, N. S., KROGER, J.
Battelle Memorial Institute, Columbus Laboratory ATUW-261-0353
NR-2 77/07/81 405pp Available at NTIS
- 8004270098 Questions on proposed actions for resolution of ATRM in
NUREG-0446-Vol. 4. NRC should initiate rulemaking to determine
need for & form of any licensing requirements for ATRM
Supports ATR positions presented in DC Bids 800627 IIR
OSD/Id H. Site Power Co. 05/03/82 7pp
- 8004270094 NUREG/CR-1263
"Compilation of State Laws & Regulations on Transportation
of Radioactive Material of Project Management" SHAW, D. J., HANEY, N. J.
Battelle Memorial Institute, Columbus Laboratory ATUW-261-0353
NR-2 77/07/81 405pp Available at NTIS
- 8004270099 NUREG/CR-1267
"Procedures Evaluation Checklist for Maint. Test & Safety
Procedures"
MCGHEE, N. H., SHAW, D. J., Human Performance Technologies, Inc. #
Battelle Memorial Institute, Columbus Laboratory ATUW-261-0353
NR-2 77/07/81 405pp Available at NTIS
- 8004270102 NUREG/CR-0829
"Measurement Control Program for Nuclear Heat Accounting"
BROOKS, R. J., JACOB, P. T., HARRISON, J. M. Battelle Memorial Institute,
Pacific Northwest Laboratory. PNL-30149 PNL-3021 05/06/80
73pp Available at NTIS
- 8004270098 NUREG/CR-0900 V2
"Function of Shielded Radioactive Mail Shipping Containers
Test & Upgrade Tests of Labeled Plates"
LINDER, R. A., HARRISON, D. P. Lawrence Livermore Laboratory PNL
A-0127-8 UCL/ES408 05/04/80 43pp Available at NTIS
- 8004270401 NUREG/CR-1446
"Preparation of Working Ref. Matrix U Dioxide"
HARRISON, D. P., SHAW, D. J., SHAW, D. J. Allied Chemical Co. PNL
A-0332 05/03/81 44pp Available at NTIS
- 8004270402 NUREG/CR-1143
"Considerations in Small Scale Modeling of Pool Boiling in
SFR Containment"
HARRISON, D. P., SHAW, D. J., ANDERSON, D. O. Massachusetts Institute of
Technology PNL A-0147 79/11/80 80pp
- 8004270403 NUREG-2442
"Technical Rept. on Operating Experience w/WR O-Ring Sys."
L. O. Environmental Evaluation Branch SHAW, D. J. Assistant
Director for System Engineering (Pw 79/03/81) SHAW, D. J. Division
of Operating Reactors 78/04/80 27pp Available at NTIS
- 8004270094 NUREG/CR-1120
"Isotopic Safety Margins Research Program (Phase II)."
Quarterly Progress Rept. S. 79/01/81
SHAW, D. J., SHAW, D. J., SHAW, D. J. Lawrence Livermore Laboratory
PNL A-0122 05/05/81 57pp Available at NTIS
- 8004270099 NUREG/CR-1243
"Methods to Assess Impacts on Hudson River Herring Run Rept.
for Period Oct 1979-March 1980."
HARRISON, D. P., CHRISTENSEN, S. J., SHAW, D. L. Oak Ridge National
Laboratory PNL A-0122 ORNL/NUREG/TR-3 05/05/81 37pp
Available at NTIS
- 8004270097 NUREG/CR-0892
"Advanced Two-Phase Flow Instrumentation Program Quarterly
Progress Rept. for Apr-June 1979"
TUNNEY, R. S., SHAW, D. J. Oak Ridge National Laboratory. PNL A-0401.
ORNL/NUREG/TR-0 79/11/80 30pp Available at NTIS
- 8004270098 NUREG/CR-1242
"Methods to Assess Impacts on Hudson River White Perch Rept.
for Period Oct 1979-March 1980"
HARRISON, D. P., SHAW, D. L., SHAW, D. L. Oak Ridge National
Laboratory PNL A-0423 ORNL/NUREG/TR-3 05/05/81 44pp
Available at NTIS
- 8004270099 NUREG-0020
"Interior Interference Alarm Sys."
Battelle Memorial Institute, Columbus Laboratory 78/02/80 47pp Available
at NTIS
- 8004270102 NUREG-0288
"Basic Aspects of Fuel Motion in Unprotected Transient
Overpower Accident in LWRs"
"Division of Project Management" SHAW, D. J., HANEY, N. S.
Virginia Univ. of, Arlington-VA-22206 77/06/80 26pp Available at
NTIS
- 8004270102 NUREG-0363
"Evaluation Behavior of Materialized Fuel Rod Failures in
LWRs"
SHAW, D. J. Reactor Systems Branch 78/03/81 30pp Available at
NTIS
- 8004270103 NUREG/CR-1266
"Critical Pathways of Radioisotopes to Man from Agro-
Ecosystems" annual progress rept. for Oct-Dec 1979
SHAW, D. J., ALBERT, J. J., ANDERSON, D. O. Savannah River Ecology
Laboratory PNL A-0124 79/01/81 26pp Available at NTIS
- 8004270103 NUREG-0286
"Study of Reactivity Effect of Bubble Collapse in Molten
Liquid Metal Cooled Reactors"
SHAW, D. J., HANEY, N. S.
Virginia Univ. of, Arlington-VA-22206 77/06/80 62pp Available at
NTIS
- 8004270104 NUREG/CR-1315
"Feasibility of Field Evaluation of Physical Protection
Procedures"
SHAW, D. J. Lawrence Livermore Laboratory. PNL A-0143 UCL-02746
05/03/81 74pp Available at NTIS
- 8004270104 NUREG-0640
"Summary of H₂O₂ Rept. of Radiological Assessment of
Ughl Nuclear Power Plants" Rept. by Univ. of Heidelberg, West
Germany #
Office of Nuclear Reactor Regulation, Director 05/06/80 159p
- 8004270105 Advances that BNL LPT pretest calculations required by
Section 2.1.9 of NUREG-0270 are scheduled to begin 79/11/81
SHAW, D. J. TMS-2 Section 2.1.9 79/10/81 5pp
- 8004270094 NUREG-2442
"Rept. Review of Radiological Assessment of Ughl Nuclear
Power Plants" Analysis of Rept. Prepared by Univ.
of Heidelberg, West Germany. draft rept.
SHAW, D. J., SHAW, D. J., SHAW, D. J. Assistant Director for
Environmental Technology 05/06/80 159pp
- 8004270099 ORNL/DEPA-6
"Side & Guidelines Pertinent to Development of
Determination Criteria for Sites Contaminated w/
Radioactive Mail"
SHAW, D. J. Oak Ridge National Laboratory US-70 78/06/81
5pp
- 8004270097 Notice of availability of proposed revision to GRF Section
3.9.4. "Intermittent Testing of Pumps & Valves," & addition of
App. A to GRF Section 3.9.4. "Leak Testing of Pressure
Containment Vessels" Comments requested by 050601.
HARRISON, D. J. Division of Safety Technology 05/04/81 2pp
- 8004270094 NUREG/CR-1243 V1
"Data Summary of LWRs of Valves at US Commercial Nuclear
Power Plants." Vol. 1, main rept. for 1978-Dec 1979
HARRISON, D. J. ES&O Idaho, Inc. HILLER, C. ES&O, Inc. PNL A-0276
05-05-8123 05/04/80 142pp Available at NTIS
- 8004270094 NUREG/CR-1243 V2
"Data Summary of LWRs of Valves at US Commercial Nuclear
Power Plants." Vol. 2, main rept. for 1978-Dec 1979
HARRISON, D. J. ES&O Idaho, Inc. HILLER, C. ES&O, Inc. PNL A-0276
05-05-8123 05/04/80 218pp Available at NTIS
- 8004270094 NUREG/CR-1243 V3
"Data Summary of LWRs of Valves at US Commercial Nuclear
Power Plants." Vol. 3, main rept. for 1978-Dec 1979
HARRISON, D. J. ES&O Idaho, Inc. HILLER, C. ES&O, Inc. PNL A-0276
05-05-8123 05/04/80 447pp Available at NTIS

8506000130 Comments on proposed rule 10CFR69 refers to worker-representatives & contractors should be clarified. Licensee should be advised of invoices prior to meeting. Present may be workable & preferable to others.
ALVIN, D. J. Cincinnati Gas & Electric Co. 80/05/04 2pp

8506000148 Comments on proposed rule 10CFR20.30.40.50.61.70 & 110 has reservations re alternative & independent EID. Critical element of NRC process is that if NRC limits licensing function to approval of final of applications.
HEDRICK, M. N. Environmental Protection Agency 80/05/05 2pp

8506000180 Comments on proposed rule 10CFR69 concerns w/ concept of self-pacing meeting procedures. Regulations should not be modified to invite individuals who license prior agreement.
SPITZER, R. P. Washington Electric Corp. 80-6-119 80/05/12 2pp

8506000184 Comments on proposed rule 10CFR19.30.40.50.70.71 & 180 proposed should be abandoned unless significant evidence is advanced re protection of employees who provide info.
HODAN, J. P. General Atomic Co. (subs. of Gulf Oil Co.) 80/05/08 2pp

8506000197 Comments on proposed rule 10CFR20 prefers option re unspecified job because operation would be free of cyclic federal govt budget & manpower constraints. Major concern is credibility of certifying lab.
BLANCHARD, A. Defense. Dept. of 80/04/17 2pp

8506000250 Response in support of State of NM motion for extension of proceeding schedule re first phase of proposed rulemaking on radioactive storage & disposal. Certificate of Doc. sent.
LEWIS, R. M. Texas. State of 80/05/21 2pp

8506000259 Comments on proposed rule 10CFR19 interested parties & consultants should not take part in discussion of tentative findings but be included in meeting end of map to review map findings.
WATKINS, R. P. Affiliation Unknown 80-80 80/05/09 1p

8506000310 Comments on proposed rule 10CFR20 independent certification. In order contract to NRC would be viable working relationship. Recommendations call for any changes of ANSI Std N22.11.
WHELAN, R. V., LANDAUER, R. B. Affiliation Unknown. 80/05/09 1p

8506000360 Comments on proposed rule 10CFR19 on behalf of Puget Sound Power & Light Co. & IA Electric Light & Power Co. Proposal is acceptable if amended to recognize right of parties to appear outside attendance at meetings.
BAHRM, M. A. Louisiana; Newham, R.A. Andover & Toli 80/05/12 App.

8506000361 Comments on proposed rule 10CFR20 supports regulation review of alternative sites for nuclear power plants. Local residents must have voice in matter.
JONES, C. Affiliation Unknown 80/05/14 1p

8506000379 Comments on proposed rule 10CFR170 objects to blank check approach to license fee assessments. GA program separate from application for approval of shipping package is of no benefit.
SCHNEIDER, R. M. Wyand. Mineral Corp. 80P-80-241. 80/04/24 2pp

8506000387 Comments on proposed rule 10CFR19 no objection to NRC inspectors having meetings during or following trip. Inspectors should not be permitted to invite outside guests.
BIECH, P. R. Chert Corp. 80/05/16 2pp

8506000398 Comments on proposed rule 10CFR73 fact that vital areas access shall be previously determined procedure need for permits numbered badge authorization codes. Criteria for authorization should be satisfied prior to entering area.
WHIT, R. E. Florida Power & Light Co. L-80-134. 80/05/15 1p

8506000399 Comments on proposed rule 10CFR20 new regulations should include some techniques for intruding national changes.
MOLINTON, J. T. Affiliation Unknown. 80/05/15 2pp

8506000401 Comments on proposed rule 10CFR20 public does not have proper protection in event of severe accident when existing monitors cannot measure amount of radiation released.
MARTIN, R. B. Affiliation Unknown. 80/05/16. 2p.

8506000408 Comments on proposed rule 10CFR19 inspectors should not be permitted to invite outside guests due to possibility of physical security plans & facility procedures being introduced on public fence.
KATZ, D. P. RMC, Inc. 80/05/27. 2pp

8506000514 Comments on proposed rule 10CFR19 supports establishment of having informal conference between DOE/IAEA. Comments re inspectors introduction of third parties could change conference to adversary proceeding.
KORSA, R. H. Atomic Industrial Forum 80/05/27 2pp

8506000520 Comments on proposed rule 10CFR73 existing regulations properly implemented provide high degree of assurance against industrial sabotage by NRC.
BYMAN, J. R. Union Electric Co. 80/05/15 1p

8506000587 Comments on proposed rule 10CFR20 radiation sources should be chosen to closely match radiation received by worker. Personnel should only be required to peak those categories of radiation for which legal records are provided.
SEER, J. L. Consumers Power Co. 80/05/20 1p

8506000600 Comments on proposed rules 10CFR20 & 81 schedule of initial phase of waste confidence rulemaking proceeding should be extended 80 days. Comments w/IAEA of ICF & 181 motions to enable participants to review documents filed by DOE.
WANCE, E. L. Virginia. State of 80/05/27 2pp

8506000607 Forwards notice of withdrawal of appearance & substitution of counsel re proposed rulemaking on storage & disposal of nuclear waste. Certificate of Doc. sent.
DANFERN, H. B. Tennessee Valley Authority 80/05/28 2pp.

8506000614 Response in support of State of NM motion for extension of schedule dates of first phase proceeding re proposed rulemaking on radioactive storage & disposal. Certificate of Doc. sent.
MCMANUS, C. D. Delaware. State of 80/05/20. 2pp.

8506000624 Notice of appearance in proceeding. Certificate of Doc. sent.
BISHOP, L. L., JORDAN, M. B. New England Coalition on Nuclear Pollution 80/05/28 1p.

8506000646 Memorandum in support of State of NM motion for 45-day extension of schedule dates re proposed rulemaking on radioactive storage & disposal. NRC delay of some bibliography filing was not anticipated. Certificate of Doc. sent.
MCMANUS, C. D., BROWN, M. J. Ohio. State of. 80/05/14 10pp

8506000684 Comments on proposed rule 10CFR20 on behalf of TX Unit. Considering re consideration of possible accidents. Different from those previously evaluated. Needs limiting language to control litigation & speedup amendment processing.
KIMBLE, D. M. D. Davenport & Loomis 80/05/27 2pp

8506000685 Comments on proposed rules 10CFR19 & 80 NRC has developed two-pronged practice that frustrates public participation & is inconsistent w/ Congressional intent. Utility is encouraged to wait until DOE review for NRC-DOE approval of rule.
WELSH, R. E. Union of Concerned Scientists. WEISS, E. R. Material Resources Defense Council. WEISS, E. R. Shelton, Herman & White 80/05/21 1pp.

8506000686 Comments on proposed rule 10CFR20 dosimetry processor certification should be performed by non-NRC regulated. Lab Private nonprofit lab or Amk Lab operated by NRC would administer further govt expansion.
KORSA, R. P. United Nuclear Corp. Naval Products Div. 80-80-8-26 80/05/25. 1p

8506000691 Comments on proposed rule 10CFR73 balance is needed between operational necessity & administrative burden of validating test for access each time entry is afforded. This believes technical security plan provides balance.
CANTILL, M. J. Consolidated Edison Co. of New York 80/05/20 2pp

8506000695 Comments on proposed rule 10CFR20 following areas should be addressed: (1) emergency response; (2) emergency response; (3) nuclear waste transfer stations. Baseline safety sources should be established. GA is prime request.
WEISS, E. R. Florida Power Corp. 80/05/20. 2pp.

8506000697 Comments on proposed rules 10CFR20 & 80 operators will be distracted from prime directive of plant operation to insure best of results are reported to NRC operators. Only safety regarding immediate action should be reported.
MARTIN, R. B. Indiana & Michigan Electric Co. 80-80-06 80/04/29 2pp.

8506000698 Comments on proposed rule 10CFR20 tag guide should be developed rather than rule or regulation. Tag guide would give small "in case" type flexibility needed & hold time on tag removed.
KALMAN, S. E. Tulsa Univ. 80/05/23 2pp

NONDOCKETED ITEMS

- 000410487 Comments on proposed rule 10CFR170 make clarification concerning language to specify when informal meetings can be held, extent of participation by parties outside NRC & licensees & requirements for adult participants
HOPKINS, D. W. Consumer Power Co. 00/05/19 1p
- 000410488 Comments on proposed rule 10CFR60 definition of disposal should mean replacement with intent to retrieve for any reason (other editorial changes suggested for clarity) (Kaphan should be on site characteristics)
QUINT, A. E. Affiliation Unknown 00/05/21 2pp
- 000410475 Comments on proposed rule 10CFR19 practical difficulties could arise re untrained participants in insp meetings
Clarification of participant qualifications & consequences of other party will facilitate resolution of insp findings
HOPKINS, D. W. Affiliation Unknown 00/05/19 1p
- 000410008 Forwards comments on proposed rules 10CFR2, 30, 40, 50, 55, 70 & 110
SCOTT, M. J. Illinois. State of 00/05/22 1p
- 000410017 Comments on proposed rules 10CFR 2, 30, 40, 50, 55, 70 & 110 NRC should make worst case analyses to make resource choices using alternative (State) accidents must be investigated & analyzed for specific sites
SCOTT, M. J. Illinois. State of 00/05/22 3pp
- 000410013 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70 & 110 provisions imposing civil penalties on licensees for actions of subcontractors or subcontractors should be clarified or deleted that need to protect taxpayer
DIERBE, D. C. Atomic Industrial Forum 00/05/21 2pp
- 000410014 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70, 110 rule does not identify procedures for identification, evaluation & protection of historical or archaeological properties affected by NRC licensing responsibility is neglected
SINKALIE, P. F. Affiliation Unknown 00/04/27 1p
- 000410015 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70, 110 NRC need not exaggerate CRP regulations NRC patterns have used practical interpretations to require enough info in EIR to make decisions
MILLS, L. H. Tennessee Valley Authority 00/05/19 2pp
- 000410025 Comments on proposed rules 10CFR2, 30, 40, 50, 70 & 110 added costs of evaluating alternative sites not cost effective
Major adverse impacts normally identified using reconnaissance-level info
PEOPLE'S, D. L. Commonwealth Edison Co. 00/04/26 7pp
- 000410017 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70 & 110 convoluted sentences, technical jargon & references to obscure documents make rule impossible for general public to understand. Comments should use writers to communicate
FORBES, C. K. Affiliation Unknown 00/04/28 1p
- 000410019 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70 & 110 wording of 10CFR31 (2)(ii)(1) should be revised to read no significant changes. Editorial change would eliminate some significant & parallel wording proposed for 10CFR31 (2)(ii)(2)
SCHWAB, R. K. Wyoming Natural Corp. RSP-80-091 00/05/21 1p
- 000410009 Comments on proposed rule 10CFR90 NRC should clarify lab w/continuous monitoring by NRC
SPILL, W. H. Louisiana. State of 00/05/17 1p
- 000410014 Comments on proposed rule 10CFR90 combining proposed rules of NRC & branch lab within NRC would gain benefits of long standing, continuous operation over contracted lab
SCHWAB, R. K. Oregon. State of 00/05/22 2pp
- 000410017 Comments on proposed rule 10CFR90 corrective measures are needed Supports proposed rule within reasonable cost limits
State add back justified should cost become excessive
Other personnel exposure measurement should be considered
SMITH, M. M. Beckman Instruments, Inc. 00/05/21 1p
- 000410021 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 NRC should consider & suggestions offered by RJ Walling of RM Dept of Natural Resources. Studies should be made full partakers in activities of site characterization
KORTMEIER, D. V. House of Rep. Armed Services 00/04/26 1p
- 000410023 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 consultation process should give state stronger voice
MALLER, P. J. Mississippi. State of 00/03/03 3pp
- 000410046 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 NRC & states should have opportunity to consult in 6 review site characterization studies to help insure that adequate data & safeguards are obtained
OMER, J. W. Mississippi. State of 00/03/03 3pp
- 000410028 Comments on proposed rule 10CFR73 better safeguards lie in areas of sound personnel screening, good mgt & training
employees Proposed amend would be costly to administer & would create unnecessary burdens on plant operations
RIVELL, L. Long Island Lighting Co. 00/05/19 2pp
- 000410029 Comments on proposed rules 10CFR2 & 50, significant hazard needs defined specifically NRC should not accept change even without regulation that may increase probability of accident
Regulations need strengthening
WAGGERS, G. A. E. Affiliation Unknown 00/05/21 1p
- 000410074 Comments on proposed rule 10CFR20 on behalf of Ionization State Director Info Bureau Present labeling practices adequate Labeling requirement should be deleted Compliance period should be extended to one yr
WAGGERS, G. A. E. Electronics 00/05/19 2pp
- 000410056 Requests 30-day extension on behalf of Association of American Railroads for comments on proposed rule 10CFR70
GARDNER, R. D. Affiliation Unknown 00/05/04, 1p
- 000410058 Comments on proposed rules 10CFR2, 30, 40, 50, 55, 70 & 110 on behalf of Baxter Edison Co., G-E, PL Power & Light Co., Houston Lighting & Power Co., Houshens 2M Public Rec. Co., Portland Electric Co., Pacific Electric Co. & Puget Sound Power & Light Co.
GRAY, P. B. Looney, Nichols, Johnson & Hayes 00/05/02 3pp
- 000410047 Forwards advance notice of proposed rulemaking re development of technical criteria for regulating geologic disposal of high level radioactive for publication in 00013 FR
CHILK, S. J. Office of the Secretary of the Commission 00/05/06, 1p
- 000410021 Advance notice of proposed rulemaking re technical criteria for regulating geologic disposal of high level radioactive comments due by 000714
CHILK, S. J. Office of the Secretary of the Commission 00/05/03 2pp
- 000410056 Forwards notice of 10CFR50 amend, requiring periodic updating of FGRs, for publication in 000509 FR
CHILK, S. J. Office of the Secretary of the Commission 00/05/06 1p
- 000410058 Notice of amend to 10CFR50 requiring periodic updating of FGRs
CHILK, S. J. Office of the Secretary of the Commission 00/05/03 10pp
- 000410072 Forwards notice of extension of comment period on advance notice of rulemaking on certification of personnel dosimetry procedures until 000427 for publication in 000509 FR
HAYLE, J. C. Office of the Secretary of the Commission 00/05/06 1p
- 000410077 Notice of extension of comment period on advance notice of rulemaking on certification of personnel dosimetry procedures until 000427 & notice of 000528-29 public meetings
DREXEL, M. J. Office of the Executive Director for Operations 00/05/08 2pp
- 000410059 Discusses draft final rules 10CFR20 & 70 on emergency planning, NRC-PSA approach should be developed & implemented to exchange state & local agencies to incorporate federal efforts into state emergency planning
PLEBERT, H. M. ACRS - Advisory Committee on Reactor Safeguards 00/05/11, 2pp
- 000410052 Forwards official suc list & 000508 memorandum & order to all participants Participating may serve two copies of filings w/NRC
CHILK, S. J. Office of the Secretary of the Commission 00/05/03 2pp
- 000410050 Order forming working group to advise Commission re adequacy of record in instant proceeding. Group will prepare guidelines to be asked of participants & of Commission providing officer or Commission Certificate of Suc. met.
CHILK, S. J. Office of the Secretary of the Commission 00/05/23, 10pp.

NONDOCKETED ITEMS

315

0006170031 Comments on proposed rule (DCPR33) distributing de-281
daughter isotopes to general public is grossly negligent &
highly irresponsible Regulations are extremely weak in
attempting to inform consumer
TDWG: M H Leigh-Pemberton Committee of Concerns 80/01/00 281

EC06175840 Comments on proposed rule 10CFR60 more definition needed re
marking of original surface of smoke detectors Marking name
of manufacturer & quantity would be of little value to
average person
NCRFP, Square D Co., Electromagnetic Industries 05/01/11 2PM

DOGA/70246 Comments on proposed rule 100FR51 alternate sources of energy should be proposed in addition to alternative sites. Negative aspects should be communicated to public in addition to positive points proffered by utility.

FRANZ, R. C. New Hampshire, State of 05/03/27 Doc

0006170247 Certifies avc of notices of appearances in proposed
reclaiming proceeding on storage & disposal of radwaste on
800530
JORDAN, H. S., BISHOP, L. L. New England Coalition on Nuclear Pollution
JORDAN, H. S. Natural Resources Defense Council 8002536 Rec

2006170277 Comments on proposed rule 50CFR50 recent legislation in CA requires upgrading of state nuclear emergency planning & capability legislation is being supported by technical assessment study of accident consequences
WLO.C California, State of 05/23/01 Ben

0006170331 Notice of appearances in proposed rulemaking proceeding
storage & disposal of radwaste AM Guterman appearance
withdrawn
BURGER, J F ; BURTON, D R Tennessee Valley Authority 80/06/28
in

0056170336 Notice of appearance in proposed rulemaking proceeding re
storage & disposal of radwaste JORDAN, W B New England Coalition re Nuclear Pollution JORDAN, W B
Natural Resources Defense Council JORDAN, W B Christo-maria
moore/22 1

0006170340 Notice of appearance in proposed rulemaking proceeding re
storage & disposal of radioactive
S1040P.L.L. New England Coalition on Nuclear Pollution
S1040P.L.L.; S1040P.L.L. Maharashtra Resource Defense Council

0266170345 Memorandum in support of Status of FBI & US actions & extension of proposed rulemaking preceding deadlines re storage & disposal of redacted documents 000701 for statements of position Certificate of Govt and

8006107015 Motion for 60-day extension of first phase schedule of proposed culminating proceeding re storage & disposal of radioactive waste materials until 02/03/21 to file statement of position if motion is not granted w/Certificate of Use

SP061970777 "Physical Protection of Irradiated Reactor Fuel in Transit,"
DOEP773 effective amendments to interim final rule Summarizes
public comments received, gives Commission responses & sets
forth interim amended rule in final form
CHLK, R J. Office of the Secretary of the Commission 06/05/97
dcm

8026[7077] Comments on proposed rule 10CFR32 decision not to include
 8026 re disposal of radioactive detectors is unacceptable
 8026 Disposal instructions necessary to avoid accumulation of
 8026 detectors in landfills areas NRC should recall the detectors
 8026 without a final approved NRC instructions. 8026[7077] is

000410700 Comments on proposed rule 106FR02 concern for inadequacy of marking on smoke detectors may be valid for devices sold retail. Class of product sent to professional fire protection specialists should not be included

STICKHAMMER, S. Walter Kilde & Co., Inc., Fenwick, Inc. 00/01/14
DIA.

8004170786. Comments proposed rule 102F822 ionizing detectors are not necessary Photoelectric can do job w/o bringing harmful radiation into home. NRC has no rules on regulation re disposal of devices

8006170814 Comments on proposed rules 10CFR2 and 30 proposed rule would be improvement in general. Rule allows for some predictability of NRC decisions NRC should set forth examples of significant hazards
STEPHEN, P. Commonwealth Edison Co STEPHEN, P. John, Lincoln & Seale, PG&E/22 Dec.

803467PC47 Paper entitled, "Legal & Financial Aspects of
Decommissioning," presented at AEE Conference on Environ
Regulation of the Nuclear Industry in San Francisco, CA on
800418-21
* Scheuflin & Liberman 80/05/21 1992

806472843 Camera44 on proposed rule 1007332 rule is important & should
be made final Rule should be strengthened to require
disposal instructions printed on outside of container
LOCKHEED, W A Affiliation Unknown 82/05/18 1p

0005170860 Paper entitled, "Util View of Decommissioning," presented at Conference on Environ Regulation of Nuclear Industry & New Reactors in San Francisco, CA on 000518-21
BLACKMON, B B Duke Power Co 000525/21 10pp

806210875 Comments on proposed rules 10CFR 83.50 wording should be changed to limit current broad criteria for significant hazards consideration
10CFR83.5 P Comments From: Co. OPT-44-80, 80/50/27 1p

development of emergency evacuation plans for fixed nuclear accidents
DO0CH41T2.R Geneva, DO/04/02 1p

0004170874 Comments on proposed rule 10CFR32 amends are strongly supported Group has suggested similar changes since 1977 Perhaps should have provision posted on lake that would keep detector away from children

SC0610025 Comments on proposed rule ICFRDO NUMBER-0634 appears to have been developed with consideration for local problems. Most damaging is method of write-off at nati level of dollar costs by cleverly worded statement.

2006ISO090 Comments on proposed rule ICEPR19 rule language is excessively broad re timing of conferences & class of persons to whom invitations might be extended Conference invitations must be limited to authorized representatives

BOGBOB comments on proposed rule 10CFR20 Alternative 4 is very attractive. NRC, in particular, would be ideal candidate since engineering skills are high & believable.
RJM, J.J. Herman-Grace Heaps Detroit, MI BOGBOB, 10

006180407 Forwards LA Galt B00312 comments on proposed rule 10CFR30
Properly organized early warning sys should address &
include emergency broadcast sys Mode to present sys &
& associated electronic equipment would be more efficient
NCS&all N J Federal Emergency Management Agency 03/04/01 4m

0000000000 Comments on proposed rule: ICEPBO properly organized early warning sys should address & include emergency broadcast sys. HE Bureau of Civil Emergency Preparedness will develop plan compatible w/Federal guidelines.

8006200540 "Capital Recovery of Nuclear Plant Decommissioning Costs
BENT, B. J., BENGLUND, R. H. Northern States Power Co. 80V001/31
100pp

0060200342 "rules of Practice for Domestic Licensing Proceedings." 10CFR2.764 proposed rulemaking lists three options being considered for amend.
CHILK, S.J. Office of the Secretary of the Commission SC/OS/IA
3pgg.

8004230049 Comments on proposed rule 10CFR140 opposes NRC view that public health & safety have been protected by ARS allowable limits of ionizing radiation. Proposes to do everything possible to stop force of ALARA.

8006220355 Comments on proposed rule 100PR140 NRC has grossly underestimated intelligence of public & insulted dignity of people weary of constitutional rights Opposes reopening of THU
WILLIAM L C Affiliation Unknown 78/07/01 1000

806240099 NUREG/CP-0011
Errata sheet for Page 45 of NUREG/CP-0011, "Proceedings of
Workshops on Proposed Rulemaking on Emergency Planning for
Nuclear Power Plants"
* Division of Histog. Health & Safeguards Standards 80/05/ST
Dra

NONDOCKETED ITEMS

9804240104 Comments on proposed rules 18CFR2.26-48, 50, 51, 70 & 110
 subjects unnecessarily to categorical exclusion for well
 logging from requirements for EEA & EIS Exclusion studies
 & unsupportable
 000000.0 0 HEM, Dept. of, US Public Health Service 00/04/06 Res

000240100 Comments on proposed rule 10CFR20 concept of adding internal
 & external doses long overdue more than one way exists to
 achieve radiation protection Decision should be left to
 prof
 WESLEY W F California, Univ. of, Los Angeles R05 G100
 06/05/09 Rys

800624200 Comments on proposed rule 10CFR220 relate re certification of personnel designing processors have been distributed to governmental agencies for review & comment Review scheduled to close on 800626
WHT246A0.0 Alaska Date of 85/04/30 3p

0054280377 "Fire Protection Program for Nuclear Power Plants Operating
Prior to 1960s." DCFR59 proposed rule Amend would require
certain min provisions for fire protection in operating
nuclear power plants
CHILK.D J Office of the Secretary of the Commission 80/05/25
430p

9394270171 UNRES/CR-0472 VI
"Summary of Technology, Safety & Costs of Decommissioning Ref
BNR Power Station." Vol 1, main rept
SAX, H O ; HOLTER, S M ; KIDNEY, W E Battelle Memorial Instit
Pacific Northwest Laboratory RD/DA/13. 18pp

9004250031 "Specific Domestic Licenses to Mfg or Transfer Certain Stone
Converting Byproduct Methyl." IDCRSQ final rule. Amend
regulations providing new requirements for labeling gas &
aerosol detectors, including smoke detectors
DISCRN/J Office of the Executive Director for Operations
00/00/27 Date.

—GD04200323 Value impact statement re need to GCP332 to provide new
Requirements for labelling gas & aerosol detectors
W. Office of the Executive Director for Operations 06/04/23
13ms

8046290344 Forwards notice of amend of 180PW35 For publication in
800014 FR.
CNDJLR J Office of the Secretary of the Commission 80/DO/OM
14

-8062250248 Notice of award of 10CP325 requiring licensee to keep
 records of misadvertisements of radioactive matl. report
 same to NRC, referring physician & patient & submit quarterly
 reports to NRC Effective on D01110
 CHL, R. J. Office of the Secretary of the Commission, 80/05/07

600429034 "Utilization of Excess & Disposal of Surplus Personnel
Property." ACE manual, App B17D
* Atomic Energy Commission 62/04/20 19pp

8042823347 Comments on proposed rules 100FR19:30-40,50,70,71 & 100-
addition of Paragraph a strengthened ability of employees
of transient workers to obtain records for employees ADDI
info necessary in order to have accurate current data
WISNES,M.D General Electric Co 04/05/80 1p

800252350 Comments on proposed rule DCFR20 Deep tapability should be modified to provide adequate safety and Provision for viable standardized description of health characteristics of population before operation of facility should be developed
BETHLEHEM Ministry of Concern for Public Health 05/05/21 300

0006260073 Transcript of Commission 0006108 public meeting in Washington, DC re FEMA's rulemaking on emergency preparedness
Pg 1-90
* Commission, 00/05/10 1:00pm

8906280170 Forwards FR notice of proposed rule for fire protection program for nuclear power plants operating prior to Jan 1979, for publication on Docket CHL&R J. Office of the Secretary of the Commission. 06/05/72

--000280173 RE notice of proposed rule for fire protection program for
 nuclear power plants operating prior to Jan 1979. For
 publication on 003209
 OMILK J Office of the Secretary of the Commission 00/05/25
 420

MS44270030 Farwande comments on proposed rule 40CFR55 Dunning of Nati
Sheldon Studies Project map, Subcommittee on Emergency
Planning & Siting Policy comments & Subcommittee on Environ
Sects comments encl
WHEC.C Atomic Industrial Forum 00/06/11 13ss

--0066270000 ASF/MCOP-010
"Alternative Siting Requirements & Practices for Nuclear
Power Plants," prepared for ASF/Mail Environ Studies
Project
* Jones & Moore 06/04/00 2000x

0906270160 Forwards statement of interim policies Accident considerations under NEPA for publication in FR Statement discusses Commission position re including considerations for future EIS

DENTON, R. Office of Nuclear Reactor Regulation, Director
00/06/06 13pp

0004000285 0486/00FA-4
"Risks & Guidelines Pertinent to Development of
Decontamination Criteria for Sites Contaminated W/
Radioactive Nukl"
DICKSON, R W Oak Ridge National Laboratory UC-70 78/08/01
50cs.

000600030 Memo to recipients of proposed rules 100719.30, 40, 50, 70, 71
 & 150 Advises that comment 30 was misread & should be
 removed from file
 * Docking & Services Branch 00/04/10 1a

0036300489 "Detection of Ref to Panama Canal Zone/Miner Amends," 1007925
 & 140 final rule. Miner amends reflect provisions of Panama
 Canal Treaty of 1977 & recently enacted Panama Canal Defense
 Act of 1979
 DINCHE, W J Office of the Executive Director for Operations
 08/05/82 Doc

0056300506 Comments on proposed rule (DOCFR) exclusionary safety std
Per acceptable site should be standoff distance & population
criteria Only reconnaissance level info is necessary to
evaluate site against new criteria
LEWISCH J W Portland General Electric Co 03/06/06 4pm

8006330361 Comments on proposed rule 10CFR36, submitted on behalf of Middle South Utility Gas endorses AEP comments Application of proposed rules to existing inventoried or banked sites is not clear
PATTERSON, J D Middle South Services, Inc 00/06/04 Gas

PRH PETITION FOR BULKHAIRING

EDC6030482 Comments in opposition to petitions for
SO-204 No legislative history cited in support of
contention
* LeBoeuf, Lamb, Leiby & MacRae 00/04/06 2p

0006120001 Comments on petition for rulemaking 50-26.petition should be discarded Radiation from direct hit of five megaton bomb would spread farther & faster than from nuclear plant
 01/04/81 Idaho Univ. of. 00/02/85. 5a

802a;20285 Comments on petition for rulemaking 50-26-Attack on US by
five neutron weapons would render issue re part of nuclear
facilities inconsequential Petition would cause further
energy cost increases & emit delays
LOWE,T Affiliation Unknown, 88/66109, 1a

000610287 Comments on petition for rulemaking 50-25.petition is overreaction due to concerns about possible radiation from power plant rather than from five megabecquerel explosion (Perrault,R.J. advertisement unknown) 000610288 1-

0004102291 Comments on petition for rehearing 30-26 petition should be denied due to reliance on erroneous assumptions. Heard above primarily from respondent from plant. No written exists to fully protect nuclear generating station from such attack. SILLMAN, R. M. See Dixon, C. A. & Klinger, C. 00-100702 See

900620272 Comments on petition for rulemaking 90-20 challenges, recommendations & suggestions in petition are valid. Urges serious consideration before finalizing proposed emergency planning regulations.

0036126426- Comments on petition for rulemaking 00-20 supports petition
 & urges fair & impartial hearing
 HUNTER, R B Indiana & Michigan Electric Co. 00/06/24. in

NONDOCKETED ITEMS

317

6004120424 Comments to petition for rulemaking 50-29 on behalf author & linked with portion of rule requiring 15-minute notification of those within 50-mile radius of plant after incident detection should be sub j of separate rulemaking
RDU/RS D P Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
RDU/RS/14 See

--0006120443 Petition for rulemaking to amend App C of 16CFR50 Fifteen-minute period for warning all those in 10-mile radius is arbitrary & unjustified issue should be subv of separate rulemaking Memorandum of support encl
KMUHL, D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
80/03/14 1309

BO04130094 Forwards notice of issuance of quarterly summary report
petitions for rulemaking pending final action
CHDLA S J Office of the Secretary of the Commission BO/05/06
10

--0006120098 Notice of issuance of quarterly summary rept of petitions
for rulemaking pending final action
CIVIL RIGHTS DIVISION OF DEPT OF JUSTICE, WASHINGTON, D.C. 20535-0005, Sep

0006170100 Forwards Duke Power Co. TX utility generating Co. to HPPSS
petition for rate-making 80-28

--0066170441 Petition for rulemaking SO-20, urging deferral of final
interim emergency response planning regulations Urges
redrafting & republishing of proposed regulations to permit
public comments on issues raised in envt statement
HOGARRY, J H Sube Power Co HOGARRY, J H Texas Utilities
Generating Co HOGARRY, J H Washington Public Power Supply

--H00647087 Statement in support of petition for releasing 30-20 Percent
events must be factored into proposed rule Urges
HUSD-0624/PD0A-SEP-1 to use only for guidance Requests
add'l use for implementation
MCAMURY, J H Duke Power Co MCAMURY, J H Texas Utilities

006170136 Fernando R. Malden 000108 11x & 000106 petition to change wording of 10CFR50-Paragraph 13 to require protection against attack by nuclear weapons
JACKSON, M N Nevada, Energy & Natural Resources 00/02/07 3p

Paragraph 13. to require protections against attack by nuclear weapons. Enclosure documentation end

0004170612 Forwards 000820 notice of denial of petition for rulemaking
2-7
CMM:M.J. Office of the Secretary of the Commission 03/05/20

--REGALTORB Notice of denial of petition for rulemaking 9-7 Consequences of proposed rule change permitting late intervention in NRC proceeding on basis of recent arrival in plant vicinity would not be conducive to orderly hearing

800675028 Comments on petition for reimbursing 30-2B capital costs should be borne by taxpayer Federal funds should pay cost of emergency plan maint & operational training.

0036260035 Comments on petitions for rulemaking 90-25 & 90-25A
proceedings being requested to alter rules re determination

806240280 Comments on petitions for rulemaking 80-29 & 23A, reserve
right to supplement petition after ASLR determination in
Bailly Nuclear Power Plant CP extension proceedings;
introduction of information concerning the

800s260134 Forwards FR notice of denial of W Edmonds petition for rulemaking 2-7, for publication as earliest possible date
CITE:R. J. CARR of the Secretary of the Commission 00000000

--2006262637 PA notice of denial of W Edelman petition for rulemaking
Re: requesting amend of 10CFR25 to define what constitutes
and cause for late filed evidence to determine

0006300521 Notice of publication of Foster Wheeler Energy Corp. petition
for rulemaking. FWH-01-0 Requests that persons licensed
pursuant to DOEFRM for industrial radiography be exempt
from approval in order to deliver licensed mail to carrier
CHSLN. G. J. Office of the Secretary of the Commission. 00/06/04
Dex

8002000508 Forwards comments on petition for rulemaking 80-6A
"Elimination of Domestic Riots & Gids of ICBP" ent
8002000508 Minister of Consumer & Public Health 78/12/18 1

==0006200000 "Evaluation of Domestic Risks & Needs of SCRP," presented at
44th Intl Congress of Radiation Research
SCHEIDT-FOURNA, ROSEBUD, E. SATURN, N. Bremen, Univ of
California, San

NOG010000 Forwards list of files designated by NRC & State of CA Dept
of Water Restricted for production from PDRS computers

8806170873 Notice of substitution of JC Ferrissey by MI Furber as
counsel for applicant. Certificate of Dkt #nc1

0066200150 Motion to dismiss appeal Agreement has been reached due to successful settlement negotiations RA Rizz declaration
encl
RIZZ, S. A., BARRY, D. W. Southern California Edison Co. 92222.R.A

0006200572 Forwards: "Post-Test Analysis of LOFT Lesson Coolant Experiment LB-3"

RC06200376 Discusses plan for extended operation of light water breeder reactor based on 21st meeting on 000901-03 at Westinghouse. still DOE & NRC/ACRS believes operation of reactor core to 24,000 RFPH is acceptable.

6646120330 Part 21 rept re Resonant Model 1152 transmitter output
between 400 & 90 mA occurs w/out pressure over or

transmitter electronics users should conduct analyses
WARD, R A Rossmount, Esc. 80V00V64 Spp.

becoming loose after continuous rotation during opening & closing of valve Caused by vibration due to play between internal & external splines

MO06100389 Part 22 repl re Rosemount Model 1152 pressure transmitters
Defect is ambiguous output when over or underpressured

SHR4000-9 G General Electric Co., Nuclear Energy Products Div
MDV-000-00 00/00/00 Typ

00362000004 Part 2: rept re two liner indications on outside surface of
ADM# Section 111, Class 1) Fitting, supplied by Capital No
defects found in either effluent tested Customer responsibility
for repair, repair and condition reported

app

review as potential deficiency. Licensee awaiting review
HARRIS A. BERNARD, Inc. 03/03/2016 See

NONDOCKETED ITEMS

DAV99 QUALITY ASSURANCE INSPECTIONS

8004030155 Act receipt of 800509 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004030162 Responds to NRC 800416 ltr re deviations noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004030163 Forwards QA Insp Rept 9900020/79-01 to 800303-05 & notice of deviation
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/04/99
 2pp

--8004030164 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Vendor Inspection Branch 05/04/99 1p

--8004030167 QA Program Insp Rept 9900020/79-01 to 800303-05
 Noncompliance noted: No evidence that QA director had prepared & approved required training golden rule procedures developed which specified rules to control visual exam.
 WINTERBELL, U.S. - WINTERBELL, U.S. Region 4, Dallas, Vendor Inspection Branch 05/04/99 10pp

8004040201 Act receipt of 800429 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99 1p

--8004040204 Responds to NRC 800405 ltr re deviations noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/04/99
 1p

--8004040205 Forwards QA Program Insp Rept 9900020/79-01 to 800303-05 & notice of deviation
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/04/99
 2pp

--8004040206 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Vendor Inspection Branch 05/04/99 1p

--8004040207 QA Program Insp Rept 9900020/79-01 to 800303-05
 Noncompliance noted: Failure to maintain callout card for Rockwell hardness tester & to include employee name ensuring tool on callout list
 WINTERBELL, U.S. - WINTERBELL, U.S. Region 4, Dallas, Vendor Inspection Branch 05/04/99 10pp

8004050208 Act receipt of 800484 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004050213 Responds to NRC ltr re violation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004050214 Act receipt of 800508 & 8429 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004050222 Responds to NRC 800414 ltr requesting additional re deviation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004050227 Responds to NRC 791228 ltr re deviation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/01/99
 1p

--8004050234 Forwards QA Program Insp Rept 9900020/79-01 to 800303-05 & notice of deviation
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/01/99
 2pp

--8004050237 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Office of the Director 05/01/99 1p

--8004050240 QA Program Insp Rept 9900020/79-01 to 800303-05
 Noncompliance noted: Failure to associate table of contents in QA manual to include QA/SA/PI II QA Procedures for pipe repair inspection not controlled by written order
 WINTERBELL, U.S. - WINTERBELL, U.S. Region 4, Dallas, Vendor Inspection Branch 05/01/99
 1p

8004060004 Act receipt of 800507 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004060003 Responds to NRC 800328 ltr re deviation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004060004 Forwards QA Program Insp Rept 9900020/79-01 to 800303-05 & notice of deviation
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 2pp

--8004060019 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Office of the Director 05/05/99 1p

--8004060022 QA Program Insp Rept 9900020/79-01 to 800303-05
 Noncompliance noted: Field tests not properly identified
 WINTERBELL, U.S. - WINTERBELL, U.S. Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

8004070128 Act receipt of 800425 ltr informing NRC of steps taken to correct violation & deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004070148 Responds to NRC 800328 ltr re violation & deviation noted in QA Program Insp Rept 9900020/79-01
 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

--8004070153 Forwards QA Program Insp Rept 9900020/79-01 to 800303-05 & notice of deviation
 POTAFQVU, U Region 4, Dallas, Office of the Director 05/05/99
 2pp

--8004070163 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Office of the Director 05/05/99 1p

--8004070167 Notice of deviation from Insp to 800303-05
 # Region 4, Dallas, Office of the Director 05/05/99 1p

--8004070173 QA Program Insp Rept 9900020/79-01 to 800303-05
 Noncompliance noted: Failure to comply w/required testing of X-ray Stereographic Analysis of 1974 & procedures & failure to record NCR number on QC data sheet
 WINTERBELL, U.S. - WINTERBELL, U.S. Region 4, Dallas, Vendor Inspection Branch 05/05/99
 7pp

8004080204 Forwards response to 800410 notice of noncompliance
 Licensee denies noncompliance, but prefers not to pursue
 separate & time-consuming proceedings. Payment for total
 amount of items 2 & 3 civil penalties and
 OUTLET, U.S. - Outlets, U.S. Co. 05/05/99 1pp

8004080447 Act receipt of 800809 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9900020/79-01
 POTAFQVU, U Region 4, Dallas, Vendor Inspection Branch 05/05/99
 1p

NONDOCKETED ITEMS

319

- 000120472 Responds to NRC 000403 ltr re deviation noted in QA Program Insp Rept V9900220/00-01 Corrective actions periodic audits scheduled to confirm requirement implementation
 CALSBERG, M. Forbore Corp 00/04/09 App
- 000120473 Forwards QA Program Insp Rept V9900220/00-01 on 000317-21 a notice of deviation
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/09 App
- 000120470 Notice of deviation from Insp on 000317-21 a Region 4, Dallas, Office of the Director 00/04/09 App
- 000120403 QA Program Insp Rept V9900220/00-01 on 000317-21 Noncompliance noted during scheduled identifying preventive maintenance, personnel performing & date of accomplishment not attached to tool folder
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/09 App
- 000120517 Advise that NRC has completed investigation of collection, evaluation & reporting of info available to BSM before TH-2 accident BSM failed to report safety info in timely manner of noncompliance & civil penalties and info will
 BELLLO, V. Office of Inspection & Enforcement, Office of the Director 00/04/10 App
- 000120516 Act receipt of 000319 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept V9900240/00-01
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/05/09 App
- 000120519 Responds to NRC 000416 ltr re deviation noted in QA Program Insp Rept V9900240/00-01 Corrective actions developed forms to gather scheduled data for verification for correction of scope of illegible records problem
 GULBERT, P E Subject & Hixco Co 00/05/09 App
- 000120521 Forwards QA Program Insp Rept V9900240/00-01 on 000311-14 a notice of deviation
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120524 Notice of deviation from Insp on 000311-14 a Region 4, Dallas, Office of the Director 00/04/10 App
- 000120528 QA Program Insp Rept V9900240/00-01 on 000311-14 Noncompliance noted, failure to retain QA audit exhibits QA records not legible Audit procedures do not contain ANSI requirements
 HALL, C J, JCHW80M, J M, PDS, D P, Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120529 Forwards QA Program Insp Rept V9900240/00-01 on 000428-0002 No noncompliance noted
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/05/12 App
- 000120533 QA Program Insp Rept V9900240/00-01 on 000428-0002 No noncompliance noted, Major areas inspected and meeting & implementation of 10CFR50, App B-np process control control of nonconformances & corrective actions & audits
 WATKINS, L, WATKINS, L S Region 4, Dallas, Vendor Inspection Branch 00/05/09 App
- 000120534 Act receipt of 000504 & 790324 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept V9900216/79-01 NRC agrees w/proposed corrective action comment made at 000307 meeting
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/03/20 App
- 000120535 Responds to NRC 791231 ltr re deviations noted in QA Program Insp Rept V9900216/79-01 Forwards attachments explaining corrective actions file attachments
 KATZ, L Tebco, Inc 00/02/04 App
- 000120542 Act receipt of 790324 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept V9900216/79-01 Forwards discussion of deviation notices for which vendor has supplied satisfactory corrective actions
 BEWITT, H V Region 4, Dallas, Office of the Director 79/12/31 App
- 000120570 Responds to NRC 790610 ltr re deviations noted in QA Program Insp Rept V9900216/79-01 Corrective actions added QA personnel will be hired, extensive personnel training will be conducted & Dept heads will review NRC report
 OLSBETH, W Tebco, Inc 79/06/24 App
- 000120574 Forwards QA Program Insp Rept V9900216/79-01 on 790212-16 a notice of deviation
 BEWITT, H V Region 4, Dallas, Office of the Director 79/04/10 App
- 000120576 Notice of deviation from Insp on 790212-16 a Region 4, Dallas, Office of the Director 79/04/10 App
- 000120582 QA Program Insp Rept V9900216/79-01 on 790212-16 Noncompliance noted, date of liquid penetrant exam refers to performance of weld repairs inconsistent with requirements No material audits by qualified auditors
 WATKINS, L, WATKINS, L S Region 4, Dallas, Vendor Inspection Branch 79/04/10 App
- 000120583 Forwards QA Program Insp Rept V9900216/79-01 on 000323-07 No noncompliance noted
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120593 QA Program Insp Rept V9900216/79-01 on 000328-07 No noncompliance noted, Major areas inspected implementation of 10CFR50, App B by applicable codes & strict review of bus deficiencies plus & vendor corrective actions & activities
 WATKINS, L S, WATKINS, L S Region 4, Dallas, Vendor Inspection Branch 00/05/21 App
- 000120593 Act receipt of 000522 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept V9900216/79-01
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/05/29 App
- 000120598 Responds to NRC 000417 ltr re deviation noted in QA Program Insp Rept V9900216/79-01 Corrective actions drawings identified in Insp will be sent out for comments by 000401 Mechanical Dept BSM 0004-1 will be reviewed & reviewed 000402
 MCFAH, J E, Sargent & Lundy, Inc 00/05/09 App
- 000120603 Forwards QA Program Insp Rept V9900216/79-01 on 000324-20 a notice of deviation
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120604 Notice of deviation from Insp on 000324-20 a Region 4, Dallas, Office of the Director 00/04/10 App
- 000120608 QA Program Insp Rept V9900216/79-01 on 000324-20 Noncompliance noted, failure to obtain interface comments on design drawings & failure of mechanical dept procedures re eye design prevent re main procedural requirements
 COTTELL, D E, HALL, C J Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120612 Act receipt of 000519 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept V9900216/79-01
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/05/03 App
- 000120616 Responds to NRC 000416 ltr re deviation noted in QA Program Insp Rept V9900216/79-01 Corrective actions records may be removed from files only by or in presence of personnel authorized list
 ASBETH, G M Bristol Steel & Iron Works, Inc 00/06/12 App
- 000120626 Forwards QA Program Insp Rept V9900216/79-01 on 000321-0403 a notice of deviation
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120629 Notice of deviation from Insp on 000321-0403 a Region 4, Dallas, Office of the Director 00/04/10 App
- 000120632 QA Program Insp Rept V9900216/79-01 on 000321-0403 Noncompliance noted etc operating procedure does not require records removed from storage to be checked out w/RA or provide for method maintaining control of records
 COTTELL, D E, HALL, C J Region 4, Dallas, Vendor Inspection Branch 00/04/10 App
- 000120633 Forwards QA Program Insp Rept V9900216/79-01 on 000324-20, No noncompliance noted
 POTAPV8V.U Region 4, Dallas, Vendor Inspection Branch 00/04/10 App

- 0004200230 GA Program Insp Rept 99000001/00-01 on 000324-28 Noncompliance noted Major areas impacted implementation of Technical Regs PCTPM-70 & Failure Action or previous Insp Findings
HMLEC J. S. 800408 R L Region 4, Dallas, Vendor Inspection Branch 00/04/97 App
- 0004200354 Ack receipt of 000506 ltr informing NRC of steps taken to correct violation & deviation noted in GA Program Insp Rept 99000003/00-01
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/05/97 App
- 0004200098 Responds to NRC 000328 ltr re violation & deviation noted in GA Program Insp Rept 99000003/00-01 Corrective actions to process of documenting procedures in areas of engineering changes & design review/meet review board & callout
GUMBERMAN E. Acme-Cleveland Co - Nucleon Controls Div 00/05/98 App
- 0004200415 Forwards GA Program Insp Rept 99000007/00-01 on 000311-14 & notice of deviation
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/04/99 App
- 0004200105 Notice of deviation from Insp on 000311-14
* Region 4, Dallas, Office of the Director 00/04/99 App
- 0004200172 GA Program Insp Rept 99000007/00-01 on 000311-14 Noncompliance noted failure to compile & implement written procedures in areas where activities affect quality
HMLEC J. S. 800408 R L Region 4, Dallas, Vendor Inspection Branch 00/04/99 App
- 0004200285 Requests add info re organizational changes discussed in 000314 ltr info needed to demonstrate that changes will not result in less effective QA program
HMLEC J. S. 800408 R L Region 4, Dallas, Vendor Inspection Branch 00/04/99 App
- 0004200077 Ack receipt of 000319 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99000001/00-01
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/04/00 App
- 0004200110 Responds to NRC 000417 ltr re deviation noted in GA Program Insp Rept 99000001/00-01 Corrective actions to process of documenting procedures in areas of engineering changes & design review/meet review board & callout
GUMBERMAN E. Acme-Cleveland Co - Nucleon Controls Div 00/05/98 App
- 0004200114 Forwards GA Program Insp Rept 99000001/00-01 on 000317-20 & notice of deviation
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/04/17 App
- 0004200118 Notice of deviation from Insp on 000317-20
* Region 4, Dallas, Office of the Director 00/04/18 App
- 0004200124 GA Program Insp Rept 99000001/00-01 on 000317-20 Noncompliance noted weld passes not recorded, welding w/e approved procedure, GA manual not submitted for approval & weld wire travel speeds not documented
WHITSELL, D. E. HARTER, V. H. Region 4, Dallas, Vendor Inspection Branch 00/04/18 App
- 0004200119 Ack receipt of 000513 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99000004/00-01
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/04/00 App
- 0004200127 Responds to NRC 000501 ltr re deviation noted in GA Program Insp Rept 99000004/00-01 Corrective actions to process of documenting procedures in areas of engineering changes & design review/meet review board & callout
GUMBERMAN E. Acme-Cleveland Co - Nucleon Controls Div 00/05/98 App
- 0004200134 Responds to NRC 000502 ltr re deviation noted in GA Program Insp Rept 99000004/00-01 Corrective actions to process of documenting procedures in areas of engineering changes & design review/meet review board & callout
GUMBERMAN E. Acme-Cleveland Co - Nucleon Controls Div 00/05/98 App
- 0004200138 Forwards GA Program Insp Rept 99000004/00-01 on 000311-14 & notice of deviation
POTAFDVU-U Region 4, Dallas, Vendor Inspection Branch 00/05/02 App
- 0004200123 Notice of deviation from Insp on 000311-14
* Region 4, Dallas, Office of the Director 00/05/01 App
- 0004200122 Notice of deviation from Insp on 000311-14
* Region 4, Dallas, Office of the Director 00/05/01 App
- 0004200121 GA Program Insp Rept 99000004/00-01 on 000311-14 Noncompliance noted failure to evaluate GA manual for description on how suppliers are selected & qualified
WHITSELL, D. E. HARTER, V. H. Region 4, Dallas, Vendor Inspection Branch 00/05/01 App

NONDOCKETED ITEMS

32

0003000143 Act receipt of 000313 ltr informing NRC of steps taken to correct deviation noted on SA Program Insp Regt
0003000207/00-01
POTPDVS,U Region 4, Dallas, Vendor Inspection Branch 00/04/00
1p

0003000144 Responds to NRC 000314 ltr re deviation noted on SA Program Insp Regt 99030207/00-01
Corrective actions made discrepancy not included on shop traveler mail. High priority reporting specifying of values w/o proper use of shop traveler
0003000150 P. H&H, Inc. 104 Mission Hq. Co. Div. 00/05/13 3pp

0003000153 Forwards DA Program Insp Regt 99030207/00-01 re 000325-08 & notice of deviation
POTPDVS,U Region 4, Dallas, Vendor Inspection Branch 00/03/14 2pp

0003000157 Notice of deviation from Insp on 000325-08
* Region 4, Dallas, Office of the Director 00/03/13 3pp

0003000172 DA Program Insp Regt 99030207/00-01 on 000329-28
Noncompliance noted with discrepancy report number not recorded on shop traveler mail. Discrepancy report disposition by QC representative
0003000173 D.M. 0003000173 Region 4, Dallas, Vendor Inspection Branch 00/03/13 3pp

REGDO REGULATORY GUIDES

0003000173 D.M. 0003000173 Region 4, Dallas, Vendor Inspection Branch 00/03/13 3pp

0003000189 Comments that draft Reg Guide 1 97, Revision 2 be issued after TMI-2 action plan requirements are settled. Guide should include AMR code
0003000189 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000190 Comments on proposed Reg Guide 1 14, Revision 2 states section 9.4 usually requires close body contact at all times during non-visible error can occur if close body contact is not maintained. Reg guide fails to support adequate dosimetry
0003000190 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000192 Comments on proposed Reg Guide 1 14, Revision 2 states section 9.4 usually requires close body contact at all times during non-visible error can occur if close body contact is not maintained. Reg guide fails to support adequate dosimetry
0003000192 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000193 Comments on proposed Reg Guide 1 14, Revision 2 states section 9.4 usually requires close body contact at all times during non-visible error can occur if close body contact is not maintained. Reg guide fails to support adequate dosimetry
0003000193 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000194 Comments on proposed Revision 2 to Reg Guide 1 14, words should be added to Paragraphs C 3 b & c to clearly indicate neutron dosimetry is not necessary when doses are expected to exceed 10 mrem/quarter. Calculated estimates better
0003000194 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000195 Reg Guide 1 14, Revision 1a, "Design & Fabrication Code Case Acceptability AMR Section 111, Div 5
* Office of Standards Development, Director 00/03/01 3pp

0003000196 Forwards notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/01 1p

0003000197 Comments on proposed Revision 2 to Reg Guide 1 14, requirements to increase endow Insp will result in increased costs w/o any justification
0003000197 E. General Electric Co. H&H-104-00 00/01/00, 3pp

0003000198 Forwards notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/01 1p

0003000199 Notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/04/00 2pp

0003000200 Comments on draft Reg Guide 1 14, recommends that after wells be included in introduction as acceptable type for dosimetry
0003000200 E. General Electric Co. H&H-104-00 00/01/00 1p

0003000201 Forwards comment on proposed Revision 2 to Reg Guide 1 14, "Personal Neutron Dosimeters - Until questions re alpha neutron dosimeters & are answered, such wells should be deleted from guide
0003000201 E. General Electric Co. H&H-104-00 00/03/01, 3pp

0003000202 Forwards notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000203 Notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000204 Notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000205 Forwards notice of issuance & availability of proposed Revision 1 to Reg Guide 1 14, "Critically Accident Alarm
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000206 Notice of issuance & availability of proposed Revision 1 to Reg Guide 1 14, "Critically Accident Alarm
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000207 Notice of issuance & availability of draft reg guide, "Instructions Concerning Risk From Occupational Radiation Exposure"
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000208 "Far Comment" issue of draft Reg Guide 1 14, "Instruction Concerning Risk From Occupational Radiation Exposure"
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000209 Notice of ACRS Subcommittee on Regulatory Activities 0003000209 open meeting in Washington, DC to discuss proposed Reg Guide 1 14, Revision 1 & revisions to 100300 & 55
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000210 Comments on proposed Reg Guide 1 14, Primary Function of personal dosimetry is not measurement by dose control
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000211 Forwards FR notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000212 FR notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000213 Forwards notice of issuance & availability of Reg Guide 1 14, Revision 1
CHILK, J. J. Office of the Secretary of the Commission 00/03/02 1p

0003000214 Discusses implementation of revised GSP 3 A 7, providing revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000214 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000215 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000215 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000216 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000216 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000217 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000217 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000218 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000218 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000219 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000219 E. General Electric Co. H&H-104-00 00/03/00 2pp

0003000220 Discusses proposed implementation of revised cooling system requirements & risk assessment re overall plant heat removal capability
0003000220 E. General Electric Co. H&H-104-00 00/03/00 2pp

NONDOCKETED ITEMS

- 0004602144 "LOFT Fuel Bundle Structural Response to Mechanical Loads During Subcooled COOL." Revision 1
HARTWELL, J. B. EG&G, Inc. LTR 1111-05 00/04/03 14pp
- 0004602194 "Special LOFT Features for Improved Monitoring & Survival of LOCA Transients." technical R&D interim report
DOODERSON, D. - MARCH, L. P. EG&G Idaho, Inc. LO-87-80-130 00/01/07 40pp
- 0004602199 "Fuel Control & Accounting Effectiveness Evaluation Development." progress report for Mar 1990
DOODERSON, D. - Lawrence Livermore Laboratory FIN A-0315 NC
00-08-03-UR 00/03/19 7pp
- 0004602481 "Experimental Data Rept for Heater Rod Test Series B-1C." experimental data
GARNOLD, J. W. - KILBURN, C. W. - SELONG, H. D. EG&G Idaho, Inc. LTR 26-67
00/01/09 37pp
- 0004602593 "Thermal Analysis of LOFT SPD TE Coated Kivi Box." analysis report
FARHULE, S. P. EG&G Idaho, Inc. LO-87-79-129 00/02/26 7pp.
- 0004602597 "Electrical Instrumentation & Control Features of Proposed HPCI & SBAP Tests." informal report
HAYES, S. E. EG&G, Inc. EDO-EX-0150 00/05/31 12pp
- 0004602596 "NRE Monthly Rept for Mar 1990."
YANAGISAWA, L. J. EG&G, Inc. YOR-87-80 00/04/30 10pp
- 0004602599 "Inventory of Two-Phase Critical Flow Experiment Data Base." preliminary assessment report
HALL, D. G. EG&G, Inc. EDO-CAAP-3140 00/04/30 42pp
- 0004602594 "Experimental Data Rept for Transient Flow Calor Facility Tests 1A81-1A102 & 1A103."
HARTWELL, J. B. EG&G, Inc. LO-80-80-114 00/03/10 20pp
- 0004602598 "Feasibility Transient Test of Correlation Time Transient Time Facility in LTRF Borehole Facility." experimental data
SILVER, A. C. EG&G, Inc. LTR-141-110 00/02/26 91pp
- 0004602610 "Offers on comments as Jan 1989 monthly progress report for NRC contract FSN B-0279."
GARNOLD, S. C. Uranium Recovery Licensing Branch FIN B-0279
00/03/24 1p
- 0004602647 "ORR Refill-Revised Program Progress." monthly ltr for Apr 1990
BURNETTE, G. M. General Electric Co. NRC-04-79-124 00/04/30 41pp
- 0004602695 "Physical Protection of Nuclear Facilities." informal progress report for Mar 1990.
CHAMBERS, D. Sandia Laboratories FIN A-1060 00/03/19 8pp
- 0004602693 "Environ Assessments of Fuel Cycle Facilities." monthly progress report for Apr 1990
SILVER, A. C. Oak Ridge National Laboratory. FIN B-0279
ORNL/RES/128 00/04/30 4pp
- 0004602695 "Nondestructive Examination Evaluation Report." monthly progress report for Apr 1990
SMITH, J. R. Oak Ridge National Laboratory FIN B-0283
ORNL/RES/0030-8 00/03/26 3pp
- 0004602693 "LAR In-Plant Measurement Program Rept." informal monthly progress report for Apr 1990
HARRIS, J. W. EG&G, Inc. FIN A-4073 00/05/15 5pp
- 0004603174 "Program for Standardized Analysis of Fuel Shipping Containers." quarterly report for 00/01-02/91.
WATSON, D. C. - WOODALL, R. H. Oak Ridge National Laboratory. FIN B-0172. ORNL/RES/11NF-80 00/03/01 8pp
- 0004603330 "Physical Protection of Nuclear Facilities." monthly progress report for Apr 1990.
CHAMBERS, D. Sandia Laboratories FIN A-1060 00/03/19 8pp
- 0004603703 "Experimental Evaluation of Ventilation Gas Components During Large Pressure Pulses." informal monthly progress report for Apr 1990
WERNER, M. R. Los Alamos Scientific Laboratory. FIN A-7020 00/05/20 3pp.
- 0004603708 "Characterization of Radionuclide Contamination Throughout LAR Pump Stations." informal monthly progress report 00/01
ROBERTSON, D. E. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-0279 00/04/11 11pp
- 0004603716 "Impact of Decontamination on LAR Radon Gas & Gas Measurements as Precondition to Decommissioning." informal monthly progress report for Apr 1990
ROBERTSON, D. E. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-0283 00/03/19 7pp
- 0004603721 "ORR Shutdown/Emergency Control Ctr Program Progress." monthly ltr for Apr 1990
BURNETTE, G. M. General Electric Co. NRC-04-79-219 00/04/12 13pp
- 0004603826 "Data Comparison of PLECHT-SMART Bolt-Off Test 20357 Using RELAP5/MCOT." temperature report
OZDEMIR, H. M. EG&G Idaho, Inc. FIN A-4037 EDO-CAAP-5192 00/03/31 30pp
- 0004603930 "Reactivity Initiated Accident Test Series: Test RIA 1-4." quiet leak report
HARTWELL, J. B. - EL-SHOW, H. B. - FLOUDA, G. M. EG&G Idaho, Inc. FIN A-4041 EDO-17EP-3144 00/05/31 53pp
- 0004603977 "Switch Lock Rept for Benchscale Mod-3 Small Break Tests B-80-01, B-80-02 & B-80-07."
SILVER, A. C. - FARMER, T. J. - HEWITT, J. R. EG&G Idaho, Inc. FIN A-4038 EDO-RENT-1137 00/04/30 48pp
- 0004603981 "Rept on New EAR Feedwater Nozzle/Boiler Design by GE." informal report
BURNETT, R. - WEICH, H. Brookhaven National Laboratory FIN A-0322 ORNL-RES/0-0329 79/12/31 29pp
- 0004604007 "Safequards for Proliferation Resistant Fuel Cycles." informal monthly ltr report for Nov 1979 through Apr 1980
SILVER, A. C. Brookhaven National Laboratory FIN A-0321 00/06/04 18pp
- 0004604004 "Test Prediction for Benchscale Mod-3 Small Break Tests B-80-01 & B-80-04."
FARMER, T. J. EG&G Idaho, Inc. FIN A-4038 EDO-RENT-1139 00/04/30 77pp
- 0004604040 "PLECHT-SMART." monthly status report for Apr 1990
FARMER, T. J. Westinghouse Electric Corp. NRC-04-77-127 00/04/28 9p
- 0004604045 "Environ Measurements Project." monthly progress report for Apr 1990
SILVER, A. C. Oak Ridge National Laboratory FIN B-0301 ORNL/RES/128 00/04/30 5pp
- 0004604046 "Parametric Analysis of Electric Demand by State & by Unit Over Area." progress report for Apr 1980
OZDEMIR, H. M. Oak Ridge National Laboratory FIN B-0196-8
ORNL/RES/048-93 00/03/31 5pp
- 0004604070 "Effect of Dispersed Condensed Phase on Rayleigh-Taylor Instability of Gas-Liquid Interface." informal report
NOZAKURA, J. H. - OHTSUKA, T. Brookhaven National Laboratory FIN A-0324 ORNL-RES/0-2780 00/03/31 41pp
- 0004604074 "Annual Rept on TRAC Independent Assessment at ORNL." informal report
SAWYER, P. - GUNATILLU, U. S. - MERTENSTEIN, L. Brookhaven National Laboratory FIN A-0324 ORNL-RES/0-2780 00/01/31 49pp
- 0004604665 "Code Development & Analysis Program Parametric Study on Sliding Surface Reactor." technical report
TAKES, E. EG&G Idaho, Inc. FIN A-4076 EDO-CAAP-2149 00/04/30 8pp
- 0004604614 Paper entitled, "Correlation of Local Heat Flux from Ignited Vol-Melted Pools in Scaled Flow," to be presented at 25th Natl Heat Transfer Conference
OZDEMIR, D. A. - ADAP, H. - JONES, W. C. Brookhaven National Laboratory ORNL-RES/0-2761 00/04/18 9pp
- 0004605017 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Spans Lines & Pipes in Steam Piping Sys." progress report for 00/04/80-02/91
YANAGISAWA, L. L. Dandelion Associates, Inc. NRC-04-79-242 00/04/04 13pp

NONDOCKETED ITEMS

0006200010 "Biside Byproducts in Aquatic Environa." quarterly rept for
Jan-Mar 1980
REML R 4 Ballester Memorial Institute, Pacific Northwest Laboratory
80/003434 3ea

#064200021 "Safeguards Analysis for Spent Fuel Melts & Small Quantities
of GDN," monthly progress report for Apr
CREDIT, R O , FARRAR, K L , RANDOLPH, L N Oak Ridge National
Laboratory P.O. Box 6808 CHATTANOOGA, TN 37604-0008

004400022 "Advanced Reactor Safety Analysis Technical Assistance: Reactor Projects," monthly highlights for Apr
SARL R A Brookhaven National Laboratory FEN A-0000 00/08/09
dx

0004260023 "Assessment of Radiation Doses Resulting from Releases of Rn-222 & Ra-226 from U Mining & Milling Activities." monthly progress report for Apr
 TRAVIS, C. C. FIDONELL-BOYER, MATHEW, A. P. Oak Ridge National
 Laboratory. FM 80021. ORNL-046580-00 20/05/12. 40p

MDA200025 "Thermal Hydraulic LMFBR Safety Experiments," Apr monthly
highlight ltr
GEMMERS, T Brookhaven National Laboratory PSN A-3034 85/04/30
See.

8004200026 "HTOR Safety Program" monthly highlights 1st Feb-Apr
8004200027 Breakdown National Laboratory File A-2016 02/03/99
...

80GA200027 "Evaluation of LWR Residual Heat Removal Under Accident Conditions, Technical Assistance/Reactor Projects," monthly highlights for Apr. 1987, U.S. Department National Laboratory, RM A-2000 80/05/04M

DDO6250001 "RAMONA Code Red & Evaluation," "IRT & RETRAM Code Red & Evaluation" & "Simulator Model Evaluation," Apr monthly highlight ltr.

ECOA2000041 "3FA-425 Pission Product Measurement Sys Description & Steoping Test Results, Thermal Poels Behavior Program." preliminary rept
APPL/HMBB.A D : SWS/JARTSON.9 CO&S, Inc FIN A-8214
R00/TWSP-SCGA 79/12/31. 43aa

WDA0235094 "Div of Reactor Safety Research - GEM Program" Apr 1995
monthly highlights
WDA0235094 Oak Ridge National Laboratory: RD/OS/ID. 34pp

EC0628001 Paper entitled: "Analysis of Passive Ex-Vessel Core Retention Device During Postulated Core Melt Event" FRATTI, T.; DAMBER, D. Brookhaven National Laboratory HAS-06080-27994 00/06A/18 Res.

BB04200009 "Sandia Core Melt & Separate Effects Program Progress,"
monthly ltr for May 1980
BB04200010 Sandia Laboratories BB-04-182 12PP

ED06250042 "Integration of Nondestructive Examination & Practice Mechanics," monthly rept for Apr 1980
DOCKEE, F L. Battelle Memorial Institute, Pacific Northwest Laboratory. PDM 8-0289. 80/000/07 1980.

00042305H "Evaluation of Socket Files of Terminated License," monthly progress report for Apr 1990
HOLDWAY, C. F.; SICKERSON, M. W. Oak Ridge National Laboratory. PDM A-9265-7 ORNL/HADR-77 85/04/30 14pp.

EO04280049 "Impact of Decantation on LAR Madrasa Mys &
Decantation as a Precursor to Decantation" Informal
weekly progress report for May 1980
PMBRIGG, L. D. Battelle Memorial Institute, Pacific Northwest
Laboratory P.O. Box 9999, Richland, WA 99360-0999
FIN 0-2000 00/00/00 3pg

8004280302 "Long Level Activation Products in Reactor Halls." Informal
monthly progress report for Apr 1980
EWING, J C Battelle Memorial Institute, Pacific Northwest
Laboratory P.O. Box 9999, Richland, WA 99352-9999
4pp.

Research Info Ltr '90 submits results of first Ofc of Nuclear Regulatory Research sponsored independent assessment of LCCA code. RELAP=4/1086
SUBMITT. R. J. Office of Nuclear Regulatory Research, Director 00/00/02 2336

8806040019 'LOCA Test Series - Test TC-1,' test results rept
YACLET R, MATERNALAN E, MACDONALD, P E EGAD, Inc PIN A-001
EG-TFEP-0049 09/09/91 110pp

W0426W0020 "Sealing Criteria & Assessment of Bendraile Mod-3 Sealing
for Gneil Break Loss of Coolant Transients"
LARDON, T K.; ANDERSON, J L.; SHIMEN, D J. 1995, INC. FIN A-4038
205-5825-5121. 80/03/22 1995p

0006260025 "Inventory of High Level Nuclear Wastes in US Govt High
Level Waste Existing Commercial High Level Waste Existing
Commercial Spent Fuel & Projections of Commercial Spent
Fuel"
MAJUMDAR, D. SINDHU, J P Brookhaven National Laboratory FEM
A-32000 CAR 000000-000000 00000000 1977-

8066260021 "Fuel Code Assessment Data Sample Rept "
CHAMBERS, R. WINTER, H L.; LAATS, E. F. EDGO, Inc. PIN A-804a
800-CAMP-9114 80/02/29 40pg

00000000 *Data comparison of PLECHT-BEASSET Refined Test 21304 Unit
RELAP4/MDM & RELAP4/MDM7
09DEC.8 H 0809: 2cc FPN A-6039 EGG-CAAF-9162. 05/05/91. 43

8004260037 "Quick-Look Rept on LOFT Nuclear Experiment LA-5 "
ROEDER, D L. EDS; 1st. FIN #=6046. EDS=LOFT-3165. 00V06/30.
21pp.

8006260029 "Test Prediction For Semiscale Mod-2 Test S-DB-4 - Small
Break Test Series"
HUTCHINS, J L. ; SHIMODA, D M. EDG. INC. FIVE A-ACORN RD-888H1-2047

6006280042 "Semiscale Small Break Grillage Cooler Tests."
COOPER, J.H. - 1968-05-22 P. 2040. 1hr. EN 6-6000 EQO-50H-500

8906250046 "Gene Reflood Dynamics Code - FLOOD4," Interim rept.
 BIRDSONG, R. W. 2040, Inc Elm A-1039 605-6293-3335 78/10/91

8004268426 "GAR Refill = Refiled Program" tenth monthly report May 1971
 8004268426 m. 41 General Electric Co. 800-44-75-104 00.000.001 11

9004270078 "Monitoring for Compliance w/Decommissioning Criteria."
Last progress rept.
BICKERMAN M., LANTZ, P.H., HELOWAY, C.F. Oak Ridge National
Laboratory. ENR. 4-20-88:7. 0000. 04/20/88. 70p. \$5.00/10. 77*

0004300171 "BRAC Assessment & Referral Development," monthly highlights
for Apr 1980
BRAC-R, Washington, National Laboratories, STM 4-0018, 00-104-000

004200103 *Analysis of Hypothetical Accidents Resulting in Core
Meltdowns." Progress report for May 1980
DENHARDT, R. B. GYSGULSKI, P. DAYBUTT, P. Battelle Memorial Institute
Columbus Laboratories FIN A-4067 00/06/10 9pp

0050300109 *Steam Generator Tube Rupture Iodine Transport Mechanisms,
progress report for May 1990
DORRIS, M. S. Battelle Memorial Institute, Columbus Laboratories,
NBC-04-75-293 89/04/13, 4pp

8004303204 "Nuclear Power Plant Design Concepts for Radiological Protection," informal progress rept, Oct-Dec 1979.
ERIC004-D H Sandia Laboratories FBN A-1240 80/01/28 14p

Protection," informal progress report, Jan-Mar 1980
ERICOM, D # Bandia Laboratories. PIN A-1216 90/06/02 7pp

Highlights for Apr 1980
ASARP/N. [Frederickson National] Laboratory. FIN A-2015 00/04/30
4pp

0004300210 "Nuclear Power Plant Design Concepts for Radiological Protection," informal progress rep., Jul-Sept 1979
ERICSSON, D H Sandia Laboratories. F1H A-1230 79/10/26 10pp

0006300004 "Stress Corrosion Cracking of PWR Steam Generator Tubing:
Monthly Highlights For Apr 1990.
BULL/SCHEER, T.; VAN ROOYEN, L. Brookhaven National Laboratory. PB
A-3208 00/05/90 7pp

- 8004030098 "Risk & Guidelines Pertinent to Development of Decommissioning Criteria for Sites Contaminated H₂ Radioactive Nuisance"
SICRADA H W Oak Ridge National Laboratory H09R-009A-4 UC-90
78/06/23 3pp
- 8004030099 "Evaluation of PDF LOFT Leak Test Results Concerning Surface Thermodynamic Perturbation Effects." (Internal)
technical report
CARLSONDALE M L, TOLMAN E L EDG4 Idaho:INC FIN A-604B
LO-06-79-128 03/05/83 12pp
- 8004030105 "US Std Problem 10 Preliminary Rept." comparison repts
S0845 C A, LACOMBE J L EDG4 Idaho:INC FIN A-604B
8004-SAP-0134 05/05/83 7pp
- 8004030580 "Monitoring for Compliance w/Decommissioning Criteria."
Task progress rept
OIGERDILL M L, LAMPT P H, HOLMWAY C F Oak Ridge National
Laboratory FIN A-9005-7 H09L-WA82-78 03/05/83 7p
- 8004030590 "Noise Allegations for Safety Assessment:Confession On-Line
Reactor Surveillance Sys." foreign internal rept
H09WEXEY P J Oak Ridge National Laboratory FIN B-0191
H09L-PTM-043 03/05/82 13pp
- REVIEW QRP NRC RESEARCH REVIEW GROUPS
H09WEXEY P J Oak Ridge National Laboratory
- 8004030592 "Forward: 'Post-Test Analysis of LOFT Loss-of-Coolant
Experiment LO-3'"
H09WEXEY P J EDG4 Idaho:INC 03/05/83 3pp
- SECY POSITION PAPERS BEFORE THE COMMISSION
H09WEXEY P J Oak Ridge National Laboratory
- 8004030631 SECY-79-038A
Orbitals analysis of need for further protection of
Category II & III mail in transit. Recommendations approval of
Alternative 2 re amendment of current NRC regulations. NRC should
prepare alternative for publication in FR
H09WEXEY P J, Office of Nuclear Material Safety & Safeguards
79/12/23 2pp
- 8004030632 SECY-79-142
Recommend Commission approval of FR publication of public
comment amend to 10CFR73 re physical protection of Category
II & III mail Table categorizing nuclear mail and
H09WEXEY P J, Office of Nuclear Material Safety & Safeguards
78/02/28, 14pp
- 8004030633 Discusses SECY-77-778.NRC & Intl physical protection stes
Commission approve general IEC approach & recommends
development of appropriate rules NRC related to SECY-79-142
and
SECY-80-4
Office of the Secretary of the Commission 77/06/30
8pp
- 8004030634 SECY-79-038A
Recommend Commission approval of FR publication of public
comment amend to 10CFR73 re physical protection of public
transportation against radiological sabotage & theft of
strategic BW proposed rule-draft press release & RIA, and
H09WEXEY P J, Office of Nuclear Material Safety & Safeguards
H09WEXEY P J, Office of Standards Development, Director 77/06/17,
7p
- 8004030635 Comments on 770601 paper re amends to 10CFR73 to provide
strengthened physical protection against radiological
sabotage & theft of strategic BW. Draft press release & RIA, and
H09WEXEY P J, Office of the General Counsel 77/06/07 5pp
- 8004040284 Forwarded and use statement for GA Co 770201 application for
license to export research reactor fuels to Iran
H09WEXEY P J General Atomic Co (subs. of Gulf Oil Co) 77/03/03
2pp
- 8004040285 Forwarded for 770201, Justification Analysis. In support of
770201 application for license to export fuel elements to
Iran. Inventory of new fuel will permit continued operation
of reactor for research purposes.
H09WEXEY P J General Atomic Co (subs. of Gulf Oil Co) 77/02/11,
13pp
- 8004040284 Application by GA Co for license to export 24 kg U-235,
contained in 24 kg U to Iran. NRC draft ltr to GA Co and
H09WEXEY P J General Atomic Co (subs. of Gulf Oil Co) TEL-938
78/07/12 3p
- 8004050215 Transcript of 000515 public meeting in Bethesda, MD re
withholding of NRC spent fuel route info from public
accession file 3-03
* Commission 05/03/83 3pp
- 8004060409 Notification of contract execution "Study of US Nuclear
Health & Safety Info Dissemination to Foreign Countries,"
awarded to Franklin Inst
H09WEXEY P J Administrative Contracts Branch FIN D-1648
HRC-08-00-038 03/05/83 1p
- 8004090302 Contract "Study of US Nuclear Health & Safety Info
Dissemination to Foreign Countries," awarded to Franklin
Inst
H09WEXEY P J Administrative Contracts Branch FIN D-1648
HRC-08-00-038 03/05/83 3pp
- 8004090303 SECY-79-038
Request Commission issue on results of studies &
recommendations re health & safety considerations in NRC
reactor licensing & nuclear assistance programs. Recommend
Commission approve anal analysis.
H09WEXEY P J, Office of International Programs, Director 78/07/03
8pp
- 8004090307 "NRC Staff Analysis of Health & Safety Considerations in
Reactor Exports & Assistance Programs"
* Commission 78/01/28 3pp
- 8004120595 Weekly info rept for unending 040503
H09WEXEY P J Office of the Executive Director for Operations
03/05/83 5pp
- 8004120615 Response to FOIA request for SECY-78-127 Document is
available in SC PM.
FELTON J N Division of Rules and Records NRC 03/06/83 1p
- 8004120617 FOIA request for SECY-78-127
H09WEXEY P J, Texas Public Interest Research Group 03/05/83 1p
- 8004120635 SECY-80-038
Forward Executive Branch view on proposed exports of fuel
& components to India & recommend preparation of order &
cover ltr to President meeting that applicable export
criteria have not been met
H09WEXEY P J, Office of International Programs, Director 03/05/83
4pp
- 8004120636 Application by Edlow Intl Co to export 487.3 kg U-235 to
India Govt of India 780411 ltr to DOE and
* Edlow International Co 78/09/20 2pp
- 8004120638 Confirms SECY-80-038
Request Executive Branch view on proposed exports of fuel
& components to India & recommend preparation of order &
cover ltr to President meeting that applicable export
criteria have not been met
H09WEXEY P J, Office of International Programs, Director 03/05/83
4pp
- 8004120647 Transcript of 030508 afternoon Affirmation Session 80-03 re
SECY-80-74 re Washington DC Ps 1-3
* Commission 03/05/83 3pp
- 8004120648 Transcript of 030518 briefing in Bethesda, MD re upgrade of
operations cfr Ps 1-73 Hearing session
* Commission 03/05/83 7pp
- 8004120649 SECY-80-038
Recommend issuance of license to Reuter-Bihler, Inc to
export low enrichment chambers to Venezuela. License request
forwarded for Commission review because proposed export is
destined for country w/o previous authorization
H09WEXEY P J, Office of International Programs, Director 03/05/83
3pp.
- 8004120649 Reuter-Bihler Executive Branch view re application by Reuter-
Bihler, Inc for license to export low enrichment chambers to
Venezuela. Recommend that license be issued
H09WEXEY P J, State Dept, Off. Bureau of Ocean & International Security
& Scientific Affairs 03/04/83 3pp
- 8004120646 SECY-80-038
Recommend that Commission candidate Applications
SECY-80-038, SECY-80-038 & SECY-80-038 of Applications listed in
SECY-90-0208, for review purposes Also recommend that
Commission make receipt of SR request to amend SECY-80-038
H09WEXEY P J, Office of International Programs, Director 03/05/83
3pp

NONDOCKETED ITEMS

325

- 8006100473 Submits Executive Branch views re application by Bryan Jackson Pump Div for license to export components & parts to India. Recommends that license be issued
HOSBETH, L. V. State, Dept. of, Bureau of Science & Internal Control & Scientific Affairs 00/05/13 2pp
- 8006100477 Submits Executive Branch views re application by Carpenter Technology Corp. for license to export L&D Zircaloy-4 elements to India. Recommends that license be issued
HOSBETH, L. V. State, Dept. of, Bureau of Science & Internal Control & Scientific Affairs 00/05/13 2pp
- 8006100482 Submits Executive Branch views re application by Pacific Pumping Inc. for license to export parts & components to India. Recommends that license be issued
HOSBETH, L. V. State, Dept. of, Bureau of Science & Internal Control & Scientific Affairs 00/05/13 2pp
- 8006100485 Responds to question re safety significance of pending export of Targum components if licensing action on pending applications continues to be withheld. Impact would be more adverse than any single export treated in isolation
BHAU, J. R. Office of International Programs, Director 00/05/08 3pp
- 9006100507 SECY-00-049
Requests review of Encl. Washington applications for license to export two power reactors to Taiwan
BHAU, J. R. Office of International Programs, Director 00/05/02 1p
- 9006100509 Transcript of 000516 discussion of SECY-00-230 in Washington, DC. Pg 1-30 Hearing session
* Commission 00/05/16 31pp
- 8006100517 SECY-00-219
Requests procedures for increased Commission involvement in major decisions of D.C. of Nuclear Reactor Regulation. Ofc of Nuclear Reactor Safety & Safeguards & IC Recommends meeting to discuss options set forth in paper
BICHAUT, L. Office of the General Counsel 00/04/29 4pp
- 8006100520 Discusses 791226 request by Chairman Abner for views on increased Commission involvement in significant regulatory actions. Proposal might lead to increased opportunities to use Encl. of supervision. Further restrictions
BHAU, J. R. Office of the Executive Legal Director 00/05/10 3pp
- 8006100530 Discusses 791226 memo from Chairman Abner re direct Commission involvement in licensing decisions. Commission can participate to greater degree in decisionmaking. Max benefit would arise if Commission participates in hearing process
BICHAUT, L. Office of Nuclear Reactor Safety & Safeguards 00/05/12 18pp
- 8006100542 Transcript of 000516 discussion of SECY-00-219 re Commission review procedures in Bethesda, MD. Pg 1-48 Afternoon session
* Commission 00/05/13 49pp
- 8006100549 Transcript of 000330 Affirmation Decision 00-04 in Washington, DC. Pg 1-2
* Commission 00/05/06 3pp
- 8006100550 SECY-00-182E
Recommends approval of Encl. revised draft order Encl. PA Bradford separate statements to be appended to order
BICHAUT, L. Office of the General Counsel 00/05/29 4pp
- 8006100558 Responds to 000328 Ltr to J. Abner re problems of evacuating large populations in short period of time. Program of operating emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant
BICHAUT, L. Office of Nuclear Reactor Regulation, Director 00/04/28 2pp
- 8006100569 Elabores on concerns expressed in 000102 Ltr re need for practical evacuation plans around nuclear power sites. Problems of evacuating large populations in short time have been understated. Requests use hearings on issues
BHAU, J. R. Affirmation Decision 00/03/24 2pp
- 8006100577 SECY-00-149
Recommends approval of outline of ACRS participation in rulemaking. Participation broken down into initiation of rulemaking, rule development, rulemaking hearings & effect of rulemaking on rulemaking
BICHAUT, L. Office of the General Counsel 00/03/31 4pp
- 8006100580 Add receipt of 000509 Ltr re ACRS participation in rulemaking re storage & disposal of radioactive waste. Comment period
FLEISCH, J. ACRS - Advisory Committee on Reactor Regulation 00/03/13 1p
- 8006100583 Proposes ACRS enter proceedings re storage & disposal of radioactive waste as commenter & adviser after statements & cross-examinations filed by parties
ACRCS/EC, J. Commission 00/03/09 1p
- 8006100584 Transcript of 000520 open Affirmation Decision 00-04 in Washington, DC. Pg 1-30 SECY-A-00-4A & SECY-00-304 Pg 1-3
* Commission 00/03/01 4pp
- 8006100586 SECY-00-202
Discusses role of NRC in waste confidence proceedings. Recommends issuance of proposed memorandum & order Draft memorandum & order Encl.
BICHAUT, L. Office of the General Counsel 00/04/24 4pp
- 8006100589 Responds to FOIA request for SECY-73-428 Forwards document W/2 Encl.
FLEISCH, J. H. Division of Rules and Records 00/05/16 1p
- 8006100592 Transcript of 000612 discussion & vote on affirmation item in Washington, DC. Pg 1-10 Draft orders & separate views of Commissioners Bradford and Encl.
* Commission 00/06/12 35pp
- 8006100596 SECY-00-271A
Forwards draft revision to TH action plan statement of policy reflecting changes made as result of SECY-00-271A Commission meeting, made to language & minor editorial changes
BICHAUT, L. Office of the General Counsel 00/04/11 31pp
- 8006100598 Add response to FOIA request for rule banning environ impact repts analysis of possible risks in event of major accidents at nuclear reactors. Forwards documents listed in App 4
FLEISCH, J. H. Division of Rules and Records 00/05/17 2pp
- 8006100599 Staff requested memo re 000616 open meeting in Washington, DC to discuss SECY-00-101, "Accident Considerations Under NRC". Commission requested that personnel conduct methods of screening plans in early, cost stage
BICHAUT, L. Office of the Secretary of the Commission 00/04/26 1p
- 8006100597 SECY-00-214
Requests Commission approval to publish advanced notice of proposed rulemaking on Tech Space New Tech Space Act. Congressional Ltr & preliminary value-impact statement Encl.
BICHAUT, L. Office of Nuclear Reactor Regulation, Director 00/04/20 35pp
- STATE PROG. STATE PROGRAM
- 8006100602 Reviews personal evaluation of U. M. training course 000506 Ltr
* Office of State Programs, Director 00/05/03 3pp
- 8006100604 Forwards "Preliminary Study on Disposal of Low Level Radioactive Generated in IL."
BHAU, J. R. Office of State Programs, Director 00/05/14 1p
- 8006100609 "Preliminary Study on Disposal of Low Level Radioactive Generated in IL."
* Illinois, State of 00/04/14 4pp
- 8006100612 Notification of 000700-02 meeting in Seattle, WA to discuss continuing of credit direct on technical meetings
BHAU, J. R. Office of State Programs, Director 00/05/14 1p
- 8006100624 Forwards economic data re generation of electric power, requested by State of MS Public Utility Commission 000509 Ltr.
BHAU, J. R. Office of State Programs, Director 00/05/16 2pp
- 8006100624 Forwards draft memo for review prior to 000602-04 meeting w/OT. Draft memo provides uniform guidance concerning emergency response program for handling transportation accidents involving radioactive waste
BICHAUT, L. Office of State Programs, Director 00/05/01 4pp
- 8006100626 Ltr to SECY
"Contribution to Emergency Response Planning Guidance Document," Draft for comment
BHAU, J. R. Health Laboratories 00/05/16 47pp

NONDOCKETED ITEMS

327

- 0004200177 Recommends that individuals & corresponding agreement states listed in encl receive copy of NRC's code & preliminary user guide for records w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200187 Forwards 000421 State of NM radiation protection regulations w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200192 Advises that review of draft Revision 2 to Reg Guide 4.1 is complete. Agrees that revision is necessary
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200194 Notifies that State of CO requests NRC assistance in evaluating significance of tritium contamination resulting from handling of foils by licensee info requested on controls as removable contamination on source metals
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200205 Discusses State of NM request for assistance in review of Kees & Hall's in situ projects. Documentation of NRC corrective actions re NV Minerals in situ project required by 000421
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200206 Forwards State of GA second quarterly report re transportation surveillance program Requests Comments
JANICE M. Office of State Programs, Director NRC-CA-70-362
00/04/09 2pp
- 0004200207 Forwards second quarterly progress report Jan-Mar 1980 re transportation surveillance program
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200208 Advises that TE Time, Inc. has agreed to cease distribution & release of tritium backfill watches until license has been amended
LORNA J. D. Office of State Programs, Director 00/04/09 1p
- 0004200209 Responds to 000226 1st requesting technical assistance in testing low level radioactive liquid wastes for structural integrity. Recommendations limiting risk assessment for tanks & rapid cleanup operation encl w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200210 Discusses NRC 000210 & 0001 1st re testing - C-250 sources from Isotope Products Lab. Ack receipt of 000229 1st reporting investigation being made by Los Angeles County Health Dept. Rept re C-250 sources encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200211 Forwards Washington Univ. report re testing C-250 sources received from Isotope Products Lab. Rept & source sent to Isotope Products Lab
JANICE M. Office of Inspection & Enforcement, Office of the Director 00/04/09 1p
- 0004200212 Comments on NRC paper re emergency preparedness at facilities licensed by NRC. Early state input into development of criteria for preparation of emergency plan is desirable
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200213 Requests Regule 3 report on investigation of licensee in Research, NM, mounting rejected military gun rights containing radioactive material in civilian handgun. State of TX Radiation Control Branch requests list of persons who received rights
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200214 Summary of Task Force on Emergency Planning for Transportation Accidents Involving Radioactive Materials. 000420-04 meeting in Washington, DC to provide attentive comments on draft sections written independently by Task Force members
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200215 Requests that Governor Miller consider appointing new individual to replace a Premier NRC/State liaison program was up to improve federal & state cooperation
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200216 Comments on State of NM Radiation Protection Regulation 3-400 requiring specific license for transportation of nuclear waste on highways. Any license issued by State of NM should not conflict w/Sections 73.37 & 73.39 of 10CFR73
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200217 Forwards list of all NRC radioactive material licenses issued to persons in Commonwealth of MA in response to 000220 request. List is current as of 000421 w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200218 Forwards "Interagency Task Force on Health Effects of Ionizing Radiation - Report of the Group on Science." In response to request w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200219 Discusses appointment of FL inspectors during 7/19/21-18 term of Scott Loomis, Inc. in St. Petersburg, FL. Noncompliance noted at sampling program is inadequate & no records of daily radiation level surveys
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200220 Advises CA Dept. of Health Services/Radiologic Health Section that CA company may be distributing impaired tritium gun rights w/o proper licensee. Requests assistance in determining whether company possesses radioactive materials
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200221 Ack receipt of 000211 assessment of State of CO law & regulations in conformance w/1978 USDOA testing of equivalent risk & preparation of written error analysis report as major problem event
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200222 Forwards TWA 000213 report re Gamma Industries 7/1/22 shipment of radioactive material to TVA. Health Effects/M. Requests results of any action taken by State of LA
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200223 Reports re Gamma Industries 7/1/22 shipment of radioactive material to TVA. Health Effects/M. Requests results of any action taken by State of LA
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200224 Requests re Gamma Industries 7/1/22 shipment of radioactive material to TVA. Health Effects/M. Requests results of any action taken by State of LA
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200225 Confirms discussion w/CA. Plans re review of state radiation control program for use of 000214-10. Review will include field evaluations of state legislation re 000214
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200226 Forwards summary of NRC inspection/enforcement activities re transportation of nuclear waste for Mar-Apr 1980 report
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200227 Forwards summary of inspection/enforcement activities re transportation of nuclear waste for Mar-Apr 1980 report
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200228 Responds to 000212 1st re request for technical assistance in testing low level radioactive liquid wastes for structural integrity. Recommendations limiting risk assessment for tanks & rapid cleanup operation encl w/o encl
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200229 Forwards additional NRC requirements resulting from investigations of TMI-2 that are required of utility WPCs before issuance of C-250 licenses & schedules will be available to NRC-0004-0004
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200230 Forwards Proposed Evaluation Panel report for EPP 88-000-004, "Safety Aspects of Industrial Radiography for State Regulatory Personnel." Recommendations that written clarification be requested of law license in competitive range
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p
- 0004200231 Forwards list of median staff salaries for Agreement States per request
NRC's G. M. Assistant Director for State Agreements Programs
00/04/09 1p

NONDOCKETED ITEMS

8004030580 Forwards annotated list of current licensing guides. Licensing guides & refs available to license review & loop guide for telephone info and
LUBENAU, J. O. Assistant Director for State Agreements Programs
05/04/83 1p

COPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8004030585 Notification of 800501 meeting w/GE to discuss fuel management design & related licensing proposed agenda and
LUBENAU, J. O. Operating Reactors Branch 2 05/05/79 3pp

8004030587 Summary of 800505 meeting w/EPRI to discuss considerations of significant transients, frequency of transients & loading frequencies of electrical portions of steam sys
Includes EPRI analysis, NRC comments & list of attendees
THOMAS, A. C. Service Issues Branch 05/05/80 25pp

8004030597 Forwards proprietary responses to 8004030580 RB & RB02 80-80-21080, "Mark II Dynamic Forcing Function
Info Req" - Response withdrawn (ref 10CFR2 790)
05/06/80, J. H. General Electric Co. RB 040-80 05/05/80 2pp

8004030598 Discusses 800417 meeting between representatives of Turbine Generator Corp. Integrating Test Facility & NRC re test facility
position on Category A units scheduled for 1980
STICKEL, W. L. Commonwealth Edison Co. 05/05/82 1p

8004030599 Forwards update to Round 2 question responses re NEDC/H030-21041, "Mark II Dynamic Forcing Function Info Req."
BUCHHEIM, J. H. General Electric Co. RB 040-80 05/05/80 75pp

8004030608 Address of forthcoming visit to Data Power Co. as 800410 re tests conducted by Southwest Research Inst. per methods stated in 800505 1p
HALL, R. E. Brookhaven National Laboratory. 05/05/82 1p

8004030610 Forwards request for add'l info re proposed 800401 Revision 4 to still project 800410-1075-10, "QA Program Description"
HARRIS, M. P. Seattle Inference Branch. 05/05/80 2pp

8004030622 Forwards responses to NRC 800524 1st re Benton Lst Number 2 transmitters info required to complete review of
Westinghouse 8004-74000 re: Proprietary info withheld (ref 10CFR2 790) AWD/awd
AWD/RENN, T. H. Westinghouse Electric Corp. RB-TM-2240 05/05/83 1pp

8004030627 Requests that 80-10P-1, Bulletin 3, "Bridge Control," be revised to meet and position statement re reactor retention requirements of 8001 RB02 2 9 suggests inclusion of flow chart that identifies each step of design process.
HARRIS, M. P. Seattle Inference Branch 05/05/84 2pp

8004030629 Discusses review of TM-2 Bulletin & Orders Test Facility report on Westinghouse plants Several recommendations will not be included in final version including accelerated RB02 review of conservation in LSCS calculations.
ROBLES, L. TM-2 Bulletin & Orders 79/12/02 3pp

8004030630 Nonproprietary version of memo discussing long-term effects of accident made by SAE RB02 1 licenses in response to RB Bulletin 79-095, "Nuclear Accident at TM-Supp."
Accurate assessment cannot yet be made.
LUBENAU, J. O. TM-2 Bulletin & Orders 189-79-508 05/05/83 2pp

8004030632 Refutes NRC of early completion of two planned reactor storage action items Control Records Ctr. at Bowers-Pa non-licensing limits with other regulations.
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/82 1p

8004030637 Discusses forthcoming generic safety evaluation for input to SAE Group re proposed operator action qualifications for early pump trip Draft evaluation should be available for final met review by 79/031
REESTHOF, J. R. TM-2 Bulletin & Orders 189-79-095, 79/09/27 1p

8004030638 Requests info re work draft request for add'l info required to complete evaluation of response for power operator action valve/safety valve activation & reactor trip frequency
CARRA, R. TM-2 Bulletin & Orders, 79/09/24 3pp.

8004030640 Forwards monthly report on licensing case review for NRC
Natic Engineering Branch
WUBENAU, J. O. Seattle Inference Branch Pacific Northwest Laboratory RB 040-80 05/05/80 3pp

8004030644 Accepts 8004-10705-3, Annex 3, "High Pressure Core Spray Sys. Power Supply Unit," qualification test results of high pressure core spray diesel generator for described generator
PABER, S. Light Water Reactors Branch 3 05/04/83 3pp

8004030648 Modification of 800420 1st meeting w/EPRI in Silver Spring. RB Requests suggested items for agenda by 800525
LUBENAU, J. O. Program Coordination Branch 05/05/80 2pp

8004030649 Summary of 800525 1st meeting w/EPRI in Bethesda-MD re joint reactor safety research programs discussed possibility of modifying LQFT facility to get better understanding of reactor parameters
LUBENAU, J. O. Program Coordination Branch 05/05/80 3pp

8004030650 Requests approval to 800525 1st re organizational changes to be incorporated in 800525 Nuclear Engineering & Operations Group effective 800401 & on Program Typical Regs No-20-1
CARRA, R. J. Northwest Utilities 04-3034 05/05/80 3pp

8004030651 "Organizational Relationship Between MURD Personnel Having Quality Related Functions"
Northwest Utilities 05/06/80 1p

8004030652 "Organizational Relationship Between MURD & NUPCC Personnel Having Quality Related Functions"
Northwest Utilities 05/06/80 1p

8004030653 Forwards NEDC-00222-P, "Mark II Improved Chugging Methodology," as part of Task 4.16 of Mark II containment Program Draft review requested kept withheld (ref 10CFR2 790)
BUCHHEIM, J. H. General Electric Co. RB 040-80 05/05/80 1p

8004030654 Forwards assessment of BAW-1544, "Integrated Control Sys. Reliability Analysis." Integrated control sys has relatively low failure rates however aspects of plant control sys should be investigated for improvement
HARRIS, M. P. Instrumentation & Control Systems Branch. 05/05/83 1p

8004030655 Topical report evaluation of 800-1304, "Integrated Control Sys. Reliability Analysis." Approves recommendations broader study should be performed
Instrumentation & Control Systems Branch 05/05/83 3pp

8004030656 Forwards solution to NRC benchmark Problem 1.325A & 4 for NEDC power spectrum analysis Description of NEDCAN sys & allow elements & post-processor COMPC and
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 20pp

8004030657 Advises that results of pretest prediction of RB02 test V 21 will be incorporated into test timing comparison updates
Test results NUPCC model used for determinations Topical report describing improvements will be submitted
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 2pp

8004030658 Forwards auxiliary feedwater sys revised Add'l Mark-Term Recommendation 2, reducing 70-h shutdown test for auxiliary feedwater test pump to 40-h Westinghouse & C-E licenses should be notified
HARRIS, M. P. TM-2 Bulletin & Orders 79/12/02 3pp

8004030659 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030660 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030661 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030662 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030663 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030664 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

8004030665 Forwards nonproprietary version of 8004-7926, "Westinghouse Technical Support Complex." Application for withholding Proprietary Info & Appendixes and Proprietary version withheld (ref 10CFR2 790)
HARRIS, M. P. Westinghouse Electric Corp. RB-TM-2240 05/05/83 13pp.

NONDOCKETED ITEMS

3

- 0006170666 Discusses insp plan & preparations re guide tube support pins from bus or more domestic Ultrasonic insp demonstrated to be viable insp technique on support pins
AMBERSON, T. H. Westinghouse Electric Corp. / PWR Systems Div
ND-176-2204 00/06/10 2pp
- 0006170748 Discusses fire resistance upgrade measures outlined in Westinghouse 80003231R re underground record storage facility. Research str is acceptable for silicon impurity or permanent storage of digitized/reproduced records
HARRIS, W. P. Quality Assurance Branch 00/06/02 2pp
- 0006170936 Discusses BSM allegation of possible conflict of interest in Instrumentation & Control Sys Branch review of 804-1544 info reveals that reviewers were not involved in past preparation while employed w/BSM
BATTOWFIELD, R. H. Electric, Instrumentation & Control Systems Branch 79/11/01 1p
- 0006170933 Discusses BSM allegation re possible conflict of interest during Instrumentation & Control Sys Branch review of 804-1544 status will be investigated by B. Battowfield. No further action required
CAPRA, R. A. TH-2 Bulletins & Orders 79/10/26 1p
- 0006170939 Notification of 79/07/18 & 17 meetings w/BSM & BSM members group in Bethesda, MD to discuss small break LOCA analysis
CAPRA, R. A. TH-2 Bulletins & Orders 79/07/17 1p
- 0006170942 Provides items for discussion during 79/07/19 meeting w/BSM members group - substitution for TH-2 issues
CAPRA, R. A. TH-2 Bulletins & Orders 79/07/16 2pp
- 0006170956 Forwards summary of status & potential problems for C-6 plants. Meeting will be held 79/10/24 to discuss issues
HARRIS, W. P. TH-2 Bulletins & Orders 79/10/22 1p
- 0006180033 Forwards updated status of activities re BSM/Westinghouse & BSM plants. Review of emergency procedure guidelines for small break LOCA must be completed by 79/10/31
HARRIS, W. P. TH-2 Bulletins & Orders 79/10/17 22pp
- 0006180033 Responds to request for NRC review of Typical Rept BSM/0-101, "Performance & Safety Features of Byron Jackson Primary Reactor Coolant Pump for BSM Rept acceptable for referencing in std or custom plant design applications
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 00/05/21 2pp
- 0006200103 Notification 8000862 meeting w/BSM & OPR, BSM will describe EPIPE computer program for pipe stress analysis. Discussion will cover program capabilities & access
WETTERBERG, R. H. Mechanical Engineering Branch 00/06/02 2pp
- 0006200549 Provides questions & comments for consideration in review of IR Bulletins 79-08C & 79-08C
ROSS, D. F. TH-2 Bulletins & Orders 00-79-08C 79/09/10 9pp
- 0006200606 Forwards updated status of activities for BSM operating plants re bulletin evaluations/compliance w/1979-1980 requirements of NRC 1979 orders & implementation of NRC-1007H items
CAPRA, R. A. TH-2 Bulletins & Orders 79/10/23 10pp
- 0006200642 Requests add info to substantiate appointment of C Dick as QA Manager for San Francisco Power Div in light of BD-70P-1 re qualification requirements for key QAP positions in quality groups
HARRIS, W. P. Quality Assurance Branch 00/06/03 1p
- 0006200648 Forwards proprietary info regarding re questions re XN-WF-312, "3N-3 Critical Power Correlation." Affidavit onl. Proprietary version withheld (ref 10CFR2 7901)
GABLE, D. F. Exton Nuclear Co., Inc. (subs of Exton Corp.) 00/06/00 1p
- 0006200650 Forwards proprietary & nonproprietary responses to NRC 800125 request re XN-WF-79-06(p), "Exton Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs." Proprietary to Exton Nuclear Co. (ref 10CFR2 7901)
GABLE, D. F. Exton Nuclear Co., Inc. (subs of Exton Corp.) 00/06/00 1p
- 0006200650 XN-WF-79-06(p)
Nonproprietary version of Amend I to XN-WF-79-06(p), "Exton Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs." Proprietary to Exton Nuclear Co., Inc. (subs of Exton Corp.) 00/04/10 14pp
- 0006200656 Notification of 800437 meeting w/SE in Bethesda, MD to discuss EPIPE code review
LAWRENCE, R. Reactor Systems Branch 00/06/10 2pp
- 0006200677 Notification of 800436 meeting w/SE in Bethesda, MD to discuss proposed code exit thermocouple sig
LAWRENCE, R. Instrumentation & Control Systems Branch 00/06/10 2pp
- 0006200685 Forwards NRC-204259, "Generic Info for Barrier Fuel Generation/Dual Licensing." & GE 800019 transmittal 1p
DOWLING, T. A. Operating Reactors Branch 00/06/10 1p
- 0006200684 Forwards NRC-204259, "Generic Info for Barrier Fuel Generation/Dual Licensing." Requests completion of NRC review by mid-Aug 1980. Summary of 800323 meeting w/BSM re barrier fuels program encl
GENERAL, R. E. General Electric Co. NEN-099-80 00/05/13 14pp
- 0006200688 NRC-204259
"Generic Info for Barrier Fuel Generation/Dual Licensing."
General Electric Co. NEN-099-80 00/05/13 27pp
- 0006200693 Advises that BSM LWF pretest calculations required by Section 2.1.9 of NRC-204259 are scheduled to begin 79/11/10
CAPRA, R. A. TH-2 Bulletins & Orders 79/10/17 2pp
- 0006200693 Advises that no plants currently reference OEMFO-177-P, "CESM-1 - Computer Code for Transient Thermal Margin Analysis of Reactor Core," in support of CL Requests req'd by withdrawal from NRC review & proprietary claims returned
SCHREIBER, A. E. E-6 Fuel Systems, L-6-60-024 00/06/22 1p
- 0006200693 Responds to 800323 31R re MOE-20394-P, "BWR/4 & BWR/6 Fuel Design." Proposed changes can be included in approved version of both proprietary & nonproprietary repts
MILLER, J. H. Standardization & Special Projects Branch 00/06/10 1p
- 0006200694 Ack receipt of NRC 800323 31R indicating contents of proprietary info in Typical Rept BSM-801-P. Requests prior notice of NRC intent to supply consultants w/own info on transmittal info to other govt agencies
HARRIS, W. P. US Chemical Co. 00/06/28 1p
- HARTE, POT. NUCLEAR WASTE MANAGEMENT
***** THIS DOCUMENT CONTAINS INFORMATION OF A CONFIDENTIAL NATURE *****
- 0006200695 Forwards "Geotechnical Design Data, Proposed Tailings Disposal Facility." Expansion, Open Mining Co. (Perd. MA) & drawing for assessment according to state request for tech assistance
RENN, D. W. Office of State Programs, Director 10002 00/06/28 2pp
- 0006200696 "Geotechnical Design Data, Proposed Tailings Disposal Facility." Expansion, Open Mining Co. (Perd. MA) & Solid Associates. 10002 79/11/02 81pp
- 0006200697 "Tailings Disposal Project Contract 1, Excavation Sitepile Location & Design."
* NRC Comp. 10002 79/11/03 1p
- 0006200698 "Tailings Disposal Project Contract 2, Liner Installation, Plan & Section."
* NRC Comp. 10002 79/11/04 1p
- 0006200698 Notification that U Recovery Licensing Branch has completed review of proposed Marston-Treat Associates U re upgrade project. Applicant has postponed project indefinitely
MILLER, J. H. Uranium Recovery Licensing Branch 00/06/07 1p
- 0006200699 Forwards responses to questions & comments re Marston Project tailings disposal; par discussion at 000417 meeting. One overruled map encl
THOMPSON, R. A. Copies Misses Corp. ND-80 37-452 00/05/12 45pp
- 0006200699 Notification of completion of U Recovery Licensing Branch review of Center Corp application for State of GE radioactive waste license to operate Schwarzschilder variator
MILLER, J. H. Uranium Recovery Licensing Branch 00/06/12 2pp
- 0006200700 Notification of completion of U Recovery Licensing Branch review of project in response to March request State 800339 1R transferred tailings licensing authority to NRC
MILLER, J. H. Uranium Recovery Licensing Branch 00/06/08 1p

NONDOCKETED ITEMS

- 0004000405 Notices of completion of evaluation of Site B tailings and debris from 8003017 and 8003019 for indication that site is not considered viable for tailings disposal.
BETHLEHEM J. Uranium Recovery Licensing Branch 00/03/20 1p
- 0004000410 Responds to 8004001 for to Union Carbide re tailing at Union Carbide Ranch Rock Facility U mill operations in NE are licensed by State of HI.
HARRIS M. Office of State Planning, Director 00/05/14 1p
- 0004000417 Responds to 8004001 for proposed procedures for contaminated waste at Canyon City U mill tailings impoundment. Irregular shaped piles should not be placed at site w/o procedures so liner is not penetrated.
MOLSON J. Colorado State Univ 14638 00/04/21 1p
- 0004000419 Forwards summary of UAC report based on Hansen Project geology & seepage sources. Details indicate seepage will be well below current state.
THERPESSE P. Cyprus Mines Corp 14634 00/04/24 3pp
- 0004000420 Forwards notes of 0004001 oral presentation by applicants & intervenors of administrative appeal re Hansen project. Record is being reviewed for expedited decision. May decision will follow.
PETERSON R. Agriculture Dept. of Forest Service 14637 00/04/19 1p
- 0004000426 Forwards proposed need to criteria for cleanup of Site 0004001. Union Carbide Corp has not been able to clean up 2-230 from average in nine months high levels could be avoided by averaging greater areas.
BURL T. E. New Mexico, State of 14640 00/04/23 4pp
- 0004000427 Submits trip report re 8004001 imp of re-entrance facility site & 8004002 meeting on documents of amended radioactive waste license application.
BETHLEHEM J. Uranium Recovery Licensing Branch 00/05/07 4pp
- 0004000433 Forwards "Geohydrologic Investigation of Tailings Disposal, Rhade Ranch Property, Huerfano County, TX." Report prepared to answer questions raised by NRC re hydrologic aspects of proposed tailings to be placed at site.
DAVID D. R. Amadaco Co. : Amadaco Copper Co. Div 14636 00/04/24 1p
- 0004000440 Advice of application for waiver of requirement to transfer lead ownership to federal govt at proposed Rhade Ranch U mining site. Attempts to purchase surface from current have been unsuccessful. Quanta survey data sent.
DAVID D. R. Amadaco Co. : Amadaco Copper Co. Div 14636 00/04/23 2pp
- 0004000447 "Geohydrologic Investigation of Tailings Disposal, Rhade Ranch Property, Huerfano County, TX." Overview drawings sent.
E. L. Reed & Associates, Inc 14638 00/04/30 103pp
- 0004000450 Forwards summary of JF Hertzbein 8003017 visit to Custer Corp. Submittal under Re-Entrance Project Corp to provide recommendations on technical aspects of amended license application & evaluation & provide technical assistance complete.
SEARANG R. A. Uranium Recovery Licensing Branch 00/05/12 1p
- 0004000459 Responds to F BUI 8004001 re requesting review of proposed revisions to cleanup criteria established w/ Custer Rock dam failure due to lack of available resources. Requested review & technical assistance cannot be provided.
SEARANG R. A. Uranium Recovery Licensing Branch 00/05/16 1p
- 0004000463 Responds to 8004001 re requesting NRC review of Union Carbide proposal to operate Pond 5 at Uranium site after completion of Phase II-A term Permit. Results & conclusion of dam safety review completed in EER transmitted to 8003019.
SEARANG R. A. Uranium Recovery Licensing Branch 00/05/19 1p
- 0004000469 Requests that radiological impact info re Union Carbide Corp. Uranium CD will be made available to public. Description of extent of info & estimate of schedule & format for release also requested.
HALL J. J. Colorado, State of 14636 00/05/07 1p
- 0004000477 Confirms suggestions that 8004001-10 conference be held w/ CD Dept of Health & Custer Corp in Brown. CD re amend of radioactive waste license application. Schedule will be open pending further advice.
HORNSTEIN E. J. 10946 00/03/26 1p
- 0004000484 Documents application for license to operate re buying skid at same time site is prepared for mill.
HALL J. J. Colorado, State of 14637 00/05/10 3pp
- 0004000484 Forwards "Groundwater Discharge Plan, Dec 1979" - 1004001 & Gulf Oil Corp. : Gulf Mineral Resources Co. 14636 00/05/11 1p
- 0004000489 "Groundwater Discharge Plan, Dec 1979" - 1004001 & Gulf Oil Corp. : Gulf Mineral Resources Co. 14636 00/05/21 203pp
- 0004000492 Forwards "Hansen Project Groundwater Investigation Proposed Tailings Disposal Area." In response to Action Items 2 & 3 discussed at 8004017 meeting.
BURNHAM D. W. A. Walker & Associates, Inc 14635 00/05/29 1p
- 0004000493 "Hansen Project Groundwater Investigation Proposed Tailings Disposal Area." - 1004001 & Walker & Associates, Inc 14635 00/05/31 37pp
- 0004000494 Forwards responses to questions & comments discussed at 800417 meeting. Some characterization of individual problems. For three cell section & evaluation of use of underdrains. Detailed drawings sent.
THERPESSE P. A. Cyprus Mines Corp 14634 00/05/29 36pp
- 0004000499 Submits conclusions re review of Richmond Corp application for use of Lyons, KS salt mine for retrievable storage of low level radioactive by product. On-site assessment of low level radioactive waste. High level waste. Licensing Branch 00/05/30 4pp
- 0004000501 "Hazard & Assessment, Lyons, KS Low Level Waste Facility, Case Study." - 1004001 & Lyons, KS 14636 00/05/31 47pp
- 0004000503 Submits trip report of 8003019-20 visit to Topeka, KS re NRC review of Richmond Corp application for use of Lyons, KS salt mine for retrievable storage of low level radioactive waste. Application deficient. NRC will provide review assessment.
BRENNER D. E. Low Level Waste Licensing Branch 00/05/28 4pp
- 0004000504 Advice that Custer Corp proposal to dispose of contaminated trash in Canyon City U mill tailings impoundment. NRC has no objection but has no adverse impact on impoundment. CD State Dept of Health notified.
BETHLEHEM J. Uranium Recovery Licensing Branch 00/05/30 1p
- 0004000506 Informs of inability to return preliminary draft license application due to preparation of radiological assessment & tailings imp evaluation. NRC review. Improvement still appears to be in compliance w/ requirements.
MILLER J. J. Uranium Recovery Licensing Branch 00/05/23 1p
- 0004000507 Responds to CD Dept of Health 800317 & 0413 ltr re assistance for Cyprus Mines Corp Hansen project & Pioneer Uranium. Sam. Request project. Certificate scope of assistance.
MILLER J. J. Uranium Recovery Licensing Branch 00/05/30 2pp
- 0004000508 Informs that OF of Waste Mgt has withdrawn from formal involvement in Huerfano Mining Co. Pit Project due to unavailability of necessary manpower.
BETHLEHEM J. Uranium Recovery Licensing Branch 00/06/09 1p
- 0004000509 Discusses 8003019-20 site visit w/ NRC representatives in Portland, OR & Huerfano, MO re NRC technical assistance for review of Pioneer Amer. proposed U mill & proposed alternative sites.
LIMBANK J. J. Uranium Recovery Licensing Branch 00/05/27 4pp
- 0004000510 REPORT AND REPORT LOGSHEET
- 0004000520 Requests change to export license application for Zircaloy-4 fuel channels. Quantity should read "150 fuel channels" instead of "150" - Corrected figure appears in cover slip.
BETHLEHEM J. J. Carpenter Technology Corp 00/05/19 1p
- 0004000521 License for OSRAD, Inc. to export 1 kg thorium oxide, containing 0.07 kg thorium, to Italy.
PETERSON R. Assistant Director for Export/Import & International Safeguards 00/05/23 2pp
- 0004000526 Executive Branch position re Washington applications for license to export 954 micrograms CR-232 to Spain. License should be granted.
SCORNO L. V. Bureau, Dept of: Bureau of Ocean & Internal Environment & Scientific Affairs 00/05/16 2pp

NONDOCKETED ITEMS

33

0000430054 Forwards application for license to export 7 A47 kg U, containing 0.070 kg U-235 & 100.386 kg U, containing 36.31 kg U-235 to France H/A latter application
NATREN, V. Transnuclear, Inc. 00/05/14 1p

--0000430063 Application by Transnuclear, Inc. for license to export 7 A47 kg U, containing 0.070 kg U-235 & 100.386 kg U, containing 36.31 kg U-235 to France
NATREN, V. Transnuclear, Inc. 00/11/03 TNP 3 00/03/14 1p

0000430061 Executive Branch position re Rockwell Intl application for license to export speciality chemicals to India
License should not be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/16 2pp

0000430070 Application by Rockwell Intl Corp. for license to export Rockwell-Rohrer glass stop valve to India
OFASIS, M. V. Rockwell International Corp. 1822 FE 00/08/14 2pp

0000430078 License for Transnuclear, Inc. to export 20.000 kg U, containing 10.707 kg U-235, to The Netherlands
SMA, J. H. Assistant Director for Export/Import & International Safeguards 00/05/12 2pp

0000430084 License for Transnuclear, Inc. to export 100.102 kg U, containing 100.399 kg U-235, to Belgium
SMA, J. H. Assistant Director for Export/Import & International Safeguards 00/05/12 2pp

0000430116 Executive Branch position re Rockwell Intl Corp. application for license to export six complete ultrasonic insp. sys. to Argentine Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/20 2pp

0000430157 Application by Integrated Phenomena, Inc. for license to export two solid fuel cells chambers from Great Britain
OTRDA, R. Interphase Corp. 00/04/20 2pp

0000430220 Ltr. of assurance re Transnuclear, Inc. application to export 452.7 kg U-235, contained in 17.985 kg U & 0.036 kg U-235, contained in 1 kg U, to The Netherlands
G3PPEL, H. European Committee, Commission of 00/03/16 1p

0000430226 Ltr. of assurance re Transnuclear, Inc. application to export 270.34 kg U-235, contained in 10.449 kg U & 0.035 kg U-235, contained in 1 kg U, to Switzerland
G3PPEL, H. European Committee, Commission of 00/03/16 1p

0000430267 Application to amend License 88-114, changing ultimate consignee address of Korea Electric Co. South Korea
REDI, J. P. Westinghouse Electric Corp., PWR Systems Div 00/03/14 1p

0000430318 Advice that vendor correspondence & application to export two pump reactors to Russian does constitute utilization
Facility
NORRIS, L. V. Office of International Programs, Director 00/03/21 1p

0000430344 Forwards and use statement for GA Co. 770011 application for license to export research reactor fuels to Iran
NORRIS, L. V. General Atomic Co. (subs. of Gulf Oil Co.) 77/02/02 2pp

--0000430358 Forwards Form INS-2, Justification Analysis, in support of 770011 application for license to export fuel elements to Iran
Inspection of new fuel will permit continued operation of reactor for research purposes
NORRIS, L. V. General Atomic Co. (subs. of Gulf Oil Co.) 77/02/11 1pp

--0000430364 Application by GA Co. for license to export 24.4 kg U-235, contained in 26.2 kg U to Iran INS-2 draft ltr to GA Co. sent
NORRIS, L. V. General Atomic Co. (subs. of Gulf Oil Co.) 77/02/11 2pp

0000430485 Executive Branch position re GE application for license to export sodium detectors to Finland Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/19 2pp

0000430532 Executive Branch position re Colson Intl application for license to export 192.320 kg U, contained in U oxide, to Federal Republic of Germany License should be granted Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of 00/05/09 3pp

0000430074 Executive Branch position re Pacific Pump, Inc. application for license to export components & parts, especially designed for Temper Pack, to India License should be granted
NORRIS, L. V. State, Dept. of 00/05/13 2pp

0000430082 Executive Branch position re Ryan-Johnson Pump Div application for license to export various components & parts for Temper plants to India License should be granted
NORRIS, L. V. State, Dept. of 00/05/13 2pp

0000430087 Executive Branch position re Langenstar Technology Corp. application for license to export 160 Zircaloy-4 fuel elements to India License should be granted
NORRIS, L. V. State, Dept. of 00/05/13 2pp

0000430091 Executive Branch position re Westinghouse application for license to export 3,917 kg U-235, contained in 75,173 kg U, to Spain Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/21 2pp

0000430093 Executive Branch position re Westinghouse application for license to export 3,450 kg U-235, contained in 75,173 kg U, to Spain Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/21 2pp

0000430095 Forwards request for Amend 1 to export license consisting of Radiochemicals 000006 & 12 ltr. re NORM statements concerning British order
NOLAN, R. Radiochemical Co., Inc. 00/05/20 2pp

0000430098 Application by SE for Amend 1 to export license, extending expiration date to 01/07/01
NORRIS, L. V. General Electric Co. 00/05/12 1p

0000430099 Executive Branch position re Westinghouse application for amend to license increasing amount of nuclear fuel
contained in 99 kg U-235, contained in 2,774 kg U, for export to Spain Ltr. of assurance and license should be granted
NORRIS, L. V. State, Dept. of, Bureau of Ocean & Internal Environ & Scientific Affairs 00/05/21 2pp

0000430112 License for Edcon Intl Co. to export 319,242 kg natural U, contained in 160,644 kg U-308, to West Germany
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 00/05/20 2pp

0000430116 License for Westinghouse to export 2,674 kg U-235, contained in 26,706 kg U, to Yugoslavia
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 00/05/20 2pp

0000430116 License for Westinghouse to export 2,674 kg U-235, contained in 26,706 kg U, to Yugoslavia
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 00/05/20 2pp

0000430120 Notification that License 1000-1657 may be issued since no not changed circumstances from issuance of License 1000-1604
NORRIS, L. V. Office of International Programs, Director 00/03/05 1p

0000430121 License for Metal Bellows Corp. to export air cooler hoses, oil cooler hoses & thermal barrier hoses to Belgium
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430141 License for Carpass Technology Corp. to export 140 Zircaloy-4 fuel elements to West Germany
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430141 License for Carpass Technology Corp. to export 140 Zircaloy-4 fuel elements to West Germany
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430141 License for Carpass Technology Corp. to export 140 Zircaloy-4 fuel elements to West Germany
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430159 Amend 1 to import license for Westinghouse, changing ultimate consignee address
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430161 Amend 1 to export license for GA Co. adding one fission chamber w/ 04 kg U, contained in 5.42 kg U-235, to Pakistan
Ins. use statement and
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430173 Application by Westinghouse for license to export fission chamber w/ 04 kg U, contained in 5.42 kg U-235, to Pakistan
Ins. use statement and
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

0000430174 License for Westinghouse to export 432 micrograms Cf-250, contained in one sealed source, to Spain
PETERSEN, H. Assistant Director for Export/Import & International Safeguards 1000-1657 00/05/20 1p

- 0004090902 License for Westinghouse to export 432 microgram Cf-252, contained in 10,300 kg U to Bulgaria
PETERSON, H. Assistant Director for Export/Import & International Safeguards 100-0287 00/05/28 App
- 0004090904 License for Transnuclear, Inc. to export 370 9795 kg U-235, contained in 10,300 kg U to Switzerland
PETERSON, H. Assistant Director for Export/Import & International Safeguards 000324 00-09/21 00/05/28 App
- 0004090909 License for Transnuclear, Inc. to export 632 734 kg U-235, contained in 17,091 kg U to Switzerland
PETERSON, H. Assistant Director for Export/Import & International Safeguards 000323 00-09/11 00/05/28 App
- 0004090904 Executive Branch position re Westinghouse application for export to license-increasing amount of nuclear fuel authorized by 09 kg U-235, contained in 2,776 kg U, for export to India Ltr of assurance not issued
WRIGHT, E. L. State Dept. of Bureau of Ocean & Internal Security & Scientific Affairs 00/05/21 App
- 0004090904 Application by GE for license to export 33 U oxide fuel rod segments to Canada
WRIGHT, E. L. General Electric Co 00000006 00/05/23 App
- 0004090917 Advises that export license XRM-1676 may be issued since no oral changes have been made since issuance of XRM-1333
WRIGHT, E. L. Office of International Programs, Director 00/05/21 App
- 0004090928 Advises that export license XRM-1629 may be issued since no oral changes have been made since issuance of XRM-1624
WRIGHT, E. L. Office of International Programs, Director 00/05/21 App
- 0004090928 Expresses disappointment re delay in issuing license for export of nuclear components to India
WRIGHT, E. L. Reuter-Shoemaker, Inc. 00/05/23 App
- 0004100437 Advises that no oral changes to circumstances associated w/ license XRM-1636 from those existing at time of issuance of XRM-1636 License may be issued
WRIGHT, E. L. Office of International Programs, Director 00/05/21 App
- 0004100578 Executive Branch position re Metal Bubbles Corp application for license to export metal bubbles & assemblies to Spain
License should be granted
WRIGHT, E. L. State Dept. of Bureau of Ocean & Internal Security & Scientific Affairs 00/05/23 App
- 0004100611 Forwarded addendum to application for license to export 540 Tircally-4 fuel channels to West Germany
WRIGHT, E. L. Carpenter Technology Corp 00/05/12 App
- 0004100611 Application by Carpenter Technology Corp for addendum to license to export 540 Tircally-4 fuel channels to West Germany
Carpenter Technology Corp 00/05/12 App
- 0004100615 Discusses request for amend to XRM-1343 Favorable response to amend expected due to approval by President Carter of fuel sale to Taiwan reactor Amend request will be resubmitted due to June 1980 expiration
REUTER-SHOEMER, A. Reuter-Shoemaker, Inc. 00/05/12 App
- 0004100620 Ltr of assurance re GE 000130 application for license to export replacement parts to Finland
Finished 00/05/16 App
- 0004100624 Advises that circumstances associated w/ license XRM-1676 are same as those existing at time of issuance of XRM-1599
License may be issued
WRIGHT, E. L. Office of International Programs, Director 00/05/21 App
- 0004100621 Advises that circumstances associated w/ license XRM-1636 are same as those existing at time of issuance of XRM-1636 License may be issued
WRIGHT, E. L. Office of International Programs, Director 00/05/21 App
- 0004100649 Ltr of assurance re Japan Atomic Power Co application for license to export 1,000 kg U-235, contained in 30,700 kg U, to Japan
HIYASHIYANAGI, M. Japan 00/05/14 App
- 0004100656 Requests amend of license to export Taiwan Units 5 & 6 to Taiwan, 4474g U-235, 7 & 8
HEDGECOCK, J. Westinghouse Electric Corp 100-0321 00/04/23 App
- 0004100656 Requests license to export Taiwan Units 5 & 6 to Taiwan
HEDGECOCK, J. Westinghouse Electric Corp 100-0321 76/01/07 App
- 0004100673 Requests amend of license to export components to Philippines, adding flask chamber
NORMAN, W. M. General Atomic Co (tube of Gulf Oil Co) 696-1577 00/05/12 App
- 0004100684 DECY-02-238
Farwest Executive Branch views on proposed export of fuel & components to India & recommends preparation of order & report for President noting that applicable export criteria have not been met
SHEA, J. R. Office of International Programs, Director 00/05/21 App
- 0004100684 Application by Effroy Intl Co to export 487.2 kg U-235 to India Govt of India 760911 Ltr to DOE email
Effroy International Co 70/05/20 App
- 0004100686 Confirms 000311 action re expedited issuance of license to export traveling in-core probe to India No spare probe available for scheduled replacement at Tarapur Atomic Power Station Unit 1
MILBORN, E. D. General Electric Co 00/01/11 App
- 0004100686 Application by Methuan Gas Products for license to export one 6 in 3 cylinder containing 500 liters chemically pure deuterium
WISSE, L. Methuan Gas Products 100-04512 00/05/21 App
- 0004100697 Submits application for license to export 1,100 lb depleted U for use as ablator in medical cancer therapy equipment to Canada
Nuclear Metals, Inc 1-201-7 00/05/27 App
- 0004100698 Forwarded license application to export 103,250 kg U, containing 90.34 kg U-235, to West Germany
TRANSCNUCLEAR, INC. 00/05/14 App
- 0004100698 Application by Transnuclear, Inc. for license to export 103,250 kg U, containing 90.34 kg U-235, to West Germany Ltr of assurance not issued
TRANSCNUCLEAR, INC. 00-118/01 NUK32 00/05/14 App
- 0004100698 DECY-02-238
Recommends issuance of license to Reuter-Shoemaker, Inc. to export 300 lbs of nuclear fuel to Venezuela License request forwarded for Commission review because proposed export is destined for country w/o previous authorization
SHEA, J. R. Office of International Programs, Director 00/05/07 App
- 0004100698 Submits Executive Branch views re application by Reuter-Shoemaker, Inc. for license to export 300 lbs of nuclear fuel to Venezuela License request forwarded for Commission review because proposed export is destined for country w/o previous authorization
SHEA, J. R. Office of International Programs, Director 00/05/16 App
- 0004100698 Withdraws application for export license
HEDGECOCK, J. Westinghouse Electric Corp 100-0323 00/05/23 App
- 0004100698 Forwarded license application to export slightly enriched U dioxide powder, containing 100 lbs fuel pellets to Brazil
HEDGECOCK, J. Westinghouse Electric Corp 100-0323 00/05/13 App
- 0004100698 Application by Westinghouse for license to export slightly enriched U dioxide powder-compressed fuel pellets to Brazil
HEDGECOCK, J. Westinghouse Electric Corp 100-0323 00/05/13 App
- 0004100698 Requests cancellation of 000325 application for license to export 800 kg to Canada
JOHNSON, M. R. Eberline Instrument Corp 00-917752 00/05/23 App
- 0004100698 Withdraws application for license to export 85 research reactor components to India
REUTER-SHOEMER, A. Reuter-Shoemaker, Inc. 00/05/21 App
- 0004100698 Forwarded license application to export 30,400 kg centrifuges containing 100 lbs of U-235
HEDGECOCK, J. Westinghouse Electric Corp 100-0323 00/05/14 App

NONDOCKETED ITEMS

339

--8006102430 Application by Westinghouse for license to export 38,400 kg
contaminated scrap polychlorinated biphenyl waste to Sweden
HERSCHEL M Westinghouse Electric Corp 508-0292 06/05/13 12

000612046B 8857-80-0202
 Recommends that Commission consolidate Applications
 XCOM-0375, XCOM-0381 & XCOM-0093 w/applications listed in
 8857-80-0336 for review purposes Also recommends that
 Commission note receipt of SE request to amend XCOM-0240
 SHEA, J M Office of International Programs, Director 80/03/19
 3m

--806420-473 Submit Executive Branch view re application by Byron Jackson Pump Div for license to export components & parts to India Recommends that license be issued
806420-473 U.S. State Dept. of Bureau of Ocean & International Affairs & Scientific Affairs 80/05/82 Rye

--0000020477 Submits Executive Branch views re application by Carpenter Technology Corp. for license to export L&D Percutaneous Catheterization System to India Recommends that license be issued
H000020477 Submits Dept of Commerce of Oceanic & Interharkl Environ
A Scientific Address 00/05/12 Gsa

--0001800462 Substantive Executive Branch views re application by Pacific
Manga, Inc for license to export parts & components to India
Recommended that license be issued
N056H2D:L W Gbate, Dept. of, Bureau of Ocean & International Environ
& Scientific Affairs. 00005/13_3oa

--900420403 Responds to question re safety significance of pending
export of Targem components if licensing action on pending
applications continues to be withheld. Impact would be more
adverse than any single export treated in isolation
Bdla, J R Office of International Programs, Director 80/05/08
One

NO5A0204047 Requests extension of export license from NO0730 to NO0201
Possibility exists that order for Union Electric will not be
completed by NO0730 due to 2-3 month delivery backlog at
primary cable supplier, Teleflex
ELECTROUT, A. Neuner-Neubach, Inc NO/05/22 1a

MO00120497 Forwards connected and use statement for 000023 license application Requests that quantities of Matl on license be adjusted to read 21,044.7 kg containing 704.977 kg U-235 HX000, W Transcalance, Inc 05/05/00 Doc

--00061200600 Forwards application for license to export 21.945 kg U containing 703.05 kg U-235 to Switzerland
HATRON, V Transvaal; Inc 86/03/23. 1p.

--0006120002 Application by Transnuclear, Inc for license to export
21.044 7 kg U-contains 704 977 kg U-235 to Switzerland
* Transnuclear, Inc 802 301 80-126 80/03/23 Das.

0006102900 Ltr of assurance re Mitsubishi America Corp application for
license to export 140 lbs U-235 contained in 5,450 kg U to
Japan.
HIYABAYASHI, M Japan. 85/03/14 In.

000412080Y Executive Branch position re Transnuclear. See application
for license to export 1,234 kg U-235, contained in 30,746
kg U & 129,324 kg natural U to West Germany Ltr of assurance
encl
NORH0203, U. S. State Dept. at. 80/016/02 See.

00A6C0000 Submits application to amend license, increasing quantity of salt per export to 4,192 kg (4-235), contained in 100-012 kg U.S. & extending expiration date to 8/1/2001.
SALTSYSTEM, C S. Huntsville Blackstone Corp. 05/05/99 iz

0001000006 Discovers application by Nuclear Metals, Inc for license to export MOO by shipped w/ to Canada, Heli will be used for non-nuclear application license issued w/o normal 10-day waiting period
PETERSON, R.R. Assistant Director for Export/Import & International Safeguards. 80/05/28 1p.

--8004300280 License for Nuclear Metals, Inc to export 800 kg depleted U
as solid metallic plates to Canada.
PETERSON, R. Assistant Director for Export/Import & International
Safeguards. 80/05/28 Dag

#00430000 Forwards application for license to export up to 20,000 lb per gr depleted U metal castings in discrete pieces up to 2 ft in dimension and individual piece weights up to 1,000 lb. for 3-yr period to United Kingdom Requests quick response
OMER, D A Nuclear Metals, Inc. 80/08/21 la

--8056130032 Application by Nucor Metals, Inc. for license to export up to 20,000 lb per yr depleted U metal savings in discrete pieces up to 2 ft max dimension & individual piece weights up to 1,000 lb, for 3-yr period, to United Kingdom
OILRNM.A.R. Nucor Metals, Inc. 889/00/008 1x

0056120041 Request approval to re-report 3.3 mg Cf-252 source to
Democratic Republic of Germany-In response to license
condition
MAGNUS, D. Edlow International Co. 05/05/97 is

000100048 Forwards ltr from Taledyne Heli Chang Albany requesting
cancellation of application 80CM-0109 re export Circaloy
tube shells to Argentina.
PETERSON, M R Assistant Director for Export/Import & International
Relations 80-0109/20. 1a

8006120049 Requests Executive Branch position re Westinghouse
application for license to export 3 fixed channel 66
Pakatan W/e encl 800925 Application
PETERSON H R Assistant Director for Export/Import & International
Affairs 85/05/30 in

NOGA130885 Executive Branch position re Taledgas isotopes application
for amendment to export license extending expiration date Per
2 yrs & limiting amount of tritium gas to 2,600 Ci.
License should be amended
NOGA130885 L. V. Shaha, Dept of 80/09/12 2pg

800A130235 Ltr of assurance re Transmedios, Inc application to export
370 94 kg U-235 contained in 80.449 kg U & O 338 kg U-235,
contained in 1 kg U to Switzerland.
MILLER, R E Switzerland 408 313 556 80/08/06 in

SECRET/NOFORN Informs that Commission approved issuance of license to
export law enriched U to Yugoslavia
CHILE-S J. Office of the Secretary of the Commission 80/04/00

800616173 Forwards Radchem Chemical Co 800820 14r transmitting addl info re amod request to Licensee XE-1012 to export tritium to Switzerland M/A end
PETERSON, M.R. Assistant Director for Export/Import & International

0005160178 Notifies that Westinghouse withdrew export license application on 000000
PETERSON M R Assistant Director for Export/Import & International
Reference 00000000 10

SC0401008 Forwards Executive Branch responses re Five export license applications Per Spain requesting Committee's action. Requests expeditious review. W/o end

SWA:J R Office of International Programs, Director. 80/86/82.
1a

800462199 Informs that Esso/line Instrument Corp withdrew expert
license application on 8/20/89
PETERSON, M R Assistant Director For Export/Import & International
Relations 86/03/20. 1a

000166257 DEET-00-263
Request review of encl Meetinghouse applications for
license to export two power reactors to Taiwan
DENA, J R Office of International Programs, Director, 00A00/2
12

5036170095 Executive Branch position re Westinghouse application for
amend to license, increasing amount of authorized nuclear
fuel by 625 kg U-235, contained in 17,650 kg U. for export to
Spain. License should be granted.
HODENIG, J. W. State Dept. of Bureau of Grants & Internatl. Services

0004170410 Executive Branch position re DOE application for license &
export 7.9 kg U-235 contained in 245 kg U to Canada Ltr of
assurance encl. License should be granted
NSSENDO, L.V. State, Sect. of, Bureau of Customs & Internal Revenue.

EOSS170125 Executive Branch position re Nissaho-Tsui American Corp application for license to export 145,485 kg U-235, contained in 7,087.75 kg U-6 Japan Ltr of Assurance and License should be granted

RECEIVED: 11/10/2013 10:05:20 AM

- 0004170229 Forwards RUC. ltr requesting Amend to License 8989-1437 to increase quantities to be exported. Amend request should be considered. W/02010 application M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170230 Executive Branch position re Washington application for license to export 8989 to Korea. License should be limited to 10 yrs & expiration date should coincide w/02010-0204 agreement for cooperation
HELMUTH, C. F. State Dept. of Bureau of Ocean & Petroleum Affairs & Scientific Affairs 00/05/92 1p
- 0004170231 License for Metal Refining Corp. to export flexible metal hose assemblies specially designed for nuclear reactors to Spain
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170232 Forwards 890502 ltr from Nuclear-Metals requesting cancellation of Export License Application 8989-1302 M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170247 License for Nuclear Metals, Inc. to export 20,300 kg depleted U as metal castings, to United Kingdom
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170248 Forwards for review pending license application & proposed license for export of 20,300 kg depleted U to United Kingdom over 2-yr period. Application no longer requires Commissioner review M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170273 Requests Executive Branch position re Nuclear-Metals application for amend to license to extend expiration date to 8/1/93
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/06/92 1p
- 0004170283 Forwards application for license to export 7,587.75 kg U enriched to 1920 to Japan. Executive Branch position & proposed license no longer require Commissioner review M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170284 Forwards application by Nuclear Metals, Inc. to renew license to export 85,000 lbs depleted U to Canada
00088 U Nuclear Metals, Inc 00/05/92 1p
- 0004170426 Application by Nuclear Metals, Inc. to renew license to export 85,000 lbs depleted U to Canada
Nuclear Metals, Inc 00/05/92 1p
- 0004170233 Requests Amends D & E to License 8909-0222 & XCHN-0274, respectively, increasing values & changing expiration dates to 01/1/93 & 01/6/93, respectively
W/02010 M. R. H. H. Inc 00/05/92 1p
- 0004170245 Forwards application for license for minor nuclear export requests existence in securing required ltr of assurance.
M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170255 Forwards 0201 Intl. Inc. and use statement re application for license statement should be considered w/application submitted 7/1/92
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170254 Forwards application by Washington for license to export 8989 to Spain. M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170255 Forwards application by Transnuclear, Inc. for license to export 8989 to West Germany M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170262 Requests amend to export license, extending expiration to 8/1/93
HARRIS, D. B. International Co 00/06/92 1p
- 0004170264 Forwards application by Isotope Products Labs for license to export Cf-252 to Saudi Arabia M/C encl
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004170267 Forwards application for license for minor nuclear export requests existence in securing required ltr of assurance
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004180066 License for Marubeni America Corp to export 148 kg U-235, contained in 3,458 kg U, to Japan
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004180073 Amend A to SE export license, extending expiration date to 8/6/93
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004180120 License for Self-Heated Lighting Ltd to export 430,000 Ci tritium in dispersed form only, incorporated into sealed light sources as optical instruments, to Albania, Bulgaria, Czechoslovakia, East Germany, Hungary & Mongolia
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004190204 Amend I to Hoke, Inc. export license extending expiration date to 8/31/92 & increasing total value of items
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards HRL-101 00/05/92 1p
- 0004190214 Amend 3 to Hoke, Inc. export license, extending expiration date to 8/31/92 & increasing total value of items
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards LIBA-C.G. 10888 00/05/92 1p
- 0004190218 Application by Union Carbide Corp for license to export 8 OIO in stainless-steel in 40 cylinders to Japan
DALAL, D. C. Union Carbide Corp 00/04/92 00/05/92 1p
- 0004190221 License for GE to export 1,008 kg U-235, contained in 34,326 kg U, to Japan
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 304 H017 00/05/92 1p
- 0004190225 License for Nishio-Tsui American Corp to export 143.685 kg U-235, contained in 7,587.75 kg U, to Japan
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 194-0277 00/05/92 1p
- 0004190289 Forwards Editor Intl Co 890402 airmail requesting that expiration date on export license XH-1503 be extended from 8/30/92 to 8/31/93 M/C encl
PETERSON, M. R. Office of International Programs, Director 00/05/92 1p
- 0004190270 Requests Executive Branch position re Editor Intl Co 890402 request for amend to license XH-1503 to allow Radiochemical Centre to re-export 2 kg Cf-252 to East Germany for medical purposes.
PETERSON, M. R. Office of International Programs, Director 00/05/92 1p
- 0004190283 Advises that proposed license to export 7,587.75 kg U enriched to 1920 to Japan no longer requires Commissioner review. Unless notified that further analysis is required, license will be issued.
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004190290 Requests existence in obtaining necessary ltr of assurance re application for license to export single pellets of 10u enriched U fuel.
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004190291 Advises that proposed license to export 305,660 kg U enriched to 1920 to Bundesamt no longer requires Commissioner review. Unless notified that further analysis is required, license will be issued.
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p
- 0004190292 Advises that Everline Instrument Corp requests withdrawal of export license application for 890518 to Japan
PETERSON, M. R. Assistant Director For Export/Import & International Safeguards 00/05/92 1p

NONDOCKETED ITEMS

- 0004240116 Requests WRC expedite approval for application to export 100 g of deuterium chemically pure, contained in five cylinders to Australia 00/05/31 1p.
- 0004240120 Ltr of assurance re export of 7 g Pu & 10 g U-235 to Japan MIYAWAKI, H Japan 00/05/31 1p
- 0004240124 Notifies that Westinghouse informed embassy that all in-core fissile elements re use of in-core fissile chamber being processed. Processing will take approx three mths. Requesting expedited export approval. Australia 00/06/20 1p.
- 0004240129 Ltr of assurance re Beemdel Transport Corp application to export 32.70 g Pu to Belgium NORDEN, J Belgium Supply Agency (Belgium) 00/05/29 1p
- 0004240207 Authorizes issuance of License 18900-1094 since no meth changed circumstances since issuance of License 18900-1636 MORGENTHAU, D Office of International Programs, Director 00/06/18 1p
- 0004240275 Ltr of assurance re export of 921 kg U-235, contained in 33,648 kg U to Japan MIYAWAKI, H Japan 00/05/26 1p
- 0004240277 Ltr of assurance re export of 1,494 kg U-235, contained in 53,125 kg U to Japan MIYAWAKI, H Japan 00/05/26 1p
- 0004240302 Responds to 000507 request for info re status of application to export certain ore not treatment was to South Africa. Executive Branch response has been delayed. South Africa is not coherent to IRT. No assurance of issuance by Nov 1990. PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/10 1p.
- 0004240309 Licenses for 9F to export 5,694 kg U-235, contained in 35,125 kg U as U oxide powder to Japan PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/10 00/06/11 2pp
- 0004240400 Add response to P23A request for documents re proposed nuclear reactor located near Gyaema, Korea. Forwarded OJ. McNeill 70/322 memo 00CF-79-141 is also sent to request & is available in P23. PETERSEN, J Division of Rules and Records 00/06/20 1p
- 0004240403 Discusses review of application for license to export reactors to Korea. No physical security concerns apparent. Request that Executive Branch provide info re Korean age of accounting & control & status of safeguards implementation. MORGENTHAU, D Physical Security Licensing Branch, 70/03/22 1p
- 0004240404 Confirms appointment of Tokyo Electric Power Co Inc as authorized party for license to export 800 kg U-235, contained in 29,125 kg U to Japan. Mail transfer will conform to Agreement for Cooperation MIYAWAKI, H Japan 00/06/11 1p
- 0004250001 Reexamined no meth changed circumstance associated w/export license application from candidate existing at time of license. License 18900-1636 license may be issued. PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/17 1p.
- 0004250003 Licenses for Signe Chemical Co to export 8.0 kg deuterium oxide to Belgium PETERSEN, M Assistant Director for Export/Import & International Safeguards 0-40 00/06/18 2pp
- 0004250005 Forwards ltr from Talsynco Wah Chang Albany requesting availability of materials 0005-0109 to export. Dividing like shells to West Germany. W/le ltr. PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/06 1p
- 0004250008 Advises that Kuwaiti Sengon Industries, Inc. allowed license 0005-0107 to expire. Export is ready for immediate shipment. Fifteen-day waiting period is waived. License encl. PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/06 1p
- 0004250024 Licenses for Kuwaiti Polymeric Industries, Inc. to export 464.4 kg dividing 5 seamless tubing to West Germany. PETERSEN, M Assistant Director for Export/Import & International Safeguards 70/00 00/06/06 1p
- 0004250036 Licenses for Matheson Gas Products to export 900 liters 100 g of deuterium chemically pure, contained in five cylinders to Australia PETERSEN, M Assistant Director for Export/Import & International Safeguards 101-7582 00/06/11 2pp
- 0004250038 License for Beutler/Ditkes, Inc. to export one unenriched & one enriched isotopic chamber, model 80-82-0000-129 to BE-01-250-115, respectively, to Venezuela MORGENTHAU, D Office of International Programs, Director 00/06/06 1p
- 0004250039 Application by Mitsubishi Int'l Corp for license to export 430 kg U-235 to Japan KURE, T Mitsubishi International Corp (subs. of Mitsubishi Corp.) 0-7404-80 00/06/23 1p
- 0004250070 Requests Executive Branch position re Talsynco Precision application for license to export one belt solder to Argentina PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/06 1p
- 0004250072 License for Westinghouse to export one in-core fissile chamber, model WL-03795, to Australia PETERSEN, M Assistant Director for Export/Import & International Safeguards 00 00/06/11 1p
- 0004250095 Licenses for Matheson Gas Products to export 900 liters deuterium chemically pure, to Australia PETERSEN, M Assistant Director for Export/Import & International Safeguards 101-04512 00/06/11 2pp
- 0004250096 Licenses for GE to export 921 kg U-235, contained in 33,648 kg U as U oxide powder to Japan PETERSEN, M Assistant Director for Export/Import & International Safeguards 30A 00/06/11 00/06/11 2pp
- 0004250098 Advises that application for license to export specially designed parts & components to India was denied on 000516 & will be referred to President for further consideration. W/le encl order. BINA, J.R. Office of International Programs, Director 00/06/16 1p
- 0004250099 Advises that application for license to export specially designed parts & components to India was denied on 000516 & will be referred to President for further consideration. W/le encl order. BINA, J.R. Office of International Programs, Director 00/06/16 1p
- 0004250207 Executive Branch position re QA Co application for license to export fuel cluster tools: fuel rod trap device & storage rack to Taiwan. Ltr of assurance encl. License should be granted. MORGENTHAU, D (State, Dept. of Bureau of Ocean & International Environ & Scientific Affairs) 00/06/12 4pp
- 0004250208 Forwards application to export U-238 oxide to Soviet Union CAPRONI, L SNC International, Inc 00/06/14 1p
- 0004250267 Licenses for Nuclear Metals, Inc. to export 34,500 kg depleted U as well enriched plates, to Canada PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/12 2pp
- 0004250202 Application by Signe Chemical Co for license to export 10 kg deuterium oxide liquid over 24-p period to France MORGENTHAU, D Signe Chemical Co (subs. of Signe-Alrich Corp.) 0-40 00/06/06 1p
- 0004250304 Forwards license for Beemdel Transport Corp to export 32.70 g Pu & 10 g U-235 to Belgium PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/16 1p
- 0004250309 License for Beemdel Transport Corp to export 32.70 g Pu & 10 g U-235 to Belgium PETERSEN, M Assistant Director for Export/Import & International Safeguards 00/06/16 1p
- 0004250310 Application by Westinghouse for license to export one pressurized reactor, model M03705, to France. PCHAL, M F Westinghouse Electric Corp 2E-00336 00/06/09 1p
- 0004250312 Forwards Mitsubishi Int'l Corp application for license to export 993 kg U-235, contained in 15,541 kg U to Japan BINA, D Mitsubishi International Corp (subs. of Mitsubishi Corp.) 0-5400-04 00/06/06 2pp

NONDOCKETED ITEMS

337

--8004260012 Application by Mitsubishi Insl Corp for license to export 490 kg U-235 contained in 15-141 kg U to Japan End use statement encl

SHIRAI, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HSA-5403-04 80/06/06 2pp

8004260014 Forwarded Mitsubishi Insl Corp application for license to export 718 kg U-235 contained in 25-186 kg U to Japan
SHIRAI, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HSA-5403-05 80/06/06 2pp

--8004260018 Application by Mitsubishi Insl Corp for license to export 718 kg U-235 contained in 25-186 kg U to Japan End use statement encl
SHIRAI, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HSA-5403-05 80/06/06 2pp

8004260019 Forwarded Transnuclear, Inc. application for license to export 420 140 kg U-235 contained in 17,501 kg U to West Germany
NATONAL V. Transnuclear, Inc. 80/06/09 1p

--8004260029 Application by Transnuclear, Inc. for license to export 420 140 kg U-235 contained in 17,501 kg U to West Germany End use statement encl
NATONAL V. Transnuclear, Inc. 800 202 80-130/ 80/06/09 2pp

8004260030 Executive Branch position re Byron Jackson Pump Div. Corp. application for license to export specially designed parts & components for primary coolant pumps to Taiwan Ltr of assurance encl. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260034 Executive Branch position re Chen-Nuclear Gas Inc. Application for license to export xenon/nuclear gas to Taiwan Ltr of assurance encl. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260036 Executive Branch position re Washington application for license to export 1800 kg U-235 in 12 radiation surveillance capsules to Taiwan. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260044 Application by Washington for license to export three compensated saturation chambers, Model SLQ277, to France
POCHAL, W. F. Washington Electric Corp. 2E-29239 80/06/05 1p

8004260047 Executive Branch position re GE application for license to export 25 kg U-235 contained in 2 5 kg U to Taiwan Ltr of assurance encl. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260050 Executive Branch position re GE application for license to export 4,000 kg U-235 contained in 14,000 kg U to Taiwan Ltr of assurance encl. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260052 Executive Branch position re Ecolux Intl Corp application for license to export 500 kg depleted U to Israel Ltr of assurance encl. License should be granted.
ROSENBL, L. V. State Dept. of Bureau of Oceans & International Environments & Scientific Affairs 80/06/12 2pp

8004260054 Petition to Intervene & request for hearing re nuclear reactor export to Taiwan Requests public availability of all pertinent data & urges USDOE assessment of volcanic & seismic issues needed for adequate appraisal of risk.
HENSEL, J. E. Center for Development Policy, HENSEL, J. E. MCNAB, J. E. 80/06/12 2pp

8004260058 Petition to Intervene & request for hearing re nuclear reactor export to Taiwan Requests public availability of all pertinent data & urges USDOE assessment of volcanic & seismic issues needed for adequate appraisal of risk.
HENSEL, J. E. Center for Development Policy, HENSEL, J. E. MCNAB, J. E. 80/06/09 2pp

8004270007 Forwarded PR notice re applications for licenses to export nuclear facilities or data
SHIRAI, S. Office of International Programs, Director 80/06/16 1p

--8004270040 Notice of receipt of applications for licenses to export facilities or data.
SHIRAI, S. Office of International Programs, Director 80/06/16 2pp

8004260080 Informs that 770211 & 780278 export license applications denied due to failure to meet Atomic Energy Act requirements
SHIRAI, S. Office of International Programs, Director 80/06/06 1p

8004260111 License for Mitsui & Co to export 25-442 lbs Zircaloy-2 tubes (190-180 ppm radiol. Japan)
PETERSON, M. E. Assistant Director for Export/Import & International Safeguards 80/06/10 1p

8004260024 Advises that AEC could not find export license applications within Atomic Energy Act criteria Application referred to President for further consideration Committee SEC015 order & SEC049 revision encl W/O encl
SHIRAI, S. Office of International Programs, Director 80/06/16 1p

8004260088 Notifies that export license application determined not to be within Atomic Energy Act criteria Application forwarded to President for further consideration Committee SEC015 order & SEC049 revision encl W/O encl
SHIRAI, S. Office of International Programs, Director 80/06/16 1p

8004260273 Notifies that application does not meet Atomic Energy Act requirements Application forwarded to President for further consideration Committee SEC015 order & SEC049 revision encl W/O encl
SHIRAI, S. Office of International Programs, Director 80/06/16 1p

8004260276 Requests info & guidance re export of British self-luminous tubes to Australia
NACHTCHIN, J. G. US Edison Corp 80/06/11 1p

8004260277 License for Transnuclear, Inc. to export 7 447 kg U containing 0 393 kg U-235 to France
PETERSON, M. E. Assistant Director for Export/Import & International Safeguards 80-130/01 TAP 3 80/06/19 2pp

8004260237 Application by Aldrich Chemical Co. Inc. for license to export 1 kg deuterium in 3 kg deuterium oxide to Israel
ROSENBL, L. V. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 13/00 80/06/12 1p

8004260238 Application by Aldrich Chemical Co. Inc. for license to export 1 kg deuterium in 3 kg deuterium oxide to Israel
ROSENBL, L. V. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 13/00 80/06/12 1p

8004260239 License for Aldrich Chemical Co. Inc. to export 1 kg deuterium contained in 3 kg deuterium oxide to India
PETERSON, M. E. Assistant Director for Export/Import & International Safeguards 80/06/12 2pp

8004260540 Transcript of 770321 briefing in Washington, DC re SRIW Intl Co application for export SRIW to India Pg 1-62 & Conclusion, 77/03/21 2pp

8004260280 Forwarded application for license to export 20 g enriched U-235 to Japan.
SHIRAI, S. Mitsui & Co., Ltd 80/06/09 1p

--8004260084 Application by Mitsui & Co for license to export 20 g enriched U-235 to Japan.
SHIRAI, S. Mitsui & Co., Ltd 80/06/09 2pp

8004260485 Requests Executive Branch position re request for amendment to export license adding activities located in Anglia Cameron & Lyman Auk Republic to list of ultimate consignees.
PETERSON, M. E. Assistant Director for Export/Import & International Safeguards 80/06/22 1p

8004270791 Responds to 800411 ltr re export of sealed self-luminous tubular light sources to Australia License does authorize export of British gas in sealed sources but does not authorize shipment of gas in bulk form
PETERSON, M. E. Assistant Director for Export/Import & International Safeguards 80/06/23 1p

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
CAYAN, J. H.	0004020489	00-013 0	CHILK, D. J.	0004020051	10CFR	CLARK, R. A.	0004020236
CECILIER, P.	0004020489	78-29F	CHILK, D. J.	0004020052	PHR	CLARK, R. A.	0004020427
CEHNE, A. H.	0004020174	00-018 0	CHILK, D. J.	0004020188	PHR	CLARK, R. A.	0004020527
CHAPMAN, R.	0004020119	00-018 0	CHILK, D. J.	0004020139*	PHR	CLARK, R. A.	0004020031
CHAPMAN, R.	0004020021	RED	CHILK, D. J.	0004020077	PHR	CLARK, R. A.	0004020192
CHAP, B. J.	0004190079	00-073 A	CHILK, R. J.	0004020134	PHR	CLARK, R. A.	0004020525
CHAPMAN, P. D.	0004110162	00-445 R	CHILK, R. J.	0004020179	PHR	CLARK, R. A.	0004020299
CHAPMAN, L. J.	0004110162	00-445 R	CHILK, R. J.	0004020232	PHR	CLARK, R. A.	0004110244
CHANDLER, L. J.	0004020209	00-020 0	CHILK, R. J.	0004020239	ROGSD	CLARK, R. A.	0004020244
CHANDLER, L. J.	0004020219	00-020 0	CHILK, R. J.	0004020170	PHR	CLARK, R. A.	0004020244
CHANDLER, L. J.	0004020101	00-026 0	CHILK, R. J.	0004020261	00-024 0	CLARK, R. A.	0004020307
CHANDLER, L. J.	0004020470	00-020 0	CHILK, R. J.	0004020262	00-021 0	CLARK, R. A.	0004020166
CHANDLER, L. J.	0004020362	00-020 0	CHILK, R. J.	0004020170	PHR	CLARK, R. A.	0004020378
CHANG, H. S.	0004120449	MURD	CHILK, R. J.	0004020430	10CFR	CLARK, R. A.	0004020386
CHAPLIN, E. B.	0004030472	00-020 0	CHILK, R. J.	0004020239	ACR	CLARK, R. A.	0004020081
CHAPLIN, E. B.	0004030278	00-020 0	CHILK, R. J.	0004020777	PH	CLARK, R. J.	0004020177
CHAPLIN, E. B.	0004100279	00-020 0	CHILK, R. J.	0004020477	PH	CLARK, R. J.	0004020394
CHAPLIN, E. B.	0004020378	00-020 0	CHILK, R. J.	0004020489	00-020 0	CLARK, R. J.	0004120097
CHAPMAN, L. D.	0004020286	MURD	CHILK, R. J.	0004100192	PH	CLARK, R. A.	0004120623
CHAPMAN, H. C.	0004020098	NURD	CHILK, R. J.	0004100168*	PH	CLARK, R. A.	0004020081
CHAPMAN, L. D.	0004020362	NURD	CHILK, R. J.	0004020310	00-489 0	CLARK, R. A.	0004120629
CHAPMAN, L. D.	0004020250	NURD	CHILK, R. J.	0004020292	00-489 0	CLARK, R. A.	0004120414
CHARNOFF, G.	0004020299	00-266 0	CHILK, R. J.	0004100502	00-272 0	CLARK, R. A.	0004120414
CHARNOFF, G.	0004020299	00-266 0	CHILK, R. J.	0004100118	00-036 0	CLARK, R. A.	0004120414
CHARNOFF, G.	0004020299	00-266 0	CHILK, R. J.	0004020292	00-047 0	CLARK, R. A.	0004120414
CHASE, J. H.	0004020273	00-039 0	CHILK, R. J.	0004020376	10CFR	CLARK, A. T.	0004120923
CHASE, J. H.	0004020174	00-039 0	CHILK, R. J.	0004020402	10CFR, LC	CLARK, R. A.	0004020499
CHASE, J. H.	0004020174	00-039 0	CHILK, R. J.	0004020402	10CFR	CLARK, R. A.	0004020404
CHAUDHARY, H. K.	0004020298	00-043 0	CHILK, R. J.	0004020194	REPO	CLARK, R. A.	0004020476
CHICK, P. A.	0004020174	CHURCHMAN	CHILK, R. J.	0004020211	10CFR	CLARK, R. A.	0004120104
CHERN, H. S.	0004190566	REF	CHILK, R. J.	0004100147	10CFR	CLARK, R. A.	0004020171
CHERN, H. S.	0004120449	00-020 0	CHILK, R. J.	0004020201	PHR	CLARK, R. A.	0004020171
CHERTNER, R. J.	0004020291	REB	CHILK, R. J.	0004020423	10CFR	CLARK, R. A.	0004020171
CHITANI, H. J.	0004110224	00-400 0	CHILK, R. J.	0004020291	PHR	CLARK, R. A.	0004020209
CHITANI, H. J.	0004110224	00-400 0	CHILK, R. J.	0004020291	PHR	CLARK, R. A.	0004020209
CHITANI, H. J.	0004020291	00-400 0	CHILK, R. J.	0004020291	PHR	CLARK, R. A.	0004020209
CHITANI, H. J.	0004020291	00-400 0	CHILK, R. J.	0004020291	PHR	CLARK, R. A.	0004020209
CHITANI, H. J.	0004020291	00-400 0	CHILK, R. J.	0004020291	PHR	CLARK, R. A.	0004020209

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

351

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

363

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, M. C.	8004280217	50-445	DIEA, J. R.	8004002070	30-000	SEIDLE, M. C.	8004280218	71-5364
SEIDLE, M. C.	8004280218	50-445	DIEA, J. R.	8004002084	30-000	SEIDLE, M. C.	8004280219	71-5364
SEIDLE, M. C.	8004280219	50-445	DIEA, J. R.	8004002085	30-000	SEIDLE, M. C.	8004280220	71-5364
SEIDLE, M. C.	8004280220	50-445	DIEA, J. R.	8004002086	30-000	SEIDLE, M. C.	8004280221	71-5364
SEIDLE, M. C.	8004280221	50-445	DIEA, J. R.	8004002087	30-000	SEIDLE, M. C.	8004280222	71-5364
SEIDLE, M. C.	8004280222	50-445	DIEA, J. R.	8004002088	30-000	SEIDLE, M. C.	8004280223	71-5364
SEIDLE, M. C.	8004280223	50-445	DIEA, J. R.	8004002089	30-000	SEIDLE, M. C.	8004280224	71-5364
SEIDLE, M. C.	8004280224	50-445	DIEA, J. R.	8004002090	30-000	SEIDLE, M. C.	8004280225	71-5364
SEIDLE, M. C.	8004280225	50-445	DIEA, J. R.	8004002091	30-000	SEIDLE, M. C.	8004280226	71-5364
SEIDLE, M. C.	8004280226	50-445	DIEA, J. R.	8004002092	30-000	SEIDLE, M. C.	8004280227	71-5364
SEIDLE, M. C.	8004280227	50-445	DIEA, J. R.	8004002093	30-000	SEIDLE, M. C.	8004280228	71-5364
SEIDLE, M. C.	8004280228	50-445	DIEA, J. R.	8004002094	30-000	SEIDLE, M. C.	8004280229	71-5364
SEIDLE, M. C.	8004280229	50-445	DIEA, J. R.	8004002095	30-000	SEIDLE, M. C.	8004280230	71-5364
SEIDLE, M. C.	8004280230	50-445	DIEA, J. R.	8004002096	30-000	SEIDLE, M. C.	8004280231	71-5364
SEIDLE, M. C.	8004280231	50-445	DIEA, J. R.	8004002097	30-000	SEIDLE, M. C.	8004280232	71-5364
SEIDLE, M. C.	8004280232	50-445	DIEA, J. R.	8004002098	30-000	SEIDLE, M. C.	8004280233	71-5364
SEIDLE, M. C.	8004280233	50-445	DIEA, J. R.	8004002099	30-000	SEIDLE, M. C.	8004280234	71-5364
SEIDLE, M. C.	8004280234	50-445	DIEA, J. R.	8004002100	30-000	SEIDLE, M. C.	8004280235	71-5364
SEIDLE, M. C.	8004280235	50-445	DIEA, J. R.	8004002101	30-000	SEIDLE, M. C.	8004280236	71-5364
SEIDLE, M. C.	8004280236	50-445	DIEA, J. R.	8004002102	30-000	SEIDLE, M. C.	8004280237	71-5364
SEIDLE, M. C.	8004280237	50-445	DIEA, J. R.	8004002103	30-000	SEIDLE, M. C.	8004280238	71-5364
SEIDLE, M. C.	8004280238	50-445	DIEA, J. R.	8004002104	30-000	SEIDLE, M. C.	8004280239	71-5364
SEIDLE, M. C.	8004280239	50-445	DIEA, J. R.	8004002105	30-000	SEIDLE, M. C.	8004280240	71-5364
SEIDLE, M. C.	8004280240	50-445	DIEA, J. R.	8004002106	30-000	SEIDLE, M. C.	8004280241	71-5364
SEIDLE, M. C.	8004280241	50-445	DIEA, J. R.	8004002107	30-000	SEIDLE, M. C.	8004280242	71-5364
SEIDLE, M. C.	8004280242	50-445	DIEA, J. R.	8004002108	30-000	SEIDLE, M. C.	8004280243	71-5364
SEIDLE, M. C.	8004280243	50-445	DIEA, J. R.	8004002109	30-000	SEIDLE, M. C.	8004280244	71-5364
SEIDLE, M. C.	8004280244	50-445	DIEA, J. R.	8004002110	30-000	SEIDLE, M. C.	8004280245	71-5364
SEIDLE, M. C.	8004280245	50-445	DIEA, J. R.	8004002111	30-000	SEIDLE, M. C.	8004280246	71-5364
SEIDLE, M. C.	8004280246	50-445	DIEA, J. R.	8004002112	30-000	SEIDLE, M. C.	8004280247	71-5364
SEIDLE, M. C.	8004280247	50-445	DIEA, J. R.	8004002113	30-000	SEIDLE, M. C.	8004280248	71-5364
SEIDLE, M. C.	8004280248	50-445	DIEA, J. R.	8004002114	30-000	SEIDLE, M. C.	8004280249	71-5364
SEIDLE, M. C.	8004280249	50-445	DIEA, J. R.	8004002115	30-000	SEIDLE, M. C.	8004280250	71-5364
SEIDLE, M. C.	8004280250	50-445						

3

PERSONAL AUTHOR INDEX

[illegible]

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondockated items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	0000230369	50-528 A		0000110040	50-513 F
	0000230370	50-528 A		0000110041	50-513 F
	0000230371	50-528 A		0000110042	50-513 F
	0000230372	50-528 A		0000110043	50-513 F
	0000230373	50-528 A		0000110044	50-513 F
	0000230374	50-528 A		0000110045	50-513 F
	0000230375	50-528 A		0000110046	50-513 F
	0000230376	50-528 A		0000110047	50-513 F
	0000230377	50-528 A		0000110048	50-513 F
	0000230378	50-528 A		0000110049	50-513 F
	0000230379	50-528 A		0000110050	50-513 F
	0000230380	50-528 A		0000110051	50-513 F
	0000230381	50-528 A		0000110052	50-513 F
	0000230382	50-528 A		0000110053	50-513 F
	0000230383	50-528 A		0000110054	50-513 F
	0000230384	50-528 A		0000110055	50-513 F
	0000230385	50-528 A		0000110056	50-513 F
	0000230386	50-528 A		0000110057	50-513 F
	0000230387	50-528 A		0000110058	50-513 F
	0000230388	50-528 A		0000110059	50-513 F
	0000230389	50-528 A		0000110060	50-513 F
	0000230390	50-528 A		0000110061	50-513 F
	0000230391	50-528 A		0000110062	50-513 F
	0000230392	50-528 A		0000110063	50-513 F
	0000230393	50-528 A		0000110064	50-513 F
	0000230394	50-528 A		0000110065	50-513 F
	0000230395	50-528 A		0000110066	50-513 F
	0000230396	50-528 A		0000110067	50-513 F
	0000230397	50-528 A		0000110068	50-513 F
	0000230398	50-528 A		0000110069	50-513 F
	0000230399	50-528 A		0000110070	50-513 F
	0000230400	50-528 A		0000110071	50-513 F
	0000230401	50-528 A		0000110072	50-513 F
	0000230402	50-528 A		0000110073	50-513 F
	0000230403	50-528 A		0000110074	50-513 F
	0000230404	50-528 A		0000110075	50-513 F
	0000230405	50-528 A		0000110076	50-513 F
	0000230406	50-528 A		0000110077	50-513 F
	0000230407	50-528 A		0000110078	50-513 F
	0000230408	50-528 A		0000110079	50-513 F
	0000230409	50-528 A		0000110080	50-513 F
	0000230410	50-528 A		0000110081	50-513 F
	0000230411	50-528 A		0000110082	50-513 F
	0000230412	50-528 A		0000110083	50-513 F
	0000230413	50-528 A		0000110084	50-513 F
	0000230414	50-528 A		0000110085	50-513 F
	0000230415	50-528 A		0000110086	50-513 F
	0000230416	50-528 A		0000110087	50-513 F
	0000230417	50-528 A		0000110088	50-513 F
	0000230418	50-528 A		0000110089	50-513 F
	0000230419	50-528 A		0000110090	50-513 F
	0000230420	50-528 A		0000110091	50-513 F
	0000230421	50-528 A		0000110092	50-513 F
	0000230422	50-528 A		0000110093	50-513 F
	0000230423	50-528 A		0000110094	50-513 F
	0000230424	50-528 A		0000110095	50-513 F
	0000230425	50-528 A		0000110096	50-513 F
	0000230426	50-528 A		0000110097	50-513 F
	0000230427	50-528 A		0000110098	50-513 F

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESION NUMBER	SUBJECT CATEGORY
	0004370734	70-8201		0004368325	50-466a
	0004370739	70-1001		0004368326	50-466a
	0004370745	70-8204		0004368327	50-466a
	0004370748	70-8204	Baldwin, W. A.	0004368328	50-466a
	0004370749	70-8204	Baltimore Gas & Electric Co	0004368329	50-466a
	0004370754	70-1208		0004368330	50-466a
	0004370756	70-1208		0004368331	50-466a
	0004370759	70-1208		0004368332	50-466a
	0004370760	70-8204		0004368333	50-466a
	0004370761	70-8204		0004368334	50-466a
	0004370762	70-1208		0004368335	50-466a
	0004370763	70-8204		0004368336	50-466a
	0004370764	70-8204		0004368337	50-466a
	0004370765	70-1208		0004368338	50-466a
	0004370766	70-1208		0004368339	50-466a
	0004370767	70-1208		0004368340	50-466a
	0004370768	70-1208		0004368341	50-466a
	0004370769	70-1208		0004368342	50-466a
	0004370770	70-1208		0004368343	50-466a
	0004370771	70-1208		0004368344	50-466a
	0004370772	70-1208		0004368345	50-466a
	0004370773	70-1208		0004368346	50-466a
	0004370774	70-1208		0004368347	50-466a
	0004370775	70-1208		0004368348	50-466a
	0004370776	70-1208		0004368349	50-466a
	0004370777	70-1208		0004368350	50-466a
	0004370778	70-1208		0004368351	50-466a
	0004370779	70-1208		0004368352	50-466a
	0004370780	70-1208		0004368353	50-466a
	0004370781	70-1208		0004368354	50-466a
	0004370782	70-1208		0004368355	50-466a
	0004370783	70-1208		0004368356	50-466a
	0004370784	70-1208		0004368357	50-466a
	0004370785	70-1208		0004368358	50-466a
	0004370786	70-1208		0004368359	50-466a
	0004370787	70-1208		0004368360	50-466a
	0004370788	70-1208		0004368361	50-466a
	0004370789	70-1208		0004368362	50-466a
	0004370790	70-1208		0004368363	50-466a
	0004370791	70-1208		0004368364	50-466a
	0004370792	70-1208		0004368365	50-466a
	0004370793	70-1208		0004368366	50-466a
	0004370794	70-1208		0004368367	50-466a
	0004370795	70-1208		0004368368	50-466a
	0004370796	70-1208		0004368369	50-466a
	0004370797	70-1208		0004368370	50-466a
	0004370798	70-1208		0004368371	50-466a
	0004370799	70-1208		0004368372	50-466a
	0004370800	70-1208		0004368373	50-466a
	0004370801	70-1208		0004368374	50-466a
	0004370802	70-1208		0004368375	50-466a
	0004370803	70-1208		0004368376	50-466a
	0004370804	70-1208		0004368377	50-466a
	0004370805	70-1208		0004368378	50-466a
	0004370806	70-1208		0004368379	50-466a
	0004370807	70-1208		0004368380	50-466a
	0004370808	70-1208		0004368381	50-466a
	0004370809	70-1208		0004368382	50-466a
	0004370810	70-1208		0004368383	50-466

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	000440003	HM000	Louenstein, Monahan, Reis, Asimov & Telli	000440008	90-446 C
	000440005	90-482 S		000440009	90-445 H
	000440004	90-482 P		000440030	90-445 H
	000440004	90-482 F		000440032	90-443 H
	000440005	90-482 S		000440033	90-445 H
	000440004	90-482 S		000440034	90-445 H
	000440012	90-482 S		000440035	90-445 H
Kentucky, State of	000440015	State Prag		000440036	90-445 H
	000440064	State Prag		000440047	90-244 O
	000440054	CONFERENCE		000440048	90-445 H
Kentucky, Univ. of	000440050	AC05		000440050	90-445 H
Keweenaw College	000440051	70-423		000440051	90-445 H
Kepford, C	000440059	90-320 G		000440052	90-445 H
Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.)	000440043	PRH		000440053	90-445 H
	000440044	PRH		000440054	90-445 H
	000440051	40-2041		000440055	90-445 H
Kerr-McGee Corp.	000440052	71-9091		000440056	90-445 H
	000440053	70-1193		000440057	90-445 H
Kerr-McGee Nuclear Corp.	000440057	40-0027		000440058	90-445 H
	000440058	40-0027		000440059	90-445 H
	000440064	40-2041		000440060	90-445 H
	000440065	40-0027		000440061	90-445 H
	000440066	40-0027		000440062	90-445 H
	000440067	40-0027		000440063	90-445 H
	000440068	40-0027		000440064	90-445 H
	000440069	40-0027		000440065	90-445 H
	000440070	40-0027		000440066	90-445 H
	000440071	40-0027		000440067	90-445 H
	000440072	40-0027		000440068	90-445 H
	000440073	40-0027		000440069	90-445 H
	000440074	40-0027		000440070	90-445 H
	000440075	40-0027		000440071	90-445 H
	000440076	40-0027		000440072	90-445 H
	000440077	40-0027		000440073	90-445 H
	000440078	40-0027		000440074	90-445 H
	000440079	40-0027		000440075	90-445 H
	000440080	40-0027		000440076	90-445 H
	000440081	40-0027		000440077	90-445 H
	000440082	40-0027		000440078	90-445 H
	000440083	40-0027		000440079	90-445 H
	000440084	40-0027		000440080	90-445 H
	000440085	40-0027		000440081	90-445 H
	000440086	40-0027		000440082	90-445 H
	000440087	40-0027		000440083	90-445 H
	000440088	40-0027		000440084	90-445 H
	000440089	40-0027		000440085	90-445 H
	000440090	40-0027		000440086	90-445 H
	000440091	40-0027		000440087	90-445 H
	000440092	40-0027		000440088	90-445 H
	000440093	40-0027		000440089	90-445 H
	000440094	40-0027		000440090	90-445 H
	000440095	40-0027		000440091	90-445 H
	000440096	40-0027		000440092	90-445 H
	000440097	40-0027		000440093	90-445 H
	000440098	40-0027		000440094	90-445 H
	000440099	40-0027		000440095	90-445 H
	000440100	40-0027		000440096	90-445 H
	000440101	40-0027		000440097	90-445 H
	000440102	40-0027		000440098	90-445 H
	000440103	40-0027		000440099	90-445 H
	000440104	40-0027		000440100	90-445 H
	000440105	40-0027		000440101	90-445 H
	000440106	40-0027		000440102	90-445 H
	000440107	40-0027		000440103	90-445 H
	000440108	40-0027		000440104	90-445 H
	000440109	40-0027		000440105	90-445 H
	000440110	40-0027		000440106	90-445 H
	000440111	40-0027		000440107	90-445 H
	000440112	40-0027		000440108	90-445 H
	000440113	40-0027		000440109	90-445 H
	000440114	40-0027		000440110	90-445 H
	000440115	40-0027		000440111	90-445 H
	000440116	40-0027		000440112	90-445 H
	000440117	40-0027		000440113	90-445 H
	000440118	40-0027		000440114	90-445 H
	000440119	40-0027		000440115	90-445 H
	000440120	40-0027		000440116	90-445 H
	000440121	40-0027		000440117	90-445 H
	000440122	40-0027		000440118	90-445 H
	000440123	40-0027		000440119	90-445 H
	000440124	40-0027		000440120	90-445 H
	000440125	40-0027		000440121	90-445 H
	000440126	40-0027		000440122	90-445 H
	000440127	40-0027		000440123	90-445 H
	000440128	40-0027		000440124	90-445 H
	000440129	40-0027		000440125	90-445 H
	000440130	40-0027		000440126	90-445 H
	000440131	40-0027		000440127	90-445 H
	000440132	40-0027		000440128	90-445 H
	000440133	40-0027		000440129	90-445 H
	000440134	40-0027		000440130	90-445 H
	000440135	40-0027		000440131	90-445 H
	000440136	40-0027		000440132	90-445 H
	000440137	40-0027		000440133	90-445 H
	000440138	40-0027		000440134	90-445 H
	000440139	40-0027		000440135	90-445 H
	000440140	40-0027		000440136	90-445 H
	000440141	40-0027		000440137	90-445 H
	000440142	40-0027		000440138	90-445 H
	000440143	40-0027		000440139	90-445 H
	000440144	40-0027		000440140	90-445 H
	000440145	40-0027		000440141	90-445 H
	000440146	40-0027		000440142	90-445 H
	000440147	40-0027		000440143	90-445 H
	000440148	40-0027		000440144	90-445 H
	000440149	40-0027		000440145	90-445 H
	000440150	40-0027		000440146	90-445 H
	000440151	40-0027		000440147	90-445 H
	000440152	40-0027		000440148	90-445 H
	000440153	40-0027		000440149	90-445 H
	000440154	40-0027		000440150	90-445 H
	000440155	40-0027		000440151	90-445 H
	000440156	40-0027		000440152	90-445 H
	000440157	40-0027		000440153	90-445 H
	000440158	40-0027		000440154	90-445 H
	000440159	40-0027		000440155	90-445 H
	000440160	40-0027		000440156	90-445 H
	000440161	40-0027		000440157	90-445 H
	000440162	40-0027		000440158	90-445 H
	000440163	40-0027		000440159	90-445 H
	000440164	40-0027		000440160	90-445 H
	000440165	40-0027		000440161	90-445 H
	000440166	40-0027		000440162	90-445 H
	000440167	40-0027		000440163	90-445 H
	000440168	40-0027		000440164	90-445 H
	000440169	40-0027		000440165	90-445 H
	000440170	40-0027		000440166	90-445 H
	000440171	40-0027		000440167	90-445 H
	000440172	40-0027		000440168	90-445 H
	000440173	40-0027		000440169	90-445 H
	000440174	40-0027		000440170	90-445 H
	000440175	40-0027		000440171	90-445 H
	000440176	40-0027		000440172	90-445 H
	000440177	40-0027		000440173	90-445 H
	000440178	40-0027		000440174	90-445 H
	000440179	40-0027		000440175	90-445 H
	000440180	40-0027		000440176	90-445 H
	000440181	40-0027		000440177	90-445 H
	000440182	40-0027		000440178	90-445 H
	000440183	40-0027		000440179	90-445 H
	000440184	40-0027		000440180	90-445 H
	000440185	40-0027		000440181	90-445 H
	000440186	40-0027		000440182	90-445 H
	000440187	40-0027		000440183	90-445 H
	000440188	40-0027		000440184	90-445 H
	000440189	40-0027		000440185	90-445 H
	000440190	40-0027		000440186	90-445 H
	000440191	40-0027		000440187	90-445 H
	000440192	40-0027		000440188	90-445 H
	000440193	40-0027		000440189	90-445 H
	000440194	40-0027		000440190	90-445 H
	000440195	40-0027		000440191	90-445 H
	000440196	40-0027		000440192	90-445 H
	000440197	40-0027		000440193	90-445 H
	000440198	40-0027		000440194	90-445 H
	000440199	40-0027		000440195	90-445 H
	000440200	40-0027		000440196	90-445 H
	000440201	40-0027		000440197	90-445 H
	000440202	40-0027		000440198	90-445 H
	000440203	40-0027		000440199	90-445 H
	000440204	40-0027		000440200	90-445 H
	000440205	40-0027		000440201	90-445 H
	000440206	40-0027		000440202	90-445 H
	000440207	40-0027		000440203	90-445 H
	000440208	40-0027		000440204	90-445 H
	000440209	40-0027		000440205	90-445 H
	000440210	40-0027		000440206	90-445 H
	000440211	40-0027		000440207	90-445 H
	000440212	40-0027		000440208	90-445 H
	000440213	40-0027		000440209	90-445 H
	000440214	40-0027		000440210	90-445 H
	000440215	40-0027		000440211	90-445 H
	000440216	40-0027		000440212	90-445 H
	000440217	40-0027		000440213	90-445 H
	000440218	40-0027		000440214	90-445 H
	000440219	40-0027		000440215	90-445 H
	000440220	40-0027		000440216	90-445 H
	000440221	40-0027		000440217	90-445 H
	000440222	40-0027		000440218	90-445 H
	000440223	40-0027		000440219	90-445 H
	000440224	40-0027		000440220	90-445 H
	000440225	40-0027		000440221	90-445 H
	000440226	40-0027		000440222	90-445 H
	000440227	40-0027		000440223	90-445 H
	000440228	40-00			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Harvard Univ. of	8006101082	50-1A4	P	8006101074	50-1A4
	8006101081	50-1A4	K	8006101075	50-1A4
	8006101080	50-1A4	K	8006101076	50-1A4
	8006101079	50-1A4	K	8006101077	50-1A4
	8006101078	50-1A4	K	8006101078	50-1A4
	8006101077	50-1A4	K	8006101079	50-1A4
	8006101076	50-1A4	K	8006101080	50-1A4
	8006101075	50-1A4	K	8006101081	50-1A4
	8006101074	50-1A4	K	8006101082	50-1A4
	8006101082	50-1A4	K	8006101083	50-1A4
	8006101081	50-1A4	K	8006101084	50-1A4
	8006101080	50-1A4	K	8006101085	50-1A4
	8006101079	50-1A4	K	8006101086	50-1A4
	8006101078	50-1A4	K	8006101087	50-1A4
	8006101077	50-1A4	K	8006101088	50-1A4
	8006101076	50-1A4	K	8006101089	50-1A4
	8006101075	50-1A4	K	8006101090	50-1A4
	8006101074	50-1A4	K	8006101091	50-1A4
	8006101073	50-1A4	K	8006101092	50-1A4
	8006101072	50-1A4	K	8006101093	50-1A4
	8006101071	50-1A4	K	8006101094	50-1A4
	8006101070	50-1A4	K	8006101095	50-1A4
	8006101069	50-1A4	K	8006101096	50-1A4
	8006101068	50-1A4	K	8006101097	50-1A4
	8006101067	50-1A4	K	8006101098	50-1A4
	8006101066	50-1A4	K	8006101099	50-1A4
	8006101065	50-1A4	K	8006101100	50-1A4
	8006101064	50-1A4	K	8006101101	50-1A4
	8006101063	50-1A4	K	8006101102	50-1A4
	8006101062	50-1A4	K	8006101103	50-1A4
	8006101061	50-1A4	K	8006101104	50-1A4
	8006101060	50-1A4	K	8006101105	50-1A4
	8006101059	50-1A4	K	8006101106	50-1A4
	8006101058	50-1A4	K	8006101107	50-1A4
	8006101057	50-1A4	K	8006101108	50-1A4
	8006101056	50-1A4	K	8006101109	50-1A4
	8006101055	50-1A4	K	8006101110	50-1A4
	8006101054	50-1A4	K	8006101111	50-1A4
	8006101053	50-1A4	K	8006101112	50-1A4
	8006101052	50-1A4	K	8006101113	50-1A4
	8006101051	50-1A4	K	8006101114	50-1A4
	8006101050	50-1A4	K	8006101115	50-1A4
	8006101049	50-1A4	K	8006101116	50-1A4
	8006101048	50-1A4	K	8006101117	50-1A4
	8006101047	50-1A4	K	8006101118	50-1A4
	8006101046	50-1A4	K	8006101119	50-1A4
	8006101045	50-1A4	K	8006101120	50-1A4
	8006101044	50-1A4	K	8006101121	50-1A4
	8006101043	50-1A4	K	8006101122	50-1A4
	8006101042	50-1A4	K	8006101123	50-1A4
	8006101041	50-1A4	K	8006101124	50-1A4
	8006101040	50-1A4	K	8006101125	50-1A4
	8006101039	50-1A4	K	8006101126	50-1A4
	8006101038	50-1A4	K	8006101127	50-1A4
	8006101037	50-1A4	K	8006101128	50-1A4
	8006101036	50-1A4	K	8006101129	50-1A4
	8006101035	50-1A4	K	8006101130	50-1A4
	8006101034	50-1A4	K	8006101131	50-1A4
	8006101033	50-1A4	K	8006101132	50-1A4
	8006101032	50-1A4	K	8006101133	50-1A4
	8006101031	50-1A4	K	8006101134	50-1A4
	8006101030	50-1A4	K	8006101135	50-1A4
	8006101029	50-1A4	K	8006101136	50-1A4
	8006101028	50-1A4	K	8006101137	50-1A4
	8006101027	50-1A4	K	8006101138	50-1A4
	8006101026	50-1A4	K	8006101139	50-1A4
	8006101025	50-1A4	K	8006101140	50-1A4
	8006101024	50-1A4	K	8006101141	50-1A4
	8006101023	50-1A4	K	8006101142	50-1A4
	8006101022	50-1A4	K	8006101143	50-1A4
	8006101021	50-1A4	K	8006101144	50-1A4
	8006101020	50-1A4	K	8006101145	50-1A4
	8006101019	50-1A4	K	8006101146	50-1A4
	8006101018	50-1A4	K	8006101147	50-1A4
	8006101017	50-1A4	K	8006101148	50-1A4
	8006101016	50-1A4	K	8006101149	50-1A4
	8006101015	50-1A4	K	8006101150	50-1A4
	8006101014	50-1A4	K	8006101151	50-1A4
	8006101013	50-1A4	K	8006101152	50-1A4
	8006101012	50-1A4	K	8006101153	50-1A4
	8006101011	50-1A4	K	8006101154	50-1A4
	8006101010	50-1A4	K	8006101155	50-1A4
	8006101009	50-1A4	K	8006101156	50-1A4
	8006101008	50-1A4	K	8006101157	50-1A4
	8006101007	50-1A4	K	8006101158	50-1A4
	8006101006	50-1A4	K	8006101159	50-1A4
	8006101005	50-1A4	K	8006101160	50-1A4
	8006101004	50-1A4	K	8006101161	50-1A4
	8006101003	50-1A4	K	8006101162	50-1A4
	8006101002	50-1A4	K	8006101163	50-1A4
	8006101001	50-1A4	K	8006101164	50-1A4
	8006101000	50-1A4	K	8006101165	50-1A4
	8006100999	50-1A4	K	8006101166	50-1A4
	8006100998	50-1A4	K	8006101167	50-1A4
	8006100997	50-1A4	K	8006101168	50-1A4
	8006100996	50-1A4	K	8006101169	50-1A4
	8006100995	50-1A4	K	8006101170	50-1A4
	8006100994	50-1A4	K	8006101171	50-1A4
	8006100993	50-1A4	K	8006101172	50-1A4
	8006100992	50-1A4	K	8006101173	50-1A4
	8006100991	50-1A4	K	8006101174	50-1A4
	8006100990	50-1A4	K	8006101175	50-1A4
	8006100989	50-1A4	K	8006101176	50-1A4
	8006100988	50-1A4	K	8006101177	50-1A4
	8006100987	50-1A4	K	8006101178	50-1A4
	8006100986	50-1A4	K	8006101179	50-1A4
	8006100985	50-1A4	K	8006101180	50-1A4
	8006100984	50-1A4	K	8006101181	50-1A4
	8006100983	50-1A4	K	8006101182	50-1A4
	8006100982	50-1A4	K	8006101183	50-1A4
	8006100981	50-1A4	K	8006101184	50-1A4
	8006100980	50-1A4	K	8006101185	50-1A4
	8006100979	50-1A4	K	8006101186	50-1A4
	8006100978	50-1A4	K	8006101187	50-1A4
	8006100977	50-1A4	K	8006101188	50-1A4
	8006100976	50-1A4	K	8006101189	50-1A4
	8006100975	50-1A4	K	8006101190	50-1A4
	8006100974	50-1A4	K	8006101191	50-1A4
	8006100973	50-1A4	K	8006101192	50-1A4
	8006100972	50-1A4	K	8006101193	50-1A4
	8006100971	50-1A4	K	8006101194	50-1A4
	8006100970	50-1A4	K	8006101195	50-1A4
	8006100969	50-1A4	K	8006101196	50-1A4
	8006100968	50-1A4	K	8006101197	50-1A4
	8006100967	50-1A4	K	8006101198	50-1A4
	8006100966	50-1A4	K	8006101199	50-1A4
	8006100965	50-1A4	K	8006101200	50-1A4
	8006100964	50-1A4	K	8006101201	50-1A4
	8006100963	50-1A4	K	8006101202	50-1A4
	8006100962	50-1A4	K	8006101203	50-1A4
	8006100961	50-1A4	K	8006101204	50-1A4
	8006100960	50-1A4	K	8006101205	50-1A4
	8006100959	50-1A4	K	8006101206	50-1A4
	8006100958	50-1A4	K	8006101207	50-1A4
	8006100957	50-1A4	K	8006101208	50-1A4
	8006100956	50-1A4	K	8006101209	50-1A4
	8006100955	50-1A4	K	8006101210	50-1A4
	8006100954	50-1A4	K	8006101211	50-1A4
	8006100953	50-1A4	K	8006101212	50-1A4
	8006100952	50-1A4	K	8006101213	50-1A4
	8006100951	50-1A4	K	8006101214	50-1A4
	8006100950	50-1A4	K	8006101215	50-1A4
	8006100949	50-1A4	K	8006101216	50-1A4
	8006100948	50-1A4	K	8006101217	50-1A4
	8006100947	50-1A4	K	8006101218	50-1A4
	8006100946	50-1A4	K	8006101219	50-1A4
	8006100945	50-1A4	K	8006101220	50-1A4
	8006100944	50-1A4	K	8006101221	50-1A4
	8006100943	50-1A4	K	8006101222	50-1A4
	8006100942	50-1A4	K	8006101223	50-1A4
	8006100941	50-1A4	K	8006101224	50-1A4
	8006100940	50-1A4	K	8006101225	50-1A4
	8006100939	50-1A4	K	8006101226	50-1A4
	8006100938	50-1A4	K	8006101227	50-1A4
	8006100937	50-1A4	K	8006101228	50-1A4
	8006100936	50-1A4	K	8006101229	50-1A4
	8006100935	50-1A4	K	8006101230	50-1A4
	8006100934	50-1A4	K	8006101231	50-1A4
	8006100933	50-1A4	K	8006101232	50-1A4
	8006100932	50-1A4	K	8006101233	50-1A4
	8006100931	50-1A4	K	8006101234	50-1A4
	8006100930	50-1A4	K	8006101235	50-1A4
	8006100929	50-1A4	K	8006101236	50-1A4
	8006100928	50-1A4	K	8006101237	50-1A4
	8006100927	50-1A4	K	8006101238	50-1A4
	8006100926	50-1A4	K	8006101239	50-1A4
	8006100925	50-1A4	K	8006101240	50-1A4
	8006100924	50-1A4	K	8006101241	50-1A4
	8006100923	50-1A4	K	8006101242	50-1A4
	8006100922	50-1A4	K	8006101243	50-1A4
	8006100921	50-1A4	K	8006101244	50-1A4
	8006100920	50-1A4	K	8006101245	50-1A4
	8006100919	50-1A4	K	8006101246	50-1A4
	8006100918	50-1A4	K	8006101247	50-1A4
	8006100917	50-1A4	K	8006101248	50-1A4
	8006100916	50-1A4	K	8006101249	50-1A4
	8006100915	50-1A4	K	8006101250	50-1A4
	8006100914	50-1A4	K	8006101251	50-1A4
	8006100913	50-1A4	K	8006101252	50-1A4
	8006100912	50-1A4	K	8006101253	50-1A4
	8006100911	50-1A4	K	8006101254	50-1A4
	8006100910	50-1A4	K	8006101255	50-1A4
	8006100909	50-1A4	K	8006101256	50-1A4
	8006100908	50-1A4	K	8006101257	50-1A4
	8006100907	50-1A4	K	8006101258	50-1A4
	8006100906	50-1A4	K	8006101259	50-1A4
	8006100905	50-1A4	K	8006101260	50-1A4
	8006100904	50-1A4	K	8006101261	50-1A4
	8006100903	50-1A4	K	8006101262	50-1A4
	8006100902				

CORPORATE SOURCE INDEX

387

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	0006000375*	20-220 S		0006000375*	20-220 S
	0006110131	20-220 R		0006110131	20-220 R
	0006110176*	20-220 R		0006110176*	20-220 R
	0006110281	20-220 J	Marathon Petroleum Electric Cooperative, Inc	0006110281	20-220 J
	0006110282	20-220 J	Marathon Petroleum Electric Cooperative, Inc	0006110282	20-220 J
	0006120388	20-220 G		0006120388	20-220 G
	0006140996	20-410 A		0006140996	20-410 A
	0006170322	20-410 A		0006170322	20-410 A
	0006170475	20-220 F		0006170475	20-220 F
	0006230880	20-410 A		0006230880	20-410 A
	0006240012	20-410 G		0006240012	20-410 G
	0006240026	20-410 H		0006240026	20-410 H
	0006270389	20-220 F		0006270389	20-220 F
	0006300255	20-220 G		0006300255	20-220 G
	0006300271	20-220 G		0006300271	20-220 G
	0006300335	20-220 F		0006300335	20-220 F
	0006300379	20-220 F		0006300379	20-220 F
	0006400145	20-220 G		0006400145	20-220 G
	0006110347	20-277 F		0006110347	20-277 F
	0006170470	20-111 M		0006170470	20-111 M
	0006170482	20-111 M		0006170482	20-111 M
	0006240094	20-240 G		0006240094	20-240 G
	0006170031	20-220 H		0006170031	20-220 H
	0006170434	20-445 H		0006170434	20-445 H
	0006320193	20-445 H		0006320193	20-445 H
	0007300283	FR		0007300283	FR
	0006000023	20-213 F		0006000023	20-213 F
	0006000211*	20-213 F		0006000211*	20-213 F
	0006000335	20-226 G		0006000335	20-226 G
	0006000392*	20-226 G		0006000392*	20-226 G
	0006000054	20-248 D		0006000054	20-248 D
	0006000474	20-236 F		0006000474	20-236 F
	0006000476*	20-236 F		0006000476*	20-236 F
	0006000111	20-236 D		0006000111	20-236 D
	0006000359	20-248 F		0006000359	20-248 F
	0006000326	20-236 F		0006000326	20-236 F
	0006000347	20-213 F		0006000347	20-213 F
	0006000350	20-248 F		0006000350	20-248 F
	0006100494	20-223 H		0006100494	20-223 H
	0006170081	20-245 F	Northwestern Univ	0006170081	20-245 F
	0006170163	20-245 F		0006170163	20-245 F
	0006170240	20-236 U	Nuclear Insurance Corp	0006170240	20-236 U
	0006170284*	20-236 H		0006170284*	20-236 H
	0006180083	20-245 F		0006180083	20-245 F
	0006180047	20-236 F		0006180047	20-236 F
	0006160096*	20-236 F		0006160096*	20-236 F
	0006170587	20-236 G		0006170587	20-236 G
	0006170644	20-236 F		0006170644	20-236 F
	0006170688	20-236 F		0006170688	20-236 F
	0006170687	20-213 F	Nuclear Energy Service, Inc	0006170687	20-213 F
	0006170688	20-213 F		0006170688	20-213 F
	0006170689	20-236 F		0006170689	20-236 F
	0006170690	20-236 F		0006170690	20-236 F
	0006170691	20-236 F		0006170691	20-236 F
	0006170692	20-236 F		0006170692	20-236 F
	0006170693	20-236 F		0006170693	20-236 F
	0006170694	20-236 F		0006170694	20-236 F
	0006170695	20-236 F		0006170695	20-236 F
	0006170696	20-236 F		0006170696	20-236 F
	0006170697	20-236 F		0006170697	20-236 F
	0006170698	20-236 F		0006170698	20-236 F
	0006170699	20-236 F		0006170699	20-236 F
	0006170700	20-236 F		0006170700	20-236 F
	0006170701	20-236 F		0006170701	20-236 F
	0006170702	20-236 F		0006170702	20-236 F
	0006170703	20-236 F		0006170703	20-236 F
	0006170704	20-236 F		0006170704	20-236 F
	0006170705	20-236 F		0006170705	20-236 F
	0006170706	20-236 F		0006170706	20-236 F
	0006170707	20-236 F		0006170707	20-236 F
	0006170708	20-236 F		0006170708	20-236 F
	0006170709	20-236 F		0006170709	20-236 F
	0006170710	20-236 F		0006170710	20-236 F
	0006170711	20-236 F		0006170711	20-236 F
	0006170712	20-236 F		0006170712	20-236 F
	0006170713	20-236 F		0006170713	20-236 F
	0006170714	20-236 F		0006170714	20-236 F
	0006170715	20-236 F		0006170715	20-236 F
	0006170716	20-236 F		0006170716	20-236 F
	0006170717	20-236 F		0006170717	20-236 F
	0006170718	20-236 F		0006170718	20-236 F
	0006170719	20-236 F		0006170719	20-236 F
	0006170720	20-236 F		0006170720	20-236 F
	0006170721	20-236 F		0006170721	20-236 F
	0006170722	20-236 F		0006170722	20-236 F
	0006170723	20-236 F		0006170723	20-236 F
	0006170724	20-236 F		0006170724	20-236 F
	0006170725	20-236 F		0006170725	20-236 F
	0006170726	20-236 F		0006170726	20-236 F
	0006170727	20-236 F		0006170727	20-236 F
	0006170728	20-236 F		0006170728	20-236 F
	0006170729	20-236 F		0006170729	20-236 F
	0006170730	20-236 F		0006170730	20-236 F
	0006170731	20-236 F		0006170731	20-236 F
	0006170732	20-236 F		0006170732	20-236 F
	0006170733	20-236 F		0006170733	20-236 F
	0006170734	20-236 F		0006170734	20-236 F
	0006170735	20-236 F		0006170735	20-236 F
	0006170736	20-236 F		0006170736	20-236 F
	0006170737	20-236 F		0006170737	20-236 F
	0006170738	20-236 F		0006170738	20-236 F
	0006170739	20-236 F		0006170739	20-236 F
	0006170740	20-236 F		0006170740	20-236 F
	0006170741	20-236 F		0006170741	20-236 F
	0006170742	20-236 F		0006170742	20-236 F
	0006170743	20-236 F		0006170743	20-236 F
	0006170744	20-236 F		0006170744	20-236 F
	0006170745	20-236 F		0006170745	20-236 F
	0006170746	20-236 F		0006170746	20-236 F
	0006170747	20-236 F		0006170747	20-236 F
	0006170748	20-236 F		0006170748	20-236 F
	0006170749	20-236 F		0006170749	20-236 F
	0006170750	20-236 F		0006170750	20-236 F
	0006170751	20-236 F		0006170751	20-236 F
	0006170752	20-236 F		0006170752	20-236 F
	0006170753	20-236 F		0006170753	20-236 F
	0006170754	20-236 F		0006170754	20-236 F
	0006170755	20-236 F		0006170755	20-236 F
	0006170756	20-236 F		0006170756	20-236 F
	0006170757	20-236 F		0006170757	20-236 F
	0006170758	20-236 F		0006170758	20-236 F
	0006170759	20-236 F		0006170759	20-236 F
	0006170760	20-236 F		0006170760	20-236 F
	0006170761	20-236 F		0006170761	20-236 F
	0006170762	20-236 F		0006170762	20-236 F
	0006170763	20-236 F		0006170763	20-236 F
	0006170764	20-236 F		0006170764	20-236 F
	0006170765	20-236 F		0006170765	20-236 F
	0006170766	20-236 F		0006170766	20-236 F
	0006170767	20-236 F		0006170767	20-236 F
	0006170768	20-236 F		0006170768	20-236 F
	0006170769	20-236 F		0006170769	20-236 F
	0006170770	20-236 F		0006170770	20-236 F
	0006170771	20-236 F		0006170771	20-236 F
	0006170772	20-236 F		0006170772	20-236 F
	0006170773	20-236 F		0006170773	20-236 F
	0006170774	20-236 F		0006170774	20-236 F
	0006170775	20-236 F		0006170775	20-236 F
	0006170776	20-236 F		0006170776	20-236 F
	0006170777	20-236 F		0006170777	20-236 F
	0006170778	20-236 F		0006170778	20-236 F
	0006170779	20-236 F		0006170779	20-236 F
	0006170780	20-236 F		0006170780	20-236 F
	0006170781	20-236 F		0006170781	20-236 F
	0006170782	20-236 F		0006170782	20-236 F
	0006170783	20-236 F		0006170783	20-236 F
	0006170784	20-236 F		0006170784	20-236 F
	0006170785	20-236 F		0006170785	20-236 F
	0006170786	20-236 F		0006170786	20-236 F
	0006170787	20-236 F		0006170787	20-236 F
	0006170788	20-236 F		0006170788	20-236 F
	0006170789	20-236 F		0006170789	20-236 F
	0006170790	20-236 F		0006170790	20-236 F
	0006170791	20-236 F		0006170791	20-236 F
	0006170792	20-236 F		0006170792	20-236 F
	0006170793	20-236 F		0006170793	20-236 F
	0006170794	20-236 F		0006170794	20-236 F
	0006170795	20-236 F		0006170795	20-236 F
	0006170796	20-236 F		0006170796	20-236 F
	0006170797	20-236 F		0006170797	20-236 F
	0006170798	20-236 F		0006170798	20-236 F
	0006170799	20-236 F		0006170799	20-236 F
	0006170800	20-236 F		0006170800	20-236 F
	0006170801	20-236 F		0006170801	20-236 F
	0006170802	20-236 F		0006170802	20-236 F
	0006170803	20-236 F		0006170803	20-236 F
	0006170804	20-236 F		0006170804	20-236 F
	0006170805	20-236 F		0006170805	20-236 F
	0006170806	20-236 F		0006170806	20-236 F
	0006170807	20-236 F		0006170807	20-236 F
	0006170808	20-236 F		0006170808	20-236 F
	0006170809	20-236 F		0006170809	20-236 F
	0006170810	20-236 F		0006170810	20-236 F
	0006170811	20-236 F		0006170811	20-236 F
	0006170812	20-236 F		0006170812	20-236 F
	0006170813	20-236 F		0006170813	20-236 F
	0006170814	20-236 F		0006170814	20-236 F
	0006170815	20-236 F		0006170815	20-236 F
	0006170816	20-236 F		0006170816	20-236 F
	0006170817	20-236 F		0006170817	20-236 F
	0006170818	20-236 F		0006170818	20-236 F
	0006170819	20-236 F		0006170819	20-236 F
	0006170820	20-236 F		0006170820	20-236 F
	0006170821	20-236 F		0006170821	20-236 F
	0006170822	20-236 F		0006170822	20-236 F
	0006170823	20-236 F		0006170823	20-236 F
	0006170824	20-236 F			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8004000386	50-277 D		8004000320	50-284 P
	8004000386	50-277 P		8004000321	50-284 P
	8004000387	50-277 D		8004000322	50-284 P
	8004000387	50-277 D		8004000323	50-284 P
	8004000387	50-282 D		8004000324	50-284 P
	8004000387	50-277 G		8004000325	50-284 P
	8004000387	50-277 G		8004000326	50-284 P
	8004000387	50-277 G		8004000327	50-284 P
	8004000387	50-277 G		8004000328	50-284 P
	8004000387	50-277 G		8004000329	50-284 P
	8004000387	50-277 G		8004000330	50-284 P
	8004000387	50-277 G		8004000331	50-284 P
	8004000387	50-277 G		8004000332	50-284 P
	8004000387	50-277 G		8004000333	50-284 P
	8004000387	50-277 G		8004000334	50-284 P
	8004000387	50-277 G		8004000335	50-284 P
	8004000387	50-277 G		8004000336	50-284 P
	8004000387	50-277 G		8004000337	50-284 P
	8004000387	50-277 G		8004000338	50-284 P
	8004000387	50-277 G		8004000339	50-284 P
	8004000387	50-277 G		8004000340	50-284 P
	8004000387	50-277 G		8004000341	50-284 P
	8004000387	50-277 G		8004000342	50-284 P
	8004000387	50-277 G		8004000343	50-284 P
	8004000387	50-277 G		8004000344	50-284 P
	8004000387	50-277 G		8004000345	50-284 P
	8004000387	50-277 G		8004000346	50-284 P
	8004000387	50-277 G		8004000347	50-284 P
	8004000387	50-277 G		8004000348	50-284 P
	8004000387	50-277 G		8004000349	50-284 P
	8004000387	50-277 G		8004000350	50-284 P
	8004000387	50-277 G		8004000351	50-284 P
	8004000387	50-277 G		8004000352	50-284 P
	8004000387	50-277 G		8004000353	50-284 P
	8004000387	50-277 G		8004000354	50-284 P
	8004000387	50-277 G		8004000355	50-284 P
	8004000387	50-277 G		8004000356	50-284 P
	8004000387	50-277 G		8004000357	50-284 P
	8004000387	50-277 G		8004000358	50-284 P
	8004000387	50-277 G		8004000359	50-284 P
	8004000387	50-277 G		8004000360	50-284 P
	8004000387	50-277 G		8004000361	50-284 P
	8004000387	50-277 G		8004000362	50-284 P
	8004000387	50-277 G		8004000363	50-284 P
	8004000387	50-277 G		8004000364	50-284 P
	8004000387	50-277 G		8004000365	50-284 P
	8004000387	50-277 G		8004000366	50-284 P
	8004000387	50-277 G		8004000367	50-284 P
	8004000387	50-277 G		8004000368	50-284 P
	8004000387	50-277 G		8004000369	50-284 P
	8004000387	50-277 G		8004000370	50-284 P
	8004000387	50-277 G		8004000371	50-284 P
	8004000387	50-277 G		8004000372	50-284 P
	8004000387	50-277 G		8004000373	50-284 P
	8004000387	50-277 G		8004000374	50-284 P
	8004000387	50-277 G		8004000375	50-284 P
	8004000387	50-277 G		8004000376	50-284 P
	8004000387	50-277 G		8004000377	50-284 P
	8004000387	50-277 G		8004000378	50-284 P

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Tenneco, Latham F. Schmidt	0006100010	30-202	Q	0006100011	30-202
US Reclaim Corp	0006000006	XPARTLIC		0006000007	30-202
Union To Minerals Exploration Co	0006000002	40-0000		0006000003	30-202
Union Carbide Corp	0006000009	71-0000		0006000010	30-202
	0006000009	71-0000		0006000012	30-202
	0006000009	71-0000		0006000013	30-202
	0006000009	71-0000		0006000017	30-202
	0006000009	71-0000		0006000018	30-202
	0006000009	71-0000		0006000019	30-202
	0006000009	71-0000		0006000020	30-202
	0006000009	71-0000		0006000021	30-202
	0006000009	71-0000		0006000022	30-202
	0006000009	71-0000		0006000023	30-202
	0006000009	71-0000		0006000024	30-202
	0006000009	71-0000		0006000025	30-202
	0006000009	71-0000		0006000026	30-202
	0006000009	71-0000		0006000027	30-202
	0006000009	71-0000		0006000028	30-202
	0006000009	71-0000		0006000029	30-202
	0006000009	71-0000		0006000030	30-202
	0006000009	71-0000		0006000031	30-202
	0006000009	71-0000		0006000032	30-202
	0006000009	71-0000		0006000033	30-202
	0006000009	71-0000		0006000034	30-202
	0006000009	71-0000		0006000035	30-202
	0006000009	71-0000		0006000036	30-202
	0006000009	71-0000		0006000037	30-202
	0006000009	71-0000		0006000038	30-202
	0006000009	71-0000		0006000039	30-202
	0006000009	71-0000		0006000040	30-202
	0006000009	71-0000		0006000041	30-202
	0006000009	71-0000		0006000042	30-202
	0006000009	71-0000		0006000043	30-202
	0006000009	71-0000		0006000044	30-202
	0006000009	71-0000		0006000045	30-202
	0006000009	71-0000		0006000046	30-202
	0006000009	71-0000		0006000047	30-202
	0006000009	71-0000		0006000048	30-202
	0006000009	71-0000		0006000049	30-202
	0006000009	71-0000		0006000050	30-202
	0006000009	71-0000		0006000051	30-202
	0006000009	71-0000		0006000052	30-202
	0006000009	71-0000		0006000053	30-202
	0006000009	71-0000		0006000054	30-202
	0006000009	71-0000		0006000055	30-202
	0006000009	71-0000		0006000056	30-202
	0006000009	71-0000		0006000057	30-202
	0006000009	71-0000		0006000058	30-202
	0006000009	71-0000		0006000059	30-202
	0006000009	71-0000		0006000060	30-202
	0006000009	71-0000		0006000061	30-202
	0006000009	71-0000		0006000062	30-202
	0006000009	71-0000		0006000063	30-202
	0006000009	71-0000		0006000064	30-202
	0006000009	71-0000		0006000065	30-202
	0006000009	71-0000		0006000066	30-202
	0006000009	71-0000		0006000067	30-202
	0006000009	71-0000		0006000068	30-202
	0006000009	71-0000		0006000069	30-202
	0006000009	71-0000		0006000070	30-202
	0006000009	71-0000		0006000071	30-202
	0006000009	71-0000		0006000072	30-202
	0006000009	71-0000		0006000073	30-202
	0006000009	71-0000		0006000074	30-202
	0006000009	71-0000		0006000075	30-202
	0006000009	71-0000		0006000076	30-202
	0006000009	71-0000		0006000077	30-202
	0006000009	71-0000		0006000078	30-202
	0006000009	71-0000		0006000079	30-202
	0006000009	71-0000		0006000080	30-202
	0006000009	71-0000		0006000081	30-202
	0006000009	71-0000		0006000082	30-202
	0006000009	71-0000		0006000083	30-202
	0006000009	71-0000		0006000084	30-202
	0006000009	71-0000		0006000085	30-202
	0006000009	71-0000		0006000086	30-202
	0006000009	71-0000		0006000087	30-202
	0006000009	71-0000		0006000088	30-202
	0006000009	71-0000		0006000089	30-202
	0006000009	71-0000		0006000090	30-202
	0006000009	71-0000		0006000091	30-202
	0006000009	71-0000		0006000092	30-202
	0006000009	71-0000		0006000093	30-202
	0006000009	71-0000		0006000094	30-202
	0006000009	71-0000		0006000095	30-202
	0006000009	71-0000		0006000096	30-202
	0006000009	71-0000		0006000097	30-202
	0006000009	71-0000		0006000098	30-202
	0006000009	71-0000		0006000099	30-202
	0006000009	71-0000		0006000100	30-202
	0006000009	71-0000		0006000101	30-202
	0006000009	71-0000		0006000102	30-202
	0006000009	71-0000		0006000103	30-202
	0006000009	71-0000		0006000104	30-202
	0006000009	71-0000		0006000105	30-202
	0006000009	71-0000		0006000106	30-202
	0006000009	71-0000		0006000107	30-202
	0006000009	71-0000		0006000108	30-202
	0006000009	71-0000		0006000109	30-202
	0006000009	71-0000		0006000110	30-202
	0006000009	71-0000		0006000111	30-202
	0006000009	71-0000		0006000112	30-202
	0006000009	71-0000		0006000113	30-202
	0006000009	71-0000		0006000114	30-202
	0006000009	71-0000		0006000115	30-202
	0006000009	71-0000		0006000116	30-202
	0006000009	71-0000		0006000117	30-202
	0006000009	71-0000		0006000118	30-202
	0006000009	71-0000		0006000119	30-202
	0006000009	71-0000		0006000120	30-202
	0006000009	71-0000		0006000121	30-202
	0006000009	71-0000		0006000122	30-202
	0006000009	71-0000		0006000123	30-202
	0006000009	71-0000		0006000124	30-202
	0006000009	71-0000		0006000125	30-202
	0006000009	71-0000		0006000126	30-202
	0006000009	71-0000		0006000127	30-202
	0006000009	71-0000		0006000128	30-202
	0006000009	71-0000		0006000129	30-202
	0006000009	71-0000		0006000130	30-202
	0006000009	71-0000		0006000131	30-202
	0006000009	71-0000		0006000132	30-202
	0006000009	71-0000		0006000133	30-202
	0006000009	71-0000		0006000134	30-202
	0006000009	71-0000		0006000135	30-202
	0006000009	71-0000		0006000136	30-202
	0006000009	71-0000		0006000137	30-202
	0006000009	71-0000		0006000138	30-202
	0006000009	71-0000		0006000139	30-202
	0006000009	71-0000		0006000140	30-202
	0006000009	71-0000		0006000141	30-202
	0006000009	71-0000		0006000142	30-202
	0006000009	71-0000		0006000143	30-202
	0006000009	71-0000		0006000144	30-202
	0006000009	71-0000		0006000145	30-202
	0006000009	71-0000		0006000146	30-202
	0006000009	71-0000		0006000147	30-202
	0006000009	71-0000		0006000148	30-202
	0006000009	71-0000		0006000149	30-202
	0006000009	71-0000		0006000150	30-202
	0006000009	71-0000		0006000151	30-202
	0006000009	71-0000		0006000152	30-202
	0006000009	71-0000		0006000153	30-202
	0006000009	71-0000		0006000154	30-202
	0006000009	71-0000		0006000155	30-202
	0006000009	71-0000		0006000156	30-202
	0006000009	71-0000		0006000157	30-202
	0006000009	71-0000		0006000158	30-202
	0006000009	71-0000		0006000159	30-202
	0006000009	71-0000		0006000160	30-202
	0006000009	71-0000		0006000161	30-202
	0006000009	71-0000		0006000162	30-202
	0006000009	71-0000		0006000163	30-202
	0006000009	71-0000		0006000164	30-202
	0006000009	71-0000		0006000165	30-202
	0006000009	71-0000		0006000166	30-202
	0006000009	71-0000		0006000167	30-202
	0006000009	71-0000		0006000168	30-202
	0006000009	71-0000		0006000169	30-202
	0006000009	71-0000		0006000170	30-202
	0006000009	71-0000		0006000171	30-202
	0006000009	71-0000		0006000172	30-202
	0006000009	71-0000		0006000173	30-202
	0006000009	71-0000		0006000174	30-202
	0006000009	71-0000		0006000175	30-202
	0006000009	71-0000		0006000176	30-202
	0006000009	71-0000		0006000177	30-202
	0006000009	71-0000		0006000178	30-202
	0006000009	71-0000		0006000179	30-202
	0006000009	71-0000		0006000180	30-202
	0006000009	71-0000		0006000181	30-202
	0006000009	71-0000		0006000182	30-202
	0006000009	71-0000		0006000183	30-202
	0006000009	71-0000		0006000184	30-202
	0006000009	71-0000		0006000185	30-202
	0006000009	71-0000		0006000186	30-202
	0006000009	71-0000		0006000187	30-202
	0006000009	71-0000		0006000188	30-202
	0006000009	71-0000		0006000189	30-202
	0006000009	71-0000		0006000190	30-202
	0006000009	71-0000		0006000191	30-202
	0006000009	71-0000		0006000192	30-202
	0006000009	71-0000		0006000193	30-202
	0006000009	71-0000		0006000194	30-202
	0006000009	71-0000		0006000195	30-202
	0006000009	71-0000		0006000196	30-202
	0006000009	71-0000		0006000197	30-202
	0006000009	71-0000		0006000198	30-202
	0006000009	71-0000		0006000199	30-202

CORPORATE SOURCE INDEX

[illegible]

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
0004040209	0004040209	50-202 P	E50-CAMP-3154	0004040238	0004040238	REB	LTR 1111-42
0004040213	0004040213	REB	E50-TPM-3548	0004040241	0004040241	REB	LTR 15-37-30-12
0004040220	0004040220	REB	E50-BH1-1121	0004040244	0004040244	REB	LTR 1111-48
0004040225	0004040225	REB	24L-MUR3-27817	0004040248	0004040248	REB	LO-37-69-130
0004040231	0004040231	REB	E50-CAMP-3114	0004040249	0004040249	REB	RE 30-03-03-LR
0004040235	0004040235	REB	E50-CAMP-1142	0004040250	0004040250	REB	LTR 2C-47
0004040237	0004040237	REB	E50-LOFT-1143	0004040253	0004040253	REB	LO-37-75-120
0004040239	0004040239	REB	E50-BH1-1047	0004040259	0004040259	REB	E50-CA-3153
0004040242	0004040242	REB	E50-BH1-1090	0004040260	0004040260	REB	YB-PT-33
0004040244	0004040244	REB	E50-BH1-1090	0004040262	0004040262	REB	E50-CAMP-3140
0004040249	0004040249	REB	E50-CAMP-1142	0004040264	0004040264	REB	LO-35-B-114
0004040270	0004040270	REB	ORNL-HARRIS-70	0004040268	0004040268	REB	LTR 141-119
0004040271	0004040271	REB	E50-BH1-1047	0004040269	0004040269	REB	
0004040283	0004040283	REB	E50-BH1-1047	0004040270	0004040270	REB	
0004040289	0004040289	REB	E50-BH1-1047	0004040271	0004040271	REB	
0004040317	0004040317	REB	E50-BH1-1047	0004040272	0004040272	30-024 P	E50-CA-3109
0004040324	0004040324	REB	E50-BH1-1047	0004040280	0004040280	REB	
0004040321	0004040321	REB	E50-BH1-1047	0004040283	0004040283	REB	ORNL-VEB/118-120
0004040323	0004040323	REB	E50-BH1-1047	0004040289	0004040289	REB	ORNL-VEB/HARRIS-80
0004040328	0004040328	REB	E50-BH1-1047	0004040296	0004040296	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040304	0004040304	REB	ORNL-VEB/118-120
0004040324	0004040324	REB	E50-BH1-1047	0004040309	0004040309	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040314	0004040314	REB	ORNL-VEB/118-120
0004040324	0004040324	REB	E50-BH1-1047	0004040317	0004040317	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040320	0004040320	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040321	0004040321	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040322	0004040322	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040323	0004040323	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040324	0004040324	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040325	0004040325	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040326	0004040326	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040327	0004040327	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040328	0004040328	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040329	0004040329	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040330	0004040330	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040331	0004040331	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040332	0004040332	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040333	0004040333	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040334	0004040334	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040335	0004040335	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040336	0004040336	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040337	0004040337	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040338	0004040338	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040339	0004040339	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040340	0004040340	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040341	0004040341	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040342	0004040342	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040343	0004040343	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040344	0004040344	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040345	0004040345	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040346	0004040346	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040347	0004040347	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040348	0004040348	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040349	0004040349	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040350	0004040350	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040351	0004040351	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040352	0004040352	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040353	0004040353	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040354	0004040354	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040355	0004040355	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040356	0004040356	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040357	0004040357	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040358	0004040358	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040359	0004040359	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040360	0004040360	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040361	0004040361	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040362	0004040362	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040363	0004040363	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040364	0004040364	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040365	0004040365	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040366	0004040366	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040367	0004040367	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040368	0004040368	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040369	0004040369	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040370	0004040370	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040371	0004040371	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040372	0004040372	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040373	0004040373	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040374	0004040374	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040375	0004040375	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040376	0004040376	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040377	0004040377	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040378	0004040378	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040379	0004040379	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040380	0004040380	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040381	0004040381	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040382	0004040382	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040383	0004040383	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040384	0004040384	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040385	0004040385	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040386	0004040386	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040387	0004040387	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040388	0004040388	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040389	0004040389	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040390	0004040390	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040391	0004040391	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040392	0004040392	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040393	0004040393	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040394	0004040394	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040395	0004040395	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040396	0004040396	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040397	0004040397	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040398	0004040398	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040399	0004040399	REB	
0004040324	0004040324	REB	E50-BH1-1047	0004040400	0004040400	20-289 P	E50-CA-5147

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 60-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocked items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

[illegible][illegible]

CROSS REFERENCE OF ENCLOSURES OF
PRINCIPAL DOCUMENTS

[illegible]

ACCIDENT NUMBER	PAYMENT ACCIDENT	DATE ECLAIR	SUB-RENT CATEGORY
0504030000	0504030000	05/04/18	50-211
0504030001	0504030001	05/04/17	50-212
0504030002	0504030002	05/04/17	50-233
0504030003	0504030003	05/04/17	50-300
0504030004	0504030004	05/04/17	50-301
0504030005	0504030005	05/04/17	50-302
0504030006	0504030006	05/04/17	50-303
0504030007	0504030007	05/04/17	50-304
0504030008	0504030008	05/04/17	50-305
0504030009	0504030009	05/04/17	50-306
0504030010	0504030010	05/04/17	50-307
0504030011	0504030011	05/04/17	50-308
0504030012	0504030012	05/04/17	50-309
0504030013	0504030013	05/04/17	50-310
0504030014	0504030014	05/04/17	50-311
0504030015	0504030015	05/04/17	50-312
0504030016	0504030016	05/04/17	50-313
0504030017	0504030017	05/04/17	50-314
0504030018	0504030018	05/04/17	50-315
0504030019	0504030019	05/04/17	50-316
0504030020	0504030020	05/04/17	50-317
0504030021	0504030021	05/04/17	50-318
0504030022	0504030022	05/04/17	50-319
0504030023	0504030023	05/04/17	50-320
0504030024	0504030024	05/04/17	50-321
0504030025	0504030025	05/04/17	50-322
0504030026	0504030026	05/04/17	50-323
0504030027	0504030027	05/04/17	50-324
0504030028	0504030028	05/04/17	50-325
0504030029	0504030029	05/04/17	50-326
0504030030	0504030030	05/04/17	50-327
0504030031	0504030031	05/04/17	50-328
0504030032	0504030032	05/04/17	50-329
0504030033	0504030033	05/04/17	50-330
0504030034	0504030034	05/04/17	50-331
0504030035	0504030035	05/04/17	50-332
0504030036	0504030036	05/04/17	50-333
0504030037	0504030037	05/04/17	50-334
0504030038	0504030038	05/04/17	50-335
0504030039	0504030039	05/04/17	50-336
0504030040	0504030040	05/04/17	50-337
0504030041	0504030041	05/04/17	50-338
0504030042	0504030042	05/04/17	50-339
0504030043	0504030043	05/04/17	50-340
0504030044	0504030044	05/04/17	50-341
0504030045	0504030045	05/04/17	50-342
0504030046	0504030046	05/04/17	50-343
0504030047	0504030047	05/04/17	50-344
0504030048	0504030048	05/04/17	50-345
0504030049	0504030049	05/04/17	50-346
0504030050	0504030050	05/04/17	50-347
0504030051	0504030051	05/04/17	50-348
0504030052	0504030052	05/04/17	50-349
0504030053	0504030053	05/04/17	50-350
0504030054	0504030054	05/04/17	50-351
0504030055	0504030055	05/04/17	50-352
0504030056	0504030056	05/04/17	50-353
0504030057	0504030057	05/04/17	50-354
0504030058	0504030058	05/04/17	50-355
0504030059	0504030059	05/04/17	50-356
0504030060	0504030060	05/04/17	50-357
0504030061	0504030061	05/04/17	50-358
0504030062	0504030062	05/04/17	50-359
0504030063	0504030063	05/04/17	50-360
0504030064	0504030064	05/04/17	50-361
0504030065	0504030065	05/04/17	50-362
0504030066	0504030066	05/04/17	50-363
0504030067	0504030067	05/04/17	50-364
0504030068	0504030068	05/04/17	50-365
0504030069	0504030069	05/04/17	50-366
0504030070	0504030070	05/04/17	50-367
0504030071	0504030071	05/04/17	50-368
0504030072	0504030072	05/04/17	50-369
0504030073	0504030073	05/04/17	50-370
0504030074	0504030074	05/04/17	50-371
0504030075	0504030075	05/04/17	50-372
0504030076	0504030076	05/04/17	50-373
0504030077	0504030077	05/04/17	50-374
0504030078	0504030078	05/04/17	50-375
0504030079	0504030079	05/04/17	50-376
0504030080	0504030080	05/04/17	50-377
0504030081	0504030081	05/04/17	50-378
0504030082	0504030082	05/04/17	50-379
0504030083	0504030083	05/04/17	50-380
0504030084	0504030084	05/04/17	50-381
0504030085	0504030085	05/04/17	50-382
0504030086	0504030086	05/04/17	50-383
0504030087	0504030087	05/04/17	50-384
0504030088	0504030088	05/04/17	50-385
0504030089	0504030089	05/04/17	50-386
0504030090	0504030090	05/04/17	50-387
0504030091	0504030091	05/04/17	50-388
0504030092	0504030092	05/04/17	50-389
0504030093	0504030093	05/04/17	50-390
0504030094	0504030094	05/04/17	50-391
0504030095	0504030095	05/04/17	50-392
0504030096	0504030096	05/04/17	50-393
0504030097	0504030097	05/04/17	50-394
0504030098	0504030098	05/04/17	50-395
0504030099	0504030099	05/04/17	50-396
0504030100	0504030100	05/04/17	50-397
0504030101	0504030101	05/04/17	50-398
0504030102	0504030102	05/04/17	50-399
0504030103	0504030103	05/04/17	50-400
0504030104	0504030104	05/04/17	50-401
0504030105	0504030105	05/04/17	50-402
0504030106	0504030106	05/04/17	50-403
0504030107	0504030107	05/04/17	50-404
0504030108	0504030108	05/04/17	50-405
0504030109	0504030109	05/04/17	50-406
0504030110	0504030110	05/04/17	50-407
0504030111	0504030111	05/04/17	50-408
0504030112	0504030112	05/04/17	50-409
0504030113	0504030113	05/04/17	50-410
0504030114	0504030114	05/04/17	50-411
0504030115	0504030115	05/04/17	50-412
0504030116	0504030116	05/04/17	50-413
0504030117	0504030117	05/04/17	50-414
0504030118	0504030118	05/04/17	50-415
0504030119	0504030119	05/04/17	50-416
0504030120	0504030120	05/04/17	50-417
0504030121	0504030121	05/04/17	50-418
0504030122	0504030122	05/04/17	50-419
0504030123	0504030123	05/04/17	50-420
0504030124	0504030124	05/04/17	50-421
0504030125	0504030125	05/04/17	50-422
0504030126	0504030126	05/04/17	50-423
0504030127	0504030127	05/04/17	50-424
0504030128	0504030128	05/04/17	50-425
0504030129	0504030129	05/04/17	50-426
0504030130	0504030130	05/04/17	50-427
0504030131	0504030131	05/04/17	50-428
0504030132	0504030132	05/04/17	50-429
0504030133	0504030133	05/04/17	50-430
0504030134	0504030134	05/04/17	50-431
0504030135	0504030135	05/04/17	50-432
0504030136	0504030136	05/04/17	50-433
0504030137	0504030137	05/04/17	50-434
0504030138	0504030138	05/04/17	50-435
0504030139	0504030139	05/04/17	50-436
0504030140	0504030140	05/04/17	50-437
0504030141	0504030141	05/04/17	50-438
0504030142	0504030142	05/04/17	50-439
0504030143	0504030143	05/04/17	50-440
0504030144	0504030144	05/04/17	50-441
0504030145	0504030145	05/04/17	50-442
0504030146	0504030146	05/04/17	50-443
0504030147	0504030147	05/04/17	50-444
0504030148	0504030148	05/04/17	50-445
0504030149	0504030149	05/04/17	50-446
0504030150	0504030150	05/04/17	50-447
0504030151	0504030151	05/04/17	50-448
0504030152	0504030152	05/04/17	50-449
0504030153	0504030153	05/04/17	50-450
0504030154	0504030154	05/04/17	50-451
0504030155	0504030155	05/04/17	50-452
0504030156	0504030156	05/04/17	50-453
0504030157	0504030157	05/04/17	50-454
0504030158	0504030158	05/04/17	50-455
0504030159	0504030159	05/04/17	50-456
0504030160	0504030160	05/04/17	50-457
0504030161	0504030161	05/04/17	50-458
0504030162	0504030162	05/04/17	50-459
0504030163	0504030163	05/04/17	50-460
0504030164	0504030164	05/04/17	50-461
0504030165	0504030165	05/04/17	50-462
0504030166	0504030166	05/04/17	50-463
0504030167	0504030167	05/04/17	50-464
0504030168	0504030168	05/04/17	50-465
0504030169	0504030169	05/04/17	50-466
0504030170	0504030170	05/04/17	50-467
0504030171	0504030171	05/04/17	50-468
0504030172	0504030172	05/04/17	50-469
0504030173	0504030173	05/04/17	50-470
0504030174	0504030174	05/04/17	50-471
0504030175	0504030175	05/04/17	50-472
0504030176	0504030176	05/04/17	50-473
0504030177	0504030177	05/04/17	50-474
0504030178	0504030178	05/04/17	50-475
0504030179	0504030179	05/04/17	50-476
0504030180	0504030180	05/04/17	50-477
0504030181	0504030181	05/04/17	50-478
0504030182	0504030182	05/04/17	50-479
0504030183	0504030183	05/04/17	50-480
0504030184	0504030184	05/04/17	50-481
0504030185	0504030185	05/04/17	50-482
0504030186	0504030186	05/04/17	50-483
0504030187	0504030187	05/04/17	50-484
0504030188	0504030188	05/04/17	50-485
0504030189	0504030189	05/04/17	50-486
0504030190	0504030190	05/04/17	50-487
0504030191	0504030191	05/04/17	50-488
0504030192	0504030192	05/04/17	50-489
0504030193	0504030193	05/04/17	50-490
0504030194	0504030194	05/04/17	50-491
0504030195	0504030195	05/04/17	50-492
0504030196	0504030196	05/04/17	50-493
0504030197	0504030197	05/04/17	50-494
0504030198	0504030198	05/04/17	50-495
0504030199	0504030199	05/04/17	50-496
0504030200	0504030200	05/04/17	50-497
0504030201	0504030201	05/04/17	50-498
0504030202	0504030202	05/04/17	50-499
0504030203	0504030203	05/04/17	50-500
0504030204	0504030204	05/04/17	50-501
0504030205	0504030205	05/04/17	50-502
0504030206	0504030206	05/04/17	50-503
0504030207	0504030207	05/04/17	50-504
0504030208	0504030208	05/04/17	50-505
0504030209	0504030209	05/04/17	50-506
0504030210	0504030210	05/04/17	50-507
0504030211	0504030211	05/04/17	50-508
0504030212	0504030212	05/04/	

ET
OHF

Q
Q
Q
Q

4

A

Q
HE
T

Q
Q
C
Q

R

Q
Q
Q
Q
Q

P
S
H
P
P

F
Q
S
P
Q

H
Q
H
Q
Q

H
Q
Q
Q
Q

H
Q
H
H
E

H
Q
Q
Q
Q

Q
H
Q
Q
Q
H

H
Q
Q
P
H

H
Q
Q
Q
Q

H
Q
Q
Q
Q

Q
Q
Q
Q
Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

[illegible]

ENCLOSURE	ORIGINAL DOCUMENT	DATE ISSUED	RELEASE CATEGORY
0000000000	0000000000	00/00/00	00-000
0000000001	0000000010	00/00/00	00-000
0000000002	0000000020	00/00/00	00-000
0000000003	0000000030	00/00/00	00-000
0000000004	0000000040	00/00/00	00-000
0000000005	0000000050	00/00/00	00-000
0000000006	0000000060	00/00/00	00-000
0000000007	0000000070	00/00/00	00-000
0000000008	0000000080	00/00/00	00-000
0000000009	0000000090	00/00/00	00-000
0000000010	0000000100	00/00/00	00-000
0000000011	0000000110	00/00/00	00-000
0000000012	0000000120	00/00/00	00-000
0000000013	0000000130	00/00/00	00-000
0000000014	0000000140	00/00/00	00-000
0000000015	0000000150	00/00/00	00-000
0000000016	0000000160	00/00/00	00-000
0000000017	0000000170	00/00/00	00-000
0000000018	0000000180	00/00/00	00-000
0000000019	0000000190	00/00/00	00-000
0000000020	0000000200	00/00/00	00-000
0000000021	0000000210	00/00/00	00-000
0000000022	0000000220	00/00/00	00-000
0000000023	0000000230	00/00/00	00-000
0000000024	0000000240	00/00/00	00-000
0000000025	0000000250	00/00/00	00-000
0000000026	0000000260	00/00/00	00-000
0000000027	0000000270	00/00/00	00-000
0000000028	0000000280	00/00/00	00-000
0000000029	0000000290	00/00/00	00-000
0000000030	0000000300	00/00/00	00-000
0000000031	0000000310	00/00/00	00-000
0000000032	0000000320	00/00/00	00-000
0000000033	0000000330	00/00/00	00-000
0000000034	0000000340	00/00/00	00-000
0000000035	0000000350	00/00/00	00-000
0000000036	0000000360	00/00/00	00-000
0000000037	0000000370	00/00/00	00-000
0000000038	0000000380	00/00/00	00-000
0000000039	0000000390	00/00/00	00-000
0000000040	0000000400	00/00/00	00-000
0000000041	0000000410	00/00/00	00-000
0000000042	0000000420	00/00/00	00-000
0000000043	0000000430	00/00/00	00-000
0000000044	0000000440	00/00/00	00-000
0000000045	0000000450	00/00/00	00-000
0000000046	0000000460	00/00/00	00-000
0000000047	0000000470	00/00/00	00-000
0000000048	0000000480	00/00/00	00-000
0000000049	0000000490	00/00/00	00-000
0000000050	0000000500	00/00/00	00-000
0000000051	0000000510	00/00/00	00-000
0000000052	0000000520	00/00/00	00-000
0000000053	0000000530	00/00/00	00-000
0000000054	0000000540	00/00/00	00-000
0000000055	0000000550	00/00/00	00-000
0000000056	0000000560	00/00/00	00-000
0000000057	0000000570	00/00/00	00-000
0000000058	0000000580	00/00/00	00-000
0000000059	0000000590	00/00/00	00-000
0000000060	0000000600	00/00/00	00-000
0000000061	0000000610	00/00/00	00-000
0000000062	0000000620	00/00/00	00-000
0000000063	0000000630	00/00/00	00-000
0000000064	0000000640	00/00/00	00-000
0000000065	0000000650	00/00/00	00-000
0000000066	0000000660	00/00/00	00-000
0000000067	0000000670	00/00/00	00-000
0000000068	0000000680	00/00/00	00-000
0000000069	0000000690	00/00/00	00-000
0000000070	0000000700	00/00/00	00-000
0000000071	0000000710	00/00/00	00-000
0000000072	0000000720	00/00/00	00-000
0000000073	0000000730	00/00/00	00-000
0000000074	0000000740	00/00/00	00-000
0000000075	0000000750	00/00/00	00-000
0000000076	0000000760	00/00/00	00-000
0000000077	0000000770	00/00/00	00-000
0000000078	0000000780	00/00/00	00-000
0000000079	0000000790	00/00/00	00-000
0000000080	0000000800	00/00/00	00-000
0000000081	0000000810	00/00/00	00-000
0000000082	0000000820	00/00/00	00-000
0000000083	0000000830	00/00/00	00-000
0000000084	0000000840	00/00/00	00-000
0000000085	0000000850	00/00/00	00-000
0000000086	0000000860	00/00/00	00-000
0000000087	0000000870	00/00/00	00-000
0000000088	0000000880	00/00/00	00-000
0000000089	0000000890	00/00/00	00-000
0000000090	0000000900	00/00/00	00-000
0000000091	0000000910	00/00/00	00-000
0000000092	0000000920	00/00/00	00-000
0000000093	0000000930	00/00/00	00-000
0000000094	0000000940	00/00/00	00-000
0000000095	0000000950	00/00/00	00-000
0000000096	0000000960	00/00/00	00-000
0000000097	0000000970	00/00/00	00-000
0000000098	0000000980	00/00/00	00-000
0000000099	0000000990	00/00/00	00-000
0000000100	0000001000	00/00/00	00-000

412

2

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to Items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of Item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to Items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.
4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR).
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (SRP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual operating reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:

Logbooks on Environmental Data

Logbooks on Radiological Data

Operations Log on Plant Systems Core

Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PNS's).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to Items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plant, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adapt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.
3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES — Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP — NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.

4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

U.S. NUCLEAR REGULATORY COMMISSION
BIBLIOGRAPHIC DATA SHEET1 REPORT NUMBER (Assigned by DDC)
NUREG-0540 Vol 2, No66

TITLE AND SUBTITLE (Add Volume No., if appropriate)

Title List of Documents Made Publicly Available
June 1-30, 1980

2 (Leave blank)

3 RECIPIENT'S ACCESSION NO

AUTHOR(S)

5. DATE REPORT COMPLETED

MONTH July YEAR 1980

PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

6. DATE REPORT ISSUED

MONTH August YEAR 1980

6 (Leave blank)

8 (Leave blank)

SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

10 PROJECT/TASK/WORK UNIT NO

11. CONTRACT NO

TYPE OF REPORT

Monthly

PERIOD COVERED (Inclusive dates)

SUPPLEMENTARY NOTES

14 (Leave blank)

ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the US NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through the U.S. Department of Energy's Technical Information Center under the title *Power Reactor Docket Information (PRDI)*. This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.

KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

18. IDENTIFIERS/OPEN-ENDED TERMS

AVAILABILITY STATEMENT

Unlimited

19. SECURITY CLASS (This report)

Unclassified

21 NO OF PAGES

20. SECURITY CLASS (This page)

Unclassified

22 PRICE

\$